

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
614320	PRAMAC GSW80P 83KVA	CAMBIO GENERADOR AC	REPARAR GRUPO ELECTROGENO	25/06/2021		Corrective Order	Maintenance Work Request	Generator
614635	SDMO J60U 60KVA	CAMBIO RADIADOR	CAMBIO RETENEDORAS	25/06/2021		Corrective Order	Maintenance Work Request	Generator
618014	Landcruiser DC	CAMBIO CABLE FRENO	LIMPIEZA BANDAS	01/07/2021	CREADA PLANEAMIENTO	Corrective Order	Maintenance Work Request	Pickup truck
618015	Landcruiser DC	CAMBIO CORREA/POLEAS	CAMBIO BALINERA/PUNTA FLECHA/ALARMA RETROCESO	01/07/2021	CREADA PLANEAMIENTO	Corrective Order	Maintenance Work Request	Pickup truck
618021	Landcruiser DC	CAMBIO AJUSTADORES BANDA	MANTENIMIENTO CORRECTIVO	01/07/2021	CREADA PLANEAMIENTO	Corrective Order	Maintenance Work Request	Pickup truck
618356	Landcruiser TC	CAMBIO PERNOS/TUERCAS	MANTENIMIENTO CORRECTIVO	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	Maintenance Work Request	Pickup truck
619936	PRAMAC GSW30Y 24 kVa	CAMBIO CORREA ALTERNADOR	CORRECTIVO PROGRAMADO	04/07/2021		Corrective Order	Maintenance Work Request	Generator
631870	Caterpillar C9 250 kVa	CAMBIO CORREA MOTOR	CORRECTIVO PROGRAMADO	22/07/2021	CATALOGACION	Corrective Order	Maintenance Work Request	Generator
636523	Freightliner CI 120	VIDRIO FRONTAL ROTO	VIDRIO FRONTAL ROTO	28/07/2021		Corrective Order	Maintenance Work Request	Mule truck
637579	Forklifts	Reparar Parrilla	REPARAR PARRILLA	30/07/2021		Corrective Order	Maintenance Work Request	Area
637623	SDMO J60U 60 kVa	CAMBIO RETENEDORA POSTERIOR	FUGA DE ACEITE	30/07/2021		Corrective Order	Maintenance Work Request	Generator
638117	Forklifts	FLE001	FLE001	31/07/2021		Corrective Order	Maintenance Work Request	Area
638119	Forklifts	FLE003	FLE002	31/07/2021		Corrective Order	Maintenance Work Request	Area
638477	Mercedes Tipper Truck	Se quedó sin clutch	SE QUEDÓ SIN CLUTCH	01/08/2021		Corrective Order	Maintenance Work Request	Tipper
638670	Toyota Hilux	MantenimientoPreventivo LV-251	MANTENIMIENTOPREVENTIVO LV-251	01/08/2021		Corrective Order	Maintenance Work Request	Pickup truck
639045	Intraax 53121 Hendrickso	BOLSAS / TORNILLO	BOLSAS / TORNILLO	02/08/2021		Corrective Order	Maintenance Work Request	Trailer / Flatbed / Lime Tank
643266	Freightliner M112 Truck Tip	Tiene el vidrio delantero esti	TIENE EL VIDRIO DELANTERO ESTI	09/08/2021		Corrective Order	Maintenance Work Request	Tipper
643332	GROVE RT600E 50TON	CAMBIO DE SELLOS	CAMBIO DE SELLOS	09/08/2021		Corrective Order	Maintenance Work Request	Crane/Hoist
650085	Manitou Mht-X1490 9t Telehand	LLANTA FLAT	LLANTA FLAG	18/08/2021		Corrective Order	Maintenance Work Request	Telehender
651296	Intraax 53121 Hendrickso	BOLSA DE AIRE	BOLSA DE AIRE	20/08/2021		Corrective Order	Maintenance Work Request	Trailer / Flatbed / Lime Tank
652285	Caterpillar C9 250 kVa	CAMBIO MANGUERA VENTILACION	SALPICADURA ACEITE	22/08/2021		Corrective Order	Maintenance Work Request	Generator
652356	Pramac GSW25P 17KVA	CAMBIO DISPLAY	NO MUESTRA VALORES	22/08/2021		Corrective Order	Maintenance Work Request	Generator
662058	Sucker Trucks	SUT001 REQUIERE ADAPTACIONES	SUT001 REQUIERE ADAPTACIONES	05/09/2021		Corrective Order	Maintenance Work Request	Area
681949	Mobile equipment	Remplazo de Luces	REEMPLAZO DE LUCES	06/10/2021		Corrective Order	Maintenance Work Request	Area
683809	Iveco 380t38	Sin bomba hidraulica y otros	SIN BOMBA HIDRAULICA Y OTROS	08/10/2021		Corrective Order	Maintenance Work Request	Bitumen truck
684063	Mobile equipment	Reparacion brazo telehandler	REPARACION BRAZO TELEHANDLER	09/10/2021		Corrective Order	Maintenance Work Request	Area
686091	Iveco 380t38	sin luz escolta	SIN LUZ ESCOLTA	11/10/2021		Corrective Order	Maintenance Work Request	Bitumen truck
686110	Caterpillar CW34 Compactor	sin escolta	SIN ESCOLTA	11/10/2021		Corrective Order	Maintenance Work Request	Compactor
686124	Bomag BW219DH-4	No tiene luz escolta	NO TIENE LUZ ESCOLTA	11/10/2021		Corrective Order	Maintenance Work Request	Compactor
692054	Manitou Mht-X1490 9t Telehand	GUARDAFANGO CAIDO/ROTULA EJE	GUARDAFANGO CAIDO	19/10/2021		Corrective Order	Maintenance Work Request	Telehender
694050	Manitou Mht-X1490 9t Telehand	Revision del equipo en Gnral	REVISION DEL EQUIPO EN GNRAL	22/10/2021		Corrective Order	Maintenance Work Request	Telehender
695094	Manitou Mht-X860 6t Telehand	Revision de equipo	REVISION DE EQUIPO	24/10/2021		Corrective Order	Maintenance Work Request	Telehender
696614	Caterpillar 426f2 Backhoe	Capo rebventado de las bases	CAPO REBVENTADO DE LAS BASES	26/10/2021		Corrective Order	Maintenance Work Request	Backhoe
696660	Intraax 53121 Hendrickso	BUJES	BUJES	26/10/2021		Corrective Order	Maintenance Work Request	Trailer / Flatbed / Lime Tank
697957	Mobile equipment	REVISION DE FILTROS	OJITO	28/10/2021		Corrective Order	Maintenance Work Request	Area
698155	PRAMAC GBW15 14 kVa	CAMBIO CORREA ALTERNADOR	CORRECTIVO PROGRAMADO	29/10/2021		Corrective Order	Maintenance Work Request	Generator
698589	Freightliner M112 Truck Tip	Gala de lado izquierdo en ma	GALA DE LADO IZQUIERDO EN MA	30/10/2021		Corrective Order	Maintenance Work Request	Tipper
701230	Manitou Mht-X860 6t Telehand	Reparacion	REPARACION	03/11/2021		Corrective Order	Maintenance Work Request	Telehender
701607	Freightliner M2 106	Tiene daños en la electroválvu	TIENE DAÑOS EN LA ELECTROVÁLVU	03/11/2021		Corrective Order	Maintenance Work Request	Bitumen truck
702589	BT019 345 IVECO GRUA 6X6	plproblemas con la pluma	PLPROBLEMAS CON LA PLUMA	05/11/2021		Corrective Order	Maintenance Work Request	Boom truck
702697	Caterpillar RM500 Reclaimer	Llanta delantera lado derecho	LLANTA DELANTERA LADO DERECHO	05/11/2021		Corrective Order	Maintenance Work Request	Road Reclaimer
703854	Unimog Service Truck	FALLA ELECT EN TABLERO DE INST	FALLA ELECT EN TABLERO DE INST	07/11/2021		Corrective Order	Maintenance Work Request	Truck
704112	Dossan	REEMPLAZO DE RUEDAS	MANTENIMIENTO CORRECTIVO	07/11/2021		Corrective Order	Maintenance Work Request	Generator
704115	USP&E GP700S/V-A 700 kVa	CAMBIO BASE FILTRO	POR ROTURA DE BASE	07/11/2021		Corrective Order	Maintenance Work Request	Generator
705411	Caterpillar D110 E2 100KVA	CAMBIO DE RADIADOR	CAMBIO DE RADIADOR ROTO	09/11/2021		Corrective Order	Maintenance Work Request	Generator
705607	Freightliner M2 106	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULIC	09/11/2021		Corrective Order	Maintenance Work Request	Bitumen truck
705608	Freightliner M2 106	No le funciona el automatico	NO LE FUNCIONA EL AUTOMATICO	09/11/2021		Corrective Order	Maintenance Work Request	Bitumen truck
705614	Caterpillar CS533E Compactor	Llanta izquierda en mal estado	LLANTA IZQUIERDA EN MAL ESTADO	09/11/2021		Corrective Order	Maintenance Work Request	Compactor
709452	Power Curbers 5700-C	Sensor de estabilidad defectuo	SENSOR DE ESTABILIDAD DEFECTUO	14/11/2021		Corrective Order	Maintenance Work Request	Kerb Machine
709872	ETNYRE QUAD	Pollera de sostener el materi	POLLERA DE SOSTENER EL MATERI	14/11/2021		Corrective Order	Maintenance Work Request	Chip Spreader
710336	Boom Truck Iveco Tector	No tiene la manija de subir y	NO TIENE LA MANIJA DE SUBIR Y	15/11/2021		Corrective Order	Maintenance Work Request	Boom truck
711388	Manitou Mht-X860 6t Telehand	FUGA HIDRAULICA	FUGA HIDRAULICA	16/11/2021		Corrective Order	Maintenance Work Request	Telehender
713409	Caterpillar 226b Skid Steer L	Vidrio frontal astillado	VIDRIO FRONTAL ASTILLADO	19/11/2021		Corrective Order	Maintenance Work Request	Skid Steer
714727	Hyster E70xn 3t Forklift (E)	REPOSITION BLUE SAFETY LIGHT	REPOSITION BLUE SAFETY LIGHT	21/11/2021		Corrective Order	Maintenance Work Request	Forklift
714781	Bomag BW24RH	Llanta flat	LLANTA FLAT	21/11/2021		Corrective Order	Maintenance Work Request	Roller PTR
714833	Unimog Service Truck	Llanta Flat Unimog 07	LLANTA FLAT UNIMOG 07	21/11/2021		Corrective Order	Maintenance Work Request	Truck
715329	Caterpillar 416F2 Backhoe	Ganchos de seguridad no funcio	GANCHOS DE SEGURIDAD NO FUNCIO	22/11/2021		Corrective Order	Maintenance Work Request	Backhoe
715353	Bomag BW219DH-4	No arranca	NO ARRANCA	22/11/2021		Corrective Order	Maintenance Work Request	Compactor
715481	Faresin FM4000 / 17F Telehandl	revicion de correas	REVICION DE CORREAS	22/11/2021		Corrective Order	Maintenance Work Request	Telehender
715482	Caterpillar 226b Skid Steer L	INSTALACION DE ESCOLTA	INSTALACION DE ESCOLTA	22/11/2021		Corrective Order	Maintenance Work Request	Skid Steer
715986	Faresin FM4000 / 17F Telehandl	Reparar horometro	REPARAR HOROMETRO	23/11/2021		Corrective Order	Maintenance Work Request	Telehender
716156	Unimog Service Truck	CORRECCIONES PARA UNIMOC 7	CORRECCIONES PARA UNIMOC 7	23/11/2021		Corrective Order	Maintenance Work Request	Truck
716321	Freightliner Columbia CI112	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	Maintenance Work Request	Mule truck
716322	Freightliner CI 120	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	Maintenance Work Request	Mule truck
716323	Freightliner CI 120	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	Maintenance Work Request	Mule truck
716325	Freightliner CI 120	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	Maintenance Work Request	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
716555	PRAMAC GSW110 82 kVa	CAMBIO DE REGULADOR DE VOLTAGE	CAMBIO DE REGULADOR DE VOLTAGE POR FLUCTUACION	24/11/2021		Corrective Order	Maintenance Work Request	Generator
716562	SDMO T11UM 10KVA	CAMBIO DE SENSOR	CAMBIO DE SENSOR DE PRESION DE ACEITE	24/11/2021		Corrective Order	Maintenance Work Request	Generator
716570	Caterpillar C7.1 200 kVa	CAMBIO DE CT & REGULADOR	CAMBIO DE CT & REGULADOR DE VOLTAJE AC	24/11/2021		Corrective Order	Maintenance Work Request	Generator
716694	Eagle Beaver 50sgl-Pt	BUJES / CILINDROS	BUJES / CILINDROS	24/11/2021		Corrective Order	Maintenance Work Request	Trailer / Flatbed / Lime Tank
716751	Caterpillar 416E	Se le cayo (partio) la tapa de	SE LE CAYO (PARTIO) LA TAPA DE	24/11/2021		Corrective Order	Maintenance Work Request	Backhoe
716835	Hilux DC	NEBULIZACION COVID	NEBULIZACION COVID	24/11/2021		Corrective Order	Maintenance Work Request	Pickup truck
716843	Freightliner Cl 120	nebulizar equipo	NEBULIZAR EQUIPO	24/11/2021		Corrective Order	Maintenance Work Request	Mule truck
717203	Caterpillar 12M	Alarma de avería en la direcci	ALARMA DE AVERÍA EN LA DIRECCI	25/11/2021		Corrective Order	Maintenance Work Request	Grader
717230	TTP-0000-102	Nebulización de equipo	NEBULIZACION DE EQUIPO	25/11/2021		Corrective Order	Maintenance Work Request	Excavator
717299	Manitou Mht-X1490 9t Telehand	Sensor de Puerta NO fFnciona	SENSOR DE PUERTA NO FFNCIONA	25/11/2021		Corrective Order	Maintenance Work Request	Telehender
717347	Freightliner M112 Truck Tip	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	25/11/2021	30,006.70 km	Corrective Order	Maintenance Work Request	Tipper
717661	Bomag BW24RH	No tiene retrovisor	NO TIENE RETROVISOR	25/11/2021		Corrective Order	Maintenance Work Request	Roller PTR
717851	Pit Operations Offices	Reparacion de grifos	REPARACION DE GRIFOS	26/11/2021		Corrective Order	Maintenance Work Request	Building
717852	Pit Operations Offices	CAMBIO DE LUCES	CAMBIO DE LUCES	26/11/2021		Corrective Order	Maintenance Work Request	Building
717854	Pit Operations Offices	cambio de ventana	CAMBIO DE VENTANA	26/11/2021		Corrective Order	Maintenance Work Request	Building
717857	Pit Operations Offices	reparacion de puertas	REPARACION DE PUERTAS	26/11/2021		Corrective Order	Maintenance Work Request	Building
718114	PRAMAC GSW460V 460 kVa	REPARACIÓN DE ALTERNADOR AC	EMBOBINADOS NACIONALES	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718115	SDMO J30U 38 kVa	REPARACIÓN DE ALTERNADOR AC	EMBOBINADOS NACIONALES	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718118	PRAMAC GSW80P 83 kVa	REPARACIÓN DE ALTERNADOR AC	EMBOBINADOS NACIONALES	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718119	PRAMAC GSW110P 82 kVa	REPARACIÓN DE ALTERNADOR AC	EMBOBINADOS NACIONALES	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718131	Olympian GEP18-6 18KVA	REEMPLAZO DE BOMBA DE MANO	MANTENIMIENTO CORRECTIVO	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718134	Pramac GSW25P 17KVA	REEMPLAZO DE BOMBA DE MANO	MANTENIMIENTO CORRECTIVO	26/11/2021		Corrective Order	Maintenance Work Request	Generator
718135	Caterpillar DE22E3 17.6 kVa	REEMPLAZO DE BOMBA DE MANO	MANTENIMIENTO CORRECTIVO	26/11/2021		Corrective Order	Maintenance Work Request	Generator
717954	EX036 EC480DL Volvo	EC480DL-MAINTENANCE 250 HRS	EC480DL-MAINTENANCE 250 HRS	26/11/2021		PM proposal JDE	WO Approved	Excavator
601187	JLG 1250 AJP Manlift	MECHANICAL REPAIRS (C&L)	CORRECTIVE	02/06/2021		Corrective Order	W/O In Planning	Manlift
602162	Gallegos Flatbed Trailer	FRENOS / LUCES / FUGA	FRENOS / LUCES, FABRICAR MANGUERA DE FRENO	04/06/2021	90011165	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
602460	Caterpillar 740B	Problemas para abrir la puerta	PROBLEMAS PARA ABRIR LA PUERTA	05/06/2021		Corrective Order	W/O In Planning	Articulated dump truck
602619	Mobile equipment	ACEITE Y GRASAS PM04	INSUMOS EQUIPOS CAT	05/06/2021	90008868 90008869 90009284	Corrective Order	W/O In Planning	Area
605004	TTP-0000-102	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	09/06/2021	90006161	Corrective Order	W/O In Planning	Excavator
605007	Hino Series 300 Truck	CAMBIO BOMBA ACEITE	TALLER TAMBOR PANAMA	09/06/2021		Corrective Order	W/O In Planning	Truck
605013	Toyota Hilux	CAMBIO FRENOS/SUSPENSION	TALLER DOLLAR MINA	09/06/2021		Corrective Order	W/O In Planning	Pickup truck
605478	WT014 H7 CISTERNA SINOTRUK	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	10/06/2021		Corrective Order	W/O In Planning	Water truck
607556	PRAMAC GSW560V 407 kVa	REPUESTOS REPARAR MOTOR	COMPRA REPUESTOS O3	14/06/2021	60020369	Corrective Order	W/O In Planning	Generator
609047	Caterpillar 336DL Excavator	reparacion de balde Cicsa	BALDE EN MAL ESTADO	16/06/2021	50014203 50014787	Corrective Order	W/O In Planning	Excavator
609410	Caterpillar 12M Motorgrader	Aire acondicionado dañado	AIRE ACONDICIONADO DAÑADO	17/06/2021	90017914	Corrective Order	W/O In Planning	Grader
609574	Caterpillar 14H Motorgrader	CILINDRO DE INCLINACIÓN DE LLA	CILINDRO DE INCLINACIÓN DE LLANTA DEFECTUSO, PARTIDO	17/06/2021	90009273	Corrective Order	W/O In Planning	Grader
610157	GROVE GMK 5170 170TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	W/O In Planning	Crane/Hoist
610160	Terex RT5551 55TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	W/O In Planning	Crane/Hoist
610168	Manitou Mht-X860 6t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	W/O In Planning	Telehender
610169	Manitou Mht-X860 6t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021	90011691 90011404	Corrective Order	W/O In Planning	Telehender
610170	Manitou Mht-X1490 9t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	W/O In Planning	Telehender
610358	JLG T350 Manlift	CYL REPAIR (MASTER TECH)	CORRECTIVE	19/06/2021	50014489	Corrective Order	W/O In Planning	Manlift
610695	New Holland Lm 1745	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Telehender
610707	Manitou Mht-X1490 9t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Telehender
610711	Hyster J40zt	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Forklift
610714	Terex RT780-1 80TON	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Crane/Hoist
610733	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
610749	JLG T350 Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
610752	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
610753	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
610755	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
610757	JLG 1850 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	W/O In Planning	Manlift
611704	Caterpillar 426f2 Backhoe	REPARACION, REPORTE TA1	INSPECCION IASA APOYO TACTICO	21/06/2021	90016410	Corrective Order	W/O In Planning	Backhoe
611717	Caterpillar 426f2 Backhoe	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021	90009508 90001007	Corrective Order	W/O In Planning	Backhoe
611718	Caterpillar 416F2 Backhoe	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021	90009787 90010374	Corrective Order	W/O In Planning	Backhoe
611740	Caterpillar 236d Skid Steer L	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021	90016411	Corrective Order	W/O In Planning	Skid Steer
612303	ATR-0000-001 4+320 AGRICO	Cambio de Pastillas de freno	PASTILLAS DE FRENOS EN MAL ESTADO	22/06/2021	90011003	Corrective Order	W/O In Planning	Tractor
612323	Mobile equipment	MATERIAL OFICINA PLANER	MATERIAL OFICINA PLANER	22/06/2021	60020405	Corrective Order	W/O In Planning	Area
612883	TTP-0000-102	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	W/O In Planning	Excavator
612896	Caterpillar D6T LGP	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	W/O In Planning	Dozer
612927	Landcruiser DC	REPARAR TRANSMISION/CAJA TIMON	TALLER DOLLAR MINA	23/06/2021		Corrective Order	W/O In Planning	Pickup truck
612929	Landcruiser DC	REPARAR TRANSFER/COCOBOLAS	TALLER DOLLAR PENONOME	23/06/2021		Corrective Order	W/O In Planning	Pickup truck
612944	Ford 450	REPARAR SUSPENSION/DIRECCION	TALLER DOLLAR MINA	23/06/2021	50013609	Corrective Order	W/O In Planning	Pickup truck
612950	Hino Serie 300	REPARACION GARANTIA	TALLER DOLLAR PANAMA	23/06/2021		Corrective Order	W/O In Planning	Truck
612951	Hino Serie 300	REPARAR A/C PARABRISAS	TALLER DOLLAR MINA	23/06/2021		Corrective Order	W/O In Planning	Truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
612952	Hino Series 300	REPARACION GENERAL	TALLER DOLLAR PENONOME	23/06/2021	50015617	Corrective Order	W/O In Planning	Truck
612954	Hino Dutro 300	REPARAR ALTERNADOR/SUSPENSION	TALLER DOLLAR MINA	23/06/2021	50013903	Corrective Order	W/O In Planning	Truck
612959	Isuzu NMR85L	REPARACION GENERAL	TALLER DOLLAR PENONOME	23/06/2021	50015653 50017787	Corrective Order	W/O In Planning	Truck
613035	Mobile equipment	COPAMA'S LUBRICANTS	CONSUMABLE	23/06/2021	90009509 90009534	Corrective Order	W/O In Planning	Area
613363	Hyster J40zt	PM4 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021	90010002	Corrective Order	W/O In Planning	Forklift
615080	Caterpillar 336DL	Cambio de casquillos	CASQUILLOS DE MAL ESTADO	26/06/2021	90009671	Corrective Order	W/O In Planning	Excavator
615375	Caterpillar 12M	INSPECCION TA1	INSPECCION IASA	27/06/2021	90010027 90010028 90016556	Corrective Order	W/O In Planning	Grader
615589	JLG 1850 AJ Manlift	Cambio de sensor de Gavilon	EQUIPO BLOQUEADO	27/06/2021	90010637 90016237	Corrective Order	W/O In Planning	Manlift
616008	Caterpillar 12M	Cambios de materiales de desga	AJUSTADPRES DE DESGASTE EN MAL ESTADO	28/06/2021	90009669	Corrective Order	W/O In Planning	Grader
616225	Broce Broom RJT 350	Cambio de bomba hidraulica	FUGA DE ACEITE HIDRAULICA	28/06/2021	60020844 60020727	Corrective Order	W/O In Planning	Scrubber / Sweeper
617272	Mobile equipment	ELEC CONSUMABLES, FUSE	ELECTRICAL CONSUMABLE WORK SHOP	30/06/2021	90016500	Corrective Order	W/O In Planning	Area
617524	Ferrari F478	CAMBIO DE 6 NEUMATICOS	CORRECTVO	30/06/2021	90009865 50015376 50015378	Corrective Order	W/O In Planning	Reach Stacker
617541	Caterpillar 226b Skid Steer L	REPARACION DE BALDE	SOLICITUD A CIGSA	30/06/2021		Corrective Order	W/O In Planning	Skid Steer
618064	Caterpillar 226b Skid Steer L	CAMBIO COMPONENTES	APOYO IASA	01/07/2021		Corrective Order	W/O In Planning	Skid Steer
618894	Caterpillar 426F2 Backhoe	Cambio de sellos	FUGA POR CUERPO DE VÁLVULA DE LEVANTE DE BALDE	03/07/2021		Corrective Order	W/O In Planning	Backhoe
618899	JLG 800 AJ Manlift	Cambio de correa y sello de ta	CORREA DEL MOTOR EN MAL ESTADO Y FUGA POR SELLO DE TAPA VALVULA	03/07/2021		Corrective Order	W/O In Planning	Manlift
618903	Caterpillar 226b Skid Steer L	Cambio de sellos y polea	FUGA DE ACEITE DE MOTOR POR SELLO DE POLEA	03/07/2021		Corrective Order	W/O In Planning	Skid Steer
618930	Freightliner M2 106 Sucker Tru	Cambio de componentes	CAMBIO DE COMPONENTES	03/07/2021	900010160 900010161	Corrective Order	W/O In Planning	Sucker truck
619427	Cargador 966H Wheel Loader	CAMBIO DE COMPONENTES	SELLOS	03/07/2021	90011027	Corrective Order	W/O In Planning	Loader
619484	Hyster H70ft 3t Forklift (M)	Cambio de balineras	BALILERAS EN MAL ESTADO	03/07/2021	90014752	Corrective Order	W/O In Planning	Forklift
619672	Caterpillar D6T LGP	CAMBIO DE FRAME	CAMBIO DE COMPONENTES IASA	04/07/2021	90009819	Corrective Order	W/O In Planning	Dozer
621387	Caterpillar 12M	cambio de polea y correa	CORREA Y POLEA DEL ALTERNADOR EN MAL ESTADO	06/07/2021		Corrective Order	W/O In Planning	Grader
622097	Caterpillar 140K	INSPECCION TA1 IASA	EQUIPO IASA	07/07/2021	90010347 90010348	Corrective Order	W/O In Planning	Grader
622250	PB012 COASTER TOYOTA	CAMBIO CINTURONES SEGURIDAD	REPARAR A/A	07/07/2021	50014307	Corrective Order	W/O In Planning	Bus
623920	Unimog Service Truck	Adaptación de Motor	ADAPTACIÓN DE MOTOR	09/07/2021		Corrective Order	W/O In Planning	Truck
623946	Caterpillar 140K	CAMBIO DE COMPONENTES	INSPECCION DE IASA	09/07/2021		Corrective Order	W/O In Planning	Grader
624033	JLG 1250 AJP Manlift	cambio de motor de arranque	CAMBIO DE MOTOR DE ARRANQUE	09/07/2021	90012042	Corrective Order	W/O In Planning	Manlift
624062	Freightliner Boom Truck	REPARACIÓN MAYOR	REPARACIÓN DE EQUIPO EN TALLER EXTERNO	09/07/2021	50014772	Corrective Order	W/O In Planning	Boom truck
624143	Caterpillar 740b Ej	REPARACION DE CILINDROS	MASTER TECH	09/07/2021		Corrective Order	W/O In Planning	Articulated dump truck
624980	Freightliner M2 106 Sucker Tru	Accesorios de Valvula	INSTALACIÓN DE VÁLVULA DE SERVICIO DE ESTACIONAMIENTO	11/07/2021	90010643 90010644	Corrective Order	W/O In Planning	Sucker truck
625983	Caterpillar 226b Skid Steer L	Cambio de piezas corrosion	CAMBIO DE TURBO, PINES DEL BALDE, MULTIPLE DE ESCAPE	12/07/2021	90010288	Corrective Order	W/O In Planning	Skid Steer
626604	Mobile equipment	CADENAS Y PARANTES	PERSONAL DE GENERADORES	13/07/2021		Corrective Order	W/O In Planning	Area
627012	Linde T30D	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	14/07/2021	90010276	Corrective Order	W/O In Planning	Forklift
627014	Linde T30D	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	14/07/2021	90010291 50014485	Corrective Order	W/O In Planning	Forklift
627211	TTP-0000-102	CAMBIO VALVULAS	CAMBIO DE VALVULAS	14/07/2021		Corrective Order	W/O In Planning	Excavator
627643	Freightliner M2 112 Sucker Tru	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	15/07/2021		Corrective Order	W/O In Planning	Sucker truck
627731	Caterpillar PS-150C	TA1 EVALUACION MECANICA	PERSONAL DE IASA	15/07/2021	90013541	Corrective Order	W/O In Planning	Roller PTR
628537	Caterpillar 12M Motorgrader	Cambio de componente	CAMBIO DE COMPONENTE	16/07/2021	90010364	Corrective Order	W/O In Planning	Grader
629044	New Holland Lm 1745	cambio de escobillas	CAMBIO DE ESCOBILLAS	17/07/2021	90016903 90017402	Corrective Order	W/O In Planning	Telehender
629056	Mobile equipment	CONSUMIBLES SPRAY SALPICA MIG	CONSUMIBLES SOLDADURA	17/07/2021	90010339	Corrective Order	W/O In Planning	Area
629489	Caterpillar 12M	TA1 EVALUACION E INSPECCION	REA;LIZADO PERSONAL IASA	18/07/2021		Corrective Order	W/O In Planning	Grader
629545	Caterpillar 300.9D MicoExcavat	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	18/07/2021		Corrective Order	W/O In Planning	Excavator
629735	Grove RT700E 60TON	Cambio de flexplate	EQUIPO NEUTRALIZADO	19/07/2021		Corrective Order	W/O In Planning	Crane/Hoist
629964	Freightliner Cl 120	SILENCIADOR / TABLERO	SILENCIADOR / TABLERO	19/07/2021		Corrective Order	W/O In Planning	Mule truck
629989	Caterpillar RM500 Reclaimer	PM02-PREVENTIVE MAINTENANCE	OIL AND FILTER REPLACEMENT	19/07/2021	PKG-10006852	Corrective Order	W/O In Planning	Road Reclaimer
629997	Caterpillar RM500 Reclaimer	PM03-PREVENTIVE MAINTENANCE	OIL AND FILTER REPLACEMENT	19/07/2021	PKG-10006852	Corrective Order	W/O In Planning	Road Reclaimer
630013	Freightliner Cl 120	LAMPARA/PALANCA / CAPOT	REPARACION CAPOT PAINT SOLUTION	19/07/2021	50014659 50016900	Corrective Order	W/O In Planning	Mule truck
630023	Caterpillar RM500 Reclaimer	PM04-PREVENTIVE MAINTENANCE	OIL AND FILTER REPLACEMENT	19/07/2021	90016456	Corrective Order	W/O In Planning	Road Reclaimer
630059	Gallegos Flatbed Trailer	LUCES / REVISION DE FRENO/PINE	LUCES / REVISION DE FRENO DE FRENO	19/07/2021	90013568	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
630665	Freightliner M2 106 Sucker Tru	Cambio de bomba de succion	CAMBIO DE BOMBA DE SUCCION Y ACOPLES	20/07/2021	pkg-10006864	Corrective Order	W/O In Planning	Sucker truck
630756	Freightliner Cl 120	Cambio de base de motor	1 BASE DE MOTOR RAJADA	20/07/2021		Corrective Order	W/O In Planning	Mule truck
630826	Caterpillar CS533E Compactor	TA1 INSPECCION Y EVALUACION	INSPECCION POR IASA	20/07/2021	PKG-10006877	Corrective Order	W/O In Planning	Compactor
630837	Freightliner M2 106 Sucker Tru	Cambio de bomba de succion	CAMBIO DE BOMBA DE SUCCION Y ACOPLES	20/07/2021		Corrective Order	W/O In Planning	Sucker truck
630849	Caterpillar 426f2 Backhoe	REEMPLAZO DE LAMPARAS	REEMPLAZO DE LAMPARAS Y GUARDA DE RADIADOR	20/07/2021		Corrective Order	W/O In Planning	Backhoe
631143	ETNYRE QUAD	Reparaciones Generales	REPARACIONES GENERALES	21/07/2021	90014968	Corrective Order	W/O In Planning	Chip Spreader
631379	Caterpillar 416E	JUNTAS DESGASTADAS	CORRECTIVO	21/07/2021	90011517 90011533 90016439	Corrective Order	W/O In Planning	Backhoe
631945	Landcruiser TC	REPARAR MOTOR RECALENTAMIENTO	EN EVALUACION DOLLAR	22/07/2021	50015868	Corrective Order	W/O In Planning	Pickup truck
631952	PB003 COASTER TOYOTA	REPARACION GENERAL	TALLER DOLLAR MINA	22/07/2021	50015074 50015429	Corrective Order	W/O In Planning	Bus
632400	PB011 COASTER TOYOTA	REPARACION GENERAL	TALLER DOLLAR PENONOME	23/07/2021	50015112 50015677	Corrective Order	W/O In Planning	Bus
632414	Hino Series 300 Truck	REPARACION GENERAL	TALLER DOLLAR MINA	23/07/2021	50015120	Corrective Order	W/O In Planning	Truck
633321	Mobile equipment	HERRAMIENTAS INSTALACION VIDRI	KIT DE INSTALACION DE VIDRIOS	24/07/2021		Corrective Order	W/O In Planning	Area
633677	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	25/07/2021	90015379	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
635582	Caterpillar 416F2 Backhoe	Cambio de bomba de inyeccion	FALLA EN SISTEMA DE INYECCION	27/07/2021	90011024	Corrective Order	W/O In Planning	Backhoe
635666	SJS SJ6530	REPARACION COMPONENTES	ENVIADOS CIGSA	27/07/2021		Corrective Order	W/O In Planning	Compactor
635683	Freightliner M112 Truck Tip	Cambio de 3er brazo de direcc	TERCER BRAZO DE DIRECCION EN MAL	27/07/2021		Corrective Order	W/O In Planning	Tipper
635793	Caterpillar CS74 Compactor	PM02 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA	27/07/2021		Corrective Order	W/O In Planning	Compactor
635794	Caterpillar CS74 Compactor	PM03 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA	27/07/2021		Corrective Order	W/O In Planning	Compactor
635805	Caterpillar CS74 Compactor	PM02 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA	27/07/2021		Corrective Order	W/O In Planning	Compactor
635806	Caterpillar CS74 Compactor	PM03 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA	27/07/2021		Corrective Order	W/O In Planning	Compactor
636312	Landcruiser TC	REPARAR DIFERENCIAL/TK COMBUST	GOLPE EN TANQUE DE COMBUSTIBLE	28/07/2021		Corrective Order	W/O In Planning	Pickup truck
636451	Caterpillar 307E Miniexcavator	Correcion de fugas	FUGAS HIDRAULICAS	28/07/2021	90016220	Corrective Order	W/O In Planning	Excavator
636949	Caterpillar 14M Motorgrader	Cambio de componentes	CAMBIO DE COMPONENTES	29/07/2021		Corrective Order	W/O In Planning	Grader
637054	Manitou Mht-X1490 9t Telehand	Cambio de correa y abrazaderas	CORREAS EN MAL ESTADO Y ABRAZADERA	29/07/2021		Corrective Order	W/O In Planning	Telehender
637055	Manitou Mht-X1490 9t Telehand	Correa y abarzadra	CORREA Y ABAZADERA EN MAL ESTADO	29/07/2021	90013564	Corrective Order	W/O In Planning	Telehender
637057	Grove RT9130E 120TON	Cambio de cables y winche	CAMBIO DE CABLES Y WINCHE	29/07/2021	90013813	Corrective Order	W/O In Planning	Crane/Hoist
638225	Freightliner M2 106 Sucker Tru	REPARACION MAYOR (IMREPSA)	ENVIADO A IMREPSA	31/07/2021	50015017 50015454	Corrective Order	W/O In Planning	Sucker truck
638512	SJS SJ6530	REPARACIONES GENERALES	REPARACION DE EJE DE TRASLACION	01/08/2021	60021629 60021630 90011837	Corrective Order	W/O In Planning	Compactor
639123	Hilux DC	REPARAR CHASIS	POR ACCIDENTE	02/08/2021	50015344	Corrective Order	W/O In Planning	Pickup truck
639213	Caterpillar 426f2 Backhoe	CAMBIO DE COMPONENTES	LEVANTAMIENTO IASA	02/08/2021	90011127	Corrective Order	W/O In Planning	Backhoe
639381	Freightliner 8170ME Water Truc	Cambio de bolsa y lampara	CAMBIO DE BOLSA Y LAMPARA	02/08/2021	90014793	Corrective Order	W/O In Planning	Water truck
639382	International 7400 SBA Water T	Cambio de Tensores	TENSORES TRASEROS EN MAL ESTADO	03/08/2021	90014998 90017976	Corrective Order	W/O In Planning	Water truck
639971	Iveco 380t38	Reparación de cilindro cabina	CILINDRO DE CABINA DEFECTUOSO	03/08/2021	50015928	Corrective Order	W/O In Planning	Bitumen truck
639972	Caterpillar 226b Skid Steer L	Reparación de cilindro levante	CILINDRO DE LEVANTE CON FUGA	03/08/2021		Corrective Order	W/O In Planning	Skid Steer
639975	Freightliner M112 Truck Tip	Reparación de cilindros	CILINDRO DE LEVANTE CON FUGA	03/08/2021	50015953	Corrective Order	W/O In Planning	Tipper
640039	Mobile equipment	REPARACION ENGRASADORA MANIUAL	REPARACION DE TALLER	03/08/2021		Corrective Order	W/O In Planning	Area
640363	PRAMAC GSW30Y 24 kVa	TINA DE CONTENCION	TINA DE CONTENCION	04/08/2021		Corrective Order	W/O In Planning	Generator
640514	AGRICO PLOUGH 5M D900	TIRES REPLACEMENT	CORRECTIVE	04/08/2021	90016626	Corrective Order	W/O In Planning	.
640741	Caterpillar RM500 Reclaimer	TA1 INSPECCION IASA	TA1 INSPECCION DE EQUIPO	04/08/2021	90014921 90017434	Corrective Order	W/O In Planning	Road Reclaimer
641066	Hilux DC	FABRICACION INSTALACION CANOPY	TALLER DOLLAR PANAMA	05/08/2021	50015145	Corrective Order	W/O In Planning	Pickup truck
641067	Hilux DC	FABRICACION INSTALACION CANOPY	TALLER DOLLAR PANAMA	05/08/2021	50015150	Corrective Order	W/O In Planning	Pickup truck
641068	Hilux DC	FABRICACION INSTALACION CANOPY	TALLER DOLLAR PANAMA	05/08/2021	50015151	Corrective Order	W/O In Planning	Pickup truck
641237	Freightliner M2 112 Sucker Tru	CAMBIO DE VALVULA DE FRENO	CAMBIO DE VALVULA DE FRENO	05/08/2021	90011838 90016209	Corrective Order	W/O In Planning	Sucker truck
641854	Terex RT5551 55TON	Fuga de aire por el tanque	FUGA DE AIRE NEUMATICO POR EL TANQUE	06/08/2021	90014582	Corrective Order	W/O In Planning	Crane/Hoist
642535	Hyster H700 Forklift	Cambio de sección de implemento	SECCION DEL IMPLEMENTO ROTA	07/08/2021	90017703 90017791	Corrective Order	W/O In Planning	Forklift
642737	Terex RT780-1 80TON	Cable de tambor de medicion	CABLE DEL TAMBOR DE MEDICION BOOM	08/08/2021	60022826 90013664	Corrective Order	W/O In Planning	Crane/Hoist
643053	Freightliner M2 106 Refrigerat	Cambio de blower de a/c	AIRE ACONDICIONADO NO FUNCIONA	09/08/2021	90016219	Corrective Order	W/O In Planning	Refrigerator truck
643261	Caterpillar 12M	Tiene el vidrio delantero queb	TIENE EL VIDRIO DELANTERO QUEB	09/08/2021		Corrective Order	W/O In Planning	Grader
643325	Freightliner CI 120	Cambio de tubo de escape	CAMBIO DE TUBO DE ESCAPE	09/08/2021		Corrective Order	W/O In Planning	Mule truck
643329	Freightliner CI 120	Cambio de tubo de escape	CAMBIO DE TUBO DE ESCAPE	09/08/2021		Corrective Order	W/O In Planning	Mule truck
643347	Landcruiser DC	CAMBIO TRANSFER	ROTURA POR GOLPE	09/08/2021	50015249	Corrective Order	W/O In Planning	Pickup truck
643396	John Deere 9370R Tractor	AIRE ACONDICIONADO	AIRE ACONDICIONADO	09/08/2021	90017953	Corrective Order	W/O In Planning	Tractor
643520	Broderson IC200-2C 9TON	Cambio de pernos de rueda	CAMBIO DE PERNOS DE RUEDA	09/08/2021		Corrective Order	W/O In Planning	Crane/Hoist
644319	Case 110JX Tractor Cable Handl	Reemplazo de lampara y correas	REEMPLAZO DE LAMPARA TRASERAS Y CORREAS DE MOTOR	10/08/2021	90013294 90013295	Corrective Order	W/O In Planning	Tractor
644466	Freightliner 8170ME Water Truc	Cambio de correa	CORREA DEL COMPRESOR	11/08/2021		Corrective Order	W/O In Planning	Water truck
644509	Grove RT600E 50TON	Cambio de Parckin Bracke	CAMBIO DE PARKIN BRACKE	11/08/2021	90013733	Corrective Order	W/O In Planning	Crane/Hoist
644596	PB013 COASTER TOYOTA	REPARACION GENERAL	TALLER DOLLAR PENONOME	11/08/2021	50015299	Corrective Order	W/O In Planning	Bus
645369	Freightliner CI 120	Cambio de correa y tensor y ce	CAMBIO DE CORREA TENSOR Y CERRADURA	12/08/2021	90017548 90018142	Corrective Order	W/O In Planning	Mule truck
646080	Iveco 380t38	Bomba de Emulsión Trancada	BOMBA DE EMULSIÓN TRANCADA	12/08/2021	90011928	Corrective Order	W/O In Planning	Bitumen truck
646380	Freightliner 8170ME Water Truc	Cambio de mangueras de A/C	MANGUERAS ROTAS DE A/C	13/08/2021	90014800	Corrective Order	W/O In Planning	Water truck
646445	Ford F550	Bomba de sistema neumatico	BOMBA DE SISTEMA NEUMATICO EN MAL ESTADO	13/08/2021		Corrective Order	W/O In Planning	Pickup truck
646463	Caterpillar 336DL	CAMBIO DE CADENA	NECESITA AJUSTE DE CADENA Y EN	13/08/2021		Corrective Order	W/O In Planning	Excavator
646473	Mobile equipment	SERVICIO INSTALACION GPS	FASTRACK - SATRACK	13/08/2021	50015338	Corrective Order	W/O In Planning	Area
646508	LV245 HILUX TOYOTA	REPARACION GENERAL EQUIPO	TALLER DOLLAR MINA	13/08/2021	50017850	Corrective Order	W/O In Planning	Light Vehicles
646825	Broderson IC200-2C 9TON	Cambio de rines y llantas	CAMBIO DE RINES Y LLANTAS	13/08/2021	90011571	Corrective Order	W/O In Planning	Crane/Hoist
647079	Mobile equipment	DURALABEL 9000 VYNIL	PRINTER SUPPLIES	14/08/2021	90011557 90013553	Corrective Order	W/O In Planning	Area
647086	Caterpillar 12M	Temperatura alta de aceite hid	TEMPERATURA ALTA DE ACEITE HID	14/08/2021		Corrective Order	W/O In Planning	Grader
647117	Kalmar	RIMS & STUDS REPLACEMENT	CORRECTIVE	14/08/2021	50015380 50015383	Corrective Order	W/O In Planning	Telehender
647655	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/08/2021		Corrective Order	W/O In Planning	Pickup truck
647929	Unimog Service Truck	Cambio filtro de sis Retorno	FUGA DE ACEITE HIDRAULICO	15/08/2021		Corrective Order	W/O In Planning	Truck
648597	Hino Series300	REPARACION GENERAL	TALLER DOLLAR PENONOME	16/08/2021	50015418	Corrective Order	W/O In Planning	Truck
648676	Caterpillar 14M Motorgrader	Liquieo en el sello de la arti	LIQUIEO EN EL SELLO DE LA ARTI	16/08/2021	90012313	Corrective Order	W/O In Planning	Grader
648865	Hyster H700 Forklift	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	16/08/2021	90017020	Corrective Order	W/O In Planning	Forklift
649352	Atlas Copco GESAN QIS 45 47KVA	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	17/08/2021	50015802	Corrective Order	W/O In Planning	Generator
649353	SDMO T11UM 10 kVa	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	17/08/2021	50015803	Corrective Order	W/O In Planning	Generator
649467	SDMO J60U 60 kVa	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	17/08/2021	50015804	Corrective Order	W/O In Planning	Generator
649821	Caterpillar 12M Motorgrader	Cambio de llantas delanteras	CAMBIO DE LLANTAS DELANTERAS	18/08/2021		Corrective Order	W/O In Planning	Grader
649930	Landcruiser TC	REPARACION CAMIONETA RETEN	RETEN EB0275	18/08/2021		Corrective Order	W/O In Planning	Pickup truck
650612	New Holland LM 1745	MECHANICAL REPAIRS (AIRCO)	REPARADO AIRCO	19/08/2021	50016000	Corrective Order	W/O In Planning	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
650712	Terex RT5551 55TON	CRUCETA ROTA	CRUCETA ROTA	19/08/2021		Corrective Order	W/O In Planning	Crane/Hoist
651088	Hilux DC	INSTALAR PORTAESCALERA	REQUERIMIENTO NUEVO	20/08/2021	50015622	Corrective Order	W/O In Planning	Pickup truck
651378	Hyster H800 32t Forklift (M)	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	20/08/2021	90011930 90011931 90012320	Corrective Order	W/O In Planning	Forklift
651509	Freightliner Cl 120	cambio de Reservoirio de wiper	CAMBIO DE RESERVORIO DE WIPER	21/08/2021	90016801	Corrective Order	W/O In Planning	Mule truck
651859	GROVE RT600E 50TON	Cambio de radiador	CAMBIO DE RADIADOR	21/08/2021	90013863	Corrective Order	W/O In Planning	Crane/Hoist
652216	GROVE RT9130E 120TON	MAJOR REPAIRS (TECNOGRUAS)	CORRECTIVE	22/08/2021	50016727	Corrective Order	W/O In Planning	Crane/Hoist
652501	Caterpillar 12M Motorgrader	AVERÍA DEL COMPRESOR	AVERÍA DEL COMPRRESOR	22/08/2021		Corrective Order	W/O In Planning	Grader
653192	CAT 930K	BUCKET REPAIR (CIGSA)	CORRECTIVE	23/08/2021	50016194	Corrective Order	W/O In Planning	Loader
653331	Freightliner Cl 120	Cambio de valvula Relay	VALVULA RELAY CON FUGA	23/08/2021		Corrective Order	W/O In Planning	Mule truck
653716	Landcruiser DC	REPARACION CAMIONETA RETEN	RETEN CX2617	24/08/2021	50015660	Corrective Order	W/O In Planning	Pickup truck
654471	Caterpillar 12M Motorgrader	PRESENTA PROBLEMA CALENTAMIENT	PERSONAL DE IASA	25/08/2021		Corrective Order	W/O In Planning	Grader
654672	Caterpillar RM300	REEMPLAZO COMPONENTES	INSPECCIONADO POR IASA	25/08/2021	90016455	Corrective Order	W/O In Planning	Road Reclaimer
655059	Caterpillar 12M	CAMBIO DE BATERIA Y TANQUE EXP	REALIZADO POR IASA	26/08/2021		Corrective Order	W/O In Planning	Grader
655060	Manitou Mht-X860 6t Telehand	CONTROL SYSTEM REPAIR	CORRECTIVE	26/08/2021	90013270 90013403	Corrective Order	W/O In Planning	Telehender
655910	Gallegos Flatbed Trailer	BUSHING REPLACEMENT	CORRECTIVE	27/08/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
655986	Caterpillar 426F2 Backhoe	ELEMENTO DE CORTE	CAMBIO DE CUCHILLA Y TORNILLERÍA	27/08/2021		Corrective Order	W/O In Planning	Backhoe
657216	Caterpillar 426F2 Backhoe	TA1 INSPECCION MECANICA	REPORT IASA	29/08/2021	90012344 90013588	Corrective Order	W/O In Planning	Backhoe
657617	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	90014692	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657628	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	90013570	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657634	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657637	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657640	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657642	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657650	Intraax 53121 Hendrickso	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657654	Intraax 53121 Hendrickso	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657656	Intraax 53121 Hendrickso	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657659	Intraax 53121 Hendrickso	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657662	Eagle Beaver 50sgl-Pt	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021	PKG-10007350	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
657881	Mobile equipment	LAMPARAS PARA FLATBED	CAMBIO DE LAMPARAS	30/08/2021		Corrective Order	W/O In Planning	Area
657903	Terex RT5551 55TON	Cambio de selenoide y spul	SELENOIDE SPUL DE ESTABILIZADORES	30/08/2021	90015138 90016236	Corrective Order	W/O In Planning	Crane/Hoist
657933	Landcruiser DC	EVALUACION/DIAGNOSTICO EXTERNO	TALLER DOLLAR PENONOME	30/08/2021		Corrective Order	W/O In Planning	Pickup truck
657934	Hilux DC	EVALUACION/DIAGNOSTICO EXTERNO	TALLER DOLLAR PENONOME	30/08/2021		Corrective Order	W/O In Planning	Pickup truck
658484	Freightliner M2 112	IMPLEMENTACION SIS LUBRICACION	PROPUESTA THP	31/08/2021		Corrective Order	W/O In Planning	Boom truck
658540	Freightliner Cl 120	CAMBIO DE FANCLUCH	CAMBIO DE COMPONENTE	31/08/2021	90014798	Corrective Order	W/O In Planning	Mule truck
658554	Caterpillar 14M Motorgrader	INSTALAR LINER DE CABINA	REPORT DE IASA	31/08/2021	90015075 90015100	Corrective Order	W/O In Planning	Grader
658616	Iveco 380t38	Da inicio pero no arranca	DA INICIO PERO NO ARRANCA	31/08/2021		Corrective Order	W/O In Planning	Bitumen truck
658949	Caterpillar 416E	PROBLEMAS ELECTRICOS	INSPECCIONADO POR IASA	01/09/2021	90013774 90014674 90014695	Corrective Order	W/O In Planning	Backhoe
659052	Grove RT700E 60TON	TRANSMISSION REPAIR (TSI)	CORRECTIVO	01/09/2021	WAITING QUOTATION	Corrective Order	W/O In Planning	Crane/Hoist
659073	Caterpillar 740B EJ ADT	REPARACION DE TRANSFER	ENAVIADO A IASA	01/09/2021		Corrective Order	W/O In Planning	Articulated dump truck
659128	Hyster H700 Forklift	COMPONENT CHANGE OUT	CORRECTIVE	01/09/2021	90013609 90013731	Corrective Order	W/O In Planning	Forklift
659132	Hyster H700 Forklift	EVALUACION DE EQUIPO	PERSONAL DE COPAMA EVALUA	01/09/2021	90013391 90015037	Corrective Order	W/O In Planning	Forklift
659310	Hilux DC	REPARACION DAÑOS EQUIPO	TALLER DOLLAR PENONOME	01/09/2021	50017027	Corrective Order	W/O In Planning	Pickup truck
659593	Mobile equipment	ANALISIS ACEITE SEPT 21	SERVI FLOTA TACTICA // IASA	02/09/2021	50016085	Corrective Order	W/O In Planning	Area
659596	Mobile equipment	ANALISIS ACEITE OCTUBRE 21	SERVI FLOTA TACTICA // IASA	02/09/2021	50016089	Corrective Order	W/O In Planning	Area
659598	Mobile equipment	ANALISIS ACEITE NOV 21	SERVI FLOTA TACTICA // IASA	02/09/2021		Corrective Order	W/O In Planning	Area
659649	BT019 345 IVECO GRUA 6X6	Boomtruck Sin bateria	BOOMTRUCK SIN BATERIA	02/09/2021		Corrective Order	W/O In Planning	Boom truck
659690	ETNYRE QUAD	PM CAMION DE FILTROS Y ACEITE	PM CAMION DE FILTROS Y ACEITE	02/09/2021		Corrective Order	W/O In Planning	Chip Spreader
659713	Caterpillar 336DL	TA1 INSPECCION MECANICA	REPORTE DE IASA	02/09/2021		Corrective Order	W/O In Planning	Excavator
659899	Freightliner M2 106 Hydroseedi	HYDROSEEDING SYSTEM OVERHAUL	REPAIR FOR PROFILE	02/09/2021	90013597 90013598	Corrective Order	W/O In Planning	Truck
660444	Caterpillar 336DL	PROBELMAS DE INYECTOR	PERSONAL DE IASA	03/09/2021		Corrective Order	W/O In Planning	Excavator
660584	Mobile equipment	IMPLEMENTACION TALLER TACTICO	SISTEMA DE LUBRICACION	03/09/2021		Corrective Order	W/O In Planning	Area
661566	Freightliner M2 112 Sucker Tru	problema de arranque	PROBLEMA DE ARRANQUE	04/09/2021	90014591	Corrective Order	W/O In Planning	Sucker truck
661860	JLG 1850 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	05/09/2021	90016397	Corrective Order	W/O In Planning	Manlift
661871	Caterpillar 14H Motorgrader	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	05/09/2021		Corrective Order	W/O In Planning	Grader
662894	EX036 EC480DL Volvo	INST/ MANTAS TERMICAS	POSIBLE CONATO DE INCENDIOS	06/09/2021	90016341	Corrective Order	W/O In Planning	Excavator
662944	Mobile equipment	COSUMIBLES SONCAR AGOSTO 21	CONSUMIBLES AGOSTO 21	06/09/2021	50016078	Corrective Order	W/O In Planning	Area
663578	Caterpillar 740b Ej	R&I Tyre septiembre 2021	R&I TYRE SETIEMBRE 2021	07/09/2021		Corrective Order	W/O In Planning	Articulated dump truck
663625	Caterpillar 12M	REHABILITACION SIST DIRECCION	EQUIPO IASA	07/09/2021		Corrective Order	W/O In Planning	Grader
663746	Toyota Hilux	REPARACION EXTERNA	TALLER DOLLAR MINA	07/09/2021	50016099	Corrective Order	W/O In Planning	Pickup truck
663916	Freightliner M2 106 Sucker Tru	CAMBIO DE COMPONENTES	INSPECCION MECANICA	07/09/2021		Corrective Order	W/O In Planning	Sucker truck
663917	Mobile equipment	SERVICIO MTTO COPAMA OCT 21	SERVICIO MTTO COPAMA OCT 21	07/09/2021		Corrective Order	W/O In Planning	Area
663935	Grove RT700E 60TON	Equipo Pierde Fuerza	CAOMBIO DE SENSOR DE COMMON RAIL	07/09/2021		Corrective Order	W/O In Planning	Crane/Hoist
664639	Mobile equipment	Insumos para taller	INSUMOS PARA TALLER	09/09/2021		Corrective Order	W/O In Planning	Area
664664	Caterpillar 226b Skid Steer L	REEMPLAZAR BOCINA	REPORTE IASA	09/09/2021	90016459	Corrective Order	W/O In Planning	Skid Steer
664881	Broce Broom RJT 350	cambio de frenos delanteros	FRENOS DELANTEROS DESGASTADOS	09/09/2021	90016255 90016256 90016364	Corrective Order	W/O In Planning	Scrubber / Sweeper
665002	Unimog Service Truck	Cambio de componentes	CAMBIO DE COMPONENTES	09/09/2021		Corrective Order	W/O In Planning	Truck
665325	Toyota Hilux	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	W/O In Planning	Pickup truck
665331	Coaster	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	W/O In Planning	Bus

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
665345	PB012 COASTER TOYOTA	CAMBIO MOTOR ABANICO AIRE	CAMBIO ASPAS ABANICO	10/09/2021	50016248	Corrective Order	W/O In Planning	Bus
665462	Unimog Service Truck	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO Y ACEITE	10/09/2021	52592 Kms	Corrective Order	W/O In Planning	Truck
665470	Caterpillar 14H Motorgrader	Revision de equipo	REVISION DE FUGA DE ACEITE HIDRAULICA	10/09/2021	90013134 90014801	Corrective Order	W/O In Planning	Grader
665510	Caterpillar 14H Motorgrader	Revision de motor	REVISION DE FUGA DE ACEITE POR EL TURBOCOMPRESOR	10/09/2021	90014114	Corrective Order	W/O In Planning	Grader
665783	Caterpillar 140K	REACONDICIONAMIENTO DE MOTOR	EQUIPO IASA	11/09/2021		Corrective Order	W/O In Planning	Grader
666078	Hyster H70ft 3t Forklift (M)	CAMBIO DE COMPONENTES	INSPECCION DE COPAMA	11/09/2021	90014871 90014872	Corrective Order	W/O In Planning	Forklift
666175	Hino Series300	Cambio de balineras	CAMBIO DE BALINERA	11/09/2021		Corrective Order	W/O In Planning	Truck
666176	TTP-0000-102	CAMBIO DE COMPONENTE	INSPECCION IASA	11/09/2021		Corrective Order	W/O In Planning	Excavator
667192	Caterpillar 140K	REACOND CIRCLE DRIVE	PERSONAL DE IASA	13/09/2021		Corrective Order	W/O In Planning	Grader
667270	Caterpillar 740B EJ ADT	CAMBIO DE COMPONENTES	PERSONAL IASA	13/09/2021		Corrective Order	W/O In Planning	Articulated dump truck
667308	Caterpillar 416F2 Backhoe	Reemplazo de pines	REEMPLAZO DE PINES DEL BALDE	13/09/2021	90015112	Corrective Order	W/O In Planning	Backhoe
667539	JLG 450 AJ Manlift	cambio de selenoides	SELENOIDES EN MAL ESTADO	13/09/2021	90015437	Corrective Order	W/O In Planning	Manlift
667594	Mobile equipment	Insumos para taller	INSUMOS PARA TALLER	14/09/2021		Corrective Order	W/O In Planning	Area
668162	Freightliner Cl 120	Revision de equipo	REPARACION DE EQUIPO	14/09/2021	90016804 90016805	Corrective Order	W/O In Planning	Mule truck
668570	WT015 H7 CISTERNA SINOTRUK	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	15/09/2021		Corrective Order	W/O In Planning	Water truck
668572	WT013 H7 CISTERNA SINOTRUK	Cambio de base de suspensión	CAMBIO D BASE DE SUSPENSIÓN	15/09/2021		Corrective Order	W/O In Planning	Water truck
668605	Mobile equipment	HERRAMIENTAS TALLER	SOLICTADO L RUJANO	15/09/2021	90015481	Corrective Order	W/O In Planning	Area
668676	Toyota Hilux	A/C REPAIR (PCR)	CORRECTIVE	15/09/2021		Corrective Order	W/O In Planning	Pickup truck
668808	Caterpillar 740B EJ ADT	Reemplazo de componentes	REEMPLAZO DE VALVULA DE FAST FILL DE COMBUSTIBLE	15/09/2021		Corrective Order	W/O In Planning	Articulated dump truck
668899	Freightliner Cl 120	Revision de equipo	REEMPLAZO DE BOMBA DE DIRECCION Y PANEL DE INSTRUMENTOS.	15/09/2021		Corrective Order	W/O In Planning	Mule truck
668947	Hilux DC	REPARACIONES MAYORES	REPARACION DOLLAR	15/09/2021	50016367	Corrective Order	W/O In Planning	Pickup truck
669122	Caterpillar 12M	CAMBIO HERRAMIENTAS CORTE	EQUIPO IASA	16/09/2021		Corrective Order	W/O In Planning	Grader
669311	ETNYRE QUAD	cambio de valvulas	VALVULAS Y CILINDROS NEUMATICOS NO ACTIVAN	16/09/2021	90014934	Corrective Order	W/O In Planning	Chip Spreader
669330	International 7400 SBA Fire Tr	Cubierta de pito timon	CUBIERTA QUEBRADA DE PITO	16/09/2021	90017541	Corrective Order	W/O In Planning	Fire truck
669334	Hilux DC	MANTENIMIENTO	MANTENIMIENTO	16/09/2021		Corrective Order	W/O In Planning	Pickup truck
669397	Unimog Service Truck	REPARACION DE MOTOR	ENVIADO A TALLER ALFREDO	16/09/2021	50018465	Corrective Order	W/O In Planning	Truck
670006	Caterpillar 12M	CAMBIO DE SENSOR ARTICULACION	EQUIPO IASA	17/09/2021	90016887 90017542	Corrective Order	W/O In Planning	Grader
670433	Caterpillar 226b Skid Steer L	Revision de equipo	REVISION DE FALLA ELECTRICA/SWITCH DE PARKING NO FUNCIONA BIEN	19/09/2021	90014818 90014867	Corrective Order	W/O In Planning	Skid Steer
670828	Caterpillar 226b Skid Steer L	CAMBIO DE COMPONENTES	EQUIPO IASA	20/09/2021	90015948	Corrective Order	W/O In Planning	Skid Steer
670865	Caterpillar 226b Skid Steer L	CAMBIO DE COMPONENTES	EQUIPO IASA	20/09/2021	90017968	Corrective Order	W/O In Planning	Skid Steer
671008	Manitou Mht-X860 6t Telehand	REEMPLAZO DE COMPONENTES	CORRECTIVO	20/09/2021	90013545 90013546 90013765	Corrective Order	W/O In Planning	Telehender
671048	Faresin FM4000 / 17F Telehandl	Revision de equipo	REVISION DE EQUIPO	20/09/2021	90013872	Corrective Order	W/O In Planning	Telehender
671273	Mobile equipment	CHECK LIST OIL	WORK SHOP TACTICAL	20/09/2021		Corrective Order	W/O In Planning	Area
671291	Mobile equipment	LINTERNAS Y FOCOS PARA TALLER	HERRAMIENTAS DE TALLER	20/09/2021		Corrective Order	W/O In Planning	Area
671392	Grove GMK4100L 100TON	Cambio de componentes Varios	CAMBIO DE COMPONENTES VARIOS	21/09/2021		Corrective Order	W/O In Planning	Crane/Hoist
672829	Caterpillar 14H Motorgrader	cambio de lamparas	CAMBIO DE LAMPARAS	22/09/2021		Corrective Order	W/O In Planning	Grader
672861	Mobile equipment	INSUMOS TALLER PUERTO	INSUMOS TALLER PUERTO	22/09/2021		Corrective Order	W/O In Planning	Area
672886	Caterpillar 14H Motorgrader	TA1 INSPECCION MECANICA	TA1 INSPECCION MECANICA	22/09/2021		Corrective Order	W/O In Planning	Grader
672946	Caterpillar 14M Motorgrader	Tiene diesel en el depósito de	TIENE DIESEL EN EL DEPÓSITO DE	22/09/2021	90013824	Corrective Order	W/O In Planning	Grader
672951	Caterpillar 740B EJ ADT	Cambio de llantas delanteras	CAMBIO DE LLANTAS DELANTERAS	22/09/2021	90013732	Corrective Order	W/O In Planning	Articulated dump truck
673014	Mobile equipment	TOOLS FOR 2 TOOLBOXES	TOOLS	22/09/2021	90016545	Corrective Order	W/O In Planning	Area
673551	Freightliner M2 106 Hydroseedi	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	90013808	Corrective Order	W/O In Planning	Truck
673741	Unimog Service Truck	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO Y ACEITE	23/09/2021		Corrective Order	W/O In Planning	Truck
674121	Caterpillar D8T Dozer	TA1 INSPECCION MECANICA	REPORTADO IASA	24/09/2021		Corrective Order	W/O In Planning	Dozer
674226	SJS SJ6530	AXLE, RACK & ASSY REPAIRS	CORRECTIVE	24/09/2021	90013891 60023130	Corrective Order	W/O In Planning	Compactor
674271	SJS SJ6530	AXLE, RACK & ASSY REPAIRS	CORRECTIVE	24/09/2021	90013901 60023131	Corrective Order	W/O In Planning	Compactor
674277	SJS SJ6530	AXLE, RACK & ASSY REPAIRS	CORRECTIVE	24/09/2021	90013906 60023133	Corrective Order	W/O In Planning	Compactor
674289	SJS SJ6530	AXLE, RACK & ASSY REPAIRS	CORRECTIVE	24/09/2021	90013907 60023134	Corrective Order	W/O In Planning	Compactor
674312	Freightliner Cl 120	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/09/2021		Corrective Order	W/O In Planning	Mule truck
674928	Caterpillar 12M	Vidrio roto de la puerta derec	VIDRIO ROTO DE LA PUERTA DERECH	25/09/2021	90016897	Corrective Order	W/O In Planning	Grader
675386	Caterpillar 14M Motorgrader	CAMBIO DE INYECTORES	EQUIPO IASA	26/09/2021	50017055	Corrective Order	W/O In Planning	Grader
675435	New Holland Lm 1745	CYLINDER REPAIR (MASTER TECH)	CORRECTIVE	26/09/2021	50017852	Corrective Order	W/O In Planning	Telehender
675918	Manitou MTH-X 10120	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	27/09/2021	50016657 50016660	Corrective Order	W/O In Planning	Telehender
675999	Caterpillar 140K	CAMBIO DE COMPONENTES	SE LE TRANCO LA RUEDA DERECHA	27/09/2021		Corrective Order	W/O In Planning	Grader
676010	Linde T30D	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	27/09/2021	50016667 50016791	Corrective Order	W/O In Planning	Forklift
676106	Ferrari F478	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	27/09/2021	50016672	Corrective Order	W/O In Planning	Reach Stacker
676167	Kalmar	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	27/09/2021	50016675	Corrective Order	W/O In Planning	Telehender
676217	Mobile equipment	FILTER WRENCHS	TOOLS	27/09/2021	90014586	Corrective Order	W/O In Planning	Area
676683	WT015 H7 CISTERNA SINOTRUK	CAMBIO DE SUSPENSION	SUSPENSION DELANTERA Y TRASERA	28/09/2021	90014699	Corrective Order	W/O In Planning	Water truck
676848	Broderson IC200-2C 9TON	revisar ruido en tornamesa	RUIDO EN TORNA MESA	28/09/2021		Corrective Order	W/O In Planning	Crane/Hoist
677207	Unimog Service Truck	Revision de equipo	REPARACION DE ASIENTO DEL OPERADOR	29/09/2021		Corrective Order	W/O In Planning	Truck
677267	Manitou Mht-X860 6t Telehand	cambio de filtro y base	CAMBIO DE FILTRO Y BASE	29/09/2021		Corrective Order	W/O In Planning	Telehender
677795	Freightliner M112 Truck Tip	Reparaciones varias	REPARACIONES VARIAS	30/09/2021	90016244 90016245	Corrective Order	W/O In Planning	Tipper

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
677868	Gallegos 28M3 Lime Tank	Revision de equipo	REVISION DE FUGA EN LA BOTELLA	30/09/2021	90014564	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
677879	T30D LINDE	Revision de equipo	REPARACION DE DIRECCION	30/09/2021	90014978	Corrective Order	W/O In Planning	.
678001	Freightliner M2 106 Refrigerat	REPARACION MAYOR (REMUSA)	ENVIAR REMUSA	30/09/2021	50016767	Corrective Order	W/O In Planning	Refrigerator truck
678326	Freightliner M2 106 Hydroseedi	cambio de cadenas	CAMBIO DE CADENAS	01/10/2021	90014594	Corrective Order	W/O In Planning	Truck
678327	Freightliner M2 106 Hydroseedi	cambio de cadenas	CAMBIO DE CADENAS	01/10/2021	90014595	Corrective Order	W/O In Planning	Truck
678876	Caterpillar 336DL Excavator	FRAME REPLACEMENT	CORRECTIVE	01/10/2021	90014614	Corrective Order	W/O In Planning	Excavator
678981	Hyster H700 Forklift	AFTER INSPECTION CONDITION	CORRECTIVE	01/10/2021	90014794	Corrective Order	W/O In Planning	Forklift
678986	Hyster E50Z-27 FORKLIFT	AFTER INSPECTION CONDITIONS	CORRECTIVE	01/10/2021	90014790 90014791	Corrective Order	W/O In Planning	Forklift
679042	Toyota Hilux	REPARACION GENERAL EQUIPO	INSPECCION GENERAL	01/10/2021	50017145	Corrective Order	W/O In Planning	Pickup truck
679424	Freightliner 8170ME Water Truc	Hoja de muelle partida	HOJA DE MUELLE PARTIDA	02/10/2021	90014743 90017973	Corrective Order	W/O In Planning	Water truck
679694	Mobile equipment	Insumos electricos Puerto	INSUMOS ELECTRICOS PUERTO	02/10/2021		Corrective Order	W/O In Planning	Area
680273	Hyster H70ft 3t Forklift (M)	cambio de llantas	CAMBIO DE LLANTAS DELANTERAS	03/10/2021	90014849 90016290 90016740	Corrective Order	W/O In Planning	Forklift
680398	Cargador 966H Wheel Loader	PROBLEMAS DE ARRANQUE	EQUIPO NO ARRANCA	03/10/2021		Corrective Order	W/O In Planning	Loader
680891	Hilux DC	EVALUAR SISTEMA TRANSMISION	TALLER DOLLAR PENONOME	04/10/2021		Corrective Order	W/O In Planning	Pickup truck
680892	Coaster	CAMBIO VIDRIO LATERAL	CARROCERIA CON GOLPE	04/10/2021		Corrective Order	W/O In Planning	Bus
680893	Coaster	CAMBIO PARABRISAS FRONTAL	POR ROTURA	04/10/2021		Corrective Order	W/O In Planning	Bus
680895	Hilux DC	REPARACION DAÑOS EQUIPO	TECHO, PARABRISAS DETRRAME MATERIAL	04/10/2021		Corrective Order	W/O In Planning	Pickup truck
680896	Landcruiser TC	EVALUACION SISTEMA TRANSMISION	TALLER DOLLAR PENONOME	04/10/2021		Corrective Order	W/O In Planning	Pickup truck
680923	Tennant T7 Scrubber	MECHANICAL REPAIRS	CORRECTIVE	04/10/2021	90014945	Corrective Order	W/O In Planning	Scrubber / Sweeper
681020	Grove GMK4100L 100TON	cambio de sellos de estabiliza	CAMBIO DE SELLOS DE ESTABILIZADORES	05/10/2021	90016059	Corrective Order	W/O In Planning	Crane/Hoist
681620	Caterpillar D110 E2 100KVA	CAMBIO CORREA MOTOR	CORREAS DESGASTADAS	05/10/2021	OJ-732528	Corrective Order	W/O In Planning	Generator
682047	Mobile equipment	COMPRA INSTRUMENTOS GENSET	BANCO PRUEBA Y MEGGER	06/10/2021	60023264 90016554	Corrective Order	W/O In Planning	Area
682122	Freightliner Cl 120	balinera / A/A	BALINERA / A/A	06/10/2021	90016430	Corrective Order	W/O In Planning	Mule truck
682339	Caterpillar 14M Motorgrader	Cambio de vidrio de Puerta LH	CAMBIO DE VIDRIO DE PUERTA LH	06/10/2021		Corrective Order	W/O In Planning	Grader
682358	Caterpillar 140K	EQUIPO FRENADO SE CALIENTA	EQUIPO FRENADO SE CALIENTA	07/10/2021	90016239 90017406	Corrective Order	W/O In Planning	Grader
682414	Caterpillar 14H Motorgrader	Bolsa de aire rota del asient	BOLSA DE AIRE ROTA DEL ASIENT	07/10/2021		Corrective Order	W/O In Planning	Grader
682459	Unimog U3000 Truck	PEDIDO DE COMPUTADORA	PEDIDO DE COMPUTADORA	07/10/2021	90016218	Corrective Order	W/O In Planning	Truck
682463	Freightliner Columbia Cl112	Inslatacion de luces laterales	INSTALACION DE LUCES LATERALES	07/10/2021		Corrective Order	W/O In Planning	Mule truck
682654	Caterpillar 740B EJ ADT	C/LINEAS DE ENFRI DE FRENOS	LINEAS CRISTALIZADAS	07/10/2021		Corrective Order	W/O In Planning	Articulated dump truck
683077	T30D LINDE	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021	90014915 90014916	Corrective Order	W/O In Planning	.
683190	Mobile equipment	Check list de equipos	CHECK LIST DE EQUIPOS	08/10/2021	90014976	Corrective Order	W/O In Planning	Area
683405	Liugong Cpcd20	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021	90014928 90014929	Corrective Order	W/O In Planning	Forklift
683466	Phoenix MK7T	MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO Y ACEITE	08/10/2021		Corrective Order	W/O In Planning	Chip Spreader
683519	Mercedes Tipper Truck	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021	90014941	Corrective Order	W/O In Planning	Tipper
683712	Freightliner Columbia Cl112	Instalación de luces laterale	INSTALACIÓN DE LUCES LATERALES	08/10/2021		Corrective Order	W/O In Planning	Mule truck
683798	USP&E GP700/V-A 700 kVa	CAMBIO REGULADOR VOLTAJE	FALLA VOLTAJE PERMANENTE	08/10/2021	90014974	Corrective Order	W/O In Planning	Generator
684663	CAT 930K	LISTADO CABINA	CORRECTIVO	09/10/2021	90015794	Corrective Order	W/O In Planning	Loader
684681	CAT 930K	LISTADO PINES Y BEARINGS	CORRECTIVO	09/10/2021	90015798 90018143	Corrective Order	W/O In Planning	Loader
684994	Hyster H300 Forklift	AFTER INSPECTION CONDITION	CORRECTIVE	10/10/2021	90015086 90016222 90016229	Corrective Order	W/O In Planning	Forklift
685031	Hyster H300 13t Forklift (M)	AFTER INSPECTION CONDITION	CORRECTIVE	10/10/2021	90015090 90015097 90016233	Corrective Order	W/O In Planning	Forklift
685103	Hyster H800 32t Forklift (M)	AFTER INSPECTION CONDITION	CORRECTIVE	10/10/2021	90016234	Corrective Order	W/O In Planning	Forklift
685214	Manitou Mht-X1490 9t Telehand	MECHANICAL REV & REP (TECNO)	CORRECTIVE	10/10/2021	50017345	Corrective Order	W/O In Planning	Telehender
686109	JLG 450 AJ Manlift	Inspeccion de equipo	REVISAR SISTEMA HIDRAULICO, ARRANQUE, CARROCERIA	11/10/2021	90018029 90018030	Corrective Order	W/O In Planning	Manlift
686111	JLG 1250 AJP Manlift	inspeccion de equipos	REVISION DE SISTEMA DE CARGA, FUGAS DE CUILINDRO, CARROCERIA	11/10/2021	90017999 90018000 90018033	Corrective Order	W/O In Planning	Manlift
686113	JLG 450 AJ Manlift	inspeccion de equipos	SE REALIZA REVISION DE SISTEMA DE CARGA, FUGAS DE CILINDROS HIDRAULICOS, CARROCE	11/10/2021	90018031 90018032	Corrective Order	W/O In Planning	Manlift
686252	John Deere 9370R Tractor	Palanca defectuosa	PALANCA DE CAMBIO DEFECTUOSO	11/10/2021		Corrective Order	W/O In Planning	Tractor
686253	John Deere 9370R Tractor	Cambio de palanca de cambio	CAMBIO DE PALANCA DE CAMBIO	11/10/2021	90015895	Corrective Order	W/O In Planning	Tractor
686671	Hiace Bus	REPARAR SEGUROS DE PUERTA	TERMINALES INTERNOS/EXTERNOS CREMALLERA	12/10/2021	50017009	Corrective Order	W/O In Planning	Bus
686755	Freightliner M2 106 Hydroseedi	OVERHAUL MAYOR	OVERHAUL MAYOR	12/10/2021	90015161 90015162 90015163	Corrective Order	W/O In Planning	Truck
686756	Hiace Bus	CAMBIO TERMINALES LH/RH	MANTENIMIENTO CORRECTIVO	12/10/2021	50017011	Corrective Order	W/O In Planning	Bus
687056	WT015 H7 CISTERNA SINOTRUK	reemplazo de tuberia de filtro	REEMPLAZO DE TUBERIA DE FILTRO DE AIRE	12/10/2021	9006242 9006243	Corrective Order	W/O In Planning	Water truck
687122	New Holland Lm 1745	Falla Aire acondicionado	REVISION DE EQUIPO / AIRE ACONDICIONADO	12/10/2021	90015893 90016285	Corrective Order	W/O In Planning	Telehender
687700	Gallegos 28M3 Lime Tank	cambio de valvula	CAMBIO DE VALVULA	13/10/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
688357	Hyster E70xn 3t Forklift (E)	Rep. de sistema de p. Brake	FALLA EN SISTEMA DE FRENO DE ESTACIONAMIENTO	14/10/2021	90015889 90016452 90016458	Corrective Order	W/O In Planning	Forklift
688366	Mobile equipment	Cotter Pin	SEGUROS DE PINES DE GRUA	14/10/2021		Corrective Order	W/O In Planning	Area
688443	Coaster Bus	CAMBIO SUSPENSION FRONTAL	TERMINALES DIRECCION/VARIO	14/10/2021	50017078	Corrective Order	W/O In Planning	Bus
688509	Caterpillar 226b Skid Steer L	Reemplazo de componentes	REEMPLAZO DE COMPONENTES	14/10/2021	90017967	Corrective Order	W/O In Planning	Skid Steer
688527	TTP-0000-102	reparacion de cilindro	REPARACION DE CILINDRO DERECHO GEMELO	14/10/2021		Corrective Order	W/O In Planning	Excavator
688530	Caterpillar DE88EO 58 kVa	CAMBIO BOMBA INYECCION	FUGA DE COMBUSTIBLE	14/10/2021	90015665	Corrective Order	W/O In Planning	Generator
689207	Caterpillar 320DL	INSPECCION BALDE	LE FALTAN DOS CANTONERAS DEL	15/10/2021		Corrective Order	W/O In Planning	Excavator
689208	Caterpillar 320DL	Cristal de la lampara rota	ENGRASE GNERAL	15/10/2021	90017689	Corrective Order	W/O In Planning	Excavator
689325	John Deere 9370R Tractor	cambio de escolta y ductos	ESCOLTA Y DUCTOS DE A/C EN MAL ESTADO	15/10/2021	90016419 90016420	Corrective Order	W/O In Planning	Tractor
689370	Freightliner 8170ME Water Truc	varilla de servo y sensor de t	VARILLA DE SERVO Y SENSOR DE TRANSMISION	15/10/2021	90016798	Corrective Order	W/O In Planning	Water truck
689720	Caterpillar 14H Motorgrader	Reemplazo de componentes	REEMPLAZO DE COMPONENTES	16/10/2021		Corrective Order	W/O In Planning	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
689762	Freightliner M112 Truck Tip	Soporte de espejo	SOPORTE DE ESPEJO	16/10/2021	90015886	Corrective Order	W/O In Planning	Tipper
689996	Mercedes Tipper Truck	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	16/10/2021		Corrective Order	W/O In Planning	Tipper
690110	Manitou Mht-X1490 9t Telehand	cambio de retenedoras y sellos	CAMBIO DE RETENEDORAS Y SELLOS DE TANDEM TRASERO	16/10/2021	90015472	Corrective Order	W/O In Planning	Telehender
690163	Bomag BW219DH-4	instalacion de rolo y shim	INSTALACION DE ROLO Y SHIM	16/10/2021	90015884	Corrective Order	W/O In Planning	Compactor
690433	Caterpillar 320DL	Fuga de aceite hidráulico por	FUGA DE ACEITE HIDRÁULICO POR	17/10/2021	90015596	Corrective Order	W/O In Planning	Excavator
690525	WT014 H7 CISTERNA SINOTRUK	CAMBIO TRANSMISION Y BARRA DIR	CAMBIO TRANSMISION Y BARRA DIRECCION	17/10/2021		Corrective Order	W/O In Planning	Water truck
690688	Freightliner M2 106 Refrigerat	cambio de lamparas	CAMBIO DE LAMPARAS	17/10/2021	90015514	Corrective Order	W/O In Planning	Refrigerator truck
690722	WT014 H7 CISTERNA SINOTRUK	cambio de hub completo	CAMBIO DE HUB COMPLETO	17/10/2021	60023630 90015557	Corrective Order	W/O In Planning	Water truck
690786	Caterpillar 226b Skid Steer L	reparar acople de mangueras	REPARAR ACOPLE DE MANGUERA HIDRAULICA	17/10/2021		Corrective Order	W/O In Planning	Skid Steer
691135	Bell 225f 4t Forklift (M)	RETROVISOR QUEBRADO	RETROVISOR QUEBRADO	18/10/2021		Corrective Order	W/O In Planning	Forklift
691282	Boom Truck Iveco Tector	REPARACION DE CILINDRO	MASTER TECH	18/10/2021		Corrective Order	W/O In Planning	Boom truck
691295	Pramac GSW30P 24KVA	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	18/10/2021		Corrective Order	W/O In Planning	Generator
691327	Mobile equipment	ACEITE OCTIBRE 2021	TALLER TACTICO	18/10/2021		Corrective Order	W/O In Planning	Area
691393	Caterpillar 14H Motorgrader	Reemplazo de componentes	REEMPLAZO DE COMPONENTES	18/10/2021		Corrective Order	W/O In Planning	Grader
691453	Mobile equipment	SERVICIO DE MANTENIMIENTO IASA	IASA	18/10/2021		Corrective Order	W/O In Planning	Area
691842	Grove GMK4100L 100TON	Cambio de limpia Brisa	CAMBIO DE LIMPIA BRISA	19/10/2021		Corrective Order	W/O In Planning	Crane/Hoist
692037	Broce Broom RJT 350	CAMBIO DE ESCOBILLA	CAMBIO DE ESCOBILLA	19/10/2021		Corrective Order	W/O In Planning	Scrubber / Sweeper
692131	Cargador 966H Wheel Loader	CAMBIO DE COMPONENTES	BACKLOG 18 OCTUBRE IASA	19/10/2021	90015719 90015882	Corrective Order	W/O In Planning	Loader
692268	Caterpillar 236d Skid Steer L	Cambio de visagras de puerta	CAMBIO DE VISAGRAS DE PUERTAS	19/10/2021	90018288	Corrective Order	W/O In Planning	Skid Steer
692496	Caterpillar 12M	REPARACION DE PUERTA	BACKLOG 19/10/2021	20/10/2021	90015881	Corrective Order	W/O In Planning	Grader
692983	Freightliner CI 120	Cambio cinturón y asiento	CAMBIO CINTURON Y ASIENTO	20/10/2021	90016254	Corrective Order	W/O In Planning	Mule truck
692990	Grove GMK4100L 100TON	Cambio de swicht de presion de	SWICHT DE PRESION DE FRENOS EN FALLO	21/10/2021	90015803	Corrective Order	W/O In Planning	Crane/Hoist
692993	Caterpillar 416E	Reparaciones hidraulicas	REPARACIONES AL SISTEMA HIDRAULICA DEL EQUIPO.	21/10/2021	90016793 90016806	Corrective Order	W/O In Planning	Backhoe
693128	Caterpillar 416E	Reparacion de balde frontal	REPARACION DE BALDE FRONTAL	21/10/2021	90016259	Corrective Order	W/O In Planning	Backhoe
693677	Gallegos Lime Tank	cambio de lamparas traseras	CAMBIO DE LAMPARAS TRASERAS	22/10/2021	90016216	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
693688	Gallegos 28M3 Lime Tank	CAMBIO DE LAMPRAS Y AMORTI	CAMBIO DE LAMPRAS Y AMORTIGUADORES	22/10/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
693698	Caterpillar 12M	Alta temperatura del sist HYD.	SE LE SUBE LA TEMPERATURA DEL EQUIPO	22/10/2021	90016358	Corrective Order	W/O In Planning	Grader
693702	Iveco 380t38	fuga diésel por el quemador de	FUGA DIÉSEL POR EL QUEMADOR DE	22/10/2021		Corrective Order	W/O In Planning	Bitumen truck
693752	Mobile equipment	BOMBILLOS NEBLINEROS	FLOTA TACTICAL	22/10/2021		Corrective Order	W/O In Planning	Area
693791	Caterpillar 226b Skid Steer L	INSTALACION MANGUERAS	SISTEMA QUICK COUPLING	22/10/2021	90016466	Corrective Order	W/O In Planning	Skid Steer
693795	Freightliner CI 120	VELOCIMETRO	VELOCIMETRO	22/10/2021		Corrective Order	W/O In Planning	Mule truck
693840	Caterpillar 236d Skid Steer L	CAMBIO DE MANGUERAS	CONDENSANDOR A/C	22/10/2021	90016810	Corrective Order	W/O In Planning	Skid Steer
693858	Freightliner Columbia CI112	RETROVISORES	RETROVISORES	22/10/2021		Corrective Order	W/O In Planning	Mule truck
693968	Mobile equipment	IMPLEMENTAR CONTENEDOR BACKLOG	COMPRA ITEMS	22/10/2021		Corrective Order	W/O In Planning	Area
694155	Mobile equipment	ACEITE DE WORK SHOP	ACEITE DE WORK SHOP	22/10/2021		Corrective Order	W/O In Planning	Area
694243	Caterpillar CS74 Compactor	Reemplazo de componentes cabin	REEMPLAZO DE COMPONENTES DE CABINA	22/10/2021	90018273 90018274	Corrective Order	W/O In Planning	Compactor
694258	Gallegos Lime Tank	cambio de sellos y luces	CAMBIO DE SELLOS Y LUCES	23/10/2021	90015994	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
694676	Caterpillar 426F2 Backhoe	PM2-MANTENIMIENTO PREVENTIVO	EQUIPO IASA	23/10/2021	90018299	Corrective Order	W/O In Planning	Backhoe
694794	Manitou Mht-X1490 9t Telehand	Equipo Neutralizado	EQUIPO NEUTRALIZADO	23/10/2021	90016440 90016616	Corrective Order	W/O In Planning	Telehender
695009	Caterpillar 12M	FUGA HIDRAULICA	FUGA DE ACEITE HIDRAULICO	24/10/2021	90016210	Corrective Order	W/O In Planning	Grader
695115	Caterpillar 426F2 Backhoe	Cambio de Esparragos	CAMBIO DE ESPARRAGOS	24/10/2021		Corrective Order	W/O In Planning	Backhoe
695116	Caterpillar DP50 Forklift (M)	PM03-PREVENTIVE MAINTENANCE	PM03-PREVENTIVE MAINTENANCE	24/10/2021	90017814 90018034	Corrective Order	W/O In Planning	Forklift
695452	Caterpillar CW34 Compactor	Componentes de cabina	INSTALACION DE COMPONENTES CABINA Y DIRECCION.	24/10/2021	90016906	Corrective Order	W/O In Planning	Compactor
695461	Caterpillar CW34 Compactor	Reemplazo de componentes/motor	REEMPLAZO DE COMPONENTES DEL MOTOR Y DIRECCION	25/10/2021	90016908	Corrective Order	W/O In Planning	Compactor
695614	Gallegos 28M3 Lime Tank	cambio de lamparas	CAMBIO DE LAMPARAS	25/10/2021	90016208	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
695623	Manitou Mht-X860 6t Telehand	cambio de sensores	EQUIPO NO SE PUEDE CALIBRAR	25/10/2021	90016207 90016432 90016615	Corrective Order	W/O In Planning	Telehender
695625	Freightliner M2 106	Cambio de Sistema de ignicion	SISTEMA DE IGNICION DE QUEMADOR SUPERIOR NO FUNCIONA	25/10/2021	90016794	Corrective Order	W/O In Planning	Bitumen truck
695627	Gallegos Lime Tank	cambio de lamparas	CAMBIO DE LAMPARAS	25/10/2021	90016206	Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
696444	Gmc Boom Truck	fuga de aceite de TRANSMISION	FUGA DE ACEITE DE TRANSMISION	26/10/2021		Corrective Order	W/O In Planning	Boom truck
696709	Hyster H300 13t Forklift (M)	SOLID TIRES REPLACEMENT	PROACTIVE MAINTENANCE	26/10/2021	90016281	Corrective Order	W/O In Planning	Forklift
696820	Freightliner M2 106 Refrigerat	CAMBIO DE VALVULA SELENOIDE	VALVULA SELENOIDE FAN CLUTCH	26/10/2021	90017906	Corrective Order	W/O In Planning	Refrigerator truck
696839	Freightliner M112 Truck Tip	REPARACION BRAZO TENSORES SUSP	BRAZOS TENSORES SUSPENSION	26/10/2021	90016800	Corrective Order	W/O In Planning	Tipper
696886	Mobile equipment	Tanques de Oxigeno	TANQUES DE OXIGENO PARA TALLER	26/10/2021		Corrective Order	W/O In Planning	Area
697234	Freightliner CI 120	BATERIA /LUZ / RETROVISOR	BATERIA /LUZ / RETROVISOR	27/10/2021	900016385 90016386 90016791	Corrective Order	W/O In Planning	Mule truck
697312	Caterpillar 740b Ej	C/VALVULA RELIFE	VALVULA EN MAL ESTADO	27/10/2021	90016352	Corrective Order	W/O In Planning	Articulated dump truck
697362	Caterpillar CW34 Compactor	CAMBIO DE COMPONENTES	CAMBIO DE LINEAS	27/10/2021	90016359 90016799	Corrective Order	W/O In Planning	Compactor
697385	Caterpillar CW34 Compactor	CAMBIO DE COMPONENTES ASIENTO	ASIENTO	27/10/2021	90016913	Corrective Order	W/O In Planning	Compactor
697389	Kalmar	EMERGENCY CALL REPAIRS	CORRECTIVE	27/10/2021	50017580	Corrective Order	W/O In Planning	Telehender
697403	Caterpillar CW34 Compactor	CAMBIO DE LUCES	CAMBIO DE LUCES	27/10/2021		Corrective Order	W/O In Planning	Compactor
697406	Caterpillar CW34 Compactor	CAMBIO SISTEMA DE ADMISION	CAMBIO DE COMPONENTE	27/10/2021	90017972	Corrective Order	W/O In Planning	Compactor
697410	Caterpillar CW34 Compactor	CAMBIO DE COMPONENTES	CAMBIO DE COMPONENTES CAPO	27/10/2021	90017617	Corrective Order	W/O In Planning	Compactor
697514	Mobile equipment	CABIO FILTRO AIRE GENSET	JDE 5606059	27/10/2021	90016363	Corrective Order	W/O In Planning	Area
697726	Mobile equipment	consumibles kaltire septiembre	CONSUMIBLES KALTIRE SEPTIEMBRE	28/10/2021		Corrective Order	W/O In Planning	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
697801	Freightliner CI 120	Cambio de retrovisor convexo	CAMBIO DE RETROVISOR CONVEXO	28/10/2021	90016387	Corrective Order	W/O In Planning	Mule truck
697832	Hyster H700 Forklift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021	90017916	Corrective Order	W/O In Planning	Forklift
697902	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021	90017110	Corrective Order	W/O In Planning	Manlift
697914	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021	90016389	Corrective Order	W/O In Planning	Manlift
697916	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021	90016390	Corrective Order	W/O In Planning	Manlift
697949	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	W/O In Planning	Manlift
698088	Mobile equipment	Insumos Para Taller	INSUMOS PARA TALLER	29/10/2021		Corrective Order	W/O In Planning	Area
698165	Manitou Mht-X1490 9t Telehand	CAMBIO DE MUÑEQUILLA	CAMBIO DE MUÑEQUILLA	29/10/2021	90016639 90016640 90016904	Corrective Order	W/O In Planning	Telehender
698444	Caterpillar 12M Motorgrader	AJUSTE DE TORNAMESA	AJUSTE DE TORNAMESA	29/10/2021		Corrective Order	W/O In Planning	Grader
698678	Internation 4400 SBA 6x4 Boom	MAJOR REPAIRS (IMREPSA)	IMREPSA	30/10/2021	50009980 50011657 50015332	Corrective Order	W/O In Planning	Boom truck
698927	Mobile equipment	CONSUMIBLES JULIO 21 KALTIRE	CONSUMIBLES TALLER TACTICO	30/10/2021		Corrective Order	W/O In Planning	Area
699362	Mobile equipment	MULTIMETER FOR WORKSHOP	TOOLS	31/10/2021	90016633 90016634	Corrective Order	W/O In Planning	Area
699409	Landcruiser DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	31/10/2021		Corrective Order	W/O In Planning	Pickup truck
699454	Hilux DC	EVALUACION/REPARACION GENERAL	TALLER DOLLAR MINA	31/10/2021		Corrective Order	W/O In Planning	Pickup truck
699630	Unimog Service Truck	CAMBIO DE EJES DIFERENCIALES	CAMBIO DE EJES DIFERENCIALES	31/10/2021	90016598	Corrective Order	W/O In Planning	Truck
699895	Hyster H70ft 3t Forklift (M)	MAST CHAIN CHANGING	CORRECTIVE	01/11/2021	90016619	Corrective Order	W/O In Planning	Forklift
699897	Hyster H300 Forklift	CAMBIO DE PINES POR CORROSION	CAMBIO DE PINDES POR CORROSION	01/11/2021	90016527 90016618	Corrective Order	W/O In Planning	Forklift
699899	Tennant T7 Scrubber	CAMBIO DE MANGUERA RADIADOR	EQUIPO COPAMA	01/11/2021	90016790	Corrective Order	W/O In Planning	Scrubber / Sweeper
699919	Hyster H70ft 3t Forklift (M)	MAST CHAIN CHANGING	CORRECTIVE	01/11/2021	90016515 90016620	Corrective Order	W/O In Planning	Forklift
699923	Hyster H70ft 3t Forklift (M)	STEERING SYSTEM REPAIRS	CORRECTIVE	01/11/2021	90016516 90017274 90017903	Corrective Order	W/O In Planning	Forklift
699950	Hyster E70xn 3t Forklift (E)	SIDE MIRROR REPLACEMENT	CORRECTIVE	01/11/2021	90016517	Corrective Order	W/O In Planning	Forklift
700032	Mobile equipment	TOOLS FOR 2 TOOLBOXES	TOOLS	01/11/2021	90016546 90016549	Corrective Order	W/O In Planning	Area
700033	Mobile equipment	TOOLS FOR 2 TOOLBOXES	TOOLS	01/11/2021	90016547 90016551	Corrective Order	W/O In Planning	Area
700035	Mobile equipment	TOOLS FOR 1 TOOLBOX	TOOLS	01/11/2021	90016548	Corrective Order	W/O In Planning	Area
700053	Olympian GEP 88-3 64 kVa	RESTAURACION TUBO ESCAPE	LIJADO Y PINTURA	01/11/2021	50017752	Corrective Order	W/O In Planning	Generator
700167	Ford Hilux D/C Light Vehicle	REPARACION GENERAL	TALLER DOLLAR PENONOME	01/11/2021	50017756	Corrective Order	W/O In Planning	Pickup truck
700174	Ford Ranger	EVALUACION/DIAGNOSTICO DOLLAR	TALLER DOLLAR	01/11/2021		Corrective Order	W/O In Planning	Pickup truck
700518	Coaster	A/C	PROBLEMAS EN LOS SECADORESY CONDENSADOR	02/11/2021	43431.00	Corrective Order	W/O In Planning	Bus
700774	Unimog Service Truck	CAMBIO DE COMPONENTES	CAMBIO DE COMPONENTES	02/11/2021	60024797	Corrective Order	W/O In Planning	Truck
700827	Freightliner FL112	REPARACION MAYOR (REMUSA)	EQUIPO EN PANAMA / REMUSA	02/11/2021	50017789	Corrective Order	W/O In Planning	Boom truck
700849	Mobile equipment	GRASA PARA CAMIONES	GRASA PARA CAMOINES	02/11/2021	90016789	Corrective Order	W/O In Planning	Area
700900	Freightliner M2 106 Hydroseedi	CAMBIO DE GRAMPAS	CAMION HIDROSIEMBRA	02/11/2021	90016787	Corrective Order	W/O In Planning	Truck
700963	JLG 450 AJ Manlift	Revision de equipo	REVISION DE EQUIPO	02/11/2021		Corrective Order	W/O In Planning	Manlift
700979	Landcruiser TC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	02/11/2021		Corrective Order	W/O In Planning	Pickup truck
701213	Mobile equipment	GRASA PARA EQUIPO CAT	EQUIPO IASA	03/11/2021		Corrective Order	W/O In Planning	Area
701365	New Holland Lm 1745	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/11/2021		Corrective Order	W/O In Planning	Telehender
701372	New Holland Lm 1745	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/11/2021	90016662	Corrective Order	W/O In Planning	Telehender
701379	JLG T350 Manlift	PM3 PREVENTIVE MAINTENANCE	PM3 PREVENTIVE MAINTENANCE	03/11/2021	90016668	Corrective Order	W/O In Planning	Manlift
701389	ATR-0000-001 4+320 AGRICO	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	03/11/2021		Corrective Order	W/O In Planning	Tractor
701395	John Deere 9370R Tractor	PM1-MANTENIMIENTO PREVENTIVO	PM1-MANTENIMIENTO PREVENTIVO	03/11/2021	90016678	Corrective Order	W/O In Planning	Tractor
701399	John Deere 9370R Tractor	PM2-MANTENIMIENTO PREVENTIVO	PM2-MANTENIMIENTO PREVENTIVO	03/11/2021	90016686	Corrective Order	W/O In Planning	Tractor
701421	John Deere 9370R Tractor	PM2-MANTENIMIENTO PREVENTIVO	PM2-MANTENIMIENTO PREVENTIVO	03/11/2021	90016694	Corrective Order	W/O In Planning	Tractor
701433	John Deere 9370R Tractor	PM2-MANTENIMIENTO PREVENTIVO	PM2-MANTENIMIENTO PREVENTIVO	03/11/2021	90016697	Corrective Order	W/O In Planning	Tractor
701434	John Deere 9370R Tractor	PM2-MANTENIMIENTO PREVENTIVO	PM2-MANTENIMIENTO PREVENTIVO	03/11/2021	90017460	Corrective Order	W/O In Planning	Tractor
701441	Case 110JX Tractor Cable Handl	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	03/11/2021		Corrective Order	W/O In Planning	Tractor
701507	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/11/2021	90016708 90016707	Corrective Order	W/O In Planning	Manlift
701521	Freightliner M2 106 Hydroseedi	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	03/11/2021		Corrective Order	W/O In Planning	Truck
701650	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/11/2021	90016713 90016714	Corrective Order	W/O In Planning	Manlift
701683	Coaster	CAMBIO DE RADIADOR	GOLPE RADIADOR	03/11/2021		Corrective Order	W/O In Planning	Bus
701816	Caterpillar 236d Skid Steer L	REEMPLAZO DE ACOUPLE	REEMPLAZO DE ACOUPLE RAPIDO DE BALDE	04/11/2021	90016716	Corrective Order	W/O In Planning	Skid Steer
701925	Caterpillar 14H Motorgrader	MONTAJE DEL EJE DELANTERO	MONTAJE DEL EJE DELANTERO	04/11/2021		Corrective Order	W/O In Planning	Grader
701943	Caterpillar 236d Skid Steer L	Reemplazo de varilla de motor	REEMPLAZO DE VARILLA DE MEDICION DE ACEITE DE MOTOR	04/11/2021		Corrective Order	W/O In Planning	Skid Steer
702051	Mobile equipment	Contencion para IBC Puerto	PALLETTs DE CONTENCION IBC PUERTO	04/11/2021	90016737	Corrective Order	W/O In Planning	Area
702214	Internation 4400 SBA 6x4 Boom	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	04/11/2021		Corrective Order	W/O In Planning	Boom truck
702246	Gmc Boom Truck	REPARACIÓN DE TRANSMISIÓN	ENVIO A REPARACION A	04/11/2021	50018049 50018477	Corrective Order	W/O In Planning	Boom truck
702250	Gmc Boom Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	04/11/2021		Corrective Order	W/O In Planning	Boom truck
702277	International F2674	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	04/11/2021		Corrective Order	W/O In Planning	Boom truck
702292	Freightliner FL112 Boom Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	04/11/2021		Corrective Order	W/O In Planning	Boom truck
702299	Freightliner FL112 Boom Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	04/11/2021		Corrective Order	W/O In Planning	Boom truck
702309	JLG T350 Manlift	PM1 PREVENTIVE MAINTENANCE	PM1 PREVENTIVE MAINTENANCE	04/11/2021	90016776	Corrective Order	W/O In Planning	Manlift
702329	Caterpillar Tl1055clrc	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	04/11/2021		Corrective Order	W/O In Planning	Telehender
702333	Caterpillar TL642	PM01-PREVENTIVE MAINTENANCE	PM01-PREVENTIVE MAINTENANCE	04/11/2021	90016782	Corrective Order	W/O In Planning	Telehender
702335	Caterpillar TL642	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	04/11/2021	90016783	Corrective Order	W/O In Planning	Telehender
702338	Caterpillar TL1055CLRC	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	04/11/2021	90016784	Corrective Order	W/O In Planning	Telehender
702386	Manitou Mht-X860 6t Telehand	Reparación de diferencial	REPARACIÓN DE DIFERENCIAL	04/11/2021	90016964 90016969 90017661	Corrective Order	W/O In Planning	Telehender
702486	Freightliner CI 120	Reparación de tubo de escape	CAMBIO DE TUBO DE ESCAPE	05/11/2021	90016785 90016786 90017545	Corrective Order	W/O In Planning	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
702552	Mobile equipment	HERRAMIENTAS TALLER/MAZOS	HERRAMIENTAS	05/11/2021	90016795 90016796	Corrective Order	W/O In Planning	Area
702596	Caterpillar TL1055CLRC	PM01-PREVENTIVE MAINTENANCE	PM0-PREVENTIVE MAINTENANCE	05/11/2021	90016802	Corrective Order	W/O In Planning	Telehender
702637	Freightliner M2 106 Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021	90016817 818 819 820	Corrective Order	W/O In Planning	Boom truck
702649	Mack Trucks GU	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021	90016825 90016824	Corrective Order	W/O In Planning	Boom truck
702666	Boom Truck Iveco Tector	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Boom truck
702678	Caterpillar 740B EJ ADT	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Articulated dump truck
702680	Caterpillar 740B EJ ADT	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Articulated dump truck
702684	Caterpillar 740B EJ ADT	PM03,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Articulated dump truck
702778	Caterpillar 336DL	PM2,MANTENIMIENTO PREVENTIVO	PM2,MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Excavator
702800	Manitou Mht-X860 6t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016888	Corrective Order	W/O In Planning	Telehender
702814	Manitou Mht-X860 6t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	05/11/2021	90016891	Corrective Order	W/O In Planning	Telehender
702816	Caterpillar 12M	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	W/O In Planning	Grader
702818	Manitou Mht-X860 6t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016893	Corrective Order	W/O In Planning	Telehender
702821	Manitou Mht-X860 6t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	05/11/2021	90016894	Corrective Order	W/O In Planning	Telehender
702826	Manitou Mht-X860 6t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016895	Corrective Order	W/O In Planning	Telehender
702828	Manitou Mht-X860 6t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	05/11/2021	90016896	Corrective Order	W/O In Planning	Telehender
702845	Caterpillar 336DL Excavator	silenciador partido	RAVIZA SILENCIADOR PARTIDO, FUGA DE DIESEL, PROBLEMA ELECTRICO, FUGA DE ACEITE	05/11/2021	90016922	Corrective Order	W/O In Planning	Excavator
702846	Hyster H300 Forklift	HAND PUMP REPLACEMENT	CORRECTIVE	05/11/2021	90017403	Corrective Order	W/O In Planning	Forklift
702864	JLG T350 Manlift	PM3 PREVENTIVE MAINTENANCE	PM3 PREVENTIVE MAINTENANCE	05/11/2021	90016907	Corrective Order	W/O In Planning	Manlift
702866	JLG T350 Manlift	PM1 PREVENTIVE MAINTENANCE	PM1 PREVENTIVE MAINTENANCE	05/11/2021	90016910	Corrective Order	W/O In Planning	Manlift
702874	Manitou MTH-X 10120	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016914	Corrective Order	W/O In Planning	Telehender
702894	Manitou MTH-X 10120	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	05/11/2021	90016917	Corrective Order	W/O In Planning	Telehender
702910	Manitou Mht-X1490 9t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016920	Corrective Order	W/O In Planning	Telehender
702913	Manitou Mht-X1490 9t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	05/11/2021		Corrective Order	W/O In Planning	Telehender
702915	Manitou Mht-X1490 9t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016925	Corrective Order	W/O In Planning	Telehender
702916	Manitou Mht-X1490 9t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016926	Corrective Order	W/O In Planning	Telehender
702917	Manitou Mht-X1490 9t Telehand	PM4-PREVENTIVE MAINTENANCE	PM4-PREVENTIVE MAINTENANCE	05/11/2021	90016927	Corrective Order	W/O In Planning	Telehender
702918	Grove RT9130E 120TON	cambio de valvula	CAMBIO DE VALVULAS	05/11/2021	90016957	Corrective Order	W/O In Planning	Crane/Hoist
703286	Freightliner Columbia CI112	LUZ QUEMADA+BATERIAS	LUZ QUEMADA	06/11/2021		Corrective Order	W/O In Planning	Mule truck
703327	Caterpillar 416F2 Backhoe	Neumatico cortado (Flat)	NEUMATICO CORTADO (FLAT)	06/11/2021	90017217	Corrective Order	W/O In Planning	Backhoe
703334	Caterpillar CS533E Compactor	Cambio de tambor	TAMBOR RAJADO	06/11/2021		Corrective Order	W/O In Planning	Compactor
703338	Manitou Mht-X1490 9t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	06/11/2021		Corrective Order	W/O In Planning	Telehender
703439	Caterpillar TL642	PM01-PREVENTIVE MAINTENANCE	PM01-PREVENTIVE MAINTENANCE	06/11/2021	90017001	Corrective Order	W/O In Planning	Telehender
703440	Caterpillar TL642	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	06/11/2021	90017002	Corrective Order	W/O In Planning	Telehender
703443	Manitou MHT10180L Telehandler	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	06/11/2021	90017003	Corrective Order	W/O In Planning	Telehender
703444	Manitou MHT10180L Telehandler	PM2-PREVENTIVE MAINTENANCE	PM2-PREVENTIVE MAINTENANCE	06/11/2021	90017004	Corrective Order	W/O In Planning	Telehender
703459	Tennant S30 Sweeper	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	06/11/2021		Corrective Order	W/O In Planning	Scrubber / Sweeper
703474	Caterpillar TL1055CLRC	Reemplazo de terminales de dir	REEMPLAZO DE TERMINALES DE DIRECCION	06/11/2021	90017009	Corrective Order	W/O In Planning	Telehender
703500	Manitou Mht-X1490 9t Telehand	compra de mangueras danadas	COMPRA DE MANGUERAS DANADAS	06/11/2021	90017012 60024207	Corrective Order	W/O In Planning	Telehender
703624	New Holland Lm 1745	reparación de diferencial	REPARACIÓN DE DIFERENCIAL	06/11/2021		Corrective Order	W/O In Planning	Telehender
703792	Grove RT880E 75TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017028	Corrective Order	W/O In Planning	Crane/Hoist
703820	Hyster H800 32t Forklift (M)	SOLENOID VALVE REPLACEMENT	CORRECTIVE	07/11/2021	90017034	Corrective Order	W/O In Planning	Forklift
703861	TCM FGH25D	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017053	Corrective Order	W/O In Planning	Forklift
703874	TCM FGH25D	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017058	Corrective Order	W/O In Planning	Forklift
703881	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017059	Corrective Order	W/O In Planning	Manlift
703885	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017060	Corrective Order	W/O In Planning	Manlift
703888	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017061 90017062	Corrective Order	W/O In Planning	Manlift
703891	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017064 90017065	Corrective Order	W/O In Planning	Manlift
703897	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017068 90017069	Corrective Order	W/O In Planning	Manlift
703918	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017074 90017075	Corrective Order	W/O In Planning	Manlift
703922	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017078 90017079	Corrective Order	W/O In Planning	Manlift
703983	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017083 90017084	Corrective Order	W/O In Planning	Manlift
703990	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017086 90017087	Corrective Order	W/O In Planning	Manlift
704000	Terex RT5551 55TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017089	Corrective Order	W/O In Planning	Crane/Hoist
704003	Terex RT5551 55TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017091	Corrective Order	W/O In Planning	Crane/Hoist
704121	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017114 90017115	Corrective Order	W/O In Planning	Manlift
704160	Freightliner M112 Truck Tip	cambio de perilla de alta y ba	CAMBIO DE PERILLA DE ALTA Y BAJA	07/11/2021	90017125	Corrective Order	W/O In Planning	Tipper
704161	Hyster H700 Forklift	CAMBIO 6 LLANTAS	CORRECTIVO	07/11/2021	90017124	Corrective Order	W/O In Planning	Forklift
704182	Linde T30D	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017128 90017129	Corrective Order	W/O In Planning	Forklift
704184	Caterpillar D8T Dozer	Instalacion de enfriador HYD	INSTALACION DE ENFRIADOR HIDRAULICO	07/11/2021	90017429 PKG-10008295 90018144	Corrective Order	W/O In Planning	Dozer
704207	T30D LINDE	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017130 90017131	Corrective Order	W/O In Planning	.
704210	T30D LINDE	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017132 90017133	Corrective Order	W/O In Planning	.
704226	JLG 800 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017138 90017139 90017140	Corrective Order	W/O In Planning	Manlift
704233	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017141 90017142	Corrective Order	W/O In Planning	Manlift
704238	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017145 90017146	Corrective Order	W/O In Planning	Manlift
704239	Caterpillar 12M	Reemplazo de tuberias de hoja	REEMPLAZO DE TUBERIAS DEL SIDESHIFT	07/11/2021	90017148	Corrective Order	W/O In Planning	Grader
704244	Grove RT700E 60TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021	90017151 90017152	Corrective Order	W/O In Planning	Crane/Hoist

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
704405	Logistic and Transport Area 22	Limpieza de areas verdes	LIMPIEZA GENERAL	08/11/2021	Requiere limpieza	Corrective Order	W/O In Planning	Building
704420	Heliport Offices	Reparacion de pintura	REPARACION DE PINTURA	08/11/2021	Se requiere reparaciones WO.	Corrective Order	W/O In Planning	Building
704424	Heliport Offices	Pintura del Helipuerto	PINTURA DEL HELIPUERTO	08/11/2021	Se requiere reparaciones WO.	Corrective Order	W/O In Planning	Building
704489	Terex RT780-1 80TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/11/2021		Corrective Order	W/O In Planning	Crane/Hoist
704501	Grove GMK4100L 100TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/11/2021	90017165	Corrective Order	W/O In Planning	Crane/Hoist
704745	Caterpillar 416F2 Backhoe	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	08/11/2021	90017218 90017219	Corrective Order	W/O In Planning	Backhoe
704756	Grove RT700E 60TON	HOUSING DE VOLANTE REPAIR (TA)	CORRECTIVE	08/11/2021	50018309	Corrective Order	W/O In Planning	Crane/Hoist
704996	LT134 D1005 DOOSAN	CAMBIO INTERRUPTOR/CORREA	CAMBIO LAMPARA /BATERIA	08/11/2021		Corrective Order	W/O In Planning	Light Tower
705407	Caterpillar D110 E2 110 kVa	CAMBIO DE BOMBA DE INYECCION	CAMBIO DE BOMBA DE INYECCION, GOBERNADOR PROGRAMADO & INYECTORES	09/11/2021		Corrective Order	W/O In Planning	Generator
705810	Manitou Mht-X860 6t Telehand	Sensor de filtro de aire	SENSOR DE FILTRO DE AIRE	09/11/2021	90017854	Corrective Order	W/O In Planning	Telehender
705841	Caterpillar 14M Motorgrader	Llanta rajada	LLANTA RAJADA	09/11/2021		Corrective Order	W/O In Planning	Grader
706000	Freightliner M112 Truck Tip	CAMBIO DE COMPONENTES	CAMBIO DE COMPONENTES	09/11/2021	90017338 90017339 60024322	Corrective Order	W/O In Planning	Tipper
706159	Caterpillar 14H Motorgrader	CAMBIO DE COMPONENTES	CAMBIO DE COMPONENTES	09/11/2021	90017354	Corrective Order	W/O In Planning	Grader
706163	Ford F550	CAMBIO DE CONTROL	PUMPMOSS PRESSURE GOVERNOR	09/11/2021		Corrective Order	W/O In Planning	Pickup truck
706384	Internation 4400 SBA 6x4 Boom	PM MANTENIMIENTO GRUA	MANTENIMIENTO GRUA	10/11/2021		Corrective Order	W/O In Planning	Boom truck
706441	Manitou Mht-X1490 9t Telehand	cambio de interruptor de trans	CAMBIO DE INTERRUPTOR DE TRANSFER	10/11/2021	90017546	Corrective Order	W/O In Planning	Telehender
706498	Freightliner 8170ME Water Truc	CAMBIO DE SENSORES	CAMBIO DE SENSORES	10/11/2021		Corrective Order	W/O In Planning	Water truck
706652	WT013 H7 CISTERNA SINOTRUK	cambio de bomba de agua	CAMBIO DE BOMBA DE AGUA	10/11/2021	90017404	Corrective Order	W/O In Planning	Water truck
706689	Gallegos Flatbed Trailer	ESTANDARIZACION DE LUCES	ESTANDARIZACION DE LUCES	10/11/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
706702	Gallegos Flatbed Trailer	ESTANDARIZACION DE LUCES	ESTANDARIZACION DE LUCES	10/11/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
706708	Gallegos Flatbed Trailer	ESTANDARIZACION DE LUCES	ESTANDARIZACION DE LUCES	10/11/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
706711	Gallegos Flatbed Trailer	ESTANDARIZACION DE LUCES	ESTANDARIZACION DE LUCES	10/11/2021		Corrective Order	W/O In Planning	Trailer / Flatbed / Lime Tank
706905	Mobile equipment	WORKSHOP BULB	INSUMOS ELECTRICOS TALLER	11/11/2021	90017407	Corrective Order	W/O In Planning	Area
706964	Caterpillar 12M	Pin que sostiene la muñequilla	PIN QUE SOSTIENE LA MUÑEQUILLA	11/11/2021	90017474	Corrective Order	W/O In Planning	Grader
707066	Kobelco CKE2500E 250TON	Cambio de modulo	CAMBIO DE MODULO	11/11/2021		Corrective Order	W/O In Planning	Crane/Hoist
707084	Mobile equipment	MATERIAL DE OFICINA TALLER	MATERIAL DE OFICINA TALLER	11/11/2021		Corrective Order	W/O In Planning	Area
707209	Hyster H300 Forklift	CAMBIO DE CABLE DE BATERIA	CAMBIO DE CABLE DE BATERIA	11/11/2021	90017742	Corrective Order	W/O In Planning	Forklift
707624	Landcruiser TC	REVISAR FRENO DE EMERGENCIA	REVISAR FRENO DE EMERGENCIA	12/11/2021		Corrective Order	W/O In Planning	Pickup truck
707631	Landcruiser DC	REPARAR AIRE ACONDICIONADO	REPARAR AIRE ACONDICIONADO	12/11/2021		Corrective Order	W/O In Planning	Pickup truck
707635	Coaster	REPARAR FRENO ESCAPE	REPARAR FRENO ESCAPE	12/11/2021		Corrective Order	W/O In Planning	Bus
707641	Coaster	PROBLEMA DE SUSPENSION	PROBLEMA SUSPENSION	12/11/2021		Corrective Order	W/O In Planning	Bus
707645	Coaster	REPARAR RETARDOR	REPARAR RETARDOR	12/11/2021		Corrective Order	W/O In Planning	Bus
707648	Coaster	REVISAR LUCES TABLERO	ABS/LUZ DE FRENO MANO/ACEITE MOTOR	12/11/2021		Corrective Order	W/O In Planning	Bus
707650	Coaster	INSPECCIONAR PUERTAS	NO CIERRAN BIEN	12/11/2021		Corrective Order	W/O In Planning	Bus
707926	Caterpillar 14M Motorgrader	CAMBIO DE COMPONENTES	TA1 PM04	12/11/2021		Corrective Order	W/O In Planning	Grader
708108	Mobile equipment	SERVICIO MTTO COPAMA NOV 21	SERVICIO MTTO COPAMA OCT 21	12/11/2021		Corrective Order	W/O In Planning	Area
708126	LB002 725 CAT	mangueras,tapones y accesorio	MANGUERAS,TAPONES Y ACCESORIO	12/11/2021		Corrective Order	W/O In Planning	Truck
708228	Manitou MTH-X 10120	Reparacion de equipo	LEVANTAMIENTO DE INFORMACION PARA REPARACION	12/11/2021	90017727 90017728 90017855	Corrective Order	W/O In Planning	Telehender
708316	Freightliner Cl 120	Reemplazo de componentes	REEMPLAZO DE TABLERO	13/11/2021		Corrective Order	W/O In Planning	Mule truck
708424	Atlas Copco Xas300 Dd	PM MANTENIMIENTO 500 HORAS	KIT MANTENIMIENTO	13/11/2021		Corrective Order	W/O In Planning	Compressor
708773	TTP-0000-102	cambio de casquillos	CAMBIO DE CASQUILLOS	13/11/2021		Corrective Order	W/O In Planning	Excavator
708779	Freightliner Cl 120	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	W/O In Planning	Mule truck
708809	Hyster H700 Forklift	reparacion de motor	REPARACION DE MOTO	13/11/2021		Corrective Order	W/O In Planning	Forklift
708847	Unimog Service Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	W/O In Planning	Truck
708852	Unimog Service Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021	90017580	Corrective Order	W/O In Planning	Truck
708873	Unimog Service Truck	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	W/O In Planning	Truck
708882	New Holland Lm 1745	Equipo bloqueado por alarma	EQUIPO BLOQUEADO POR ALARMA	13/11/2021		Corrective Order	W/O In Planning	Telehender
709148	Mobile equipment	enviase de muestras de aceite	ENVIASE DE MUESTRAS DE ACEITE	13/11/2021		Corrective Order	W/O In Planning	Area
709155	Manitou MHT10180L Telehandler	INSPECCIÓN PRE-ENTREGA	INSPECCIÓN DE PRE-ENTREGA	13/11/2021	90017934 90017935 90018027	Corrective Order	W/O In Planning	Telehender
709161	TTP-0000-102	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021	90017599	Corrective Order	W/O In Planning	Excavator
709190	Caterpillar 226b Skid Steer L	Reemplazo de rin danado	REEMPLAZO DE RIN DANADO	13/11/2021	90017658	Corrective Order	W/O In Planning	Skid Steer
709194	JLG 800 AJ Manlift	Reemplazo de motor de arranque	REEMPLAZO DE MOTOR DE ARRANQUE	13/11/2021		Corrective Order	W/O In Planning	Manlift
709467	EX036 EC480DL Volvo	C/BATERIAS	C/BATERIAS	14/11/2021		Corrective Order	W/O In Planning	Excavator
709555	Caterpillar CS74 Compactor	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	14/11/2021		Corrective Order	W/O In Planning	Compactor
709888	Freightliner M2 106 Hydroseedi	Problemas con el embrague	PROBLEMAS CON EL EMBRAGUE	14/11/2021		Corrective Order	W/O In Planning	Truck
710275	Caterpillar TL642	CAMBIO CILINDRO COMPENSACION	TA1 EQUIPO IASA	15/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
710303	Caterpillar 12M	cambio de componentes	CAMBIO DE COMPONENTES	15/11/2021		Corrective Order	W/O In Planning	Grader
710343	Caterpillar 14M Motorgrader	Cambio de componenets d direcc	CMBIO DE COMPONENTES DE DIRECCION	15/11/2021		Corrective Order	W/O In Planning	Grader
710352	Caterpillar CS533E Compactor	Reparacion de sist. de traslac	REPARACION DE SISTEMA DE VIBRACION Y TRASLACION	15/11/2021		Corrective Order	W/O In Planning	Compactor
710364	Caterpillar TL642	CAMBIO DE COMPONENTES	CILINDRO EXTENSION	15/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
710397	Caterpillar TL642	FIRST BOOM PADS	TA1 EQUIPO IASA	15/11/2021		Corrective Order	W/O In Planning	Telehender
710475	Caterpillar 336DL Excavator	cambio de componentes	CAMBIO DE COMPONENTES	15/11/2021		Corrective Order	W/O In Planning	Excavator
710487	Caterpillar D6T LGP	REPARACION MAYOR (IASA)	BASTIDOR-RODILLOS-FRAME	15/11/2021		Corrective Order	W/O In Planning	Dozer
710892	John Deere 9370R Tractor	cambio de compresor de a/c	CAMBIO DE COMPRESOR DE A/C	15/11/2021	90017990	Corrective Order	W/O In Planning	Tractor
710902	Caterpillar 12M	cambio de cover	COVER DEL FILTRO HIDRAULICO EN MAL ESTADO	15/11/2021		Corrective Order	W/O In Planning	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
710904	Freightliner M2 106 Sucker Tru	Fuga Neumática y Chumacera	FUGA NEUMÁTICA Y CHUMACERA	15/11/2021		Corrective Order	W/O In Planning	Sucker truck
710939	Manitou Mht-X1490 9t Telehand	REP DIFERENCIAL (TECNOGRUAS)	CORECTIVO	15/11/2021	50018251	Corrective Order	W/O In Planning	Telehender
710945	Caterpillar 226b Skid Steer L	Fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO POR EL ENFRIADOR.	15/11/2021		Corrective Order	W/O In Planning	Skid Steer
711257	New Holland Lm 1745	Revision de fugas hidraulicas	REVISION DE FUGAS HIDRAULICAS DEL EQUIPO.	16/11/2021	90017913 90018036	Corrective Order	W/O In Planning	Telehender
711464	Mobile equipment	CHAIN WEAR SCALE TOOL	CHAIN WEAR SCALE TOOL	16/11/2021	90017900 90017901	Corrective Order	W/O In Planning	Area
711519	PB003 COASTER TOYOTA	REPARACION MAYOR (DOLLARS)	CHAPITERIA,EMBRAGUE	16/11/2021		Corrective Order	W/O In Planning	Bus
711568	Caterpillar TL642	CAMBIO DE COMPONENTE	ENGINE	16/11/2021	90017738	Corrective Order	W/O In Planning	Telehender
711577	Caterpillar TL642	CAMBIO DE COMPONENTES CABINA	CAB	16/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
711610	Caterpillar TL642	CAMBIO MANGUERA HIDRAULICA	HYDO	16/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
711618	Caterpillar TL642	CAMBIO DE COMPONENTE FUEL TANK	FUEL TANK	16/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
711628	Caterpillar TL642	CAMBIO DE COMPONENTES FRAME	FRAME	16/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
711641	Caterpillar TL642	CAMBIO DE COMPONENTES	FRONT AXLE	16/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
711706	Caterpillar 236d Skid Steer L	Cambio de Shut Down	CAMBIO DE SHUT DOWN	17/11/2021	90017904	Corrective Order	W/O In Planning	Skid Steer
711923	Caterpillar TL642	CAMBIO DE COMPONENTES	REAR AXLE	17/11/2021		Corrective Order	W/O In Planning	Telehender
712102	AGRICO PLOUGH 5M D900	GENERAL REPAIRS	CORRECTIVE	17/11/2021	90017907 90017943	Corrective Order	W/O In Planning	.
712134	Caterpillar TL642	CAMBIO DE COMPONENTES	SECOND BOOM	17/11/2021	pkg-10008338	Corrective Order	W/O In Planning	Telehender
712143	Caterpillar TL642	CAMBIO DE COMPONENTES	LIFT CYLINDER	17/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
712162	Caterpillar TL642	CAMBIO DE COMPONENTES	SWAY CYLINDER	17/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
712170	Caterpillar TL642	CAMBIO DE COMPONENTES	TRANSMISION	17/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
712192	Caterpillar TL642	CAMBIO DE COMPONENTES	THIRD BOOM PADS	17/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
712217	Caterpillar TL642	CAMBIO DE COMPONENTES	SECOND BOOM	17/11/2021	PKG-10008338	Corrective Order	W/O In Planning	Telehender
712253	Caterpillar 226b Skid Steer L	CAMBIO DE COMPONENTES	CAMBIO DE PARTES DE RADIADOR	17/11/2021	90018043	Corrective Order	W/O In Planning	Skid Steer
712255	Caterpillar TL642	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	17/11/2021		Corrective Order	W/O In Planning	Telehender
712282	Caterpillar 416F2 Backhoe	REEMPLAZO DE PUNTAS	REPARACION DE AIRE ACONDICIONADO	17/11/2021		Corrective Order	W/O In Planning	Backhoe
712299	Freightliner M2 106 Sucker Tru	Cambio de bolsa de cabina	CAMBIO DE BOLSA DE AIRE DE CABINA	17/11/2021	90018041	Corrective Order	W/O In Planning	Sucker truck
712627	Caterpillar DP50 Forklift (M)	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	18/11/2021	90017818 90017819	Corrective Order	W/O In Planning	Forklift
712654	Caterpillar DP50 Forklift (M)	PM03-PREVENTIVE MAINTENANCE	PM03-PREVENTIVE MAINTENANCE	18/11/2021	90017820 90018035	Corrective Order	W/O In Planning	Forklift
712668	Caterpillar DP50 Forklift (M)	PM02-PREVENTIVE MAINTENANCE	PM02-PREVENTIVE MAINTENANCE	18/11/2021	90017822 90017823	Corrective Order	W/O In Planning	Forklift
712683	Caterpillar D6T Dozer	CAMBIO DE COMPONENTES	SISTEMA DE RODADO	18/11/2021	90018042	Corrective Order	W/O In Planning	Dozer
712842	Caterpillar 416F2 Backhoe	INSTALACION DE SEGUROS VENTANA	POSTERIOR LADO DERECHO	18/11/2021	90017838	Corrective Order	W/O In Planning	Backhoe
712850	Caterpillar 416F2 Backhoe	REEMPLAZO PIN CILINDRO BOOM	REEMPLAZO PIN CILINDRO BOOM	18/11/2021	90018040	Corrective Order	W/O In Planning	Backhoe
712889	Mobile equipment	herramientas de taller, Puerto	HERRAMIENTAS PARA TLLER PUERTO Y MINA	18/11/2021		Corrective Order	W/O In Planning	Area
712928	JLG 800 AJ Manlift	Falla con aceleración	PEDAL DE ACELERACIÓN DEFECTUOSO	18/11/2021	90017848	Corrective Order	W/O In Planning	Manlift
712975	Mobile equipment	GATOS HIDRAULICOS PARA TALLER	HERRAMIENTAS	18/11/2021	60024759 PKG-10008386	Corrective Order	W/O In Planning	Area
712998	Isuzu NMR85L	No le funciona el A/C	NO LE FUNCIONA EL A/C	18/11/2021		Corrective Order	W/O In Planning	Truck
713008	ETNYRE QUAD	joystick de control de avance	JOYSTICK DE CONTROL DE AVANCE	18/11/2021		Corrective Order	W/O In Planning	Chip Spreader
713312	Mobile equipment	Arbol Navideño	ARBOL NAVIDEÑO	19/11/2021		Corrective Order	W/O In Planning	Area
713327	Grove GMK 4080 80TON	Inspección del Equipo	INSPECCIÓN DEL EQUIPO	19/11/2021		Corrective Order	W/O In Planning	Crane/Hoist
713347	Grove RT600E 50TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017856 90017858 90018157	Corrective Order	W/O In Planning	Crane/Hoist
713351	Grove RT600E 50TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017859 90017860 90017861	Corrective Order	W/O In Planning	Crane/Hoist
713386	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017866	Corrective Order	W/O In Planning	Manlift
713388	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017867	Corrective Order	W/O In Planning	Manlift
713396	Caterpillar 416E	PM04 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	19/11/2021		Corrective Order	W/O In Planning	Backhoe
713397	Caterpillar 236d Skid Steer L	Reparacion de base de extintor	REPARACION DE BASE DE EXTINTOR	19/11/2021		Corrective Order	W/O In Planning	Skid Steer
713400	Toyota Hilux	STARTING MOTOR REPAIRS (PCR)	CORRECTIVE	19/11/2021	50018327	Corrective Order	W/O In Planning	Pickup truck
713443	Mobile equipment	AGENDAS 2022	PERSONAL SUPERVISOR	19/11/2021	90017872	Corrective Order	W/O In Planning	Area
713457	New Holland Lm 1745	CYLINDER REPAIRS (MASTER TECH)	CORRECTIVE	19/11/2021	WAITING QUOTATION	Corrective Order	W/O In Planning	Telehender
713543	Grove RT890 90TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017886 90017887	Corrective Order	W/O In Planning	Crane/Hoist
713554	Kobelco CE2500E 250TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021	90017891	Corrective Order	W/O In Planning	Crane/Hoist
713988	Caterpillar 236d Skid Steer L	Cambio de manija de puerta	CAMBIO DE MANIJA DE PUERTA	20/11/2021		Corrective Order	W/O In Planning	Skid Steer
714196	Unimog Service Truck	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	20/11/2021	90017954	Corrective Order	W/O In Planning	Truck
714293	TTP-0000-102	EVALUACION CONDICION TA2	REPARACION MAYOR IASA PANAMA	20/11/2021	50018363	Corrective Order	W/O In Planning	Excavator
714302	Freightliner Columbia CI112	Reparar cerraduras	REPARAR CERRADURAS	20/11/2021		Corrective Order	W/O In Planning	Mule truck
714316	Freightliner CI 120	cambio de tanque de expansion	CAMBIO DE TANQUE DE EXPANSION	20/11/2021	PKG-10008431	Corrective Order	W/O In Planning	Mule truck
714322	Hyster H300 Forklift	Cambio de caliper de frenos	FALLA FRENOS ESTACIONAMIENTO	20/11/2021	PKG-10008412	Corrective Order	W/O In Planning	Forklift
714323	Hyster H300 13t Forklift (M)	Cambio de cilindro de gancho	VASTAGO DE CILINDRO TORCIDO	20/11/2021	90017963 PKG-10008412	Corrective Order	W/O In Planning	Forklift
714584	JLG 1250 AJP Manlift	Inspección de Equipo	INSPECCIÓN DE EQUIPO	21/11/2021		Corrective Order	W/O In Planning	Manlift
714608	Caterpillar 236d Skid Steer L	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	W/O In Planning	Skid Steer
714619	Hyster E70xn 3t Forklift (E)	CONVERTIDOR DC DC	CONVERTIDOR DC DC	21/11/2021		Corrective Order	W/O In Planning	Forklift
714621	CAT 930K	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021	90017970	Corrective Order	W/O In Planning	Loader
714626	Bomag BW219DH-4	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	W/O In Planning	Compactor
714672	WT015 H7 CISTERNA SINOTRUK	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	W/O In Planning	Water truck
714688	LV205 RANGER FORD	Cambio de llantas	CAMBIO DE LLANTAS EN MAL ESTADO	21/11/2021		Corrective Order	W/O In Planning	Light Vehicles
714709	Cargador 966H Wheel Loader	REPARACION ESCALERA Y OTROS	BACKLOG IASA	21/11/2021	90018015 PKG-10008426	Corrective Order	W/O In Planning	Loader
714748	Freightliner CI 120	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	W/O In Planning	Mule truck
714750	Freightliner Columbia CI112	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	W/O In Planning	Mule truck
714922	Pit Operations Offices	Mantenimiento	MANTENIMIENTO	21/11/2021	W48	Corrective Order	W/O In Planning	Building

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
715305	Caterpillar 226b Skid Steer L	CAMBIO DE EXTINTOR	CAMBIO DE POSSICIÓN DEL EXTINTOR		22/11/2021			Corrective Order	W/O In Planning	Skid Steer
715319	CAT 930K	sin tapa de la batería	SIN TAPA DE LA BATERÍA		22/11/2021	PKG-10008447		Corrective Order	W/O In Planning	Loader
715455	New Holland Lm 1745	CONFECCIONES MANGUERA	CONFECCIONES MANGUERA		22/11/2021			Corrective Order	W/O In Planning	Telehender
716702	Freightliner Cl 120	FUGA DE AIRE / PUERTA	FUGA DE AIRE / PUERTA		24/11/2021			Corrective Order	W/O In Planning	Mule truck
716710	Ford 450	ENGINE REPAIR (TALL. ALFREDO)	CORRECTIVE		24/11/2021	50018466		Corrective Order	W/O In Planning	Pickup truck
716808	Mobile equipment	Cargador de batería y arrancad	CARGADOR DE BATERIA Y ARRANCADORES		24/11/2021	60024844 PKG-10008437		Corrective Order	W/O In Planning	Area
716840	Grove RT600E 50TON	cambio de asiento	CAMBIO DE ASIENTO		24/11/2021	90018177		Corrective Order	W/O In Planning	Crane/Hoist
716879	Freightliner Cl 120	Cambio Tanque de expansión	CAMBIO DE TANQUE DE EXPANSION		24/11/2021	90018196		Corrective Order	W/O In Planning	Mule truck
716880	Freightliner Cl 120	Cambio de Tanque de expansión	CAMBIO DE TANQUE DE EXPANSION		24/11/2021	90018188		Corrective Order	W/O In Planning	Mule truck
716881	Freightliner Cl 120	Cambio de tanque de expansion	CAMBIO DE TANQUE DE EXPANSION		24/11/2021	90018192		Corrective Order	W/O In Planning	Mule truck
716883	Freightliner Cl 120	Cambio de tanque de expansion	CAMBIO DE TANQUE DE EXPANSION		24/11/2021	90018189		Corrective Order	W/O In Planning	Mule truck
716885	Freightliner Cl 120	Cambio de tanque de expansion	CAMBIO DE TANQUE DE EXPANSION		24/11/2021	90018191		Corrective Order	W/O In Planning	Mule truck
716893	Grove GMK4100L 100TON	Cambio de filtros de motores	CAMBIO DE FILTROS DE MOTORES		24/11/2021	PKG-10008439		Corrective Order	W/O In Planning	Crane/Hoist
716896	Kalmar	MECHANICAL REPAIRS (GPE)	CORRECTIVE		24/11/2021	50018495		Corrective Order	W/O In Planning	Telehender
716899	Grove GMK4100L 100TON	Cambio de tuerca de llanta	CAMBIO DE TUERCA DE LLANTA		24/11/2021	PKG-10008439		Corrective Order	W/O In Planning	Crane/Hoist
716971	Internation 4400 SBA 6x4 Boom	cambio de maquinas de vidrio	CAMBIO DE MAQUINAS DE VIDRIO		24/11/2021	PKG-10008444		Corrective Order	W/O In Planning	Boom truck
717274	Case 110JX Tractor Cable Handl	cambio de vidrio	CAMBIO DE VIDRIO		25/11/2021	90018223 90018241		Corrective Order	W/O In Planning	Tractor
717294	Heliport Offices	REP DE BRAZO DE PUERTA	REP DE BRAZO HIDRAULICO		25/11/2021			Corrective Order	W/O In Planning	Building
717326	General Mod Quad Buildings	REP. DE BANO	URINAL DANADO		25/11/2021			Corrective Order	W/O In Planning	Building
717490	Logistic and Transport Area 22	CERRRADURA DE BANO	CERRRADURA DE BANO		25/11/2021			Corrective Order	W/O In Planning	Building
717498	Logistic and Transport Area 22	CAMBIO DE CERRADURA	CERRADURA COMEDOR		25/11/2021			Corrective Order	W/O In Planning	Building
717501	Logistic and Transport Area 22	REP. PASA MANOS MADERA	REP. PASA MANOS MADERA		25/11/2021			Corrective Order	W/O In Planning	Building
717524	Logistic and Transport Area 22	REP. PISO MADERA	REP. PISO MADERA		25/11/2021			Corrective Order	W/O In Planning	Building
717527	Valle Grande Area	Instalar Compresor - OT Padre	INSTALAR COMPRESOR - OT PADRE		25/11/2021			Corrective Order	W/O In Planning	.
717624	Grove GMK 4080 80TON	cambio de Flexiplate	FLEXIPLATE DAÑADO		25/11/2021			Corrective Order	W/O In Planning	Crane/Hoist
717856	Pit Operations Offices	limpieza de maleza	LIMPIEZA DE MALEZA		26/11/2021			Corrective Order	W/O In Planning	Building
717915	Caterpillar 336DL	Reparacion de comp. de cabina	REPARACION DE COMPONENTES DE CABINA		26/11/2021			Corrective Order	W/O In Planning	Excavator
717939	Caterpillar CS74 Compactor	Sapos ligeramente rajados	SAPOS LIGERAMENTE RAJADOS		26/11/2021			Corrective Order	W/O In Planning	Compactor
718082	Mobile equipment	BOMBS MANUALES GENSET	LIMPIEZA DE RADIADORES		26/11/2021			Corrective Order	W/O In Planning	Area
718091	Freightliner M112 Truck Tip	cambio de sistema de susp. tra	CAMBIO DE SISTEMA DE SUSP. TRASERA		26/11/2021			Corrective Order	W/O In Planning	Tipper
600888	Terex RT780-1 80TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600890	Terex RT670 64TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600891	Shuttlelift RTCD5540F 15TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600892	Shuttlelift RTCD5540F 15TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600893	Broderson IC200-2C 9TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600894	GROVE GMK 2035E 35TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Crane/Hoist
600895	JLG 1250 AJP Manlift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Manlift
600898	Manitou Mht-X860 6t Telehand	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Telehender
600899	New Holland LM 1745	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Telehender
600900	Bell 225f 4t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Forklift
600901	Bell 225f 4t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Forklift
600902	Caterpillar DP50 Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Forklift
600903	Hyster H700 Forklift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Forklift
600904	Hyster H700 Forklift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Forklift
600905	JLG 450 AJ Manlift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA		02/06/2021			PM Orders	WO Ready to Schedule	Manlift
601619	Hiace Bus	CAMBIO PARABRISAS FRONTAL	TALLER DOLLAR PENONOME		03/06/2021			Corrective Order	WO Ready to Schedule	Bus
603172	PRAMAC GSW80P 83KVA	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION		06/06/2021			PM Orders	WO Ready to Schedule	Generator
604985	Hiace Bus	CAMBIO LAMPARA TRASERA	POR ROTURA		09/06/2021			Corrective Order	WO Ready to Schedule	Bus
604987	Hiace Bus	REPARAR PUERTA TRASERA	NO ABRE		09/06/2021			Corrective Order	WO Ready to Schedule	Bus
604988	Hiace Bus	CAMBIAR CINTURON DELANTERO	NO FUNCIONA		09/06/2021			Corrective Order	WO Ready to Schedule	Bus
605297	LV268 HINO TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		10/06/2021			PM Orders	WO Ready to Schedule	Light Vehicles
606445	Toyota Hilux	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS		12/06/2021			Corrective Order	WO Ready to Schedule	Pickup truck
607210	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607213	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607221	Olympian GEP 88-3 64 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607222	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607224	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607227	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607228	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607229	SDMO K12UM 11KVA	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607236	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607238	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607239	Olympian GEP18-6 18 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607241	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D		13/06/2021			PM Orders	WO Ready to Schedule	Generator
607638	PRAMAC GSW460V 460 kVa	CAMBIO PLACA DIODOS	EQUIPO INOPERATIVO		14/06/2021	90009283		Corrective Order	WO Ready to Schedule	Generator
609249	HINO Xzu710I-QkfmI3	CAMBIO CLUTCH	MANTENIMIENTO CORRECTIVO		17/06/2021			Corrective Order	WO Ready to Schedule	Pickup truck
609279	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		17/06/2021			PM Orders	WO Ready to Schedule	Bus
609303	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		17/06/2021			PM Orders	WO Ready to Schedule	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
609311	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Ready to Schedule	Bus
609313	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Ready to Schedule	Bus
609875	USP&E GP700S/V-A 700 kVa	CAMBIO PLACA DIODOS	MANTENIMIENTO CORRECTIVO	18/06/2021	90009289	Corrective Order	WO Ready to Schedule	Generator
610457	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021		PM Orders	WO Ready to Schedule	Generator
612426	PRAMAC GSW560V 407 kVa	COMPRA GENERADOR ECO401L/4	MANTENIMIENTO PROGRAMADO	22/06/2021	90009438	Corrective Order	WO Ready to Schedule	Generator
612638	Caterpillar 426f2 Backhoe	Radiador y aspas roto	RADIADOR Y ASPAS ROTO	23/06/2021	90009656	Corrective Order	WO Ready to Schedule	Backhoe
613422	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Pickup truck
613423	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Pickup truck
613424	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Pickup truck
613426	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Pickup truck
613441	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Bus
613442	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Ready to Schedule	Bus
615286	USP&E GP700/V-A 700 kVa	CAMBIO TURBOCARGADOR	FUGA ACEITE POR TURBOS	27/06/2021	90011720 90011155 90011156	Corrective Order	WO Ready to Schedule	Generator
615597	CAT 930K	TA1 INSPECCION EQUIPO	REVISION DE EQUIPO IIASA	27/06/2021	90013995	Corrective Order	WO Ready to Schedule	Loader
617712	Bomag BW219DH-4	CAMBIO DENEUMATICOS	NECESITA NEUMATICOS	01/07/2021		Corrective Order	WO Ready to Schedule	Compactor
619120	PRAMAC GSW330V 315 kVa	PM PRA GSW330V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021		PM Orders	WO Ready to Schedule	Generator
619139	Olympian GEP150 135 kVa	PM OLY GEP 150 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021		PM Orders	WO Ready to Schedule	Generator
621904	Grove RT9130E 120TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	07/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
623479	Terex MAC25 25TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	09/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
623669	Hilux DC	CAMBIO PARABRISAS FRONTAL	RAJADURA LADO COPILOTO	09/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
623670	Toyota Hilux	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	09/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
623698	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
623723	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
623728	PB003 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Ready to Schedule	Bus
625175	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021		PM Orders	WO Ready to Schedule	Generator
625177	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021		PM Orders	WO Ready to Schedule	Generator
625179	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021		PM Orders	WO Ready to Schedule	Generator
625195	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021		PM Orders	WO Ready to Schedule	Generator
625630	Grove RT700E 60TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	12/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
627534	Hyster E70xn 3t Forklift (E)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Forklift
627535	Hyster E70xn 3t Forklift (E)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Forklift
627536	Hyster H800 32t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Forklift
627537	Grove RT890 90TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
627538	GROVE RT600E 50TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
627539	GROVE RT700E 60TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	15/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
627621	Hilux DC	INSTALAR CINTURON PASAJEROS	CAMBIO POR DETERIORO	15/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
627950	Landcruiser DC	CAMBIO PERTIGA	DAÑO PERDIGA / EXTINTOR CADUCA	15/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
628712	Manitou Mht-X860 6t Telehand	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	17/07/2021		PM Orders	WO Ready to Schedule	Telehender
629217	Hyster H70ft 3t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	18/07/2021		PM Orders	WO Ready to Schedule	Forklift
629218	Hyster H70ft 3t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	18/07/2021		PM Orders	WO Ready to Schedule	Forklift
629219	Hyster H300 13t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	18/07/2021		PM Orders	WO Ready to Schedule	Forklift
629697	Hyster H800 32t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	19/07/2021		PM Orders	WO Ready to Schedule	Forklift
629698	Terex RT5551 55TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	19/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
630348	Hyster H70ft 3t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	20/07/2021		PM Orders	WO Ready to Schedule	Forklift
630349	Hyster H300 13t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	20/07/2021		PM Orders	WO Ready to Schedule	Forklift
630350	Hyster H800 32t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	20/07/2021		PM Orders	WO Ready to Schedule	Forklift
631007	GROVE RT530E 30TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	21/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
631008	Kobelco CKE2500E 250TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	21/07/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
631009	Hyster H70ft 3t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	21/07/2021		PM Orders	WO Ready to Schedule	Forklift
632201	Bell 225f 4t Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	23/07/2021		PM Orders	WO Ready to Schedule	Forklift
632202	Caterpillar DP50 Forklift (M)	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	23/07/2021		PM Orders	WO Ready to Schedule	Forklift
632743	PRAMAC GSW705V 770 kVa	CAMBIO DE FRECUENCIA Y VOLTAJE	CORRECTIVO PROGRAMADO	23/07/2021		Corrective Order	WO Ready to Schedule	Generator
632949	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
632952	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
632958	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
633569	PRAMAC GSW705V 770 kVa	PM PRA GSW705V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021		PM Orders	WO Ready to Schedule	Generator
634208	Hilux DC	CAMBIO PARABRISAS FRONTAL	CORRECTIVO PROGRAMADO	25/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
634836	Coaster	CAMBIO BATERIA	EVALUAR SISTEMA ELECTRICO	26/07/2021		Corrective Order	WO Ready to Schedule	Bus
635714	Hilux DC	GPS INSTALLING	TRACKING SYSTEM	27/07/2021		Corrective Order	WO Ready to Schedule	Pickup truck
635732	Caterpillar 735B	FLUSHING MF1 MF2 DIF2	FLUSHING MF1 MF2 DIF2	27/07/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
636799	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
636803	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Ready to Schedule	Pickup truck
636818	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Ready to Schedule	Bus
637982	Atlas Copco Hilight V5	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021		Corrective Order	WO Ready to Schedule	Light Tower
639323	Toyota Hilux	CAMBIO EXTINTOR	NO TIENE	02/08/2021		Corrective Order	WO Ready to Schedule	Pickup truck
639793	Toyota Hilux	CAMBIO LIMPIAPARABRISAS	DANADOS	03/08/2021		Corrective Order	WO Ready to Schedule	Pickup truck
639794	Toyota Hilux	ASEGURAR SOPORTE BATERIA	SOPORTE MAL ESTADO	03/08/2021		Corrective Order	WO Ready to Schedule	Pickup truck
639795	Toyota Hilux	CAMBIO AMORTIGUADORES	REVISION DE DISCOS FRENOS	03/08/2021		Corrective Order	WO Ready to Schedule	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
641194	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
641197	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
641208	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
641826	Caterpillar D110 E2 110 KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021		PM Orders	WO Ready to Schedule	Generator
641827	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021		PM Orders	WO Ready to Schedule	Generator
641833	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021		PM Orders	WO Ready to Schedule	Generator
642018	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021		PM Orders	WO Ready to Schedule	Light Tower
642019	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021		PM Orders	WO Ready to Schedule	Light Tower
642022	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021		PM Orders	WO Ready to Schedule	Light Tower
642023	Atlas Copco HILIGHT V5 Light T	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021		PM Orders	WO Ready to Schedule	Light Tower
642905	Coaster	CAMBIO ALARMA RETROCESO	AJUSTE FRENO SERVICIO Y PARQUEO	08/08/2021		Corrective Order	WO Ready to Schedule	Bus
643389	SDMO J60U 60KVA	CAMBIO RETENEDORAS	FUGA ACEITE	09/08/2021		Corrective Order	WO Ready to Schedule	Generator
646573	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
646579	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
646583	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
646594	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
646611	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Ready to Schedule	Bus
647994	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
647995	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
647996	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
648001	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
648013	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Ready to Schedule	Bus
650333	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	19/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651600	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651839	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651857	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651862	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651867	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
651873	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Bus
651875	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Ready to Schedule	Bus
653769	SDMO J60U 60KVA	O-RING AND GASKET REPLACE	CORRECTIVE MAINTENANCE	24/08/2021	90012946	Corrective Order	WO Ready to Schedule	Generator
654722	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
654725	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
654727	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Ready to Schedule	Pickup truck
654735	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Ready to Schedule	Bus
654740	Hino Serie 300 Box Truck	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Ready to Schedule	Truck
655739	Caterpillar 740B EJ ADT	DESGASTE POS 5,6	POR CONDICION	27/08/2021	PROG DEL 30 AGOST AL 05 SEP	Corrective Order	WO Ready to Schedule	Articulated dump truck
656529	Landcruiser TC	CAMBIO ARO NEUMATICO	CAMBIO 01 RIN	28/08/2021	90012372	Corrective Order	WO Ready to Schedule	Pickup truck
657056	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021		PM Orders	WO Ready to Schedule	Generator
658955	Landcruiser TC	EVALUAR SISTEMA FRENO	ALARMA DE FRENO ACTIVADA	01/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
659452	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	02/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
659689	Toyota Hilux	REVISAR TABLERO ADVERTENCIA	SE MANTIENE ENCENDIDA	02/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
660490	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
660491	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
660492	Coaster Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Ready to Schedule	Bus
660493	Coaster Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Ready to Schedule	Bus
660499	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
661012	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	04/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
661290	Caterpillar 740b Ej	REEM/ RECEPTOR LLENADO COMBUST	FUGA	04/09/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
661295	Caterpillar 740b Ej	REEM/ BUJE BARRA SUSPENSION RH	DESGASTE	04/09/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
661300	Caterpillar 740b Ej	C/ COJINETE INF CYL SUSP RH/LH	DESGASTE	04/09/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
661428	Caterpillar 735B	DESGASTE POS 3	DESGASTE POS 3	04/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
661429	Caterpillar 735B	DESGASTE POS 4	R&I TYRE POS 4	04/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
661430	Caterpillar 735B	DESGASTE POS 5	DESGASTE POS 5	04/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
661431	Caterpillar 735B	DESGASTE PO 6	DESGASTE PO 6	04/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
661433	Caterpillar 735B	DESGASTE POS 6	DESGASTE POS 6	04/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
662021	PRAMAC GSW110 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021		PM Orders	WO Ready to Schedule	Generator
662023	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021		PM Orders	WO Ready to Schedule	Generator
662026	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021		PM Orders	WO Ready to Schedule	Generator
663445	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	07/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
663557	Caterpillar 740B EJ ADT	R&I Tyre septiembre 2021	R&I TYRE SEPTIEMBRE 2021	07/09/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
663589	LV074 RANGER FORD	REPARACION GENERAL	TALLER DOLLAR MINA	07/09/2021	50017036	Corrective Order	WO Ready to Schedule	Light Vehicles
665512	LV162 RANGERS SC FORD	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Light Vehicles
665580	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
665586	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
665588	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
665593	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Bus
665594	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Bus

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
665600	LV268 HINO TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Ready to Schedule	Truck
666013	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021		PM Orders	WO Ready to Schedule	Generator
666428	EX036 EC480DL Volvo	REEM/ HARNES DE INJECTOR MOTOR	REQUIERE CAMBIO	12/09/2021		Corrective Order	WO Ready to Schedule	Excavator
666890	Intraax 53121 Hendrickso	Reacondicionamiento de frenos	REACONDICIONAMIENTO DE FRENOS	12/09/2021		Corrective Order	WO Ready to Schedule	Trailer / Flatbed / Lime Tank
666910	Caterpillar 416F2 Backhoe	Instalacion de cable del boom	INSTALACION DEL CABLE DE TRANSPORTE DEL BOOM.	12/09/2021		Corrective Order	WO Ready to Schedule	Backhoe
667204	Caterpillar 416F2 Backhoe	CAMBIO DE COMPONENTES	EQUIPO IASA	13/09/2021		Corrective Order	WO Ready to Schedule	Backhoe
667593	Hilux DC	REPARAR LUZ FRONTAL	INSTALAR GPS	13/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
669042	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	16/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
670346	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	19/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
670487	SDMO J60U 60 kVa	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021		PM Orders	WO Ready to Schedule	Generator
670539	USP&E GP700/V-A 700 kVa	PRUEBA FUNCIONAL GENERADORES	ARRANQUE E INSPECCION QUINCENAL	19/09/2021		PM Orders	WO Ready to Schedule	Generator
671969	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	21/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673738	Manitou Mht-X1490 9t Telehand	Fuga de aceite	FUGA DE ACEITE, MAMNGUERA ROTA	23/09/2021		Corrective Order	WO Ready to Schedule	Telehender
673752	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673754	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673764	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673773	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673775	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673776	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673780	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673781	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
673795	Hino Serie 300 Box Truck	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Ready to Schedule	Truck
673917	Grove RT650E 45TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	24/09/2021		PM Orders	WO Ready to Schedule	Crane/Hoist
674311	Caterpillar 740B EJ ADT	OBTENER STATUS REPORT	OBTENER STATUS REPORT	24/09/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
675370	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021		PM Orders	WO Ready to Schedule	Light Tower
675472	Hilux DC	CAMBIO FORROS ASIENOS	POR DESGASTE Y TIEMPO USO	26/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
675932	Landcruiser DC	AJUSTE SISTEMA DE FRENOS	FRENO DE PARQUEO Y DE SERVICIO	27/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
676222	Hilux DC	CAMBIO LUZ DELANTERA LH	LUZ QUEMADA	27/09/2021		Corrective Order	WO Ready to Schedule	Pickup truck
677847	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	30/09/2021		PM Orders	WO Ready to Schedule	Pickup truck
678457	Landcruiser TC	REVISAR SISTEMA TRANSMISION	PRIMERA MARCHA NO FUNCIONA	01/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
678459	Landcruiser TC	REPARAR PUERTA POSTERIOR	NO ABRE	01/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
678469	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678470	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678473	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678478	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678479	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678484	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678485	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Bus
678487	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678488	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678491	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Bus
678492	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Bus
678493	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678494	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678500	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678501	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678502	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678503	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678505	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678506	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
678509	Hino Series300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Truck
678511	Toyota Land Cruiser	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
679193	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	02/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
680124	Caterpillar 740b Ej	REEMP/ DE EMPAQUE DE MOTOR	FUGA DE ACEITE	03/10/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
680216	Pramac GSW30P 24KVA	PM1 PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021		PM Orders	WO Ready to Schedule	Generator
680237	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021		Corrective Order	WO Ready to Schedule	Light Tower
680900	PB015 COASTER TOYOTA	REPARACION GENERAL EQUIPO	TALLER DOLLAR MINA	04/10/2021	50016862 50017585	Corrective Order	WO Ready to Schedule	Bus
680916	Coaster	REVISAR SEÑAL GPS	FALSA SEÑAL	04/10/2021		Corrective Order	WO Ready to Schedule	Bus
682150	HT164 740B CAT	Compra de llantas octubre	COMPRA DE LLANTAS OCTUBRE	06/10/2021		Corrective Order	WO Ready to Schedule	Truck
682452	Ford Ranger Sc	A/C INSPECTION & REPAIR	NO ENFRIA	07/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
682599	Caterpillar 740B	R&I Suspension Cylinder Left F	R&I SUSPENSION CYLINDER LEFT FRONT	07/10/2021		PM Orders	WO Ready to Schedule	Articulated dump truck
682613	Caterpillar 740B EJ ADT	C/BEARING AR GFRAME CENTRAL	REQUIERE CAMBIO	07/10/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
682624	Caterpillar 740B EJ ADT	C/BEARING AR FRAME POSTERIOR	PRESENTA DESGASTE	07/10/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
682761	Ford Hilux D/C Light Vehicle	AJUSTE SISTEMA DE FRENOS	FRENO DE MANO Y SERVICIO	07/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
683070	Ford Hilux D/C Light Vehicle	CAMBIO PARABRISAS FRONTAL	CAMBIO DE CINTURONES	08/10/2021	50017331	Corrective Order	WO Ready to Schedule	Pickup truck
683076	Ford Hilux D/C Light Vehicle	CAMBIO CINTURONES SEGURIDAD	REPONER ACCESORIOS	08/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
683079	Ford Hilux D/C Light Vehicle	REPONER HERRAMIENTAS/EXTINTOR	REPONER LLANTA DE REPUESTO	08/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
683081	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683082	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683085	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683086	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683087	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683090	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
683649	Landcruiser TC	CAMBIO BOCINA	BCINA EN MAL ESTADO	08/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
683690	Landcruiser TC	CAMBIO ALARMA RETROCESO	NO FUNCIONA	08/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
685081	PRAMAC GSW170i 164 kVa	PM1 PRA GSW170i MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021		PM Orders	WO Ready to Schedule	Generator
685085	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021		PM Orders	WO Ready to Schedule	Light Tower
685090	DOOSAN C185	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021		Corrective Order	WO Ready to Schedule	Compressor
686513	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	12/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
686722	Ford Hilux D/C Light Vehicle	REPARAR ALARMA RETROCESO	EVALUACION ELCTRICA	12/10/2021	50017756	Corrective Order	WO Ready to Schedule	Pickup truck
686868	Coaster Bus	A/C INSPECTION & REPAIR	NO ENFRIA	12/10/2021		Corrective Order	WO Ready to Schedule	Bus
687162	Manitou Mht-X860 6t Telehand	Cambio de motor de ventilador	CAMBIO DE MOTOR DE VENTILADOR	13/10/2021	90015199	Corrective Order	WO Ready to Schedule	Telehender
687387	Landcruiser TC	AJUSTE CORREA ALTERNADOR	CAMBIO BATERIA	13/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
687567	Hilux DC	CAMBIO FARO POSTERIOR	CRACKED REAR DRIVER SIDE LIGHT	13/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
687931	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	13/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
688029	Mobile equipment	Insumos de taller	INSUMOS DE TALLER	13/10/2021		Corrective Order	WO Ready to Schedule	Area
689071	Hyndai HD65	ARRANQUE EQUIPO	VEHICULO NO ENCIENDE	15/10/2021		Corrective Order	WO Ready to Schedule	Truck
689434	Landcruiser DC	A/C INSPECTION & REPAIR	REPARACION DE AC	15/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
689436	Landcruiser DC	A/C INSPECTION & REPAIR	REPARACION DE AC	15/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
689443	SDMO T16 16KVA	CAMBIO RETENEDORA DELANTERA	FUGA DE ACEITE	15/10/2021	90016457	Corrective Order	WO Ready to Schedule	Generator
689602	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	16/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
689958	Caterpillar 336DL Excavator	Reemplazo de tapones	REEMPLAZO DE TAPONES DE LOS MANDOS FINALES	16/10/2021		Corrective Order	WO Ready to Schedule	Excavator
690146	Ford Hilux D/C Light Vehicle	CAMBIO TERMINALES DIRECCION	CAMBIO DE PIEZAS DE UNIDAD	16/10/2021	50017756	Corrective Order	WO Ready to Schedule	Pickup truck
690151	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021		PM Orders	WO Ready to Schedule	Light Tower
690839	Unimog Service Truck	Fallas Varias	FALLAS VARIAS	17/10/2021		Corrective Order	WO Ready to Schedule	Truck
691744	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	19/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
692045	Mobile equipment	COMPRA EXTINTORES 5LB	COMPRA BASES PORTA EXTINTOR	19/10/2021	90015662 90015663	Corrective Order	WO Ready to Schedule	Area
692883	Coaster	CAMBIO ESCOBILLAS PARABRISAS	DESGASTE	20/10/2021		Corrective Order	WO Ready to Schedule	Bus
692931	Toyota Land Cruiser	CAMBIO DE ESTRIBOS	EQUIPO GENERAL	20/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
692934	Toyota Land Cruiser	CAMBIO SIRENA EMERGENCIA	ARREGLO DE SIRENA	20/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
693095	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693121	Caterpillar 416E	Reparaciones a mandos finales	REPARACIONES A MANDOS FINALES	21/10/2021	90016267 90016268	Corrective Order	WO Ready to Schedule	Backhoe
693123	Caterpillar 416E	Reparacion de accesorios	REPARACION DE ACCESORIOS	21/10/2021	90016250	Corrective Order	WO Ready to Schedule	Backhoe
693160	Caterpillar 416E	REEMPLAZO SELENOIDE SHUTOFF	EQUIPO IASA	21/10/2021	90015977	Corrective Order	WO Ready to Schedule	Backhoe
693167	Toyota Hilux	REVISAR SISTEMA ARRANQUE	PROBLEMAS DE ARRANQUE	21/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
693204	Toyota Hilux	REPARAR ASIENTOS	GASTADOS POR USO	21/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
693206	Toyota Hilux	INSTALACION TIRO REMOLQUE	NECESARIO PARA ACTIVIDADES	21/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
693413	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693417	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693418	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693419	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693421	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693422	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693425	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693426	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693428	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693435	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693436	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693438	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Bus
693459	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693461	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693462	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693463	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693464	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693466	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693467	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693471	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
693472	PT050 NMR85L-HH5WA ISUZU	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Truck
693477	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
694187	PRAMAC GSW90P 74 kVa	INSTALAR CARGADOR BATERIA	DAÑO POR TIEMPO DE SERVICIO	22/10/2021	90015975	Corrective Order	WO Ready to Schedule	Generator
694527	Coaster Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/10/2021		PM Orders	WO Ready to Schedule	Bus
695158	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Generator
695166	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Light Tower
695167	DOOSAN 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
695169	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Light Tower
695170	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Light Tower
695171	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021		PM Orders	WO Ready to Schedule	Light Tower
695922	Freightliner Columbia CI112	GUARDAFANGO / TORNILLOS	GUARDAFANGO / TORNILLOS	25/10/2021		Corrective Order	WO Ready to Schedule	Mule truck
696042	DOOSAN 1005	CAMBIO FOCOS ILUMINACION	FOCOS QUEMADOS	25/10/2021		Corrective Order	WO Ready to Schedule	Light Tower
696383	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	26/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
696559	Caterpillar 416E	CAMBIO DE RADIADOR	PKG-10008023	26/10/2021	90016226	Corrective Order	WO Ready to Schedule	Backhoe
696637	Olympian GEP150 135 kVa	CAMBIO POSTES BATERIA	DESGASTE	26/10/2021	90016258	Corrective Order	WO Ready to Schedule	Generator
697649	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697684	Landcruiser DC	REVISAR ALARMA RETROCESO	NO FUNCIONA	28/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
697776	Toyota Hilux	A/C INSPECTION & REPAIR	REPARACION A/A	28/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
697976	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697977	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697978	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697979	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697980	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697983	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Bus
697984	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Bus
697985	Toyota Land Cruiser	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
697988	Caterpillar D110 E2 110 kVa	MANTENIMIENTO MEDIA VIDA	CAMBIO BOMBA, GOBERNADOR, INYECTORES	28/10/2021	90016413	Corrective Order	WO Ready to Schedule	Generator
698215	Caterpillar 740B EJ ADT	R&I TYRES POS 1	R&I TIRES POS 1	29/10/2021	PROG 01 AL 07 NOV	PM Orders	WO Ready to Schedule	Articulated dump truck
698218	Caterpillar 740B EJ ADT	R&I TYRES POS 2	R&I TYRES POS 2	29/10/2021	PROG 01 AL 07 NOV	PM Orders	WO Ready to Schedule	Articulated dump truck
698975	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	30/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
698987	Coaster	CAMBIO BATERIA/REVISAR LUCES	PROBLEMA ARRANQUE LUCES NO ENCIENDEN	30/10/2021		Corrective Order	WO Ready to Schedule	Bus
699164	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	31/10/2021		PM Orders	WO Ready to Schedule	Pickup truck
699181	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021		PM Orders	WO Ready to Schedule	Generator
699259	GS189 D110 E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021		PM Orders	WO Ready to Schedule	Generator
699281	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021		PM Orders	WO Ready to Schedule	Light Tower
699520	Landcruiser TC	CAMBIO ASIENTO CONDUCTOR	DETERIORADO	31/10/2021		Corrective Order	WO Ready to Schedule	Pickup truck
699766	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	01/11/2021		PM Orders	WO Ready to Schedule	Generator
699767	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	01/11/2021		PM Orders	WO Ready to Schedule	Generator
699911	LV162 RANGERS SC FORD	KIT DE HERRAMIENTAS	POR PERDIDA DE HERRAMIENTAS	01/11/2021		Corrective Order	WO Ready to Schedule	Light Vehicles
699912	LV205 RANGER FORD	KIT DE HERRAMIENTA	POR PERDIDA DE HERRAMIENTAS	01/11/2021		Corrective Order	WO Ready to Schedule	Light Vehicles
699913	LV070 RANGER FORD	KIT DE HERRAMIENTA	POR PERDIDA DE HERRAMIENTAS	01/11/2021		Corrective Order	WO Ready to Schedule	Light Vehicles
699917	Hiace Bus	KIT DE HERRAMIENTA	POR PERDIDA DE HERRAMIENTAS	01/11/2021		Corrective Order	WO Ready to Schedule	Bus
700461	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	02/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
701562	Freightliner CI 120	balinera de centro	CAMBIO DE BALINERA DE CENTRO	03/11/2021	90016712	Corrective Order	WO Ready to Schedule	Mule truck
701772	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	04/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702391	Landcruiser DC	CAMBIO ALARMA RETROCESO	NO FUNCIONA	04/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
702393	Landcruiser TC	REVISAR TRANSFER	POR DAÑO EN EL SISTEMA	04/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
702394	Landcruiser TC	EVALUACION GARANTIA MOTOR	REPARACION MOTOR	04/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
702396	Landcruiser TC	REPARA CLAXON/ALARMA RETROCESO	NO FUNCIONA	04/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
702531	Landcruiser TC	AJUSTAR JUEGO CARDAN	RUIDO EN LA TRACCION	05/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
702572	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702573	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702574	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702575	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702576	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702577	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702578	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702579	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702580	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
702581	PB013 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Bus
702582	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Bus
702583	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Bus
702584	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Bus
702585	Ford F550	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
703425	Hilux DC	REPARAR FRENO MANO	SENSOR DOBLE NO FUNCIONA	06/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
703872	Hilux DC	REPARAR SENSOR PUERTA	SE MANTIENE ENCENDIDO	07/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
703952	PRAMAC GSW120 120 kVa	PM1 PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Generator
703955	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Generator
703959	Atlas Copco GESAN QIS 45 47KVA	PM1 ATL QIS45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Generator
703961	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Light Tower
703962	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Light Tower
703963	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Light Tower
703965	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
703974	Caterpillar C4.4 88KVA	PM1 CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Generator
703976	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Ready to Schedule	Light Tower
703981	General Mobile MLT3060K	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		Corrective Order	WO Ready to Schedule	Light Tower
703984	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		Corrective Order	WO Ready to Schedule	Light Tower
703986	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		Corrective Order	WO Ready to Schedule	Light Tower
704644	Ford Hilux D/C Light Vehicle	REPARAR SISTEMA ABASTECIMIENTO	OBSTRUCCION EN TANQUE DE GASOL	08/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
704838	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	08/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
704989	Ford Ranger Sc	REVISION POR GARANTIA	PRESENTA PROBLEMAS EN PARTES REPARADA	08/11/2021	50018100 50018447	Corrective Order	WO Ready to Schedule	Pickup truck
706192	Coaster	REPARAR MALETERO/REPARAR FRENO	VARIAS REPARACIONES	10/11/2021		Corrective Order	WO Ready to Schedule	Bus
706483	Landcruiser TC	REPARACION TRANSFER	RUIDO EN LA TRANSMISION	10/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
706843	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	11/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
706844	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/11/2021		PM Orders	WO Ready to Schedule	Generator
706845	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/11/2021		PM Orders	WO Ready to Schedule	Generator
706977	Landcruiser DC	CAMBIO PARABRISAS FRONTAL	POR RAJADURA	11/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
707508	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707510	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707511	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707514	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707515	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707516	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707518	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707520	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707521	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707523	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707524	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707526	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Bus
707543	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707544	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
707545	Hino Serie 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Ready to Schedule	Truck
707963	Hilux DC	CAMBIO BATERIA	PROBLEMAS AL ARRANQUE	12/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
708300	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	13/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
708552	Caterpillar 14M Motorgrader	Advertencia en la presión de C	ADVERTENCIA EN LA PRESIÓN DE COMBUSTIBLE	13/11/2021		Corrective Order	WO Ready to Schedule	Grader
708830	Landcruiser TC	REPARAR SISTEMA FRENO	FRENO LARGO	13/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
709451	Power Curbers 5700-C	Problema con la direccion	PROBLEMA CON LA DIRECCION	14/11/2021		Corrective Order	WO Ready to Schedule	Kerb Machine
709750	Coaster	AUXILIO ARRANQUE EQUIPO	COASTER NO ARRANCA	14/11/2021		Corrective Order	WO Ready to Schedule	Bus
711277	Landcruiser TC	REVISAR SISTEMA SUSPENSION	REVISAR SISTEMA DE DIRECCION POR RUIDOS	16/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
711356	Landcruiser TC	AUXILIO ARRANQUE EQUIPO	VEHICULO NO ARRANCA	16/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
711360	Coaster	TIRE AND RING INSPECT/CHANGE	CAMBIO 06 LLANTAS	16/11/2021		Corrective Order	WO Ready to Schedule	Bus
711451	Hilux DC	REPARAR SISTEMA EMBRAGUE	PROBLEMAS CLUTCH	16/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
711634	Caterpillar 735B	C/TRANSMISION	DESGASTE	16/11/2021		Corrective Order	WO Ready to Schedule	Articulated dump truck
712035	Hilux DC	REPARAR CARROCERIA	PRESENTA MULTIPLES OBSERVACIONES	17/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
712491	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	18/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
712868	Toyota Land Cruiser	AUXILIO ARRANQUE EQUIPO	PROBLEMAS DE ENENDIDO	18/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
712999	Caterpillar 12M	CAMBIO DE HOJA DE CORTE	CAMBIO DE HOJA DE CORTE	18/11/2021		Corrective Order	WO Ready to Schedule	Grader
713754	Hilux DC	REPARAR SISTEMA FRENO	AJUSTE FRENO SERVICIO Y PARQUEO	19/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
714113	BT014 M2-112 Freightliner	CONFECCION DE MANGUERA	CONFECCION DE MANGUERA	20/11/2021		Corrective Order	WO Ready to Schedule	.
714182	Landcruiser DC	REPARAR SISTEMA FRENO	AJUSTE FRENO SERVICIO Y PARQUEO	20/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
714183	Landcruiser DC	EVALUACION DOBLE TRACCION	RUIDO AL MOMENTO DE APLICAR LA MARCHA	20/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
714212	MAN 33.360 V20	INSPECCION Y EVALUACION GRUA	EVALUACION REMUSA	20/11/2021		Corrective Order	WO Ready to Schedule	Boom truck
714519	Valle Grande Nursery Offices	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	21/11/2021		PM Orders	WO Ready to Schedule	Building
714520	Security Checkpoint Gold Room	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	21/11/2021		PM Orders	WO Ready to Schedule	Building
714607	Landcruiser DC	INDICADOR TABLERO ENCENDIDO	LUZ INTERNA DEFECTUOSA	21/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
715209	Valle Grande Geology Offices	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715210	Valle Grande Environment Offic	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715211	Valle Grande Archeology Office	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715212	Pit Operations Offices	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715220	Logistic and Transport Area 22	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715221	Heliport Offices	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715222	General Mod Quad Buildings	13W Inspect And Clean Air Cond	13W INSPECT AND CLEAN AIR COND	22/11/2021		PM Orders	WO Ready to Schedule	Building
715436	Hilux DC	CAMBIO LLAVE CONTACTO	PROBLEMAS CON EL PASADOR	22/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
715650	Mobile equipment	lamparas para taller	LAMPARAS PARA TALLER	22/11/2021		Corrective Order	WO Ready to Schedule	Area
715918	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	23/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
716334	Toyota Land Cruiser	A/C INSPECTION & REPAIR	REPARACION AIRE ACONDICIONADO	23/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
716335	Toyota Hilux	CAMBIO SIRENA EMERGENCIA	NO ENCIENDE	23/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
716336	EX036 EC480DL Volvo	INT/CASQUILLOS DE BUCKET	CASQUILLO EXTRABIADO	23/11/2021	programar 5/12/2021	Corrective Order	WO Ready to Schedule	Excavator
716693	Landcruiser TC	REPARAR ALARMA RETROCESO	NO FUNCIONA	24/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
716887	Landcruiser DC	REVISAR SISTEMA DIRECCION	VOLANTE GIRADO 180 GRADOS	24/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717122	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	25/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
717123	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	25/11/2021		PM Orders	WO Ready to Schedule	Generator
717124	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	25/11/2021		PM Orders	WO Ready to Schedule	Generator
717266	Landcruiser DC	CAMBIO DE BATERIA	EVALUAR SISTEMA ELECTRICO	25/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717312	Hilux DC	REPARAR ALARMA RETROCESO	NO FUNCIONA	25/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717659	Freightliner CI 120	Nebulización de Equipo	NEBULIZACIÓN DE EQUIPO	25/11/2021		Corrective Order	WO Ready to Schedule	Mule truck
717978	Landcruiser DC	REVISAR LUCES NIEBLA	NO ENCIENDEN	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717981	Landcruiser DC	CAMBIO PARABRISAS FRONTAL	BAJA VISIBILIDAD	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717982	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717997	Hilux DC	REPARAR SISTEMA 4X4	NO FUNCIONA	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717998	Hilux DC	CAMBIO PLUMILLAS PARABRISAS	DAÑADOS	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
717999	Hilux DC	REPARAR SISTEMA FRENO	AJUSTAR FRENO SERVICIO/PARQUEO	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
718000	Hilux DC	REPARAR ASIENTO CONDUCTOR	NO AJUSTA	26/11/2021		Corrective Order	WO Ready to Schedule	Pickup truck
718027	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718028	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718030	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718031	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718032	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718033	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718040	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718042	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718043	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718044	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718045	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718046	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718047	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718048	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718049	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718050	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718051	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718052	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718053	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718054	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718055	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718056	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718057	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718059	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718060	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718061	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718062	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Pickup truck
718064	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	26/11/2021		PM Orders	WO Ready to Schedule	Bus
600451	Caterpillar 740b Ej	Falta aceite de motor	FALTA ACEITE DE MOTOR	01/06/2021		Corrective Order	WO Issued & Released	Articulated dump truck
600632	Coaster Bus	CAMBIO LUCES ESCOLTA	BULBO QUEMADO	01/06/2021		Corrective Order	WO Issued & Released	Bus
601670	Unimog Service Truck	CAMBIO DE MOTOR	CORRECTIVO	03/06/2021		Corrective Order	WO Issued & Released	Truck
603524	Caterpillar 320DL Excavator	MECHANICAL REPAIRS (IIASA)	CORRECTIVE	07/06/2021	50013509 50016886 50017680	Corrective Order	WO Issued & Released	Excavator
604813	Hilux DC	CAMBIO BATERIA	MANTENIMIENTO CORRECTIVO	09/06/2021		Corrective Order	WO Issued & Released	Pickup truck
605429	Hilux DC	CAMBIO BOMBILLO RH LUZ CORTA	BOMBILLO DEFICIENTE	10/06/2021		Corrective Order	WO Issued & Released	Pickup truck
606601	Coaster	REPARAR SISTEMA FRENO	FALLA EN LOS FRENOS	12/06/2021		Corrective Order	WO Issued & Released	Bus
607181	PRAMAC GSW460V 460 kVa	CAMBIO RETENEDORA/EMPAQUE	POR FUGA DE ACEITE	13/06/2021	90012311 90016902	Corrective Order	WO Issued & Released	Generator
607242	SDMO T11UM 10 kVa	INSPECCION GENERAL EQUIPO	EVALUACION POST CUARENTENA	13/06/2021		PM Orders	WO Issued & Released	Generator
607243	SDMO K12UM 11KVA	INSPECCION GENERAL EQUIPO	EVALUACION POST CUARENTENA	13/06/2021		PM Orders	WO Issued & Released	Generator
607406	Hilux DC	REPARAR ALARMA RETROCESO	NO SE ACTIVA	14/06/2021		Corrective Order	WO Issued & Released	Pickup truck
607510	Hilux DC	INSTALAR BOLA TIRO/CARGA	PARA TALLER DE GENERADORES	14/06/2021		Corrective Order	WO Issued & Released	Pickup truck
607513	Hilux DC	INSTALAR BOLA TIRO/CARGA	PARA TALLER DE GENERADORES	14/06/2021		Corrective Order	WO Issued & Released	Pickup truck
609300	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Issued & Released	Pickup truck
609307	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Issued & Released	Pickup truck
609310	Coaster Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Issued & Released	Bus
609318	Hino Series300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Issued & Released	Truck
609859	PRAMAC GSW460V 460 kVa	CAMBIO PLACA DIODOS	MANTENIMIENTO CORRECTIVO	18/06/2021	90009285	Corrective Order	WO Issued & Released	Generator
609951	Liugong Cpcd20	ROTURA TUBERIA REFRIGERACION	ROTURA TUBERIA REFRIGERACION	18/06/2021		Corrective Order	WO Issued & Released	Forklift
610161	Grove RT650E 45TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Issued & Released	Crane/Hoist
610162	Shuttlelift RTCD5540F 15TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Issued & Released	Crane/Hoist
610165	Caterpillar TI1055clrc	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Issued & Released	Telehender
610167	Caterpillar TL642	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Issued & Released	Telehender
610171	Manitou Mht-X1490 9t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Issued & Released	Telehender

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
610172	Hyster E70xn 3t Forklift (E)	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610174	Hyster E70xn 3t Forklift (E)	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610175	Linde T30D	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610176	Hyster H300 13t Forklift (M)	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610177	Hyster H300 Forklift	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610179	TCM FGH25D	INSPECCION PRE-CERTIFICACION	INSPECCION		18/06/2021			Corrective Order	WO Issued & Released	Forklift
610360	Ford 450	REPARAR MASTERSWITCH	NO ALIMENTA LUCES TRASERAS		19/06/2021			Corrective Order	WO Issued & Released	Pickup truck
610712	Liugong Cpcd20	INSPECCION PRE-CERTIFICACION	INSPECCION		19/06/2021			Corrective Order	WO Issued & Released	Forklift
610718	GROVE RT600E 50TON	INSPECCION PRE-CERTIFICACION	INSPECCION		19/06/2021			Corrective Order	WO Issued & Released	Crane/Hoist
610720	Grove RT700E 60TON	INSPECCION PRE-CERTIFICACION	INSPECCION		19/06/2021			Corrective Order	WO Issued & Released	Crane/Hoist
610724	GROVE GMK 2035E 35TON	INSPECCION PRE-CERTIFICACION	INSPECCION		19/06/2021			Corrective Order	WO Issued & Released	Crane/Hoist
611400	Hilux DC	INSTALAR BOLA TIRO/CARGA	REQUERIMIENTO NUEVO		21/06/2021			Corrective Order	WO Issued & Released	Pickup truck
611498	Terex MAC25 25TON	MECHANICAL REPAIRS (DCF)	CORRECTIVE		21/06/2021			Corrective Order	WO Issued & Released	Crane/Hoist
611730	Caterpillar 735B ADT	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO		21/06/2021			Corrective Order	WO Issued & Released	Articulated dump truck
612808	Caterpillar 226B	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA		23/06/2021			Corrective Order	WO Issued & Released	Skid Steer
612858	Caterpillar RM300	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA		23/06/2021			Corrective Order	WO Issued & Released	Road Reclaimer
612941	PB002 COASTER TOYOTA	REPARAR PISO SALON	TALLER DOLLAR PENONOME		23/06/2021			Corrective Order	WO Issued & Released	Bus
613429	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		24/06/2021			PM Orders	WO Issued & Released	Pickup truck
614388	Hilux DC	CAMBIO FARO POSTERIOR	MICA ROTA		25/06/2021			Corrective Order	WO Issued & Released	Pickup truck
615852	Caterpillar 416E	Cambio de radiador	RADIADOR ROTO		28/06/2021	90016438		Corrective Order	WO Issued & Released	Backhoe
615959	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS		28/06/2021			Corrective Order	WO Issued & Released	Pickup truck
615961	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS		28/06/2021			Corrective Order	WO Issued & Released	Pickup truck
615968	Landcruiser DC	INSPECCION ARRANQUE EQUIPO	PROBLEMAS DE ARRANQUE		28/06/2021			Corrective Order	WO Issued & Released	Pickup truck
616840	Hilux DC	CAMBIO VIDRIO FRONTAL	RAJADURA EN LA ENTREGA		29/06/2021			Corrective Order	WO Issued & Released	Pickup truck
617678	Caterpillar 236d Skid Steer L	Cambio de mangueras de coolam	FUGAS DE COOLAM POR MANGUERAS		01/07/2021	90001032		Corrective Order	WO Issued & Released	Skid Steer
618836	Caterpillar 307E Miniexcavator	Cambio de tapa de llenado de a	TAPA DE LLENADO DE ACEITE DE MOTOR		03/07/2021	90014971		Corrective Order	WO Issued & Released	Excavator
618837	Caterpillar 307E Miniexcavator	cambio de vidrio delantero	VIDRIO DELANTERO ROTO		03/07/2021			Corrective Order	WO Issued & Released	Excavator
619146	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION		03/07/2021			PM Orders	WO Issued & Released	Generator
619147	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION		03/07/2021			PM Orders	WO Issued & Released	Generator
619842	Caterpillar 426f2 Backhoe	cambio de baldes	CAMBIO DE BALDES, DELANTERO Y TRASERO		04/07/2021			Corrective Order	WO Issued & Released	Backhoe
621585	Caterpillar C9 250 kVa	INSPECCION DE GENERADOR	EQUIPO DE APOYO IASA		06/07/2021			Corrective Order	WO Issued & Released	Generator
623705	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Pickup truck
623712	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Pickup truck
623722	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Pickup truck
623726	Coaster Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Bus
623730	PB011 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Bus
623731	PB015 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Bus
623732	H1 Bus Pasajeros	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Bus
623737	Ford Ranger	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Pickup truck
623745	Toyota LAND CRUISER S/W	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Pickup truck
623750	Hino Series 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		09/07/2021			PM Orders	WO Issued & Released	Truck
625163	Olympian GEP150 135 kVa	PM OLY GEP 150 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION		11/07/2021			PM Orders	WO Issued & Released	Generator
625260	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION		11/07/2021			PM Orders	WO Issued & Released	Generator
626497	Hilux DC	REPARAR ALARMA RETROCESO	SIN ALARMA DE RETROCESO		13/07/2021			Corrective Order	WO Issued & Released	Pickup truck
627230	Broce Broom 250B	MAJOR REPAIRS (RESANSIL)	CORRECTIVE		14/07/2021	50014520 50015555		Corrective Order	WO Issued & Released	Scrubber / Sweeper
627952	Caterpillar 300.9D MicoExcavat	TA1 EVALUACION Y MODIFICACIONE	REALIZADO POR IASA		15/07/2021	90016444 90016751		Corrective Order	WO Issued & Released	Excavator
628472	Caterpillar 226b Skid Steer L	TAI INSPECCION GENERAL	INSPECCION EQUIPO IASA		16/07/2021	90010987 90011169		Corrective Order	WO Issued & Released	Skid Steer
629471	Broderson IC200-2C 9TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE		18/07/2021			Corrective Order	WO Issued & Released	Crane/Hoist
629846	Grove RT890 90TON	alta temperatura	ALTA TEMPERATURA, SISTEMA DE ENFRIAMIENTO		19/07/2021			Corrective Order	WO Issued & Released	Crane/Hoist
630020	Freightliner Cl 120	CAMBIO DE COMPONENTES	A/A / FUGA DE AIRE		19/07/2021	90011168		Corrective Order	WO Issued & Released	Mule truck
630037	Freightliner Cl 120	NO ENCIENDE / LAMPARAS/ VIDRIO	NO ENCIENDE / LAMPARAS/ VIDRIO		19/07/2021			Corrective Order	WO Issued & Released	Mule truck
630057	Intraax 53121 Hendrickso	LUCES / POLLERA / FRENOS	LUCES / POLLERA / FRENOS		19/07/2021			Corrective Order	WO Issued & Released	Trailer / Flatbed / Lime Tank
630064	Freightliner Cl 120	NO ENCIENDE/BANDA/AMORTIGUADOR	NO ENCIENDE/BANDA/AMORTIGUADOR		19/07/2021			Corrective Order	WO Issued & Released	Mule truck
630586	Caterpillar CS74 Compactor	CAMBIO DE MANGUERA MOTOR	IIASA-SONCAR -CENMAN		20/07/2021			Corrective Order	WO Issued & Released	Compactor
630662	Hilux DC	SPARE TIRE REPLACEMENT	ASIGNAR ARO/NEUMATICO REPUESTO		20/07/2021			Corrective Order	WO Issued & Released	Pickup truck
631902	Caterpillar C9 250 kVa	CAMBIO RETENEDORA DELANTERA	CORRECTIVO PROGRAMADO		22/07/2021	reprogramar		Corrective Order	WO Issued & Released	Generator
632946	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		23/07/2021			PM Orders	WO Issued & Released	Pickup truck
632979	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		23/07/2021			PM Orders	WO Issued & Released	Pickup truck
632983	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		23/07/2021			PM Orders	WO Issued & Released	Pickup truck
632985	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		23/07/2021			PM Orders	WO Issued & Released	Pickup truck
632995	Ford Hilux D/C Light Vehicle	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION		23/07/2021			PM Orders	WO Issued & Released	Pickup truck
633140	Landcruiser TC	CAMBIO RADIADOR	FUGA DE REFRIGERANTE		24/07/2021			Corrective Order	WO Issued & Released	Pickup truck
633479	Toyota Hilux	REPARAR SISTEMA ELECTRICO	FALLA EN TABLERO DE INSTRUMENTOS		24/07/2021			Corrective Order	WO Issued & Released	Pickup truck
634788	Caterpillar D110 E2 100KVA	CAMBIO RETENEDORA POSTERIOR	FUGA DE ACEITE		26/07/2021	reprogramar		Corrective Order	WO Issued & Released	Generator
635668	USP&E GP700S/V-A 700 kVa	CAMBIO BOMBA DRENAJE	FUGA ACEITE		27/07/2021	90010803		Corrective Order	WO Issued & Released	Generator
635792	Caterpillar CS74 Compactor	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA		27/07/2021			Corrective Order	WO Issued & Released	Compactor
636363	PRAMAC GSW80P 83 kVa	CAMBIO ALTERNADOR DC	INCLUIR CORREAS		28/07/2021	90010844		Corrective Order	WO Issued & Released	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
636434	Toyota Land Cruiser	INSTALAR CAMILLAS	MANTENIMIENTO MEJORATIVO	28/07/2021		Corrective Order	WO Issued & Released	Pickup truck
636439	Caterpillar 307E Miniexcavator	Cambio de tapa de llenado de m	TAPA DE MOTOR ROTA	28/07/2021	90014972	Corrective Order	WO Issued & Released	Excavator
636443	Caterpillar 307E Miniexcavator	Cambio de casquillos	CASQUILLOS EN MAL ESTADO	28/07/2021		Corrective Order	WO Issued & Released	Excavator
636540	Caterpillar D110 E2 110 kVa	CAMBIO RETENEDORA POSTERIOR	FUGA ACEITE	28/07/2021		Corrective Order	WO Issued & Released	Generator
636805	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Issued & Released	Pickup truck
636808	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Issued & Released	Pickup truck
636810	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Issued & Released	Pickup truck
636811	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Issued & Released	Pickup truck
636813	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Issued & Released	Pickup truck
636971	Freightliner 8170ME Water Truc	REPARACION MAYOR (IMREPSA)	SE ENVIA IMREPSA	29/07/2021	50014926 50015455	Corrective Order	WO Issued & Released	Water truck
637058	Grove RT600E 50TON	Cambio de cable	CAMBIO DE CABLE	30/07/2021		Corrective Order	WO Issued & Released	Crane/Hoist
637059	Grove GMK 4080 80TON	Cambio de Balinera de Polea de	CAMBIO DE BALINERA DE POLEA DE PATECA	30/07/2021		Corrective Order	WO Issued & Released	Crane/Hoist
637399	SJS SJ6530	REPARACION DE COMPONENTES	REPARACION IMREPSA	30/07/2021	50014929	Corrective Order	WO Issued & Released	Compactor
637524	Landcruiser TC	REPOSICION HERRAMIENTAS	POR PERDIDA DE HERRAMIENTAS	30/07/2021		Corrective Order	WO Issued & Released	Pickup truck
637525	Landcruiser TC	FUMIGAR UNIDAD	POR PRESENCIA DE INSECTOS	30/07/2021		Corrective Order	WO Issued & Released	Pickup truck
638140	Caterpillar 12M	Reemplazo de hojas	REEMPLAZO DE HOJAS DE CORTE	31/07/2021		Corrective Order	WO Issued & Released	Grader
638809	Caterpillar 140K	Terminal de la dirección delan	TERMINAL DE LA DIRECCIÓN DELAN	01/08/2021		Corrective Order	WO Issued & Released	Grader
639166	Hilux DC	CAMBIO LUZ FRENO LH	LUZ QUEMADA	02/08/2021		Corrective Order	WO Issued & Released	Pickup truck
639329	Hilux DC	SENAL INDICADORA ENCENDIDA	LUZ FRENO ABS	02/08/2021		Corrective Order	WO Issued & Released	Pickup truck
639330	Hilux DC	CAMBIO PERNOS/TUERCAS	REVISAR RINES	02/08/2021		Corrective Order	WO Issued & Released	Pickup truck
640515	Ford Ranger	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	04/08/2021		Corrective Order	WO Issued & Released	Pickup truck
640574	Landcruiser DC	AJUSTE SISTEMA DE FRENOS	FRENO SERVICIO Y PARQUEO	04/08/2021		Corrective Order	WO Issued & Released	Pickup truck
640595	Landcruiser DC	REVISION GENERAL	EVALUAR SISTEMA DIRECCION	04/08/2021		Corrective Order	WO Issued & Released	Pickup truck
640933	Ford Hilux D/C Light Vehicle	EVALUAR SISTEMA SUSPENSION	DESGASTE PREMATURO DE NEUMATICOS	05/08/2021	700167	Corrective Order	WO Issued & Released	Pickup truck
640993	Caterpillar 320DL Excavator	CAMBIO DE CILINDROS RH / LH	DESGASTE	05/08/2021	60017131 50011114	Corrective Order	WO Issued & Released	Excavator
641189	Landcruiser DC	CAMBIO AMORTIGUADORES	GOLPES	05/08/2021		Corrective Order	WO Issued & Released	Pickup truck
641190	Landcruiser DC	CAMBIO BOMBILLO LUCES BAJA	NO ENCIENDE	05/08/2021		Corrective Order	WO Issued & Released	Pickup truck
641210	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Issued & Released	Pickup truck
641211	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Issued & Released	Pickup truck
641863	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021		Corrective Order	WO Issued & Released	Generator
641997	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	07/08/2021	EJECUTADO	PM Orders	WO Issued & Released	Pickup truck
642024	Atlas Copco HILIGHT V5 Light T	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021		PM Orders	WO Issued & Released	Light Tower
642947	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021		PM Orders	WO Issued & Released	Pickup truck
643525	Grove GMK4100L 100TON	FRONT PANE REPLACEMENT	CORRECTIVE	09/08/2021		Corrective Order	WO Issued & Released	Crane/Hoist
643910	Caterpillar TI1055clrc	CAMBIO DE 2 NEUMATICOS	CORRECTIVO	10/08/2021	90011436	Corrective Order	WO Issued & Released	Telehender
643961	Hilux DC	CAMBIO LLANTA REPUESTO	CAMBIO 04 LLANTAS	10/08/2021		Corrective Order	WO Issued & Released	Pickup truck
644094	Landcruiser DC	INSTALAR BOLA TIRO/CARGA	REQUERIMIENTO NUEVO	10/08/2021		Corrective Order	WO Issued & Released	Pickup truck
646571	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646572	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646580	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646582	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646591	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646592	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646598	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646600	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646602	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646603	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646605	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646606	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646608	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Pickup truck
646616	Isuzu NMR85L	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Issued & Released	Truck
646922	Caterpillar 735B ADT	Reparacion AFEX	REPARACION AFEX	14/08/2021		Corrective Order	WO Issued & Released	Articulated dump truck
647998	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Issued & Released	Pickup truck
648003	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Issued & Released	Pickup truck
648007	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Issued & Released	Pickup truck
648008	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Issued & Released	Pickup truck
648015	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Issued & Released	Pickup truck
648031	Hilux DC	mantenimiento 15000 kms	MANTENIMIENTO 15000 KMS	15/08/2021		Corrective Order	WO Issued & Released	Pickup truck
648304	Caterpillar 12M	Inspeccion mensual AFEX	INSPECCION MENSUAL AFEX	15/08/2021		Corrective Order	WO Issued & Released	Grader
648867	Hyster H700 Forklift	Cambio de Turbo Compresor	CAMBIO DE TURBO COMPRESOR	16/08/2021	90011859	Corrective Order	WO Issued & Released	Forklift
649341	Toyota Hilux	MECHANICAL REPAIRS (PCR)	CORRECTIVE	17/08/2021	50015451	Corrective Order	WO Issued & Released	Pickup truck
650443	Caterpillar 12M Motorgrader	AIRE ACONDICIONADO DANADO	AIRE ACONDICIONADO DANADO	19/08/2021	90012041	Corrective Order	WO Issued & Released	Grader
650629	Hilux DC	CAMBIO VIDRIO POSTERIOR	POR ROTURA	19/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651439	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651601	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651611	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651838	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651854	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
651860	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651866	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651868	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651871	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Pickup truck
651883	Isuzu NMR85L	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Issued & Released	Truck
651936	Hilux DC	REVISAR SEÑAL GPS	NO EMITE DATOS	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651942	Coaster Bus	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Bus
651943	Coaster Bus	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Bus
651945	Coaster Bus	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Bus
651946	Ford Ranger	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651949	Ford 450	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651953	Toyota Hilux	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651954	Toyota Hilux	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651955	Toyota Hilux	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Pickup truck
651957	Hino Serie 300	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Truck
651958	Hino Dutro 300	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Truck
651960	Hino Series300	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Issued & Released	Truck
651987	Caterpillar TI1055clrc	Revision de motor	REVISION DE FUGA DE COMBUSTIBLE	21/08/2021	90013895	Corrective Order	WO Issued & Released	Telehender
652482	Freightliner CI 120	PREVENTIVE MAINTENANCE	PREVENTIVO	22/08/2021		Corrective Order	WO Issued & Released	Mule truck
652603	Grove GMK 4080 80TON	EVALUAR CAMBIO DE SELLOS	FUGA POR PISTON DE CONTRAPESO	22/08/2021		Corrective Order	WO Issued & Released	Crane/Hoist
652987	Landcruiser DC	CAMBIO DE BATERIA	PROBLEMAS AL ARRANQUE	23/08/2021		Corrective Order	WO Issued & Released	Pickup truck
653149	Caterpillar D110 E2 110 kVa	CAMBIO BATERIA	CORRECTIVO PROGRAMADO	23/08/2021	50015631	Corrective Order	WO Issued & Released	Generator
653170	Hilux DC	REPARAR AUTOMATICO VENTANA rh	NO ACCIONA	23/08/2021		Corrective Order	WO Issued & Released	Pickup truck
653547	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	24/08/2021		PM Orders	WO Issued & Released	Pickup truck
654732	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Bus
654734	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Bus
654736	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Bus
654737	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Bus
654739	Ford 450	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Pickup truck
654741	Hino Serie 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Issued & Released	Truck
655014	Magni HTH 10,10 Telehandler	CAMBIO DE 1 NEUMATICO	CORRECTIVO	26/08/2021		Corrective Order	WO Issued & Released	Telehender
656415	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/08/2021		PM Orders	WO Issued & Released	Pickup truck
656418	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/08/2021		PM Orders	WO Issued & Released	Pickup truck
656478	Landcruiser DC	CAMBIO ARO NEUMATICO	CAMBIO 02 RINES	28/08/2021	90012367	Corrective Order	WO Issued & Released	Pickup truck
656488	Landcruiser TC	CAMBIO ARO NEUMATICO	CAMBIO 02 RINES	28/08/2021	90012368	Corrective Order	WO Issued & Released	Pickup truck
656505	Landcruiser DC	CAMBIO ARO NEUMATICO	CAMBIO 01 RIN	28/08/2021	90012370	Corrective Order	WO Issued & Released	Pickup truck
656508	Landcruiser TC	CAMBIO ARO NEUMATICO	CAMBIO 01 RIN	28/08/2021	90012371	Corrective Order	WO Issued & Released	Pickup truck
656897	Caterpillar 307E Miniexcavator	CAMBIO DE COMPONENTES	BACKLOG REPORT DE IASA	29/08/2021		Corrective Order	WO Issued & Released	Excavator
656918	Coaster	INSTALAR CINTURON PASAJEROS	TALLER DOLLAR PENONOME	29/08/2021		Corrective Order	WO Issued & Released	Bus
656926	Coaster	INSTALAR CINTURON PASAJEROS	TALLER DOLLAR PENONOME	29/08/2021		Corrective Order	WO Issued & Released	Bus
656929	Coaster	INSTALAR CINTURON PASAJEROS	TALLER DOLLAR PENONOME	29/08/2021		Corrective Order	WO Issued & Released	Bus
657041	Caterpillar D110 E2 110 kVa	PM SERVICIO GENERADOR MEC 90 D	PM SERVICIO GENERADOR MEC 90 D	29/08/2021		PM Orders	WO Issued & Released	Generator
657066	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021		PM Orders	WO Issued & Released	Light Tower
657904	International 7400 SBA Fire Tr	CAMBIO DE COMPONENTE	COOPER BUSSMAN EATON THERMAL SWITCHABLE	30/08/2021	90013978	Corrective Order	WO Issued & Released	Fire truck
657910	Grove RT890 90TON	Reparacion de frenos	REPARACION DE FRENOS	30/08/2021		Corrective Order	WO Issued & Released	Crane/Hoist
658006	Hyster H300 Forklift	COPAMA'S RECOMMENDATIONS	CORRECTIVE	30/08/2021		Corrective Order	WO Issued & Released	Forklift
658295	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	31/08/2021		PM Orders	WO Issued & Released	Pickup truck
660484	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Pickup truck
660485	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Pickup truck
660486	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Pickup truck
660488	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Pickup truck
660495	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Bus
660496	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Bus
660498	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Issued & Released	Pickup truck
662142	PB011 COASTER TOYOTA	TIRE AND RING INSPECT/CHANGE	CAMBIO 06 LLANTAS	05/09/2021		Corrective Order	WO Issued & Released	Bus
662339	Landcruiser DC	A/C INSPECTION & REPAIR	REVISION DEL A/C	05/09/2021		Corrective Order	WO Issued & Released	Pickup truck
663036	Hilux DC	CAMBIO BATERIA	FALLA CARGA	06/09/2021		Corrective Order	WO Issued & Released	Pickup truck
663911	Toyota Land Cruiser	A/C INSPECTION & REPAIR	PROBLEMAS CON EL ABANICO	07/09/2021		Corrective Order	WO Issued & Released	Pickup truck
663912	Toyota Land Cruiser	CAMBIO MANIGUETA TRASERA	MANIGUETA ROTA	07/09/2021		Corrective Order	WO Issued & Released	Pickup truck
664270	Hino Dutro 300	A/C INSPECTION & REPAIR	NO ENFRIA	08/09/2021		Corrective Order	WO Issued & Released	Truck
664525	Hilux DC	REPARAR PUERTA PASAJERO	NO ABRE DESDE AFUERA	08/09/2021		Corrective Order	WO Issued & Released	Pickup truck
664598	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	09/09/2021		PM Orders	WO Issued & Released	Pickup truck
664870	International 7400 SBA Fire Tr	Cambio de blower y compresor	CAMBIO DE BLOWER Y COMPRESOR	09/09/2021	PKG-10007558	Corrective Order	WO Issued & Released	Fire truck
664924	Grove RT650E 45TON	PRE-EVALUACION PARA CERTIFICAC	EVALUACION MECANICA	09/09/2021		Corrective Order	WO Issued & Released	Crane/Hoist
665232	Unimog Service Truck	Mant preventivo	MANT. PREVENTIVO	10/09/2021	75,849 kms	Corrective Order	WO Issued & Released	Truck
665393	Ford 450	REPARAR CLUTCH	ADICIONALES MOTOR	10/09/2021	50016933	Corrective Order	WO Issued & Released	Pickup truck
665499	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
665511	LV070 RANGER FORD	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Light Vehicles
665513	LV205 RANGER FORD	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Light Vehicles
665531	Hilux DC	REVISAR SEÑAL GPS	GPS NO EMITE DATOS	10/09/2021		Corrective Order	WO Issued & Released	Pickup truck
665552	LV050 RANGER FORD	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Light Vehicles
665577	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665581	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665583	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665585	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665589	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665592	PB002 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Bus
665597	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Bus
665598	Ford Ranger SC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Pickup truck
665599	Hino Dutro 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Issued & Released	Truck
665804	Coaster Bus	REVISION GENERAL	MECHANICAL REPAIR	11/09/2021		Corrective Order	WO Issued & Released	Bus
665805	Landcruiser DC	REVISION GENERAL	MECHANICAL REPAIR	11/09/2021		Corrective Order	WO Issued & Released	Pickup truck
666010	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021		PM Orders	WO Issued & Released	Generator
666120	Caterpillar 307E Miniexcavator	CAMBIO COMPONENTES TA1	PERSONAL DE IASA	11/09/2021		Corrective Order	WO Issued & Released	Excavator
666135	Caterpillar 740b Ej	CAMBIO DE COMPONENTES	INSPECCION POST PM04	11/09/2021		Corrective Order	WO Issued & Released	Articulated dump truck
666618	Caterpillar 735B	735D-MAINTENANCE - 1000HRS-PM6	735D-MAINTENANCE - 1000HRS-PM6	12/09/2021	EQUIPO DOWN	PM Orders	WO Issued & Released	Articulated dump truck
666626	Mobile equipment	TOMA DE DATOS DE BOOM	DATOS DE MARCA Y N SERIE	12/09/2021		Corrective Order	WO Issued & Released	Area
666628	Mobile equipment	LEVANTAMIENTO DE MOTORES	TOMA DE NUMERO DE SERIE	12/09/2021		Corrective Order	WO Issued & Released	Area
666674	Caterpillar 740B EJ ADT	CAMBIO DE FENDER RH	DESGASTADO/DANADO	12/09/2021	90017725	Corrective Order	WO Issued & Released	Articulated dump truck
667323	Caterpillar 426f2 Backhoe	REPARACION DE SEGUROS DE PUERT	CAMBIO DE SEGUROS DE PUERTA FRONTAL DEL MOTOR	13/09/2021		Corrective Order	WO Issued & Released	Backhoe
667838	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	14/09/2021		PM Orders	WO Issued & Released	Pickup truck
668766	Hyster H700 Forklift	cambio de tapon de diferencial	TAPON DE HOUSING DE DIFERENCIAL CON FUGA	15/09/2021		Corrective Order	WO Issued & Released	Forklift
669628	Caterpillar CS533E Compactor	Soportes del tambor danados	CAUCHOS DE SOPORTE DEL TAMBOR DANADOS	17/09/2021		Corrective Order	WO Issued & Released	Compactor
669988	Hyster H700 Forklift	MANGUERAS SIST ENGRASE	EQUIPO COPAMA	17/09/2021		Corrective Order	WO Issued & Released	Forklift
670003	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	17/09/2021		Corrective Order	WO Issued & Released	Pickup truck
670532	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021		PM Orders	WO Issued & Released	Generator
670533	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021		PM Orders	WO Issued & Released	Generator
670590	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021		PM Orders	WO Issued & Released	Generator
671420	Hyster H800 32t Forklift (M)	FILTER HOLDER RUSTY	CORRECTIVE	21/09/2021		Corrective Order	WO Issued & Released	Forklift
672830	Mobile equipment	MATERIAl OFICINA GENERADORES	MATERIAL OFICINA	22/09/2021		Corrective Order	WO Issued & Released	Area
673314	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673751	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673756	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673757	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673759	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673762	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673767	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673768	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673769	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673770	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673771	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673774	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673777	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673784	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673786	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673788	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673789	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673790	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Pickup truck
673793	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Issued & Released	Bus
674046	Hilux DC	GPS INSTALLING	REVISION INSTALACION Y FUNCIONAMIENTO	24/09/2021		Corrective Order	WO Issued & Released	Pickup truck
674048	Hilux DC	GPS INSTALLING	REVISION INSTALACION Y FUNCIONAMIENTO	24/09/2021		Corrective Order	WO Issued & Released	Pickup truck
674054	Hilux DC	GPS INSTALLING	REVISION INSTALACION Y FUNCIONAMIENTO	24/09/2021		Corrective Order	WO Issued & Released	Pickup truck
674199	Landcruiser TC	AJUSTE SISTEMA DE FRENOS	FRENO DE PARQUEO Y DE SERVICIO	24/09/2021		Corrective Order	WO Issued & Released	Pickup truck
674967	Toyota Land Cruiser	REPARACION GENERAL	TALLER DOLLAR PENONOME	25/09/2021	50016929	Corrective Order	WO Issued & Released	Pickup truck
676224	Caterpillar 236d Skid Steer L	CAMBIO DE ACOPLE	CAMBIO DE ACOPLE	27/09/2021	90015157	Corrective Order	WO Issued & Released	Skid Steer
676570	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	28/09/2021		PM Orders	WO Issued & Released	Pickup truck
676949	Hilux DC	SPARE TIRE REPLACEMENT	ASIGNAR ARO/NEUMATICO REPUESTO	28/09/2021		Corrective Order	WO Issued & Released	Pickup truck
678328	Landcruiser TC	CAMBIO AMORTIGUADOR TRASERO	REPARACION DE VARIAS AVERIAS	01/10/2021		Corrective Order	WO Issued & Released	Pickup truck
678471	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678474	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678475	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
678476	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678480	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678482	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678490	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678496	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678497	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678498	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021		PM Orders	WO Issued & Released	Pickup truck
678877	Hilux DC	INSTALACION TIRO REMOLQUE	REQUERIMIENTO NUEVO	01/10/2021		Corrective Order	WO Issued & Released	Pickup truck
678878	Hilux DC	INSTALACION TIRO REMOLQUE	REQUERIMIENTO NUEVO	01/10/2021		Corrective Order	WO Issued & Released	Pickup truck
678882	Hilux DC	INSTALACION TIRO REMOLQUE	REQUERIMIENTO NUEVO	01/10/2021		Corrective Order	WO Issued & Released	Pickup truck
678886	Hilux DC	INSTALACION TIRO REMOLQUE	REQUERIMIENTO NUEVO	01/10/2021		Corrective Order	WO Issued & Released	Pickup truck
680286	Caterpillar 305ECR	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Issued & Released	Excavator
680294	JLG 450 AJ Manlift	MECHANICAL INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Issued & Released	Manlift
680296	Mercedes Tipper Truck	MECHANICAL INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Issued & Released	Tipper
680298	Freightliner CI 120	MECHANICAL INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Issued & Released	Mule truck
680328	New Holland Lm 1745	Compra de cilindros estabiliza	CILONDRO DE ESTABILIZADOR DELKANTERO	03/10/2021		Corrective Order	WO Issued & Released	Telehender
680404	SJS SJ6530	FABRICACION DE PIEZA	FABRICACION DE EJE .	03/10/2021		Corrective Order	WO Issued & Released	Compactor
682585	Pramac GSW30P 24KVA	CAMBIO DE BATERIA	MANENIMIENTO CORRECTIVO	07/10/2021		Corrective Order	WO Issued & Released	Generator
682685	Unimog Service Truck	PROB CON LOS CAMBIOS D MARCHA	PROB CON LOS CAMBIOS D MARCHA	07/10/2021		Corrective Order	WO Issued & Released	Truck
682693	Bomag BW24RH	falta cinturon de seguridad,	FALTA CINTURON DE SEGURIDAD,	07/10/2021		Corrective Order	WO Issued & Released	Roller PTR
682714	Caterpillar 236d Skid Steer L	Cambio de componentes	CAMBIO DE COMPONENTES	07/10/2021	90014895 90014896 90016217	Corrective Order	WO Issued & Released	Skid Steer
683084	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Issued & Released	Pickup truck
683088	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Issued & Released	Pickup truck
683089	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Issued & Released	Pickup truck
683489	Freightliner M2 106 Refrigerat	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021		Corrective Order	WO Issued & Released	Refrigerator truck
683620	Landcruiser DC	CAMBIO PERTIGA	DETERIORADO	08/10/2021		Corrective Order	WO Issued & Released	Pickup truck
683636	Landcruiser TC	CAMBIO CINTURONES SEGURIDAD	SUCIOS EN MAL ESTADO	08/10/2021		Corrective Order	WO Issued & Released	Pickup truck
683659	Landcruiser DC	REPONER KITS PRIMEROS AUXILIOS	POR USO	08/10/2021		Corrective Order	WO Issued & Released	Pickup truck
683711	Landcruiser TC	REPONER KIT ANTIDERRAME	POR USO	08/10/2021		Corrective Order	WO Issued & Released	Pickup truck
683797	Caterpillar CS74 Compactor	sin escolta ni pertiga	SIN ESCOLTA NI PERTIGA	08/10/2021		Corrective Order	WO Issued & Released	Compactor
683825	Mobile equipment	CAMBIO BOMBA HIDROLAVADORA	TALLER GENERADORES	08/10/2021	90014975	Corrective Order	WO Issued & Released	Area
685028	Caterpillar CS74 Compactor	No escolta ni extintor y otros	NO ESCOLTA NI EXTINTOR	10/10/2021		Corrective Order	WO Issued & Released	Compactor
685178	Caterpillar D110 E2 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021		PM Orders	WO Issued & Released	Generator
685179	Olympian GEP18-6 18 kVa	PM1 OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021		PM Orders	WO Issued & Released	Generator
685385	Caterpillar TI1055clrc	LOW VOLTAGE ISSUES	CORRECTIVE	10/10/2021		Corrective Order	WO Issued & Released	Telehender
685964	Olympian GEP150 135 kVa	Tina de Contención y Techado	TINA DE CONTENCIÓN Y TECHADO	11/10/2021		Corrective Order	WO Issued & Released	Generator
687341	Hilux DC	CAMBIO ALARMA RETROCESO	ALARMA NO ACTIVA	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688018	Landcruiser DC	REPOSICION HERRAMIENTAS	POR PERDIDA DE HERRAMIENTAS	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688019	Landcruiser DC	REPARAR PUERTA TRASERA LH	NO ABRE	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688020	Landcruiser DC	CAMBIO EXTINTOR/CUÑAS	VENCIDO	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688022	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688023	Landcruiser TC	CAMBIO CUÑAS	POR PERDIDA	13/10/2021		Corrective Order	WO Issued & Released	Pickup truck
688131	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	14/10/2021		PM Orders	WO Issued & Released	Pickup truck
688342	Hino Dutro 300	CAMBIO EMBRAGUE	SISTEMA CLUTH	14/10/2021	50017069	Corrective Order	WO Issued & Released	Truck
688404	Caterpillar 226b Skid Steer L	Reemplazo de motor del w/w/	REEMPLAZO DE MOTOR DEL W/W	14/10/2021		Corrective Order	WO Issued & Released	Skid Steer
689444	Hino Dutro 300	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	15/10/2021		Corrective Order	WO Issued & Released	Truck
690092	Coaster	REPOSICION HERRAMIENTAS	POR PERDIDA DE HERRAMIENTAS	16/10/2021		Corrective Order	WO Issued & Released	Bus
690435	Caterpillar 320DL	Cable eléctrico de la escolta	CABLE ELÉCTRICO DE LA ESCOLTA	17/10/2021		Corrective Order	WO Issued & Released	Excavator
690436	Caterpillar 320DL	Necesita ajuste de wipers	NECESITA AJUSTE DE WIPERS	17/10/2021		Corrective Order	WO Issued & Released	Excavator
690529	Unimog Service Truck	DESMONTAJE DE TRANSMISION	DESMONTAJE DE TRANSMISION	17/10/2021		Corrective Order	WO Issued & Released	Truck
690609	Caterpillar CS74 Compactor	Sapos ligeramente rajados	SAPOS LIGERAMENTE RAJADOS	17/10/2021		Corrective Order	WO Issued & Released	Compactor
690690	Freightliner M2 106 Refrigerat	Cambio de lamparas delanteras	CAMBIO DE LAMPARAS DELANTERAS	17/10/2021	90015512	Corrective Order	WO Issued & Released	Refrigerator truck
691267	Hilux DC	CAMBIO LAMPARA DELANTERA RH	LAMPARA QUEMADA	18/10/2021		Corrective Order	WO Issued & Released	Pickup truck
691279	Internation F2674	REPARACION DE CILINDRO	MASTER TECH	18/10/2021	50017991	Corrective Order	WO Issued & Released	Boom truck
693414	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693424	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693437	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Bus
693439	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Bus
693440	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Bus
693441	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693449	Toyota Land Cruiser	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693465	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693468	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693469	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Bus
693470	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Issued & Released	Pickup truck
693528	Mobile equipment	Reemplazo de llantas	REEMPLAZO DE LLANTAS	21/10/2021		Corrective Order	WO Issued & Released	Area
693817	Caterpillar 236d Skid Steer L	CAMBIO DE BASES DE MOTOR	FUGA TAPON DEL CARTER	22/10/2021	90017418	Corrective Order	WO Issued & Released	Skid Steer
693864	Caterpillar 426f2 Backhoe	CAMBIO DE PINES EN MAL ESTADO	EQUIPO IASA	22/10/2021		Corrective Order	WO Issued & Released	Backhoe

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
694136	Hilux DC	CAMBIO BATERIA	PROBLEMAS DE CARGA	22/10/2021		Corrective Order	WO Issued & Released	Pickup truck
694773	Caterpillar CS533E Compactor	PM1-MANTENIMIENTO PREVENTIVO	EQUIPO IASA	23/10/2021		Corrective Order	WO Issued & Released	Compactor
694799	Grove GMK4100L 100TON	ENGRASE DE CABLE,POLEA,BOOM	LUBRICACION BOOM	23/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
694995	Freightliner Columbia CI112	Cambio espejo y tensor de Sile	CAMBIO DE ESPEJOS Y TENSOR DEL SILENCIADOR	24/10/2021	90017412	Corrective Order	WO Issued & Released	Mule truck
695044	Grove GMK 4080 80TON	LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION CABLES,POLEAS,BOOM	24/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
695050	Terex RT670 64TON	LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION EQUIPO	24/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
695056	Grove RT880E 75TON	LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION EQUIPO	24/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
695129	Caterpillar 236d Skid Steer L	CAMBIO DE MOTOR TRASLACION	EQUIPO IASA	24/10/2021		Corrective Order	WO Issued & Released	Skid Steer
695209	Terex RT670 64TON	LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION EQUIPO	24/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
695212	Grove GMK 4080 80TON	INSPECCION TECNICA MANIITOWOC	EQUIPO TECNOGRUA	24/10/2021		Corrective Order	WO Issued & Released	Crane/Hoist
695381	Hyster H700 Forklift	LIMPIEZA Y LUBRICACION CADENAS	EQUIPO COPAMA	24/10/2021		Corrective Order	WO Issued & Released	Forklift
695918	Magni HTH 10,10 Telehandler	MAJOR REPAIRS (POWER LIFT)	CORRECTIVE (POWER LIFT)	25/10/2021	5009234 10951 13125 50016375	Corrective Order	WO Issued & Released	Telehender
696442	Hino Serie 300	EVALUAR MOTOR FUGA ACEITE	FUGA DE ACEITE	26/10/2021		Corrective Order	WO Issued & Released	Truck
696836	AC066 XAVS450 ATLAS COPCO	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	26/10/2021	90016412 90016361 90016627	Corrective Order	WO Issued & Released	Compressor
697148	Freightliner M2 106 Refrigerat	CAMBIO DE CONDENSADOR A/C	CAMBIO DE COMPONENTE	27/10/2021		Corrective Order	WO Issued & Released	Refrigerator truck
697201	Caterpillar 416E	tapa ausente	TAPA AUSENTE	27/10/2021	90016453	Corrective Order	WO Issued & Released	Backhoe
697971	New Holland Lm 1745	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Issued & Released	Telehender
697982	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021		PM Orders	WO Issued & Released	Pickup truck
698191	Caterpillar 12M Motorgrader	FUGA DE ACIETE POR CILINDRO	FUGA DE ACIETE POR CILINDRO	29/10/2021	90016422	Corrective Order	WO Issued & Released	Grader
698314	Landcruiser DC	CAMBIO DE 2 NEUMATICO	CORRECTIVO	29/10/2021		Corrective Order	WO Issued & Released	Pickup truck
698778	Caterpillar CS533E Compactor	Luz trasera, lado derecho no f	LUZ TRASERA, LADO DERECHO NO F	30/10/2021		Corrective Order	WO Issued & Released	Compactor
698865	Coaster Bus	CAMBIO DE 1 NEUMATICO	CAMBIO DE NEUMATICO	30/10/2021		Corrective Order	WO Issued & Released	Bus
698887	Mobile equipment	CONSUMIBLES JUNIO21 KALTIRE	CONSUMIBLE JUNIO 21 EQ TACTICO	30/10/2021		Corrective Order	WO Issued & Released	Area
698960	Mobile equipment	consumibles agosto kaltire	CONSUMIBLES KALTIRE	30/10/2021		Corrective Order	WO Issued & Released	Area
699951	Mobile equipment	PRODUCTOS DE LIEMPEZA	TALLER GENERADORES	01/11/2021	90016529 60024055	Corrective Order	WO Issued & Released	Area
701342	Power Curbers 5700-C	CAMBIO DE PETATES	CAMBIO DE PETATES	03/11/2021		Corrective Order	WO Issued & Released	Kerb Machine
701444	Caterpillar TI1055clrc	PM01-PREVENTIVE MAINTENANCE	PM01-PREVENTIVE MAINTENANCE	03/11/2021		Corrective Order	WO Issued & Released	Telehender
701491	International 7400 SBA Fire Tr	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	03/11/2021	90016706 90016705	Corrective Order	WO Issued & Released	Fire truck
701597	PB002 COASTER TOYOTA	Instalacion de baterias	INSTALACION DE BATERIAS	03/11/2021		Corrective Order	WO Issued & Released	Bus
701933	Caterpillar 14H Motorgrader	REPARACION DE EJE DELANTERO	EQUIPO IASA	04/11/2021	90016733	Corrective Order	WO Issued & Released	Grader
702119	Caterpillar CS74 Compactor	USER REQUESTS (SEE ATTACHMENTS	INSPECTION	04/11/2021		Corrective Order	WO Issued & Released	Compactor
702303	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702312	Landcruiser DC	KIT DE HERRAMIENTA	POR PERDIDA DE HERRAMIENTAS	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702389	Landcruiser DC	SPARE TIRE REPLACEMENT	ASIGNAR ARO/NEUMATICO REPUESTO	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702390	Landcruiser DC	A/C INSPECTION & REPAIR	REQUIERE MANTENIMIENTO	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702392	Landcruiser DC	REPARAR INDICADOR COMBUSTIBLE	NO FUNCIONA	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702399	Landcruiser TC	REPARAR PUERTA TRASERA	PROBLEMA AL ABRIR	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702400	Landcruiser TC	REVISAR INDICADOR COMBUSTIBLE	NO FUNCIONA	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702401	Landcruiser DC	REPARAR ACCIONAMIENTO VIDRIOS	NO BAJAN NI SUBEN	04/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702402	Coaster	A/C INSPECTION & REPAIR	NO ENFRIA	04/11/2021		Corrective Order	WO Issued & Released	Bus
702536	Landcruiser DC	SPARE TIRE REPLACEMENT	ASIGNAR ARO/NEUMATICO REPUESTO	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702539	Landcruiser DC	CAMBIO BOMBILLO DIRECCIONAL	POSICION POSTERIOR DERECHO	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702549	Landcruiser TC	CAMBIO BOMBILLO POSTERIOR	NO FUNCIONA	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702555	Landcruiser DC	REPARAR MANIGUETA PUERTA	LADO CHOFER NO FUNCIONA	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702556	Landcruiser DC	REPARAR ALARMA RETROCESO	NO FUNCIONA	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702557	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702608	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	05/11/2021		Corrective Order	WO Issued & Released	Pickup truck
702627	Coaster	Suministro de bombillos	SUMINISTRO DE BOMBILLOS	05/11/2021		Corrective Order	WO Issued & Released	Bus
702629	Coaster	Suministro de bombillos	SUMINISTRO DE BOMBILLOS	05/11/2021		Corrective Order	WO Issued & Released	Bus
703336	Manitou Mht-X1490 9t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	06/11/2021		Corrective Order	WO Issued & Released	Telehender
703337	Manitou Mht-X1490 9t Telehand	PM1-PREVENTIVE MAINTENANCE	PM1-PREVENTIVE MAINTENANCE	06/11/2021		Corrective Order	WO Issued & Released	Telehender
703400	Mack Trucks GU	Reparacion de cilindro de grua	REPARACION DE CILINDRO DE GRUA	06/11/2021		Corrective Order	WO Issued & Released	Boom truck
703580	Grove GMK 4080 80TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	06/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
703814	Hyster E70xn 3t Forklift (E)	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Issued & Released	Forklift
703857	Hyster J40zt	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Issued & Released	Forklift
703898	Hilux DC	REPARAR SENSOR PUERTA TRASERA	REPARAR RADIO	07/11/2021		Corrective Order	WO Issued & Released	Pickup truck
703950	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021	90018145	PM Orders	WO Issued & Released	Generator
703951	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021		PM Orders	WO Issued & Released	Generator
703987	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Issued & Released	Manlift
704101	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704106	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704163	Hyster H700 Forklift	CAMBIO 2 LLANTAS	CORRECTIVO	07/11/2021		Corrective Order	WO Issued & Released	Forklift
704224	Caterpillar RM300	Reemplazo de cableado	REEMPLAZO DE CABLEADO DE CABINA Y CHASIS	07/11/2021		Corrective Order	WO Issued & Released	Road Reclaimer
704422	Heliport Offices	Filtracion de techo	FILTRACION DE TECHO	08/11/2021		Corrective Order	WO Issued & Released	Building
704470	Valle Grande Environment Offic	Reparacion de techo	REPARACION DE TECHO	08/11/2021		Corrective Order	WO Issued & Released	Building
704667	Landcruiser DC	REVISAR SISTEMA FRENOS	ENGRASE GENERAL EQUIPO	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704668	Landcruiser DC	REVISAR SISTEMA FRENOS	ENGRASE GENERAL EQUIPO	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704669	Landcruiser DC	REVISAR SISTEMA FRENOS	ABS / CONTROL TRACCION / ENGRASE	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
704670	Landcruiser TC	REVISAR SISTEMA FRENOS	ABS / CONTROL TRACCION / ENGRASE	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704671	Landcruiser DC	REVISAR SISTEMA FRENOS	ABS / CONTROL TRACCION / ENGRASE	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck
704816	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	08/11/2021		Corrective Order	WO Issued & Released	Pickup truck
705359	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	09/11/2021		PM Orders	WO Issued & Released	Pickup truck
705533	CAT 930K	CAMBIO DE GAVILANES	EQUIPO IASA	09/11/2021	90017295	Corrective Order	WO Issued & Released	Loader
706203	Coaster	INSPECCIÓN DE CONDICIONES	REVISAR CHECK LIST	10/11/2021		Corrective Order	WO Issued & Released	Bus
706205	Landcruiser DC	REPARAR LUCES	PRESENTA DANOS	10/11/2021		Corrective Order	WO Issued & Released	Pickup truck
706745	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	10/11/2021		Corrective Order	WO Issued & Released	Bus
706931	Landcruiser DC	A/C INSPECTION & REPAIR	REVISION Y REPARACION DEL A/C	11/11/2021		Corrective Order	WO Issued & Released	Pickup truck
707519	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Issued & Released	Pickup truck
707522	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	12/11/2021		PM Orders	WO Issued & Released	Pickup truck
707883	Hino Series 300 Truck	rep de sistema de direccion y	REP DE SISTEMA DE DIRECCION Y FRENOS	12/11/2021		Corrective Order	WO Issued & Released	Truck
708650	CAT 930K	CAMBIO DE BATERIA Y CABLE NEG	CAMBIO DE BATERIA Y CABLE NEG	13/11/2021		Corrective Order	WO Issued & Released	Loader
708978	Hyster H700 Forklift	LIMPIEZA Y LUBRICACION CADENAS	LUBRICACION DE EQUIPO	13/11/2021		Corrective Order	WO Issued & Released	Forklift
709413	Cargador 966H Wheel Loader	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Issued & Released	Loader
709455	Caterpillar 140K	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Issued & Released	Grader
709460	Caterpillar CS533E Compactor	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Issued & Released	Compactor
709510	Caterpillar RM300	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	14/11/2021		Corrective Order	WO Issued & Released	Road Reclaimer
709549	Cargador 966H Wheel Loader	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Issued & Released	Loader
709740	International 7400 SBA Fire Tr	INSPECCION GENERAL MECANICA	MECANICA Y ELECTRICA	14/11/2021		Corrective Order	WO Issued & Released	Fire truck
709758	Hyster E70xn 3t Forklift (E)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Issued & Released	Forklift
709833	Hyster E70xn 3t Forklift (E)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Issued & Released	Forklift
709834	Hyster H300 13t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Issued & Released	Forklift
709836	Hyster H800 32t Forklift (M)	LIMPIEZA Y LUBRICACION CADENAS	LUBRICACION DE EQUIPO	14/11/2021		Corrective Order	WO Issued & Released	Forklift
710138	Valle Grande Nursery Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	15/11/2021		PM Orders	WO Issued & Released	Building
710139	Valle Grande Archeology Office	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	15/11/2021		PM Orders	WO Issued & Released	Building
710140	Valle Grande Geology Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	15/11/2021		PM Orders	WO Issued & Released	Building
710141	Valle Grande Environment Offic	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	15/11/2021		PM Orders	WO Issued & Released	Building
710228	Freightliner M112 Truck Tip	Pieza que sostiene el machete	PIEZA QUE SOSTIENE EL MACHETE	15/11/2021		Corrective Order	WO Issued & Released	Tipper
710256	Landcruiser TC	cambio de alternador	ALTERNADOR EN MAL ESTADO	15/11/2021		Corrective Order	WO Issued & Released	Pickup truck
710317	Gallegos Flatbed Trailer	AJUSTE DE FRENOS	AJUSTE DE FRENOS	15/11/2021		Corrective Order	WO Issued & Released	Trailer / Flatbed / Lime Tank
710948	Caterpillar 226b Skid Steer L	REVISION DE EQUIPO	REVISION DE EQUIPO	15/11/2021		Corrective Order	WO Issued & Released	Skid Steer
710950	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	15/11/2021		Corrective Order	WO Issued & Released	Pickup truck
711205	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	16/11/2021		PM Orders	WO Issued & Released	Pickup truck
711271	Hyster H300 13t Forklift (M)	Reparacion	REPARACION	16/11/2021		Corrective Order	WO Issued & Released	Forklift
711423	Mobile equipment	CAPACITACION DE OPERADORES	PUEBTE GRUA	16/11/2021		Corrective Order	WO Issued & Released	Area
711512	Hyster H300 13t Forklift (M)	Reparacion de Hister	REPARACION DE HISTER	16/11/2021		Corrective Order	WO Issued & Released	Forklift
711574	TTP-0000-102	fuga de aceite, mando final	FUGA DE ACEITE	16/11/2021		Corrective Order	WO Issued & Released	Excavator
712118	Unimog Service Truck	Timón Dura y perdida de potenc	TIMÓN DURA Y PERDIDA DE POTENC	17/11/2021		Corrective Order	WO Issued & Released	Truck
712167	Toyota Hilux	REPARACIONES MENORES	CORRECTIVO	17/11/2021	50018233	Corrective Order	WO Issued & Released	Pickup truck
712655	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	18/11/2021		Corrective Order	WO Issued & Released	Trailer / Flatbed / Lime Tank
712952	Mack Trucks Gu813e	reparacion de frenos	REPARACION DE FRENOS	18/11/2021		Corrective Order	WO Issued & Released	Truck
713359	Hyster H800 32t Forklift (M)	PM01-PREVENTIVE MAINTENANCE	PM01-PREVENTIVE MAINTENANCE	19/11/2021		Corrective Order	WO Issued & Released	Forklift
713394	Caterpillar 307E Miniexcavator	reposicion de dientes	REPOSICION DE DIENTES	19/11/2021		Corrective Order	WO Issued & Released	Excavator
713494	Hyster E50Z-27 FORKLIFT	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	19/11/2021		Corrective Order	WO Issued & Released	Forklift
713515	Caterpillar 307E Miniexcavator	PM01 MANTENIMIENTO PREVENTIVO	PM01 MANTENIMIENTO PREVENTIVO	19/11/2021		Corrective Order	WO Issued & Released	Excavator
713557	Cargador 966H Wheel Loader	instalar extintor	INSTALAR EXTINTOR	19/11/2021		Corrective Order	WO Issued & Released	Loader
713628	Caterpillar 12M Motorgrader	PM02 MANTENIMIENTO PREVENTIVO	PREVENTIVE MAINTENANCE	19/11/2021		Corrective Order	WO Issued & Released	Grader
713650	Freightliner M2 106 Refrigerat	REEMPLAZO DE RETROVISOR	REEMPLAZO DE RETROVISOR	19/11/2021		Corrective Order	WO Issued & Released	Refrigerator truck
713663	Caterpillar 336DL Excavator	reparacion de sistema de A/A	RE[PARAR SISTEMA DE A/A	19/11/2021		Corrective Order	WO Issued & Released	Excavator
713935	Hyster H700 Forklift	INSPECCION DE EQUIPO	INSPECCION Y ENGRASE DE EQUIPO	20/11/2021		Corrective Order	WO Issued & Released	Forklift
713984	Caterpillar 740B EJ ADT	Reparacion de sistema afex	REPARACION SISTEMA AFEX	20/11/2021		Corrective Order	WO Issued & Released	Articulated dump truck
714003	Grove RT600E 50TON	Equipo Pierde Fuerza	EQUIPO PIERDE FUERZA	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714037	Grove RT600E 50TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714070	Grove RT880E 75TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714077	Grove GMK 4080 80TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714087	Terex RT5551 55TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714090	Grove RT650E 45TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714094	Grove RT9130E 120TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714095	Grove RT600E 50TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714098	Gmc Boom Truck	INSPECCION Y EVALUACION GRUA	INSPECCION DE REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714143	Internation F2674	INSPECCION Y EVALUACION GRUA	INSPECCION DE GRUA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714153	Internation 4400 SBA 6x4 Boom	INSPECCION Y EVALUACION GRUA	INSPECCION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714154	International F2674	INSPECCION Y EVALUACION GRUA	EVALUACION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714157	Freightliner FL112 Boom Truck	INSPECCION Y EVALUACION GRUA	INSPECCION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714158	Freightliner FL112	INSPECCION Y EVALUACION GRUA	INSPECCION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714159	Freightliner M2 106 Truck	CALIBRACION Y PRUEBAS FUNCIONA	INSPECCION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714164	Freightliner M2 112	INSPECCION Y EVALUACION GRUA	EVALUACION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
714166	Mack Trucks GU	INSPECCION Y EVALUACION GRUA	EVALUACION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714169	Boom Truck Iveco Tector	INSPECCION Y EVALUACION GRUA	EVALUACION REMUSA	20/11/2021		Corrective Order	WO Issued & Released	Boom truck
714216	Toyota LAND CRUISER S/W	MECHANICAL REPAIRS (PCR)	CORRECTIVE	20/11/2021	50018357	Corrective Order	WO Issued & Released	Pickup truck
714350	Caterpillar 300.9D MicoExcavat	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	20/11/2021		Corrective Order	WO Issued & Released	Excavator
714357	Caterpillar 14H Motorgrader	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	20/11/2021	90017964	Corrective Order	WO Issued & Released	Grader
714613	Caterpillar 226b Skid Steer L	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	WO Issued & Released	Skid Steer
714614	Caterpillar 226b Skid Steer L	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	WO Issued & Released	Skid Steer
714617	Caterpillar 226b Skid Steer L	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	WO Issued & Released	Skid Steer
714624	CAT 930K	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	WO Issued & Released	Loader
714637	USP&E GP700S/V-A 700 kVa	CAMBIO DE RADIADOR	RADIADOR CON FUGA POR FISURA	21/11/2021		Corrective Order	WO Issued & Released	Generator
714647	Ford Ranger	CAMBIO 3 NEUMATICOS	CORRECTIVO	21/11/2021		Corrective Order	WO Issued & Released	Pickup truck
714712	Caterpillar 14M Motorgrader	Fuga de aceite	FUGA DE ACEITE	21/11/2021		Corrective Order	WO Issued & Released	Grader
714741	JLG 1250 AJP Manlift	Cambio de mangueras hodraulica	FUGA DE ACEITE HIDRAULICO	21/11/2021		Corrective Order	WO Issued & Released	Manlift
714752	International 7400 SBA Fire Tr	INSPECCION GENERAL MECANICA	MECANICA Y ELECTRICA	21/11/2021		Corrective Order	WO Issued & Released	Fire truck
714774	Grove RT890 90TON	TOMA DE MUESTRAS DE ACEITES	TOMA DE MUESTRAS DE ACEITES	21/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714776	Terex RT5551 55TON	TOMA DE MUESTRAS DE ACEITES	TOMA DE MUESTRAS DE ACEITES	21/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714783	GROVE RT700E 60TON	TOMA DE MUESTRAS DE ACEITES	TOMA DE MUESTRAS DE ACEITES	21/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
714786	John Deere 9370R Tractor	INSPECCION GENERAL EQUIPO	INSPECCION GENERAL EQUIPO	21/11/2021		Corrective Order	WO Issued & Released	Tractor
714804	John Deere 9370R Tractor	INSPECCION GENERAL EQUIPO	INSPECCION GENERAL EQUIPO	21/11/2021		Corrective Order	WO Issued & Released	Tractor
714806	John Deere 9370R Tractor	INSPECCION GENERAL Y ENGRASE	INSPECCION MECANICA	21/11/2021		Corrective Order	WO Issued & Released	Tractor
714809	Tennant T7 Scrubber	INSPECCION GENERAL MECANICA	INSPECCION MECANICA	21/11/2021		Corrective Order	WO Issued & Released	Scrubber / Sweeper
714813	Tennant T7 Scrubber	INSPECCION MECANICA	INSPECCION MECANICA	21/11/2021		Corrective Order	WO Issued & Released	Scrubber / Sweeper
714818	Tennant S30 Sweeper	INSPECCION MECANICA	INSPECCION MECANICA	21/11/2021		Corrective Order	WO Issued & Released	Scrubber / Sweeper
714819	Tennant S30 Sweeper	INSPECCION MECANICA	EQUIPO COPAMA	21/11/2021		Corrective Order	WO Issued & Released	Scrubber / Sweeper
714856	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021		PM Orders	WO Issued & Released	Generator
714867	SDMO J30U 38 kVa	VERIFICACION DE HOROMETRO	CONFLICTO DE INFORMACION	21/11/2021		Corrective Order	WO Issued & Released	Generator
714918	FG WILSON P88-3 80 kVa	VERIFICACION DE HOROMETRO	VERIFICACION DE HOROMETRO	21/11/2021		Corrective Order	WO Issued & Released	Generator
714921	ATLAS COPCO HILIGHT V5+	VERIFICACION DE HOROMETRO	VERIFICACION DE HOROMETRO	21/11/2021		Corrective Order	WO Issued & Released	Light Tower
714924	ATLAS COPCO HILIGHT V5+	VERIFICACION DE HOROMETRO	VERIFICACION DE HOROMETRO	21/11/2021		Corrective Order	WO Issued & Released	Light Tower
714925	DOOSAND 1005	VERIFICACION DE HOROMETRO	VERIFICACION DE HOROMETRO	21/11/2021		Corrective Order	WO Issued & Released	Light Tower
714964	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021	839 horas	PM Orders	WO Issued & Released	Generator
714987	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021	63238 hrs	PM Orders	WO Issued & Released	Generator
714990	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021		PM Orders	WO Issued & Released	Generator
714992	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021		PM Orders	WO Issued & Released	Generator
714999	Ford F550	INSPECCION GENERAL MECANICA	MACANICA Y ELECTRICA	21/11/2021		Corrective Order	WO Issued & Released	Pickup truck
715352	Freightliner Cl 120	FUGA DE AIRE / ASIENTO / Luces	FUGA DE AIRE / ASIENTO / LUCES	22/11/2021		Corrective Order	WO Issued & Released	Mule truck
715412	Cargador 966H Wheel Loader	Rompió manguera del turbo	ROMPIÓ MANGUERA DEL TURBO	22/11/2021		Corrective Order	WO Issued & Released	Loader
715432	Caterpillar 14M Motorgrader	cambio de sellos	SAMBIO DE SELLOS	22/11/2021		Corrective Order	WO Issued & Released	Grader
715640	Landcruiser DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	22/11/2021		Corrective Order	WO Issued & Released	Pickup truck
715641	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	22/11/2021		Corrective Order	WO Issued & Released	Pickup truck
715642	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	22/11/2021		Corrective Order	WO Issued & Released	Pickup truck
715651	Hiace Bus	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	23/11/2021		Corrective Order	WO Issued & Released	Bus
716066	Mobile equipment	Suministros de taller	INSUMOS PARA TOMA DE MUESTRAS EN EQUIPOS EN GENERAL	23/11/2021		Corrective Order	WO Issued & Released	Area
716096	LV215 HILUX TOYOTA	MECHANICAL REPAIRS (PCR)	CORRECTIVE	23/11/2021	50018422	Corrective Order	WO Issued & Released	Light Vehicles
716283	Ford 450	MECHANICAL REPAIRS (PCR)	CORRECTIVE	23/11/2021	50018453	Corrective Order	WO Issued & Released	Pickup truck
716314	Caterpillar 236d Skid Steer L	Reparacion de A/C	REPARACION DE A/C	23/11/2021		Corrective Order	WO Issued & Released	Skid Steer
716315	Hyster H300 13t Forklift (M)	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	WO Issued & Released	Forklift
716317	Hyster H800 32t Forklift (M)	Base para extintor ABC 20lb	BASE PARA EXTINTOR ABC 20LB	23/11/2021		Corrective Order	WO Issued & Released	Forklift
716319	Freightliner Columbia Cl112	reparacion de sistema electric	REPARACION DE SISTEMA ELECTRICA	23/11/2021		Corrective Order	WO Issued & Released	Mule truck
716675	Hilux DC	Revision general	PITO DE REVERSA, REVISION DE CARROCERIA	24/11/2021		Corrective Order	WO Issued & Released	Pickup truck
716706	Linde T30D	problema con montacarga	PROBLEMA CON MONTACARGA	24/11/2021		Corrective Order	WO Issued & Released	Forklift
716759	Gallegos Flatbed Trailer	ACEITE	ACEITE	24/11/2021		Corrective Order	WO Issued & Released	Trailer / Flatbed / Lime Tank
716832	Case 110JX Tractor Cable Handl	Revision de equipo	NO ARRANCA	24/11/2021		Corrective Order	WO Issued & Released	Tractor
716900	Caterpillar 14M Motorgrader	Revision de fuga de diesel	FUGA DE DIESEL POR EL TANQUE DE COMBUSTIBLE	24/11/2021		Corrective Order	WO Issued & Released	Grader
717011	ATR-0000-001 4+320 AGRICO	Reparacion de W/W	REPASRACION DE W/W	24/11/2021		Corrective Order	WO Issued & Released	Tractor
717224	Hyster H700 Forklift	cambio de manguera	MANGUERA DE TURBO ROTA	25/11/2021		Corrective Order	WO Issued & Released	Forklift
717278	Caterpillar 14H Motorgrader	Reemplazo de cuchillas	REEMPLAZO DE CUCHILLAS	25/11/2021		Corrective Order	WO Issued & Released	Grader
717282	Hyster H700 Forklift	cambio de manguera	CAMBIO DE MANGUERA	25/11/2021		Corrective Order	WO Issued & Released	Forklift
717295	AC066 XAVS450 ATLAS COPCO	LAVADO GENERAL	MANTENIMIENTO CORRECTIVO	25/11/2021		Corrective Order	WO Issued & Released	Compressor
717297	Manitou Mht-X1490 9t Telehand	Llanta Trasera Derecha-Flat	LLANTA TRASERA DERECHA-FLAT	25/11/2021		Corrective Order	WO Issued & Released	Telehender
717304	Freightliner M112 Truck Tip	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	25/11/2021		Corrective Order	WO Issued & Released	Tipper
717309	Magni HTH 10,10 Telehandler	CAMBIO 4 LLANTAS	CORRECTIVO	25/11/2021		Corrective Order	WO Issued & Released	Telehender
717551	Faresin FM4000 / 17F Telehandl	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	25/11/2021		Corrective Order	WO Issued & Released	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
717609	JLG 800 AJ Manlift	Revision de fuga hidraulica	REVISION DE FUGA HIDRAULICA	25/11/2021		Corrective Order	WO Issued & Released	Manlift
717644	Intraax 53121 Hendrickso	Cambio de bandas de frenos	CAMBIO DE BANDAS DE FRENOS	25/11/2021		Corrective Order	WO Issued & Released	Trailer / Flatbed / Lime Tank
717666	Caterpillar 236d Skid Steer L	PM01-PREVENTIVE MAINTENANCE	PM01-PREVENTIVE MAINTENANCE	25/11/2021		Corrective Order	WO Issued & Released	Skid Steer
717674	Freightliner M112 Truck Tip	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	25/11/2021		Corrective Order	WO Issued & Released	Tipper
717721	Terex RT670 64TON	Sin fuerza	SIN FUERZA	26/11/2021		Corrective Order	WO Issued & Released	Crane/Hoist
717843	Freightliner M112 Truck Tip	Cambio de mangueras	CAMBIO DE MANGUERAS	26/11/2021		Corrective Order	WO Issued & Released	Tipper
717912	Hyster H700 Forklift	cambio de llantas	LLANTAS EN MAL ESTADO	26/11/2021		Corrective Order	WO Issued & Released	Forklift
717940	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	26/11/2021		Corrective Order	WO Issued & Released	Pickup truck
717943	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	26/11/2021		Corrective Order	WO Issued & Released	Pickup truck
717944	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	26/11/2021		Corrective Order	WO Issued & Released	Pickup truck
717950	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	26/11/2021		Corrective Order	WO Issued & Released	Pickup truck
717955	EX036 EC480DL Volvo	EC480DL-MAINTENANCE 500 HRS	EC480DL-MAINTENANCE 500 HRS	26/11/2021		PM proposal JDE	WO Issued & Released	Excavator
717962	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	26/11/2021		Corrective Order	WO Issued & Released	Pickup truck
717972	Caterpillar 14H Motorgrader	BLADE SUPPORT NUTS	CORRECTIVE	26/11/2021		Corrective Order	WO Issued & Released	Grader
717983	LV162 RANGERS FORD	revision de cajas de cambios	CORRECTIVO	26/11/2021	79,118.00 km	Corrective Order	WO Issued & Released	Light Vehicles
718017	Coaster Bus	revision de bomba de inyeccion	CORRECTIVO	26/11/2021	82,410.00 kms	Corrective Order	WO Issued & Released	Bus
718029	LV162 RANGERS FORD	revision de transmision	CORRECTIVO	26/11/2021	79,118.00 km	Corrective Order	WO Issued & Released	Light Vehicles
718070	Caterpillar 426f2 Backhoe	PM02-MANTENIMIENTO PREVENTIVO	PERSONAL DE IASA	26/11/2021		Corrective Order	WO Issued & Released	Backhoe
718077	Caterpillar 416E	PM01-MANTENIMIENTO PREVENTIVO	PM01-PREVENTIVE MAINTENANCE	26/11/2021		Corrective Order	WO Issued & Released	Backhoe
600343	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	01/06/2021		PM Orders	WO Completed	Pickup truck
600394	Caterpillar 735B	Revision de equipo	FILTRO DE TRANSMISION TAPONADO	01/06/2021		Corrective Order	WO Completed	Articulated dump truck
600396	PRAMAC GSW80P 83 kVa	CORRECTIVO	CAMBIO DE CONTROL Y PROGRAMAR	01/06/2021	6432 hrs	Corrective Order	WO Completed	Generator
600400	PRAMAC GSW65 48 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	01/06/2021	22446 hrs	Corrective Order	WO Completed	Generator
600453	Cargador 966H Wheel Loader	Vidrio despegado por caerse	VIDRIO DESPEGADO POR CAERSE	01/06/2021		Corrective Order	WO Completed	Loader
600455	Caterpillar 740B	fuga de aceite hidráulico	FUGA DE ACEITE HIDRÁULICO	01/06/2021		Corrective Order	WO Completed	Articulated dump truck
600471	Caterpillar 740B EJ ADT	problema con frenos de parking	PROBLEMA CON FRENOS DE PARKING	01/06/2021		Corrective Order	WO Completed	Articulated dump truck
600475	Caterpillar 14M Motorgrader	Alarma de bloqueo activada	ALARMA DE BLOQUEO ACTIVADA	01/06/2021		Corrective Order	WO Completed	Grader
600476	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE EXITATRIZ	01/06/2021	13599 horas	Corrective Order	WO Completed	Generator
600496	Landcruiser DC	CAMBIO POLEA AJUSTE/COMPRESOR	CAMBIO CORREA COMPRESOR/CAUCHO BANDAS	01/06/2021	38542	Corrective Order	WO Completed	Pickup truck
600499	Landcruiser DC	CAMBIO BATERIA	NO MANTIENE CARGA	01/06/2021		Corrective Order	WO Completed	Pickup truck
600507	Landcruiser TC	REPARAR SISTEMA ELECTRICO	CABLE ROTO	01/06/2021	54147	Corrective Order	WO Completed	Pickup truck
600508	Landcruiser DC	INSTALAR PERTIGA	MANTENIMIENTO CORRECTIVO	01/06/2021	76165	Corrective Order	WO Completed	Pickup truck
600509	Freightliner M112 Truck Tip	TUERCAS FLOJAS	TUERCAS FLOJAS	01/06/2021		Corrective Order	WO Completed	Tipper
600593	Caterpillar 740b Ej	Cambio pin de cabina ausente	CAMBIO PIN DE CABINA AUSENTE	01/06/2021		Corrective Order	WO Completed	Articulated dump truck
600607	Cargador 966H Wheel Loader	manteniento de sistema afex	MANTENIMIENTO DE DE SISTEMA AFEX	01/06/2021		Corrective Order	WO Completed	Loader
600609	Gallegos Lime Tank	FUGA POR LINEA DE DISTRIBUACIO	FUGA POR LINEA DE DISTRIBUACIO	01/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
600637	Caterpillar 740B EJ ADT	fuga de aceite hidráulico	FUGA DE ACEITE HIDRÁULICO	01/06/2021		Corrective Order	WO Completed	Articulated dump truck
600649	Hyster H800 32t Forklift (M)	Reparacion de circuto electric	REPARACION DE CIRCUITO ELECTRICO DE W/W	01/06/2021		Corrective Order	WO Completed	Forklift
600652	Hyster H70ft 3t Forklift (M)	Reparacion de llantas	REPARACION DE LLANTAS	01/06/2021		Corrective Order	WO Completed	Forklift
600654	Manitou Mht-X1490 9t Telehand	Fuga de aceite	FUGA DE ACEITE	01/06/2021		Corrective Order	WO Completed	Telehender
600675	Caterpillar 140K	Sensor de AFex en corto	SENSOR DE AFEX EN CORTO	01/06/2021		Corrective Order	WO Completed	Grader
600678	Ferrari F478	ALTERNATOR REPAIR (GPE)	CORRECTIVE	01/06/2021	50013343	Corrective Order	WO Completed	Reach Stacker
600886	Grove GMK 4080 80TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	02/06/2021		PM Orders	WO Completed	Crane/Hoist
600887	Grove GMK4100L 100TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	02/06/2021		PM Orders	WO Completed	Crane/Hoist
600889	Terex RT5551 55TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	02/06/2021		PM Orders	WO Completed	Crane/Hoist
600896	JLG 1250 AJP Manlift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	02/06/2021		PM Orders	WO Completed	Manlift
600897	JLG 1850 AJ Manlift	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	02/06/2021		PM Orders	WO Completed	Manlift
600937	Freightliner M2 106 Sucker Tru	Cambio de Blower	CAMBIO DE BLOWER	02/06/2021		Corrective Order	WO Completed	Sucker truck
600957	Coaster	Reparación de neumático	CAMBIO DE NEUMÁTICO	02/06/2021		Corrective Order	WO Completed	Bus
600963	Broce Broom RJT 350	Equipo no enciende	AIRE EN EL SISTEMA DE COMBUSTIBLE	02/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
600968	Caterpillar 14M Motorgrader	necesita cambio de filtro de a	NECESITA CAMBIO DE FILTRO DE A	02/06/2021		Corrective Order	WO Completed	Grader
600975	Caterpillar 740B EJ ADT	Llanta flat	LLANTA FLAT	02/06/2021		Corrective Order	WO Completed	Articulated dump truck
600991	Grove RT880E 75TON	FUGA HIDRAULICA	FUGA HIDRAULICA	02/06/2021		Corrective Order	WO Completed	Crane/Hoist
600993	Broce Broom 250B	Tiene fuga en el radiador	TIENE FUGA EN EL RADIADOR	02/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
601011	Coaster	Cambio de dos llanatas	CAMBIO DE DOS LLANATAS	02/06/2021		Corrective Order	WO Completed	Bus
601019	SDMO J60U 60KVA	CAMBIO DE GENERADOR	DESCONEXION & CONEXION DE GENERADOR	02/06/2021	11574 horas	Corrective Order	WO Completed	Generator
601021	Grove RT880E 75TON	FUGA HIDRAULICA	FUGA HIDRAULICA	02/06/2021		Corrective Order	WO Completed	Crane/Hoist
601077	PB002 COASTER TOYOTA	CAMBIO BATERIA	REPARACION VARIAS	02/06/2021	286248	Corrective Order	WO Completed	Bus
601084	Freightliner M2 106 Sucker Tru	Problemas de direccion	PROBLEMAS DE DIRECCION	02/06/2021		Corrective Order	WO Completed	Sucker truck
601122	Freightliner CI 120	ARRANQUE /LUCES/ RADIADOR	ARRANQUE /LUCES/ RADIADOR	02/06/2021		Corrective Order	WO Completed	Mule truck
601124	Gallegos Flatbed Trailer	CAMBIO DFE BOLSA DE AIRE	CAMBIO DFE BOLSA DE AIRE	02/06/2021	90009035	Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
601152	Freightliner Columbia CI112	Revisar niveles de los fluido	REVISAR NIVEL DE ACEITE	02/06/2021		Corrective Order	WO Completed	Mule truck
601166	Terex RT5551 55TON	Reparacion de llantas	REPARACION DE LLANTAS	02/06/2021		Corrective Order	WO Completed	Crane/Hoist
601197	Intraax 53121 Hendrickso	REPAIR A FLAT TIRE	REPAIR A FLAT TIRE	02/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
601205	Caterpillar D8T Dozer	tapa trasera desprendida	REPARAR TAPA TRASERA	02/06/2021		Corrective Order	WO Completed	Dozer
601208	Caterpillar 236d Skid Steer L	Equipo se recalienta	EQUIPO SE RECALIENTA	02/06/2021		Corrective Order	WO Completed	Skid Steer
601210	Gallegos Flatbed Trailer	REPAIR 2 FLATS TIRE	REPAIR 2 FLATS TIRE	02/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
601347	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	03/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
601384	John Deere 9370R Tractor	Confección de Manguera	CONFECCIÓN DE MANGUERA HIDRÁULICA	03/06/2021		Corrective Order	WO Completed	Tractor
601420	International 7400 SBA Water T	llanta flat	LLANTA FLAT	03/06/2021		Corrective Order	WO Completed	Water truck
601421	International 7400 SBA Water T	Fuga en tanque de agua	FUGA EN TANQUE DE AGUA	03/06/2021		Corrective Order	WO Completed	Water truck
601443	Intraax 53121 Hendrickso	FUGA DE AIRE	FUGA DE AIRE	03/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
601448	Hilux DC	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	03/06/2021		PM Orders	WO Completed	Pickup truck
601452	Caterpillar 12M Motorgrader	Se activan las alarmas cuando	SE ACTIVAN LAS ALARMAS CUANDO	03/06/2021		Corrective Order	WO Completed	Grader
601453	Caterpillar 12M Motorgrader	Necesita hoja de corte	NECESITA HOJA DE CORTE	03/06/2021		Corrective Order	WO Completed	Grader
601489	Caterpillar 236d Skid Steer L	Cambio de solenoide de fan	CAMBIO DE SOLENOIDE DE FAN	03/06/2021	90009036	Corrective Order	WO Completed	Skid Steer
601566	Unimog Service Truck	Fugas y direccion parte delant	FUGAS Y DIRECCION PARTE DELANT	03/06/2021		Corrective Order	WO Completed	Truck
601578	John Deere 9370R Tractor	Llanta flat	LLANTA FLAT	03/06/2021		Corrective Order	WO Completed	Tractor
601586	Hyster H700 Forklift	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	03/06/2021		Corrective Order	WO Completed	Forklift
601590	JLG 800 AJ Manlift	Equipo Bloqueado	EQUIPO BLOQUEADO	03/06/2021		Corrective Order	WO Completed	Manlift
601601	Caterpillar 740B	alarma de filtro obstruido	ALARMA DE FILTRO OCTRUIDO	03/06/2021		Corrective Order	WO Completed	Articulated dump truck
601640	Freightliner Columbia C112	Fuga de liquido refrigerante	FUGA DE LIQUIDO REFRIGERANTE	03/06/2021		Corrective Order	WO Completed	Mule truck
601642	New Holland Lm 1745	Inspeccion por incidente	INSPECCION GENERA POR INCIDENTE	03/06/2021		Corrective Order	WO Completed	Telehender
601643	Freightliner CI 120	fuga de aire neumatico	FUGA DE AIRE NEUMATICO	03/06/2021		Corrective Order	WO Completed	Mule truck
601644	Intraax 53121 Hendrickso	Fuga de neumatico	FUGA DE NEUMATICO	03/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
601646	Caterpillar DE88E0 58 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE CORREA	03/06/2021	35065 horas	Corrective Order	WO Completed	Generator
601666	Unimog Service Truck	CAMBIO DE MOTOR	CORRECTIVO	03/06/2021		Corrective Order	WO Completed	Truck
601677	Mobile equipment	RECEPTACULOS RETENCION	RETENER ACEITE PARA TALLER	03/06/2021		Corrective Order	WO Completed	Area
601679	Landcruiser DC	CAMBIO AMORTIGUADOR TRASERO	CAMBIO CAUCHO/POLEA TENSORA/	03/06/2021	68371	Corrective Order	WO Completed	Pickup truck
601680	Landcruiser DC	CAMBIO HUB AUTOMATICO	GOLPE EN LA 4X4	03/06/2021	60467	Corrective Order	WO Completed	Pickup truck
601682	Landcruiser DC	CAMBIO BALINERAS/AMORTIGUADORE	CAMBIO TERMINALES DIRECCION/BUJES	03/06/2021	48570	Corrective Order	WO Completed	Pickup truck
601684	Landcruiser DC	REPARAR COCOBOLAS	AJUSTE FRENOS/LIMPIEZA BANDA	03/06/2021	48570	Corrective Order	WO Completed	Pickup truck
601692	Landcruiser DC	CAMBIO BANDA FRENO	CAMBIO CAUCHO AMORTIGUADOR	03/06/2021	72234	Corrective Order	WO Completed	Pickup truck
601693	Landcruiser DC	CAMBIO CORREA A/A	CAMBIO BOMBILLOS	03/06/2021	81201	Corrective Order	WO Completed	Pickup truck
601694	Landcruiser DC	CAMBIO COMPRESOR AA	CARGA DE GAS REFRIGERANTE	03/06/2021	82051	Corrective Order	WO Completed	Pickup truck
601871	WT013 H7 CISTERNA SINOTRUK	cAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	04/06/2021		Corrective Order	WO Completed	Water truck
601898	Landcruiser DC	CAMBIO MUELLES	MANTENIMIENTO CORRECTIVO	04/06/2021	64021	Corrective Order	WO Completed	Pickup truck
601901	Hilux DC	CAMBIO MUELLES	REPARAR SISTEMA SUSPENSION	04/06/2021	59,538	Corrective Order	WO Completed	Pickup truck
601904	Landcruiser DC	CAMBIO MUELLES/BASE AMORTIGUAD	MANTENIMIENTO CORRECTIVO	04/06/2021	90775	Corrective Order	WO Completed	Pickup truck
601906	John Deere 310K	Reparación de neumático y sist	REPARACIÓN DE NEUMÁTICO Y SISTEMA DE LUCES	04/06/2021		Corrective Order	WO Completed	Backhoe
601910	Landcruiser DC	CAMBIO BALINERA POLEA	REPARAR CABLEADO ABS	04/06/2021	55156	Corrective Order	WO Completed	Pickup truck
601914	Landcruiser DC	CAMBIO TERMINAL DIRECCION	MANTENIMIENTO CORRECTIVO	04/06/2021	83000	Corrective Order	WO Completed	Pickup truck
601915	Landcruiser DC	CAMBIO EJES/BALINERA COCOBOLA	CAMBIO PUNTA FLECHA/BALINERA RUEDA TRASERA	04/06/2021	80112	Corrective Order	WO Completed	Pickup truck
601918	Landcruiser DC	CAMBIO BUJE MUELLE	CAMBIO TERMINALES DIRECCION	04/06/2021	97909	Corrective Order	WO Completed	Pickup truck
601920	Landcruiser DC	CAMBIO CALIPER/CAUCHOS	CAMBIO SPRING BANDAS	04/06/2021	49,575	Corrective Order	WO Completed	Pickup truck
601924	Landcruiser DC	CAMBIO AMORTIGUADOR/BANDAS	CAMBIO ESCOBILLAS	04/06/2021	57133	Corrective Order	WO Completed	Pickup truck
601942	Broce Broom RJT 350	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE	04/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
601943	Landcruiser DC	CAMBIO RETENEDORA/PUNTA FLECHA	CAMBIO RETENEDORA COCOBOLA/TUERCA SPINDLE/FREEWHEEL	04/06/2021	43353	Corrective Order	WO Completed	Pickup truck
601945	Landcruiser DC	CAMBIO BUJES/BUSHING BARRA EST	CAMBIO EJE FRONTAL/RETENEDORA	04/06/2021	55359	Corrective Order	WO Completed	Pickup truck
601948	Landcruiser DC	CAMBIO SENSOR ABS	AJUSTE FRENO EMERGENCIA	04/06/2021	55,480	Corrective Order	WO Completed	Pickup truck
601950	Landcruiser DC	CAMBIO HOUSING COMPLETO	CAMBIO TODO COMPONENTES	04/06/2021	55,813	Corrective Order	WO Completed	Pickup truck
601952	Landcruiser DC	CAMBIO SENSOR ABS	MANTENIMIENTO CORRECTIVO	04/06/2021	55,813	Corrective Order	WO Completed	Pickup truck
601956	Landcruiser DC	REPARACION TOLVA	MANTENIMIENTO CORRECTIVO	04/06/2021	58,185	Corrective Order	WO Completed	Pickup truck
601957	Landcruiser DC	CAMBIO CORREA UNICA/BOMBILLO	CAMBIO LAMPARA TRASERA	04/06/2021	51202	Corrective Order	WO Completed	Pickup truck
601963	Hilux DC	CAMBIO CABLE FRENO	AJUSTE FRENO EMERGENCIA	04/06/2021	42315	Corrective Order	WO Completed	Pickup truck
601966	Hilux DC	CAMBIO KIT EMBRAGUE	MANTENIMIENTO CORRECTIVO	04/06/2021	38047	Corrective Order	WO Completed	Pickup truck
601967	Hilux DC	A/C INSPECTION & REPAIR	RECARGA GAS A/C	04/06/2021	38389	Corrective Order	WO Completed	Pickup truck
601968	Hilux DC	CAMBIO LAMPARA/EJE IMPULSO	CAMBIO MUELLES/LUCES	04/06/2021	52901	Corrective Order	WO Completed	Pickup truck
601970	Caterpillar 307E Miniexcavator	PREVENTIVE MAINTENANCE	OIL & FILTERS REPLACEMENT	04/06/2021		Corrective Order	WO Completed	Excavator
601975	Caterpillar 740B EJ	Neumatico #3 baja de aire	NEUMATICO #3 BAJA DE AIRE	04/06/2021		Corrective Order	WO Completed	Articulated dump truck
601978	Hilux DC	REPARAR ROSCA TORNILLO	SOPORTE BARRA ESTABILIZADORA	04/06/2021	52,907	Corrective Order	WO Completed	Pickup truck
601984	Hilux DC	CAMBIO HOJA MUELLES	MANTENIMIENTO CORRECTIVO	04/06/2021	58247	Corrective Order	WO Completed	Pickup truck
601985	Hilux DC	CAMBIO KIT EMBRAGUE	MANTENIMIENTO CORRECTIVO	04/06/2021	49084	Corrective Order	WO Completed	Pickup truck
601988	Hilux DC	CAMBIO AMORTIGUADOR DELANTERO	CAMBIO TERMINAL DIRECCION	04/06/2021	49746	Corrective Order	WO Completed	Pickup truck
601990	Landcruiser DC	CAMBIO ALTERNADOR	PENDIENTE VIDRIO/EVAPORADOR	04/06/2021	55480	Corrective Order	WO Completed	Pickup truck
601999	Hilux DC	CAMBIO CAUCHO BARRA	CAMBIO HORQUILLA CLUTCH	04/06/2021	80520	Corrective Order	WO Completed	Pickup truck
602001	PRAMAC GSW560V 407 kVa	CAMBIO INYECTORES	FALLA DE 06 INYECTORES	04/06/2021	18779 horas	Corrective Order	WO Completed	Generator
602003	Grove RT600E 50TON	reparacion de freno	REPARACION DE FRENO	04/06/2021		Corrective Order	WO Completed	Crane/Hoist
602006	Hyster E70xn 3t Forklift (E)	Cambio de freno de estacionam	CAMBIO DE FRENO DE ESTACIONAMIENTO	04/06/2021		Corrective Order	WO Completed	Forklift
602007	Hyster E70xn 3t Forklift (E)	Cambio de palanca de cambios	CAMBIO DE PALANCA DE CAMBIOS	04/06/2021		Corrective Order	WO Completed	Forklift
602017	Freightliner CI 120	Cambio de baterias	CAMBIO DE 4 BATERIAS	04/06/2021		Corrective Order	WO Completed	Mule truck
602020	Caterpillar 740B EJ ADT	Tapadera de la Tolva no cierra	TAPADERA DE LA TOLVA NO CIERRA	04/06/2021		Corrective Order	WO Completed	Articulated dump truck
602032	Caterpillar 12M Motorgrader	Cambio de dientes	CAMBIO DE DIENTES	04/06/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
602049	Caterpillar 336DL Excavator	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	04/06/2021		Corrective Order	WO Completed	Excavator
602063	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	04/06/2021		Corrective Order	WO Completed	Mule truck
602064	Gallegos 28M3 Lime Tank	LLANTA FLAT	LLANTA FLAT	04/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
602077	Landcruiser TC	CAMBIO ALTERNADOR/BATERIA	CAMBIO POLEA/CORREA UNICA	04/06/2021 52898		Corrective Order	WO Completed	Pickup truck
602078	Landcruiser TC	CAMBIO ALARMA RETROCESO	CAMBIO BOMBILLOS	04/06/2021 57849		Corrective Order	WO Completed	Pickup truck
602081	Landcruiser TC	CAMBIO HOUSING/COCOBOLAS	CAMBIO PUNTA FLECHA/EJE/SPINDLE/CLIP	04/06/2021 60243		Corrective Order	WO Completed	Pickup truck
602082	Hilux DC	CAMBIO BANDAS FRENO	CAMBIO MOTOR ARRANQUE/CRUCETAS	04/06/2021 33165		Corrective Order	WO Completed	Pickup truck
602085	Landcruiser TC	CAMBIO AMORTIGUADOR	AMORTIGUADORES DELANTEROS	04/06/2021 23252		Corrective Order	WO Completed	Pickup truck
602086	Hilux DC	CAMBIO MUELLES	CAMBIO TORNILLO CENTRO HORQUILLA	04/06/2021 25473		Corrective Order	WO Completed	Pickup truck
602092	Hilux DC	CAMBIO PERNO/TUERCAS	MANTENIMIENTO CORRECTIVO	04/06/2021 42261		Corrective Order	WO Completed	Pickup truck
602094	Hilux DC	CAMBIO CAUCHO BARRA ESTABILIZA	REPARACION ABS	04/06/2021 54379		Corrective Order	WO Completed	Pickup truck
602119	Freightliner M112 Truck Tip	2 LLANTAS EXPLOTADAS	2 LLANTAS EXPLOTADAS	04/06/2021		Corrective Order	WO Completed	Tipper
602126	Caterpillar 12M Motorgrader	La hoja de bronce se cayó	LA HOJA DE BRONCE SE CAYÓ	04/06/2021		Corrective Order	WO Completed	Grader
602131	Hilux DC	CAMBIO ACTUADOR/BANDAS	CAMBIO SENSOR/BALINERA RUEDA	04/06/2021 40155		Corrective Order	WO Completed	Pickup truck
602133	Landcruiser TC	CAMBIO BALINERA/TACOS/CALIPER	CAMBIO TERMINALES DIRECCION/TUERCA AJUSTADORA	04/06/2021 50903		Corrective Order	WO Completed	Pickup truck
602135	Landcruiser TC	CAMBIO FREWHEEL	MANTENIMIENTO CORRECTIVO	04/06/2021 49,586		Corrective Order	WO Completed	Pickup truck
602137	Landcruiser DC	CAMBIO RETENEDORAS EJE DELANTE	MANTENIMIENTO CORRECTIVO	04/06/2021 54354		Corrective Order	WO Completed	Pickup truck
602138	Landcruiser TC	CAMBIO SPINDLE/TUERCA AJUSTADO	CAMBIO RETENEDORA RUEDA/BALINERA RUEDA/FREWHEEL	04/06/2021 13630		Corrective Order	WO Completed	Pickup truck
602144	Caterpillar 14H Motorgrader	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	04/06/2021		Corrective Order	WO Completed	Grader
602146	Hilux DC	CAMBIO PERTIGA	MANTENIMIENTO CORRECTIVO	04/06/2021 16334		Corrective Order	WO Completed	Pickup truck
602158	Gallegos 28M3 Lime Tank	LLANTA FLAT	LLANTA FLAT	04/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
602161	Freightliner CI 120	RETROVISOR / TABLERO / TUERCA	RETROVISOR / TABLERO / TUERCA	04/06/2021		Corrective Order	WO Completed	Mule truck
602170	Manitou Mht-X860 6t Telehand	Fuga de aceite Telehandler	FUGA DE ACEITE TELEHANDER	04/06/2021 90008636		Corrective Order	WO Completed	Telehender
602180	Intraax 53121 Hendrickso	INSPECCION BUJES,LUCES,PINES	INSPECCION GENERAL DEL EQUIPO	04/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
602192	Hilux DC	REPARACION CABLEADO ABS	MANTENIMIENTO CORRECTIVO	04/06/2021 400		Corrective Order	WO Completed	Pickup truck
602196	Hilux DC	CAMBIO ESCOLTA	MANTENIMIENTO CORRECTIVO	04/06/2021 2608		Corrective Order	WO Completed	Pickup truck
602197	Coaster	CAMBIO CILINDRO FRENOS	CAMBIO KIT BANDAS/SPRING	04/06/2021 27416		Corrective Order	WO Completed	Bus
602200	Coaster	ENDEREZADO RESPIRADOR	BASE SNORKEL POR DEFORMACION	04/06/2021 4205		Corrective Order	WO Completed	Bus
602203	Coaster	CAMBIO BANDA FRENO/SPRING	CAMBIO CILINDRO FRENO/BOMBILLOS/	04/06/2021 26849		Corrective Order	WO Completed	Bus
602209	Coaster	CAMBIO LAPARA LH	MANTENIMIENTO CORRECTIVO	04/06/2021 11660		Corrective Order	WO Completed	Bus
602213	GROVE GMK 5170 170TON	Reparacion de fuga deaceite	REPARACION DE FUGA DE ACEITE HIDRAULICO	04/06/2021		Corrective Order	WO Completed	Crane/Hoist
602214	Landcruiser DC	CAMBIO CLUTCH/PLATA/DISCO	CAMBIO BALINERA	04/06/2021 88236		Corrective Order	WO Completed	Pickup truck
602231	Hilux DC	CAMBIO ESCOLTA	MANTENIMIENTO CORRECTIVO	04/06/2021 21148		Corrective Order	WO Completed	Pickup truck
602232	Hilux DC	CAMBIO MUELLE	CAMBIO BOMBILLOS	04/06/2021 40581		Corrective Order	WO Completed	Pickup truck
602265	Grove RT880E 75TON	Cambio de Modulo	EQUIPO SE ENCIENDE SOLO	04/06/2021 90009585		Corrective Order	WO Completed	Crane/Hoist
602279	Caterpillar DE88E0 58 kVa	LLAMADA DE EMERGENCIA	FALLO POR EQUIPO SIN DIESEL	04/06/2021 35087 horas		Corrective Order	WO Completed	Generator
602280	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE RETENEDORA DE LA VOLANTE	04/06/2021 13606 horas		Corrective Order	WO Completed	Generator
602318	Freightliner Columbia CI112	Cambio de neumático	CAMBIO DE NEUMÁTICO	04/06/2021		Corrective Order	WO Completed	Mule truck
602345	Coaster	Cambio de 3 Llantas	CAMBIO DE 3 NEUMÁTICOS	04/06/2021		Corrective Order	WO Completed	Bus
602454	Caterpillar 12M Motorgrader	MANTENIMIENTO SEMESTRAL	MANTENIMIENTO SEMESTRAL AFEX	05/06/2021		Corrective Order	WO Completed	Grader
602455	Bomag BW219DH-4	fuga por motor de vibración	FUGA POR MOTOR DE VIBRACIÓN	05/06/2021		Corrective Order	WO Completed	Compactor
602474	Freightliner Columbia CI112	Retrovisor ROTO / LUZ ESCOLTA	RETROVISOR ROTO	05/06/2021		Corrective Order	WO Completed	Mule truck
602491	PRAMAC GSW560V 407 kVa	INSTALACION ELECTRICA	INSTALACION ELECTRICA DE BOMBA DE SUMINISTRO	05/06/2021 13602 horas		Corrective Order	WO Completed	Generator
602570	PRAMAC GSW30Y 24 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE CORREA Y PORTA FILTRO	05/06/2021 19738 horas		Corrective Order	WO Completed	Generator
602597	Caterpillar 12M Motorgrader	strp cambio	STRIP	05/06/2021		Corrective Order	WO Completed	Grader
602605	Unimog Service Truck	direccion parte delantera	DIRECCION PARTE DELANTERA	05/06/2021		Corrective Order	WO Completed	Truck
602768	GROVE GMK 5170 170TON	fabricacion de mangueras	FABRICACION DE MANGUERAS	05/06/2021		Corrective Order	WO Completed	Crane/Hoist
602795	Caterpillar 236d Skid Steer L	Cambio de componentes	CAMBIO DE COMPONENTES	05/06/2021 AUTOCLOSED		Corrective Order	WO Completed	Skid Steer
602797	Caterpillar 14H Motorgrader	HYD HOSES RPLC STRATEGY	CORRECTIVE	05/06/2021		Corrective Order	WO Completed	Grader
602844	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 27013 horas		PM Orders	WO Completed	Generator
602845	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 28048 horas		PM Orders	WO Completed	Generator
602846	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 18440 horas		PM Orders	WO Completed	Generator
602847	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 5336 hrs		PM Orders	WO Completed	Generator
602848	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 15334 horas		PM Orders	WO Completed	Generator
602863	PRAMAC GSW170i 164 kVa	PM PRA GSW170i MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 539HORAS		PM Orders	WO Completed	Generator
602869	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 19191		PM Orders	WO Completed	Generator
602870	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 15816 hrs		PM Orders	WO Completed	Generator
602871	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/06/2021 30336 horas		PM Orders	WO Completed	Generator
602875	Mobile equipment	Bombillos para almacen	BOMBILLOS PARA ALMACEN DE TALLER	05/06/2021		Corrective Order	WO Completed	Area
602986	Coaster	Cambio de 6 Llantas	CAMBIO DE 6 LLANTAS	06/06/2021		Corrective Order	WO Completed	Bus
603042	Caterpillar 740B EJ ADT	Inyector no recoge la tolva	INYECTOR NO RECOGE LA TOLVA	06/06/2021		Corrective Order	WO Completed	Articulated dump truck
603051	Caterpillar 735B	Nivel de aceite hidráulico de	EL INYECTOR NO RECOGE LA TOLVA	06/06/2021		Corrective Order	WO Completed	Articulated dump truck
603057	Caterpillar 426f2 Backhoe	Fabricar manguera y conectores	FABRICAR MANGUERA Y CONECTORES	06/06/2021		Corrective Order	WO Completed	Backhoe
603070	Atlas Copco Hilight V5	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	06/06/2021		Corrective Order	WO Completed	Light Tower
603107	Grove RT600E 50TON	Cambio de caliper de parking	CAMBIO DE CALIPER DE PARKING BRAKE	06/06/2021		Corrective Order	WO Completed	Crane/Hoist

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
603109	Grove RT600E 50TON	Cambio de caliper de frenos	CAMBIO DE CALIPER DE FRENOS	06/06/2021		Corrective Order	WO Completed	Crane/Hoist
603150	Landcruiser TC	REPARAR BOLA REMOLQUE	REPARAR O REEMPLAZAR	06/06/2021	68904.00 kms	Corrective Order	WO Completed	Pickup truck
603173	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/06/2021	13950 hrs	PM Orders	WO Completed	Generator
603199	Caterpillar 740B EJ	Problemas con el cono del pin	PROBLEMAS CON EL CONO DEL PINJ	06/06/2021		Corrective Order	WO Completed	Articulated dump truck
603255	PRAMAC GSW460V 460 kVa	MANTNIMIENTO CORRECTIVO	CAMBIO DE BATERIA	06/06/2021	26983 horas	Corrective Order	WO Completed	Generator
603258	Hyster H300 13t Forklift (M)	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	06/06/2021		Corrective Order	WO Completed	Forklift
603260	Hyster H300 13t Forklift (M)	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	06/06/2021		Corrective Order	WO Completed	Forklift
603269	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	06/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
603300	Freightliner Columbia CI112	Revisar sistema de arranque	REPARACION DE CABLEADO	06/06/2021		Corrective Order	WO Completed	Mule truck
603301	Caterpillar 336DL Excavator	Reparacion de pines	REPARACION DE PINES BALDE	06/06/2021		Corrective Order	WO Completed	Excavator
603303	Freightliner Columbia CI112	ajuste y reparacion de luces	AJUSTE DE FRENOS Y REPARACION D ELUCES	06/06/2021		Corrective Order	WO Completed	Mule truck
603308	Bell 225f 4t Forklift (M)	EQUIPO SE APAGA	CAMBIO DE CORREA DE ALTERNADOR	06/06/2021		Corrective Order	WO Completed	Forklift
603314	Coaster	Reparacion de llanta flat	REPARACION DE LLANTA FLAT	06/06/2021		Corrective Order	WO Completed	Bus
603317	Iveco 380t38	Bomba trancada emulsion	BOMBA TRANCADA EMULSION	06/06/2021		Corrective Order	WO Completed	Bitumen truck
603367	Caterpillar 14M Motorgrader	Bronces de la guia de la hoja	CAMBIO DE BRONCES DE LA GUIA DE DESPLAZAMIENTO DE LA HOJA	07/06/2021		Corrective Order	WO Completed	Grader
603455	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	INSTALACIÓN DE PUENTE DE BATERÍA	07/06/2021	9773 HORAS	Corrective Order	WO Completed	Generator
603494	Manitou Mht-X860 6t Telehand	fUGA hIDRÁULICA	MANGUERA HIDRÁULICA REVENTADA	07/06/2021		Corrective Order	WO Completed	Telehender
603513	Broce Broom RJT 350	Equipo no arranca	EQUIPO NO ARRANCA	07/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
603514	Manitou Mht-X860 6t Telehand	FUGA HIDRAULICA	FUGA HIDRAULICA	07/06/2021		Corrective Order	WO Completed	Telehender
603516	Caterpillar 740B EJ ADT	RELLENO DE HIDRÁULICO	RELLENO DE ACEITE HIDRÁULICO	07/06/2021		Corrective Order	WO Completed	Articulated dump truck
603518	Freightliner M2 106 Sucker Tru	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	07/06/2021		Corrective Order	WO Completed	Sucker truck
603588	Internation F2674	Mantenimiento	MANTENIMIENTO	07/06/2021		Corrective Order	WO Completed	Boom truck
603699	Gallegos Lime Tank	FUGA Y JUSTE DE FRENOS	FUGA Y JUSTE DE FRENOS	07/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
603788	Freightliner M112 Truck Tip	Barra de dirección delantera	BARRA DE DIRECCIÓN DELANTERA	07/06/2021		Corrective Order	WO Completed	Tipper
603797	Gallegos Flatbed Trailer	Reparacion de llntas	REPARACION DE LLANTAS	07/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
603802	Caterpillar 740b Ej	cambio de mangueras podridas	CAMBIO DE MANGUERAS, Y W/W NO FUNCIONA	07/06/2021		Corrective Order	WO Completed	Articulated dump truck
603812	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/06/2021	268.4 HORAS	PM Orders	WO Completed	Generator
603818	PRAMAC GSW560V 407 kVa	REVISION DE EQUIPO	PARQAMETROS GENERALES	07/06/2021	13635 horas	Corrective Order	WO Completed	Generator
603831	Terex RT670 64TON	Engrase de del Boom	ENGRASE DEL BOOM	07/06/2021		Corrective Order	WO Completed	Crane/Hoist
604052	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	08/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
604114	Hyster E70xn 3t Forklift (E)	No enciende error	NO ENCIENDE ERROR	08/06/2021		Corrective Order	WO Completed	Forklift
604115	Hyster H300 13t Forklift (M)	Ganchos no retraen	GANCHOS NO RETRAEN	08/06/2021		Corrective Order	WO Completed	Forklift
604117	Gallegos Flatbed Trailer	cambio de un neumático	CAMBIO DE UN NEUMÁTICO	08/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
604120	Caterpillar 336DL	CODIGO DE ERROR ACTIVO	CODIGO DE ERROR ACTIVO POR TEMPERATURA DEL AIRE DE ADMISIÓN	08/06/2021		Corrective Order	WO Completed	Excavator
604157	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	LIMPIZA DE TANQUE DE COMBUSTIBLE	08/06/2021	17858 horas	Corrective Order	WO Completed	Generator
604191	Freightliner M2 106 Hydroseedi	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	08/06/2021		Corrective Order	WO Completed	Truck
604193	Caterpillar 14H Motorgrader	drenage del del combustible	DRENAGE DE COMBUSTIBLE	08/06/2021		Corrective Order	WO Completed	Grader
604205	Case 110JX Tractor Cable Handl	íZAJE DE TRACTOR	IZAJE DE TRACTOR	08/06/2021	SOPORTE W23	Corrective Order	WO Completed	Tractor
604209	Coaster Bus	CAMBIO PERNO LH	MANTENIMIENTO CORRECTIVO	08/06/2021	74952	Corrective Order	WO Completed	Bus
604211	Ford Ranger	CAMBIO TACOS BANDAS FRENO	CAMBIO BASE TRANSMISION/BOMBILLO FRENO	08/06/2021	17326	Corrective Order	WO Completed	Pickup truck
604212	Toyota Land Cruiser	CAMBIO TERMINALES DIRECCION	CAMBIO CAUCHO/AMORTIGUADOR DELANTERO/ALARMA	08/06/2021	152138	Corrective Order	WO Completed	Pickup truck
604214	Toyota Hilux	CAMBIO TERMINALES DIRECCION	CAMBIO RETENEDORA EJE FLECHA/AJUSTE BANDA	08/06/2021	89314	Corrective Order	WO Completed	Pickup truck
604215	Coaster Bus	REVISION SISTEMA FRENO	PURGA SISTEMA, AJUSTE BANDAS	08/06/2021	96264	Corrective Order	WO Completed	Bus
604216	Hino Series300	CAMBIO BATERIA	02 BATERIAS	08/06/2021	58941	Corrective Order	WO Completed	Truck
604218	Internation F2674	Manguera hidraulica rota	MANGUERA HIDRAULICA ROTA	08/06/2021		Corrective Order	WO Completed	Boom truck
604263	Caterpillar 12M	Vidrio de la puerta derecha r	VIDRIO DE LA PUERTA DERECHA R	08/06/2021		Corrective Order	WO Completed	Grader
604269	Caterpillar 14H Motorgrader	Mantenimiento de sistema afex	MANTENIMIENTO DE SISTEMA AFEX	08/06/2021		Corrective Order	WO Completed	Grader
604296	Freightliner Columbia CI112	Retrovisor ROTO/BOMBILLO ROTO	RETROVISOR ROTO/BOMBILLO ROTO	08/06/2021	59,290.80 Km	Corrective Order	WO Completed	Mule truck
604329	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	08/06/2021		Corrective Order	WO Completed	Mule truck
604389	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	REVISION DE ALTERNADOR AC POR FALLA DE VOLTAGE	08/06/2021	17918 horas	Corrective Order	WO Completed	Generator
604394	Internation F2674	CYLINDER REPAIR (MASTER TECH)	REPARACIÓN MAYOR	08/06/2021	50015442	Corrective Order	WO Completed	Boom truck
604402	Caterpillar 740B	REPARACION DE FRENO	REPARACION DE FRENO	08/06/2021		Corrective Order	WO Completed	Articulated dump truck
604429	Freightliner M2 106 Hydroseedi	CAMBIO DE PULMONES Y NEUMATICO	CAMBIO DE DOS PULMONES Y NEUMÁTICOS	08/06/2021		Corrective Order	WO Completed	Truck
604433	Freightliner M2 106 Hydroseedi	PULMON, NEUMÁTICOS Y FILTRO	CAMBIO DE DOS PULMONES, INSTALACIÓN DE 2 NEUMÁTICOS Y CAMBIO DE FILTRO DE DIFERE	08/06/2021		Corrective Order	WO Completed	Truck
604619	John Deere 310K	Fuga hidráulica	CAMBIO DE MANGUERAS HIDRÁULICAS	09/06/2021		Corrective Order	WO Completed	Backhoe
604636	Caterpillar 14M Motorgrader	bajo nivel de refrigerante	CARGA DE REFRIGERANTE	09/06/2021		Corrective Order	WO Completed	Grader
604641	Iveco 380t38	Park brake	PARK BRAKE	09/06/2021		Corrective Order	WO Completed	Bitumen truck
604646	Iveco 380t38	Luces traseras	LUCES TRASERAS	09/06/2021		Corrective Order	WO Completed	Bitumen truck
604649	Iveco 380t38	Quemadores no conectados	QUEMADORES NO CONECTADOS	09/06/2021		Corrective Order	WO Completed	Bitumen truck
604661	Caterpillar 740B EJ ADT	No enciende	NO ENCIENDE	09/06/2021		Corrective Order	WO Completed	Articulated dump truck
604745	Landcruiser DC	Cambio de 4 llantas	CANBIO DE 4 LLANTAS	09/06/2021		Corrective Order	WO Completed	Pickup truck
604750	Hilux DC	CAMBIO DE 2 LLANTAS	CAMBIO DE 2 LLANTAS	09/06/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
604796	Freightliner M2 106 Sucker Tru	cambio de 4 llmantas	CAMBIO DE 4 LLANATAS	09/06/2021		Corrective Order	WO Completed	Sucker truck
604864	SDMO J30U 38KVA	LLAMADA DE EMERGENCIA	FALLO DE ARRANQUE	09/06/2021 9519 horas		Corrective Order	WO Completed	Generator
604867	Toyota Hilux	CAMBIAR BOMBILLO y bateria	MANTENIMIENTO CORRECTIVO	09/06/2021		Corrective Order	WO Completed	Pickup truck
605008	Ford Ranger	CAMBIO SUSPENSION	CAMBIO SENSORES ABS	09/06/2021 CERRADO POR PLANEAMIENTO		Corrective Order	WO Completed	Pickup truck
605010	Toyota Land Cruiser	REPARAR MUELLES/LAMPARA FRONTA	REPARAR PISO	09/06/2021 50013609 CERRADO PLANEAMIENTO		Corrective Order	WO Completed	Pickup truck
605012	Isuzu NMR85L	REPARACION GENERAL	TALLER DOLLAR MINA	09/06/2021 50015069 50015875 PLANEAMIEN		Corrective Order	WO Completed	Truck
605014	Ford F550	CAMBIO DIRECCION/SUSPENSION/FR	TALLER DOLLAR MINA	09/06/2021 50013609 96664		Corrective Order	WO Completed	Pickup truck
605029	Landcruiser DC	CAMBO KIT BANDAS/AMORTIGUADOR	AMBIO BASE AMORTIGUADOR/BOMBILLOS	09/06/2021 73830		Corrective Order	WO Completed	Pickup truck
605030	Landcruiser DC	CAMBIO BATERIA	MANTENIMIENTO CORRECTIVO	09/06/2021 49642		Corrective Order	WO Completed	Pickup truck
605031	Landcruiser DC	CAMBIO LAMPARA TRASERA	MANTENIMIENTO CORRECTIVO	09/06/2021 64107		Corrective Order	WO Completed	Pickup truck
605032	DOOSAND 1005	LLAMADA DE EMERGENCIA	REVISION DE EQUIPO	09/06/2021 252015 horas		Corrective Order	WO Completed	Light Tower
605033	MAGNUM Light Tower	LLAMADA DE EMERGENCIA	REVISION ELCTRICA	09/06/2021 25791 horas		Corrective Order	WO Completed	Light Tower
605034	Landcruiser DC	CAMBIO ALTERNADOR	CAMBIO RETENEDORA DIFERENCIAL/BUJES BARRA	09/06/2021 58332		Corrective Order	WO Completed	Pickup truck
605036	Landcruiser TC	CAMBIO BOMBILLO	REVISION LUCES	09/06/2021 50375		Corrective Order	WO Completed	Pickup truck
605037	Landcruiser TC	INSTALAR PERTIGA	MANTENIMIENTO CORRECTIVO	09/06/2021 39043		Corrective Order	WO Completed	Pickup truck
605041	Hilux DC	CAMBIO ALTENADOR/MUELLE	CAMBIO GRAPAS/BOMBILLOS	09/06/2021		Corrective Order	WO Completed	Pickup truck
605042	Hilux DC	CAMBIO TACOS/CAUCHO BARRA	CAMBIO ESCOBILLAS	09/06/2021 66706		Corrective Order	WO Completed	Pickup truck
605044	Hilux DC	CAMBIO CRUCETA EJE	REVISION SUSPENSION DIRECCION	09/06/2021 69279		Corrective Order	WO Completed	Pickup truck
605045	Hilux DC	CAMBIO PERTIGA	MANTENIMIENTO CORRECTIVO	09/06/2021 68874		Corrective Order	WO Completed	Pickup truck
605046	Hilux DC	CAMBIO TERMINALES DIRECCION	CAMBIO CRUCETA EJE/LAMPARAS TRASERAS	09/06/2021 59538		Corrective Order	WO Completed	Pickup truck
605047	Landcruiser TC	CAMBIO BANDA/TACOS DELANTERO	CAMBIO BALINERA LH/RH FRENOS	09/06/2021 39912		Corrective Order	WO Completed	Pickup truck
605049	Landcruiser TC	CAMBIO CILINDRO/BANDAS FRENO	CAMBIO TAMBOR FRENO	09/06/2021 61505		Corrective Order	WO Completed	Pickup truck
605050	Landcruiser DC	CAMBIO TERMINALES DIRECCION	CAMBO BOMBILLOS/ALARMA RETROCESO	09/06/2021 43214		Corrective Order	WO Completed	Pickup truck
605051	Hilux DC	CAMBIO BANDAS/CABLE FRENO	CAMBO CRUCETAS EJE CORTO/TRASERO/HOJA MUELLE/GRAMPAS	09/06/2021 44713		Corrective Order	WO Completed	Pickup truck
605053	Landcruiser TC	CAMBIO RETENEDORA DIFERENCIAL	CABMBIO CRUCETA EJE CORTO/TACOS/BANDAS/COLA PEZ	09/06/2021 51981		Corrective Order	WO Completed	Pickup truck
605056	Coaster	cambio de 6 neumáticos	CAMBIO DE 6 NEUMÁTICOS	09/06/2021		Corrective Order	WO Completed	Bus
605061	Landcruiser DC	cambio de neumático	CAMBO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605071	Landcruiser DC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605072	Landcruiser DC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605073	Landcruiser TC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605074	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO DE NEUMÁTICO	10/06/2021 44638		Corrective Order	WO Completed	Pickup truck
605075	Hilux DC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605076	Hilux DC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605077	Hilux DC	cambio de neumático	CAMBIO DE NEUMÁTICO	10/06/2021		Corrective Order	WO Completed	Pickup truck
605135	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	10/06/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
605161	Caterpillar 12M	CAMBIO DE HOJA DE CORTE	CAMBIO DE HOJA DE CORTE	10/06/2021		Corrective Order	WO Completed	Grader
605163	Caterpillar 226b Skid Steer L	INSPECCIÓN DE EQUIPO	INSPECCIÓN DE EQUIPO	10/06/2021		Corrective Order	WO Completed	Skid Steer
605166	Caterpillar CS533E Compactor	EQUIPO NO ENCIENDE LUCES	EQUIPO NO ENCIENDE LUCES	10/06/2021		Corrective Order	WO Completed	Compactor
605167	Case 110JX Tractor Cable Handl	REPARACIÓN DEL MOTOR DE ARRANQ	REPARACIÓN DEL MOTOR DE ARRANQUE	10/06/2021 3697.7 (HRM)		Corrective Order	WO Completed	Tractor
605168	Caterpillar 226b Skid Steer L	RELLENO DE HID. AJUSTE DE ACEL	RELLENO DE HIDRÁULICO Y AJUSTE DEL CABLEADO DEL ACCELERADOR	10/06/2021		Corrective Order	WO Completed	Skid Steer
605174	WT013 H7 CISTERNA SINOTRUK	REPARACION DE LUCES	REPARACIÓN DEL SISTEMA DE LUCES	10/06/2021		Corrective Order	WO Completed	Water truck
605180	Landcruiser TC	CAMBIO PLATO/DISCO CLUTCH	CAMBIO BALINERA DE EJE PILOTO	10/06/2021 52592		Corrective Order	WO Completed	Pickup truck
605181	Caterpillar 12M	Vidrio de la puerta izquierda	VIDRIO DE LA PUERTA IZQUIERDA	10/06/2021		Corrective Order	WO Completed	Grader
605184	Landcruiser DC	CAMBIO CRUCETA EJE/BANDA FRENO	CAMBIO RESORTE BANDAS/TAMBOR FRENO	10/06/2021 47000		Corrective Order	WO Completed	Pickup truck
605186	Coaster Bus	REVISION MECANICA	DIAGNOSTICO DOLLAR	10/06/2021 74952		Corrective Order	WO Completed	Bus
605188	Hiace Bus	CAMBIOO BATERIA	CAMBIO BOMBILLOS	10/06/2021 60938		Corrective Order	WO Completed	Bus
605191	Coaster	CAMBIO RING	REVISION DE BANDAS ENGRASE RUEDA	10/06/2021 30439		Corrective Order	WO Completed	Bus
605192	Coaster	CAMBIO CILINDRO FRENOS	CAMBIO KIT SPRINGS/BANDAS FRENO	10/06/2021 27682		Corrective Order	WO Completed	Bus
605194	Toyota Hilux	CAMBIO KIT BANDAS FRENO	CAMBIO TAMBORES FRENO	10/06/2021 91247		Corrective Order	WO Completed	Pickup truck
605197	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	DISPOSITIVO AVRI DAÑADO	10/06/2021 16485 horas		Corrective Order	WO Completed	Generator
605203	Caterpillar D110 E2 100KVA	REVISION DE EQUIPO	FALLO DE CORREA DE ALTERNADOR DC	10/06/2021 15906 horas		Corrective Order	WO Completed	Generator
605217	Landcruiser DC	CAMBIO AMORTIGUADORES	MANTENIMIENTO CORRECTIVO	10/06/2021 61929		Corrective Order	WO Completed	Pickup truck
605228	Hilux DC	REPARAR SISTEMA ELECTRICO	MANTENIMIENTO CORRECTIVO	10/06/2021 55780		Corrective Order	WO Completed	Pickup truck
605233	Landcruiser DC	REPARAR CAJA TIMON	MANTENIMIENTO CORRECTIVO	10/06/2021 76693		Corrective Order	WO Completed	Pickup truck
605239	Hilux DC	CAMBIO MUELLES	CAMBIO GRAPAS/BOMBILLOS	10/06/2021 60487		Corrective Order	WO Completed	Pickup truck
605255	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 69743		PM Orders	WO Completed	Pickup truck
605257	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 73974		PM Orders	WO Completed	Pickup truck
605258	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 74902		PM Orders	WO Completed	Pickup truck
605259	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 85169		PM Orders	WO Completed	Pickup truck
605261	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021		PM Orders	WO Completed	Pickup truck
605262	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 67150		PM Orders	WO Completed	Pickup truck
605263	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021		PM Orders	WO Completed	Pickup truck
605264	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021		PM Orders	WO Completed	Pickup truck
605266	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 31931		PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
605267	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 48774		PM Orders	WO Completed	Pickup truck
605268	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 28953		PM Orders	WO Completed	Pickup truck
605269	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 57682		PM Orders	WO Completed	Pickup truck
605271	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 52745		PM Orders	WO Completed	Pickup truck
605272	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 13315		PM Orders	WO Completed	Pickup truck
605275	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 10344		PM Orders	WO Completed	Pickup truck
605276	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 9532		PM Orders	WO Completed	Pickup truck
605277	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 11281		PM Orders	WO Completed	Pickup truck
605278	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 11813		PM Orders	WO Completed	Pickup truck
605279	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 44394		PM Orders	WO Completed	Pickup truck
605280	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 13246		PM Orders	WO Completed	Pickup truck
605281	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 13359		PM Orders	WO Completed	Pickup truck
605282	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 65028		PM Orders	WO Completed	Bus
605283	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 36126		PM Orders	WO Completed	Bus
605284	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 33826		PM Orders	WO Completed	Bus
605285	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 25603		PM Orders	WO Completed	Bus
605286	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 35005		PM Orders	WO Completed	Bus
605288	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 19142		PM Orders	WO Completed	Bus
605289	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 13407		PM Orders	WO Completed	Bus
605290	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 32036 KM		PM Orders	WO Completed	Bus
605291	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 31590		PM Orders	WO Completed	Bus
605293	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/06/2021 96309		PM Orders	WO Completed	Pickup truck
605312	Unimog Service Truck	NO ENCIENDE LA UNIDAD	NO ENCIENDE LA UNIDAD	10/06/2021		Corrective Order	WO Completed	Truck
605319	Grove RT650E 45TON	Fuga por manguera hidraulica	FUGA POR MANGUERA HIDRAULICA	10/06/2021		Corrective Order	WO Completed	Crane/Hoist
605339	Hilux DC	Cambio de batería	CAMBIO DE BATERÍA	10/06/2021		Corrective Order	WO Completed	Pickup truck
605341	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	FALLO POR TEMPERATURA	10/06/2021		Corrective Order	WO Completed	Generator
605364	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	FALLO DE BOMBA DE CEBa	10/06/2021 6107 horas		Corrective Order	WO Completed	Generator
605385	Hilux DC	AUXILIO ARRANQUE EQUIPO	INSPECCION DE EQUIPO	10/06/2021 64946		Corrective Order	WO Completed	Pickup truck
605391	Terex RT670 64TON	CERTIFICATION BY ITS	CERTIFICATION BY ITS	10/06/2021 NOT CERTIFICATED		Corrective Order	WO Completed	Crane/Hoist
605402	Manitou Mht-X1490 9t Telehand	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	10/06/2021		Corrective Order	WO Completed	Telehender
605405	Bell 225f 4t Forklift (M)	CERTIFICATION BY ITS	CERTIFICATION BY ITS	10/06/2021 CERTIFICATED		Corrective Order	WO Completed	Forklift
605408	Bell 225f 4t Forklift (M)	CERTIFICATION BY ITS	CERTIFICATION BY ITS	10/06/2021 CERTIFICATED		Corrective Order	WO Completed	Forklift
605409	Caterpillar DP50 Forklift (M)	CERTIFICATION BY ITS	CERTIFICATION BY ITS	10/06/2021 CERTIFICATED		Corrective Order	WO Completed	Forklift
605411	New Holland Lm 1745	CERTIFICATION BY ITS	CERTIFICATION BY ITS	10/06/2021 NOT CERTIFICATED		Corrective Order	WO Completed	Telehender
605445	John Deere 9370R Tractor	REPARACION DEL IMPLEMENTO	REPARACION DEL IMPLEMENTO	10/06/2021		Corrective Order	WO Completed	Tractor
605449	Manitou Mht-X1490 9t Telehand	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	10/06/2021		Corrective Order	WO Completed	Telehender
605455	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	LIMPIEZA DE CABLES DE BATERIA	10/06/2021 9774 horas		Corrective Order	WO Completed	Generator
605456	Manitou Mht-X860 6t Telehand	desmontaje cilindro	DESMONTAJE CILINDRO	10/06/2021		Corrective Order	WO Completed	Telehender
605462	Toyota Hilux	Aire acondicionado no funciona	AIRE ACONDICIONADO NO FUNCIONA	10/06/2021		Corrective Order	WO Completed	Pickup truck
605474	Freightliner Cl 120	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	10/06/2021		Corrective Order	WO Completed	Mule truck
605502	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO DE 4 LLANTAS	10/06/2021		Corrective Order	WO Completed	Pickup truck
605697	Caterpillar 12M Motorgrader	Cambio de Cuchilla	CAMBIO DE CUCHILLA	11/06/2021		Corrective Order	WO Completed	Grader
605705	Hilux DC	cambio de neumático	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Pickup truck
605721	Hilux DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Pickup truck
605729	Hilux DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Pickup truck
605730	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Bus
605731	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Bus
605732	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Bus
605733	Coaster	cAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	11/06/2021		Corrective Order	WO Completed	Bus
605735	Caterpillar 735B	RELLENO DE ACEITE HIDRÁULICO	RELLENO DE ACEITE HIDRÁULICO	11/06/2021		Corrective Order	WO Completed	Articulated dump truck
605755	Hino Dutro 300	REPARAR CAJON POSTERIOR	REPARAR AC/SUSPENSIÓN/PISO	11/06/2021 86198 KM		Corrective Order	WO Completed	Truck
605763	Hyster H800 32t Forklift (M)	LEAK MANGUERA HIDRAULICA	LEAK MANGUERA HIDRAULICA	11/06/2021		Corrective Order	WO Completed	Forklift
605765	Manitou Mht-X1490 9t Telehand	Leak de Aceite por Debajo	LEAK DE ACEITE POR DEBAJO	11/06/2021		Corrective Order	WO Completed	Telehender
605790	PRAMAC GSW110P 82 kVa	CAMBIO DE TUBERIA DE DIESEL	MANTENIMIENTO CORRECTIVO	11/06/2021 12223 horas		Corrective Order	WO Completed	Generator
605823	Grove RT600E 50TON	REPARACION DE FUGAS DE ACEITE	REPARACION DE FUGAS DE ACEITE	11/06/2021		Corrective Order	WO Completed	Crane/Hoist
605824	Mobile equipment	ENTRENAMIENTO OPERADORES	MONTACARGA - TELEHANDLER	11/06/2021		Corrective Order	WO Completed	Area
605826	TTP-0000-102	reprcaion de fuga de aceite	REPARACAION DE FUGA DE ACEITE	11/06/2021		Corrective Order	WO Completed	Excavator
605833	PRAMAC GSW460V 460 kVa	CAMBIO DE GENERADOR	CAMBIO POR FALLA DE BREAKER, SWITCH & REVISION	11/06/2021 6108 horas		Corrective Order	WO Completed	Generator
605835	PRAMAC GSW330V 315 kVa	INTALACION DE GENERADOR	CONECCIÓN & AJUSTE DE VOLTAGE POR CAMBIO DE EQUIPO	11/06/2021 8554 horas		Corrective Order	WO Completed	Generator
605836	Hino Serie 300 Box Truck	EVALUAR SISTEMA DIRECCION	EVALUAR SISTEMA DE SUSPENSION	11/06/2021		Corrective Order	WO Completed	Truck
605840	PRAMAC GSW460V 460 kVa	REVISION DE GENERADOR	FALLO DE ALTERNADOR POR VOLTAGE	11/06/2021 12940 horas		Corrective Order	WO Completed	Generator
605853	Manitou Mht-X860 6t Telehand	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	11/06/2021 90009049		Corrective Order	WO Completed	Telehender
605896	Isuzu NMR85L	REPARACION EXTERNA	TALLER MELO COPAMA CHITRE	11/06/2021 50013898 PLANEAMIENTO		Corrective Order	WO Completed	Truck
605974	Grove GMK4100L 100TON	PINTAR CONTRAPESOS DE GRUA	PINTAR CONTRAPESOS DE GRUA	11/06/2021		Corrective Order	WO Completed	Crane/Hoist
605975	Freightliner Columbia Cl112	LLANTA FLAT	LLANTA FLAT	11/06/2021		Corrective Order	WO Completed	Mule truck
606049	Hyster H700 Forklift	ENGRASE MANIPULADOR DE LLANTAS	PREVENTIVO	11/06/2021		Corrective Order	WO Completed	Forklift

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
606051	Hyster H700 Forklift	ENGRASE MANIPULADOR DE LLANTAS	PREVENTIVO	11/06/2021		Corrective Order	WO Completed	Forklift
606081	Freightliner M112 Truck Tip	Esparragos desajustados dañaro	ESPARRAGOS DESAJUSTADOS DAÑARO	11/06/2021	900010336 900010337	Corrective Order	WO Completed	Tipper
606082	Unimog Service Truck	cambio de radiador	CAMBIO DE RADIADOR	11/06/2021		Corrective Order	WO Completed	Truck
606083	Freightliner M112 Truck Tip	Reparacion de A/c	REPARACION DE A/C	11/06/2021		Corrective Order	WO Completed	Tipper
606085	Freightliner M2 106 Sucker Tru	reparacion del A/c	REPARACION DEL A/C	11/06/2021		Corrective Order	WO Completed	Sucker truck
606115	USP&E GP700S/V-A 700 kVa	ALTA TEMPERATURA DE COOLANT	LLAMADA DE EMERGENCIA	11/06/2021	16397 horas	Corrective Order	WO Completed	Generator
606242	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	13440.8	PM Orders	WO Completed	Generator
606243	Olympian GEP 88-3 64 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	2:53	PM Orders	WO Completed	Generator
606244	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	14388 hrs	PM Orders	WO Completed	Generator
606245	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	3159.37	PM Orders	WO Completed	Generator
606246	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	FUERA SERVICIO 6329	PM Orders	WO Completed	Generator
606247	Olympian GEP18-6 18 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	12/06/2021	INSTALAR ODOMETRO	PM Orders	WO Completed	Generator
606253	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	12/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
606267	PRAMAC GSW45P 48 kVa	PM OLY GEP 88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	8281 hrs	PM Orders	WO Completed	Generator
606295	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	12/06/2021		Corrective Order	WO Completed	Pickup truck
606296	Landcruiser TC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606297	Landcruiser DC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606298	Landcruiser TC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606299	Landcruiser DC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606300	Landcruiser DC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606301	Landcruiser DC	Cambio de neumático	CAMBIO DE NEUMÁTICO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606303	John Deere 310K	Pin del Balde suelto	PIN DEL BALDE SUELTO	12/06/2021		Corrective Order	WO Completed	Backhoe
606307	Freightliner M2 106	Fuga de diésel en los quemado	FUGA DE DIÉSEL EN LOS QUEMADO	12/06/2021		Corrective Order	WO Completed	Bitumen truck
606308	Caterpillar 226b Skid Steer L	INSPECCION PASADORES Y PERNOS	PERSONAL DE CONTRATO IASA	12/06/2021		Corrective Order	WO Completed	Skid Steer
606309	Grove GMK 4080 80TON	Falla de Comunicación de ECU	FALLA EN LA COMUNICACIÓN DE COMPUTADORAS	12/06/2021		Corrective Order	WO Completed	Crane/Hoist
606459	Freightliner Columbia Cl112	BALINERAS / POLLERA	BALINERAS / POLLERA	12/06/2021		Corrective Order	WO Completed	Mule truck
606465	Caterpillar 12M	reparacion de A/C	REPARACION DE A/C	12/06/2021		Corrective Order	WO Completed	Grader
606466	Freightliner Columbia Cl112	CORREA / BALINERA / RETROVISOR	CORREA / BALINERA / RETROVISOR	12/06/2021	90011166 90011167	Corrective Order	WO Completed	Mule truck
606470	Caterpillar 14H Motorgrader	Vidrios Quebrados	VIDRIOS QUEBRADOS	12/06/2021		Corrective Order	WO Completed	Grader
606493	Unimog Service Truck	Cambio de radiador	CAMBIO DE RADIADOR	12/06/2021		Corrective Order	WO Completed	Truck
606494	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	12/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
606502	Caterpillar 336DL	Cambio de radiador roto	CAMBIO DE RADIADOR ROTO	12/06/2021		Corrective Order	WO Completed	Excavator
606513	PRAMAC GSW460V 460 kVa	CAMBIO BATERIA	MANTENIMIENTO CORRECTIVO	12/06/2021	27026 hrs	Corrective Order	WO Completed	Generator
606582	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	23290 horas	PM Orders	WO Completed	Generator
606583	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	19558 hrs	PM Orders	WO Completed	Generator
606584	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	12319 horas	PM Orders	WO Completed	Generator
606585	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	15739 hrs	PM Orders	WO Completed	Generator
606588	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	11644 hrs	PM Orders	WO Completed	Generator
606589	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	12627 hrs	PM Orders	WO Completed	Generator
606590	PRAMAC GSW80P 83 kVa	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	10298 hrs	PM Orders	WO Completed	Generator
606591	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	15821 hrs	PM Orders	WO Completed	Generator
606592	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	18761 hrs	PM Orders	WO Completed	Generator
606593	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	35528 hrs	PM Orders	WO Completed	Generator
606594	PRAMAC GSW90P 74 kVa	PM PRA GSW90P MEC 300 HR	PM PRA GSW90P MEC 300 HR	12/06/2021	24152 hrs	PM Orders	WO Completed	Generator
606595	PRAMAC GSW65 48 kVa	PM PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	20017 HRS	PM Orders	WO Completed	Generator
606596	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	26602 hrs	PM Orders	WO Completed	Generator
606597	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	21904 horas	PM Orders	WO Completed	Generator
606598	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	6630 HRS	PM Orders	WO Completed	Generator
606599	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	20004 hrs	PM Orders	WO Completed	Generator
606610	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	18039 hrs	PM Orders	WO Completed	Generator
606611	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	6117 hrs	PM Orders	WO Completed	Generator
606634	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	3490 HRS	Corrective Order	WO Completed	Light Tower
606641	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	22396 horas	Corrective Order	WO Completed	Light Tower
606645	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	23910 hrs	Corrective Order	WO Completed	Light Tower
606648	DOOSAN 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	12/06/2021	19346	Corrective Order	WO Completed	Light Tower
606700	Caterpillar 307E Miniexcavator	balde nuevo	BALDE NUEVO	12/06/2021		Corrective Order	WO Completed	Excavator
606718	Tennant S30 Sweeper	COPAMA'S RECOMMENDATIONS	CORRECTIVE	12/06/2021	90009190	Corrective Order	WO Completed	Scrubber / Sweeper
606723	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	12/06/2021		Corrective Order	WO Completed	Pickup truck
606729	Freightliner Columbia Cl112	equipo no enciende	EQUIPO NO ENCIENDE	12/06/2021		Corrective Order	WO Completed	Mule truck
606731	Caterpillar 14H Motorgrader	Llanta flat	LLANTA FLAT	12/06/2021		Corrective Order	WO Completed	Grader
606771	Landcruiser TC	CAMBIO LUCES TRASERAS LH	CAMBIO ALARMA RETROCESO	12/06/2021		Corrective Order	WO Completed	Pickup truck
606772	Landcruiser TC	REVISAR FRENOS SERVICIO/PARQUE	REVISAR AMORTIGUADORES Y CLUTCH	12/06/2021	61577	Corrective Order	WO Completed	Pickup truck
606774	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	12/06/2021		Corrective Order	WO Completed	Pickup truck
606778	Freightliner Columbia Cl112	CAMBIO DE MASTER SWITCH	CAMBIO DE MASTER SWITCH	12/06/2021		Corrective Order	WO Completed	Mule truck
606800	Caterpillar 735B	BUJES DEL SEGURO DE CABINA	CAMBIO DE SEGUROS DEL BUJE DE CABINA	12/06/2021		Corrective Order	WO Completed	Articulated dump truck
606962	Freightliner 8170ME Water Truc	EMBRAGUE Y CRUCETA	FALLA DEL SISTEMA DE EMBRAGUE Y CRUCETA DE LA BOMBA EN MAL ESTADO	13/06/2021		Corrective Order	WO Completed	Water truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
606982	Caterpillar 140K	MARCO DE LA PUERTA	ENDEREZADO DEL MARCO DE LA PUERTA	13/06/2021		Corrective Order	WO Completed	Grader
607053	Hyster J40zt	PLUG DE CARGA	PLUG DE CARGA	13/06/2021		Corrective Order	WO Completed	Forklift
607099	Mobile equipment	Insumos para taller	INSUMOS PARA TALLER	13/06/2021		Corrective Order	WO Completed	Area
607154	Caterpillar 740B EJ ADT	Desprendimiento del vidrio del	DESPRENDIMIENTO DEL VIDRIO DEL	13/06/2021		Corrective Order	WO Completed	Articulated dump truck
607165	Caterpillar 12M Motorgrader	Necesita reemplazo de casquill	NECESITA REEMPLAZO DE CASQUILL	13/06/2021		Corrective Order	WO Completed	Grader
607175	PRAMAC GSW460V 460 kVa	CAMBIO ASPAS VENTILADOR	REPOSICION SE TOMO PARA GSL302	13/06/2021 19893 horas		Corrective Order	WO Completed	Generator
607177	PRAMAC GSW460V 460 kVa	CAMBIO BATERIA	SE TOMA BATERIAS PARA EL GSL302	13/06/2021 19870 HORAS		Corrective Order	WO Completed	Generator
607187	Caterpillar 320DL	Fuga de aceite hidráulico	FUGA DE ACEITE HIDRÁULICO	13/06/2021		Corrective Order	WO Completed	Excavator
607193	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 14608 hrs		PM Orders	WO Completed	Generator
607203	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 1776		PM Orders	WO Completed	Generator
607204	SDMO K12UM 11KVA	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 649 hrs		PM Orders	WO Completed	Generator
607206	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 13248.4		PM Orders	WO Completed	Generator
607207	Olympian GEP 88-3 64 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 23.18 HRS SEISA		PM Orders	WO Completed	Generator
607208	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 14966 HRS SEISA		PM Orders	WO Completed	Generator
607211	Olympian GEP18-6 18 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 SIN ODO		PM Orders	WO Completed	Generator
607214	SDMO T11UM 10 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 1926 HRS SEISA		PM Orders	WO Completed	Generator
607215	SDMO K12UM 11KVA	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 659		PM Orders	WO Completed	Generator
607220	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 13776.7		PM Orders	WO Completed	Generator
607225	Olympian GEP18-6 18 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 SEISA		PM Orders	WO Completed	Generator
607234	Caterpillar D110 E2 110 kVa	PM SERVICIO MANTTO EXTERNO	PM SERVICIO GENERADOR MEC 90 D	13/06/2021 14125 hrs		PM Orders	WO Completed	Generator
607235	Olympian GEP 88-3 64 kVa	INSPECCION GENERAL EQUIPO	EVALUACION POST CUARENTENA	13/06/2021 23.18 HRS SEISA		PM Orders	WO Completed	Generator
607265	Grove RT700E 60TON	Cambio de pasador de pin cable	CAMBIO DE PASADOR DE PIN DE LAGRIMA DEL CABLE	13/06/2021		Corrective Order	WO Completed	Crane/Hoist
607266	New Holland Lm 1745	Base de alternador roto	BASE DE ALTERNADOR ROTO	13/06/2021		Corrective Order	WO Completed	Telehender
607270	Coaster	Cambio de 6 llantas	CAMBIO DE 6 LLANTAS	13/06/2021		Corrective Order	WO Completed	Bus
607277	Intraax 53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	13/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
607278	Mobile equipment	INSUMOS TALLER TE	SOLICITADO L RUJANO	13/06/2021		Corrective Order	WO Completed	Area
607285	Pramac GSW25P 17KVA	INSPECCION DE EQUIPO	RODAMIENTO DAÑADO & FUGA DE ACEITE	13/06/2021 4619 horas		Corrective Order	WO Completed	Generator
607419	Landcruiser DC	CAMBIO PLUMILLAS PARABRISAS	CAMBIO DE CAUCHO DE VIDRIO	14/06/2021 56401		Corrective Order	WO Completed	Pickup truck
607421	Caterpillar 740B EJ ADT	MANT. SEMESTRAL AFEX	MANTENIMIENTO SEMESTRAL AFEX	14/06/2021		Corrective Order	WO Completed	Articulated dump truck
607430	Caterpillar 735B	Llanta #5flat	LLANTA #5FLAT	14/06/2021		Corrective Order	WO Completed	Articulated dump truck
607477	MAGNUM Light Tower	FOCOS QUEMADOS	LLAMADA DE EMERGENCIA	14/06/2021 25877 horas		Corrective Order	WO Completed	Light Tower
607484	Grove RT600E 50TON	GRUA NO ARRANCA	GRUA NO ARRANCA	14/06/2021		Corrective Order	WO Completed	Crane/Hoist
607485	JLG 1250 AJP Manlift	FUGA HIDRAULICA	FUGA HIDRAULICA	14/06/2021		Corrective Order	WO Completed	Manlift
607504	Landcruiser TC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	14/06/2021		Corrective Order	WO Completed	Pickup truck
607528	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	14/06/2021 6244		PM Orders	WO Completed	Pickup truck
607529	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	14/06/2021 8446		PM Orders	WO Completed	Pickup truck
607531	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	14/06/2021		PM Orders	WO Completed	Pickup truck
607532	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	14/06/2021 5533		PM Orders	WO Completed	Pickup truck
607533	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	14/06/2021 9608		PM Orders	WO Completed	Pickup truck
607534	Hilux DC	Cambio de luz de escolta	CAMBIO DE LUZ DE ESCOLTA	14/06/2021		Corrective Order	WO Completed	Pickup truck
607657	John Deere 9370R Tractor	PM04 PREVENTIVE MAINTENANCE	COPAMA CONTRACTOR	14/06/2021 90009934		Corrective Order	WO Completed	Tractor
607658	Grove RT600E 50TON	Cambio de bomba de ceba	CAMBIO DE BOMBA DE CEBA	14/06/2021		Corrective Order	WO Completed	Crane/Hoist
607694	PRAMAC GSW560V 407 kVa	CAMBIO FILTRO RESPIRADORES	TANQUE COMBUSTIBLE PRINCIPAL	14/06/2021 17918 hrs		Corrective Order	WO Completed	Generator
607775	Caterpillar 226b Skid Steer L	cambio de bateria	CAMBIO DE BATERIA	14/06/2021		Corrective Order	WO Completed	Skid Steer
607787	SDMO J60U 60 kVa	EQUIPO SIN DIESEL	LLAMADA DE EMERGENCIA	14/06/2021 23763 horas		Corrective Order	WO Completed	Generator
608055	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	15/06/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
608105	Landcruiser DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608106	Landcruiser DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608107	Landcruiser TC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608108	Landcruiser TC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608109	Landcruiser DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608111	Landcruiser TC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608113	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Bus
608114	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Bus
608115	Coaster	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Bus
608116	Coaster	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	15/06/2021		Corrective Order	WO Completed	Bus
608146	Grove RT600E 50TON	PROBLEMAS DE COMUNICACIÓN	PROBLEMAS DE COMUNICACIÓN	15/06/2021		Corrective Order	WO Completed	Crane/Hoist
608148	Grove GMK4100L 100TON	ESTABILIZADOR NO FUNCIONA	ESTABILIZADOR NO FUNCIONA	15/06/2021		Corrective Order	WO Completed	Crane/Hoist
608163	PRAMAC GSW560V 407 kVa	CAMBIO FILTRO RESPIRADORES	TANQUE COMBUSTIBLE PRINCIPAL	15/06/2021 18497		Corrective Order	WO Completed	Generator
608225	Tennant S30 Sweeper	Cambio de filtros	BARREDORA SE RECALIENTA	15/06/2021 AUTOCLOSED		Corrective Order	WO Completed	Scrubber / Sweeper
608266	CAT 930K	Necesita cambio de fitting de	NECESITA CAMBIO DE FITTING DE	15/06/2021		Corrective Order	WO Completed	Loader
608277	Hilux DC	cambio de 4 llantas	LLANTAS EN MAL ESTADO	15/06/2021		Corrective Order	WO Completed	Pickup truck
608298	Mobile equipment	UTILES ESCRITORIO GENSET	ADMINISTRATIVO	15/06/2021		Corrective Order	WO Completed	Area
608502	Hyster H700 Forklift	PM5 PREVENTIVE MAINTENANCE	PM5 PREVENTIVE MAINTENANCE	15/06/2021 90009221		Corrective Order	WO Completed	Forklift
608510	Hyster H700 Forklift	PM5 PREVENTIVE MAINTENANCE	PM5 PREVENTIVE MAINTENANCE	15/06/2021 90009222		Corrective Order	WO Completed	Forklift
608512	Caterpillar 320DL	Revision de a/c	A/C NO FUNCIONA	15/06/2021 20,760.40 hrs		Corrective Order	WO Completed	Excavator
608527	GROVE GMK 5170 170TON	correccion de fuga de aire	FUGA DE AIRE	15/06/2021		Corrective Order	WO Completed	Crane/Hoist

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
608532	Freightliner M2 106 Hydroseedi	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	15/06/2021		Corrective Order	WO Completed	Truck
608718	Hyster H300 13t Forklift (M)	bajo nivel de aceite	BAJO NIVEL DE ACEITE	16/06/2021		Corrective Order	WO Completed	Forklift
608739	Hino Serie 300	reparación de 1 llanta flat	REPARACIÓN DE 1 LLANTA FLAT	16/06/2021		Corrective Order	WO Completed	Truck
608740	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	16/06/2021		Corrective Order	WO Completed	Bus
608741	Bell 225f 4t Forklift (M)	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULIC	16/06/2021		Corrective Order	WO Completed	Forklift
608742	Hyster H300 13t Forklift (M)	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRÁULICO MOTOR	16/06/2021		Corrective Order	WO Completed	Forklift
608743	Hyster H300 13t Forklift (M)	Bajo nivel de aceite motor	BAJO NIVEL DE ACEITE MOTOR	16/06/2021		Corrective Order	WO Completed	Forklift
608744	Caterpillar 307E Miniexcavator	tensión de cadena y engrase de	TENSIÓN DE CADENA Y ENGRASE	16/06/2021		Corrective Order	WO Completed	Excavator
608746	Hyster E50Z-27 FORKLIFT	FUGA DE ACIDO DE BATERIA	FUGA DE ACIDO DE BATERIA	16/06/2021		Corrective Order	WO Completed	Forklift
608747	Caterpillar 140K	Reparacion de llanta delantera	REPARACION DE LLANTA DELANTERA	16/06/2021		Corrective Order	WO Completed	Grader
608792	Toyota Hilux	CAMBIO MUELLE POSTERIOR	AMORTIGUADOR TRASERO IZQUIERDO	16/06/2021 99164		Corrective Order	WO Completed	Pickup truck
608796	Manitou Mht-X1490 9t Telehand	LLANTA FLAT	LLANTA FLAT	16/06/2021		Corrective Order	WO Completed	Telehender
608806	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	16/06/2021		Corrective Order	WO Completed	Pickup truck
608829	Caterpillar 14H Motorgrader	Daño en una manguera	DAÑO EN UNA MANGUERA	16/06/2021		Corrective Order	WO Completed	Grader
608830	Caterpillar 14H Motorgrader	tiene exceso de nivel de aceit	TIENE EXCESO DE NIVEL DE ACEIT	16/06/2021		Corrective Order	WO Completed	Grader
608873	Broce Broom RJT 350	cambio de Filtro hidraulico	FUGA POR FILTRO HIDRAULICO	16/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
608874	International 7400 SBA Water T	Revision de luces y alarma	LUCES SE QUEDAN ENCENDIDAS	16/06/2021		Corrective Order	WO Completed	Water truck
608878	WT015 H7 CISTERNA SINOTRUK	cambio de 4 llantas	LLANTAS EN MAL ESTADO	16/06/2021		Corrective Order	WO Completed	Water truck
608917	Freightliner M112 Truck Tip	cambio de 2 llantas	LLANTAS EN MAL ESTADO	16/06/2021		Corrective Order	WO Completed	Tipper
608974	Caterpillar 320DL	cambio de mangueras	FUGA DE ACEITE HIDRAULICO	16/06/2021		Corrective Order	WO Completed	Excavator
609010	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	16/06/2021 13812 hrs		Corrective Order	WO Completed	Generator
609013	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	16/06/2021 27026 hrs		Corrective Order	WO Completed	Generator
609040	Hilux DC	cambio de 2 llantas	LLANTAS FLAT	16/06/2021		Corrective Order	WO Completed	Pickup truck
609042	Shuttlelift RTCD5540F 15TON	reparacion de cableado	TABLERO DESARMADO	16/06/2021		Corrective Order	WO Completed	Crane/Hoist
609048	Hyster H300 13t Forklift (M)	Hyster 300 Llanta Flat	HYSTER 300 LLANTA FLAT	16/06/2021		Corrective Order	WO Completed	Forklift
609052	JLG 800 AJ Manlift	nivelacion de aceite	BAJO NIVEL DE ACEITE DE MOTOR	16/06/2021 4215878.20 hrs		Corrective Order	WO Completed	Manlift
609057	Gallegos Flatbed Trailer	reparacion de llanta	LLANTA FLAT	16/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
609058	Hilux DC	Alarma de retroceso	ALARMA DE RETROCESO	16/06/2021		Corrective Order	WO Completed	Pickup truck
609075	Mobile equipment	Candados para taller	CANDADOS PARA TALLER	16/06/2021		Corrective Order	WO Completed	Area
609076	Landcruiser TC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	16/06/2021		Corrective Order	WO Completed	Pickup truck
609147	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	17/06/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
609167	SDMO J30U 38KVA	FLUCTUACION DE EQUIPO	LLAMADA DE EMERGENCIA	17/06/2021 6444 horas		Corrective Order	WO Completed	Generator
609199	Freightliner Columbia C1112	llanta flat	LLANTA FLAT	17/06/2021		Corrective Order	WO Completed	Mule truck
609200	Grove RT880E 75TON	Cambio de odometro	CAMBIO DE ODOMETRO	17/06/2021		Corrective Order	WO Completed	Crane/Hoist
609201	Grove RT600E 50TON	Cambio de odometro	CAMBIO DE ODOMETRO	17/06/2021		Corrective Order	WO Completed	Crane/Hoist
609202	Freightliner Columbia C1112	Bajo nivel de aceite motor	BAJO NIVEL DE ACEITE MOTOR	17/06/2021		Corrective Order	WO Completed	Mule truck
609278	Landcruiser TC	PREVENTIVE MAINTENANCE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 62386		PM Orders	WO Completed	Pickup truck
609295	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 91878		PM Orders	WO Completed	Pickup truck
609296	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Completed	Pickup truck
609297	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 31045		PM Orders	WO Completed	Pickup truck
609298	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 67032		PM Orders	WO Completed	Pickup truck
609299	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Completed	Pickup truck
609301	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 71826		PM Orders	WO Completed	Pickup truck
609304	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 34005		PM Orders	WO Completed	Pickup truck
609305	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Completed	Pickup truck
609306	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Completed	Pickup truck
609308	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 34230		PM Orders	WO Completed	Pickup truck
609309	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 12815		PM Orders	WO Completed	Pickup truck
609312	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 36599		PM Orders	WO Completed	Bus
609317	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021 82215		PM Orders	WO Completed	Pickup truck
609319	Hino Series300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	17/06/2021		PM Orders	WO Completed	Truck
609320	Caterpillar 226b Skid Steer L	colocacion de tornillos	CABINA SIN TORNILLOS	17/06/2021 2,083.3 Hrs		Corrective Order	WO Completed	Skid Steer
609329	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	17/06/2021		Corrective Order	WO Completed	Pickup truck
609331	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	17/06/2021		Corrective Order	WO Completed	Pickup truck
609333	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	TIRE AND RING INSPECT/CHANGE	17/06/2021		Corrective Order	WO Completed	Pickup truck
609335	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	TIRE AND RING INSPECT/CHANGE	17/06/2021		Corrective Order	WO Completed	Pickup truck
609338	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	17/06/2021 76813		Corrective Order	WO Completed	Pickup truck
609339	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	TIRE AND RING INSPECT/CHANGE	17/06/2021		Corrective Order	WO Completed	Pickup truck
609341	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	TIRE AND RING INSPECT/CHANGE	17/06/2021		Corrective Order	WO Completed	Pickup truck
609425	Hilux DC	REVISAR EVAPORADOR	MANTENIMIENTO CORRECTIVO	17/06/2021		Corrective Order	WO Completed	Pickup truck
609434	Grove RT700E 60TON	INSPECCION FUGA HIDRAULICA	FUGA HIDRAULICA	17/06/2021		Corrective Order	WO Completed	Crane/Hoist
609436	Caterpillar 740B	cambio de sello y PM	FUGA DE ACEITE E MOTOR	17/06/2021		Corrective Order	WO Completed	Articulated dump truck
609438	GROVE GMK 5170 170TON	Cambio de Carrete	CABLE DRUM EN MAL ESTADO	17/06/2021 90009262		Corrective Order	WO Completed	Crane/Hoist
609450	Mack Trucks GU	Reparacion de a/c	FALLO EN A/C	17/06/2021 90009786		Corrective Order	WO Completed	Boom truck
609494	Freightliner Columbia C1112	nivelacion de aceite	BAJO NIVEL DE ACEITE DE MOTOR	17/06/2021 3,896.20 hrs		Corrective Order	WO Completed	Mule truck
609496	Hilux DC	camboio de 1 llanta	LLANTA FLAT	17/06/2021 8,038.00 Km		Corrective Order	WO Completed	Pickup truck
609502	Caterpillar 426f2 Backhoe	Revision de presion de aire	LLANTA BAJA	17/06/2021 2,208.70 Hrs		Corrective Order	WO Completed	Backhoe
609507	Hyster E70xn 3t Forklift (E)	revision de cableado Electrico	EQUIPO NO CARGABA	17/06/2021		Corrective Order	WO Completed	Forklift

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
609509	Freightliner Columbia Cl112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	17/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Mule truck
609510	Hyster H300 13t Forklift (M)	Revision de activasion de ganc	GANCHOS NO ACTIVAN	17/06/2021	2,057.00 hrs	Corrective Order	WO Completed	Forklift
609521	Freightliner Columbia Cl112	reparacion de retrovisor	RETROVISOR SUELTO	17/06/2021	67,052.80 Km	Corrective Order	WO Completed	Mule truck
609527	Hyster H700 Forklift	Rectificacion de brazo	PIN PARTIDO	17/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Forklift
609541	Landcruiser DC	cambios de 2 llantas	LLANTAS EN MAL ESTADO	17/06/2021		Corrective Order	WO Completed	Pickup truck
609542	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	17/06/2021		Corrective Order	WO Completed	Bus
609550	SITE SERVICES	Carga de Material de Andamios	CARGA DE MATERIAL DE ANDAMIOS	17/06/2021	SOORTE W24	Corrective Order	WO Completed	Area
609649	John Deere 310K	Cambio de 2 mangueras	CAMBIO DE 2 MANGUERAS	18/06/2021		Corrective Order	WO Completed	Backhoe
609779	ATR-0000-001 4+320 AGRICO	Reparación de llanta flat	REPARACIÓN DE LLANTA FLAT	18/06/2021		Corrective Order	WO Completed	Tractor
609781	Grove RT600E 50TON	Luces no funcionan	LUCES NO FUNCIONAN	18/06/2021		Corrective Order	WO Completed	Crane/Hoist
609783	Mack Trucks GU	Reparacion de luces	REPARACIO DE LUCES	18/06/2021		Corrective Order	WO Completed	Boom truck
609830	Ford 450	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	18/06/2021	732411	Corrective Order	WO Completed	Pickup truck
609838	Freightliner 8170ME Water Truc	Lámpara delantera no funciona	UNA LÁMPARA DELANTERA NO SIRVE	18/06/2021		Corrective Order	WO Completed	Water truck
609862	PRAMAC GSW560V 407 kVa	CAMBIO PLACA DIODOS	MANTENIMIENTO CORRECTIVO	18/06/2021	14974 horas	Corrective Order	WO Completed	Generator
609871	USP&E GP700S/V-A 700 kVa	CAMBIO PLACA DIODOS	MANTENIMIENTO CORRECTIVO	18/06/2021	24798 hrs	Corrective Order	WO Completed	Generator
609906	Caterpillar 226b Skid Steer L	cambio de vidrio frontal	VIDRIO FRONTAL ROTO	18/06/2021	90009290	Corrective Order	WO Completed	Skid Steer
610025	John Deere 310K	Llanta #4 Flat	LLANTA #4 FLAT	18/06/2021		Corrective Order	WO Completed	Backhoe
610060	Intraax 53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	18/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
610068	SDMO J60U 60KVA	EVALUACION/DIAGNOSTICO	GENERADOR RESPALDO DATA CENTER PUERTO	18/06/2021	580 hrs	Corrective Order	WO Completed	Generator
610073	Freightliner Columbia Cl112	Reparacion de 1 llanta	LLANTA FLAT	18/06/2021		Corrective Order	WO Completed	Mule truck
610076	Caterpillar 426f2 Backhoe	Reparacion de 1 llanta	LLANTA FLAT	18/06/2021		Corrective Order	WO Completed	Backhoe
610079	Hyster H300 13t Forklift (M)	Reparacion de 1 llanta	LLANTA FLAT	18/06/2021		Corrective Order	WO Completed	Forklift
610104	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Mule truck
610110	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021		Corrective Order	WO Completed	Mule truck
610111	USP&E GP700S/V-A 700 kVa	REVISAR FUGA DE REFRIGERANTE	RELLENOS CONTINUOS	18/06/2021	16690 hrs	Corrective Order	WO Completed	Generator
610112	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021	67,868.90 km	Corrective Order	WO Completed	Mule truck
610115	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021		Corrective Order	WO Completed	Mule truck
610119	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021		Corrective Order	WO Completed	Mule truck
610121	Caterpillar C4.4 88KVA	LEVANTAMIENTO INFORMACION	OVERHAUL REPARACION GENERAL	18/06/2021	27287 horas	Corrective Order	WO Completed	Generator
610123	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021		Corrective Order	WO Completed	Mule truck
610129	Freightliner Columbia Cl112	INSTALACION DE LUCES TRASERA	INSTALACION DE LUCES TRASERA	18/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Mule truck
610130	Caterpillar 14H Motorgrader	instalacion de cilindro de inc	CILINDRO DE INCLINACION DE RUEDA DELANTERO ROTA	18/06/2021		Corrective Order	WO Completed	Grader
610139	GROVE GMK 5170 170TON	Reparacion de Cable Drum	CABLE DRUM DAÑADO	18/06/2021		Corrective Order	WO Completed	Crane/Hoist
610141	Hino Series 300	reparacion de tuberia	FUGA DE ACEITE DE FRENO	18/06/2021		Corrective Order	WO Completed	Truck
610142	Caterpillar 740b Ej	Cambio de manguera	FUGA DE ACEITE HIDRAULICO	18/06/2021		Corrective Order	WO Completed	Articulated dump truck
610150	Grove GMK 4080 80TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Completed	Crane/Hoist
610164	Broderson IC200-2C 9TON	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Completed	Crane/Hoist
610178	Hyster J40zt	INSPECCION PRE-CERTIFICACION	INSPECCION	18/06/2021		Corrective Order	WO Completed	Forklift
610184	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	18/06/2021		Corrective Order	WO Completed	Manlift
610225	Grove RT600E 50TON	Cambio de pola de fan motor	CAMBIO DE POLEA DE FAN MOTOR	19/06/2021	90009472	Corrective Order	WO Completed	Crane/Hoist
610319	Intraax 53121 Hendrickso	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	19/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
610348	Caterpillar 336DL	Inspeccion general AFEX	INSPECCION GENERAL AFEX	19/06/2021		Corrective Order	WO Completed	Excavator
610354	Freightliner M112 Truck Tip	Guardafango resprendido	GUARDAFANGO RESPRENDIDO	19/06/2021		Corrective Order	WO Completed	Tipper
610355	Freightliner 8170ME Water Truc	Reparacion de luces y llanta	REPARACION DE LUCES Y LLANTA	19/06/2021		Corrective Order	WO Completed	Water truck
610356	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	19/06/2021		Corrective Order	WO Completed	Bus
610357	Caterpillar 140K	Falla electrico sin comunicaci	FALLA ELECTRICO SIN COMUNICACION CON EL ECM	19/06/2021		Corrective Order	WO Completed	Grader
610359	Manitou Mht-X860 6t Telehand	eje de mando partido	EJE DE MANDO PARTIDO	19/06/2021		Corrective Order	WO Completed	Telehender
610442	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	16300 hrs	PM Orders	WO Completed	Generator
610443	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	27287 horas	PM Orders	WO Completed	Generator
610444	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021		PM Orders	WO Completed	Generator
610445	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	28460 hrs	PM Orders	WO Completed	Generator
610446	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	10610 hrs	PM Orders	WO Completed	Generator
610447	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	18765 hrs	PM Orders	WO Completed	Generator
610448	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	20349 hrs	PM Orders	WO Completed	Generator
610456	Caterpillar D110 E2 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	16085 HORAS	PM Orders	WO Completed	Generator
610459	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	16690 HORAS	PM Orders	WO Completed	Generator
610463	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	30708 hrs	PM Orders	WO Completed	Generator
610464	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	24135 hrs	PM Orders	WO Completed	Generator
610465	SDMO J30U 38 kVa	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	12339 HRS	PM Orders	WO Completed	Generator
610466	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/06/2021	15668 hrs	PM Orders	WO Completed	Generator
610469	Caterpillar 740B EJ ADT	R&I Autolubrication Pump	R&I AUTOLUBRICATION PUMP	19/06/2021		PM Orders	WO Completed	Articulated dump truck
610472	Caterpillar 740B EJ ADT	C/ BUJE BARRA ESTABILIZAD CENT	BUEJS EN MAL ESTAD	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610475	Unimog Service Truck	REPORTE DE DANOS //CHECK LIST	REPORTE DE DANOS //CHECK LIST	19/06/2021		Corrective Order	WO Completed	Truck
610478	Gallegos Flatbed Trailer	Cambio de 2 llantas	LLANTAS FLAT	19/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
610487	Caterpillar 740B EJ ADT	C/ BEARING BUSING PIN HITCH	BEARING DESGASTADOS	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610493	Caterpillar 740B EJ ADT	C/ CYL LEVANTE CABINA Y PASAD	CILINDRO CON FUGA	19/06/2021		Corrective Order	WO Completed	Articulated dump truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
610494	Caterpillar 740B EJ ADT	C/ MANG HYD ENFRIAMIENTO LH RH	MANGUERAS ROTAS	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610497	Caterpillar 12M	Temperatura de aceite hidrául	TEMPERATURA DE ACEITE HIDRÁULI	19/06/2021		Corrective Order	WO Completed	Grader
610500	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	19/06/2021		Corrective Order	WO Completed	Pickup truck
610509	Caterpillar 740B EJ ADT	C/ PINS COJINE CYL DIREC LH RJ	MAL ESTADO	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610513	Unimog Service Truck	C. de Reversa y Pito	ALARMA DE REVERSA Y PITO NO FUNCIONAN	19/06/2021		Corrective Order	WO Completed	Truck
610551	New Holland Lm 1745	arranque auxiliar	EQUIPO NO ARRANCA	19/06/2021	16,434.00 hrs	Corrective Order	WO Completed	Telehender
610556	Grove RT650E 45TON	Revision de pin y mangueras	PIN SUELTO Y MAMGUERA	19/06/2021	765.80 hrs	Corrective Order	WO Completed	Crane/Hoist
610621	Freightliner Columbia CI112	cambio de 4 llantas	LLANTAS EN MAL ESTADO	19/06/2021		Corrective Order	WO Completed	Mule truck
610656	John Deere 9370R Tractor	cambio de sensores	SENSORES DE A/C EN FALLA	19/06/2021	90011371	Corrective Order	WO Completed	Tractor
610680	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	APAGADO POR ALTA TEMPERATURA	19/06/2021	13882 hrs	Corrective Order	WO Completed	Generator
610681	Manitou Mht-X1490 9t Telehand	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Telehender
610682	Caterpillar 740B EJ ADT	C/ BUJE BARRA ESTABILIZADORA	BUJES EN MAL ESTADO	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610683	Hyster E50Z-27 FORKLIFT	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Forklift
610684	Caterpillar 740B EJ ADT	C/ BEARING PIN HITCH	BEARING DESGASTADO	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610688	Caterpillar 740B EJ ADT	C/ MANG HYD DE FRENO	MANGUERA ROTA	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610689	Caterpillar 740B EJ ADT	C/ MOUN DE SUSP POST 3 Y 4	MOUNT RAJDOS	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610691	Caterpillar 740B EJ ADT	C/ PASADOR BEARNG FRAME POST	PASADOR BEARING DESGASTADOS	19/06/2021		Corrective Order	WO Completed	Articulated dump truck
610698	Manitou MTH-X 10120	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Telehender
610700	Manitou Mht-X860 6t Telehand	Cambio de componentes	INSPECCION	19/06/2021	90011692 90011359	Corrective Order	WO Completed	Telehender
610716	Grove RT600E 50TON	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Crane/Hoist
610719	Terex RT670 64TON	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Crane/Hoist
610721	Grove RT880E 75TON	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Crane/Hoist
610723	Terex MAC25 25TON	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Crane/Hoist
610725	JLG T350 Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610728	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610730	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610731	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610732	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610734	JLG 800 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610735	JLG 800 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610736	JLG 800 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610737	JLG 800 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610738	JLG 800 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610741	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610743	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610744	Grove RT9130E 120TON	cambio de mangueras	FUGA DE ACEITE HIDRAULICO	19/06/2021		Corrective Order	WO Completed	Crane/Hoist
610745	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610747	JLG 1250 AJP Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610750	JLG 450 AJ Manlift	INSPECCION PRE-CERTIFICACION	INSPECCION	19/06/2021		Corrective Order	WO Completed	Manlift
610787	SDMO J60U 60KVA	CAMBIO DE RADIADOR	MANTENIMIENTO CORRECTIVO	20/06/2021	11574 horas	Corrective Order	WO Completed	Generator
610864	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	20/06/2021	23.61 Kh	PM Orders	WO Completed	Generator
610882	Hilux DC	EVALUAR EMBRAGUE 4W	VERIFICAR 4W	20/06/2021	83308 KM	Corrective Order	WO Completed	Pickup truck
610883	SDMO J60U 60 kVa	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	20/06/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
610892	SDMO J60U 60KVA	CAMBIO DE BOMBA DE CEBA DIESEL	FUGA DE ACEITE Y DIESEL	20/06/2021	11574 horas	Corrective Order	WO Completed	Generator
610923	WT015 H7 CISTERNA SINOTRUK	Cambio de correas y compresor	SIN CORREA DE ALTERNADOR Y COMPRESOR DE A/C	20/06/2021		Corrective Order	WO Completed	Water truck
610932	Caterpillar 740B EJ ADT	INSP/ SISTEMA A/C	FILTROS OBSTRUIDOS	20/06/2021		Corrective Order	WO Completed	Articulated dump truck
610937	Caterpillar 740B EJ ADT	INSP/ SISTEMA A/C	FILTROS OBSTRUIDOS	20/06/2021		Corrective Order	WO Completed	Articulated dump truck
610959	Freightliner M112 Truck Tip	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	20/06/2021		Corrective Order	WO Completed	Tipper
610961	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	20/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
610972	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	20/06/2021		Corrective Order	WO Completed	Bus
610974	Coaster	cambio de 2 llantas	LLANTAS FLAT	20/06/2021		Corrective Order	WO Completed	Bus
611038	Coaster	cambio de 2 llantas	LLANTAS FLAT	20/06/2021		Corrective Order	WO Completed	Bus
611048	Coaster	cambio de 2 llanta	LLANTAS FLAT	20/06/2021		Corrective Order	WO Completed	Bus
611064	Caterpillar 140K	Revision y engrase	REVISION Y ENGRASE	20/06/2021		Corrective Order	WO Completed	Grader
611127	Gallegos 28M3 Lime Tank	MANIGUETA DE VALVULA	MANIGUETA DE VALVULA	20/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
611128	Gallegos Lime Tank	FUGA DE AIRE	FUGA DE AIRE	20/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
611132	Freightliner Columbia CI112	ESCOLTA	ESCOLTA	20/06/2021		Corrective Order	WO Completed	Mule truck
611133	Manitou Mht-X1490 9t Telehand	Llanta Trasera-Der Flat	LLANTA TRASERA-DER FLAT	20/06/2021		Corrective Order	WO Completed	Telehender
611138	Freightliner Columbia CI112	LUCES	LUCES	20/06/2021		Corrective Order	WO Completed	Mule truck
611141	Freightliner Columbia CI112	BALINERA/ TUERCA	BALINERA/ TUERCA	20/06/2021		Corrective Order	WO Completed	Mule truck
611142	Freightliner Columbia CI112	INSPECCION TORQUE NEUMATICO	AJUSTE DE PERNOS	20/06/2021		Corrective Order	WO Completed	Mule truck
611173	JLG 1250 AJP Manlift	cambio de bateria	BATRIA NO SIRVE	20/06/2021		Corrective Order	WO Completed	Manlift
611192	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	RELLENO DE COOLANT Y ACEITE, REVISION GENERAL	20/06/2021	24103 hrs	Corrective Order	WO Completed	Generator
611196	USP&E GP700S/V-A 700 kVa	CORRECTIVO	REPARACION DE FUGA DE COOLANT Y RELLENO DE REFRIGERANTE	20/06/2021	16392 hrs	Corrective Order	WO Completed	Generator
611199	SDMO J60U 60 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	20/06/2021	23891 hrs	Corrective Order	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
611204	JLG 800 AJ Manlift	Revision de equipo	REVISION DE EQUIPO	20/06/2021	4,536.10 hrs	Corrective Order	WO Completed	Manlift
611212	Unimog Service Truck	Correas defectuosas	CORREAS DEFECTUOSAS	20/06/2021		Corrective Order	WO Completed	Truck
611318	Hyster H700 Forklift	Mangueras de engrasdefectuosas	MANGUERAS DE ENGRASDEFECTUOSAS	21/06/2021		Corrective Order	WO Completed	Forklift
611322	Caterpillar C9 250 kVa	LIMPIEZA DE ACEITE EN PISO	LLAMADA DE EMERGENCIA	21/06/2021	18520 horas	Corrective Order	WO Completed	Generator
611398	Hilux DC	INSTALAR BOLA TIRO/CARGA	REQUERIMIENTO NUEVO	21/06/2021		Corrective Order	WO Completed	Pickup truck
611409	Coaster	REVISAR FRENOS SERVICIO/PARQUE	MANTEIMIENTO CORRECTIVO	21/06/2021	16972 KM	Corrective Order	WO Completed	Bus
611455	Freightliner M112 Truck Tip	Cambio de 2 llantas	LLANTAS FLAT	21/06/2021		Corrective Order	WO Completed	Tipper
611463	Manitou Mht-X860 6t Telehand	Cambio de manguera	FUGA DE ACEITE HIDRAULICO	21/06/2021		Corrective Order	WO Completed	Telehender
611486	Caterpillar CS533E Compactor	cambio de valvula selenoide	FUGA DE ACEITE HIDRAULICA	21/06/2021		Corrective Order	WO Completed	Compactor
611521	Caterpillar 12M	Recalentamiento del equipo	RECALENTAMIENTO DEL EQUIPO	21/06/2021		Corrective Order	WO Completed	Grader
611524	Caterpillar 740B EJ ADT	C/ MOUNTS ANCLAJE TRNASFER	MAL ESTADO	21/06/2021		Corrective Order	WO Completed	Articulated dump truck
611526	Caterpillar 140K	Neumático Flat	NEUMÁTICO FLAT	21/06/2021		Corrective Order	WO Completed	Grader
611527	Power Curbers 5700-C	Daño en el pistón frontal lado	DAÑO EN EL PISTÓN FRONTAL LADO	21/06/2021		Corrective Order	WO Completed	Kerb Machine
611528	Power Curbers 5700-C	2 clavijas de la banda transpo	2 CLAVIJAS DE LA BANDA TRANSP	21/06/2021		Corrective Order	WO Completed	Kerb Machine
611530	Power Curbers 5700-C	la tapa del dispensador se con	LA TAPA DEL DISPENSADOR SE CON	21/06/2021		Corrective Order	WO Completed	Kerb Machine
611568	Caterpillar 426f2 Backhoe	cambio de manguera	FUGA HIDRAULICA	21/06/2021		Corrective Order	WO Completed	Backhoe
611619	JLG 450 AJ Manlift	GIRO BLOQUEADO	GIRO BLOQUEADO	21/06/2021		Corrective Order	WO Completed	Manlift
611666	SDMO J30U 38KVA	LLAMADA DE EMERGENCIA	CAMBIO DE CORREA REVENTADA Y RELLENO DE COOLANT	21/06/2021	18761 hrs	Corrective Order	WO Completed	Generator
611697	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	RELLENO DE COOLANT	21/06/2021	24132 hrs	Corrective Order	WO Completed	Generator
611705	Caterpillar 740B EJ ADT	C/ ARM FRAME FRONTAL	ALOJAMIENTO BUSHING DESGASTADO	21/06/2021		PM Orders	WO Completed	Articulated dump truck
611722	Caterpillar 740b Ej	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Articulated dump truck
611724	Hyster H800 32t Forklift (M)	Leak Aceite - Manguera Hyster	LEAK ACEITE - MANGUERA HYSTER	21/06/2021		Corrective Order	WO Completed	Forklift
611726	Caterpillar 740B EJ	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Articulated dump truck
611732	Caterpillar D8T Dozer	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Dozer
611736	Caterpillar 14M Motorgrader	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Grader
611739	Caterpillar 14H Motorgrader	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Grader
611747	JLG 450 AJ Manlift	cambio de mangueras	FUGAS HIDRAULICAS	21/06/2021		Corrective Order	WO Completed	Manlift
611750	Manitou Mht-X860 6t Telehand	Cambio de manguera	FUGA DE ACEITE HIDRAULICO	21/06/2021		Corrective Order	WO Completed	Telehender
611751	JLG 800 AJ Manlift	REPARACION CILINDROS (TSI)	CORRECTIVO	21/06/2021	50014177	Corrective Order	WO Completed	Manlift
611753	Caterpillar 236d Skid Steer L	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021	90010518	Corrective Order	WO Completed	Skid Steer
611758	Caterpillar 226B	INSPECCION REVISION TA1	INSPECCION IASA APOYO TACTICO	21/06/2021		Corrective Order	WO Completed	Skid Steer
611761	SITE SERVICES	Movimiento de Material Andamio	MOVIMIENTO DE MATERIAL ANDAMIO	21/06/2021	SOPORTE W25	Corrective Order	WO Completed	Area
611762	Hyster H800 32t Forklift (M)	Fuga de aceite	FUGA DE ACEITE	21/06/2021		Corrective Order	WO Completed	Forklift
612029	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	22/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
612102	Caterpillar 226b Skid Steer L	LLANTA FLAT	LLANTA FLAT	22/06/2021		Corrective Order	WO Completed	Skid Steer
612103	Hilux DC	Cambio de baterias	CAMBIO DE BATERIAS	22/06/2021		Corrective Order	WO Completed	Pickup truck
612104	Hyster H800 32t Forklift (M)	Cambio de manguera de direccio	CAMBIO DE MANGUERA DE DIRECCIO	22/06/2021		Corrective Order	WO Completed	Forklift
612106	Hyster E70xn 3t Forklift (E)	Codigos de llanta activos	CODIGOS DE LLANTA ACTIVOS	22/06/2021		Corrective Order	WO Completed	Forklift
612107	Freightliner M112 Truck Tip	Manguera hidraulica rota	MANGUERA HIDRAULICA ROTA	22/06/2021		Corrective Order	WO Completed	Tipper
612108	WT013 H7 CISTERNA SINOTRUK	Luz delantera quemada	LUZ DELANTERA QUEMADA	22/06/2021		Corrective Order	WO Completed	Water truck
612113	Freightliner Columbia Cl112	VIDRIO ROTO / LUCES PILOTO	VIDRIO ROTO	22/06/2021		Corrective Order	WO Completed	Mule truck
612114	Freightliner Columbia Cl112	BALINERAS TENSORAS	BALINERAS TENSORAS	22/06/2021		Corrective Order	WO Completed	Mule truck
612118	Gallegos 28M3 Lime Tank	1FLAT / TRANCADO COMPARTIMENTO	LLANTA FLAT	22/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
612120	Freightliner Columbia Cl112	MANIGUETA ROTA / LUCES	MANIGUETA ROTA	22/06/2021		Corrective Order	WO Completed	Mule truck
612148	SDMO T11UM 10 kVa	SERVICIO INSTALACION GENERADOR	INTERCAMBIO CON GS155 POR REPARACION	22/06/2021	50013875	Corrective Order	WO Completed	Generator
612194	Landcruiser DC	CAMBIO BUJE MUELLE/BARRA ESTAB	CAMBIO ALARMA RETROCESO/AMORTIGUADOR TRASERO	22/06/2021	79038	Corrective Order	WO Completed	Pickup truck
612231	Landcruiser DC	CAMBIO SUBCONJUNTO DIRECCION	REPARACION DE COCOBOLAS	22/06/2021	66924	Corrective Order	WO Completed	Pickup truck
612241	Manitou Mht-X1490 9t Telehand	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	22/06/2021	90009389	Corrective Order	WO Completed	Telehender
612244	Manitou Mht-X1490 9t Telehand	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	22/06/2021	90009390	Corrective Order	WO Completed	Telehender
612278	Freightliner M2 106 Sucker Tru	Reparacion de a/c	A/C NO FUNCIONA	22/06/2021		Corrective Order	WO Completed	Sucker truck
612280	Freightliner M2 106 Sucker Tru	correccion de fuga de aceite d	FUGA DE ACEITE DE MOTOR	22/06/2021		Corrective Order	WO Completed	Sucker truck
612321	Caterpillar 740B EJ ADT	C/ BEARING CYL LEVANT LH RH	BEARING EN MAL ESTADO	22/06/2021		Corrective Order	WO Completed	Articulated dump truck
612377	Caterpillar C9 250 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR BAJA RPM	22/06/2021	18601 hrs	Corrective Order	WO Completed	Generator
612381	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR ALTA TEMPERATURA	22/06/2021		Corrective Order	WO Completed	Generator
612386	Freightliner 8170ME Water Truc	Se le daño la cruceta del eje	SE LE DAÑO LA CRUCETA DEL EJE	22/06/2021		Corrective Order	WO Completed	Water truck
612390	JLG 450 AJ Manlift	CAMBIO DE MANGUERAS	FUGA HIDRAULICA	22/06/2021		Corrective Order	WO Completed	Manlift
612392	Terex RT5551 55TON	CAMBIO DE FILTROS	FILTROS MALOS	22/06/2021		Corrective Order	WO Completed	Crane/Hoist
612433	Power Curbers 5700-C	Cambio de valvulas	FALLA EN CILINDRO DE SISTEMA DE LEVANTE	22/06/2021		Corrective Order	WO Completed	Kerb Machine
612434	Freightliner Cl 120	Rep de luces y ajuste de freno	VERIFICACION DE LUCES Y FRENO	22/06/2021		Corrective Order	WO Completed	Mule truck
612435	Freightliner Columbia Cl112	CAMBIO DE COMPONENTES	CAMBIO BALINERAS Y LAMPARAS	22/06/2021	90010342	Corrective Order	WO Completed	Mule truck
612437	Gallegos Flatbed Trailer	cambio de pulmon y ajuste fr	REVISION DE PULMOS Y AJUSTE DE FRENO	22/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
612439	Freightliner Columbia Cl112	instalacion de retrovisor	INSTALACION DE RETROVISOR	22/06/2021		Corrective Order	WO Completed	Mule truck
612440	JLG 450 AJ Manlift	Revision de movimientos	MOVIMIENTOS LENTOS	22/06/2021		Corrective Order	WO Completed	Manlift
612442	Caterpillar 426f2 Backhoe	Revision de Equipo IIASA	REVISION DE EQUIPO IIASA	22/06/2021		Corrective Order	WO Completed	Backhoe
612443	Manitou Mht-X1490 9t Telehand	Revision de llanta	REVISION DE LLANTA	22/06/2021		Corrective Order	WO Completed	Telehender
612452	Mobile equipment	Varillas de bronce	VARILLAS DE BRONCE	22/06/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
612453	Landcruiser TC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	22/06/2021		Corrective Order	WO Completed	Pickup truck
612636	Caterpillar 336DL	Problema con tensado de cadena	PROBLEMA CON TENSADO DE CADENA	23/06/2021		Corrective Order	WO Completed	Excavator
612639	Caterpillar CS74 Compactor	Problema con sist. de inyeccio	PROBLEMA CON SIST. DE INYECCIO	23/06/2021	90009959	Corrective Order	WO Completed	Compactor
612659	Freightliner Columbia CI112	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	23/06/2021		Corrective Order	WO Completed	Mule truck
612662	Freightliner Columbia CI112	Ajuste de varillaje	AJUSTE DE VARILLAJE	23/06/2021		Corrective Order	WO Completed	Mule truck
612663	Manitou Mht-X860 6t Telehand	No enciendefalla con arranque	NO ENCIENDEFALLA CON ARRANQUE	23/06/2021		Corrective Order	WO Completed	Telehender
612665	JLG 1250 AJP Manlift	EQUIPO SE RECALIENTA	EQUIPO SE RECALIENTA	23/06/2021		Corrective Order	WO Completed	Manlift
612668	Caterpillar 307E Miniexcavator	Engrase y tension de la cadena	ENGRASE Y TENSION DE LA CADENA	23/06/2021		Corrective Order	WO Completed	Excavator
612670	Caterpillar DE165E0 165 kVa	EMERGENCY CALL	ENGINE BEL REPLACE	23/06/2021	14767 HRS	Corrective Order	WO Completed	Generator
612671	Caterpillar C7.1 200 kVa	EMERGENCY CALL	AVR AJUSTMENT	23/06/2021	16836	Corrective Order	WO Completed	Generator
612772	Freightliner Boom Truck	Cambio de 2 llantas	LLANTAS DAÑADAS	23/06/2021	43,840.00 km	Corrective Order	WO Completed	Boom truck
612788	Caterpillar 426F2 Backhoe	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Backhoe
612789	Caterpillar 307E Miniexcavator	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Excavator
612803	Caterpillar 226b Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612805	Caterpillar 226b Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612807	Caterpillar 300.9D MicoExcavat	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Excavator
612820	Caterpillar 226b Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612825	Caterpillar 416E	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Backhoe
612828	Caterpillar D8T Dozer	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Dozer
612830	Caterpillar D8T Dozer	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Dozer
612835	Caterpillar 305ECR	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Excavator
612836	Caterpillar 12M Motorgrader	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Grader
612841	Caterpillar 14H Motorgrader	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Grader
612844	Caterpillar 140K	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Grader
612851	Caterpillar RM300	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Road Reclaimer
612857	Freightliner Columbia CI112	Camabio de 8 llantas	LLANTAS EN MAL ESTADO	23/06/2021	67,868.00 Km	Corrective Order	WO Completed	Mule truck
612860	CAT 930K	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Loader
612867	Caterpillar 426f2 Backhoe	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Backhoe
612876	John Deere 310K	Neumático atascado	NEUMÁTICO ATASCADO	23/06/2021		Corrective Order	WO Completed	Backhoe
612877	Caterpillar 226b Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612879	Freightliner CI 120	LUCES / AIRE REMOLQUE	LUCES / AIRE REMOLQUE	23/06/2021		Corrective Order	WO Completed	Mule truck
612882	Caterpillar 226b Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612884	Caterpillar 320DL	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Excavator
612886	Caterpillar 336DL Excavator	TA1 EVALUACION GENERAL EQUIPO	INSPECCION ESPECIALIZADA IASA	23/06/2021	90010610 90010952 90011414	Corrective Order	WO Completed	Excavator
612893	Caterpillar 426f2 Backhoe	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Backhoe
612894	Caterpillar 416F2 Backhoe	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021	90010662	Corrective Order	WO Completed	Backhoe
612903	Caterpillar D8T Dozer	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Dozer
612906	Caterpillar 12M	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Grader
612907	JLG 1250 AJP Manlift	Cambio de selenoide	SELENOIDE EN MAL ESTADO	23/06/2021	90009460	Corrective Order	WO Completed	Manlift
612908	Caterpillar 14H Motorgrader	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Grader
612917	Caterpillar 236d Skid Steer L	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612928	Caterpillar 226B	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	23/06/2021		Corrective Order	WO Completed	Skid Steer
612931	Freightliner M112 Truck Tip	neumático reventado	NEUMÁTICO REVENTADO	23/06/2021		Corrective Order	WO Completed	Tipper
612957	Caterpillar C9 250 kVa	CORRECTIVO	CAMBIO DE INYECTORES	23/06/2021	18601 hrs	Corrective Order	WO Completed	Generator
612960	Landcruiser TC	cambio de 4 llantas	LLANTAS EN MAL ESTADO	23/06/2021		Corrective Order	WO Completed	Pickup truck
612995	Freightliner Columbia CI112	cambio de filtro por fuga	FUGA EN FILTRO DE ACEITE	23/06/2021	56,813.20 km	Corrective Order	WO Completed	Mule truck
613033	PRAMAC GSW560V 407 kVa	ALTERNATOR AC REMOVE	CORRECTIVE MAINTENANCE	23/06/2021	17918 hrs	Corrective Order	WO Completed	Generator
613036	Caterpillar C9 250 kVa	GENERATOR CONNECTION	CORRECTIVE MAINTENANCE	23/06/2021	18600 hrs	Corrective Order	WO Completed	Generator
613043	Eagle Beaver 50sgl-Pt	Revision de arranque	MOTOR DE BOMBA HIDRAULICA NO ARRANCA	23/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
613046	Freightliner CI 120	rellenado de coolam	BAJO NIVEL DE COOLAM	23/06/2021	291,143.00 Km	Corrective Order	WO Completed	Mule truck
613051	Freightliner Columbia CI112	Reparacion de espejos	ESPEJOS SUELTOS	23/06/2021	59,662.50 Km	Corrective Order	WO Completed	Mule truck
613054	Power Curbers 5700-C	reparacion de escotilla	ESCOTILLA DE SIN FIN NO CIERRA	23/06/2021	122.70 hrs	Corrective Order	WO Completed	Kerb Machine
613056	SJS SJ6530	Cambios de mount	MOUNT EN MAL ESTADO	23/06/2021		Corrective Order	WO Completed	Compactor
613062	Freightliner Boom Truck	equipo no arranca	EQUIPO NO ARRANCA	23/06/2021		Corrective Order	WO Completed	Boom truck
613123	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	24/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
613137	Cargador 966H Wheel Loader	Pin de barra de articulacion	PIN DE BARRA PARA EVITAR ARTICULACION AUSENTES	24/06/2021		Corrective Order	WO Completed	Loader
613174	PRAMAC GSW560V 407 kVa	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	24/06/2021	50013948 60020884	Corrective Order	WO Completed	Generator
613212	Hyster H300 13t Forklift (M)	PM5 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021	90009493 90009948	Corrective Order	WO Completed	Forklift
613214	Hyster H300 13t Forklift (M)	PM5 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021	90009494 90009949	Corrective Order	WO Completed	Forklift
613225	PRAMAC GSW90P 74 kVa	CAMBIO TRANSFER BOMBA DIESEL	FUGA COMBUSTIBLE	24/06/2021	25398 horas	Corrective Order	WO Completed	Generator
613243	Caterpillar 740B	C/PINES Y COJINETES CYL DIREC	EN MAL ESTADO	24/06/2021		Corrective Order	WO Completed	Articulated dump truck
613245	Gallegos Lime Tank	cambio de 2 pulmones	FUGA DE AIRE	24/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
613247	Bomag BW219DH-4	Cambio de actuadores de cabina	ACTUADORES DE CABINA DE SISTEMA AFEX DAÑADOS	24/06/2021	AUTCLOSED	Corrective Order	WO Completed	Compactor
613248	Caterpillar 740B	C/PINES Y BEARING CYL LEVANTE	EN MAL ESTADO	24/06/2021		Corrective Order	WO Completed	Articulated dump truck
613251	Caterpillar 740B	C/MOUNTING POS 3 Y4	EN MAL ESTADO	24/06/2021		Corrective Order	WO Completed	Articulated dump truck
613255	Caterpillar 740B	C/BUSHING Y BEARING PIN HITCH	DEFECTUOSOS	24/06/2021		Corrective Order	WO Completed	Articulated dump truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
613259	Freightliner M2 112 Sucker Tru	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	24/06/2021		Corrective Order	WO Completed	Sucker truck
613313	Freightliner Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021		Corrective Order	WO Completed	Mule truck
613329	PRAMAC GSW90P 74 kVa	CORRECTIVO	CAMBIO DE BOMBA DE BOMBA AGUA, LAVADO DE RADIADOR Y MOTOR	24/06/2021 24194 hrs		Corrective Order	WO Completed	Generator
613336	Landcruiser DC	CAMBIO CABLE FRENO	CAMBIO CRUCETA EJE MANDO	24/06/2021 63,866		Corrective Order	WO Completed	Pickup truck
613340	Landcruiser DC	REPARACION MECANICA	REPARACION ELECTRICA	24/06/2021 63,999		Corrective Order	WO Completed	Pickup truck
613343	Hilux DC	CAMBIO HOJA MUELLES	MANTENIMIENTO CORRECTIVO	24/06/2021 58,247		Corrective Order	WO Completed	Pickup truck
613350	Hyster H70ft 3t Forklift (M)	PM5 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021 90010000		Corrective Order	WO Completed	Forklift
613371	Landcruiser DC	CAMBIO HOJA MUELLES/BANDAS	CAMBIO AMORTIGUADORES TRASEROS	24/06/2021 107,527		Corrective Order	WO Completed	Pickup truck
613375	Landcruiser TC	CAMBIO AMORTIGUADOR/BALINERA	CAMBIO RETENEDORA	24/06/2021 58,702		Corrective Order	WO Completed	Pickup truck
613376	Freightliner Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	24/06/2021		Corrective Order	WO Completed	Mule truck
613377	Hilux DC	CAMBIO MOTOR ARRANQUE	CAMBIO CRUCETAS	24/06/2021 33,165		Corrective Order	WO Completed	Pickup truck
613378	Mobile equipment	Reparacion de 2 llantas	LLANTAS FLAT	24/06/2021		Corrective Order	WO Completed	Area
613386	Hilux DC	CAMBIO PARABRISA TRASERO	MANTENIMIENTO CORRECTIVO	24/06/2021 13,900		Corrective Order	WO Completed	Pickup truck
613390	PRAMAC GSW45P 48 kVa	LLAMADA DE EMERGENCIA	EQUIPO NO ENCIENDE	24/06/2021 8281 hrs		Corrective Order	WO Completed	Generator
613394	Hilux DC	CAMBIO KIT EMBRAGUE/MUELLE RH	CAMBIO MUELLE RH	24/06/2021 26,416		Corrective Order	WO Completed	Pickup truck
613404	Freightliner M2 106	Cambio de sellos	FUGA DE EMULSION POR SELLOS DE TUBERIAS	24/06/2021		Corrective Order	WO Completed	Bitumen truck
613406	Gallegos Flatbed Trailer	ajuste de frenos	FRENOS DESAJUSTADOS	24/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
613409	TTP-0000-102	Cambio de mangueras	CAMBIO DE MANGERAS	24/06/2021		Corrective Order	WO Completed	Excavator
613411	Freightliner CI 120	Ajuaste de fenos	AJUSTES DE FRENOS	24/06/2021		Corrective Order	WO Completed	Mule truck
613412	Gallegos Flatbed Trailer	Ajuste de frenos	AJUSTES DE FRENOS	24/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
613413	Caterpillar 336DL	rellenado de aceite hidraulico	BAJO NIVEL DE ACEITE HIDRAULICO	24/06/2021		Corrective Order	WO Completed	Excavator
613414	John Deere 310K	Rueda delantera trancada	RUEDA DELANTERA TRANCADA	24/06/2021		Corrective Order	WO Completed	Backhoe
613425	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 90806		PM Orders	WO Completed	Pickup truck
613427	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 44,638		PM Orders	WO Completed	Pickup truck
613428	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 23257		PM Orders	WO Completed	Pickup truck
613430	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Completed	Pickup truck
613431	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Completed	Pickup truck
613433	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 14102		PM Orders	WO Completed	Pickup truck
613434	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 21019 KM		PM Orders	WO Completed	Pickup truck
613435	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 10080		PM Orders	WO Completed	Pickup truck
613436	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Completed	Pickup truck
613437	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 11757		PM Orders	WO Completed	Pickup truck
613438	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 6,684		PM Orders	WO Completed	Pickup truck
613439	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 13222		PM Orders	WO Completed	Pickup truck
613440	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 29333		PM Orders	WO Completed	Bus
613443	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021 28461		PM Orders	WO Completed	Bus
613444	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	24/06/2021		PM Orders	WO Completed	Bus
613451	Caterpillar 12M	Inspeccion IIASa	INSPECCION IIASA	24/06/2021		Corrective Order	WO Completed	Grader
613452	Caterpillar 416E	inspeccion iiasa	INSPECCION IIASA	24/06/2021		Corrective Order	WO Completed	Backhoe
613453	Gmc Boom Truck	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	24/06/2021		Corrective Order	WO Completed	Boom truck
613455	Intraax 53121 Hendrickso	INSPECCION GENERAL	INSPECCION GENERAL	24/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
613469	Coaster	Cambio de llantas	CAMBIO DE LLANTAS	24/06/2021		Corrective Order	WO Completed	Bus
613470	Coaster	Cambio de llantas	CAMBIO DE LLANTA	24/06/2021		Corrective Order	WO Completed	Bus
613471	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/06/2021		Corrective Order	WO Completed	Pickup truck
613472	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/06/2021		Corrective Order	WO Completed	Pickup truck
613475	Landcruiser DC	Cambio de llantas	CAMBIO DE LLANTAS	24/06/2021		Corrective Order	WO Completed	Pickup truck
613476	Landcruiser DC	Cambio de 2 llanta	CAMBIO DE 2 LLANTA	24/06/2021		Corrective Order	WO Completed	Pickup truck
613477	Caterpillar 416E	Fuga por joke de trasmision	FUGA POR JOKE DE TRASMISION	24/06/2021		Corrective Order	WO Completed	Backhoe
613480	Landcruiser TC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	24/06/2021		Corrective Order	WO Completed	Pickup truck
613481	WT015 H7 CISTERNA SINOTRUK	Cambio de 3 llantas	CAMBIO DE 3 LLANTAS	24/06/2021		Corrective Order	WO Completed	Water truck
614311	Caterpillar 226b Skid Steer L	PASADORES DEL VALDE DAÑADO	PASADORES DEL VALDE DAÑADO	25/06/2021		Corrective Order	WO Completed	Skid Steer
614321	Freightliner CI 120	Instalacion de gps	INSTALACION DE GPS	25/06/2021		Corrective Order	WO Completed	Mule truck
614323	Grove RT650E 45TON	Falla por baja presion de comb	FALLA POR BAJA PRESION DE COMB	25/06/2021		Corrective Order	WO Completed	Crane/Hoist
614325	DOOSAN 1005	EMERGENCY CALL	CAPACITOR REPLACE	25/06/2021 19363 hrs		Corrective Order	WO Completed	Light Tower
614326	DOOSAN 1005	EMERGENCY CALL	LAMP REPLACE	25/06/2021 27956 HRS		Corrective Order	WO Completed	Light Tower
614327	SDMO J60U 60KVA	EMERGENCY CALL	FUEL PUMP AJUSTMENT	25/06/2021 18847 HRS		Corrective Order	WO Completed	Generator
614330	Intraax 53121 Hendrickso	INSPECCION GENERAL	INSPECCION MECANICA	25/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
614352	Freightliner 8170ME Water Truc	cambio de 10 llantas	4 LLANTAS FLAT Y 6 EN MAL ESTADO	25/06/2021		Corrective Order	WO Completed	Water truck
614375	Gallegos Flatbed Trailer	CAMBIO DE 4 LLANTAS	LLANTAS EN MAL ESTADO	25/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
614380	Terex RT5551 55TON	cambio de sensor	SENSOR CAUSA FALLE EN COMUN REAL	25/06/2021		Corrective Order	WO Completed	Crane/Hoist
614408	Hilux DC	CAMBIO CILINDROS	MANTENIMIENTO CORRECTIVO	25/06/2021 59,849		Corrective Order	WO Completed	Pickup truck
614410	Hilux DC	CAMBIO CILINDROS	MANTENIMIENTO CORRECTIVO	25/06/2021 78,473		Corrective Order	WO Completed	Pickup truck
614413	Hilux DC	REPARACION CHOQUE	MANTENIMIENTO CORRECTIVO	25/06/2021 494		Corrective Order	WO Completed	Pickup truck
614417	Hilux DC	CAMBIO CILINDROS	MANTENIMIENTO CORRECTIVO	25/06/2021 59,849		Corrective Order	WO Completed	Pickup truck
614440	Grove RT700E 60TON	ENGRASE DE CABLES	ENGRASE DE CABLE	25/06/2021		Corrective Order	WO Completed	Crane/Hoist
614450	WT015 H7 CISTERNA SINOTRUK	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	25/06/2021		Corrective Order	WO Completed	Water truck
614457	Unimog Service Truck	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	25/06/2021		Corrective Order	WO Completed	Truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
614462	Grove RT600E 50TON	ENGRASE E INSPECCION CABLE	INSPECCIO DE CABLE	25/06/2021		Corrective Order	WO Completed	Crane/Hoist
614471	Caterpillar 740B EJ ADT	C/ SWITCH LIMPIA PARABRISA	DEFECTUOSO	25/06/2021		Corrective Order	WO Completed	Articulated dump truck
614473	Caterpillar 426f2 Backhoe	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	25/06/2021	90012254	Corrective Order	WO Completed	Backhoe
614524	Caterpillar 740B EJ ADT	C/TAPON DRENAJE TANQUE HYD	TAPONES EN MAL ESTADO	25/06/2021		Corrective Order	WO Completed	Articulated dump truck
614534	Caterpillar 740B EJ ADT	C/MANGUERA ENF HYD	MANGUERAS EN MAL ESTADO	25/06/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
614613	GROVE GMK 5170 170TON	Reparacion de lines neumaticas	REPARACION DE LINEAS NEUMATICAS DE FRENOS	25/06/2021		Corrective Order	WO Completed	Crane/Hoist
614640	Landcruiser DC	REVISAR FRENOS SERVICIO/PARQUE	AJUSTE FRENO SERVICIO Y PARQUEO	25/06/2021	16545	Corrective Order	WO Completed	Pickup truck
614642	Landcruiser DC	EVALUAR SISTEMA DIRECCION	REVISAR RUIDO-LLANTA DELANTERA	25/06/2021	16545	Corrective Order	WO Completed	Pickup truck
614661	Hino Serie 300	REPARAR GENERAL	TALLER DOLLAR PENONOME	25/06/2021	50013953	PLANEAMIENTO	Corrective Order	Truck
614672	Broce Broom RJT 350	cambio de bomba hidraulica	FUGA DE ACEITE	25/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
614673	JLG 800 AJ Manlift	correccion de fuga	FUGA HIDRAULICA	25/06/2021		Corrective Order	WO Completed	Manlift
614674	Coaster	cambio de 1 llanta	LLANTA EN MAL ESTADO	25/06/2021		Corrective Order	WO Completed	Bus
614709	Freightliner M2 106 Sucker Tru	EQUIPO PIERDE FUERZA	EQUIPO PIERDE FUERZA	26/06/2021		Corrective Order	WO Completed	Sucker truck
614720	Caterpillar 12M	Aire acondicionado dañado	AIRE ACONDICIONADO DAÑADO	26/06/2021		Corrective Order	WO Completed	Grader
614801	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	26/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
614874	Pramac GSW25P 17KVA	REPARAR GENERADOR AC	FALLA EN RODAMIENTO	26/06/2021	4945 horas	Corrective Order	WO Completed	Generator
614875	New Holland Lm 1745	Verificacion de luces	VERIFICACION DE LUCES	26/06/2021		Corrective Order	WO Completed	Telehender
614877	Faresin FM4000 / 17F Telehandl	Verificacion de luces	VERIFICACION DE LUCES	26/06/2021		Corrective Order	WO Completed	Telehender
614882	PRAMAC GSW460V 460 kVa	CORRECTIVO	LAVADO DE RADIADOR Y MOTOR	26/06/2021	27026 hrs	Corrective Order	WO Completed	Generator
614885	Hyster H70ft 3t Forklift (M)	ruido en llanta trasera	RUIDO EN LLANTA TRASERA	26/06/2021		Corrective Order	WO Completed	Forklift
614988	Caterpillar 336DL	cambio de 1 lampara	LAMPARA DAÑADA	26/06/2021		Corrective Order	WO Completed	Excavator
614991	PRAMAC GSW560V 407 kVa	TOMA MEDIDAS MOTOR	FABRICAR AISLAMIENTO TERMICO	26/06/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
615107	Caterpillar DE165E0 165 kVa	PM CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	14849 hrs	PM Orders	WO Completed	Generator
615108	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	19871 hrs	PM Orders	WO Completed	Generator
615109	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	16052 hrs	PM Orders	WO Completed	Generator
615110	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	12010 hrs	PM Orders	WO Completed	Generator
615111	PRAMAC GSW80P 83 kVa	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	10608 hrs	PM Orders	WO Completed	Generator
615112	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	18741 horas	PM Orders	WO Completed	Generator
615113	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	19032 horas	PM Orders	WO Completed	Generator
615114	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	6941 hrs	PM Orders	WO Completed	Generator
615115	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	35859 hrs	PM Orders	WO Completed	Generator
615117	PRAMAC GSW90P 74 kVa	PM PRA GSW90P MEC 300 HR	PM PRA GSW90P MEC 300 HR	26/06/2021	24513 hrs	PM Orders	WO Completed	Generator
615118	PRAMAC GSW65 48 kVa	PM PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	23329 hrs	PM Orders	WO Completed	Generator
615119	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	23046 hrs	PM Orders	WO Completed	Generator
615120	Pramac GSW25P 17KVA	PM PRA GSW25 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	4838 hrs	PM Orders	WO Completed	Generator
615124	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	26/06/2021	35004 hrs	Corrective Order	WO Completed	Light Tower
615128	GROVE GMK 5170 170TON	cambio de cable telescopico	CABLE TELESCOPICO DAÑADO	26/06/2021	90009564	Corrective Order	WO Completed	Crane/Hoist
615138	Grove RT600E 50TON	Revision de Equipo	REVISION DE EQUIPO	26/06/2021		Corrective Order	WO Completed	Crane/Hoist
615147	WT015 H7 CISTERNA SINOTRUK	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	26/06/2021		Corrective Order	WO Completed	Water truck
615265	Caterpillar 14H Motorgrader	Luces no funcionan	LUCES NO FUNCIONAN	27/06/2021		Corrective Order	WO Completed	Grader
615271	Coaster	Cambio de 6 llantas	CAMBIO DE 6 LLANTAS	27/06/2021		Corrective Order	WO Completed	Bus
615272	Landcruiser TC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	27/06/2021		Corrective Order	WO Completed	Pickup truck
615279	Freightliner 8170ME Water Truc	cambio de correa del motor	CAMBIO DE CORREA DEL MOTOR	27/06/2021		Corrective Order	WO Completed	Water truck
615284	Freightliner Columbia CI112	Cambio de 1 llantta	CAMBIO DE 1 LLANTA	27/06/2021		Corrective Order	WO Completed	Mule truck
615285	Caterpillar 426F2 Backhoe	luces no encienden	LUCES NO ENCIENDEN	27/06/2021		Corrective Order	WO Completed	Backhoe
615288	Caterpillar D8T Dozer	Necesita aceite hidraulico	NECESITA ACEITE HIDRAULICO	27/06/2021		Corrective Order	WO Completed	Dozer
615290	Coaster	CAMBIO PLUMILLAS PARABRISAS	DETERIORADOS	27/06/2021	39276	Corrective Order	WO Completed	Bus
615291	Grove RT650E 45TON	Cambio de manguera e refrigera	MANGUERA DE REFRIGERANTE ROTA	27/06/2021		Corrective Order	WO Completed	Crane/Hoist
615292	Coaster	EVALUAR MOTOR	RUIDO EN EL MOTOR	27/06/2021	39276	Corrective Order	WO Completed	Bus
615293	JLG 1250 AJP Manlift	FALLA ACTIVA BLOQUEADO	FALLA ACTIVA BLOQUEADO	27/06/2021		Corrective Order	WO Completed	Manlift
615294	PRAMAC GSW120 120 kVa	EMERGENCY CALL	INSPECTION AND EVALUATION	27/06/2021	NO METER	Corrective Order	WO Completed	Generator
615296	SDMO J60U 60KVA	EMERGENCY CALL	FUEL PUMP AJUSTMENT	27/06/2021	18887 HRS	Corrective Order	WO Completed	Generator
615304	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	27/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
615306	Freightliner CI 120	ABRAZADERA	ABRAZADERA	27/06/2021		Corrective Order	WO Completed	Mule truck
615308	Intraax 53121 Hendrickso	INSPECCIONAR LUCES QUEMADA	LUZ QUEMADA	27/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
615312	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	27/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
615314	Caterpillar 416E	Fuga de coolant	FUGA DE COOLANT	27/06/2021		Corrective Order	WO Completed	Backhoe
615327	Hyster H700 Forklift	PINS AND BUSHING RPLC	CORRECTIVE	27/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Forklift
615331	Freightliner CI 120	FUGA Y CORREAS	FUGA Y CORREAS	27/06/2021		Corrective Order	WO Completed	Mule truck
615333	Hyster H700 Forklift	PINS AND BUSHING RPLC	CORRECTIVE	27/06/2021	AUTO CLOSED	Corrective Order	WO Completed	Forklift
615341	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	27/06/2021		Corrective Order	WO Completed	Mule truck
615387	Gallegos Flatbed Trailer	Cambio de llantas	CAMBIO DE LLANTAS	27/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
615417	PRAMAC GSW120 120 kVa	CAMBIO BATERIA	NO MANTIENE CARGA	27/06/2021	5386 hrs	Corrective Order	WO Completed	Generator
615486	Caterpillar 336DL	INSPECCION HERRAMIENTA CORTE	INSPECCION ESPECIALIZADA IASA	27/06/2021		Corrective Order	WO Completed	Excavator
615567	PRAMAC GSW45P 48 kVa	PM OLY GEP 88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	27/06/2021	8803 horqs	PM Orders	WO Completed	Generator
615572	Hyster H700 Forklift	maquinado de bushin	MAQUINADO DE BUSHIN	27/06/2021		Corrective Order	WO Completed	Forklift
615591	Freightliner Columbia CI112	Rep de llanta y cambio de espa	LLANTA FLAT Y ESPARRAGO EN MAL ESTADO	27/06/2021		Corrective Order	WO Completed	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
615592	Mercedes Tipper Truck	LEVANTAMIENTO DE INFORMACION	INSPECCION	27/06/2021		Corrective Order	WO Completed	Tipper
615593	Gallegos Flatbed Trailer	Cambio de 3 llantas	LLANTAS EN MAL ESTADO	27/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
615596	Freightliner Columbia CI112	BRAZO FLOJO / GUARDAFANGO	BRAZO FLOJO / GUARDAFANGO	27/06/2021		Corrective Order	WO Completed	Mule truck
615600	Hyster H70ft 3t Forklift (M)	revision de equipo	REVISION DE EQUIPO	27/06/2021		Corrective Order	WO Completed	Forklift
615631	Hyster H700 Forklift	Mangueras de engrase rotas	MANGUERAS DE ENGRASE ROTAS	27/06/2021		Corrective Order	WO Completed	Forklift
615777	Grove GMK 4080 80TON	Cambio de maguera hidraulica	CAMBIO DE MAGUERA HIDRAULICA	28/06/2021		Corrective Order	WO Completed	Crane/Hoist
615804	CAT 930K	Cambio de componentes	CAMBIO DE COMPONENTES	28/06/2021		Corrective Order	WO Completed	Loader
615828	Landcruiser DC	reponer aceite de frenos	REPONER ACEITE DE FRENOS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615829	Hilux DC	reponer aceitte de frenos	REPONER ACEITE DE FRENOS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615837	New Holland Lm 1745	reparar cinturon de seguridad	REPARAR CINTURON DE SEGURIDAD	28/06/2021		Corrective Order	WO Completed	Telehender
615838	Faresin FM4000 / 17F Telehandl	Reparar aire acondicionado	REPARAR AIRE ACONDICIONADO	28/06/2021		Corrective Order	WO Completed	Telehender
615839	New Holland Lm 1745	Cerradura de puerta dañada	CERRADURA DE PUERTA DAÑADA	28/06/2021		Corrective Order	WO Completed	Telehender
615841	Caterpillar 426F2 Backhoe	EVALUA CAMBIO DE TAPA BATERIA	INSPECCION IASA	28/06/2021		Corrective Order	WO Completed	Backhoe
615842	New Holland Lm 1745	Reparar aire acondicionado	REPARAR AIRE ACONDICIONADO	28/06/2021		Corrective Order	WO Completed	Telehender
615851	Caterpillar 226b Skid Steer L	PINES DEL BALDE DAÑADO	PINES DEL BALDE DAÑADO	28/06/2021		Corrective Order	WO Completed	Skid Steer
615854	Caterpillar 307E Miniexcavator	Engrase y tensado de cadena	ENGRASE Y TENSADO DE CADENA	28/06/2021		Corrective Order	WO Completed	Excavator
615855	New Holland Lm 1745	Reparacion de luces	REPARACION DE LUCES	28/06/2021		Corrective Order	WO Completed	Telehender
615856	Hino Series 300	cAMBIO DE 1 LLANTA	CAMBIO DE 1 LLANTA	28/06/2021		Corrective Order	WO Completed	Truck
615858	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	28/06/2021		Corrective Order	WO Completed	Bus
615859	Freightliner M2 106 Sucker Tru	Cambio de manija de puerta	CAMBIO DE MANIJA DE PUERTA	28/06/2021		Corrective Order	WO Completed	Sucker truck
615860	Hyster H70ft 3t Forklift (M)	Reparacion de 2 llantas	REPARACION DE 2 LLANTAS	28/06/2021		Corrective Order	WO Completed	Forklift
615861	Caterpillar 14H Motorgrader	Necesita reemplazo de hoja	NECESITA REEMPLAZO DE HOJA	28/06/2021		Corrective Order	WO Completed	Grader
615915	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 3 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615917	PRAMAC GSW120 120 kVa	CORRECTIVO	RECONEXION DE GENERADOR	28/06/2021	5386 hrs	Corrective Order	WO Completed	Generator
615919	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 3 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615926	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 3 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615928	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 4 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615931	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 1 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615935	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 2 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615937	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 2 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615965	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	28/06/2021		Corrective Order	WO Completed	Pickup truck
615989	Caterpillar 740B EJ ADT	C/ DE BOMBILLO LUCES TRABAJO	QUEMADAS	28/06/2021		Corrective Order	WO Completed	Articulated dump truck
616009	Gallegos Flatbed Trailer	Cambio de manguera de feenos	CAMBIO DE MANGUERAS	28/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
616015	Mobile equipment	CONSUMIBLE KALTIRE MAYO	CONSUMIBLE KALTIRE MAYO	28/06/2021		Corrective Order	WO Completed	Area
616082	Broce Broom RJT 350	cambio de llavin	LLAVIN EN MAL ESTADO	28/06/2021		Corrective Order	WO Completed	Scrubber / Sweeper
616114	Mobile equipment	FABRICACION MANGUERAS	CENMAN MAYO	28/06/2021		Corrective Order	WO Completed	Area
616137	Caterpillar D8T Dozer	Aire acondicionado	AIRE ACONDICIONADO	28/06/2021		Corrective Order	WO Completed	Dozer
616139	Caterpillar D8T Dozer	Cadena del lado derecho	CADENA DEL LADO DERECHO	28/06/2021		Corrective Order	WO Completed	Dozer
616168	PRAMAC GSW80P 83 kVa	CORRECTIVO	DESCONECCION DE GENERADOR	28/06/2021	13681 hrs	Corrective Order	WO Completed	Generator
616170	Freightliner CI 120	cambio de baterias	CAMBIO DE BATERIAS	28/06/2021		Corrective Order	WO Completed	Mule truck
616173	Landcruiser DC	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	28/06/2021	CIERRE MASIVO - REVISADO JIGSA	PM Orders	WO Completed	Pickup truck
616175	Landcruiser DC	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	28/06/2021	CIERRE MASIVO - REVISADO JIGSA	PM Orders	WO Completed	Pickup truck
616176	Landcruiser DC	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	28/06/2021	CIERRE MASIVO - REVISADO JIGSA	PM Orders	WO Completed	Pickup truck
616184	JLG 1250 AJP Manlift	Revision de equipo	REEMPLAZO DE FILTROS	28/06/2021		Corrective Order	WO Completed	Manlift
616205	International 7400 SBA Fire Tr	cambio de valvula de aire de c	VALVULA DE AIRE DE BOLSA DE CABINA CON FUGA	28/06/2021		Corrective Order	WO Completed	Fire truck
616231	Manitou Mht-X1490 9t Telehand	Cambio de pernos, abrazaderas	CAMBIO DE PERNOS , ABRAZADERAS	28/06/2021	90014592 60023126	Corrective Order	WO Completed	Telehender
616240	Landcruiser DC	cambio de 4 llantas	LLANTAS FLAT	28/06/2021		Corrective Order	WO Completed	Pickup truck
616258	PRAMAC GSW110P 82 kVa	CORRECTIVO	CAMBIO DE BOMBA DE AGUA	28/06/2021	12632 hrs	Corrective Order	WO Completed	Generator
616261	CAT 930K	cambio de hojas de corte	CAMBIO DE HOJAS DE CORTE	28/06/2021		Corrective Order	WO Completed	Loader
616274	WT013 H7 CISTERNA SINOTRUK	cambio trabado	NO LE ENTRAN LOS CAMBIOS	28/06/2021		Corrective Order	WO Completed	Water truck
616278	Manitou Mht-X1490 9t Telehand	reparacion de cinturon del op	REPARACION DE CINTURON DEL OPERADOR	28/06/2021		Corrective Order	WO Completed	Telehender
616286	Freightliner Columbia CI112	Cambio de tuercas del terminal	CAMBIO DE TUERCAS DEL TERMINAL DE DIRECCION	28/06/2021		Corrective Order	WO Completed	Mule truck
616290	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	EQUIPO SIN COMBUSTIBLE Y BAJO NIVEL DE COOLANT	28/06/2021	24290 hrs	Corrective Order	WO Completed	Generator
616303	Manitou MTH-X 10120	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	28/06/2021	50014267	Corrective Order	WO Completed	Telehender
616306	Mobile equipment	CONSUMIBLES TALLER GENSET	PEDIDO JULIO	28/06/2021		Corrective Order	WO Completed	Area
616307	Coaster	cambio de llanta	LLANTA EN MAL ESTADO	28/06/2021		Corrective Order	WO Completed	Bus
616308	Gallegos Lime Tank	reparacion de 1 llanta	LLANTA FLAT	28/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
616309	Freightliner Columbia CI112	cambio de 1 llanta	LLANTA FLAT	28/06/2021		Corrective Order	WO Completed	Mule truck
616310	Freightliner Columbia CI112	reparacion de 4 llantas	LLANTAS FLAT	28/06/2021		Corrective Order	WO Completed	Mule truck
616313	John Deere 9370R Tractor	reparacion de compactor	REPARACION DE COMPACTOR	28/06/2021		Corrective Order	WO Completed	Tractor
616316	Unimog Service Truck	Cambio de luces	CAMBIO DE LUCES	28/06/2021		Corrective Order	WO Completed	Truck
616564	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	29/06/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
616657	Caterpillar 307E Miniexcavator	Cambio de filtros	CAMBIO DE FILTROS	29/06/2021		Corrective Order	WO Completed	Excavator
616662	Freightliner 8170ME Water Truc	Cambio de bomba de agua	BOMBA DE AGUA DE MOTOR DEFECTUOSA	29/06/2021	autoclosed	Corrective Order	WO Completed	Water truck
616665	Caterpillar 140K	Aire Acondicionado	AIRE ACONDICIONADO	29/06/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
616667	Caterpillar 140K	No tiene las cuñas de la hoja	NO TIENE LAS CUÑAS DE LA HOJA		29/06/2021		Corrective Order	WO Completed	Grader
616669	Caterpillar 140K	Caja de la batería y los estri	CAJA DE LA BATERÍA Y LOS ESTRÍ		29/06/2021		Corrective Order	WO Completed	Grader
616696	Hilux DC	INSTALAR BOLA TIRO/CARGA	REQUERIMIENTO NUEVO		29/06/2021		Corrective Order	WO Completed	Pickup truck
616711	Mobile equipment	ACEITE 15W40 GENSET - JULIO	CONSUMO JULIO		29/06/2021		Corrective Order	WO Completed	Area
616717	Gallegos Flatbed Trailer	LLANTA Mal ESTADO	LLANTA MAL ESTADO		29/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
616718	Gallegos Flatbed Trailer	LUCES	LUCES		29/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
616754	John Deere 9370R Tractor	Cambio de Amortiguadores	CAMBIO DE AMORTIGUADORES DE LA DINBAMICA		29/06/2021		Corrective Order	WO Completed	Tractor
616921	WT013 H7 CISTERNA SINOTRUK	Problema de la Transmision	PROBLEMA DE LA TRANSMISION		29/06/2021	90009736 90009779	Corrective Order	WO Completed	Water truck
616937	Kalmar	CAMBIO DE 6 LLANTAS	CORRECTIVO		29/06/2021	50014270 50015084 50015085	Corrective Order	WO Completed	Telehender
616994	JLG 800 AJ Manlift	FALLAS ACTIVAS	FALLAS ACTIVAS		29/06/2021		Corrective Order	WO Completed	Manlift
616996	Unimog Service Truck	instalacion de alarma backup	SIN ALARMA DE REVERSA		29/06/2021		Corrective Order	WO Completed	Truck
617005	Grove GMK 4080 80TON	CAMBIO FILTRO DE DIESEL	FILTRO DE DIESEL SELLO DAÑADO		29/06/2021		Corrective Order	WO Completed	Crane/Hoist
617188	Coaster	cambio de 6 llantas	LLANTAS EN MAL ESTADO		30/06/2021		Corrective Order	WO Completed	Bus
617196	Freightliner 8170ME Water Truc	cambio de tornillos	GUARDAFANGO SUELTO		30/06/2021		Corrective Order	WO Completed	Water truck
617203	Cargador 966H Wheel Loader	FRONT BUCKET REPAIR (CIGSA)	CORRECTIVE		30/06/2021		Corrective Order	WO Completed	Loader
617206	Caterpillar 226b Skid Steer L	Revision de equipo	ENGRASE GENERAL DE EQUIPO		30/06/2021		Corrective Order	WO Completed	Skid Steer
617210	Gallegos Flatbed Trailer	reparacion de 1 llanta	LLANTA FLAT		30/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
617214	Caterpillar 740b Ej	Reparacion de cilindro de cili	REPARACION DE CILINDRODE DIRECCION		30/06/2021		Corrective Order	WO Completed	Articulated dump truck
617316	Freightliner Columbia Cl112	Cambio de tercer brazo de dire	CAMBIO DE TERCER BRAZO DE DIRECCION		30/06/2021	90009960	Corrective Order	WO Completed	Mule truck
617450	Manitou Mht-X1490 9t Telehand	FOCO DE CIRCULINA QUEMADA	FOCO DE CIRCULINA QUEMADA		30/06/2021		Corrective Order	WO Completed	Telehender
617453	Manitou Mht-X1490 9t Telehand	LUCES & CONDUCTO DE AIRE	LUCES & CONDUCTO DE AIRE		30/06/2021		Corrective Order	WO Completed	Telehender
617454	Freightliner Cl 120	reparacion de fuga coolant	REPARACION FUGA DE COOLANT		30/06/2021		Corrective Order	WO Completed	Mule truck
617460	Freightliner Columbia Cl112	Reparar bases de los amortigua	REPARAR BASE DE AMORTIGUADOR		30/06/2021		Corrective Order	WO Completed	Mule truck
617479	JLG 1250 AJP Manlift	Bloqueado, no realiza movimien	BLOQUEADO, NO REALIZA MOVIMIENTO		30/06/2021		Corrective Order	WO Completed	Manlift
617531	JLG 450 AJ Manlift	REPARACION CILINDROS (TSI)	CORRECTIVO		30/06/2021	50014176	Corrective Order	WO Completed	Manlift
617533	Freightliner Columbia Cl112	TRANSMISSION REPAIR (AUTOSTAR)	ENVIO A AUTOSTAR		30/06/2021	50014205 50014450	Corrective Order	WO Completed	Mule truck
617537	Coaster	Reemplazo de 2 llantas	REEMPLAZO DE 2 LLANTAS		30/06/2021		Corrective Order	WO Completed	Bus
617538	Gallegos Flatbed Trailer	Reemplazo de llantas	REEMPLAZO DE LLANTAS		30/06/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
617544	Grove RT650E 45TON	Pin del seguro de Giro	PIN DEL SEGURO DE GIRO DOBLADO		30/06/2021		Corrective Order	WO Completed	Crane/Hoist
617545	Caterpillar 236d Skid Steer L	CAMBIO HERRAMIENTA DESGASTE	CAMBIO DE COMPONENTES DESGASTE		30/06/2021		Corrective Order	WO Completed	Skid Steer
617547	Grove GMK 4080 80TON	Funcion de Telescopio del Boom	PROBLEMAS CON LA FUNCION DE TELESCOPIO		30/06/2021		Corrective Order	WO Completed	Crane/Hoist
617548	Freightliner M2 106 Sucker Tru	Reemplazo de filtro de aire	REEMPLAZO DE FILTRO DE AIRE		30/06/2021		Corrective Order	WO Completed	Sucker truck
617549	Caterpillar 14M Motorgrader	Baja presion de transmision	BAJA PRESION DE TRANSMISION		30/06/2021		Corrective Order	WO Completed	Grader
617550	Freightliner M112 Truck Tip	relleno de power steering	RELLENO DE CAEITE DE DIRECCION		30/06/2021		Corrective Order	WO Completed	Tipper
617551	Caterpillar CS533E Compactor	Relleno de aceite hidraulico	RELLENO DE ACEITE HIDRAULICO		30/06/2021		Corrective Order	WO Completed	Compactor
617572	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617573	Hilux DC	cambio de 3 llantas	LLANTAS EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617574	Hilux DC	Cambio de 1 llanta	LLANTA EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617575	Landcruiser DC	cambio de 5 llantas y 4 rines	LLANTA EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617576	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617610	Landcruiser TC	cambio de 2 llantas	LLANTAS EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617611	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617612	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL		01/07/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
617673	Hyster H700 Forklift	Engrase de Equipo	ENGRASE DE EQUIPO		01/07/2021		Corrective Order	WO Completed	Forklift
617679	Caterpillar 236d Skid Steer L	Cambio de luces	LUCES EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Skid Steer
617680	Hyster H700 Forklift	Revision de Equipo	REVISIONB DE EQUIPO		01/07/2021		Corrective Order	WO Completed	Forklift
617714	Broce Broom RJT 350	Fuga de aceite hidráulico y de	FUGA DE ACEITE HIDRÁULICO Y DE		01/07/2021		Corrective Order	WO Completed	Scrubber / Sweeper
617774	Landcruiser TC	CAMBIAR PARABRISA	PARA BRISA EN MAL ESTADO		01/07/2021		Corrective Order	WO Completed	Pickup truck
617806	Caterpillar 740b Ej	C/ PIN DE CYL DE DIRECCION	DESGASTE		01/07/2021		Corrective Order	WO Completed	Articulated dump truck
617869	Freightliner M2 106 Sucker Tru	CAMBIO 1 NEUMATICO	CORRECTIVO		01/07/2021		Corrective Order	WO Completed	Sucker truck
617899	Freightliner M2 106 Sucker Tru	Carga de A/A y cambio de rueda	CARGA DE A/A Y CAMBIO DE RUEDA		01/07/2021		Corrective Order	WO Completed	Sucker truck
617942	Caterpillar 740b Ej	C/MANG HYD PILOTO DE FRENO	FUGA/RECALENTADAS		01/07/2021		Corrective Order	WO Completed	Articulated dump truck
617980	Caterpillar 12M	Presión de aceite hidráulico y	PRESIÓN DE ACEITE HIDRÁULICO Y		01/07/2021		Corrective Order	WO Completed	Grader
617983	CAT 930K	Cruceta desajustada y sin bali	CRUCETA DESAJUSTADA Y SIN BALI		01/07/2021	90010341	Corrective Order	WO Completed	Loader
617985	Gallegos Flatbed Trailer	Ajuste dee frenos, engrase	AJUSTE DE FRENOS, ENGRASE		01/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
617987	Freightliner Columbia Cl112	fuga de aceite motor	FUGA DE ACEITE DE MOTOR		01/07/2021		Corrective Order	WO Completed	Mule truck
617989	Manitou Mht-X1490 9t Telehand	Reparar fuga aceite	REPARACION DE FUGA DE ACEITE HIDRAULICO		01/07/2021		Corrective Order	WO Completed	Telehender
617998	Mobile equipment	REFRIGERANTE	CONSUMIBLE		01/07/2021		Corrective Order	WO Completed	Area
618000	Landcruiser DC	CAMBIO TACO/CALIPER/BOMBILLO	CAMBIO FELCHA/EJES/RETENEDORAS		01/07/2021	58836	Corrective Order	WO Completed	Pickup truck
618006	Landcruiser DC	CAMBIO RETENEDORA DIFERENCIAL	CAMBIO MUELLE/BASE AMORTIGUADORES		01/07/2021	49,739	Corrective Order	WO Completed	Pickup truck
618008	Landcruiser DC	CAMBIO DIFERENCIAL	CAMBIO AMORTIGUADORES		01/07/2021	63,404	Corrective Order	WO Completed	Pickup truck
618009	Landcruiser DC	CAMBIO FLECHAS	REPARACION ABS		01/07/2021	63,404	Corrective Order	WO Completed	Pickup truck
618010	Landcruiser DC	CAMBIO KIT EMBRAGUE	CAMBIO RETENEDORA DIFERENCIAL		01/07/2021	63,483	Corrective Order	WO Completed	Pickup truck
618017	Landcruiser DC	CAMBIO DIFERENCIAL	CAMBIO TAMBORES DE FRENO		01/07/2021	53,281	Corrective Order	WO Completed	Pickup truck
618019	Landcruiser DC	CAMBIO FLECHA/EJE/SPINDLE	CAMBIO CALIPER/BANDAS		01/07/2021	53,281	Corrective Order	WO Completed	Pickup truck
618020	Landcruiser DC	CAMBIO SENSOR ABS	TABLERO MARCA		01/07/2021	53,281	Corrective Order	WO Completed	Pickup truck
618023	Hilux DC	CAMBIO BALINERA DIFERENCIAL	CAMBI RETENEDORA/CABLE FRENO		01/07/2021	42,315	Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
618024	Hilux DC	CAMBIO HOJA MUELLE	MANTENIMIENTO CORRECTIVO	01/07/2021	42,539	Corrective Order	WO Completed	Pickup truck
618026	Hilux DC	CAMBIO KIT EMBRAGUE	MANTENIMIENTO CORRECTIVO	01/07/2021	27,830	Corrective Order	WO Completed	Pickup truck
618029	Landcruiser TC	CAMBIO BATERIA/ALARMA RETROCES	CAMBIO BUSHING BARRA ESTABILIZADORA	01/07/2021	28,914	Corrective Order	WO Completed	Pickup truck
618031	Landcruiser DC	CAMBIO BANDAS/TAMBORES	CAMBIO RETENEADORA JOCK TRASNFER	01/07/2021	43,354	Corrective Order	WO Completed	Pickup truck
618033	Hilux DC	CAMBIO TERMINALES DIRECCION	CAUCHO BARRA ESTABILIZADORA	01/07/2021	63,285	Corrective Order	WO Completed	Pickup truck
618035	Hilux DC	CAMBIO CREMALLERA	SANGRADO POWERSTERING	01/07/2021	69,280	Corrective Order	WO Completed	Pickup truck
618036	Hilux DC	CAMBIO MUELLES	CAMBIO PERNO Y TUERCA	01/07/2021	48,045	Corrective Order	WO Completed	Pickup truck
618041	Hilux DC	CAMBIO MUELLE	PRIMER CAMBIO MUELLES	01/07/2021	52,416	Corrective Order	WO Completed	Pickup truck
618042	Hilux DC	CAMBIO MUELLE/CRUCETAS	CAMBIO TERMINALES INTERNOS	01/07/2021	56,518	Corrective Order	WO Completed	Pickup truck
618043	Hilux DC	CAMBIO BUSHING BARRA ESTABILIZ	CAMBIO AMORTIGUADOR DELANTERO	01/07/2021	67,652	Corrective Order	WO Completed	Pickup truck
618052	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/07/2021		Corrective Order	WO Completed	Bus
618054	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE 3 LLANTAS	01/07/2021		Corrective Order	WO Completed	Pickup truck
618055	Hilux DC	Reemplazo de llantas	REEMPLAZO DE 2 LLANTAS	01/07/2021		Corrective Order	WO Completed	Pickup truck
618066	JLG 1250 AJP Manlift	Problema con los movimeintos	PROBLEMA CON LOS MOVIMIENTOS	01/07/2021		Corrective Order	WO Completed	Manlift
618067	Freightliner M2 106 Sucker Tru	Carga de gas refrigerante	CARGA DE GAS REFRIGERANTE	01/07/2021		Corrective Order	WO Completed	Sucker truck
618074	Caterpillar D8T Dozer	Reemplazo de tapon de aceite	REEMPLAZO DE TAPON DE ACEITE	01/07/2021		Corrective Order	WO Completed	Dozer
618271	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	02/07/2021		Corrective Order	WO Completed	Pickup truck
618295	Hilux DC	EVALUAR MOTOR	REVISIÓN CAMBIO DE MOTOR/OTHR	02/07/2021	39954	Corrective Order	WO Completed	Pickup truck
618296	SDMO J30U 38KVA	LLAMADA DE EMERGENCIA	AJUSTE DE RPM Y GRECUENCIA BOMBA DE INYECCION	02/07/2021	6800 hrs	Corrective Order	WO Completed	Generator
618297	Caterpillar 320DL	engrase de Equipo	ENGRASE DE EQUIPO	02/07/2021	20,911.70 hrs	Corrective Order	WO Completed	Excavator
618301	Freightliner Cl 120	revision de presiones	BAJA PRESION DE ACEITE	02/07/2021		Corrective Order	WO Completed	Mule truck
618304	Manitou Mht-X860 6t Telehand	revision de fuga	FUGA DE ACEITE DE MOTOR	02/07/2021		Corrective Order	WO Completed	Telehender
618308	Caterpillar 416E	Luces traseras no funcionan	LUCES TRASERAS NO FUNCIONAN	02/07/2021		Corrective Order	WO Completed	Backhoe
618311	Caterpillar 416E	Se neutraliza	SE NEUTRALIZA	02/07/2021		Corrective Order	WO Completed	Backhoe
618316	Hilux DC	CAMBIO COMPRESOR	RECARGA GAS A/C	02/07/2021	81,186	Corrective Order	WO Completed	Pickup truck
618318	Coaster	Cambio de llantas delanteras	CAMBIO DE LLANTAS DELANTERAS	02/07/2021		Corrective Order	WO Completed	Bus
618320	Landcruiser TC	CAMBIO AJUSTADORES/BUJES BARRA	CAMBIO TACOS/BANDAS FRENO	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
618321	Landcruiser DC	CAMBIO PERTIGA	NO FUNCIONA	02/07/2021	46,646	Corrective Order	WO Completed	Pickup truck
618322	Hilux DC	CAMBIO TACOS/CRUCETAS	REVISION AJUSTE BANDAS	02/07/2021	31,364	Corrective Order	WO Completed	Pickup truck
618323	Hilux DC	CAMBIO CRUCETAS	INSPECCION DE LUCES/DIRECCION/SUSPENSION	02/07/2021	34005	Corrective Order	WO Completed	Pickup truck
618327	Hilux DC	CAMBIO ALTERNADOR/CORREA	CAMBIO TERMINALES INTERNOS/BUJE BARRA	02/07/2021	58,072	Corrective Order	WO Completed	Pickup truck
618329	Hilux DC	CAMBIO TACOS/FRENO/TAMBORES	CAMBIO BALINERA RUEDA/CRUCETA/CREMALLERA	02/07/2021	51,715	Corrective Order	WO Completed	Pickup truck
618330	Hilux DC	CAMBIO RETENEDORA DIFERENCIAL/	CAMBIO PUNTA FLECHA	02/07/2021	44,638	Corrective Order	WO Completed	Pickup truck
618333	Hilux DC	CAMBIO CREMALLERA/ACTUADOR	CAMBIO TERMINALES EXTERNOS	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
618338	Landcruiser TC	CAMBIO AMORTIGUADOR DIRECCION	CAMBIO TERMINAL DIRECCION	02/07/2021	36,229	Corrective Order	WO Completed	Pickup truck
618349	Hilux DC	CAMBIO BANDA/TERMINALES	CAMBIO LAMPARA TRASERA	02/07/2021	49,245	Corrective Order	WO Completed	Pickup truck
618350	Landcruiser TC	REAPRAR CAJA TIMON	MANTENIMIENTO CORRECTIVO	02/07/2021	36,928	Corrective Order	WO Completed	Pickup truck
618353	Landcruiser TC	CAMBIO BANDA/BASE/AMORTIGUADOR	CAMBIO AJUSTADORES/ZAPATAS/COCOBOLA	02/07/2021	23,437	Corrective Order	WO Completed	Pickup truck
618354	Landcruiser TC	CAMBIO BANDAS/TACOSCRUCETAS	CAMBIO BATERIA	02/07/2021	54,116	Corrective Order	WO Completed	Pickup truck
618358	Landcruiser TC	CAMBIO FLECHA/BALINERA/AMORTIG	CAMBIO BANDAS/TAMBORES	02/07/2021	57,469	Corrective Order	WO Completed	Pickup truck
618365	Caterpillar 740B	cambio de filtro secante	CAMBIO DE FILTRO SECANTE	02/07/2021		Corrective Order	WO Completed	Articulated dump truck
618368	Manitou Mht-X860 6t Telehand	Fuga por enfriador motor	FUGA POR ENFRIADOR MOTOR	02/07/2021		Corrective Order	WO Completed	Telehender
618372	Landcruiser DC	CAMBIO KIT EMBRAGUE	CAMBIO JOCK DIFERENCIAL/RETENEDORA	02/07/2021	77,420	Corrective Order	WO Completed	Pickup truck
618373	Hilux DC	CAMBIO TRANSMISION	MANTENIMIENTO CORRECTIVO	02/07/2021	49,084	Corrective Order	WO Completed	Pickup truck
618377	Landcruiser DC	CAMBIO BALINERA/RETENEDORA	CAMBIO BANDAS/BUSHING/TERMINALES	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
618379	Landcruiser DC	CAMBIO CALIPER/TACOS	CAMBIO RETENEDORA DIFERENCIAL	02/07/2021	21,450	Corrective Order	WO Completed	Pickup truck
618381	Coaster	CAMBIO SPRNG BANDAS	MANTENIMIENTO CORRECTIVO	02/07/2021	25,001	Corrective Order	WO Completed	Bus
618432	Freightliner Cl 120	Cambio de llantas	CAMBIO DE LLANTAS	02/07/2021		Corrective Order	WO Completed	Mule truck
618438	Mobile equipment	Key for CAT equipment	KEY FOR CAT EQUIPMENT	02/07/2021		Corrective Order	WO Completed	Area
618439	Freightliner Cl 120	Cambio de llantas	CAMBIO DE LLANTAS	02/07/2021		Corrective Order	WO Completed	Mule truck
618441	Freightliner Cl 120	Cambio de llantas	CAMBIO DE LLANTAS	02/07/2021		Corrective Order	WO Completed	Mule truck
618479	Toyota Hilux	CAMBIO BATERIA	MANTENIMIENTO CORRECTIVO	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
618480	Hino Serie 300 Box Truck	CAMBIO ESCOBILLAS	AJUSTE BANDAS DELANTERA/TRASERA	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Truck
618483	Hino Dutro 300	CAMBIO BATERIA	SE CAMBIARON 02	02/07/2021	CREADA PLANEAMIENTO	Corrective Order	WO Completed	Truck
618504	Caterpillar C9 250 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	02/07/2021	18799 HORAS	Corrective Order	WO Completed	Generator
618618	Caterpillar 12M	REPLAZO DE BEARING	DESGASTE EXCESIVO	02/07/2021		Corrective Order	WO Completed	Grader
618688	Tennant S30 Sweeper	FUGA DE COOLANT	FUGA DE COOLANT	02/07/2021		Corrective Order	WO Completed	Scrubber / Sweeper
618748	Ford F550	Instalacion de lamparas	NSTALACION DE LAMPARAS	02/07/2021		Corrective Order	WO Completed	Pickup truck
618760	JLG 450 AJ Manlift	Cambio de baterias	CAMBIO DE BATERIAS	02/07/2021		Corrective Order	WO Completed	Manlift
618763	Gallegos Flatbed Trailer	Engrase de carroceria	ENGRASE DE CARROCERIA	02/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
618797	Bomag BW24RH	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/07/2021	90006029	Corrective Order	WO Completed	Roller PTR
618805	Freightliner M2 106 Sucker Tru	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/07/2021		Corrective Order	WO Completed	Sucker truck
618807	Broce Broom RJT 350	REPARACION MAYOR (RESANSIL)	ENVIO A RESANSIL PANAMA	02/07/2021	50014208	Corrective Order	WO Completed	Scrubber / Sweeper
618809	JLG 800 AJ Manlift	Problema de desplazamiento	PROBLEMA DE DESPLAZAMIENTO Y SENSOR DE RANGO	02/07/2021		Corrective Order	WO Completed	Manlift
618810	Caterpillar D8T Dozer	Fuga de Aceite hid, diesel	FUGA DE ACEITE HIDRÁULICO, DIESEL Y A/A	02/07/2021		Corrective Order	WO Completed	Dozer

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
618812	Freightliner M2 106 Hydroseedi	CAMBIO DE CADENA	CAMBIO DE CADENA	02/07/2021		Corrective Order	WO Completed	Truck
618816	Landcruiser DC	cambio de 4 llanta	LLANTAS EN MAL ESTADO	02/07/2021		Corrective Order	WO Completed	Pickup truck
618817	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	02/07/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
618823	LT128 D1005 DOOSAN	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTROS	02/07/2021	14342 hrs	Corrective Order	WO Completed	Light Tower
618828	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR FALTA DE COMBUSTIBLE	03/07/2021	27046 hrs	Corrective Order	WO Completed	Generator
618829	PRAMAC GSW30Y 24 kVa	CORRECTIVO	CAMBIO DE CORREA DE MOTOR REVENTADA Y CARGA DE BATERIA	03/07/2021	20639 hrs	Corrective Order	WO Completed	Generator
618932	Grove RT600E 50TON	Cambio de sellos y retenedora	FUGA DE ACEITE POR EL WINCHE	03/07/2021		Corrective Order	WO Completed	Crane/Hoist
619041	Gallegos Flatbed Trailer	Reparacion de cableado	LUCES NO ENCIENDEN	03/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
619042	Hyster H300 13t Forklift (M)	Equipo bloqueado	EQUIPO BLOQUEADO	03/07/2021		Corrective Order	WO Completed	Forklift
619049	Gallegos Flatbed Trailer	cambio de llanta	LLANTA DAÑADA	03/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
619050	Caterpillar 226b Skid Steer L	Rep. de luces	LUCES DE FRENO Y DE TRABAJO TRASERAS NO FUNCIONAN	03/07/2021		Corrective Order	WO Completed	Skid Steer
619052	Freightliner 8170ME Water Truc	Perdio presión en los frenos	PERDIO PRESIÓN EN LOS FRENOS	03/07/2021		Corrective Order	WO Completed	Water truck
619059	PRAMAC GSW110P 82 kVa	LAVADO RADIADOR	CORRECTIVO PROGRAMADO	03/07/2021	13988 horas	Corrective Order	WO Completed	Generator
619068	PRAMAC GSW30Y 24 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE CORREA BATERIA	03/07/2021	20639 HORAS	Corrective Order	WO Completed	Generator
619121	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	6646 HORAS	PM Orders	WO Completed	Generator
619122	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	10910 horas	PM Orders	WO Completed	Generator
619123	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	23930 HRS	PM Orders	WO Completed	Generator
619124	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	16066 HRS	PM Orders	WO Completed	Generator
619125	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	31134 HRS	PM Orders	WO Completed	Generator
619126	Expert Power PN45 10KVA	PRUEBA FUNCIONAL GENERADORES	ARRANQUE E INSPECCION QUINCENAL	03/07/2021	6554 hrs	PM Orders	WO Completed	Generator
619141	Caterpillar DE165E0 165 kVa	PM CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	15246	PM Orders	WO Completed	Generator
619142	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	12883 HRS	PM Orders	WO Completed	Generator
619144	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	13135 horas	PM Orders	WO Completed	Generator
619145	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	28749 hrs	PM Orders	WO Completed	Generator
619148	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	19078 HRS	PM Orders	WO Completed	Generator
619149	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	14253 hrs	PM Orders	WO Completed	Generator
619150	Caterpillar C7.1 200 kVa	PM CAT C7.1 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	16560 hrs	PM Orders	WO Completed	Generator
619151	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	20600 hrs	PM Orders	WO Completed	Generator
619170	Caterpillar 740b Ej	C/ PINES Y BEARING DE TOLVA	DESGASTE	03/07/2021		Corrective Order	WO Completed	Articulated dump truck
619206	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	35337 HORAS	Corrective Order	WO Completed	Light Tower
619207	MAGNUM Light Tower	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	03/07/2021	26409 horas	Corrective Order	WO Completed	Light Tower
619261	Caterpillar 12M	Tapón del mando derecho suelto	TAPÓN DEL MANDO DERECHO SUELTO	03/07/2021		Corrective Order	WO Completed	Grader
619262	Manitou Mht-X1490 9t Telehand	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/07/2021		Corrective Order	WO Completed	Telehender
619327	Hyster H300 Forklift	CAMBIO DE 4 LLANTAS	CAMBIO DE 4 LLANTAS	03/07/2021		Corrective Order	WO Completed	Forklift
619331	Manitou Mht-X1490 9t Telehand	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/07/2021		Corrective Order	WO Completed	Telehender
619360	Hyster E70xn 3t Forklift (E)	equipo bloqueado	EQUIPO BLOQUEADO	03/07/2021		Corrective Order	WO Completed	Forklift
619366	Freightliner 8170ME Water Truc	Tuberia partida del drenajes p	TUBERIA PARTIDA DEL DRENAJES P	03/07/2021		Corrective Order	WO Completed	Water truck
619377	Caterpillar 307E Miniexcavator	CAMBIO DE LINEA DE COMBUSTIBLE	CAMBIO DE LINEA DE COMBUSTIBLE	03/07/2021		Corrective Order	WO Completed	Excavator
619381	Landcruiser DC	CAMBIO DE DOS NEUMÁTICOS	CAMBIO DE DOS NEUMÁTICOS	03/07/2021		Corrective Order	WO Completed	Pickup truck
619399	JLG 450 AJ Manlift	reparacion de mangueras	REOATRACION DE MANGUERAS	03/07/2021		Corrective Order	WO Completed	Manlift
619405	Caterpillar 12M	CAMBIO COMPONENTE POWER TRAIN	CAMBIO DE COMPONENTES	03/07/2021		Corrective Order	WO Completed	Grader
619412	TCM FGH25D	Intalacion Luz Led Azul	INTALACION LUZ LED AZUL	03/07/2021		Corrective Order	WO Completed	Forklift
619415	Hyster E70xn 3t Forklift (E)	instalacion de luz led Azul	INSTALACION DE LUZ LED AZUL	03/07/2021		Corrective Order	WO Completed	Forklift
619419	Hyster E70xn 3t Forklift (E)	instalacion de luz led Azul	INSTALACION DE LUZ LED AZUL	03/07/2021		Corrective Order	WO Completed	Forklift
619431	Terex T5551 55TON	Reparacion de cilindro	REPARACION DE CILINDRO	03/07/2021		Corrective Order	WO Completed	Crane/Hoist
619434	JLG 1250 AJP Manlift	Reparacion de motor de arranqu	REPARACION DE MOTOR DE ARRANQUE	03/07/2021		Corrective Order	WO Completed	Manlift
619435	Hilux DC	reparacion de llanta	REPARACION D ELLANTA	03/07/2021		Corrective Order	WO Completed	Pickup truck
619445	Grove RT700E 60TON	PERDIDA DE POTENCIA	EL QUIPO PERDIO POTENCIA EN FUNCIONAMIENTO	03/07/2021		Corrective Order	WO Completed	Crane/Hoist
619447	Grove RT650E 45TON	FUGA POR LÍNEA HIDRAULICA	EQUIPO PRESENTA FUGA POR LÍNEA HIDRÁULICA	03/07/2021		Corrective Order	WO Completed	Crane/Hoist
619480	Unimog Service Truck	CAMBIO DE CADENA	CAMBIO DE CADENA	03/07/2021		Corrective Order	WO Completed	Truck
619483	Hyster H300 Forklift	Cambio de esparragos	ESPARRAGOS DE RUEDA EN MAL ESTADO	03/07/2021		Corrective Order	WO Completed	Forklift
619488	Gallegos Flatbed Trailer	Ajuste de Frenos	BAJAS DE FRENOS	03/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
619576	Gallegos Flatbed Trailer	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
619578	PRAMAC GSW120 120 kVa	PM PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	04/07/2021	5881 hrs	PM Orders	WO Completed	Generator
619579	PRAMAC GSW45 35 kVa	PM PRA GSW45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	04/07/2021	163.5 horas	PM Orders	WO Completed	Generator
619580	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	04/07/2021	22358 hrs	PM Orders	WO Completed	Generator
619582	SDMO J60U 60KVA	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	04/07/2021	19030 hrs	Corrective Order	WO Completed	Generator
619607	New Holland Lm 1745	Cambio de lamparas delanteras	LAMPARA DELANTERAS EN MAL ESTADO	04/07/2021	90009815	Corrective Order	WO Completed	Telehender
619613	Gallegos Lime Tank	cambio de 2llanta	LLANTA EN MAL ESTADO	04/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
619614	Coaster	Cambio de 2 llantas	LLANTAS EN MAL ESTADO	04/07/2021		Corrective Order	WO Completed	Bus
619621	Atlas Copco HILIGHT V5 Light T	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	04/07/2021	no se ubica equipo	Corrective Order	WO Completed	Light Tower
619622	Doosan D1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	04/07/2021	no se ubica equipo	Corrective Order	WO Completed	Light Tower
619636	Hilux DC	INSTALAR BOLA TIRO/CARGA	INSTALACION DE BOLA DE CARGA	04/07/2021	3753	Corrective Order	WO Completed	Pickup truck
619643	Hilux DC	INSTALAR BOLA TIRO/CARGA	INSTALACION DE BOLA DE CARGA	04/07/2021		Corrective Order	WO Completed	Pickup truck
619740	Caterpillar 740b Ej	C/RETROVISORES LH/RH	FLOJOS NO MANTIENE AJUSTE	04/07/2021		Corrective Order	WO Completed	Articulated dump truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
619816	Caterpillar 14H Motorgrader	cambio de hojas de corte	CAMBIO DE HOJAS DE CORTE	04/07/2021		Corrective Order	WO Completed	Grader
619833	Hino Series 300	Reparacion de llantas	REPARACION DE LLANTAS	04/07/2021		Corrective Order	WO Completed	Truck
619835	Caterpillar 14M Motorgrader	Manguera del sistema hidrául	MANGUERA DEL SISTEMA HIDRÁULI	04/07/2021		Corrective Order	WO Completed	Grader
619836	Freightliner Columbia CI112	Cambio de llantas flat	CAMBIO DE LLANTAS	04/07/2021		Corrective Order	WO Completed	Mule truck
619876	Landcruiser DC	CAMBIO ARO	POR DANO ESTRUCTURAL	04/07/2021		Corrective Order	WO Completed	Pickup truck
619890	Faresin FM4000 / 17F Telehandl	A/C REVISION	INSPECTION	04/07/2021	90009870	Corrective Order	WO Completed	Telehender
619913	Unimog Service Truck	UM007 INOPERATIVO	UM007 INOPERATIVO	04/07/2021		Corrective Order	WO Completed	Truck
619978	Caterpillar 336DL	Sello del Tapa Valvulas	CAMBIO DEL SELLO DEL TAPA VALVULAS, TAPA DEL TANQUE HIDRÁULICO, REVISIÓN DE A/A,	04/07/2021	(HR) 17715.3	Corrective Order	WO Completed	Excavator
619981	ATR-0000-001 4+320 AGRICO	CINTURON DE SEGURIDAD, PUERTA	CINTURON DE SEGURIDAD Y PUERTA DAÑADAS	04/07/2021	(HR) 539	Corrective Order	WO Completed	Tractor
619982	SJS SJ6530	ENGRASE Y CAMBIO DE HITCH	ENGRASE Y CAMBIO DE HITCH	04/07/2021		Corrective Order	WO Completed	Compactor
619983	Faresin FM4000 / 17F Telehandl	INSPECCIÓN DEL A/A	INSPECCIÓN DEL A/A	04/07/2021		Corrective Order	WO Completed	Telehender
620005	Caterpillar 416E	cambio de manguera	FUGA DE HIDRAULICO POR MANGUERA	04/07/2021		Corrective Order	WO Completed	Backhoe
620149	Gallegos 28M3 Lime Tank	cambio de 2 llantas	LLANTAS EN MAL ESTADO	05/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
620165	John Deere 9370R Tractor	desmonatje de hetch	DESMOMNATJE DE HETCH	05/07/2021		Corrective Order	WO Completed	Tractor
620198	John Deere 9370R Tractor	Desmontar Hetch	DESMONATR HETCH	05/07/2021		Corrective Order	WO Completed	Tractor
620199	Hyster H700 Forklift	Calibracion de equipo	CALIBRACION DE EQUIPO	05/07/2021		Corrective Order	WO Completed	Forklift
620205	Grove RT650E 45TON	Cambio de sensor de presion	SENSOR DE PRESION DE COMBUSTIBLE EN FALLA	05/07/2021	90009831	Corrective Order	WO Completed	Crane/Hoist
620207	Caterpillar 14H Motorgrader	Reparacion de a/c	FALLA EN SISTEMA DE A/C	05/07/2021	20,863.00 hrs	Corrective Order	WO Completed	Grader
620208	Gallegos Lime Tank	Cambio de estabilizadores	EZTABILIZADOR EN MAL ESTADO	05/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
620285	Caterpillar 740B	R&I Wiper Motor	R&I WIPER MOTOR	05/07/2021		PM Orders	WO Completed	Articulated dump truck
620333	Landcruiser DC	cambio de llantas	DETERIORADA	05/07/2021		Corrective Order	WO Completed	Pickup truck
620379	Landcruiser TC	cambio 1 llanta	DETERIORADA	05/07/2021	cambio por deterioro	Corrective Order	WO Completed	Pickup truck
620386	Landcruiser TC	cambio de llanta 1	DETERIORADA	05/07/2021	cambio 1 llanta	Corrective Order	WO Completed	Pickup truck
620462	Caterpillar 740B EJ ADT	REP/FRAME POSTERIOR	DESGASTE/HORAS DE SERVICIO	05/07/2021		Corrective Order	WO Completed	Articulated dump truck
620465	Caterpillar 740B EJ ADT	C/BEARING AFRAME CENTRAL	JUEGO EN EL MECANISMO	05/07/2021		Corrective Order	WO Completed	Articulated dump truck
620476	Caterpillar 336DL	cambio de lavula de carga	CAMBIO DE VALVULA DE CARGA	05/07/2021		Corrective Order	WO Completed	Excavator
620537	Freightliner Columbia CI112	AJUSTE PUERTA / ENGRASE	AJUSTE PUERTA / ENGRASE	05/07/2021		Corrective Order	WO Completed	Mule truck
620538	JLG 450 AJ Manlift	Programacion de movimientos	PROGRAMACION DE MOVIMIENTO	05/07/2021		Corrective Order	WO Completed	Manlift
620546	Caterpillar 12M	mantenimiento mensual Afex	MANTENIMIENTO MENSUAL AFEX	05/07/2021		Corrective Order	WO Completed	Grader
620551	Gallegos Flatbed Trailer	Repatracion d ellanta	REPARACION D ELLANTA	05/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
620552	Manitou Mht-X1490 9t Telehand	Reparacion de llanta	REPARACION DE LLANTA	05/07/2021		Corrective Order	WO Completed	Telehender
620555	Manitou Mht-X1490 9t Telehand	reparacion de llantas	REPARACION D ELLANTAS	05/07/2021		Corrective Order	WO Completed	Telehender
620570	ATR-0000-001 4+320 AGRICO	Trabajos de Soldadura Puerta	TRABAJOS DE SOLDADURA PUERTA	05/07/2021		Corrective Order	WO Completed	Tractor
620571	Unimog Service Truck	instalación de tren delantero	INSTALACIÓN DE TREN DELANTERO	05/07/2021		Corrective Order	WO Completed	Truck
620584	Hyster E70xn 3t Forklift (E)	Blue safety light	BLUE SAFETY LIGHT	05/07/2021		Corrective Order	WO Completed	Forklift
620589	Kalmar	CABIN JOINT REPAIR (GPE)	CORRECTIVE	05/07/2021	50014268	Corrective Order	WO Completed	Telehender
621306	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	06/07/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
621385	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	06/07/2021		Corrective Order	WO Completed	Pickup truck
621386	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	06/07/2021		Corrective Order	WO Completed	Pickup truck
621390	Gallegos Flatbed Trailer	ajuste de freno	AJUSTE DE FRENO	06/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
621391	Freightliner CI 120	ajuste de freno	AJUSTE DE FRENO	06/07/2021		Corrective Order	WO Completed	Mule truck
621393	Grove GMK 4080 80TON	cambio de valvulas de Est	ESTABLIZADORES CON FUGA EN VALVULA	06/07/2021	90009873	Corrective Order	WO Completed	Crane/Hoist
621434	Caterpillar 12M	Remplazo de mangueras hidraul	REEMPLAZO DE MANGUERA HIDRÁULICA	06/07/2021		Corrective Order	WO Completed	Grader
621560	International 7400 SBA Fire Tr	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	06/07/2021	90009899	Corrective Order	WO Completed	Fire truck
621649	Unimog Service Truck	cambio de motor de arranque	CAMBIO DE MOTOR DE ARRANQUE	06/07/2021		Corrective Order	WO Completed	Truck
621651	Manitou Mht-X1490 9t Telehand	Cambio de sellos del cuerpo	CAMBIO DEL CUERPO DE VALVULA	06/07/2021		Corrective Order	WO Completed	Telehender
621652	JLG 1250 AJP Manlift	No arranca	NO ARRANCA	06/07/2021		Corrective Order	WO Completed	Manlift
621655	Freightliner Columbia CI112	Instalar p[olleras	INSTALACION DE POLLERAS	06/07/2021		Corrective Order	WO Completed	Mule truck
621657	Caterpillar 740B EJ ADT	Testigo en tablero	TESTIGO EN TABLERO OTG, TRANSFER	06/07/2021		Corrective Order	WO Completed	Articulated dump truck
621705	Gmc Boom Truck	CAMBIO DE BATERÍAS	CAMBIO DE BATERIAS	06/07/2021		Corrective Order	WO Completed	Boom truck
621717	Caterpillar CS533E Compactor	BAJO NIVEL DE ACEITE DE MOTOR	BAJO NIVEL DE ACEITE DE MOTOR	06/07/2021		Corrective Order	WO Completed	Compactor
621934	Caterpillar 307E Miniexcavator	cambio de manguera	MANGUERA ROTA	07/07/2021		Corrective Order	WO Completed	Excavator
621960	Freightliner M2 106 Hydroseedi	Rep. de cadena y guia	CADENA Y GUIA DAÑADOS	07/07/2021		Corrective Order	WO Completed	Truck
621961	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
621962	Unimog Service Truck	reparacion de 1 llanta	LLANTA FLAT	07/07/2021		Corrective Order	WO Completed	Truck
621963	Caterpillar 226b Skid Steer L	arranque de equipo	EQUIPO NO ARRANCA	07/07/2021		Corrective Order	WO Completed	Skid Steer
621965	Freightliner Columbia CI112	Reparacion de llanta	LLANTA FLAT	07/07/2021		Corrective Order	WO Completed	Mule truck
622011	Caterpillar 740B EJ ADT	C/MANGUERAS DE ENFIRAMIENTO	DESGASTE/HORAS DE SERVICIO	07/07/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
622064	Caterpillar CS74 Compactor	CAMBIO DE COMPONENTE	CAMBIO DE COMPONENTE	07/07/2021		Corrective Order	WO Completed	Compactor
622067	Freightliner Boom Truck	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/07/2021		Corrective Order	WO Completed	Boom truck
622068	Caterpillar 740B EJ ADT	C/ LINEA HYD SYST FRENOS	ROTA	07/07/2021		Corrective Order	WO Completed	Articulated dump truck
622099	PRAMAC GSW170I 164 kVa	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	07/07/2021	8220 horas	Corrective Order	WO Completed	Generator
622220	John Deere 9370R Tractor	Reparacion Hitc para Compactad	MODIFICACIN	07/07/2021	AUTO CLOSED	Corrective Order	WO Completed	Tractor
622248	Hilux DC	CAMBIO DE RIM Y LLANTA	CAMBIO DE RIM Y LLANTA	07/07/2021		Corrective Order	WO Completed	Pickup truck
622264	Freightliner Columbia CI112	Reparacion de llantas	REPARACION DE LLANTAS	07/07/2021		Corrective Order	WO Completed	Mule truck
622265	Manitou Mht-X1490 9t Telehand	Reparacion d ellantas	REPARACION DE LLANTAS	07/07/2021		Corrective Order	WO Completed	Telehender
622266	Grove RT890 90TON	Repatracion de fuga de coulant	REPARACION DE FUGA DE COULANT	07/07/2021		Corrective Order	WO Completed	Crane/Hoist

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
622267	Freightliner M2 106 Sucker Tru	cambio de Pulmón	CAMBIO DE PULMÓN	07/07/2021	22,642.00 Hrs	Corrective Order	WO Completed	Sucker truck
622270	Caterpillar 140K	Fuga de de aire	FUGA DE DE AIRE	07/07/2021		Corrective Order	WO Completed	Grader
622272	Caterpillar 140K	cambio de hoja de corte	CAMBIO DE HOJA DE CORTE	07/07/2021		Corrective Order	WO Completed	Grader
622275	Caterpillar 14H Motorgrader	Manguera del filtro de aire	MANGUERA DEL FILTRO DE AIRE	07/07/2021		Corrective Order	WO Completed	Grader
622276	Caterpillar 14H Motorgrader	No tiene aire acondicionado	NO TIENE AIRE ACONDICIONADO	07/07/2021		Corrective Order	WO Completed	Grader
622293	Hyster E70xn 3t Forklift (E)	PM4 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/07/2021	90009942	Corrective Order	WO Completed	Forklift
622296	Hyster E70xn 3t Forklift (E)	PM4 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/07/2021	90009943	Corrective Order	WO Completed	Forklift
622298	Hyster E70xn 3t Forklift (E)	PM4 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/07/2021	90009944	Corrective Order	WO Completed	Forklift
622308	Landcruiser TC	cambio de 1 llanta	LLANTA EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
622310	Hilux DC	cambio de llanta	LLANTA FLAT	07/07/2021		Corrective Order	WO Completed	Pickup truck
622311	Hilux DC	cambio de 2 llanta	LLANTA EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
622312	Hilux DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
622313	Landcruiser TC	cambio de 1 llanta	LLANTA FLAT	07/07/2021		Corrective Order	WO Completed	Pickup truck
622314	Landcruiser TC	cambio de 3 llanta	LLANTA EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
622315	Landcruiser DC	camdio de 1 llanta	LLANTA EN MAL ESTADO	07/07/2021		Corrective Order	WO Completed	Pickup truck
622407	Grove RT600E 50TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	08/07/2021		PM Orders	WO Completed	Crane/Hoist
622420	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	08/07/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
622448	Hilux DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	08/07/2021		Corrective Order	WO Completed	Pickup truck
622452	Landcruiser TC	cambio de rim	RIM EN MAL ESTADO	08/07/2021		Corrective Order	WO Completed	Pickup truck
622460	Coaster	Rescate de Equipo	EQUIPO FLAT	08/07/2021		Corrective Order	WO Completed	Bus
622464	Caterpillar 416E	Falla en sitema hidraulico	FALLA EN SISTEMA HIDRAULICO	08/07/2021		Corrective Order	WO Completed	Backhoe
622465	Gmc Boom Truck	Instalacion de alarma y luces	SIN LUZ DE REVERZA Y ALARMA	08/07/2021		Corrective Order	WO Completed	Boom truck
622468	Freightliner 8170ME Water Truc	Remplazo de empaque de manguer	REEMPLAZO DE EMPAQUE DE MANGUER	08/07/2021		Corrective Order	WO Completed	Water truck
622479	Caterpillar 12M	CAMBIO DE BOMBA FAN & BRAKE	EQUIPO DE IASA	08/07/2021	90010028 90010953	Corrective Order	WO Completed	Grader
622526	Caterpillar 426f2 Backhoe	Reparación de Palanca de contr	REPARACIÓN DE PALANCA DE CONTROL	08/07/2021		Corrective Order	WO Completed	Backhoe
622531	Freightliner CI 120	Relleno de coollant	RELLENO DE COOLLANT	08/07/2021		Corrective Order	WO Completed	Mule truck
622555	Caterpillar 426f2 Backhoe	Cambio de filtro de aire	CAMBIO DE FILTRO DE AIRE	08/07/2021		Corrective Order	WO Completed	Backhoe
622603	Freightliner M112 Truck Tip	Enfriador de Aceite de Direcci	ENFRIADOR DE ACEITE DE DIRECCIÓN	08/07/2021	90010034	Corrective Order	WO Completed	Tipper
622662	Toyota Hilux	AJUSTE SISTEMA DE FRENOS	FRENO EMERGENCIA NO FUNCIONA	08/07/2021		Corrective Order	WO Completed	Pickup truck
622690	Hiace Bus	reparacion electrica	REPARACION ELECTRICA	08/07/2021		Corrective Order	WO Completed	Bus
622700	Caterpillar 140K	CAMBIO DE ASIENTO OPERADOR	REPORTE IASA	08/07/2021	90010344	Corrective Order	WO Completed	Grader
622734	Gallegos Flatbed Trailer	FRENOS/ FUGA DE AIRE	FRENOS/ FUGA DE AIRE	08/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
622756	Manitou MTH-X 10120	PREVENTIVE MAINTENANCE (500 H)	PREVENTIVE MAINTENANCE	08/07/2021	6956.4 Hrs	Corrective Order	WO Completed	Telehender
622757	Kalmar	PREVENTIVE MAINTENANCE (500 H)	PREVENTIVE MAINTENANCE	08/07/2021	2657.9 Hr	Corrective Order	WO Completed	Telehender
622761	Ferrari F478	PREVENTIVE MAINTENANCE (500 H)	PREVENTIVE MAINTENANCE	08/07/2021	6795.9 Hr	Corrective Order	WO Completed	Reach Stacker
622762	Linde T30D	PREVENTIVE MAINTENANCE (500 H)	PREVENTIVE MAINTENANCE	08/07/2021	3684.9 Hrs	Corrective Order	WO Completed	Forklift
622805	Grove RT600E 50TON	Equipo no arranca	REVISIÓN DE EQUIPO, NO ARRANCA	08/07/2021		Corrective Order	WO Completed	Crane/Hoist
622814	Freightliner M2 106 Refrigerat	Instalación de Luces	INSTALACIÓN DE LUCES	08/07/2021		Corrective Order	WO Completed	Refrigerator truck
622817	Freightliner M2 106 Refrigerat	Ruptura de Correa	CORREA Y TENSOR DAÑADOS	08/07/2021		Corrective Order	WO Completed	Refrigerator truck
622818	JLG 800 AJ Manlift	Nivel bajo de hidráulico	BAJO NIVEL DE ACEITYE HIDRÁULICO	08/07/2021		Corrective Order	WO Completed	Manlift
622819	Caterpillar TL1055CLRC	Reparación de Neumático	REPARACIÓN DE NEUMÁTICO	08/07/2021		Corrective Order	WO Completed	Telehender
622820	Freightliner 8170ME Water Truc	Falla de Embrague	FALLA DE EMBRAGUE	08/07/2021		Corrective Order	WO Completed	Water truck
622821	Grove RT650E 45TON	Nivel de aceite de transmisión	NIVEL DE ACEITE DE TRANSMISIÓN	08/07/2021		Corrective Order	WO Completed	Crane/Hoist
623478	Grove RT600E 50TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	09/07/2021		PM Orders	WO Completed	Crane/Hoist
623612	Caterpillar 320DL	Mantenimiento semestral AFEX	MANTENIMIENTO SEMESTRAL AFEX	09/07/2021		Corrective Order	WO Completed	Excavator
623682	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623683	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623684	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	51639	PM Orders	WO Completed	Pickup truck
623685	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	79395	PM Orders	WO Completed	Pickup truck
623686	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623687	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623688	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623689	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623691	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	27754	PM Orders	WO Completed	Pickup truck
623692	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623693	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623694	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	57320	PM Orders	WO Completed	Pickup truck
623695	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623696	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623697	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	48775	PM Orders	WO Completed	Pickup truck
623699	Caterpillar 12M Motorgrader	fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	09/07/2021		Corrective Order	WO Completed	Grader
623700	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	68744	PM Orders	WO Completed	Pickup truck
623701	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623702	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	44393	PM Orders	WO Completed	Pickup truck
623703	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	129428	PM Orders	WO Completed	Pickup truck
623704	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623706	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623707	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021	28167	PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
623708	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 46205		PM Orders	WO Completed	Pickup truck
623709	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 50168		PM Orders	WO Completed	Pickup truck
623710	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 9373		PM Orders	WO Completed	Pickup truck
623711	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 40581		PM Orders	WO Completed	Pickup truck
623713	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623714	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 17158		PM Orders	WO Completed	Pickup truck
623715	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 15622		PM Orders	WO Completed	Pickup truck
623716	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 10019		PM Orders	WO Completed	Pickup truck
623717	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 11246		PM Orders	WO Completed	Pickup truck
623718	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 13574		PM Orders	WO Completed	Pickup truck
623719	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623720	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623721	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623727	PB002 COASTER TOYOTA	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 286248 KM		PM Orders	WO Completed	Bus
623733	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 30237		PM Orders	WO Completed	Bus
623734	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 39276		PM Orders	WO Completed	Bus
623736	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Bus
623741	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Pickup truck
623748	Hino Serie 300 Box Truck	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Truck
623749	Hino Serie 300 Box Truck	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021		PM Orders	WO Completed	Truck
623751	Hino Dutro 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 86198		PM Orders	WO Completed	Truck
623756	Ford F550	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	09/07/2021 38782		PM Orders	WO Completed	Pickup truck
623759	Hino Dutro 300	REPARACION DE EQUIPO	REPARACION POR DOLLARS	09/07/2021 50016908		Corrective Order	WO Completed	Truck
623761	PRAMAC GSW110 82 kVa	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	09/07/2021 839 horas		Corrective Order	WO Completed	Generator
623764	Caterpillar 12M Motorgrader	CAMBIO DE VIDRIO	CORRECTIVO	09/07/2021		Corrective Order	WO Completed	Grader
623770	PB002 COASTER TOYOTA	REPARACION VEHICULO	REPARACION DOLLARS	09/07/2021 286248 KM		Corrective Order	WO Completed	Bus
623771	SJS SJ6530	Cambio de componentes	CAMBIO DE COMPONENTES	09/07/2021		Corrective Order	WO Completed	Compactor
623782	Case 110JX Tractor Cable Handl	Cambio de Batería	CAMBIO DE BATERÍAS	09/07/2021		Corrective Order	WO Completed	Tractor
623799	PRAMAC GSW460V 460 kVa	REPARAR GENERADOR AC	EMBOBINADOS NACIONALES	09/07/2021 12940 hrs		Corrective Order	WO Completed	Generator
623808	Trucks	TIRE INSTALLATION	TIRE INSTALLATION	09/07/2021		Corrective Order	WO Completed	Area
623849	Freightliner Cl 120	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	09/07/2021		Corrective Order	WO Completed	Mule truck
623851	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	09/07/2021		Corrective Order	WO Completed	Pickup truck
623862	Landcruiser TC	Cambio de un neumático	CAMBIOD E UN NEUMÁTICO	09/07/2021		Corrective Order	WO Completed	Pickup truck
623863	Freightliner Cl 120	AJUSTE FRENOS	AJUSTE FRENOS	09/07/2021		Corrective Order	WO Completed	Mule truck
623870	Hilux DC	cambio de un neumático	CAMBIO DE UN NEUMÁTICO	09/07/2021		Corrective Order	WO Completed	Pickup truck
623872	Intraax 53121 Hendrickso	AJUSTE FRENOS	AJUSTE FRENOS	09/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
623877	Freightliner Columbia Cl112	LUZ ESCOLTA	LUZ ESCOLTA	09/07/2021 70787.6		Corrective Order	WO Completed	Mule truck
623885	Mobile equipment	HELMET LAMPS	WORKSHOP TOOLS	09/07/2021 90009980		Corrective Order	WO Completed	Area
623931	Caterpillar 140K	CAMBIO DE ADAPTER Y ESCARIFICA	CAMBIO DE ESCARIFICADORES	09/07/2021		Corrective Order	WO Completed	Grader
623971	Caterpillar D8T Dozer	Problema con los cambios	PROBLEMA CON LOS CAMBIOS	09/07/2021		Corrective Order	WO Completed	Dozer
623998	CAT 930K	No funciona la bocina	NO FUNCIONA LA BOCINA	09/07/2021		Corrective Order	WO Completed	Loader
624004	CAT 930K	estribo le hace falta 1	ESTRIBO LE HACE FALTA 1	09/07/2021		Corrective Order	WO Completed	Loader
624005	CAT 930K	ReparLimpia parabrisas, luces	REPARLIMPIA PARABRISAS, LUCES	09/07/2021		Corrective Order	WO Completed	Loader
624028	Gallegos 28M3 Lime Tank	Tapa quebrada del cono	TAPA QUEBRADA DEL CONO	09/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
624064	Unimog Service Truck	INNOOPERATIVO / NEUMATICO FLAT	INNOOPERATIVO / NEUMATICO FLAT	09/07/2021		Corrective Order	WO Completed	Truck
624097	Landcruiser TC	RIM REPLACEMENT	CORRECTIVE	09/07/2021		Corrective Order	WO Completed	Pickup truck
624107	Freightliner 8170ME Water Truc	CAMBIO DE BOMBA DE AGUA	CAMBIO DE BOMBA DE AGUA SISTEMA DE RIEGO	09/07/2021		Corrective Order	WO Completed	Water truck
624148	Hilux DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	09/07/2021		Corrective Order	WO Completed	Pickup truck
624152	Gallegos Flatbed Trailer	cambio de 1 llanta	LLANTA EN MAL ESTADO	09/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
624153	Freightliner M112 Truck Tip	cambio de llantas y rines	LLANTAS EN MAL ESTADO	09/07/2021		Corrective Order	WO Completed	Tipper
624255	Grove RT600E 50TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	10/07/2021		PM Orders	WO Completed	Crane/Hoist
624269	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	10/07/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
624293	Randon SR-SI-TV-03-27 Lime Tan	cambio de pulmon	PULMON EN MAL ESTADO	10/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
624317	John Deere 9370R Tractor	Revisión de sistema Afex	SISTEMA AFEX CON FALLO	10/07/2021 3,082.10 hrs		Corrective Order	WO Completed	Tractor
624319	Caterpillar 416E	Revisión de Equipo	EQUIPO CON FALLA ELÉCTRICA	10/07/2021		Corrective Order	WO Completed	Backhoe
624328	Caterpillar 12M	Cambio de manguera	FUGA DE ACEITE HIDRÁULICO	10/07/2021		Corrective Order	WO Completed	Grader
624334	Hyster H700 Forklift	engrase de manipulador	ENGRASE DE MANIPULADOR	10/07/2021		Corrective Order	WO Completed	Forklift
624335	Hyster H700 Forklift	engrase de manipulador	ENGRASE DE MANIPULADOR	10/07/2021		Corrective Order	WO Completed	Forklift
624338	Broce Broom RJT 350	Soldadura de funda de escobill	FUNDA DE ESCOBILLON SUELTA	10/07/2021		Corrective Order	WO Completed	Scrubber / Sweeper
624345	Caterpillar 226b Skid Steer L	Cambio de vidrios frontales	CAMBIO VIDRIOS FRONTALES	10/07/2021 90010137		Corrective Order	WO Completed	Skid Steer
624352	PRAMAC GSW560V 407 kVa	PUESTA EN MARCHA	INSTALACION Y AJUSTE DEL ALTERNADOR AC	10/07/2021 17919 horas		Corrective Order	WO Completed	Generator
624423	Gallegos 28M3 Lime Tank	BOLSAS DE AIRE/ LUCES	BOLSAS DE AIRE/ LUCES	10/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
624438	Freightliner Columbia Cl112	CAMBIO DE 4 NEUMÁTICOS	CAMBIO DE 4 NEUMÁTICOS	10/07/2021 AUTOCLOSED		Corrective Order	WO Completed	Mule truck
624446	Freightliner Cl 120	RADIADOR DRENAJE	RADIADOR DRENAJE	10/07/2021		Corrective Order	WO Completed	Mule truck
624454	Freightliner Cl 120	LUCES	LUCES	10/07/2021		Corrective Order	WO Completed	Mule truck
624482	Freightliner Columbia Cl112	Cambio de correas	CAMBIO DE CORREAS	10/07/2021		Corrective Order	WO Completed	Mule truck
624507	SJS SJ6530	Reparación Mayor (IMREPSA)	REPARACIÓN MAYOR	10/07/2021 50014934		Corrective Order	WO Completed	Compactor
624541	Freightliner 8170ME Water Truc	Marca temperatura alta	MARCA TEMPERATURA ALTA	10/07/2021		Corrective Order	WO Completed	Water truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
624552	Trucks	Colocacion de llanta	COLOCACION DE LLANTA	10/07/2021		Corrective Order	WO Completed	Area
624564	Grove RT890 90TON	Cambio de mangueras	CAMBIO DE MANGUERAS	10/07/2021		Corrective Order	WO Completed	Crane/Hoist
624590	Hiace Bus	Reparacion de luces	REPARACION DE LUCES	10/07/2021		Corrective Order	WO Completed	Bus
624712	Landcruiser TC	CAMBIO DE NEUMÁTICO	LLANTA DETERIORADA	10/07/2021		Corrective Order	WO Completed	Pickup truck
624714	Landcruiser DC	1 llanta	DETERIORO	10/07/2021	cambio de llanta	Corrective Order	WO Completed	Pickup truck
624715	Coaster	1 llanta	DETERIORADA	10/07/2021	cambio	Corrective Order	WO Completed	Bus
624725	JLG 450 AJ Manlift	Revisar movimientos	REVISAR MOVIMIENTOS Y NIVEL DE ACEITE	10/07/2021		Corrective Order	WO Completed	Manlift
624769	Caterpillar 226B	TA1 INSPECCION MECANICA	EQUIPO IASA	10/07/2021		Corrective Order	WO Completed	Skid Steer
624786	Doosan D1005	MANTENIMIENTO CORRECTIVO	REPARACION DE LUMINARIAS	10/07/2021	EQUIPO SCRAPS	Corrective Order	WO Completed	Light Tower
624788	Mercedes Tipper Truck	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	10/07/2021		Corrective Order	WO Completed	Tipper
624818	Caterpillar D8T Dozer	Revision de transmision	EQUIPO NEUTRALIZADO	10/07/2021		Corrective Order	WO Completed	Dozer
624819	Liugong Cpcd20	LEVANTAMIENTO DE FILTROS	LEVANTAMIENTO DE INFORMACION	10/07/2021		Corrective Order	WO Completed	Forklift
624820	JLG 450 AJ Manlift	INSPECCION DE FALLA	LEVANTAMIENTO DE INFORMACION	10/07/2021		Corrective Order	WO Completed	Manlift
624822	JLG T350 Manlift	INSPECCION DE FALLA	LEVANTAMIENTO DE INFORMACION	10/07/2021		Corrective Order	WO Completed	Manlift
624824	Caterpillar CS74 Compactor	Revision de diferencial	CAMBIO DE ACEITE DE DIFERENCIAL	10/07/2021		Corrective Order	WO Completed	Compactor
624825	Hilux DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	10/07/2021		Corrective Order	WO Completed	Pickup truck
624826	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	10/07/2021		Corrective Order	WO Completed	Pickup truck
624827	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	10/07/2021		Corrective Order	WO Completed	Pickup truck
624828	Landcruiser DC	cambio de 2 llantas	LLANTA EN MAL ESTADO	10/07/2021		Corrective Order	WO Completed	Pickup truck
624857	Ford F550	Reparación de a/c	REPARACIÓN DE A/C	11/07/2021		Corrective Order	WO Completed	Pickup truck
624858	Caterpillar 416E	verificación de sistema Electr	EQUIPO NO ARRANCA	11/07/2021		Corrective Order	WO Completed	Backhoe
624958	USP&E GP700S/V-A 700 kVa	CORRECTIVO	DESCONEXION Y DESMOTAJE DE ALTERNADOR AC	11/07/2021	12940 hrs	Corrective Order	WO Completed	Generator
625001	Freightliner CI 120	cambio de 2 llantas	LLANTAS EN MAL ESTADO	11/07/2021		Corrective Order	WO Completed	Mule truck
625002	Gallegos Flatbed Trailer	cambio de 2 llantas	LLANTAS EN MAL ESTADO	11/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
625024	Caterpillar 14H Motorgrader	REVISIÓN DE BLOQUEO DE DIFEREN	REVISIÓN DE BLOQUEO DE DIFERENCIAL	11/07/2021		Corrective Order	WO Completed	Grader
625034	Freightliner M2 106 Hydroseedi	HYDROSEEDING SYSTEM CHECK	INSPECTION	11/07/2021		Corrective Order	WO Completed	Truck
625035	Freightliner M2 106 Hydroseedi	HYDROSEEDING SYSTEM CHECK	INSPECTION	11/07/2021		Corrective Order	WO Completed	Truck
625037	Intraax 53121 Hendrickso	Fuga de aceite	FUGA DE ACEITE	11/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
625041	GROVE RT9130E 120TON	CRANE FREIGHT PREPARING	CRANE FREIGHT PREPARING	11/07/2021	AUTO CLOSED	Corrective Order	WO Completed	Crane/Hoist
625073	Manitou Mht-X1490 9t Telehand	Problema Para Encender	PROBLEMA PARA ENCENDER	11/07/2021		Corrective Order	WO Completed	Telehender
625107	Landcruiser DC	CAMBIO DE LLANTA	CAMBIO DE LLANTA	11/07/2021		Corrective Order	WO Completed	Pickup truck
625116	Landcruiser DC	CAMBIO DE LLANTA	CAMBIO DE LLANTA	11/07/2021		Corrective Order	WO Completed	Pickup truck
625134	John Deere 9370R Tractor	CONFECCIÓN DE MANGUERAS	CONFECCIÓN DE MANGUERAS	11/07/2021		Corrective Order	WO Completed	Tractor
625164	Caterpillar D110 E2 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	16367 horas	PM Orders	WO Completed	Generator
625165	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	20302 HORAS	PM Orders	WO Completed	Generator
625167	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	16621 HRS	PM Orders	WO Completed	Generator
625168	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	12259 HRS	PM Orders	WO Completed	Generator
625169	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	16354 HRS	PM Orders	WO Completed	Generator
625170	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	12216 HRS	PM Orders	WO Completed	Generator
625171	PRAMAC GSW80P 83 kVa	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	10840 HRS	PM Orders	WO Completed	Generator
625173	PRAMAC GSW170I 164 kVa	PM PRA GSW170I MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	8259 horas	PM Orders	WO Completed	Generator
625176	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	23734 hrs	PM Orders	WO Completed	Generator
625178	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	16083 horas	PM Orders	WO Completed	Generator
625180	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	18759 HRS	PM Orders	WO Completed	Generator
625185	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	5612 horas	PM Orders	WO Completed	Generator
625187	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	6398 horas	PM Orders	WO Completed	Generator
625188	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	793 hrs	PM Orders	WO Completed	Generator
625189	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	7129 HORAS	PM Orders	WO Completed	Generator
625191	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	36217 HORAS	PM Orders	WO Completed	Generator
625193	PRAMAC GSW90P 74 kVa	PM PRA GSW90P MEC 300 HR	PM PRA GSW90P MEC 300 HR	11/07/2021	24720 HRS	PM Orders	WO Completed	Generator
625194	PRAMAC GSW65 48 kVa	PM PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	23734 HORAS	PM Orders	WO Completed	Generator
625196	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	23259 HORAS	PM Orders	WO Completed	Generator
625197	Olympian GEP18-6 18KVA	PM OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	28680 horas	PM Orders	WO Completed	Generator
625198	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	22592 HORAS	PM Orders	WO Completed	Generator
625199	PRAMAC GSW25 17 kVa	PM PRA GSW25 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	555 horas	PM Orders	WO Completed	Generator
625200	Pramac GSW25P 17KVA	PM PRA GSW25 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	4945 horas	PM Orders	WO Completed	Generator
625215	Manitou Mht-X860 6t Telehand	Cambio de Lamparas	CAMBIO DE LAMPARAS	11/07/2021	90010159	Corrective Order	WO Completed	Telehender
625235	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	24182 horas	Corrective Order	WO Completed	Light Tower
625238	DOOSAN 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	19586 horas	Corrective Order	WO Completed	Light Tower
625259	PRAMAC GSW110 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/07/2021	839 horas	PM Orders	WO Completed	Generator
625374	Mercedes Tipper Truck	ELECTRICAL SYS REVISION	INSPECTION	11/07/2021		Corrective Order	WO Completed	Tipper
625378	Freightliner M2 106 Refrigerat	CAMBIO MOTOR DE ARRANQUE	EQUIPO NO ENCIENDE	11/07/2021		Corrective Order	WO Completed	Refrigerator truck
625399	Freightliner M112 Truck Tip	MECHANICAL INSPECTION	INSPECTION	11/07/2021		Corrective Order	WO Completed	Tipper
625476	Caterpillar 336DL	Reparación de aire acondiona	REPARACIÓN DE AIRE ACONDICIONADO	11/07/2021		Corrective Order	WO Completed	Excavator
625481	Caterpillar 14M Motorgrader	Inspeccion AFEX	INSPECCION MENSUAL AFEX	11/07/2021		Corrective Order	WO Completed	Grader
625483	Caterpillar 14M Motorgrader	INSPECCION DE EQUIPO	REPARACION DE LUCES	11/07/2021		Corrective Order	WO Completed	Grader
625681	Hyster H800 32t Forklift (M)	Reemplazo de Bomba	REEMPLAZO DE BOMBITA DEL LIMPIAPARABRISAS	12/07/2021	90011693	Corrective Order	WO Completed	Forklift

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
625703	Caterpillar 416E	correccion de fuga hidraulica	FUGA HIDRAULICA	12/07/2021		Corrective Order	WO Completed	Backhoe
625705	Broce Broom RJT 350	Cebado de Sistema de diesel	EQUIPO AGARRO AIRE SE QUEDO SIN DIESEL	12/07/2021		Corrective Order	WO Completed	Scrubber / Sweeper
625739	Landcruiser DC	Cambio de 4 neumáticos	CAMBIO DE 4 NEUMÁTICOS	12/07/2021		Corrective Order	WO Completed	Pickup truck
625742	Caterpillar 14M Motorgrader	reparación de A/A	REPARACIÓN DE A/A Y CUCHILLA	12/07/2021		Corrective Order	WO Completed	Grader
625745	Toyota Hilux	REPARAR SISTEMA FRENO	CAMBIO ESTABILIZADORA	12/07/2021	90743	Corrective Order	WO Completed	Pickup truck
625759	Coaster	Cambio de dos neumáticos	CAMBIO DE DOS NEUMÁTICOS	12/07/2021		Corrective Order	WO Completed	Bus
625770	Manitou Mht-X1490 9t Telehand	Flat Llanta Delantera Izq.	FLAT LLANTA DELANTERA IZQ.	12/07/2021		Corrective Order	WO Completed	Telehender
625940	Caterpillar 735B	C/ LLANT POS 6 POR FLAT	CAMBIO DE LLANTA	12/07/2021		Corrective Order	WO Completed	Articulated dump truck
625973	Freightliner Columbia Cl112	REPAIR 2 FLAT TIRES	REPAIR 2 FLAT TIRES	12/07/2021		Corrective Order	WO Completed	Mule truck
625995	Caterpillar 735B	C/ FILTROS TRANSF TRANSMISION	ALARMA FILTRO OBSTRUIDO	12/07/2021		Corrective Order	WO Completed	Articulated dump truck
625996	Freightliner Columbia Cl112	ESCOBOLLA DE LIMPIA PARABRISAS	ESCOBOLLA DE LIMPIA PARABRISAS	12/07/2021		Corrective Order	WO Completed	Mule truck
626037	Freightliner 8170ME Water Truc	Fuga de aire d válvula	FUGA DE AIRE POR VÁLVULA DE CIERRE	12/07/2021		Corrective Order	WO Completed	Water truck
626039	Iveco 380t38	AIRE ACONDICIONADO	PROBLEMAS DE AIRE ACONDICIONADO	12/07/2021		Corrective Order	WO Completed	Bitumen truck
626040	Manitou Mht-X860 6t Telehand	CYL REPAIR (MASTER TECH)	CORRECTIVO	12/07/2021	50014488	Corrective Order	WO Completed	Telehender
626042	Caterpillar 236d Skid Steer L	INSTALACIÓN DE PISTON	INSTALACIÓN DE PISTON	12/07/2021		Corrective Order	WO Completed	Skid Steer
626045	Grove RT650E 45TON	PIN DE GIRO EN MAL ESTADO	PIN DE GIRO EN MAL ESTADO	12/07/2021		Corrective Order	WO Completed	Crane/Hoist
626048	Caterpillar 236d Skid Steer L	Reemplazo de lamparas	REEMPLAZO DE LAMPARAS	12/07/2021		Corrective Order	WO Completed	Skid Steer
626049	Caterpillar 236d Skid Steer L	Reemplazo de correas	REEMPLAZO DE CORREAS DEL MOTOR	12/07/2021		Corrective Order	WO Completed	Skid Steer
626050	Caterpillar 236d Skid Steer L	Inspeccion de equipo	REPARACION DE LIMPIAPARABRISAS	12/07/2021		Corrective Order	WO Completed	Skid Steer
626054	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/07/2021		Corrective Order	WO Completed	Pickup truck
626055	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	12/07/2021		Corrective Order	WO Completed	Pickup truck
626056	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/07/2021		Corrective Order	WO Completed	Bus
626057	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/07/2021		Corrective Order	WO Completed	Bus
626060	DOOSAND 1005	CORRECTIVO	CAMBIO DE BATERIA Y REVISION DE ALTERNADOR DC	12/07/2021	23760 hrs	Corrective Order	WO Completed	Light Tower
626063	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	APAGADO	12/07/2021	14041 hrs	Corrective Order	WO Completed	Generator
626283	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	13/07/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
626374	Intraax 53121 Hendrickso	reparacion de 2 llantas	LLANTAS FLAT	13/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
626375	Freightliner Columbia Cl112	reparacion de 2 llantas	LLANTAS FLAT	13/07/2021		Corrective Order	WO Completed	Mule truck
626434	Freightliner Cl 120	AJUSTE FRENOS	AJUSTE FRENOS	13/07/2021		Corrective Order	WO Completed	Mule truck
626449	Caterpillar 307E Miniexcavator	engrase general	GENERAL	13/07/2021		Corrective Order	WO Completed	Excavator
626470	Hilux DC	AJUSTE SISTEMA DE FRENOS	FRENO DE MANO Y SERVICIO	13/07/2021		Corrective Order	WO Completed	Pickup truck
626482	ATR-0000-001 4+320 AGRICO	Cambio de mangueras Hidraulico	MANGUERAS HIDRAULICOAS ROTAS	13/07/2021		Corrective Order	WO Completed	Tractor
626549	USP&E GP700/V-A 700 kVa	MOVIMIENTO DE EQUIPO	ARRANQUE E INSTALACION	13/07/2021	12745 HORAS	Corrective Order	WO Completed	Generator
626557	Trucks	FLAT TIRE +CHANGE TIRE	FLAT TIRE +CHANGE TIRE	13/07/2021		Corrective Order	WO Completed	Area
626602	T30D LINDE	CAMBIO CINTURON DE SEGURIDAD	CORRECTIVO	13/07/2021	90011836	Corrective Order	WO Completed	.
626616	Broce Broom RJT 350	NO AVANZA, NI SUBE EL CEPILLO	NO AVANZA, NI SUBE EL CEPILLO	13/07/2021		Corrective Order	WO Completed	Scrubber / Sweeper
626620	JLG 450 AJ Manlift	no realiza los movimiento	NO AVANZA	13/07/2021		Corrective Order	WO Completed	Manlift
626622	USP&E GP700S/V-A 700 kVa	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	13/07/2021	16023 HORAS	Corrective Order	WO Completed	Generator
626626	USP&E GP700S/V-A 700 kVa	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	13/07/2021	23430 HORAS	Corrective Order	WO Completed	Generator
626630	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	REVISION DE EQUIPO	13/07/2021	14041 HORAS	Corrective Order	WO Completed	Generator
626641	Gallegos Flatbed Trailer	INSP LUCES TRASERAS Y PINES	EVALAUCION GENERAL	13/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
626873	Caterpillar 236d Skid Steer L	piston roto	PISTON ROTO	14/07/2021		Corrective Order	WO Completed	Skid Steer
626896	Freightliner 8170ME Water Truc	LUCES DE REVERSA	LUCES DE REVERSA	14/07/2021		Corrective Order	WO Completed	Water truck
626897	Landcruiser DC	CAMBIO DE NEUMÁTICO	CAMBIO DE NEUMÁTICO	14/07/2021		Corrective Order	WO Completed	Pickup truck
626916	Caterpillar D8T Dozer	Tenzado de Cadena	TENZADO DE CADENA	14/07/2021		Corrective Order	WO Completed	Dozer
626917	Hyster H800 32t Forklift (M)	Problemas con las marchas	PROBLEMAS CON LAS MARCHAS	14/07/2021		Corrective Order	WO Completed	Forklift
627099	Landcruiser DC	REEMPLAZO DE 1 LLANTA	REEMPLAZO DE 1 LLANTA	14/07/2021		Corrective Order	WO Completed	Pickup truck
627121	Grove GMK 4080 80TON	CAMBIO DE MANGUERA	CAMBIO DE MANGUERA	14/07/2021		Corrective Order	WO Completed	Crane/Hoist
627239	SITE SERVICES	Fabricacion de Orejas para man	FABRICACION DE OREJAS PARA MAN	14/07/2021	2021W29	Corrective Order	WO Completed	Area
627241	SITE SERVICES	Soldar orejas a mantos	SOLDAR OREJAS A MANTOS	14/07/2021	2021W29	Corrective Order	WO Completed	Area
627250	Hilux DC	A/C INSPECTION & REPAIR	REPARACION DE A/A	14/07/2021		Corrective Order	WO Completed	Pickup truck
627252	Caterpillar CS74 Compactor	TA1 EQUIPO FUERA SERVICIO	PERSONAL DE IASA	14/07/2021	90010281 900010215 90010975	Corrective Order	WO Completed	Compactor
627385	Manitou MTH-X 10120	LHS REAR MIRROR REPLACEMENT	CORRECTIVE	14/07/2021	50014483	Corrective Order	WO Completed	Telehender
627432	Ferrari F478	SPREADER LIGHTS REPLACEMENT	CORRECTIVE	14/07/2021	50014487	Corrective Order	WO Completed	Reach Stacker
627458	Caterpillar 226b Skid Steer L	REPARACION MAYOR (IIASA)	ENVIADO A IASA	14/07/2021	50014535 50015448	Corrective Order	WO Completed	Skid Steer
627463	Coaster Bus	cambio de 6 llantas	CAMBIO DE 6 LLANTAS	14/07/2021		Corrective Order	WO Completed	Bus
627465	John Deere 9370R Tractor	CAMBIO DE BATERÍAS	CAMBIO DE BATERÍAS	14/07/2021	AUTOCLOSED	Corrective Order	WO Completed	Tractor
627476	Caterpillar 416E	Manguera hidráulica	CONFECCIÓN DE MANGUERA HIDRÁULICA	14/07/2021		Corrective Order	WO Completed	Backhoe
627554	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	15/07/2021	96309	PM Orders	WO Completed	Pickup truck
627578	Freightliner M2 106 Sucker Tru	cambio de baterías	CAMBIO DE BATERÍAS	15/07/2021		Corrective Order	WO Completed	Sucker truck
627633	DOOSAN C185	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	15/07/2021	1888 horas	Corrective Order	WO Completed	Compressor
627652	Caterpillar 740B	C/ MANG HYD ENFRIAMIENTO FRENO	MANGUERA ROTA	15/07/2021		Corrective Order	WO Completed	Articulated dump truck
627654	Freightliner Columbia Cl112	ENGRASE	ENGRASE	15/07/2021		Corrective Order	WO Completed	Mule truck
627660	Kalmar	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	15/07/2021	50014521 50015066 50015086	Corrective Order	WO Completed	Telehender
627706	Caterpillar CS533E Compactor	BRUSH REPLACEMENT	CORRECTIVE	15/07/2021		Corrective Order	WO Completed	Compactor
627708	Caterpillar CS533E Compactor	MOTOR WIPER RPL	CORRECTIVE	15/07/2021	90010219	Corrective Order	WO Completed	Compactor
627710	Bomag BW219DH-4	ROLLER REPAIR	CORRECTIVE	15/07/2021		Corrective Order	WO Completed	Compactor

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
627714	Freightliner Cl 120	cambio de tercer brazo	CAMBIO DE TERCER BRAZO	15/07/2021	90010242	Corrective Order	WO Completed	Mule truck
627735	Freightliner Cl 120	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	15/07/2021		Corrective Order	WO Completed	Mule truck
627745	Caterpillar DE22E3 17.6 kVa	INSTALACIÓN Y PRUEBA	INSTALACIÓN Y PRUEBA	15/07/2021	14933 HRS	Corrective Order	WO Completed	Generator
627746	Caterpillar DE22E3 17.6 kVa	CAMBIO DE VOLTAJE	CAMBIO DE VOLTAJE	15/07/2021	14933 HRS	Corrective Order	WO Completed	Generator
627782	Freightliner M2 112 Sucker Tru	fabricar rmangueras	FABRICAR MANGUERAS	15/07/2021		Corrective Order	WO Completed	Sucker truck
627801	Freightliner Cl 120	FUGA DE COOLANT	FUGA DE COOLANT	15/07/2021		Corrective Order	WO Completed	Mule truck
627836	Hilux DC	lavado de auto	LAVADO DE AUTO	15/07/2021		Corrective Order	WO Completed	Pickup truck
627858	Freightliner 8170ME Water Truc	AFTERCOOLER INSTALLING	CORRECTIVE	15/07/2021		Corrective Order	WO Completed	Water truck
627915	SDMO J60U 60 kVa	EMERGENCY CALL	INSPECTION AND EVALUATION	15/07/2021	5568 HRS	Corrective Order	WO Completed	Generator
627940	Gallegos 28M3 Lime Tank	PATAS DEFECTUOSAS	PATAS DEFECTUOSAS	15/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
627946	Freightliner Cl 120	BANDAS Y RATCHERS	BANDAS Y RATCHERS	15/07/2021		Corrective Order	WO Completed	Mule truck
627951	Freightliner Columbia Cl112	LUZ PILTO QUEMADA	LUZ PILTO QUEMADA	15/07/2021		Corrective Order	WO Completed	Mule truck
627954	Freightliner Columbia Cl112	RETROVISOR IZQUIERDO ROTO	RETROVISOR IZQUIERDO ROTO	15/07/2021	70787.6 km	Corrective Order	WO Completed	Mule truck
627958	Freightliner Columbia Cl112	LUZ ESCOLTA Y PILOTOS	LUZ ESCOLTA Y PILOTOS	15/07/2021		Corrective Order	WO Completed	Mule truck
627962	Freightliner Columbia Cl112	LUZ ESCOLTA Y PILOTOS	LUZ ESCOLTA Y PILOTOS	15/07/2021		Corrective Order	WO Completed	Mule truck
627963	Intraax 53121 Hendrickso	Cambio de luces traseras	INSPECCION GENERAL	15/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
627967	Hilux DC	CAMBIO ALARMA RETROCESO	DAÑO CLAXON Y ALARMA DE RETROCESO	15/07/2021	3753	Corrective Order	WO Completed	Pickup truck
627974	Freightliner Columbia Cl112	RETROVISOR IZQ / DER ROTOA	RETROVISOR IZQ / DER ROTOA	15/07/2021		Corrective Order	WO Completed	Mule truck
627990	Freightliner M112 Truck Tip	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	15/07/2021		Corrective Order	WO Completed	Tipper
627998	Unimog Service Truck	CAMBIO DE RADIADOR	CAMBIO DE RADIADOR	15/07/2021	730751	Corrective Order	WO Completed	Truck
628054	Grove RT880E 75TON	CERTIFICACION EQUIPO IZAJE	CERTIFICACION ANUAL EXTERNA	16/07/2021		PM Orders	WO Completed	Crane/Hoist
628224	Freightliner M2 106 Sucker Tru	INSPECCIÓN DE SEGURIDAD	INSPECCION DE SEGURIDAD	16/07/2021		Corrective Order	WO Completed	Sucker truck
628229	Caterpillar 226b Skid Steer L	cambio de 2 neumáticos	CAMBIO DE DOS NEUMÁTICOS	16/07/2021		Corrective Order	WO Completed	Skid Steer
628233	Freightliner M112 Truck Tip	Llanta flat	LLANTA FLAT	16/07/2021		Corrective Order	WO Completed	Tipper
628239	Gallegos Flatbed Trailer	INSPECCION DE PINES Y NEUMATIC	EVALAUACION GENERAL	16/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
628256	Gallegos 28M3 Lime Tank	PATAS DEFECTUOSAS	PATAS DEFECTUOSAS	16/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
628259	Freightliner Cl 120	FUGA DE AIRE	FUGA DE AIRE	16/07/2021		Corrective Order	WO Completed	Mule truck
628261	Freightliner Cl 120	REPAIR 2 FLAT TIRES	REPAIR 2 FLAT TIRES	16/07/2021		Corrective Order	WO Completed	Mule truck
628271	Manitou Mht-X1490 9t Telehand	ACEITE DE MOTOR BAJO	ACEITE DE MOTOR BAJO	16/07/2021		Corrective Order	WO Completed	Telehender
628277	Caterpillar 12M Motorgrader	Inspección Mensual de AFEX	INSPECCIÓN MENSUAL DE AFEX	16/07/2021		Corrective Order	WO Completed	Grader
628279	Landcruiser DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	16/07/2021	31406 kms	Corrective Order	WO Completed	Pickup truck
628281	Freightliner Cl 120	MANGUERAS DECAIRE- REMOLQUE	MANGUERAS DECAIRE- REMOLQUE	16/07/2021		Corrective Order	WO Completed	Mule truck
628298	Landcruiser TC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	16/07/2021		Corrective Order	WO Completed	Pickup truck
628356	Caterpillar 735B	735D-MAINTENANCE - 2000HRS-PM4	735D-MAINTENANCE - 2000HRS-PM4	16/07/2021		PM Orders	WO Completed	Articulated dump truck
628435	Coaster	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	16/07/2021		Corrective Order	WO Completed	Bus
628473	Caterpillar 226b Skid Steer L	INSP HERRAMIENTA DESGASTE	INSPECCION EQUIPO IASA	16/07/2021		Corrective Order	WO Completed	Skid Steer
628486	SDMO J60U 60 kVa	EMERGENCY CALL	LOW FUEL LEVEL	16/07/2021	5568 HRS	Corrective Order	WO Completed	Generator
628554	Mercedes Tipper Truck	INSPECCION DE EQUIPO	INSPECCION DE EQUIPO	16/07/2021		Corrective Order	WO Completed	Tipper
628600	Waker Neuson RD27-100 Compacto	INSPECCION LEVANTAMIENTO INFO	LEVANTAMIENTO DE INFORMACION	16/07/2021		Corrective Order	WO Completed	Compactor
628606	JLG 450 AJ Manlift	INSPECCION GENERAL EQUIPO	LEVANTAMIENTO DE INFORMACION	16/07/2021		Corrective Order	WO Completed	Manlift
628814	PRAMAC GBW15 14 kVa	PREVENTIVE MAINTENANCE	OIL AND FILTERS REPLACE	17/07/2021	23349 HRS	Corrective Order	WO Completed	Generator
628820	Freightliner Cl 120	Luz de check activada	ACEITE Y RESPIRADERO	17/07/2021		Corrective Order	WO Completed	Mule truck
628831	Freightliner Columbia Cl112	BATERIAS EN MALAS CONDICIONES	BATERIAS EN MALAS CONDICIONES	17/07/2021		Corrective Order	WO Completed	Mule truck
628841	Caterpillar 740B	C/ MNGUERA DE REFRIGERANTE	FUGA DE REFRIGERANTE	17/07/2021		Corrective Order	WO Completed	Articulated dump truck
628857	Freightliner M2 106 Sucker Tru	Fabricación de cuña de de 3/8	FABRICACIÓN DE CUÑA DE DE 3/8	17/07/2021	2021BD28	Corrective Order	WO Completed	Sucker truck
628858	John Deere 9370R Tractor	Operador para instalar Impleme	OPERADOR PARA INSTALAR IMPLEME	17/07/2021	SOPORTE W28	Corrective Order	WO Completed	Tractor
628877	Hilux DC	Kit de cambio de llanta	SIN KIT DE CAMBIO DE LLANTA	17/07/2021		Corrective Order	WO Completed	Pickup truck
628884	Freightliner Cl 120	FUGA DE AIRE	FUGA DE AIRE	17/07/2021		Corrective Order	WO Completed	Mule truck
628908	Freightliner Cl 120	SOLDAR EL MOFLE	SOLDAR EL MOFLE	17/07/2021		Corrective Order	WO Completed	Mule truck
628911	Caterpillar 740b Ej	C/ TUBERIA ENFRIADOR TX	FUGA POR TUBERIA	17/07/2021		Corrective Order	WO Completed	Articulated dump truck
628977	Caterpillar 735B	INSPECCION ANUAL AFEX	INSPECCION ANUAL AFEX	17/07/2021		PM Orders	WO Completed	Articulated dump truck
629005	Grove RT700E 60TON	FUGA HIDRAULICA	FUGA HIDRAULICA	17/07/2021		Corrective Order	WO Completed	Crane/Hoist
629010	Freightliner M2 112 Sucker Tru	Reparar fuga hidraulica	REPARAR FUGA HIDRAULICA	17/07/2021		Corrective Order	WO Completed	Sucker truck
629024	Hyster E70xn 3t Forklift (E)	revision de banco de bateria	REVISION DE BANCO DE BATERIA	17/07/2021		Corrective Order	WO Completed	Forklift
629026	Landcruiser DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	17/07/2021		Corrective Order	WO Completed	Pickup truck
629053	Mobile equipment	CONSUMIBLES ELECTRICOS FUSIBLE	MES DE JULIO	17/07/2021	90010338	Corrective Order	WO Completed	Area
629076	Caterpillar 740B	C/ RETROVISOR	RETROVISOR EN MAL ESTADO	17/07/2021		Corrective Order	WO Completed	Articulated dump truck
629122	Caterpillar 226b Skid Steer L	Reparación del Balde	REPARACIÓN DEL BALDE	17/07/2021		Corrective Order	WO Completed	Skid Steer
629132	Landcruiser DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	17/07/2021		Corrective Order	WO Completed	Pickup truck
629158	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE DOS NEUMÁTICOS	18/07/2021		Corrective Order	WO Completed	Pickup truck
629160	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE DOS NEUMÁTICOS	18/07/2021		Corrective Order	WO Completed	Pickup truck
629216	Coaster	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE DOS NEUMÁTICOS	18/07/2021		Corrective Order	WO Completed	Bus
629300	Grove RT600E 50TON	TERMINAL DE DIRECCIÓN ROTO	TERMINAL DE DIRECCIÓN ROTO	18/07/2021		Corrective Order	WO Completed	Crane/Hoist
629317	PRAMAC GSW110P 82 kVa	RADIATOR WASH	CORRECTIVE MAINTENANCE	18/07/2021	13102 HRS	Corrective Order	WO Completed	Generator
629319	Caterpillar D110 E2 100KVA	RADIATOR WASH	CORRECTIVE MAINTENANCE	18/07/2021	16332 HRS	Corrective Order	WO Completed	Generator
629320	Freightliner Cl 120	FUGA DE AIRE Y A/A	FUGA DE AIRE Y PROBLEMAS DE AIRE ACONDICIONADO	18/07/2021		Corrective Order	WO Completed	Mule truck
629321	SDMO J60U 60 kVa	RADIATOR WASH	CORRECTIVE MAINTENANCE	18/07/2021	5612 HRS	Corrective Order	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
629322	SDMO J60U 60 kVa	RADIATOR WASH	CORRECTIVE MAINTENANCE	18/07/2021 23914 hrs		Corrective Order	WO Completed	Generator
629340	SDMO J30U 38 kVa	EMERGENCY CALL	INAPECTION AND EVALUATION	18/07/2021 12339 HRS		Corrective Order	WO Completed	Generator
629350	Freightliner M2 106 Sucker Tru	Fabricacion de pieza de acople	FABRICACION DE PIEZA DE ACOPL	18/07/2021		Corrective Order	WO Completed	Sucker truck
629401	Hino Series 300 Truck	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	18/07/2021		Corrective Order	WO Completed	Truck
629425	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 24300 horas		PM Orders	WO Completed	Generator
629427	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 29095 horas		PM Orders	WO Completed	Generator
629428	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 27526 hrs		PM Orders	WO Completed	Generator
629431	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 23592 hrs		PM Orders	WO Completed	Generator
629432	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 23265 hrs		PM Orders	WO Completed	Generator
629434	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 20957 horas		PM Orders	WO Completed	Generator
629436	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 11269 hrs		PM Orders	WO Completed	Generator
629437	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 6945 hrs		PM Orders	WO Completed	Generator
629438	Caterpillar 300.9D MicoExcavat	Cambio de luces	CAMBIO DE LUCES	18/07/2021		Corrective Order	WO Completed	Excavator
629453	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 35602 horas		Corrective Order	WO Completed	Light Tower
629454	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 22553 horas		Corrective Order	WO Completed	Light Tower
629456	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 23943 horas		Corrective Order	WO Completed	Light Tower
629459	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 264 HORAS		Corrective Order	WO Completed	Light Tower
629460	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 344 hrs		Corrective Order	WO Completed	Light Tower
629461	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 208 hrs		Corrective Order	WO Completed	Light Tower
629463	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 318 horas		Corrective Order	WO Completed	Light Tower
629466	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 318 hrs		Corrective Order	WO Completed	Light Tower
629467	ATLAS COPCO HILIGHT V5+	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	18/07/2021 295 hrs		Corrective Order	WO Completed	Light Tower
629477	Caterpillar D110 E2 100KVA	CAMBIO DE VOLTAJE A 480V	MANTENIMIENTO CORRECTIVO	18/07/2021 15968 HORS		Corrective Order	WO Completed	Generator
629478	Caterpillar D110 E2 100KVA	EVALUACION Y SOLUCION DE FALLA	MANTENIMIENTO CORRECTIVO	18/07/2021 2729 horas		Corrective Order	WO Completed	Generator
629491	SDMO J30U 38 kVa	CAMBIO DE VOLTAJE	MANTENIMIENTO CORRECTIVO	18/07/2021 12339 HRS		Corrective Order	WO Completed	Generator
629498	Gallegos Lime Tank	FUGA Y TORNILLOS	FUGA Y TORNILLOS	18/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
629502	Eagle Beaver 50sgl-Pt	PATIN	PATIN	18/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
629544	Caterpillar 740B	C/ TAPA FILTRO ELEMENTO	TAPA DAÑADA	18/07/2021		Corrective Order	WO Completed	Articulated dump truck
629604	PB002 COASTER TOYOTA	INSPECCIÓN GENERAL	INSPECCIÓN GENERAL	18/07/2021		Corrective Order	WO Completed	Bus
629709	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/07/2021 16384 horas		PM Orders	WO Completed	Generator
629736	Freightliner Cl 120	REPARACIÓN DEL MOTOR DE ARRANQ	REPARACIÓN DEL MOTOR DE ARRANQUE	19/07/2021		Corrective Order	WO Completed	Mule truck
629745	Bell 225f 4t Forklift (M)	no enciende	NO ENCIENDE	19/07/2021		Corrective Order	WO Completed	Forklift
629780	Hilux DC	Cambio de llantas	CAMBIO DE 2 LLANTAS	19/07/2021		Corrective Order	WO Completed	Pickup truck
629802	Hilux DC	Cambio de 1 llantas	CAMBIO DE LLANTAS	19/07/2021		Corrective Order	WO Completed	Pickup truck
629808	Caterpillar D110 E2 100KVA	LAVADO GENERAL	MANTENIMIENTO CORRECTIVO	19/07/2021 16621 HRS		Corrective Order	WO Completed	Generator
629810	Manitou Mht-X1490 9t Telehand	SE SALIO LA MANGUERA	SE SALIO LA MANGUERA	19/07/2021		Corrective Order	WO Completed	Telehender
629923	Freightliner Columbia Cl112	LUZ ESCOLTA	LUZ ESCOLTA	19/07/2021		Corrective Order	WO Completed	Mule truck
629936	Freightliner Columbia Cl112	POLLERA / ESPEJO /TRANSMISION	POLLERA / ESPEJO /TRANSMISION	19/07/2021		Corrective Order	WO Completed	Mule truck
629957	Caterpillar RM500 Reclaimer	PM01-PREVENTIVE MAINTENANCE	OIL AND FILTER REPLACEMENT	19/07/2021		Corrective Order	WO Completed	Road Reclaimer
629975	Freightliner Cl 120	ESCOBILLAS	ESCOBILLAS	19/07/2021		Corrective Order	WO Completed	Mule truck
630014	Hilux DC	Cambio de llanta	CAMBIO DE 1 LLANTA	19/07/2021		Corrective Order	WO Completed	Pickup truck
630018	Freightliner Cl 120	FUGA/FAN CLUTCH/ BASES/MOFLE	FUGA/FAN CLUTCH/ BASES/MOFLE	19/07/2021		Corrective Order	WO Completed	Mule truck
630024	Freightliner Cl 120	EVALUAR BASES DE MOTOR	BASES DE MOTOR/ MOFLE ROTO	19/07/2021		Corrective Order	WO Completed	Mule truck
630038	USP&E GP700/V-A 700 kVa	LLAMADA DE EMERGENCIA	EQUIPO DETENIDO	19/07/2021 10312 hrs		Corrective Order	WO Completed	Generator
630051	Freightliner Columbia Cl112	Reparacion de llantas	REPARACION DE LLANTAS	19/07/2021		Corrective Order	WO Completed	Mule truck
630053	Intraax 53121 Hendrickso	LLANTA PARA REPARAR	LLANTA PARA REPARAR	19/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
630054	Freightliner Cl 120	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	19/07/2021		Corrective Order	WO Completed	Mule truck
630060	Gallegos Flatbed Trailer	INSP MANGUERAS / PULMON/PINES	EVALUACION GENERAL	19/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
630063	Gallegos Flatbed Trailer	INSP FRENOS,LUCES,PINES	BANDAS / LUCES /OVERHALL FRENO	19/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
630084	Gallegos 28M3 Lime Tank	FUGA + FLAT	FUGA + FLAT	19/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
630102	PRAMAC GSW560V 407 kVa	TRASLADO DE EQUIPO	ALTERNADOR AC	19/07/2021		Corrective Order	WO Completed	Generator
630357	Hilux DC	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	20/07/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
630430	Caterpillar D8T Dozer	TORNILLO DE RUEDA GUIA	TORNILLO DE RUEDA GUIA	20/07/2021		Corrective Order	WO Completed	Dozer
630447	New Holland Lm 1745	Telehandler de molinos 6291	TELEHANDLER DE MOLINOS 6291	20/07/2021		Corrective Order	WO Completed	Telehender
630450	Grove RT600E 50TON	Fan No enciende, Pantalla, Luc	FAN DEL ENFRIADOR HIDRÁULICO NO ENCIENDE, PANTALLA DAÑADA, LUCES	20/07/2021		Corrective Order	WO Completed	Crane/Hoist
630451	Hyster H700 Forklift	PROBLEMAS DE A/A	PROBLEMAS DE A/A	20/07/2021		Corrective Order	WO Completed	Forklift
630453	Caterpillar CS74 Compactor	Manguera hidráulica Rota	MANGUERA HIDRÁULICA ROTA	20/07/2021		Corrective Order	WO Completed	Compactor
630506	Caterpillar CS74 Compactor	Cambio de mangueras hidraulica	CAMBIO DE MANGUERAS HIDRAULICAS	20/07/2021		Corrective Order	WO Completed	Compactor
630526	PRAMAC GSW170i 164 kVa	CAMBIO DE VOLTAJE	MANTO CORRECTIVO	20/07/2021 5389 HRS		Corrective Order	WO Completed	Generator
630607	WT013 H7 CISTERNA SINOTRUK	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	20/07/2021		Corrective Order	WO Completed	Water truck
630614	Caterpillar 740b Ej	C/ SENSOR INERCIAL	SENSOR INERCIAL FISURADO	20/07/2021		Corrective Order	WO Completed	Articulated dump truck
630616	Freightliner Cl 120	POLLERA / FUGA DE AIRE	POLLERA / FUGA DE AIRE	20/07/2021		Corrective Order	WO Completed	Mule truck
630724	Caterpillar 336DL Excavator	FABRICACION BALDE NUEVO	BALDE DE REEMPLAZO	20/07/2021 60021124		Corrective Order	WO Completed	Excavator
630821	Caterpillar 740b Ej	C/ BEARING FRAME CENTRAL	BEARING DESGASTADO	20/07/2021		Corrective Order	WO Completed	Articulated dump truck
631137	Caterpillar RM500 Reclaimer	confección de Manguera	CONFECCIÓN DE MANGUERA	21/07/2021		Corrective Order	WO Completed	Road Reclaimer
631230	Freightliner Cl 120	FUGA Y JUSTE DE FRENOS/PUERTA	FUGA Y JUSTE DE FRENOS	21/07/2021		Corrective Order	WO Completed	Mule truck
631234	Gallegos Lime Tank	REP. DE FRENOS / PATAS	REP. DE FRENOS / PATAS	21/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
631302	PRAMAC GSW560V 407 kVa	AJUSTES OPERACIONALES	MANTENIMIENTO CORRECTIVO	21/07/2021	17919 HRS	Corrective Order	WO Completed	Generator
631304	Freightliner M112 Truck Tip	Soporte de guarda fango roto	SOPORTE DE GUARDA FANGO ROTO	21/07/2021		Corrective Order	WO Completed	Tipper
631315	PRAMAC GSW560V 407 kVa	CONFIGURACION DE VOLTAJE	MANTENIMIENTO CORRECTIVO	21/07/2021	14065 HRS	Corrective Order	WO Completed	Generator
631322	Caterpillar 426f2 Backhoe	FABRICACION MANGUERA HDRAULICA	PARA IASA / CEMAN / SONCAR	21/07/2021		Corrective Order	WO Completed	Backhoe
631334	Freightliner CI 120	Cambio de v/v Parking brake	PARKING BRAKE DE TRAINER NO LINEA	21/07/2021		Corrective Order	WO Completed	Mule truck
631537	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	22/07/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
631606	SDMO T16 16KVA	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	22/07/2021	22767 horas	Corrective Order	WO Completed	Generator
631630	Caterpillar 236d Skid Steer L	Cambio de 2 lanta	CAMBIO DE 2 LLANTA	22/07/2021		Corrective Order	WO Completed	Skid Steer
631656	Caterpillar 336DL	Se descarrilo una de las oruga	SE DESCARRILO UNA DE LAS ORUGA	22/07/2021		Corrective Order	WO Completed	Excavator
631684	Landcruiser DC	CAMBIO ALTERNADOR	MANTENIMIENTO CORRECTIVO	22/07/2021	44,229	Corrective Order	WO Completed	Pickup truck
631687	Landcruiser TC	CAMBIO EJE BALINERA	CAMBIO PUNTA FLECHA/TAMBOR FRENO	22/07/2021	54,972	Corrective Order	WO Completed	Pickup truck
631688	Landcruiser DC	REPARAR COCOBOLAS	CAMBIO TAMBOR	22/07/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Pickup truck
631691	Landcruiser DC	CAMBIO BASE AMORTIGUADOR	CAMBIO BANDAS/POLEA TENSORA	22/07/2021	73,424	Corrective Order	WO Completed	Pickup truck
631782	Mobile equipment	Oxigeno y acetileno taller	TANQUES DE OXIGENO Y ACETINELO VACIOS EN TALLER	22/07/2021		Corrective Order	WO Completed	Area
631837	Caterpillar 416E	FABRICACION DE MANGUERAS	CAMBIO DE COMPONENTES	22/07/2021	AUTO CLOSED	Corrective Order	WO Completed	Backhoe
631839	Freightliner CI 120	FUGA COOLANT	FUGA COOLANT	22/07/2021		Corrective Order	WO Completed	Mule truck
631864	Caterpillar C9 250 kVa	CAMBIO CORREA BOMBA AGUA	CORRECTIVO PROGRAMADO	22/07/2021	19167 hrs	Corrective Order	WO Completed	Generator
631934	Caterpillar 735B	C/ MANG HYD ENFRIAMIENTO HITCH	MANGERAS DETERIORADAS	22/07/2021		Corrective Order	WO Completed	Articulated dump truck
631943	FG WILSON P88-3 80 kVa	EQUIPO SIN COMBUSTIBLE	COMBUSTIBLE BLOQUEADO	22/07/2021	24100 horas	Corrective Order	WO Completed	Generator
631953	SDMO T11UM 10KVA	EQUIPO NO GENERA	MANTENIMIENTO CORRECTIVO	22/07/2021	12489 horas	Corrective Order	WO Completed	Generator
631957	GROVE RT9130E 120TON	Problema con freno de winche	PROBLEMA CON FRENO DE WINCHE	22/07/2021		Corrective Order	WO Completed	Crane/Hoist
631963	PRAMAC GSW560V 407 kVa	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	22/07/2021	17921 horas	Corrective Order	WO Completed	Generator
631983	Caterpillar D110 E2 100KVA	EQUIPO SIN DIESEL	TOKEN DE COMBUSTIBLE BLOQUEADO	22/07/2021	16425 horas	Corrective Order	WO Completed	Generator
632410	Caterpillar 14M Motorgrader	Vidrio de la puerta derecha	VIDRIO DE LA PUERTA DERECHA	23/07/2021		Corrective Order	WO Completed	Grader
632422	Caterpillar 740b Ej	R&I TYRE POS 1	R&I TYRE POS 1	23/07/2021		PM Orders	WO Completed	Articulated dump truck
632425	Caterpillar 740b Ej	R&I TYRE POS 2	R&I TYRE POS 2	23/07/2021		PM Orders	WO Completed	Articulated dump truck
632515	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGEMNCIA	FALLO DE ALIMENTACION EN PETAQUILLA TOWER	23/07/2021	24804 horas	Corrective Order	WO Completed	Generator
632521	PRAMAC GSW560V 407 kVa	INPECCION DE EQUIPO	REVISION DE SINCRONISMO DE GENERADORES	23/07/2021	17949 horas	Corrective Order	WO Completed	Generator
632568	Case 110JX Tractor Cable Handl	INSPECCION GENERAL EQUIPO	PROBLEMAS HIDRAULICOS	23/07/2021		Corrective Order	WO Completed	Tractor
632590	Caterpillar 740B EJ ADT	Cambio de switch de presion	CAMBIO DE SWITCH DE PRESION	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632591	Caterpillar 740B EJ ADT	Cambio De Switch de presion	CAMBIO DE SWITCH DE PRESION	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632659	Caterpillar 740B EJ ADT	R&I Tires Pos 1	R&I TIRES POS 1	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632669	Caterpillar 740B EJ ADT	R&I Tires Pos 2	R&I TIRES POS 2	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632740	Caterpillar 740B EJ ADT	RESELLADO VALVULA CONT FRENO	CONTROL DE VALVULA CON FUGA	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632832	Caterpillar 735B	C/ FILTRO DE AIRE	FILTRO OBSTRUIDOS	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632847	Hino Serie 300 Box Truck	CAMBIO MOTOR DE ARRANQUE	SE ENCUENTRA PEGADO A LA VOLANTE	23/07/2021	50015041	Corrective Order	WO Completed	Truck
632871	Caterpillar 735B	C/ EJE CARDAN DEL HITCH	FISURA EN EJE CARDAN	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632900	Grove RT9130E 120TON	Falla de freno winche	FALLA DE FRENO WINCHE	23/07/2021		Corrective Order	WO Completed	Crane/Hoist
632909	Caterpillar 735B	C/ FILTRO TRASMISION TRANSFER	FILTROS OBTRUIDOS	23/07/2021		Corrective Order	WO Completed	Articulated dump truck
632945	SDMO J60U 60 kVa	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	23/07/2021	24047 HORS	Corrective Order	WO Completed	Generator
632947	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	78845	PM Orders	WO Completed	Pickup truck
632948	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	79438	PM Orders	WO Completed	Pickup truck
632950	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632951	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	60967 kms	PM Orders	WO Completed	Pickup truck
632953	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	57300	PM Orders	WO Completed	Pickup truck
632954	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	59230	PM Orders	WO Completed	Pickup truck
632955	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	79062	PM Orders	WO Completed	Pickup truck
632956	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632957	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	74938	PM Orders	WO Completed	Pickup truck
632959	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	69294	PM Orders	WO Completed	Pickup truck
632960	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	53406	PM Orders	WO Completed	Pickup truck
632961	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632962	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	44339	PM Orders	WO Completed	Pickup truck
632963	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632964	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	64483	PM Orders	WO Completed	Pickup truck
632965	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	86480	PM Orders	WO Completed	Pickup truck
632966	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	53861	PM Orders	WO Completed	Pickup truck
632967	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632968	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632969	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	58246	PM Orders	WO Completed	Pickup truck
632970	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	35114	PM Orders	WO Completed	Pickup truck
632971	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	62291	PM Orders	WO Completed	Pickup truck
632972	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	70099	PM Orders	WO Completed	Pickup truck
632973	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021	56401	PM Orders	WO Completed	Pickup truck
632974	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632975	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
632976	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632977	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632980	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632981	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632982	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632984	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632986	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 18019		PM Orders	WO Completed	Pickup truck
632987	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 18298		PM Orders	WO Completed	Pickup truck
632988	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 19424		PM Orders	WO Completed	Pickup truck
632989	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632990	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 19215		PM Orders	WO Completed	Pickup truck
632991	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632992	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Pickup truck
632993	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021		PM Orders	WO Completed	Bus
632994	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 28427		PM Orders	WO Completed	Bus
632996	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 88599		PM Orders	WO Completed	Pickup truck
632997	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/07/2021 100985		PM Orders	WO Completed	Pickup truck
633073	Ford 450	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	24/07/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
633080	Manitou Mht-X860 6t Telehand	CAMBIO DE BATERIAS Y SWITCH	CAMBIO DE BATERIAS Y TERMO SWITCH	24/07/2021		Corrective Order	WO Completed	Telehender
633116	Coaster	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	24/07/2021		Corrective Order	WO Completed	Bus
633117	Coaster	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE DOS NEUMÁTICOS	24/07/2021		Corrective Order	WO Completed	Bus
633132	Mercedes Tipper Truck	Sistema de Luces y dirección	TREN CORRIDO,SISTEMA DE LUCES, BOMBA DE DIDIRECCIÓN	24/07/2021		Corrective Order	WO Completed	Tipper
633180	PRAMAC GSW170i 164 kVa	CAMBIO DE VOLTAGE	CAMBIO DE 480 VOLTIOS A 400 VOLTIOS	24/07/2021 5393 horas		Corrective Order	WO Completed	Generator
633210	Caterpillar D110 E2 100KVA	LLAMADA DE EMERGENCIA	EQUIPO SE APAGA POR FRECUENCIA BAJA	24/07/2021 2730 horas		Corrective Order	WO Completed	Generator
633251	Gallegos Lime Tank	BARRA ROTA	BARRA ROTA	24/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
633268	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/07/2021		Corrective Order	WO Completed	Pickup truck
633302	Caterpillar 735B	C/ MOTOR WIPER	MOTOR NO GIRA	24/07/2021		Corrective Order	WO Completed	Articulated dump truck
633303	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/07/2021		Corrective Order	WO Completed	Pickup truck
633447	Freightliner Cl 120	VALVULA / A/A	VALVULA / A/A	24/07/2021		Corrective Order	WO Completed	Mule truck
633448	Caterpillar 140K	FABRICACION MANGUERAS	IIASA CENMAN / SONCAR	24/07/2021		Corrective Order	WO Completed	Grader
633488	Caterpillar 226b Skid Steer L	Cambio 1 llanta	CAMBIO 1 LLANTA	24/07/2021		Corrective Order	WO Completed	Skid Steer
633499	Freightliner 8170ME Water Truc	Tiene daño en el clutch,	TIENE DAÑO EN EL CLUTCH,	24/07/2021		Corrective Order	WO Completed	Water truck
633527	Caterpillar D110 E2 100KVA	CAMBIO DE GENERADOR	DESCONEXION, CONEXION Y CAMBIO DE VOLTAJE	24/07/2021 15968 horas		Corrective Order	WO Completed	Generator
633558	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 17009 hrs		PM Orders	WO Completed	Generator
633559	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 13481 hrs		PM Orders	WO Completed	Generator
633560	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 16741 hrs		PM Orders	WO Completed	Generator
633561	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 12511 horas		PM Orders	WO Completed	Generator
633562	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 13495 horas		PM Orders	WO Completed	Generator
633563	PRAMAC GSW80P 83 kVa	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 11227 hrs		PM Orders	WO Completed	Generator
633564	PRAMAC GSW120 120 kVa	PM PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 5945 horas		PM Orders	WO Completed	Generator
633565	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 16587 hrs		PM Orders	WO Completed	Generator
633566	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 31526 hora		PM Orders	WO Completed	Generator
633567	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 19460 horas		PM Orders	WO Completed	Generator
633568	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 19167 hrs		PM Orders	WO Completed	Generator
633570	FG WILSON P88-1 64 kVa	PM FGW P88-1 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 5851 horas		PM Orders	WO Completed	Generator
633571	SDMO J30U 38 kVa	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 12898 HORAS		PM Orders	WO Completed	Generator
633572	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 7430 hrs		PM Orders	WO Completed	Generator
633573	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/07/2021 36579 horas		PM Orders	WO Completed	Generator
633574	PRAMAC GSW90P 74 kVa	PM PRA GSW90P MEC 300 HR	PM PRA GSW90P MEC 300 HR	24/07/2021 25398 horas		PM Orders	WO Completed	Generator
633770	Intraax 53121 Hendrickso	INSPECCION GENERAL PINES	INSPECCION GENERAL DE EQUIPO	25/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
633794	Mobile equipment	Gas Refrigerante	GAS REFRRIGERANTE PARA TALLER	25/07/2021		Corrective Order	WO Completed	Area
633886	Caterpillar 226b Skid Steer L	Cambio de 2 llanta	CAMBIO DE 2 LLANTA	25/07/2021		Corrective Order	WO Completed	Skid Steer
633966	PRAMAC GSW110 82 kVa	EVALUACION/DIAGNOSTICO	LEVANTAMIENTO BACKLOGS	25/07/2021 839 horas		Corrective Order	WO Completed	Generator
634001	Gallegos Lime Tank	FUGA DE AIRE POR ESCOTILLA	FUGA DE AIRE POR ESCOTILLA	25/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
634004	Gallegos 28M3 Lime Tank	TUERCA / SOPORTE PATAS	TUERCA / SOPORTE PATAS	25/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
634005	Dossan	EVALUACION/DIAGNOSTICO	LEVANTAMIENTO BACKLOGS	25/07/2021 5833 hrs		Corrective Order	WO Completed	Generator
634010	Gallegos 28M3 Lime Tank	VALVULA	VALVULA	25/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
634015	Cummins C100D6 91KVA	EVALUACION/DIAGNOSTICO	LEVANTAMIENTO BACKLOGS	25/07/2021 6159 horas		Corrective Order	WO Completed	Generator
634096	DOOSAND 1005	LUCES NO ENCIENDEN	MANTENIMIENTO CORRECTIVO	25/07/2021 23958 horas		Corrective Order	WO Completed	Light Tower
634156	Caterpillar 740B EJ ADT	C/ MANG HYD DIRECCION	MANGUERA ROTA	25/07/2021		Corrective Order	WO Completed	Articulated dump truck
634211	Caterpillar 416E	Fuga de aceite hidráulico	FUGA DE ACEITE HIDRÁULICO	25/07/2021		Corrective Order	WO Completed	Backhoe
634249	Manitou Mht-X1490 9t Telehand	Leak Aceite - Manguera Turbo	LEAK ACEITE - MANGUERA TURBO	25/07/2021		Corrective Order	WO Completed	Telehender
634408	Mobile equipment	Elementos Afex Para Taller	ELEMENTOS AFEX PARA TALLER	25/07/2021		Corrective Order	WO Completed	Area
634719	PRAMAC GSW80P 83 kVa	CAMBIO DE VOLTAJE A 480/277	CAMBIO DE VOLTAJE A 480/277	26/07/2021 6450 horas		Corrective Order	WO Completed	Generator
634726	Unimog Service Truck	FALLA EN DIRECCION DE UMT07	FALLA EN DIRECCION DE UMT07	26/07/2021		Corrective Order	WO Completed	Truck
634744	JLG 800 AJ Manlift	Cambio de mangueras hidraulico	CAMBIO DE MANGUERAS HIDRAULICO	26/07/2021		Corrective Order	WO Completed	Manlift

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
634768	Freightliner CI 120	Cambio de 1 pulmon	CAMBIO DE 1 PULMON	26/07/2021		Corrective Order	WO Completed	Mule truck
634777	Manitou Mht-X1490 9t Telehand	fuga de aie por turno	FUGA POR AREA DE TURNO	26/07/2021		Corrective Order	WO Completed	Telehender
634863	John Deere 9370R Tractor	Reparacion	REPARACION	26/07/2021		Corrective Order	WO Completed	Tractor
634867	Mobile equipment	Insumos para taller	INSUMOS PARA TALLER	26/07/2021		Corrective Order	WO Completed	Area
634904	Caterpillar 12M	Aire acondicionado	AIRE ACONDICIONADO	26/07/2021		Corrective Order	WO Completed	Grader
634933	USP&E GP700/V-A 700 kVa	INSPECCION & ARRANQUE	PRUEBA DE FUNCIONAMIENTO	26/07/2021 8643 horas		Corrective Order	WO Completed	Generator
635000	JLG 1250 AJP Manlift	Cambio de manguera hidráulica	CAMBIO DE MANGUERA	26/07/2021		Corrective Order	WO Completed	Manlift
635001	Coaster	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	26/07/2021		Corrective Order	WO Completed	Bus
635246	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	27/07/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
635400	JLG 1850 AJ Manlift	Equipo No arranca	EQUIPO NO ARRANCA	27/07/2021		Corrective Order	WO Completed	Manlift
635437	Caterpillar 740B EJ ADT	C/ MANG HYD DE FRENO	MANGUERA ROTA	27/07/2021		Corrective Order	WO Completed	Articulated dump truck
635505	Freightliner Columbia CI112	BRAZO DE DIRECCION	BRAZO DE DIRECCION	27/07/2021 90010835		Corrective Order	WO Completed	Mule truck
635506	Manitou Mht-X1490 9t Telehand	THM-103 Frenos muy ajustados	THM-103 FRENOS MUY AJUSTADOS	27/07/2021		Corrective Order	WO Completed	Telehender
635518	Power Curbers 5700-C	Problema en la dirección	PROBLEMA EN LA DIRECCIÓN	27/07/2021		Corrective Order	WO Completed	Kerb Machine
635524	Caterpillar 416E	Manguera rota de aceite hidráu	MANGUERA ROTA DE ACEITE HIDRÁU	27/07/2021		Corrective Order	WO Completed	Backhoe
635558	PRAMAC GSW460V 460 kVa	LAVADO DE RADIADOR Y MOTOR	MANTENIMIENTO CORRECTIVO	27/07/2021 12940 hrs		Corrective Order	WO Completed	Generator
635559	PRAMAC GSW460V 460 kVa	INSTALACION DE ALTERNADOR AC	MANTENIMIENTO CORRECTIVO	27/07/2021 12940 hrs		Corrective Order	WO Completed	Generator
635574	Gallegos 28M3 Lime Tank	LLANTA FLAT / LUCES	LLANTA FLAT / LUCES	27/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
635638	Mobile equipment	BOMBAS SISTEMA LUBRICACION	BOMBAS D ETALLER	27/07/2021		Corrective Order	WO Completed	Area
635643	PRAMAC GSW90P 74 kVa	CAMBIO BOMBA AGUA	FUGA REFRIGERANTE	27/07/2021 25398 HORAS		Corrective Order	WO Completed	Generator
635644	Caterpillar 740B	C/ PEDAL DE ACELERADOR	PEDAL MANTIENE FALLA	27/07/2021		Corrective Order	WO Completed	Articulated dump truck
635645	Coaster	Cambio de 6 llantas	LLANTAS EN MAL ESTADO	27/07/2021		Corrective Order	WO Completed	Bus
635650	Caterpillar 740B EJ ADT	C/ FILTRO SECADOR AIRE ACOND	FILTRO SECADOR OBSTRUIDO	27/07/2021		Corrective Order	WO Completed	Articulated dump truck
635653	Caterpillar 740B EJ ADT	C/ ESPEJO RETROVISOR	RETROVISOR DEFECTUOSO	27/07/2021		Corrective Order	WO Completed	Articulated dump truck
635661	Freightliner M2 112 Sucker Tru	Reemplazo de mangueras	REEMPLAZO DE MANGUERAS	27/07/2021		Corrective Order	WO Completed	Sucker truck
635718	Power Curbers 5700-C	Maguera hidráulica	MAGUERA HIDRÁULICA	27/07/2021		Corrective Order	WO Completed	Kerb Machine
635726	Coaster	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	27/07/2021		Corrective Order	WO Completed	Bus
635728	Pramac GSW25P 17KVA	CAMBIO RETENEDORA POSTERIOR	FUGA DE ACEITE	27/07/2021 4945 horas		Corrective Order	WO Completed	Generator
635737	Caterpillar 320DL	No enciende	NO ENCIENDE	27/07/2021		Corrective Order	WO Completed	Excavator
635752	Mobile equipment	ACEITE 15W40 GENSET - AGOSTO	CONSUMO AGOSTO	27/07/2021 CERRADO POR PLANEAMIENTO		Corrective Order	WO Completed	Area
635756	Caterpillar 236d Skid Steer L	Reparacion de fuga de aceite	REPARACION DE FUGA DE ACEITE	27/07/2021		Corrective Order	WO Completed	Skid Steer
635762	Caterpillar D8T Dozer	Cambio de componentes	CAMBIO DE COMPONENTES	27/07/2021		Corrective Order	WO Completed	Dozer
635767	Caterpillar 226b Skid Steer L	fuga de aceite	FUGA DE ACEITE	27/07/2021		Corrective Order	WO Completed	Skid Steer
635801	Caterpillar CS74 Compactor	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO IASA	27/07/2021		Corrective Order	WO Completed	Compactor
635823	Grove GMK 4080 80TON	Equipo Bloqueado	EQUIPO BLOQUEADO	27/07/2021		Corrective Order	WO Completed	Crane/Hoist
635824	John Deere 9370R Tractor	Codigo activo	CODIGO ACTIVO	27/07/2021		Corrective Order	WO Completed	Tractor
635825	JLG 1250 AJP Manlift	Revision de sensor de Inclínac	EQUIPO BLOQUEADO	27/07/2021		Corrective Order	WO Completed	Manlift
635826	Caterpillar 226b Skid Steer L	reparacion de llanta	LLANTA FLAT	27/07/2021		Corrective Order	WO Completed	Skid Steer
636106	Faresin FM4000 / 17F Telehandl	revicion del sistema de freno	REVICION DEL SISTEMA DE FRENO	28/07/2021		Corrective Order	WO Completed	Telehender
636125	PRAMAC GSW120 120 kVa	CAMBIO BOMBA AGUA	FUGA DE REFRIGERANTE	28/07/2021 6041 horas		Corrective Order	WO Completed	Generator
636167	Caterpillar 14M Motorgrader	Reemplazo de vidrio	REEMPLAZO DE VIDRIO	28/07/2021		Corrective Order	WO Completed	Grader
636177	Mobile equipment	FRENO JCB 6291 MAL ESTADO	FRENO JCB 6291 MAL ESTADO	28/07/2021		Corrective Order	WO Completed	Area
636189	Caterpillar 416F2 Backhoe	Reemplazo de bateria	REEMPLAZO DE BATERIA	28/07/2021		Corrective Order	WO Completed	Backhoe
636194	JLG 1250 AJP Manlift	Boom control system warning	CANASTA BLOQUEADA, NO DEJA OPERAR	28/07/2021		Corrective Order	WO Completed	Manlift
636219	Power Curbers 5700-C	Reemplazo de manguera hidrauli	REEMPLAZO DE MANGUERA HIDRAULICA	28/07/2021		Corrective Order	WO Completed	Kerb Machine
636359	Caterpillar 236d Skid Steer L	Reemplazo de manguera	REEMPLAZO DE MANGUERA HIDRAULICA	28/07/2021		Corrective Order	WO Completed	Skid Steer
636375	Caterpillar 740b Ej	C/ BEARING CYL LEVANT RH LH	BEARING CON DESGASTE	28/07/2021		Corrective Order	WO Completed	Articulated dump truck
636428	Caterpillar 307E Miniexcavator	Cambio de sellos	FUGA DE SISTEMA HIDRAULICO	28/07/2021		Corrective Order	WO Completed	Excavator
636432	Caterpillar 307E Miniexcavator	colocacion de diente	DIENTE SUELTO	28/07/2021		Corrective Order	WO Completed	Excavator
636433	Toyota Land Cruiser	INSTALAR CAMILLAS	MANTENIMIENTO MEJORATIVO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636435	Toyota Hilux	INSTALAR CAMILLAS	MANTENIMIENTO MEJORATIVO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636491	Coaster	Cambio de 2 llantas	LLANTAS EN MAL	28/07/2021		Corrective Order	WO Completed	Bus
636496	Landcruiser TC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636498	Hilux DC	Cambio de 2 llantas	LLANTAS EN MAL ESTADO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636499	Hilux DC	Cambio de 2 llantas	LLANNTAS EN MAL ESTADO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636505	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	28/07/2021		Corrective Order	WO Completed	Pickup truck
636541	Caterpillar D110 E2 110 kVa	CAMBIO CONEXION REFRIGERANTE	FUGA REFRIGERANTE	28/07/2021 17527 hrs		Corrective Order	WO Completed	Generator
636557	Freightliner M112 Truck Tip	Instalacion de Estribo	INSTALACION DE ESTRIBO	28/07/2021		Corrective Order	WO Completed	Tipper
636558	Gallegos 28M3 Lime Tank	Rep. de brazo de valvula	BRAZO DE VALVULA DAÑADA	28/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
636559	Manitou Mht-X1490 9t Telehand	Colocacion de manguera del tur	FUERA DE POSICION DE MANGUERA DEL TURBO	28/07/2021		Corrective Order	WO Completed	Telehender
636560	Ford 450	reparacion de llanta	LLANTA DE FLAT	28/07/2021		Corrective Order	WO Completed	Pickup truck
636561	Freightliner Columbia CI112	Reparacion de llanta	LLANTA FLAT	28/07/2021		Corrective Order	WO Completed	Mule truck
636563	SDMO J60U 60KVA	MANTENIMIENTO CORRECTIVO	CAMBIO DE BOMBA DE INYECCION LAVADO DE RADIADOR Y RETENEDORAS	28/07/2021 6398 horas		Corrective Order	WO Completed	Generator
636635	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	29/07/2021 EJECUTADO		PM Orders	WO Completed	Pickup truck
636726	Caterpillar D8T Dozer	El limpiaparabrisas de la puer	EL LIMPIAPARABRISAS DE LA PUER	29/07/2021		Corrective Order	WO Completed	Dozer
636727	Caterpillar CS533E Compactor	No enciende	NO ENCIENDE	29/07/2021		Corrective Order	WO Completed	Compactor
636781	Caterpillar 14M Motorgrader	Revision AFEX	REVISION AFEX	29/07/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
636798	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636800	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636801	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636802	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636804	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636806	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636807	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636809	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636812	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636814	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636815	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021	10253.00	PM Orders	WO Completed	Pickup truck
636816	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021		PM Orders	WO Completed	Pickup truck
636817	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021	59186	PM Orders	WO Completed	Bus
636819	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	29/07/2021	30099	PM Orders	WO Completed	Bus
636860	Freightliner Columbia Cl112	Instalacion de GPS	IMNSTALACION DE GPS	29/07/2021		Corrective Order	WO Completed	Mule truck
636861	Bell 225f 4t Forklift (M)	Revision de equipo	EQUIPO NO ARRANCA	29/07/2021		Corrective Order	WO Completed	Forklift
636878	Caterpillar 336DL Excavator	Instalacion de fittins	INSTALACION DE FITTINS DE ENGRASE	29/07/2021		Corrective Order	WO Completed	Excavator
636893	Toyota Hilux	CAMBIO ESPARRAGAS Y TUERCA	RUEDA IZQUIERDA	29/07/2021		Corrective Order	WO Completed	Pickup truck
636895	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636897	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636899	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636900	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636901	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636904	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636905	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636906	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636907	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636908	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636909	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636910	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636911	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636914	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	29/07/2021		Corrective Order	WO Completed	Pickup truck
636952	Hilux DC	CAMBIO BOMBA POWER STEERING	CORRECTIVO PROGRAMADO	29/07/2021		Corrective Order	WO Completed	Pickup truck
636981	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	29/07/2021	18069 hrs	Corrective Order	WO Completed	Generator
636982	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	29/07/2021	14249 hrs	Corrective Order	WO Completed	Generator
637004	Landcruiser DC	Reparacion de llanta	REPARACION DE LLANTA	29/07/2021		Corrective Order	WO Completed	Pickup truck
637008	Caterpillar CS533E Compactor	Arranque auxiliar	ARRANQUE AUXILIAR	29/07/2021		Corrective Order	WO Completed	Compactor
637009	Freightliner Columbia Cl112	Reemplazo de 1 llanta	REEMPLAZO DE 1 LLANTA	29/07/2021		Corrective Order	WO Completed	Mule truck
637036	International 7400 SBA Fire Tr	revision de luces traseras	LUCES TRASERAS	29/07/2021		Corrective Order	WO Completed	Fire truck
637050	Manitou Mht-X1490 9t Telehand	Colocacion de manguera del tur	MANGUERA DE TURBO SUELTA	29/07/2021		Corrective Order	WO Completed	Telehender
637051	Manitou Mht-X1490 9t Telehand	rep. de cerradura de capo de m	CERRADURA DEL CAPO DE MOTOR DEFECTUOSA	29/07/2021		Corrective Order	WO Completed	Telehender
637056	Freightliner Cl 120	Cambio de filtroo secante	FILTRO SECANTE EN MAL ESTADO	29/07/2021		Corrective Order	WO Completed	Mule truck
637383	Mobile equipment	CONSUMIBLES GENSET - AGOSTO	PRODUCTOS CONSUMIBLES	30/07/2021	90010897	Corrective Order	WO Completed	Area
637391	Caterpillar D8T Dozer	El tablero no marca la condici	EL TABLERO NO MARCA LA CONDICI	30/07/2021		Corrective Order	WO Completed	Dozer
637418	Caterpillar 740B	C/ALARMA DE RETROCESO	SONIDO BAJO	30/07/2021		Corrective Order	WO Completed	Articulated dump truck
637435	Gallegos Lime Tank	FUGA EN ESCOTILLA	FUGA EN ESCOTILLA	30/07/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
637450	Unimog Service Truck	Repara. de falla de encendido	REPARA. DE FALLA DE INCENDIO	30/07/2021		Corrective Order	WO Completed	Truck
637455	Caterpillar 320DL	No enciende	NO ENCIENDE	30/07/2021		Corrective Order	WO Completed	Excavator
637469	Caterpillar 336DL	Bajo nivel de refrigerante	BAJO NIVEL DE REFRIGERANTE	30/07/2021		Corrective Order	WO Completed	Excavator
637490	Caterpillar 740B EJ ADT	C/ MANG HYD DIRECCION	MMANGUERA ROTA	30/07/2021		Corrective Order	WO Completed	Articulated dump truck
637511	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	30/07/2021		Corrective Order	WO Completed	Pickup truck
637516	Landcruiser TC	VERIFICAR INGRESO AGUA LADO RH	POSIBLE INGRESO CABLE ESCOLTA	30/07/2021	14835 kms	Corrective Order	WO Completed	Pickup truck
637523	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	30/07/2021		Corrective Order	WO Completed	Bus
637532	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	30/07/2021		Corrective Order	WO Completed	Pickup truck
637540	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	30/07/2021		Corrective Order	WO Completed	Pickup truck
637545	Power Curbers 5700-C	C/ MANG PRESION AL VIBRADOR	MANGUERA DESGASTADA	30/07/2021		Corrective Order	WO Completed	Kerb Machine
637587	Freightliner Columbia Cl112	Revision de equipo	EQUIPO NO ARRANCA	30/07/2021		Corrective Order	WO Completed	Mule truck
637604	New Holland Lm 1745	Boom no recoge	BOOM NO RECOGE	30/07/2021		Corrective Order	WO Completed	Telehender
637607	Faresin FM4000 / 17F Telehandl	No arranca	NO ARRANCA	30/07/2021		Corrective Order	WO Completed	Telehender
637615	PRAMAC GSW560V 407 kVa	CORRECTIVO	CORRECTIVO	30/07/2021	18071 hrs	Corrective Order	WO Completed	Generator
637626	Caterpillar D110 E2 110 kVa	LAVADO RADIADOR	RADIADOR SUCIO	30/07/2021	17729 hrs	Corrective Order	WO Completed	Generator
637630	Freightliner M2 106 Refrigerat	Cambio de motor de arranque	MOTOR DE ARRANQUE DEFECTUOSO	30/07/2021	90011000	Corrective Order	WO Completed	Refrigerator truck
637632	Freightliner M2 106 Refrigerat	Cambio de motor de arranque	SOLICITUD DE CAMBIO DE MOTOR DE ARRANQUE	30/07/2021		Corrective Order	WO Completed	Refrigerator truck
637638	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	COLOCACION DE MODULO BASE Y REPARACION DE COMBUSTIBLE	30/07/2021	18069 horas	Corrective Order	WO Completed	Generator
637645	JLG 1250 AJP Manlift	LEVANTAMIENTO INFORMACION	EQUIPO FUERA DE SERVICIO	30/07/2021		Corrective Order	WO Completed	Manlift
637648	Freightliner Boom Truck	izaje de equipo	IZAJE DE EQUIPO	30/07/2021	SOPORTE W30	Corrective Order	WO Completed	Boom truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
637649	Freightliner 8170ME Water Truc	Izaje de equipo	IZA=JE DE EQUIPO	30/07/2021	SOPORTE W30	Corrective Order	WO Completed	Water truck
637760	PRAMAC GSW65 48 kVa	PM PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	24411 hrs	PM Orders	WO Completed	Generator
637761	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	23934 hrs	PM Orders	WO Completed	Generator
637762	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	12844 hrs	PM Orders	WO Completed	Generator
637763	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	29448 horas	PM Orders	WO Completed	Generator
637764	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	7755 hrs	PM Orders	WO Completed	Generator
637765	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	11612 hrs	PM Orders	WO Completed	Generator
637767	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	24516 horas	PM Orders	WO Completed	Generator
637768	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	21308 hrs	PM Orders	WO Completed	Generator
637769	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	20655 hrs	PM Orders	WO Completed	Generator
637857	Caterpillar D8T Dozer	Fuga por la bomba de aceite	FUGA POR LA BOMBA DE ACEITE	31/07/2021		Corrective Order	WO Completed	Dozer
637860	Caterpillar 12M	Manguera hidráulica rota	MANGUERA HIDRÁULICA ROTA	31/07/2021		Corrective Order	WO Completed	Grader
637934	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	24680 hrs	PM Orders	WO Completed	Generator
637935	Caterpillar DE165E0 165 kVa	PM CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	15639 horas	PM Orders	WO Completed	Generator
637936	Caterpillar D110 E2 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	16954 horas	PM Orders	WO Completed	Generator
637939	Caterpillar 336DL	Fuga aceite hidráulico	FUGA ACEITE HIDRÁULICO	31/07/2021		Corrective Order	WO Completed	Excavator
637941	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	13307 hrs	PM Orders	WO Completed	Generator
637942	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	16084 hrs	PM Orders	WO Completed	Generator
637943	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	6076 hrs	PM Orders	WO Completed	Generator
637947	Mobile equipment	CONSUMIBLE	PRODUCTO CONSUMIBLE	31/07/2021		Corrective Order	WO Completed	Area
637965	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	31/07/2021		Corrective Order	WO Completed	Pickup truck
637970	Coaster	Reemplazo de llanta	REEMPLAZO DE LLANTA	31/07/2021		Corrective Order	WO Completed	Bus
637983	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	24479 hrs	Corrective Order	WO Completed	Light Tower
637988	DOOSAN 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	19890hroas	Corrective Order	WO Completed	Light Tower
637991	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	24281 hrs	Corrective Order	WO Completed	Light Tower
637993	MAGNUM Light Tower	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/07/2021	26798 horas	Corrective Order	WO Completed	Light Tower
637998	Grove RT600E 50TON	Revision de equipo	REPARACION DE FUGA HIDRAULICA	31/07/2021		Corrective Order	WO Completed	Crane/Hoist
638015	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	31/07/2021		Corrective Order	WO Completed	Pickup truck
638032	International 7400 SBA Fire Tr	Cambio de Componentes	REVISION DEL SISTEMA ELECTRICO	31/07/2021	PKG-10007016	Corrective Order	WO Completed	Fire truck
638083	Caterpillar 416E	Revision Electrica y Swicht	NO ENCIENDE	31/07/2021		Corrective Order	WO Completed	Backhoe
638093	Freightliner 8170ME Water Truc	Revision de equipo	REVISION DE FUGA DE AIRE	31/07/2021		Corrective Order	WO Completed	Water truck
638095	Hyster H300 13t Forklift (M)	Flat Llanta interna lado izqui	FLAT LLANTA INTERNA LADO IZQUI	31/07/2021		Corrective Order	WO Completed	Forklift
638113	Caterpillar 226b Skid Steer L	Reemplazo de hojas	REEMPLAZO DE HOJAS DE CORTE	31/07/2021		Corrective Order	WO Completed	Skid Steer
638116	John Deere 9370R Tractor	Revision de equipo	INSTALACION DE BOMBILLOS	31/07/2021		Corrective Order	WO Completed	Tractor
638152	Freightliner M112 Truck Tip	cambio de llanta	LLANTA EN MAL ESTADO	31/07/2021		Corrective Order	WO Completed	Tipper
638163	Internation F2674	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	31/07/2021		Corrective Order	WO Completed	Boom truck
638197	FG WILSON P88-3 80 kVa	LLAMADA DE EMERGENCIA	LINEA DE COMBUSTIBLE OBSTRUIDA	31/07/2021	24.32 kh	Corrective Order	WO Completed	Generator
638245	Grove GMK 4080 80TON	Cambio de pateca	CAMBIO DE PATECA	31/07/2021		Corrective Order	WO Completed	Crane/Hoist
638263	Freightliner M2 106 Sucker Tru	instalacion de Pertiga	EQUIPO SIN PERTIGA	31/07/2021		Corrective Order	WO Completed	Sucker truck
638267	John Deere 9370R Tractor	cambio de bombillos	BOMBILLO QUEMADOS DE LUCES PRINCIPAL	31/07/2021		Corrective Order	WO Completed	Tractor
638268	JLG 1250 AJP Manlift	aranque auxiliar de equipo	EQUIPO NO ARRANCA	31/07/2021		Corrective Order	WO Completed	Manlift
638269	Grove RT600E 50TON	arranque auxiliar	TERNIMAL DE MOTR DE ARRANQUE AISLADO	31/07/2021		Corrective Order	WO Completed	Crane/Hoist
638271	John Deere 9370R Tractor	Cambio de manguera	FUGA DE SISTEMA HIDRAULICA	31/07/2021	90011383	Corrective Order	WO Completed	Tractor
638466	Faresin FM4000 / 17F Telehandl	Cambio de válvulas solenoides	REVICION DE EQUIPO	01/08/2021	90011798 90013268	Corrective Order	WO Completed	Telehender
638496	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	01/08/2021		Corrective Order	WO Completed	Pickup truck
638497	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	01/08/2021		Corrective Order	WO Completed	Pickup truck
638498	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	01/08/2021		Corrective Order	WO Completed	Pickup truck
638511	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	01/08/2021		Corrective Order	WO Completed	Pickup truck
638518	SJS SJ6530	REPARACIONES GENERALES	REPARACION DE EJE DE TRASLACION	01/08/2021		Corrective Order	WO Completed	Compactor
638539	TTP-0000-102	Confeccion de buje	CONFECION DE BUJE	01/08/2021	2021W31	Corrective Order	WO Completed	Excavator
638555	Hilux DC	Cambio de 3 llantas	CAMBIO DE 3 LLANTAS	01/08/2021		Corrective Order	WO Completed	Pickup truck
638557	Manitou Mht-X1490 9t Telehand	Dañada Abrazadera del Turbo	DAÑADA ABRAZADERA DEL TURBO	01/08/2021		Corrective Order	WO Completed	Telehender
638569	Caterpillar D8T Dozer	Revision al sistema AFEX	REVISION AL SISTEMA AFEX	01/08/2021		Corrective Order	WO Completed	Dozer
638586	SDMO J60U 60KVA	CORRECTIVO	CAMBIO DE VOLETAJE	01/08/2021	11157 hrs	Corrective Order	WO Completed	Generator
638589	Caterpillar D110 E2 100KVA	LAVADO RADIADOR	REVISION GENERAL DE EQUIPO	01/08/2021	2732 hrs	Corrective Order	WO Completed	Generator
638594	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/08/2021	16721 hrs	PM Orders	WO Completed	Generator
638608	Power Curbers 5700-C	Perdida de aceite hidráulico,	PERDIDA DE ACEITE HIDRÁULICO,	01/08/2021		Corrective Order	WO Completed	Kerb Machine
638722	Freightliner CI 120	PUERTA LADO PASAJERO	PUERTA LADO PASAJERO	01/08/2021		Corrective Order	WO Completed	Mule truck
638739	Freightliner 8170ME Water Truc	Revision de equipo	REVISION DE FUGA DE AIRE	01/08/2021		Corrective Order	WO Completed	Water truck
638790	Manitou Mht-X1490 9t Telehand	REPARACION DE ABRAZADERA	REPARACION DE ABRAZADERA	01/08/2021		Corrective Order	WO Completed	Telehender
638795	Caterpillar 426F2 Backhoe	Bajo nivel aceite transmision	BAJO NIVEL ACEITE TRANSMISION	01/08/2021		Corrective Order	WO Completed	Backhoe
638796	Grove RT600E 50TON	Revision de equipo	REVISION DE FUGA HIDRAULICA	01/08/2021		Corrective Order	WO Completed	Crane/Hoist
638798	Hyster E70xn 3t Forklift (E)	Montacargas se Apago	MONTACARGAS SE APAGO	01/08/2021		Corrective Order	WO Completed	Forklift
638807	Power Curbers 5700-C	Sensor posterior no marca lect	SENSOR POSTERIOR NO MARCA LECT	01/08/2021		Corrective Order	WO Completed	Kerb Machine
638810	Caterpillar 416E	No enciende	NO ENCIENDE	01/08/2021		Corrective Order	WO Completed	Backhoe
638851	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Pickup truck
638852	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Pickup truck
638853	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Bus

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
638854	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Bus
638855	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Bus
638876	Freightliner M2 106 Hydroseedi	cambio de 2 llantas	LLANTAS EN MAL ESTADO	01/08/2021		Corrective Order	WO Completed	Truck
638879	Freightliner CI 120	c. motor de arranque y bateria	EQUIPO NO ARRANCA	01/08/2021		Corrective Order	WO Completed	Mule truck
638880	Manitou Mht-X860 6t Telehand	reparacion de llanta	LLANTA FLAT	01/08/2021		Corrective Order	WO Completed	Telehender
638881	Caterpillar 14H Motorgrader	Correccion de fuga hidraulica	FUGA HIDRAULICA	01/08/2021		Corrective Order	WO Completed	Grader
638882	Freightliner Columbia CI112	reparacion de llanta	LLANTA FLAT	01/08/2021		Corrective Order	WO Completed	Mule truck
638885	Manitou Mht-X1490 9t Telehand	Reparacion de llanta	LLANTA FLAT	01/08/2021		Corrective Order	WO Completed	Telehender
638886	Hilux DC	Reparacion de llanta	LLANTA FLAT	01/08/2021		Corrective Order	WO Completed	Pickup truck
639024	Caterpillar 12M	Se esta calentando aceite hid	SE ESTA CALENTANDO ACEITE HID	02/08/2021		Corrective Order	WO Completed	Grader
639041	Caterpillar 426F2 Backhoe	Revision de equipo	REEMPLAZO DE BOMBILLOS	02/08/2021		Corrective Order	WO Completed	Backhoe
639065	Caterpillar 426f2 Backhoe	Cambio de alarma de reversa	ALARMA DE REVERSA NO FUNCIONA	02/08/2021		Corrective Order	WO Completed	Backhoe
639086	Freightliner CI 120	FRENOS	FRENOS	02/08/2021		Corrective Order	WO Completed	Mule truck
639102	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	02/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
639210	Gallegos Lime Tank	BANDAS	BANDAS	02/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
639215	Caterpillar D8T Dozer	Fuga de aceite de motor	FUGA DE ACEITE DE MOTOR	02/08/2021		Corrective Order	WO Completed	Dozer
639241	Caterpillar 336DL	Manguera de afex	REVISION DE SISTEMA DE AFEX	02/08/2021		Corrective Order	WO Completed	Excavator
639242	Freightliner Columbia CI112	BALINERA/RETROVISORES/POLLERAS	BALINERA/RETROVISORES/POLLERAS	02/08/2021		Corrective Order	WO Completed	Mule truck
639244	Freightliner M2 112 Sucker Tru	Revision de equipo	ARRANQUE DE EQUIPO	02/08/2021		Corrective Order	WO Completed	Sucker truck
639247	Freightliner CI 120	Revision de equipo	EQUIPO NO ARRANCA	02/08/2021		Corrective Order	WO Completed	Mule truck
639249	Caterpillar 12M	Aire acondicionado dañado (no	AIRE ACONDICIONADO DAÑADO (NO	02/08/2021		Corrective Order	WO Completed	Grader
639262	Hyster H700 Forklift	ENGINE REPAIR & INSTALL	CORRECTIVE	02/08/2021	50015044 50015765	Corrective Order	WO Completed	Forklift
639302	Freightliner M2 112 Sucker Tru	Revision de equipo	REEMPLAZO DE PULMONES DE FRENO - AMBOS LADOS ULTIMO TANDEM	02/08/2021		Corrective Order	WO Completed	Sucker truck
639326	USP&E GP700S/V-A 700 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR PERDIDA DE ACEITE	02/08/2021	23733 hrs	Corrective Order	WO Completed	Generator
639340	John Deere 9370R Tractor	Sin aire acondicionado	SIN AIRE ACONDICIONADO	02/08/2021		Corrective Order	WO Completed	Tractor
639350	Caterpillar D8T Dozer	Correccion de fuga coolam	EQUIPO CON FUGA COOLAM	02/08/2021		Corrective Order	WO Completed	Dozer
639378	JLG 1850 AJ Manlift	Equipo con falla activa	EQUICPO CON CODIGO ACTIVO	02/08/2021		Corrective Order	WO Completed	Manlift
639379	Freightliner M2 106 Sucker Tru	Correccion de arranque	EQUIPO CON FALLA EN ARRANQUE	02/08/2021		Corrective Order	WO Completed	Sucker truck
639380	Terex RT5551 55TON	correccion de falla	FALLA ACTIVA	02/08/2021		Corrective Order	WO Completed	Crane/Hoist
639765	CAT 930K	Liqueo de aceite hidráulico po	LIQUEO DE ACEITE HIDRÁULICO PO	03/08/2021		Corrective Order	WO Completed	Loader
639766	Broce Broom RJT 350	EVALUAR CAMBIO DE ESCOBILLAS	NECESITA CAMBIO DE ESCOBILLAS	03/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
639796	Hilux DC	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	03/08/2021		Corrective Order	WO Completed	Pickup truck
639809	USP&E GP700S/V-A 700 kVa	CORRECTIVO	INSTALAR MAGNETIC PICK UP Y LIMPIEZA DE FUGA ACEITE	03/08/2021	23734 hrs	Corrective Order	WO Completed	Generator
639813	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	APAGADO PO CORREA REVENTADA	03/08/2021	25133 hrs	Corrective Order	WO Completed	Generator
639816	Hyster H70ft 3t Forklift (M)	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	03/08/2021	90011199	Corrective Order	WO Completed	Forklift
639826	Mobile equipment	SENALIZACION TALLER	MANTENIMIENTO MEJORATIVO	03/08/2021		Corrective Order	WO Completed	Area
639870	CAT 930K	Escalera de acceso dañada	ESCALERA DE ACCESO DAÑADA	03/08/2021		Corrective Order	WO Completed	Loader
639884	Freightliner Columbia CI112	Cambio de llantas	CAMBIO DE LLANTADS	03/08/2021		Corrective Order	WO Completed	Mule truck
639889	Hyster H700 Forklift	ARM REPAIR & INSTALL	CORRECTIVE	03/08/2021	50015090 50015331	Corrective Order	WO Completed	Forklift
639895	Freightliner Columbia CI112	fuga de aceite de motor	FUGA DE ACEITE DE MOTOR	03/08/2021		Corrective Order	WO Completed	Mule truck
639917	SJS SJ6530	Confeccion de bujes	CONFECION DE BUJES	03/08/2021	Emergency	Corrective Order	WO Completed	Compactor
639935	JLG T350 Manlift	Cambio de baterías	BATERIAS EN MAL ESTADO	03/08/2021		Corrective Order	WO Completed	Manlift
639939	JLG T350 Manlift	Cambio de baterías	BATERIAS ORIGINALES EN MAL ESTADO	03/08/2021	90011240	Corrective Order	WO Completed	Manlift
639951	Grove RT9130E 120TON	reparación de Winche	REPARACIÓN DE WINCHE	03/08/2021	50015444	Corrective Order	WO Completed	Crane/Hoist
639969	JLG 450 AJ Manlift	CYLINDER REPAIR (MASTER TECH)	FUGA POR CILINDRO DE LEVANTE	03/08/2021	50015955	Corrective Order	WO Completed	Manlift
639981	TTP-0000-102	Revisar niveles de aceite	REVISAR NIVELES DE ACEITE	03/08/2021		Corrective Order	WO Completed	Excavator
639991	Freightliner Columbia CI112	Reparacion e llantas	REPARACIONDE LLANTAS	03/08/2021		Corrective Order	WO Completed	Mule truck
639993	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/08/2021		Corrective Order	WO Completed	Pickup truck
640004	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/08/2021		Corrective Order	WO Completed	Pickup truck
640005	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/08/2021		Corrective Order	WO Completed	Pickup truck
640014	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/08/2021		Corrective Order	WO Completed	Pickup truck
640040	Mobile equipment	SERVICIO TRASLADO GENERADORES	EQUIPOS SCRAP	03/08/2021	SE CIERRA POR TIEMPO DE RESPUE	Corrective Order	WO Completed	Area
640095	Caterpillar D8T Dozer	cambio de crucetas	FALLO EN CRUCETAS D EJE DE MANDO	03/08/2021		Corrective Order	WO Completed	Dozer
640113	Grove GMK4100L 100TON	Calibracion de Equipo	REVISION DE EQUIPO	03/08/2021		Corrective Order	WO Completed	Crane/Hoist
640117	Freightliner Columbia CI112	Reparacion de llanta	LLANTA FLAT	03/08/2021		Corrective Order	WO Completed	Mule truck
640124	Gallegos Lime Tank	cambio de estabilizadores	FALLO EN ESTABILIZADORES	03/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
640145	Freightliner CI 120	Reparacion de a/c	A/C NO FUNCIONA	04/08/2021		Corrective Order	WO Completed	Mule truck
640375	Caterpillar 740B	C/PALANCA MULTIFUNCIONES WIPER	MAL CONTACTO DE LAS VELOCIDADES	04/08/2021		Corrective Order	WO Completed	Articulated dump truck
640434	Gallegos 28M3 Lime Tank	FUGA	FUGA	04/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
640455	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Pickup truck
640456	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Pickup truck
640457	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Pickup truck
640460	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Pickup truck
640462	Coaster	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Bus
640464	Iveco 380t38	Da inicio pero no arranca	DA INICIO PERO NO ARRANCA	04/08/2021		Corrective Order	WO Completed	Bitumen truck
640510	DOOSAND 1005	CAMBIO BOMBA SEBA	FALSA SEÑAL	04/08/2021	36601 hrs	Corrective Order	WO Completed	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
640516	Caterpillar CS74 Compactor	Only work in slow mode (Turtel	ONLY WORK IN SLOW MODE (TURTEL	04/08/2021		Corrective Order	WO Completed	Compactor
640520	Caterpillar TI1055clrc	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	04/08/2021	AUTO CLOSED	Corrective Order	WO Completed	Telehender
640545	Caterpillar CS74 Compactor	Confeccion de manguera	CONFECCION DE MANGUERA	04/08/2021		Corrective Order	WO Completed	Compactor
640548	Caterpillar 336DL	TANK INSPECTION (ADEMINSA)	INSPECTION	04/08/2021	50015106	Corrective Order	WO Completed	Excavator
640628	Caterpillar RM500 Reclaimer	Reparación de motor de arranqu	REPARACIÓN DE MOTOR DE ARRANQUE	04/08/2021		Corrective Order	WO Completed	Road Reclaimer
640654	Caterpillar 740B EJ ADT	C/MANGUERA DE DIRECCION	REQUIERE CAMBIO	04/08/2021		Corrective Order	WO Completed	Articulated dump truck
640664	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/08/2021		Corrective Order	WO Completed	Pickup truck
640665	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/08/2021		Corrective Order	WO Completed	Pickup truck
640669	Freightliner M2 112 Sucker Tru	Reemplazo de llanta	REEMPLAZO DE LLANTA	04/08/2021		Corrective Order	WO Completed	Sucker truck
640671	Manitou Mht-X1490 9t Telehand	revisar mangueras de turbo	REVISAR MANGUERAS E TURBO	04/08/2021		Corrective Order	WO Completed	Telehender
640674	Freightliner M2 106 Sucker Tru	reparacion e manguera neumatic	REPARACION DE MANGUERA NEUMATICA	04/08/2021		Corrective Order	WO Completed	Sucker truck
640675	Caterpillar 740B	C/FILTRO Y ACEITE DE MOTOR	REQUIERE CAMBIO	04/08/2021		Corrective Order	WO Completed	Articulated dump truck
640694	Tennant S30 Sweeper	Safety Blue Light-Installation	SAFETY BLUE LIGHT-INSTALLATION	04/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
640698	Tennant T7 Scrubber	Safety Blue Light-Installation	SAFETY BLUE LIGHT-INSTALLATION	04/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
640721	Caterpillar 416E	Correccion de fuga de aceite	CORRECCION DE FUGA DE ACEITE POR TAPAVALVULAS DEL MOTOR	04/08/2021		Corrective Order	WO Completed	Backhoe
640730	PRAMAC GSW460V 460 kVa	CORRECTIVO	CAMBIO DE BASE FE FILTROS DE COMBUSTIBLES	04/08/2021	12940 hrs	Corrective Order	WO Completed	Generator
640735	Mobile equipment	DRENAJE FLUIDOS EQUIPOS SCRAP	PREPARATIVO DEMOVILIZACION EQUIPOS	04/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Area
640750	Landcruiser DC	Cambio de 2 llantas	LLANTAS EN MAL ESTADO	04/08/2021		Corrective Order	WO Completed	Pickup truck
640752	Freightliner M2 106 Sucker Tru	Equipo con fuga de aire	EQUIPO FRENADO	04/08/2021		Corrective Order	WO Completed	Sucker truck
640753	Hyster H800 32t Forklift (M)	Inspeccion de equipo	INSPECCION DE EQUIPO	05/08/2021		Corrective Order	WO Completed	Forklift
640828	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	05/08/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
640915	Freightliner M112 Truck Tip	Aire Acondicionado	AIRE ACONDICIONADO	05/08/2021		Corrective Order	WO Completed	Tipper
640917	John Deere 310K	Problema con la dirección	PROBLEMA CON LA DIRECCIÓN	05/08/2021		Corrective Order	WO Completed	Backhoe
640958	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	05/08/2021		Corrective Order	WO Completed	Pickup truck
640978	Unimog Service Truck	Luces y Alarma Retroceso	LUCES Y ALARMA RETROCESO	05/08/2021		Corrective Order	WO Completed	Truck
640997	Eagle Beaver 50sgl-Pt	LUCES/FUGA DE AIRE/ESPARRAGOS	LUCES/FUGA DE AIRE/ESPARRAGOS	05/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
641012	Freightliner Cl 120	MANGUERA	MANGUERA	05/08/2021		Corrective Order	WO Completed	Mule truck
641055	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	05/08/2021		Corrective Order	WO Completed	Pickup truck
641072	Freightliner Columbia Cl112	LLANTA FLAT	LLANTA FLAT	05/08/2021		Corrective Order	WO Completed	Mule truck
641073	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	05/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
641074	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	05/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
641081	Freightliner Cl 120	Reemplazo de lamparas	REEMPLAZO DE LAMPARAS DELANTERAS	05/08/2021		Corrective Order	WO Completed	Mule truck
641086	John Deere 9370R Tractor	Se le activo alarma.	SE LE ACTIVO ALARMA.	05/08/2021		Corrective Order	WO Completed	Tractor
641182	Caterpillar 14M Motorgrader	Daño en manguera de la articul	DAÑO EN MANGUERA DE LA ARTICUL	05/08/2021		Corrective Order	WO Completed	Grader
641184	Manitou Mht-X1490 9t Telehand	Luces quemadas/llanta baja	LUCES QUEMADAS/LLANTA BAJA	05/08/2021		Corrective Order	WO Completed	Telehender
641188	Freightliner 8170ME Water Truc	Necesita ajuste en el clutch	NECESITA AJUSTE EN EL CLUTCH	05/08/2021		Corrective Order	WO Completed	Water truck
641195	Landcruiser TC	PREVENTIVE MAINTENANCE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	68011	PM Orders	WO Completed	Pickup truck
641196	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	34969 kms	PM Orders	WO Completed	Pickup truck
641198	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641199	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641200	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641201	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641202	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641203	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641204	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641205	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	21665	PM Orders	WO Completed	Pickup truck
641206	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641207	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641209	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641212	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Bus
641213	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	26501 km	PM Orders	WO Completed	Bus
641214	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	20056 KM	PM Orders	WO Completed	Bus
641215	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021	19142 KM	PM Orders	WO Completed	Bus
641216	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Bus
641217	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	05/08/2021		PM Orders	WO Completed	Pickup truck
641236	Freightliner Columbia Cl112	cambio de 2 llantas	LLANTAS DELANTERAS EN MAL ESTADO	05/08/2021		Corrective Order	WO Completed	Mule truck
641242	Hyster H300 Forklift	Revison de arranque y fallas	EQUIPO NO ARRANCA Y REVISION GENERAL	05/08/2021		Corrective Order	WO Completed	Forklift
641253	Broce Broom RJT 350	Cambio de escobillas	ESCOBILLAS EN MAL ESTADO	06/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
641437	Manitou Mht-X860 6t Telehand	Cambio de alternador	ALTERNADOR EN MAL ESTADO	06/08/2021		Corrective Order	WO Completed	Telehender
641526	Hino Serie 300 Box Truck	REPARACION DE LLANTA	REPARACION DE LLANTA	06/08/2021		Corrective Order	WO Completed	Truck
641532	PRAMAC GSW460V 460 kVa	CAMBIO DE REGULADOR DE VOLTAGE	MANTENIMEINTO CORRECTIVO	06/08/2021	12941 hrs	Corrective Order	WO Completed	Generator
641536	Caterpillar RM500 Reclaimer	Reparacion de bomba de agua	REPARACION DE BOMBA DE AGUA DE LA EMULSION	06/08/2021		Corrective Order	WO Completed	Road Reclaimer
641756	Caterpillar TL1055CLRC	Reemplazo de manguera	TELEHANDER CON FUGA HIDRAULICA	06/08/2021		Corrective Order	WO Completed	Telehender
641779	SDMO J30U 38 kVa	LLAMADA DE EMAERGENCIA	FUGA DE DIESEL	06/08/2021	12544 hrs	Corrective Order	WO Completed	Generator
641825	Caterpillar DE165E0 165 kVa	PM CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	15997 hrs	PM Orders	WO Completed	Generator
641828	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	17314 HORAS	PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
641830	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	13988 horas	PM Orders	WO Completed	Generator
641831	PRAMAC GSW80P 83 kVa	PM PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	11895 HORAS	PM Orders	WO Completed	Generator
641832	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	24000 horas	PM Orders	WO Completed	Generator
641834	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	19820 hrs	PM Orders	WO Completed	Generator
641835	Olympian GEP18-6 18KVA	PM OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	28970 HORAS	PM Orders	WO Completed	Generator
641836	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	7292 hrs	PM Orders	WO Completed	Generator
641849	Olympian GEP 88-3 64 kVa	CAMBIO BATERIA	CONTRATISTA EXTERNO	06/08/2021	23180 HRS EXTERNO 50017650	Corrective Order	WO Completed	Generator
641864	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	06/08/2021	8644 horas	Corrective Order	WO Completed	Generator
642020	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	EQUIPO FUERA DE SERVICIO	PM Orders	WO Completed	Light Tower
642021	Atlas Copco Hilight V5	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	10116 hrs	PM Orders	WO Completed	Light Tower
642111	PRAMAC GSW170i 164 kVa	PM PRA GSW170i MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	5551 hors	PM Orders	WO Completed	Generator
642112	PRAMAC GSW120 120 kVa	PM PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	6364 horas	PM Orders	WO Completed	Generator
642113	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	18497 horas	PM Orders	WO Completed	Generator
642114	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	14628 horas	PM Orders	WO Completed	Generator
642115	SDMO J60U 60KVA	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	6479 horas	PM Orders	WO Completed	Generator
642138	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	35918 hrs	Corrective Order	WO Completed	Light Tower
642139	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	22836 hrs	Corrective Order	WO Completed	Light Tower
642155	Caterpillar 735B	C/BEARING DE DIRECCION	ALTO JUEGO POR DESGASTE	07/08/2021		Corrective Order	WO Completed	Articulated dump truck
642162	Caterpillar 735B	C/BEARING AFRAME POSTERIOR	JUEGO EN EL MECANISMO	07/08/2021		Corrective Order	WO Completed	Articulated dump truck
642200	Caterpillar 735B	C/BEARING FRAME FRONTAL	ALTO JUEGO POR DESGASTE	07/08/2021		Corrective Order	WO Completed	Articulated dump truck
642231	Freightliner Columbia C112	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Mule truck
642261	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	17132 hrs	PM Orders	WO Completed	Generator
642262	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/08/2021	36913 hrs	PM Orders	WO Completed	Generator
642268	Gallegos Flatbed Trailer	LLANTA FLAT / AUSTE DE FRENOS	LLANTA FLAT / AUSTE DE FRENOS	07/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
642296	Caterpillar 735B	C/MANGUERA DIRECCION BOMBA ORB	DESGASTE	07/08/2021		Corrective Order	WO Completed	Articulated dump truck
642342	Case 110JX Tractor Cable Handl	Reemplazo de correas	REEMPLAZO DE CORREAS	07/08/2021		Corrective Order	WO Completed	Tractor
642350	Hyster H300 Forklift	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	07/08/2021		Corrective Order	WO Completed	Forklift
642366	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Pickup truck
642368	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Pickup truck
642372	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Pickup truck
642378	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Pickup truck
642382	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/08/2021		Corrective Order	WO Completed	Pickup truck
642410	Freightliner M2 106 Refrigerat	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	07/08/2021	90011360 90011361	Corrective Order	WO Completed	Refrigerator truck
642416	Gallegos 28M3 Lime Tank	Cambio de pata de soporte	CAMBIO DE PATA DE SOPORTE	07/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
642426	Grove GMK4100L 100TON	EVALUAR CAMBIO PARABRISA	LEVANTAR INFORMACION	07/08/2021		Corrective Order	WO Completed	Crane/Hoist
642437	Caterpillar 740B	C/MANG ENFRIAMIENTO DE FRENOS	REQUIEREN CAMBIO	07/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
642441	Caterpillar DE110E 110 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	20961.7 horas	PM Orders	WO Completed	Generator
642444	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	36948 HORAS	PM Orders	WO Completed	Generator
642445	PRAMAC GSW110P 82 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	12884 horas	PM Orders	WO Completed	Generator
642446	Caterpillar C4.4 88KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	29477.7 horas	PM Orders	WO Completed	Generator
642448	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	CERRADO POR PLANEAMIENTO	PM Orders	WO Completed	Generator
642449	USP&E GP700/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	CERRADO POR PLANEAMIENTO	PM Orders	WO Completed	Generator
642450	PRAMAC GSW460V 460 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	equipo fuera de servicio	PM Orders	WO Completed	Generator
642451	PRAMAC GSW460V 460 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	27526 hrs	PM Orders	WO Completed	Generator
642452	SDMO J60U 60KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	3633 horas	PM Orders	WO Completed	Generator
642453	SDMO J60U 60KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	581 horas	PM Orders	WO Completed	Generator
642454	SDMO J30U 38KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	7793.0 HORS	PM Orders	WO Completed	Generator
642455	SDMO J30U 38KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	29477.7	PM Orders	WO Completed	Generator
642456	PRAMAC GSW65 48 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	24411 hrs	PM Orders	WO Completed	Generator
642457	PRAMAC GBW15 14 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	23967.9 HORAS	PM Orders	WO Completed	Generator
642458	PRAMAC GSW30Y 24 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	21326	PM Orders	WO Completed	Generator
642459	Pramac GSW30P 24KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	11621. horas	PM Orders	WO Completed	Generator
642460	Caterpillar DE22E3 17.6 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	equipo fuera de servicio	PM Orders	WO Completed	Generator
642461	Expert Power PN45 10KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	7325 horas	PM Orders	WO Completed	Generator
642463	Atlas Copco Hilight V5	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	CERRADO POR PLANEAMIENTO	PM Orders	WO Completed	Light Tower
642464	General Mobile MLT3060K	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	5057 horas	PM Orders	WO Completed	Light Tower
642475	PRAMAC GSW110 82 kVa	Correctivo	CORRECTIVO	07/08/2021	359 hrs	Corrective Order	WO Completed	Generator
642494	Hino Serie 300 Box Truck	Cambio de llanta	CAMBIUO DE 6 LLANTAS	07/08/2021		Corrective Order	WO Completed	Truck
642495	New Holland Lm 1745	reparacion electrica no recoge	PROBLEMA ELECTRICO CON ESTENCION DEL BOOM	07/08/2021		Corrective Order	WO Completed	Telehender
642498	Atlas Copco Hilight V4W	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	CERRADO POR PLANEAMIENTO	PM Orders	WO Completed	Light Tower
642503	Atlas Copco Hilight V4W	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	4448 HORAS	PM Orders	WO Completed	Light Tower
642504	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	264 HORAS	PM Orders	WO Completed	Light Tower
642505	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	CERRADO POR PLANEAMIENTO	PM Orders	WO Completed	Light Tower
642514	DOOSAND 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	07/08/2021	35951	PM Orders	WO Completed	Light Tower
642515	Caterpillar 236d Skid Steer L	Revision de equipo	MOTOR BOTO EL REFRIGERANTE	07/08/2021		Corrective Order	WO Completed	Skid Steer
642532	WT013 H7 CISTERNA SINOTRUK	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/08/2021		PM Orders	WO Completed	Water truck
642560	DOOSAND 1005	FALLO DE TOMACORRIENTE Y RUIDO	MANTENIMIENTO CORRECTIVO	07/08/2021	24366 horas	Corrective Order	WO Completed	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
642565	Caterpillar D8T Dozer	Revision de sistema Afex	REVISION DE SISTEMA AFEX	07/08/2021		Corrective Order	WO Completed	Dozer
642718	Caterpillar D8T Dozer	Correccionn de fugas	CORRECCION DE FUGAS DE ACEITE EN EL EQUIPO	08/08/2021	90011402	Corrective Order	WO Completed	Dozer
642724	WT015 H7 CISTERNA SINOTRUK	Cambio de hub completo	CAMBIO DE HUB COMPLETO	08/08/2021		Corrective Order	WO Completed	Water truck
642733	Caterpillar 740b Ej	C/BEARING CYL LEVANTE RH Y LH	JUEGO EXCESIVO	08/08/2021		Corrective Order	WO Completed	Articulated dump truck
642735	Freightliner M2 106 Sucker Tru	revision de sistema electrico	REVISION DE SISTEMA ELECTRICO	08/08/2021		Corrective Order	WO Completed	Sucker truck
642748	Mobile equipment	INSPECCION EQUIPOS NUEVOS	LEVANTAMIENTO DE INFORMACION TECNICA	08/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Area
642753	SDMO T11UM 10 kVa	EVALUACION/DIAGNOSTICO	LEVANTAMIENTO BACKLOGS	08/08/2021	control Nexys efectivo	Corrective Order	WO Completed	Generator
642756	Freightliner M2 106 Sucker Tru	Mantenimiento completo filtros	CAMBIO DE FILTROS	08/08/2021		Corrective Order	WO Completed	Sucker truck
642763	Manitou Mht-X860 6t Telehand	Cambio de correas	CAMBIO DE CORREAS	08/08/2021	90011370	Corrective Order	WO Completed	Telehender
642774	Caterpillar 740b Ej	C/BUSHING DE LINK POSTERIOR	DESGASTE	08/08/2021		Corrective Order	WO Completed	Articulated dump truck
642804	Caterpillar 226b Skid Steer L	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	08/08/2021		Corrective Order	WO Completed	Skid Steer
642879	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	64433	PM Orders	WO Completed	Pickup truck
642884	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	72336	PM Orders	WO Completed	Pickup truck
642886	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	64446	PM Orders	WO Completed	Pickup truck
642888	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	20127	PM Orders	WO Completed	Pickup truck
642891	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	26205	PM Orders	WO Completed	Pickup truck
642930	JLG 1250 AJP Manlift	reparar y revisar sistema de a	REPARACION Y REPARACION DE SISTEMA DE ARRANQUE	08/08/2021		Corrective Order	WO Completed	Manlift
642939	LB002 725 CAT	Revision de equipo	REEMPLAZO DE BATERIAS Y REVISION DE FUGAS	08/08/2021		Corrective Order	WO Completed	Truck
642946	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/08/2021	83308 KM	PM Orders	WO Completed	Pickup truck
642976	Broce Broom RJT 350	Reparación de luces	REPARACIÓN DE LUCES	08/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
643199	Grove GMK 4080 80TON	fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	09/08/2021		Corrective Order	WO Completed	Crane/Hoist
643200	Mobile equipment	Cambio de 6 llantas	LLANTAS EN MAL ESTADO SERIE 7HXB1FL23JP007036	09/08/2021		Corrective Order	WO Completed	Area
643202	Bell 225f 4t Forklift (M)	cambio de posicion de llanta	CAMBIO DE POSICION DE LLANTA	09/08/2021		Corrective Order	WO Completed	Forklift
643271	Caterpillar 416E	No enciende	NO ENCIENDE	09/08/2021		Corrective Order	WO Completed	Backhoe
643286	Caterpillar D8T Dozer	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	09/08/2021		Corrective Order	WO Completed	Dozer
643300	Hyster H300 Forklift	Cambio de pastillas de freno	CAMBIO DE PASTILLAS DE FRENO	09/08/2021	90011407	Corrective Order	WO Completed	Forklift
643303	Caterpillar 740b Ej	C/GASKET TAPA DE TRANSMISION	FUGA DE ACEITE HYD	09/08/2021		Corrective Order	WO Completed	Articulated dump truck
643306	Caterpillar 740b Ej	C/ LINEA DEL HMU	C/ LINEA DEL HMU	09/08/2021		Corrective Order	WO Completed	Articulated dump truck
643318	Caterpillar D8T Dozer	Mantenimiento PM4	MANTENIMIENTO PM4	09/08/2021	24,343.10 hrs	Corrective Order	WO Completed	Dozer
643331	Freightliner Columbia C1112	LAMPARAS DELANTERAS	LAMPARAS DELANTERAS	09/08/2021		Corrective Order	WO Completed	Mule truck
643345	Broderson IC200-2C 9TON	reparacion de perno de llanta	REPARACION DE PERNO DE LLANTA	09/08/2021		Corrective Order	WO Completed	Crane/Hoist
643348	Manitou Mht-X1490 9t Telehand	Instalacion de llamparas led	INSTALACION DE LAMPARAS LED	09/08/2021		Corrective Order	WO Completed	Telehender
643352	Mobile equipment	herramientas, port	HERRAMIENTA DE PORT	09/08/2021		Corrective Order	WO Completed	Area
643353	Caterpillar 740b Ej	C/MANGUERA DIRECCION	ROTAS	09/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
643382	Ford Hilux D/C Light Vehicle	CAMBIO BATERIA	DESCARGA	09/08/2021	99337	Corrective Order	WO Completed	Pickup truck
643421	Freightliner Columbia C1112	AJUSTE DE TERMINAL	AJUSTE DE TERMINAL	09/08/2021		Corrective Order	WO Completed	Mule truck
643431	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	TALLER DOLLAR PENONOME	09/08/2021		Corrective Order	WO Completed	Pickup truck
643461	Terex RT780-1 80TON	Cambio de filtro	CAMBIO DE FILTRO ACEITE	09/08/2021		Corrective Order	WO Completed	Crane/Hoist
643514	Hyster H700 Forklift	desmomntaje de motor	DESMOMNTAJE DE MOTOR	09/08/2021		Corrective Order	WO Completed	Forklift
643515	Iveco 380t38	izaje de cabina	IZAJE DE CABINA	09/08/2021		Corrective Order	WO Completed	Bitumen truck
643534	PRAMAC GSW110 82 kVa	LLAMADA DE EMERGENCIA	BATERIA DAÑADA	09/08/2021	359 hrs	Corrective Order	WO Completed	Generator
643540	Manitou Mht-X860 6t Telehand	Revision de equipo	EQUIPO BLOQUEADO	09/08/2021	3556 Hrs	Corrective Order	WO Completed	Telehender
643559	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	09/08/2021		Corrective Order	WO Completed	Pickup truck
643787	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	10/08/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
643876	Grove RT880E 75TON	cambio de manguera	FUGA DE ACEITE HIDRAULICO	10/08/2021		Corrective Order	WO Completed	Crane/Hoist
643877	Landcruiser DC	Cambio de llanta	LLANTA EN MAL ESTADO	10/08/2021		Corrective Order	WO Completed	Pickup truck
643881	Landcruiser DC	Reparacion de 1 llanta	LLANTA FLAT	10/08/2021		Corrective Order	WO Completed	Pickup truck
643904	Caterpillar 735B	REP/ FUGA POR GRUPO CONTR LEV	FUGA	10/08/2021		Corrective Order	WO Completed	Articulated dump truck
643926	Freightliner Columbia C1112	LLANTA BAJA / LAMPARA	LLANTA BAJA / LAMPARA	10/08/2021		Corrective Order	WO Completed	Mule truck
644004	Caterpillar D8T Dozer	Necesita aceite hidraulico	NECESITA ACEITE HIDRAULICO	10/08/2021		Corrective Order	WO Completed	Dozer
644115	Hyster H300 13t Forklift (M)	LUCES QUEMADAS	LUCES QUEMADAS	10/08/2021		Corrective Order	WO Completed	Forklift
644116	Landcruiser DC	CAMBIO BATERIA	PROBLEMAS DESCARGA	10/08/2021		Corrective Order	WO Completed	Pickup truck
644194	JLG 450 AJ Manlift	Reparacion e manguera	REPARACION DE MAGUERA	10/08/2021		Corrective Order	WO Completed	Manlift
644244	Manitou Mht-X1490 9t Telehand	Reparacion de luces	REPARACION DE LUCES E INSTALACION	10/08/2021		Corrective Order	WO Completed	Telehender
644247	JLG 1250 AJP Manlift	No realiza los movimientos	NO REALIZA LOS MOVIMIENTOS	10/08/2021		Corrective Order	WO Completed	Manlift
644297	Hyster H300 Forklift	Problemas de Arranque	PROBLEMAS DE ARRANQUE	10/08/2021		Corrective Order	WO Completed	Forklift
644299	Freightliner M2 106 Sucker Tru	Equipo Pierde Fuerza	EQUIPO PIERDE FUERZA Y FLEXIBLE DEL ESCAPE ROTO, PROBLEMAS DE A/A Y VENTANAS	10/08/2021		Corrective Order	WO Completed	Sucker truck
644320	Mobile equipment	suministro taller	SUMINISTRO TALLER	10/08/2021		Corrective Order	WO Completed	Area
644495	WT015 H7 CISTERNA SINOTRUK	Cambio de Componentes	COMPONENETS DE DIRECCION	11/08/2021		Corrective Order	WO Completed	Water truck
644497	Caterpillar 226b Skid Steer L	Revision de equipo	REVISION DE EQUIPO	11/08/2021		Corrective Order	WO Completed	Skid Steer
644505	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	11/08/2021	31168 hrs	Corrective Order	WO Completed	Generator
644507	Freightliner 8170ME Water Truc	bajo nivel coolam y aceite de	EQUIPO NO ARRANCA BAJO NIVEL DE ACEITE Y COOLAM	11/08/2021		Corrective Order	WO Completed	Water truck
644515	Kobelco CKE2500E 250TON	revision d Equipo	REVISIONDE EQUIPO	11/08/2021		Corrective Order	WO Completed	Crane/Hoist
644526	Caterpillar TL1055CLRC	Reparacion de la cadena de Boo	REPARACION DE LA CADENA DE BOO	11/08/2021		Corrective Order	WO Completed	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
644631	Freightliner M2 106 Sucker Tru	CLAMPS REPLACEMENT	CORRECTIVE	11/08/2021		Corrective Order	WO Completed	Sucker truck
644761	Hyster H700 Forklift	Tornillería del Manipulador	TORNILLERÍA DEL MANIPULADOR	11/08/2021		Corrective Order	WO Completed	Forklift
644803	Landcruiser DC	CAMBIO PORTABANDA/REPARAR ABS	CAMBIO DIFERENCIAL DELATERO/EJE MANDO CORTO	11/08/2021	55,826	Corrective Order	WO Completed	Pickup truck
644835	Landcruiser DC	CAMBIO AMORTIGUADORES	CAMBIO CALIPER RETENEDORAS/EJE MANDO	11/08/2021	76,813	Corrective Order	WO Completed	Pickup truck
644839	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	11/08/2021	31179 hors	Corrective Order	WO Completed	Generator
644841	Landcruiser DC	CAMBIO MUELLE	CAMBIO BASE AMORTIGUADOR/CABLE FRENO MANO	11/08/2021	46,078	Corrective Order	WO Completed	Pickup truck
644850	Landcruiser DC	CAMBIO KIT EMBRAGUE	PRIMER CAMBIO	11/08/2021	39,998	Corrective Order	WO Completed	Pickup truck
644853	PRAMAC GSW110P 82 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	11/08/2021	12839 horas	Corrective Order	WO Completed	Generator
644856	Landcruiser DC	CAMBIO KIT EMBRAGUE	CAMBIO ALTERNADOR	11/08/2021	57,116	Corrective Order	WO Completed	Pickup truck
644860	Landcruiser DC	CAMBIO MUELLES	MANTENIMIENTO CORRECTIVO	11/08/2021	70,395	Corrective Order	WO Completed	Pickup truck
644863	Hilux DC	CAMBIO ACTUADOR	CAMBIO KIT EMBRAGUE	11/08/2021	75,148	Corrective Order	WO Completed	Pickup truck
644864	Hilux DC	CAMBIO AMORTIGUADOR	CAMBIO 2 HOJAS DE MUELLE	11/08/2021	49,843	Corrective Order	WO Completed	Pickup truck
644911	Landcruiser TC	CAMBIO HOJA MUELLE	PRIMER CAMBIO MUELLES	11/08/2021	64,509	Corrective Order	WO Completed	Pickup truck
644918	Landcruiser DC	REPARAR COCOBOLAS	AMORTIGUADOR TRASERO,DELANTERO	11/08/2021	83,289	Corrective Order	WO Completed	Pickup truck
644922	Landcruiser DC	CAMBIO MUELLES/CRUCETA MANDO	CAMNIO BASE AMORTIGUADOR REAR/BUJE BARRA/AMORTIGUADOR REAR	11/08/2021	42,672	Corrective Order	WO Completed	Pickup truck
644932	Hilux DC	CAMBIO KIT EMBRAGUE	CAMBIO MUELLES/BALINERA EJE/ALARMA	11/08/2021	39,954	Corrective Order	WO Completed	Pickup truck
644950	Hilux DC	CAMBIO KIT EMBRAGUE	CAMBIO ACTUADOR DELANTERO	11/08/2021	61,974	Corrective Order	WO Completed	Pickup truck
644964	Caterpillar 336DL Excavator	Cadena suelta	CADENA SUELTA	11/08/2021		Corrective Order	WO Completed	Excavator
644966	Landcruiser DC	INSTALAR PERTIGA	MANTENIMIENTO CORRECTIVO	11/08/2021	63,900	Corrective Order	WO Completed	Pickup truck
644981	Landcruiser DC	CAMBIO ESCOLTA	ALINEAMIENTO DIRECCION	11/08/2021	75,190	Corrective Order	WO Completed	Pickup truck
644984	Landcruiser DC	CAMBIO ALARMA RETROCESO	RECARGA GAS A/C	11/08/2021	65,815	Corrective Order	WO Completed	Pickup truck
644989	Landcruiser DC	CAMBIO ALARMA RETROCESO	SUMINISTRO EXTINTOR/ KIT ANTIDERRAME	11/08/2021	66,591	Corrective Order	WO Completed	Pickup truck
644991	Landcruiser DC	CAMBIO EVAPORADOR	RECARGA GAS A/C	11/08/2021	45,517	Corrective Order	WO Completed	Pickup truck
644993	Landcruiser DC	CAMBIO ALTERNADOR	MANTENIMIENTO CORRECTIVO	11/08/2021	44,172	Corrective Order	WO Completed	Pickup truck
644995	Landcruiser DC	CAMBIO LAMPARA TRASERA LH	MANTENIMIENTO CORRECTIVO	11/08/2021	44,374	Corrective Order	WO Completed	Pickup truck
644997	Landcruiser DC	REPARAR CAJA TIMON	MANTENIMIENTO CORRECTIVO	11/08/2021	55,600	Corrective Order	WO Completed	Pickup truck
644999	Landcruiser DC	CAMBIO EXTINTOR/ESCOLTA	CAMBIO KIT ANTIDERRAMES	11/08/2021	50,557	Corrective Order	WO Completed	Pickup truck
645000	Hilux DC	CAMBIO CABLE FRENO	CAMBIO CAUCHO BARRA ESTABILIZADORA	11/08/2021	46,320	Corrective Order	WO Completed	Pickup truck
645001	Hilux DC	KIT DE EMBRAGUE	MANTENIMIENTO CORRECTIVO	11/08/2021	60,482	Corrective Order	WO Completed	Pickup truck
645006	Caterpillar 14M Motorgrader	BLADE REPLACEMENT	CORRECTIVE	11/08/2021		Corrective Order	WO Completed	Grader
645007	Hilux DC	CAMBIO TUERCA PERNO	REPARAR CERRADURA PUERTA	11/08/2021	67,032	Corrective Order	WO Completed	Pickup truck
645008	Landcruiser DC	REPARAR COCOBOLAS	CAMBIO TUERCA Y PERNOS	11/08/2021	61,158	Corrective Order	WO Completed	Pickup truck
645009	Landcruiser TC	CAMBIO EVAPORADOR	CAMBIO PARABRISAS	11/08/2021	62,888	Corrective Order	WO Completed	Pickup truck
645011	Landcruiser TC	CAMBIO EVAPORADOR/BOMBILLOS	CARGA DE GAS REFRIGERANTE	11/08/2021	39,007	Corrective Order	WO Completed	Pickup truck
645012	Hilux DC	CAMBIO CERRADURA	FALLA CIERRE PORTON	11/08/2021	41,708	Corrective Order	WO Completed	Pickup truck
645013	Hilux DC	CAMBIO PLATO SUSPENSION	CAMBIO ALARMA RETROCESO	11/08/2021	40,330	Corrective Order	WO Completed	Pickup truck
645014	Hilux DC	CAMBIO PLATO SUSPENSION	LH Y RH	11/08/2021	61,974	Corrective Order	WO Completed	Pickup truck
645017	Hilux DC	CAMBIO CREMALLERA	MANTENIMIENTO CORRECTIVO	11/08/2021	61,974	Corrective Order	WO Completed	Pickup truck
645019	Landcruiser DC	CAMBIO CALIPER FRENOS	MANTENIMIENTO CORRECTIVO	11/08/2021	V	Corrective Order	WO Completed	Pickup truck
645021	Hilux DC	INSTALACION TIRO REMOLQUE	REQUERIMIENTO NUEVO	11/08/2021	9,458	Corrective Order	WO Completed	Pickup truck
645022	Coaster	CAMBIO CILINDRO FRENO	CAMBIO ALARMA RETROCESO	11/08/2021	33,826	Corrective Order	WO Completed	Bus
645026	Toyota Hilux	CAMBIO SIRENA LUCES ESCOLTA	MANTENIMIENTO DE LUCES	11/08/2021		Corrective Order	WO Completed	Pickup truck
645037	Caterpillar 236d Skid Steer L	Problemas de encendido	PROBLEMAS DE ENCENDIDO	11/08/2021		Corrective Order	WO Completed	Skid Steer
645039	DOOSAND 1005	CAMBIO BOMBILLO LUMINARIA	FOCOS QUEMADOS	11/08/2021	24643 horas	Corrective Order	WO Completed	Light Tower
645162	Coaster	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	11/08/2021		Corrective Order	WO Completed	Bus
645163	Coaster	cambio de 4 llantas	LLANTAS EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Bus
645165	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645168	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645169	Landcruiser TC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645170	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645171	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645172	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645173	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645174	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645176	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	11/08/2021		Corrective Order	WO Completed	Pickup truck
645298	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	12/08/2021	EJECUTADO	PM Orders	WO Completed	Pickup truck
645380	Caterpillar 426F2 Backhoe	Desgaste dientes de balde	DESGASTE DIENTES DE BALDE	12/08/2021		Corrective Order	WO Completed	Backhoe
645382	Caterpillar 426F2 Backhoe	Fuga de aceite motor	FUGA DE ACEITE MOTOR	12/08/2021		Corrective Order	WO Completed	Backhoe
645389	Hilux DC	reparacion de 1 llanta	LLANTA FLAT	12/08/2021		Corrective Order	WO Completed	Pickup truck
645390	SJS SJ6530	armado de ejesy coloc. de rued	ARMADO DE EJESY COLOC. DE RUED	12/08/2021		Corrective Order	WO Completed	Compactor
645391	Terex RT5551 55TON	Rellenado de aceite de transm	EQUIPO PIERDE FUERZA	12/08/2021		Corrective Order	WO Completed	Crane/Hoist
645408	Caterpillar 416E	No acciona la palanca que sube	NO ACCIONA LA PALANCA QUE SUBE	12/08/2021		Corrective Order	WO Completed	Backhoe
645409	Gallegos 28M3 Lime Tank	LLANTA FLAT	LLANTA FLAT	12/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
645410	DOOSAND 1005	CAMBIO BOMBILLO	FOCOS QUEMADOS	12/08/2021	36518 hora	Corrective Order	WO Completed	Light Tower
645481	Hilux DC	CAMBIO FAN CLUTCH	MANTENIMIENTO CORRECTIVO	12/08/2021	53,504	Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
645487	Landcruiser DC	CAMBIO CILINDRO FRENO	CAMBI TAMBOR TRASERO/COCOBOLA	12/08/2021	54,390	Corrective Order	WO Completed	Pickup truck
645502	Landcruiser DC	CAMBIO EJE LARGO Y CORTO	CAMBIO PUNTA FLECHA/BALINERAS	12/08/2021	1,358.56	Corrective Order	WO Completed	Pickup truck
645503	Hilux DC	CAMBIO RADIADOR HILUX	FUGA REFRIGERANTE	12/08/2021	53,504	Corrective Order	WO Completed	Pickup truck
645505	Landcruiser TC	CAMBIO DE MUELLE	CAMBIO AMORTIGUADOR TRASERO	12/08/2021	64,686	Corrective Order	WO Completed	Pickup truck
645506	Landcruiser DC	CAMBIO AMORTIGUADOR DIRECCION	CAMBIO BALINERAS	12/08/2021	50,557	Corrective Order	WO Completed	Pickup truck
645507	Hilux DC	CAMBIO COMPRESO/EVAPORADOR	CAMBIO CONDENSADOR	12/08/2021	53,504	Corrective Order	WO Completed	Pickup truck
645509	Landcruiser TC	CAMBIO EJE MANDO	CAMBIO BUJE MUELLES	12/08/2021	59,921	Corrective Order	WO Completed	Pickup truck
645510	Landcruiser DC	CAMBIO TAMBOR FRENO/CALIPER	CAMBIO ALARMA RETROCESO	12/08/2021	68,388	Corrective Order	WO Completed	Pickup truck
645516	Landcruiser DC	CAMBIO TAMBOR	CAMBIO CILINDROS	12/08/2021	64,804	Corrective Order	WO Completed	Pickup truck
645519	Landcruiser DC	REPARACION COCOBOLA	ULTIMO CAMBIO OCTUBRE	12/08/2021	63,740	Corrective Order	WO Completed	Pickup truck
645523	Landcruiser DC	CAMBIO ALTERNADOR	PRIMER CAMBIO PRORATEADO	12/08/2021	55,766	Corrective Order	WO Completed	Pickup truck
645531	Hilux DC	CAMBIO MUELLES	ULTIMO CAMBIO ENERO	12/08/2021	40,686	Corrective Order	WO Completed	Pickup truck
645532	Freightliner M2 106 Sucker Tru	reparacion de manguera	REPARACION DE MANGUERA NEUMATICA	12/08/2021		Corrective Order	WO Completed	Sucker truck
645533	Landcruiser DC	CAMBIO ALTERNADOR	ALTERNADOR PRORATEADO	12/08/2021	43,934	Corrective Order	WO Completed	Pickup truck
645577	Landcruiser DC	REPARAR COCOBOLAS	SOLO DE UN LADO	12/08/2021	48,281	Corrective Order	WO Completed	Pickup truck
645581	Landcruiser DC	CAMBIO CAJA TIMON	HORQUILLA CLUTCH/COCOBOLAS	12/08/2021	57,116	Corrective Order	WO Completed	Pickup truck
645586	Landcruiser DC	CAMBIO PERTIGA	REPARAR CABLEADO ABS/RECARGA GAS	12/08/2021	41,965	Corrective Order	WO Completed	Pickup truck
645588	Landcruiser DC	CAMBIO AMORTIGUADORES/BASES	CAMBIO PERTIGA/REP PUERTA	12/08/2021	60,596	Corrective Order	WO Completed	Pickup truck
645591	Landcruiser TC	CAMBIO TAMBOR TRASERO	CAMBIO CUBO RUEDA LIBRE/AMORTIGUADOR	12/08/2021	57,108	Corrective Order	WO Completed	Pickup truck
645594	Landcruiser DC	CAMBIO ALTERNADOR	PRIMER CAMBIO	12/08/2021	77,842	Corrective Order	WO Completed	Pickup truck
645598	Landcruiser DC	CAMBIO SENSOR POSTERIOR	MANTENIMIENTO CORRECTIVO	12/08/2021	55,889	Corrective Order	WO Completed	Pickup truck
645602	Landcruiser TC	CAMBIO KIT EMBRAGUE	CAMBIO CAUCHO BARRA ESTABILIZADORA	12/08/2021	38,429	Corrective Order	WO Completed	Pickup truck
645772	Hilux DC	Cambio de Neumático	CAMBIO DE NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
645773	Caterpillar D8T Dozer	VOLTEO DE HOJAS DE CUCHILLAS	CORRECTIVO	12/08/2021		Corrective Order	WO Completed	Dozer
645785	Atlas Copco Xa597jd	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645786	Atlas Copco Xats400cd	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645787	Atlas Copco Xas300 Dd	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645788	Atlas Copco 4,4 Xas 400 Cd7 T3	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645789	Chicago Pneumatic Cps 185 Kd7	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645790	Chicago Pneumatic Cps 185 Kd7	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Compressor
645866	Olympian GEP150 135 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645869	FG WILSON P88-3 80 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	24.7 horas	Corrective Order	WO Completed	Generator
645872	Caterpillar DE165E0 165 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	17056 hrs	Corrective Order	WO Completed	Generator
645873	Caterpillar D110 E2 110 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	17729 hrs	Corrective Order	WO Completed	Generator
645875	Caterpillar D110 E2 110 KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645876	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645878	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	17436 HORAS	Corrective Order	WO Completed	Generator
645879	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645880	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	13847 horas	Corrective Order	WO Completed	Generator
645881	Caterpillar D110 E2 100KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	17325 horas	Corrective Order	WO Completed	Generator
645884	PRAMAC GSW110 82 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645885	PRAMAC GSW110 82 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
645886	PRAMAC GSW110P 82 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	14734 HORAS	Corrective Order	WO Completed	Generator
645887	PRAMAC GSW80P 83 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	11841 horas	Corrective Order	WO Completed	Generator
645889	PRAMAC GSW80P 83 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645890	PRAMAC GSW80P 83 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	13682 horas	Corrective Order	WO Completed	Generator
645891	PRAMAC GSW170i 164 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645892	PRAMAC GSW170i 164 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	5559 horas	Corrective Order	WO Completed	Generator
645893	PRAMAC GSW120 120 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	6712 hrs	Corrective Order	WO Completed	Generator
645894	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	16586.6 HORAS	Corrective Order	WO Completed	Generator
645895	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645896	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	24302 HORAS	Corrective Order	WO Completed	Generator
645897	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645899	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645900	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645905	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645906	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645907	USP&E GP700S/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645911	USP&E GP700/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	104.58 horas	Corrective Order	WO Completed	Generator
645912	USP&E GP700/V-A 700 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645913	PRAMAC GSW460V 460 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645914	PRAMAC GSW460V 460 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
645915	PRAMAC GSW460V 460 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
645916	Caterpillar C9 250 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645917	Caterpillar C9 250 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	20761 hrs	Corrective Order	WO Completed	Generator
645918	PRAMAC GSW560V 407 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	15361 horas	Corrective Order	WO Completed	Generator
645919	PRAMAC GSW560V 407 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	14681 HORAS	Corrective Order	WO Completed	Generator
645920	Caterpillar C7.1 200 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
645921	PRAMAC GSW330V 315 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645922	PRAMAC GSW705V 770 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645923	Olympian GEP 88-3 64 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645924	FG WILSON P88-1 64 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645925	SDMO J60U 60 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645926	SDMO J60U 60 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
645927	SDMO J60U 60KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645928	SDMO J60U 60KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645929	SDMO J60U 60KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645930	Caterpillar DE88E0 58 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	37925 hrs	Corrective Order	WO Completed	Generator
645931	PRAMAC GSW45 35 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645934	PRAMAC GSW90P 74 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	25737	Corrective Order	WO Completed	Generator
645937	SDMO T11UM 10KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	24841 hrs	Corrective Order	WO Completed	Generator
645939	SDMO K12UM 11KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Generator
645940	PRAMAC GBW15 14 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645941	Olympian GEP18-6 18 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645942	Olympian GEP18-6 18KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	28997 horas	Corrective Order	WO Completed	Generator
645943	SDMO T16 16KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	23207 HORAS	Corrective Order	WO Completed	Generator
645944	PRAMAC GSW25 17 kVa	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645945	Pramac GSW25P 17KVA	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Generator
645951	Atlas Copco HILIGHT V5 Light T	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645952	Atlas Copco Hilight V5	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645956	DOOSAND 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	22764 HORAS	Corrective Order	WO Completed	Light Tower
645957	DOOSAND 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	2450 horas	Corrective Order	WO Completed	Light Tower
645958	DOOSAN 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645959	DOOSAN 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	2877 horas	Corrective Order	WO Completed	Light Tower
645960	DOOSAND 1005	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645961	MAGNUM Light Tower	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645963	Atlas Copco Hilight V4W	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645964	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	676 hrs	Corrective Order	WO Completed	Light Tower
645966	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	540 HORAS	Corrective Order	WO Completed	Light Tower
645967	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	329 horas	Corrective Order	WO Completed	Light Tower
645969	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	363	Corrective Order	WO Completed	Light Tower
645970	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645971	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645972	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645973	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	420 HORAS	Corrective Order	WO Completed	Light Tower
645974	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645975	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Light Tower
645976	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645977	ATLAS COPCO HILIGHT V5+	INSTALACION SISTEMA JIGSAW	MANTENIMIENTO MEJORATIVO	12/08/2021	CIERRE MASIVO - REVISADO JIGSA	Corrective Order	WO Completed	Light Tower
645989	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
645993	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
645997	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
646002	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
646009	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
646012	Hilux DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE UN NEUMÁTICO	12/08/2021		Corrective Order	WO Completed	Pickup truck
646020	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	12/08/2021	25350.7 horas	Corrective Order	WO Completed	Generator
646027	Freightliner Columbia Cl112	revisar niveles de aceite	REVISAR NIVELES DE ACEITES	12/08/2021		Corrective Order	WO Completed	Mule truck
646030	Freightliner Columbia Cl112	Completar niveles de aceite	COMPLETAR NIVELES DE ACEITE	12/08/2021		Corrective Order	WO Completed	Mule truck
646139	Internation F2674	BAJA pRESIÓN DE ACEITE	BAJA PRESION DE ACXEITE	12/08/2021		Corrective Order	WO Completed	Boom truck
646146	Gallegos 28M3 Lime Tank	REPARACIÓN DE 4 NEUMÁTICOS	REPARACIÓN DE 4 NEUMÁTICOS	12/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
646147	Ford F550	PROBLEMAS DE TRANSMISIÓN	PROBLEMAS DE TRANSMISIÓN	12/08/2021		Corrective Order	WO Completed	Pickup truck
646187	Coaster	cambio de 6 llantas	LLANTAS EN MAL ESTADO	12/08/2021		Corrective Order	WO Completed	Bus
646213	Caterpillar 416F2 Backhoe	cambio de visagra	VISAGRA DE VENTANA ROTA	13/08/2021	90011678	Corrective Order	WO Completed	Backhoe
646249	New Holland Lm 1745	Camble de Freno de Estaciona	SIN FRENO DE ESTACIONAMIENTO	13/08/2021	90011679	Corrective Order	WO Completed	Telehender
646448	WT013 H7 CISTERNA SINOTRUK	Cambio de tornillo de base	CAMBIO DE TORNILLO DE LA BASE DEL COMPRESOR DE A/C	13/08/2021		Corrective Order	WO Completed	Water truck
646450	Freightliner Columbia Cl112	reparacion de llanta	LLANTA FLAT	13/08/2021		Corrective Order	WO Completed	Mule truck
646451	Freightliner Columbia Cl112	cambio de 2 llantas	LLANTA FLAT	13/08/2021		Corrective Order	WO Completed	Mule truck
646456	Terex RT780-1 80TON	revision de codigos activos	CODIGOS ACTIVOS DE FALLA DE MOTOR	13/08/2021	11,706.00 hrs	Corrective Order	WO Completed	Crane/Hoist
646464	Caterpillar 14H Motorgrader	El tablero indica una averia	EL TABLERO INDICA UNA AVERIA	13/08/2021		Corrective Order	WO Completed	Grader
646489	Mack Trucks Gu813e	Retorno de filtros	REORNO DE FILTROS INCORRECTOS	13/08/2021		Corrective Order	WO Completed	Truck
646506	Caterpillar 740B EJ ADT	C/SELLO TAPA VALVULA 3	FUGA POR SELLO	13/08/2021		Corrective Order	WO Completed	Articulated dump truck
646521	Caterpillar 740B EJ ADT	REP/HARNES BOMBA DE GRASA	REQUIEREN CAMBIO	13/08/2021		Corrective Order	WO Completed	Articulated dump truck
646576	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646578	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646581	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
646584	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646585	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646586	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646587	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646588	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646589	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646590	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646593	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646595	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646596	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646597	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646599	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646601	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646604	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646607	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646609	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021 35044		PM Orders	WO Completed	Bus
646613	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021		PM Orders	WO Completed	Pickup truck
646614	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	13/08/2021 104521		PM Orders	WO Completed	Pickup truck
646633	Mobile equipment	fiting, boquilla	FITING, BOQUILLA	13/08/2021		Corrective Order	WO Completed	Area
646640	Caterpillar 416F2 Backhoe	WHEEL BOLTS REPLACEMENT	CORRECTIVE	13/08/2021 90011677		Corrective Order	WO Completed	Backhoe
646645	Mobile equipment	SEÑALES DE SEGURIDAD TE	TE FLEET	13/08/2021 60021807 SENALES INSTALADAS		Corrective Order	WO Completed	Area
646691	Caterpillar 740B	C/ SELLO DE TAPON VAL DE MOTOR	DEFECTUOSO	13/08/2021		Corrective Order	WO Completed	Articulated dump truck
646700	Landcruiser DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	13/08/2021		Corrective Order	WO Completed	Pickup truck
646704	Landcruiser DC	REPARAR LUCES FRONTALES	FAROS LH Y NEBLINERO	13/08/2021 91878		Corrective Order	WO Completed	Pickup truck
646706	Caterpillar 740B	R&I Autolubrication Pump	R&I AUTOLUBRICATION PUMP	13/08/2021		PM Orders	WO Completed	Articulated dump truck
646707	Landcruiser DC	A/C INSPECTION & REPAIR	REPARACION_AIRE ACONDICIONADO	13/08/2021 91878		Corrective Order	WO Completed	Pickup truck
646709	Landcruiser DC	CAMBIO ALARMA RETROCESO	REPARACIÓN ALARMA DE RETROCESO	13/08/2021 91878		Corrective Order	WO Completed	Pickup truck
646713	Caterpillar 740B	REEMPLAZAR HARNESS	DESGASTE	13/08/2021		Corrective Order	WO Completed	Articulated dump truck
646762	Freightliner Cl 120	ajuste de frenos	AJUSTE DE FRENOS Y REPARAR FUGA DE AIRE	13/08/2021		Corrective Order	WO Completed	Mule truck
646764	Intraax 53121 Hendrickso	Reparacion y cambio de pines	REPARACION DE PINES PARA ANCLAR CONTENEDORES	13/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
646765	Caterpillar 740B EJ ADT	C/LINEA HYD SISTEMA FRENO	FUGA	13/08/2021 CENMAN		Corrective Order	WO Completed	Articulated dump truck
646778	Caterpillar 740B EJ ADT	C/BOMBA DE GRASA	EN MAL ESTADO	13/08/2021		Corrective Order	WO Completed	Articulated dump truck
646884	PRAMAC GSW460V 460 kVa	REPARAR BLOQUE REGISTRO	EN MAL ESTADO	13/08/2021 27851 horas		Corrective Order	WO Completed	Generator
646895	Unimog Service Truck	FUGA POR TANQUE HIDRÁULICO	FUGA POR TANQUE HIDRÁULICO	13/08/2021		Corrective Order	WO Completed	Truck
646896	Unimog Service Truck	FUGA SISTEMA DE FRENO	FUGA_DEL SISTEMA DE FRENO	13/08/2021 33957.9 Kms		Corrective Order	WO Completed	Truck
646897	DOOSAND 1005	LLAMADA DE EMERGENCIA	DERRAME DE LIQUIDO	13/08/2021 35986 hrs		Corrective Order	WO Completed	Light Tower
647046	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	14/08/2021 31237 hrs		Corrective Order	WO Completed	Generator
647048	Caterpillar CS533E Compactor	Correccion de fuga hidraulica	CORRECCION DE FUGA HIDRAULICA	14/08/2021		Corrective Order	WO Completed	Compactor
647080	Faresin FM4000 / 17F Telehandl	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	14/08/2021		Corrective Order	WO Completed	Telehender
647140	Freightliner Cl 120	FRENOS / NO MACHIMBRA	FRENOS / NO MACHIMBRA	14/08/2021		Corrective Order	WO Completed	Mule truck
647142	Freightliner Cl 120	Cambio V rela y parkin brake	FUGA DE AIRE	14/08/2021 90011598		Corrective Order	WO Completed	Mule truck
647167	Caterpillar 740B EJ ADT	C/ TUBERIA ENFRIAMIENTO TRANSM	ROTA	14/08/2021		Corrective Order	WO Completed	Articulated dump truck
647177	Freightliner Cl 120	Cambio de bujes de muelles y t	RUEIDO A NORMAL EN CHASIS	14/08/2021		Corrective Order	WO Completed	Mule truck
647193	Gallegos Lime Tank	FUGA DE AIRE	FUGA DE AIRE	14/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
647277	PRAMAC GSW65 48 kVa	REPARAR FUGA ACEITE	REGISTRO BLOQUE MOTOR	14/08/2021 25114 hrs		Corrective Order	WO Completed	Generator
647293	Caterpillar 740B EJ ADT	INSTA PROTECTOR MANGUERA	EVITAR PROYECCION DE FLUIDOS	14/08/2021		Corrective Order	WO Completed	Articulated dump truck
647399	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 21093 HORAS		PM Orders	WO Completed	Generator
647400	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 13697 horas		PM Orders	WO Completed	Generator
647401	PRAMAC GSW110 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 839 horas		PM Orders	WO Completed	Generator
647402	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 13169 horas		PM Orders	WO Completed	Generator
647404	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 29896 horas		PM Orders	WO Completed	Generator
647406	PRAMAC GSW460V 460 kVa	PM PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 27851 horas		PM Orders	WO Completed	Generator
647408	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 8066 hrs		PM Orders	WO Completed	Generator
647409	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 9737 horas		PM Orders	WO Completed	Generator
647410	PRAMAC GSW65 48 kVa	PM PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 24716 horas		PM Orders	WO Completed	Generator
647411	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 24338 HORS		PM Orders	WO Completed	Generator
647412	PRAMAC GSW30Y 24 kVa	PM PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 21733 horas		PM Orders	WO Completed	Generator
647413	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 12034 horas		PM Orders	WO Completed	Generator
647414	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 7650 HORAS		PM Orders	WO Completed	Generator
647415	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 771 hrs		PM Orders	WO Completed	Light Tower
647416	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 698 horas		PM Orders	WO Completed	Light Tower
647418	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 539 horas		PM Orders	WO Completed	Light Tower
647419	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 614 horas		PM Orders	WO Completed	Light Tower
647420	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 370 hrs		PM Orders	WO Completed	Light Tower
647421	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 396 horas		PM Orders	WO Completed	Light Tower
647422	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 383 horas		PM Orders	WO Completed	Light Tower
647423	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021 365 horas		PM Orders	WO Completed	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
647424	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	333 hrs	PM Orders	WO Completed	Light Tower
647425	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	293 hrs	PM Orders	WO Completed	Light Tower
647521	Broderon IC200-2C 9TON	reparacion electrica	REPARACION ELECTRICA	14/08/2021		Corrective Order	WO Completed	Crane/Hoist
647565	Caterpillar DE22E3 17.6 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	14965 horas	Corrective Order	WO Completed	Generator
647568	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	36250 horas	Corrective Order	WO Completed	Light Tower
647572	General Mobile MLT3060K	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	5057 horas	Corrective Order	WO Completed	Light Tower
647575	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	14/08/2021	14061 horas	Corrective Order	WO Completed	Light Tower
647639	Hyster H700 Forklift	Bajo Nivel de Coolant	BAJO NIVEL DE COOLANT	14/08/2021		Corrective Order	WO Completed	Forklift
647640	John Deere 9370R Tractor	PROGRAMACIÓN DE COMPUTADORA	PROGRAMACIÓN DE COMPUTADORA	14/08/2021		Corrective Order	WO Completed	Tractor
647641	Caterpillar 307E Miniexcavator	PROBLEMAS DE ARRANQUE	PROBLEMAS DE ARRANQUE	14/08/2021		Corrective Order	WO Completed	Excavator
647643	Grove RT650E 45TON	EQUIPO NO ARRANCA	EQUIPO NO ARRANCA	14/08/2021		Corrective Order	WO Completed	Crane/Hoist
647647	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647648	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647649	Mobile equipment	suministro	SUMINISTRO	14/08/2021		Corrective Order	WO Completed	Area
647651	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647652	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647653	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647654	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 02 LLANTAS	14/08/2021		Corrective Order	WO Completed	Pickup truck
647657	Caterpillar 416E	Fuga de aceite hidraulico	REVISION DE FUGA HIDRAULICA POR CILINDRO DE DIRECCION DELANTERA	14/08/2021	90011599	Corrective Order	WO Completed	Backhoe
647860	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021	17056 HORAS	PM Orders	WO Completed	Generator
647922	PRAMAC GSW30Y 24 kVa	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	15/08/2021	21341 hrs	Corrective Order	WO Completed	Generator
647925	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	SIN COMBUSTIBLE	15/08/2021	27547 hrs	Corrective Order	WO Completed	Generator
647932	Caterpillar 226b Skid Steer L	Cambio de tuberias	FUGA HIDRAULICA POR TUBERIAS DEL BALDE	15/08/2021		Corrective Order	WO Completed	Skid Steer
647942	Caterpillar 14M Motorgrader	Niveles bajo de aceite hidrául	NIVELES BAJO DE ACEITE HIDRÁUL	15/08/2021		Corrective Order	WO Completed	Grader
647946	Caterpillar 12M Motorgrader	Botando aceite de un diferenci	BOTANDO ACEITE DE UN DIFERENCI	15/08/2021		Corrective Order	WO Completed	Grader
647956	WT015 H7 CISTERNA SINOTRUK	LEVANTAMIENTO DE BALINERAS	INSPECCION	15/08/2021		Corrective Order	WO Completed	Water truck
647997	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021	88975	PM Orders	WO Completed	Pickup truck
647999	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Pickup truck
648000	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021	14835 kms	PM Orders	WO Completed	Pickup truck
648002	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Pickup truck
648004	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Pickup truck
648005	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Pickup truck
648006	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Pickup truck
648009	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021	45905 kms	PM Orders	WO Completed	Bus
648011	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Bus
648012	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Bus
648014	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	15/08/2021		PM Orders	WO Completed	Bus
648054	Power Curbers 5700-C	Compuertas inicial y final del	COMPUERTAS INICIAL Y FINAL DEL	15/08/2021		Corrective Order	WO Completed	Kerb Machine
648071	Caterpillar 740B EJ ADT	CONFECCION MANGUERA	CORRECTIVO	15/08/2021		Corrective Order	WO Completed	Articulated dump truck
648124	Caterpillar 740B EJ ADT	CONFECCION MANGUERA	CORRECTIVO	15/08/2021		Corrective Order	WO Completed	Articulated dump truck
648155	PT050 NMR85L-HH5WA ISUZU	Cambio de Llanta	CAMBIO DE LLANTA	15/08/2021		Corrective Order	WO Completed	Truck
648184	JLG 800 AJ Manlift	Mobimientos bloqueados	MOBIMIENTOS BLOQUEADOS	15/08/2021		Corrective Order	WO Completed	Manlift
648186	Manitou Mht-X1490 9t Telehand	revisar nivel de aceite	REVISAR NIVEL DE ACEITE	15/08/2021		Corrective Order	WO Completed	Telehender
648193	Caterpillar 740b Ej	C/LINEA NEUMATICA	REQUIERE CAMBIO	15/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
648210	Olympian GEP150 135 kVa	EVALUAR PROGRAMACION ATS	PROGRAMAR DISPLAY CON ATS	15/08/2021	6705 horas	Corrective Order	WO Completed	Generator
648234	Hyster H700 Forklift	Daño de Turbo Compresor	DAÑO DE TURBO COMPRESOR	15/08/2021	AUTO CLOSED	Corrective Order	WO Completed	Forklift
648272	Caterpillar 226b Skid Steer L	Inpeccion de equipo	INPECCION DE EQUIPO	15/08/2021		Corrective Order	WO Completed	Skid Steer
648274	Freightliner M112 Truck Tip	Cambio de 2 llantas	LLANTAS EN MAL ESTADO	15/08/2021		Corrective Order	WO Completed	Tipper
648275	Intraax 53121 Hendrickso	cambio de 3 llantas	LLANTAS EN MAL ESTADO	15/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648277	Unimog Service Truck	Fuga de aceite hidraulico	MANGUERA ROTA DE ACEITE HIDRAULICO	15/08/2021	33,457.90 km	Corrective Order	WO Completed	Truck
648303	Caterpillar 14M Motorgrader	Inspeccion mensual AFEX	INSPECCION MENSUAL AFEX	15/08/2021		Corrective Order	WO Completed	Grader
648305	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	15/08/2021		Corrective Order	WO Completed	Pickup truck
648306	Landcruiser DC	cambio de 1 llanta	LLANTA EN MAL ESTADO	15/08/2021		Corrective Order	WO Completed	Pickup truck
648471	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	16/08/2021		Corrective Order	WO Completed	Pickup truck
648472	Hyster H70ft 3t Forklift (M)	INSPECCION EQUIPO,ELIMINAR COD	REVISION FAULT 676-3	16/08/2021	2,650.00 hrs	Corrective Order	WO Completed	Forklift
648473	DOOSAND 1005	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	16/08/2021	36034 hrs	Corrective Order	WO Completed	Light Tower
648499	Hyster E70xn 3t Forklift (E)	INSP ALARMA RETROCESO Y LUCES	EQUIPO COPAMA EVALUA	16/08/2021		Corrective Order	WO Completed	Forklift
648512	Unimog Service Truck	ENGINE & RADIATOR REMOVE	CORRECTIVE	16/08/2021		Corrective Order	WO Completed	Truck
648548	Broce Broom RJT 350	EVALUAR SIST FRENOS DEL EQUIPO	PROBLEMA CON LOS FRENOS	16/08/2021		Corrective Order	WO Completed	Scrubber / Sweeper
648562	Freightliner M2 112 Sucker Tru	Confeccionar mangueras	CONFECCIONAR MANGUERAS	16/08/2021		Corrective Order	WO Completed	Sucker truck
648567	Freightliner M2 112 Sucker Tru	confeccion de acoples y mangue	CONFECCION DE ACOPLES Y MANGUERAS	16/08/2021		Corrective Order	WO Completed	Sucker truck
648574	Mobile equipment	COMPRA HERRAMIENTAS GENSET	IMPLEMENTACION TALLER	16/08/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Area
648578	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	16/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648586	Gallegos 28M3 Lime Tank	LLANTA FLAT	LLANTA FLAT	16/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648673	Cargador 966H Wheel Loader	No enciende	NO ENCIENDE	16/08/2021		Corrective Order	WO Completed	Loader
648797	Gallegos Flatbed Trailer	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	16/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648800	ETNYRE QUAD	CAMBIO DE BATERÍA	CAMBIO DE BATERÍA	16/08/2021		Corrective Order	WO Completed	Chip Spreader

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
648805	Caterpillar D8T Dozer		BLADE REPLACEMENT	CORRECTIVE	16/08/2021			Corrective Order	WO Completed	Dozer
648811	Gallegos Lime Tank		ajustar frenos	REVIZAR FRENOS	16/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648851	Gallegos Lime Tank		Cambio de bandas, rachet y amo	REVIZAR FRENOS	16/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648853	Gallegos Flatbed Trailer		cambio de 2 llantas	LLANTAS EN MAL ESTADO	16/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
648854	Freightliner CI 120		LLANTA FLAT, SWITCH Y FRENO	LLANTA FLAT, CAMBIO DE TROMPITO Y FRENO	16/08/2021			Corrective Order	WO Completed	Mule truck
648875	Hilux DC		Reemplazo de rim	REEMPLAZO DE RIM	16/08/2021			Corrective Order	WO Completed	Pickup truck
648876	Freightliner M2 112		Reemplazo de baterias	REEMPLAZO DE BATERIAS	16/08/2021			Corrective Order	WO Completed	Boom truck
648878	PRAMAC GSW460V 460 kVa		LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	16/08/2021	31279 hrs		Corrective Order	WO Completed	Generator
648879	DOOSAND 1005		LLAMADA DE EMERGENCIA	CAMBIO DE CAPACITADOR	16/08/2021	24479 hrs		Corrective Order	WO Completed	Light Tower
648887	ATLAS COPCO HILIGHT V5+		CORRECTIVO	CORRECTIVO	16/08/2021	0.00 hrs		Corrective Order	WO Completed	Light Tower
648888	ATLAS COPCO HILIGHT V5+		CORRECTIVO	CORRECTIVO	16/08/2021	0.00 hrs		Corrective Order	WO Completed	Light Tower
649127	Hilux DC		PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	17/08/2021			PM Orders	WO Completed	Pickup truck
649211	ATLAS COPCO HILIGHT V5+		CORRECTIVO	CORRECTIVO	17/08/2021	0.00 hrs		Corrective Order	WO Completed	Light Tower
649215	ATLAS COPCO HILIGHT V5+		CORRECTIVO	CORRECTIVO	17/08/2021	0.00 hrs		Corrective Order	WO Completed	Light Tower
649232	Freightliner Columbia CI112		cambio de 1 llanta	LLANTA EN MAL ESTADO	17/08/2021			Corrective Order	WO Completed	Mule truck
649242	Landcruiser DC		Reparacion de 1 llanta	LLANTA FLAT	17/08/2021			Corrective Order	WO Completed	Pickup truck
649243	Caterpillar RM500 Reclaimer		Reemplazo de herramientas	REEMPLAZO DE HERRAMIENTAS DE CORTE	17/08/2021			Corrective Order	WO Completed	Road Reclaimer
649244	Freightliner M2 106 Sucker Tru		cambio de sensor de transmisio	SENSOR DE TRANSMISION	17/08/2021	60021861		Corrective Order	WO Completed	Sucker truck
649245	John Deere 9370R Tractor		acople de compactador	ACOPLE DE COMPACTADOR	17/08/2021			Corrective Order	WO Completed	Tractor
649246	ATR-0000-001 4+320 AGRICO		acople de rastra	ACOPLE DE RASTRA	17/08/2021			Corrective Order	WO Completed	Tractor
649248	Cargador 966H Wheel Loader		Cambio de palanca de transmisi	PALANCA DE LA TRANSMISION CON EXCESO DE JUEGO	17/08/2021	90011724		Corrective Order	WO Completed	Loader
649272	Gallegos Flatbed Trailer		LLANTA FLAT / AUSTE DE FRENOS	LLANTA FLAT / AUSTE DE FRENOS	17/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
649292	Olympian GEP150 135 kVa		REVISION Y DIAGOSTICO	REVISION DE SISTEMA	17/08/2021	64.5 HORAS		Corrective Order	WO Completed	Generator
649311	Mobile equipment		Confeccion de acoples	SISTEMA DE SUCCIÓN DE LAS BOMBAS DE ACEITE USADO EN TALLER	17/08/2021			Corrective Order	WO Completed	Area
649354	GROVE RT600E 50TON		RADIATOR REPAIRS (ALASKA)	CORRECTIVE	17/08/2021	AUTO CLOSED		Corrective Order	WO Completed	Crane/Hoist
649363	Caterpillar 416F2 Backhoe		salió pin del brazo trasero	SALIÓ PIN DEL BRAZO TRASERO	17/08/2021			Corrective Order	WO Completed	Backhoe
649368	Caterpillar 140K		Cambio de cuchilla	CAMBIO DE CUCHILLA	17/08/2021			Corrective Order	WO Completed	Grader
649390	JLG 800 AJ Manlift		Cambio de Manguera	CAMBIO DE MANGUERA	17/08/2021			Corrective Order	WO Completed	Manlift
649471	Caterpillar 416F2 Backhoe		PIN REPLACEMENT	CORRECTIVE	17/08/2021	90011884		Corrective Order	WO Completed	Backhoe
649529	Caterpillar 740B		C/CINTURON DE SEGURIDAD	CINTURON EN MAL ESTADO	17/08/2021			Corrective Order	WO Completed	Articulated dump truck
649577	Atlas Copco GESAN QIS 45 47KVA		DESMONTE BE ALTERNADOR AC	PARA EPARACION	17/08/2021	5303 HORAS		Corrective Order	WO Completed	Generator
649596	DOOSAND 1005		CORRECTIVO	CORRECTIVO	17/08/2021	36077 hrs		Corrective Order	WO Completed	Light Tower
649604	Gallegos Flatbed Trailer		Revision de frenos y luces	REVISION Y AJUSTE DE FRENOS E INSDPECCION DE LUCES	17/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
649606	Caterpillar CS533E Compactor		Fuga de refrigerante	REVISION DE FUGA DE REFRIGERANTE	17/08/2021	11430.1 Hrs		Corrective Order	WO Completed	Compactor
649607	Coaster		TIRE AND RING INSPECT/CHANGE	REEMPLAZO DE LLANTAS	17/08/2021			Corrective Order	WO Completed	Bus
649608	Coaster		Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/08/2021			Corrective Order	WO Completed	Bus
649780	PRAMAC GSW30Y 24 kVa		LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	18/08/2021	21401 hrs		Corrective Order	WO Completed	Generator
649797	SJS SJ6530		Reparacionj de componentes	REEMPLAZO DE PERNOS ROTOS	18/08/2021			Corrective Order	WO Completed	Compactor
649799	PRAMAC GSW460V 460 kVa		LLAMADA DE EMERGENCIA	EQUIPO SIN COMBUSTIBLE	18/08/2021	27575 hrs		Corrective Order	WO Completed	Generator
649806	Cargador 966H Wheel Loader		Inspeccion TA1	INSPECCION TA1	18/08/2021	2487406 Hrs		Corrective Order	WO Completed	Loader
649807	Cargador 966H Wheel Loader		Corto electrico en el equipo	REPARACION DE CORTOCIRCUITO ELECTRICO EN EL EQUIPO	18/08/2021	24876.4 Hrs		Corrective Order	WO Completed	Loader
649813	Manitou Mht-X860 6t Telehand		Fuga de aceite en motor	REVISION DE EQUIPO POR FUGA DE ACEITE EN EL MOTOR	18/08/2021			Corrective Order	WO Completed	Telehender
649822	Caterpillar 12M Motorgrader		Cambio de hoja de corte	CAMBIO DE HOJA DE CORTE	18/08/2021			Corrective Order	WO Completed	Grader
649824	Caterpillar 14H Motorgrader		Cambio de hoja de corte	CAMBIO DE HOJA DE CORTE	18/08/2021			Corrective Order	WO Completed	Grader
649826	Caterpillar 14H Motorgrader		Alarma de transmision activada	ALARMA DE TRANSMISION ACTIVADA	18/08/2021			Corrective Order	WO Completed	Grader
649871	Freightliner CI 120		cambio de 2 llantas	LLANTAS EN MAL ESTADO	18/08/2021			Corrective Order	WO Completed	Mule truck
649885	Freightliner M2 112 Sucker Tru		Cambio de manguera hidráulica	CAMBIO DE MANGUERA HIDRÁULICA	18/08/2021			Corrective Order	WO Completed	Sucker truck
650059	Freightliner Columbia CI112		CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	18/08/2021			Corrective Order	WO Completed	Mule truck
650087	Manitou Mht-X1490 9t Telehand		Direccion de emergencia no sir	DIRECCION DE EMERGENCIA NO SIR	18/08/2021			Corrective Order	WO Completed	Telehender
650125	Caterpillar D8T Dozer		MANTENIMEINTO SEMESTRAL AFEX	MANTENIMIENTO SEMESTRAL AFEX	18/08/2021			Corrective Order	WO Completed	Dozer
650129	Cargador 966H Wheel Loader		MANTENIMIENTO MENSUAL AFEX	MANTENIMIENTO MENSUAL AFEX	18/08/2021			Corrective Order	WO Completed	Loader
650213	Freightliner CI 120		CAMBIO DE 8 NEUMÁTICOS	CAMBIO DE 8 NEUMÁTICOS	18/08/2021			Corrective Order	WO Completed	Mule truck
650222	Gallegos Flatbed Trailer		LLANTA FLAT	LLANTA FLAT	18/08/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
650240	International 7400 SBA Fire Tr		Reparación de neumático	REPARACIÓN DE NEUMÁTICO	18/08/2021			Corrective Order	WO Completed	Fire truck
650265	Freightliner CI 120		CAMBIO DE VALVULA	CAMBIO DE VALVULA	19/08/2021			Corrective Order	WO Completed	Mule truck
650400	International 7400 SBA Fire Tr		cambio de depurador de aire	FUGA POR SISTEMA DE DEPURACION DE AIRE	19/08/2021			Corrective Order	WO Completed	Fire truck
650420	Caterpillar CS533E Compactor		equipo con falla en motor c	EQUIPO SE APAGA	19/08/2021			Corrective Order	WO Completed	Compactor
650447	Freightliner 8170ME Water Truc		IAMPARA DELANTERA FLOJA	LAMPARA DELANTERA FLOJA	19/08/2021			Corrective Order	WO Completed	Water truck
650462	Caterpillar 12M		LLANTA FLAT	LLANTA FLAT	19/08/2021			Corrective Order	WO Completed	Grader
650663	Caterpillar 14H Motorgrader		CAMBIO DE FITTING DE ENGRASE	CAMBIO DE FITTING DE ENGRASE	19/08/2021			Corrective Order	WO Completed	Grader
650675	Hyster H300 13t Forklift (M)		AFTER MAINTENANCE CONDITIONS	CORRECTIVE	19/08/2021	90012144		Corrective Order	WO Completed	Forklift
650684	Hyster H300 Forklift		AFTER MAINTENANCE CONDITIONS	CORRECTIVE	19/08/2021	90012134 90011865		Corrective Order	WO Completed	Forklift
650700	Caterpillar D8T Dozer		Reemplazo de silenciador	REEMPLAZO DE SILENCIADOR	19/08/2021	90011871		Corrective Order	WO Completed	Dozer

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
650707	John Deere 9370R Tractor	FALLA DEL A/A	FALLA DEL A/A	19/08/2021		Corrective Order	WO Completed	Tractor
650709	John Deere 9370R Tractor	FALLA DEL SSTEMA AFEX	FALLA DEL SISTEMA AFEX	19/08/2021		Corrective Order	WO Completed	Tractor
650711	Freightliner Columbia Cl112	EQUIPO NO ARRANCA	EQUIPO NO ARRANCA	19/08/2021		Corrective Order	WO Completed	Mule truck
650726	Caterpillar D8T Dozer	PM4	PM4	20/08/2021		Corrective Order	WO Completed	Dozer
650998	Freightliner Cl 120	mangueras con fugas	REVISION GENERAL DEL EQUIPO,MANGUERAS ROTAS	20/08/2021	AUTO CLOSED	Corrective Order	WO Completed	Mule truck
651002	Caterpillar Tl1055clrc	Reparacion de ac	AC NO FUNCIONA	20/08/2021	4,455.00 hrs	Corrective Order	WO Completed	Telehender
651005	Caterpillar CS533E Compactor	Revision de sistema de luces	LUCES NO ENCIENDEN	20/08/2021		Corrective Order	WO Completed	Compactor
651108	Hilux DC	CAMBIO HOJA MUELLE	HOJA DE MAZO ESPRIN PARTIDA	20/08/2021		Corrective Order	WO Completed	Pickup truck
651144	Caterpillar 740B	C/MANGUERA SISTEMA HYD	MANGUERA FUGANDO POR ACOPLES	20/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
651152	Hino Dutro 300	REPARACION GENERAL	REVISAR OBSERVACIONES ADJUNTAS	20/08/2021	86198 KM	Corrective Order	WO Completed	Truck
651297	Freightliner Cl 120	BOLSA DE AIRE / PUERTA	BOLSA DE AIRE / PUERTA	20/08/2021		Corrective Order	WO Completed	Mule truck
651298	Freightliner Cl 120	AJUSTE DE FRENOS	AJUSTE DE FRENOS	20/08/2021		Corrective Order	WO Completed	Mule truck
651303	Freightliner Cl 120	CAMBIO DE COMPRESOR A/C	BALINERA / FRENOS	20/08/2021		Corrective Order	WO Completed	Mule truck
651304	Freightliner Cl 120	RETROSIVOR / ESCOBILLA	RETROSIVOR / ESCOBILLA /FUGA	20/08/2021		Corrective Order	WO Completed	Mule truck
651310	Freightliner Cl 120	VALVULA DE MACHIMBRE	VALVULA DE MACHIMBRE	20/08/2021		Corrective Order	WO Completed	Mule truck
651311	Freightliner Columbia Cl112	LUCES / FUGA POR ESCAPE	LUCES / FUGA POR ESCAPE	20/08/2021		Corrective Order	WO Completed	Mule truck
651313	Freightliner Columbia Cl112	REPARACION + BATERIAS	REPARACION GENERAL, BATERIAS	20/08/2021		Corrective Order	WO Completed	Mule truck
651314	Caterpillar 740b Ej	C/CRUCETAS Y TORNILLOS	EN MAL ESTADO	20/08/2021		Corrective Order	WO Completed	Articulated dump truck
651317	Freightliner Columbia Cl112	MANIGUETA/AMORTIGUADOR/MOFLE	MANIGUETA/AMORTIGUADOR/MOFLE	20/08/2021		Corrective Order	WO Completed	Mule truck
651326	Freightliner Columbia Cl112	LUCES / ESCOLTA	LUCES / ESCOLTA	20/08/2021	77276.9 km	Corrective Order	WO Completed	Mule truck
651331	Freightliner Columbia Cl112	LUCES	LUCES	20/08/2021		Corrective Order	WO Completed	Mule truck
651344	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	20/08/2021	27634 horas	Corrective Order	WO Completed	Generator
651381	Freightliner M2 106 Sucker Tru	Fuga de aceite de motor	REVISION DE FUGA DE ACEITE DE MOTOR	20/08/2021		Corrective Order	WO Completed	Sucker truck
651385	Caterpillar TL1055CLRC	CAMBIO DE NEUMÁTICOS	CAMBIO DE NEUMÁTICOS	20/08/2021		Corrective Order	WO Completed	Telehender
651387	WT013 H7 CISTERNA SINOTRUK	CAMBIO DE CRUCETA	CAMBIO DE CRUCETA	20/08/2021		Corrective Order	WO Completed	Water truck
651389	Caterpillar DP50 Forklift (M)	EQUIPO NEUTRALIZADO	EQUIPO NEUTRALIZADO	20/08/2021		Corrective Order	WO Completed	Forklift
651392	Dossan	CORRECTIVO	CORRECTIVO	20/08/2021	5833 hrs	Corrective Order	WO Completed	Generator
651393	Caterpillar 14H Motorgrader	ajuste de caja de prolink	CAJA DE SISTEMA PROLINK SUELTA	21/08/2021		Corrective Order	WO Completed	Grader
651395	New Holland Lm 1745	Cambio de componentes varios	REEMPLAZO DE COMPONENTES DE DIRECCION Y LAMPARAS	21/08/2021	90012125 90012100	Corrective Order	WO Completed	Telehender
651503	WT013 H7 CISTERNA SINOTRUK	Cambio de crucetas y yock	CAMBIO DE YOCK Y CRUCETAS	21/08/2021		Corrective Order	WO Completed	Water truck
651512	Hyster H300 Forklift	Reparacion de llanta	LLANTA FLAT	21/08/2021		Corrective Order	WO Completed	Forklift
651513	Caterpillar 226b Skid Steer L	mandos invertidos	MANDOS INVERTIDOS	21/08/2021		Corrective Order	WO Completed	Skid Steer
651544	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	21/08/2021		Corrective Order	WO Completed	Pickup truck
651586	Mobile equipment	Gas refrigerante para Taller	GAS REFRIGERANTE PARA TALLER	21/08/2021		Corrective Order	WO Completed	Area
651599	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651602	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651603	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021	76335	PM Orders	WO Completed	Pickup truck
651604	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651605	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651606	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021	6922	PM Orders	WO Completed	Pickup truck
651607	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651608	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651609	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651610	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651613	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Bus
651614	Hino Serie 300	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Truck
651615	Isuzu NMR85L	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021	63173	PM Orders	WO Completed	Truck
651617	PT050 NMR85L-HH5WA ISUZU	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021	280384	PM Orders	WO Completed	Truck
651697	Hino Serie 300	CAMBIO BOMBILLO	REPARAR LUCES TRASERAS	21/08/2021	107975	Corrective Order	WO Completed	Truck
651698	Caterpillar 740b Ej	C/MAQNGUE ENFRIAMIENTO FRENO	MANGUERA EN MAL ESTADO	21/08/2021		Corrective Order	WO Completed	Articulated dump truck
651701	Hino Serie 300	CAMBIO BATERIA	DESCARGA	21/08/2021	99337	Corrective Order	WO Completed	Truck
651716	Caterpillar 12M Motorgrader	Accugrade Control	CAMBIO DE PERNO	21/08/2021		Corrective Order	WO Completed	Grader
651727	Coaster	CAMBIO DE 6 LLANTAS	CAMBIO DE 6 LLANTAS	21/08/2021		Corrective Order	WO Completed	Bus
651735	Coaster	CAMBIO DE 4 NEUM]ATICOS	CAMBIO DE 4 NEUM[ATICOS	21/08/2021		Corrective Order	WO Completed	Bus
651737	Toyota Land Cruiser	A/C INSPECTION & REPAIR	CARGA DE GAS REFRIGERANTE	21/08/2021	153752	Corrective Order	WO Completed	Pickup truck
651740	Hino Series 300 Truck	REPARAR SISTEMA FRENO	LIMPIEZA BANDAS	21/08/2021		Corrective Order	WO Completed	Truck
651741	PB002 COASTER TOYOTA	CAMBIO BATERIA	CAMBIO 02 BATERIAS	21/08/2021		Corrective Order	WO Completed	Bus
651744	Hiace Bus	CAMBIO ESTABILIZADORA	CAMBIO BOMBILLO COLA PEZ	21/08/2021	57037	Corrective Order	WO Completed	Bus
651748	PB013 COASTER TOYOTA	CAMBIO BATERIA	CAMBIO 02 BATERIAS	21/08/2021	81983	Corrective Order	WO Completed	Bus
651750	Coaster	CAMBIO DE 2 NEUMATICOS	CAMBIO DE 2 NEUMATICOS	21/08/2021		Corrective Order	WO Completed	Bus
651754	Coaster	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICO	21/08/2021		Corrective Order	WO Completed	Bus
651775	Caterpillar 740B	C/LLANTA POS 3	POR FLAT	21/08/2021		Corrective Order	WO Completed	Articulated dump truck
651835	Caterpillar 740B	C/MANGUERA DEL SYS HYD	FUGA	21/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
651837	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021	78337	PM Orders	WO Completed	Pickup truck
651850	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651851	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
651855	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021 42020		PM Orders	WO Completed	Pickup truck
651858	Caterpillar 740b Ej	C/LINEA DE FRENO	FUGA DE ACEITE	21/08/2021		Corrective Order	WO Completed	Articulated dump truck
651869	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021 11757		PM Orders	WO Completed	Pickup truck
651870	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Pickup truck
651874	Hiace Bus	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021 67096		PM Orders	WO Completed	Bus
651877	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021 38359		PM Orders	WO Completed	Bus
651879	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/08/2021		PM Orders	WO Completed	Bus
651880	Hyster H700 Forklift	CAMBIO DE 6 NEUMATICOS	CORRECTIVO	21/08/2021		Corrective Order	WO Completed	Forklift
651885	Hyster H700 Forklift	Cambio de motor	CAMBIO DE MOTOR	21/08/2021 90011961		Corrective Order	WO Completed	Forklift
651912	Manitou Mht-X860 6t Telehand	Instalaci�n de Blower	INSTALACI�N DE BLOWER	21/08/2021		Corrective Order	WO Completed	Telehender
651918	Caterpillar 12M	Torniller�a para cambio de hoj	TORNILLER�A PARA CAMBIO DE HOJA	21/08/2021		Corrective Order	WO Completed	Grader
651924	Freightliner M2 106 Sucker Tru	Mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	21/08/2021		Corrective Order	WO Completed	Sucker truck
651951	Toyota Hilux	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Completed	Pickup truck
651952	Ford F550	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Completed	Pickup truck
651956	Hino Serie 300 Box Truck	GPS INSTALLING	TRACKING SYSTEM	21/08/2021		Corrective Order	WO Completed	Truck
651964	PRAMAC GSW110P 82 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	21/08/2021 13075 HORAS		Corrective Order	WO Completed	Generator
651965	Terex MAC25 25TON	retirro dde cable	RETIRO DDE CABLE	21/08/2021		Corrective Order	WO Completed	Crane/Hoist
651970	Freightliner M2 106 Refrigerat	No arranca detenido en la via	NO ARRANCA DETENIDO EN LA VIA	21/08/2021 72312.5 kms		Corrective Order	WO Completed	Refrigerator truck
651978	Freightliner 8170ME Water Truc	Equipo No arranca	EQUIPO NO ARRANCA	21/08/2021		Corrective Order	WO Completed	Water truck
651981	New Holland Lm 1745	Manguera de Combustible	MANGUERA DE COMBUSTIBLE	21/08/2021		Corrective Order	WO Completed	Telehender
651982	Gallegos Flatbed Trailer	Cambio de Esparrago	CAMBIO DE ESPARRAGO	21/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
651994	Freightliner 8170ME Water Truc	EQUIPO NO ARRANCA	EQUIPO NO ARRANCA	21/08/2021 El medidor de kms no funciona		Corrective Order	WO Completed	Water truck
652220	Caterpillar 236d Skid Steer L	Revision de fuga	REVISION DE FUGA DE ACEITE DE MOTOR	22/08/2021 4083.6 Hrs		Corrective Order	WO Completed	Skid Steer
652221	Freightliner M2 106 Hydroseedi	Revision de equipo	REPARACION DE ESCALERAS Y CADENAS DE LAS BOMBAS	22/08/2021		Corrective Order	WO Completed	Truck
652224	Gallegos Flatbed Trailer	Reparacion de llanta	REPARACION DE LLANTA	22/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
652225	Coaster	Reparacion de llanta	REEMPLAZO DE LLANTA	22/08/2021		Corrective Order	WO Completed	Bus
652227	Hilux DC	Reparacion de llanta	REEMPLAZO DE LLANTA	22/08/2021		Corrective Order	WO Completed	Pickup truck
652235	JLG 1250 AJP Manlift	Revision de equipo	REVISION DE CODIGOS ACTIVOS	22/08/2021		Corrective Order	WO Completed	Manlift
652243	Caterpillar 740b Ej	C/SENSORES	SENSORES DEFECTUOSOS	22/08/2021		Corrective Order	WO Completed	Articulated dump truck
652250	Caterpillar 416F2 Backhoe	Pierde fuerza	PIERDE FUERZA	22/08/2021		Corrective Order	WO Completed	Backhoe
652251	Internation F2674	Alarma activada al encender	ALARMA ACTIVADA AL ENCENDER	22/08/2021		Corrective Order	WO Completed	Boom truck
652286	Caterpillar C9 250 kVa	LIMPIEZA GENERAL EQUIPO	LAVADO RADIADOR	22/08/2021 20588 hras		Corrective Order	WO Completed	Generator
652297	Caterpillar 740b Ej	C/ACCIONADOR FRENO ESTACIONAM	ACCIONADOR PRESENTA FUGA	22/08/2021		Corrective Order	WO Completed	Articulated dump truck
652426	New Holland Lm 1745	Confecci�n de Manguera	CONFECCI�N DE MANGUERA	22/08/2021		Corrective Order	WO Completed	Telehender
652427	Caterpillar 12M Motorgrader	Dano en el alternador	DANO EN EL ALTERNADOR	22/08/2021		Corrective Order	WO Completed	Grader
652429	Caterpillar 416E	No arranca	NO ARRANCA	22/08/2021		Corrective Order	WO Completed	Backhoe
652459	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	22/08/2021 24990 horas		PM Orders	WO Completed	Generator
652460	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	22/08/2021 17472 hrs		PM Orders	WO Completed	Generator
652461	PRAMAC GSW90P 74 kVa	PM PRA GSW90P MEC 300 HR	PM PRA GSW90P MEC 300 HR	22/08/2021 25798 horas		PM Orders	WO Completed	Generator
652462	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	22/08/2021 23551 HORAS		PM Orders	WO Completed	Generator
652496	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	22/08/2021 19547 horas		PM Orders	WO Completed	Generator
652515	Caterpillar 12M Motorgrader	SISTEMA AFEX	SISTEMA AFEX	22/08/2021		Corrective Order	WO Completed	Grader
652519	Caterpillar 740b Ej	C/MANG DE TRANSMISION HOIST	DESGASTE/HORAS DE SERVICIO	22/08/2021 CENMAN		Corrective Order	WO Completed	Articulated dump truck
652523	PRAMAC GSW460V 460 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE RADIADOR	22/08/2021 NO TIENE LECTURA		Corrective Order	WO Completed	Generator
652567	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652568	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652569	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652570	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652571	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652572	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652575	Landcruiser DC	A/C INSPECTION & REPAIR	REPARACION DE AC	22/08/2021		Corrective Order	WO Completed	Pickup truck
652576	Landcruiser DC	EVALUAR MOTOR	PERDIDA FUERZA/RUIDOS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652577	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/08/2021		Corrective Order	WO Completed	Pickup truck
652580	Internation F2674	Cambio de Compresor de AC	COMPRESOR DE A/C DA�ADO	22/08/2021		Corrective Order	WO Completed	Boom truck
652594	WT015 H7 CISTERNA SINOTRUK	cambio de filtro de diesel	FUGA DE COMBUSTIBLE	22/08/2021 6521.2 Kms		Corrective Order	WO Completed	Water truck
652788	Caterpillar DE88E0 58 kVa	PM CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	23/08/2021 37272 horas		PM Orders	WO Completed	Generator
652789	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	23/08/2021 18767 horas		PM Orders	WO Completed	Generator
652790	PRAMAC GSW560V 407 kVa	PM PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	23/08/2021 14974 horas		PM Orders	WO Completed	Generator
652810	Freightliner M2 106 Sucker Tru	Revision electrica del equipo	REVISION ELECTRICA DEL EQUIPO	23/08/2021		Corrective Order	WO Completed	Sucker truck
652811	Eagle Beaver 50sgl-Pt	Frenos /esparragos de llanta	REVISION DE FRENOS- CAMBIO DE ESPARRAGOS DE LLANTA	23/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
652877	Freightliner CI 120	Instalacion de componentes	INSTALACION DE COMPONENTES.	23/08/2021 353514.4 Kms		Corrective Order	WO Completed	Mule truck
652880	Grove GMK4100L 100TON	revisoion de equipo	REVISION DE EQUIPO	23/08/2021		Corrective Order	WO Completed	Crane/Hoist
652881	Freightliner M2 106 Hydroseedi	reparacion de escalera y def	REPARACION DE ESCALERA Y DEFENSA	23/08/2021		Corrective Order	WO Completed	Truck
652890	Freightliner 8170ME Water Truc	Rrevision de embrague	REVISION DE EMBRAGUE	23/08/2021		Corrective Order	WO Completed	Water truck
652914	Power Curbers 5700-C	Mnguera hidraulica danada	MNGUERA HIDRAULICA DANADA	23/08/2021		Corrective Order	WO Completed	Kerb Machine
653000	EX036 EC480DL Volvo	REP/ SCI AFEX	INABILITADO	23/08/2021		Corrective Order	WO Completed	Excavator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
653037	Bell 225f 4t Forklift (M)	Falla del alternador	FALLA DEL ALTERNADOR	23/08/2021		Corrective Order	WO Completed	Forklift
653069	EX036 EC480DL Volvo	EC480DL-MAINTENANCE 2000 HRS	EC480DL-MAINTENANCE 2000 HRS	23/08/2021	NECESARIO CA COMPTOS	PM proposal JDE	WO Completed	Excavator
653168	Freightliner M2 106 Sucker Tru	Reparacion de A/A	REPARACION DE A/A	23/08/2021		Corrective Order	WO Completed	Sucker truck
653183	EX036 EC480DL Volvo	C/MANG HYD CONTROL DE VALVULAS	DESGASTADAS	23/08/2021	CENMAN	Corrective Order	WO Completed	Excavator
653189	CAT 930K	BUCKET REPLACEMENT (NEW)	CORRECTIVE	23/08/2021	90012231	Corrective Order	WO Completed	Loader
653196	Freightliner 8170ME Water Truc	regreso de equip[os	REGRESO DE EREPUESTOS	23/08/2021		Corrective Order	WO Completed	Water truck
653278	Hyster H800 32t Forklift (M)	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	23/08/2021	90013282	Corrective Order	WO Completed	Forklift
653299	Hyster E70xn 3t Forklift (E)	AFTER MAINTENANCE CONDITIONS	CORRECTIVE	23/08/2021	90012321 90013781	Corrective Order	WO Completed	Forklift
653323	Grove RT880E 75TON	Falla de Comunicaci3n	FALLA DE COMUNICACI3N	23/08/2021		Corrective Order	WO Completed	Crane/Hoist
653606	Mobile equipment	Reparacion de llanta	REPARACOION DE LLANTA JCB DE MOLINOS	24/08/2021		Corrective Order	WO Completed	Area
653618	Freightliner M112 Truck Tip	Revision de luces	REVISION DE LUCES Y REVISION ELECTRICA DEL EQUIPO	24/08/2021		Corrective Order	WO Completed	Tipper
653621	Freightliner 8170ME Water Truc	Reparacion de llanta	REEMPLAZO DE LLANTA	24/08/2021	5063.4 Hrs	Corrective Order	WO Completed	Water truck
653697	SDMO J60U 60KVA	EQUIPO SE APAGA	LLAMADO DE EMERGENCIA	24/08/2021	11923 horas	Corrective Order	WO Completed	Generator
653709	WT013 H7 CISTERNA SINOTRUK	Reparacion de bomba de agua	REPARACION DE BOMBA DE AGUA	24/08/2021		Corrective Order	WO Completed	Water truck
653762	Hyster H300 13t Forklift (M)	LLANTA FLAT	LLANTA FLAT	24/08/2021		Corrective Order	WO Completed	Forklift
653768	EX036 EC480DL Volvo	FAB/MANGUERA DEL SISTEMA AFEX	DESGASTE	24/08/2021	CENMAN	Corrective Order	WO Completed	Excavator
653771	Caterpillar 12M Motorgrader	fabricar manguerasd	FABRICAR MANGUERAS	24/08/2021		Corrective Order	WO Completed	Grader
653787	EX036 EC480DL Volvo	C/CILINDRO DE BUCKET	FUGA INTERNA	24/08/2021	Reporte P1	Corrective Order	WO Completed	Excavator
653850	Caterpillar RM300	FABRICACION DE MANGUERAS	CAMBIO PERSONAL IASA	24/08/2021		Corrective Order	WO Completed	Road Reclaimer
654201	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654202	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654203	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654283	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654284	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654285	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654291	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654312	Freightliner M2 106 Hydroseedi	Aceite de Transmisión y A/A	NIVEL DE ACEITE DE TRANSMISI3N Y REPARACI3N DEL A/A	25/08/2021		Corrective Order	WO Completed	Truck
654318	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654320	Bell 225f 4t Forklift (M)	CAMBIO DE BATERÍA	CAMBIO DE BATERÍA	25/08/2021		Corrective Order	WO Completed	Forklift
654321	PRAMAC GSW110P 82 kVa	LLAMADA DE EMERGENCIA	EQUIPO APADO	25/08/2021	14002 horas	Corrective Order	WO Completed	Generator
654349	Freightliner M2 106 Sucker Tru	Rueda trasera izquierda tranca	RUEDA TRASERA IZQUIERDA TRANCADA	25/08/2021		Corrective Order	WO Completed	Sucker truck
654351	Caterpillar 307E Miniexcavator	Equipo Descarrilado	EQUIPO DESCARRILADO	25/08/2021		Corrective Order	WO Completed	Excavator
654424	WT013 H7 CISTERNA SINOTRUK	reparacion de eje	REPARACION DE EJE	25/08/2021	Emerergency	Corrective Order	WO Completed	Water truck
654433	PRAMAC GSW110P 82 kVa	LAVADO DE RADIADOR	RADIADOR OBSTRUIDO Y SUCIO	25/08/2021	13163 horas	Corrective Order	WO Completed	Generator
654479	Freightliner CI 120	reposicion de llantas cambiada	REPOSICION DE LLANTAS CAMBIADAS	25/08/2021		Corrective Order	WO Completed	Mule truck
654516	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021	30681	PM Orders	WO Completed	Bus
654518	Landcruiser DC	REPARACION DE ALTERNADOR	DESGASTE DE BROCHAS	25/08/2021	9953.00	Corrective Order	WO Completed	Pickup truck
654523	Hilux DC	CAMBIO DE CORREA UNICA ACC	INSTALACION DE PERTIGA NUEVA	25/08/2021	41667.00	Corrective Order	WO Completed	Pickup truck
654524	Coaster	GOLPE EN TANQUE DE COMBUSTIBLE	GOLPE EN TANQUE DE COMBUSTIBLE	25/08/2021	38359.00	Corrective Order	WO Completed	Bus
654528	Coaster Bus	REPARACION DE ODOMETRO	ENGRASE DE BALINERAS TRASERAS	25/08/2021	74952.00	Corrective Order	WO Completed	Bus
654529	Landcruiser DC	CAMBIO DE ALTERNADOR	MANTENIMIENTO CORRECTIVO	25/08/2021	57630.00	Corrective Order	WO Completed	Pickup truck
654530	Landcruiser DC	CAMBIO DE ALTERNADOR	MANTENIMIENTO CORRECTIVO	25/08/2021	36662.00	Corrective Order	WO Completed	Pickup truck
654531	Hilux DC	CAMBIO DE EXTINTOR	MANTENIMIENTO CORRECTIVO	25/08/2021	57630.00	Corrective Order	WO Completed	Pickup truck
654533	Hilux DC	REVISION DE LUCES	CAMBIO ALARMA RETROCESO	25/08/2021	4675.00	Corrective Order	WO Completed	Pickup truck
654534	Landcruiser DC	CAMBIO DIFERENCIAL DELANTERO	CAMBIO DE EJES FLECHAS, TACOS, CALIPER LH, CRUZETAS, TERMINALES, BALINERAS.	25/08/2021	25873.00	Corrective Order	WO Completed	Pickup truck
654535	Landcruiser DC	CAMBIO DE MOTOR DE ARRANQUE	MANTENIMIENTO CORRECTIVO	25/08/2021	9953.00	Corrective Order	WO Completed	Pickup truck
654545	Coaster	REPARACIONES ELECTRICAS	MANTENIMIENTO CORRECTIVO	25/08/2021	3566.00	Corrective Order	WO Completed	Bus
654555	Landcruiser TC	CAMBIO CLUTCH RETEN DE DIFEREN	CAMBIO DE CLUTCH, RETENEDORA DE DIFERENCIAL	25/08/2021	43100.00	Corrective Order	WO Completed	Pickup truck
654574	Coaster	CAMBIO DE BRAZO SUSPENSION	CAMBIO DE PLATO SUSP.REPARACION DE CAJA DE FILTRO DE AIRE POR GOLPE.	25/08/2021	37241.00	Corrective Order	WO Completed	Bus
654580	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021	44524.00	PM Orders	WO Completed	Pickup truck
654589	Hilux DC	REPARACION CABLEADO	REPARACION CABLEADO DE AX4	25/08/2021	66781.00	Corrective Order	WO Completed	Pickup truck
654597	Landcruiser TC	CAMBIO BALINERAS/COCOBOLAS	CAMBIO DE COCOBOLA LH,REPARACION DE CERRADURAS,A/C	25/08/2021	44525.00	Corrective Order	WO Completed	Pickup truck
654605	Hilux DC	REPARCION DE CORTO EN ALARMA	FALSO CONTACTO	25/08/2021	19637.00	Corrective Order	WO Completed	Pickup truck
654612	WT013 H7 CISTERNA SINOTRUK	soldadura y fabricacion bases	SOLDADURA Y FABRICACION BASES	25/08/2021		Corrective Order	WO Completed	Water truck
654614	Landcruiser TC	AIRE A/C,CAJA DE TIMON	ESPERA EVAPORADOR,CAJA TIMON	25/08/2021	7241.00	Corrective Order	WO Completed	Pickup truck
654616	Grove RT880E 75TON	fabricacion de mangueras	FABRICACION DCDE MANGUERAS	25/08/2021		Corrective Order	WO Completed	Crane/Hoist
654618	Hilux DC	CREMALLERA,BOMBA	CAMBIO DE CREMALLERA,BOMA	25/08/2021	66550.00	Corrective Order	WO Completed	Pickup truck
654631	Caterpillar 740B EJ ADT	bomba de sistema de W/W	BOMBA DEL SISTEMA DE W/W	25/08/2021		Corrective Order	WO Completed	Articulated dump truck
654669	Caterpillar 12M Motorgrader	cable de alternador reventado	CABLE DE ALTERNADOR REVENTADO	25/08/2021		Corrective Order	WO Completed	Grader
654720	Caterpillar 12M Motorgrader	HORN REPLACEMENT	CORRECTIVE	25/08/2021		Corrective Order	WO Completed	Grader
654723	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654724	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021	47155	PM Orders	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
654726	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654728	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654729	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654730	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654731	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654733	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Bus
654738	Toyota Land Cruiser	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654752	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	25/08/2021		PM Orders	WO Completed	Pickup truck
654754	Caterpillar RM300	CAMBIO DE FILTRO	REPORADO IASA	25/08/2021		Corrective Order	WO Completed	Road Reclaimer
654755	PRAMAC GSW110P 82 kVa	FALLO DE TEMPERATURA	LLAMADA DE EMERGENCIA	25/08/2021	13163 horas	Corrective Order	WO Completed	Generator
654765	Gmc Boom Truck	gmc tRUCK	GMC TRUCK	25/08/2021		Corrective Order	WO Completed	Boom truck
654779	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654780	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654782	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654784	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/08/2021		Corrective Order	WO Completed	Pickup truck
654865	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	26/08/2021		PM Orders	WO Completed	Pickup truck
654893	Freightliner M2 112 Sucker Tru	cambio de Baterías	CAMBIO DE BATERÍAS	26/08/2021		Corrective Order	WO Completed	Sucker truck
655075	Caterpillar 12M Motorgrader	CAMBIO ESCARIFICADOR	CORRECTIVE	26/08/2021		Corrective Order	WO Completed	Grader
655101	Gallegos Lime Tank	PATAS DURAS/FUGA DE AIRE	PATAS DURAS/FUGA DE AIRE	26/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
655152	Freightliner CI 120	ACEITE / LLANTA BAJA	ACEITE / LLANTA BAJA	26/08/2021		Corrective Order	WO Completed	Mule truck
655154	Caterpillar CS533E Compactor	Reventó Correa	REVENTÓ CORREA	26/08/2021		Corrective Order	WO Completed	Compactor
655167	Caterpillar RM500 Reclaimer	BITUMEN PUMP REPLACEMENT	CORRECTIVE	26/08/2021	90013272	Corrective Order	WO Completed	Road Reclaimer
655168	Terex RT5551 55TON	Cambio de mangueras	CAMBIO DE MANGUERAS	26/08/2021		Corrective Order	WO Completed	Crane/Hoist
655174	Gallegos Flatbed Trailer	Reparacion de frenos	REPARACION DE LLANTAS	26/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
655214	EX036 EC480DL Volvo	CAMBIO DE VIDRIO FRONTAL	VIDRIO FISURADO	26/08/2021		Corrective Order	WO Completed	Excavator
655304	Caterpillar TI1055clrc	reparqacion de llantas	REPARACION DE LLANTAS	26/08/2021		Corrective Order	WO Completed	Telehender
655312	Caterpillar 416E	no realiza los movimientos	NO REALIZXA LOS MOVCImientos	26/08/2021		Corrective Order	WO Completed	Backhoe
655314	Caterpillar 14M Motorgrader	Inspeccion post reparacion	INSPECCION POST REPARACION	26/08/2021		Corrective Order	WO Completed	Grader
655316	Freightliner FL112	Reparacion de llantas	REPARACION DE LLANTAS	26/08/2021		Corrective Order	WO Completed	Boom truck
655331	Shuttlelift RTCD5540F 15TON	Cambio de Batería	CAMBIO DE BATERÍA	26/08/2021		Corrective Order	WO Completed	Crane/Hoist
655333	Caterpillar CS74 Compactor	CAMBIO DE CORREA	CAMBIO DE CORREA	26/08/2021		Corrective Order	WO Completed	Compactor
655528	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	27/08/2021		Corrective Order	WO Completed	Pickup truck
655529	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	27/08/2021		Corrective Order	WO Completed	Pickup truck
655530	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	27/08/2021		Corrective Order	WO Completed	Pickup truck
655531	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	27/08/2021		Corrective Order	WO Completed	Pickup truck
655533	Landcruiser DC	Cambio de neumático y Rim	CAMBIO DE NEUMÁTICO Y RIN	27/08/2021		Corrective Order	WO Completed	Pickup truck
655619	Caterpillar 12M	Instalación de Pin de cilindro	INSTALACIÓN DE PIN DE CILINDRO DE INCLINACIÓN DE LA HOJA	27/08/2021		Corrective Order	WO Completed	Grader
655624	John Deere 9370R Tractor	NIVEL DE ACEITE HIDRÁULICO	BAJO NIVEL DE ACEITE HIDRAULICO	27/08/2021		Corrective Order	WO Completed	Tractor
655648	Caterpillar 12M	Pin de la hoja	PIN DE LA HOJA SE SALIÓ	27/08/2021		Corrective Order	WO Completed	Grader
655652	Freightliner M112 Truck Tip	llanta trasera flat	LLANTA TRASERA FLAT	27/08/2021		Corrective Order	WO Completed	Tipper
655666	Caterpillar 740b Ej	C/MANG AUTO LUB	MANGUERA EN MAL ESTADO	27/08/2021	CENMAN	Corrective Order	WO Completed	Articulated dump truck
655694	Caterpillar 14M Motorgrader	AFEX SYSTEM MAINT & REPAIR	PREVENTIVE MAINTENANCE	27/08/2021	90012240	Corrective Order	WO Completed	Grader
655755	Caterpillar 426f2 Backhoe	Baterías	BATERIA	27/08/2021		Corrective Order	WO Completed	Backhoe
655762	Caterpillar 426F2 Backhoe	Cambio de llantas	CAMBIO DE LLANTAS	27/08/2021		Corrective Order	WO Completed	Backhoe
655800	New Holland LM 1745	Grua,para montaje.	GRUA,PARA MONTAJE.	27/08/2021	SOPORTE W34	Corrective Order	WO Completed	Telehender
655802	Caterpillar CS533E Compactor	BELT REPLACEMENT	CORRECTIVE	27/08/2021		Corrective Order	WO Completed	Compactor
655814	PRAMAC GSW170i 164 kVa	FALLO DE INTERRUPTOR	LLAMADA DE EMERGENCIA	27/08/2021	5551 horas	Corrective Order	WO Completed	Generator
655914	Caterpillar 426F2 Backhoe	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	27/08/2021		Corrective Order	WO Completed	Backhoe
655929	PRAMAC GSW170i 164 kVa	CIRCUIT BREAKER REPLACE	CORRECTIVE MAINTENANCE	27/08/2021	5551 HORAS	Corrective Order	WO Completed	Generator
655976	Freightliner M2 112 Sucker Tru	Instalacion de acoples mang	INSTALACION DE ACOPLS DE MANGUERAS SUCCION	27/08/2021		Corrective Order	WO Completed	Sucker truck
655977	Unimog Service Truck	revisar grua	REVISSAR GRUA	27/08/2021		Corrective Order	WO Completed	Truck
655979	Eagle Beaver 50sgl-Pt	Reparacion de del motor	REAPARACION DE MOTOR DE COMBUSTION DEL SISTEMA DE HIDRAULICO	27/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
655980	JLG 1250 AJP Manlift	Bloqueado los movimientos	BLOQUEADO LOS MOVIMIENTOS	27/08/2021		Corrective Order	WO Completed	Manlift
655981	JLG 800 AJ Manlift	Bloqueado los movimientos	BLOQUEADO LOS MOVIMIENTOS	27/08/2021		Corrective Order	WO Completed	Manlift
655982	Case 110JX Tractor Cable Handl	reparacion de llanta y rim	REPARAVCION DE LLANTA Y RIN	27/08/2021		Corrective Order	WO Completed	Tractor
656000	Caterpillar 14M Motorgrader	PROBLEMAS DE DIRECCIÓN	PROBLEMAS DE DIRECCIÓN, CONFECCIÓN DE MANGUERAS	27/08/2021		Corrective Order	WO Completed	Grader
656002	Caterpillar 12M	REPARACIÓN SISTEMA AFEX	REPARACIÓN SISTEMA AFEX	27/08/2021		Corrective Order	WO Completed	Grader
656104	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656151	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656152	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656153	Landcruiser DC	Cambio de 3 neumaticos	CAMBIO DE 3 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656155	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656159	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656160	Landcruiser DC	CAMBIO DE 2 NEUMÁTICO	CAMBIO DE 2 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
656161	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656197	Caterpillar D6T LGP	CONFECCEI;ON DE MANGUERA	CONFECCIÓN DE MANGUERA	28/08/2021		Corrective Order	WO Completed	Dozer
656199	Bomag BW24RH	EQUIPO NO ENCIENDE	EQUIPO NO ENCIENDE	28/08/2021		Corrective Order	WO Completed	Roller PTR
656200	Caterpillar CS74 Compactor	EQUIPO NO ENCIENDE	EQUIPO NO ENCIENDE	28/08/2021		Corrective Order	WO Completed	Compactor
656204	Freightliner Columbia C1112	INSTALACIÓN DE RETROVISOR	INSTALACIÓN DE RETROVISOR	28/08/2021		Corrective Order	WO Completed	Mule truck
656284	Caterpillar 426F2 Backhoe	CONFECCEION MANGUERA	CORRECTIVE	28/08/2021		Corrective Order	WO Completed	Backhoe
656289	Caterpillar 740B EJ ADT	C/ PERNO SUJECCION DE TOLVA	PERNOS ROTOS	28/08/2021		Corrective Order	WO Completed	Articulated dump truck
656414	PRAMAC GSW170i 164 kVa	CAMBIO DE VOLTAGE	VOLTAGE DE 400V A 480V	28/08/2021 5551 horas		Corrective Order	WO Completed	Generator
656416	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/08/2021 90891		PM Orders	WO Completed	Pickup truck
656420	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/08/2021 137754		PM Orders	WO Completed	Pickup truck
656449	Case 110JX Tractor Cable Handl	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/08/2021		Corrective Order	WO Completed	Tractor
656459	Caterpillar DE165E0 165 kVa	LAVADO DE RADIADOR	FALLO POR ALTA TEMPERATURA, RADIADOR SUCIO	28/08/2021 16255 horas		Corrective Order	WO Completed	Generator
656464	Caterpillar 740B EJ ADT	PM04-PREVENTIVE MAINTENANCE	PM04-PREVENTIVE MAINTENANCE	28/08/2021		Corrective Order	WO Completed	Articulated dump truck
656493	Landcruiser TC	CAMBIO ARO NEUMATICO	CAMBIO 04 RINES	28/08/2021 90012369		Corrective Order	WO Completed	Pickup truck
656502	Caterpillar C9 250 kVa	REVISION DE EQUIPO	EQUIPO CON FALLO DE DOS INYECTORES	28/08/2021 19839 horas		Corrective Order	WO Completed	Generator
656504	EX036 EC480DL Volvo	C/ TUBERIAS CILINDRO BUCKET	TUBERIAS EN MAL ESTADO	28/08/2021 90013199		Corrective Order	WO Completed	Excavator
656543	Landcruiser TC	CAMBIO ARO NEUMATICO	CAMBIO 01 RIN	28/08/2021 90012374		Corrective Order	WO Completed	Pickup truck
656546	Caterpillar 426f2 Backhoe	TA1 MECANICO POR IIASA	INSPECCION	28/08/2021 90012312		Corrective Order	WO Completed	Backhoe
656556	Olympian GEP150 135 kVa	CONG. DE CONRXION DE ATS	INSPECCION, CONEXION DE ATS	28/08/2021 64.5 horas		Corrective Order	WO Completed	Generator
656585	Freightliner CI 120	Reparacion de llantas	REPARACION DE LLANTAS	28/08/2021		Corrective Order	WO Completed	Mule truck
656589	Mobile equipment	BATERÍA PARA SF006	BATERÍA PARA SF006	28/08/2021		Corrective Order	WO Completed	Area
656590	Coaster	CAMBIO DE3 NEUMATICOS	CAMBIO DE 3 NEUMATICOS	28/08/2021		Corrective Order	WO Completed	Bus
656593	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656597	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656598	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/08/2021		Corrective Order	WO Completed	Pickup truck
656599	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	29/08/2021		Corrective Order	WO Completed	Pickup truck
656862	Manitou Mht-X1490 9t Telehand	Bajo de Aceite Hidraulico	BAJO DE ACEITE HIDRAULICO, MANGUERA DE TURBO	29/08/2021		Corrective Order	WO Completed	Telehender
656865	Caterpillar TL642	EQUIPO NEUTRALIZADO	EQUIPO NEUTRALIZADO	29/08/2021		Corrective Order	WO Completed	Telehender
656866	Grove GMK4100L 100TON	EVALUAR FRENO ESTACIONAMIENTO	LUZ DE FRENO ESTACIONAMIENTO	29/08/2021		Corrective Order	WO Completed	Crane/Hoist
656871	Caterpillar 307E Miniexcavator	INSPECCION SISTEMA RODADO	REPORT DE IASA	29/08/2021		Corrective Order	WO Completed	Excavator
656884	TTP-0000-102	Reparacion de mangueras	REPARACION DE MANGUERAS	29/08/2021		Corrective Order	WO Completed	Excavator
656885	Caterpillar 307E Miniexcavator	REPARACION DE BASTIDOR	REPORT DE IASA	29/08/2021		Corrective Order	WO Completed	Excavator
656898	PRAMAC GSW80P 83 kVa	CAMBIO DE HORAS DE CONTROL	CONTROL CON HORAS NO CORRESPONDIENTES	29/08/2021 10802 hora		Corrective Order	WO Completed	Generator
656913	Caterpillar 336DL	PM4 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	29/08/2021		Corrective Order	WO Completed	Excavator
656916	Hilux DC	Cambio de llantas	CAMBIO DE LLANTAS	29/08/2021		Corrective Order	WO Completed	Pickup truck
656931	Freightliner 8170ME Water Truc	Fuga en los tanques de aire	FUGA EN LOS TANQUES DE AIRE	29/08/2021		Corrective Order	WO Completed	Water truck
656933	Caterpillar RM300	Fuga de diesel	FUGA DE DIESEL	29/08/2021		Corrective Order	WO Completed	Road Reclaimer
656936	Hilux DC	A/C INSPECTION & REPAIR	RVISION DEL AIRE ACONDICIONAD	29/08/2021		Corrective Order	WO Completed	Pickup truck
656958	Unimog Service Truck	NSPECCION DE DIRECCION DURA	DIRECCION DURA	29/08/2021		Corrective Order	WO Completed	Truck
656974	Landcruiser DC	Cambio de llantas	CAMBIO DE LLANTAS	29/08/2021		Corrective Order	WO Completed	Pickup truck
656996	Hyster E70xn 3t Forklift (E)	MECHANICAL INSPECT BY COPAMA	INSPECTION	29/08/2021		Corrective Order	WO Completed	Forklift
656997	Hiace Bus	Cambio de llantas	CAMBIO DE LLANTAS	29/08/2021		Corrective Order	WO Completed	Bus
656998	Hyster E70xn 3t Forklift (E)	MECHANICAL INSPECT BY COPAMA	INSPECTION	29/08/2021		Corrective Order	WO Completed	Forklift
657000	Landcruiser DC	Cambio de llantas	CAMBIO DE LLANTAS	29/08/2021		Corrective Order	WO Completed	Pickup truck
657003	EX036 EC480DL Volvo	C/CASQUILLO	EXTRAVIADO	29/08/2021		Corrective Order	WO Completed	Excavator
657034	GS246 DE110E2 CAT	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 24011 hrs		PM Orders	WO Completed	Generator
657039	FG WILSON P88-3 80 kVa	PM FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 25300 horas		PM Orders	WO Completed	Generator
657040	Caterpillar DE165E0 165 kVa	PM CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 16378 horas		PM Orders	WO Completed	Generator
657043	Caterpillar DE110E 110 kVa	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 21429 horas		PM Orders	WO Completed	Generator
657044	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 17844 hrs		PM Orders	WO Completed	Generator
657045	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 14067 horas		PM Orders	WO Completed	Generator
657046	Caterpillar D110 E2 100KVA	PM CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 17520 horas		PM Orders	WO Completed	Generator
657047	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 13541 hrs		PM Orders	WO Completed	Generator
657048	PRAMAC GSW110P 82 kVa	PM PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 14365 horas		PM Orders	WO Completed	Generator
657050	Caterpillar C4.4 88KVA	PM CAT C4.4 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 30428 horas		PM Orders	WO Completed	Generator
657051	PRAMAC GSW170i 164 kVa	PM PRA GSW170i MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 5609 horas		PM Orders	WO Completed	Generator
657052	USP&E GP700S/V-A 700 kVa	PM UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 16914 horas		PM Orders	WO Completed	Generator
657053	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 20588 horas		PM Orders	WO Completed	Generator
657054	Caterpillar C9 250 kVa	PM CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 20349 horas		PM Orders	WO Completed	Generator
657055	SDMO J60U 60 kVa	PM SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 6387 hrs		PM Orders	WO Completed	Generator
657057	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 8353 horas		PM Orders	WO Completed	Generator
657058	SDMO T11UM 10KVA	PM SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 17393 horas		PM Orders	WO Completed	Generator
657060	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 16876 horas		PM Orders	WO Completed	Generator
657061	PRAMAC GBW15 14 kVa	PM PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 24674 horas		PM Orders	WO Completed	Generator
657062	Olympian GEP18-6 18KVA	PM OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 29.27khr		PM Orders	WO Completed	Generator
657063	SDMO T16 16KVA	PM SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021 23908 hrs		PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
657064	Pramac GSW30P 24KVA	PM PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	12380 horas	PM Orders	WO Completed	Generator
657065	Expert Power PN45 10KVA	PM EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	7988 horas	PM Orders	WO Completed	Generator
657067	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	676 hrs	PM Orders	WO Completed	Light Tower
657068	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	509 horas	PM Orders	WO Completed	Light Tower
657069	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	650 hrs	PM Orders	WO Completed	Light Tower
657070	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	372 hors	PM Orders	WO Completed	Light Tower
657102	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	10911 hrs	Corrective Order	WO Completed	Generator
657123	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	3685 horas	Corrective Order	WO Completed	Light Tower
657124	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	4466 horas	Corrective Order	WO Completed	Light Tower
657130	DOOSAN 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	29011 horas	Corrective Order	WO Completed	Light Tower
657131	DOOSAND 1005	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	24608 horas	Corrective Order	WO Completed	Light Tower
657132	MAGNUM Light Tower	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	27128 horas	Corrective Order	WO Completed	Light Tower
657133	General Mobile MLT3060K	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	29/08/2021	5068 horas	Corrective Order	WO Completed	Light Tower
657153	Hyster H300 Forklift	INSTALACION DE TAPA DE COMBUST	INSTALACION DE TAPA DE COMBUST	29/08/2021		Corrective Order	WO Completed	Forklift
657162	Caterpillar 12M	FABRICACION MANGUERA	PERSONAL DE IASA	29/08/2021		Corrective Order	WO Completed	Grader
657186	PRAMAC GSW460V 460 kVa	CAMBIO DE GENERADOR	LLAMADA DE EMERGENCIA	29/08/2021	31279 horas	Corrective Order	WO Completed	Generator
657208	Grove RT880E 75TON	recalentamiento	RECALENTAMIENTO	29/08/2021		Corrective Order	WO Completed	Crane/Hoist
657209	Grove GMK4100L 100TON	testigos activos en el tablero	TESTIGO DE SEGURIDFAD DE CARGA	29/08/2021		Corrective Order	WO Completed	Crane/Hoist
657211	Gallegos Flatbed Trailer	reparacion de llantas	REPARACION DE LLANTAS	29/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
657213	Freightliner M2 106 Sucker Tru	Reparacion de frenos	REPARACION DE FRENOS	29/08/2021		Corrective Order	WO Completed	Sucker truck
657277	PRAMAC GSW460V 460 kVa	EQUIPO SIN DIESEL	LLAMADA DE EMERGENCIA	29/08/2021	27805 horas	Corrective Order	WO Completed	Generator
657522	Caterpillar 336DL	PIN DE CADENA	PIN DE CADENA	30/08/2021		Corrective Order	WO Completed	Excavator
657532	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	30/08/2021	6307 horas	Corrective Order	WO Completed	Generator
657548	Doosan D1005	CAMBIO CABLE Y CAPACITORES	MANTENIMIENTO CORRECTIVO	30/08/2021	18571 HRS	Corrective Order	WO Completed	Light Tower
657577	Freightliner M2 106 Refrigerat	Cambio de llantas	CAMBIO DE LLANTAS	30/08/2021		Corrective Order	WO Completed	Refrigerator truck
657597	ETNYRE QUAD	Daño en la manguera hidráulica	DAÑO EN LA MANGUERA HIDRÁULICA	30/08/2021		Corrective Order	WO Completed	Chip Spreader
657627	USP&E GP700S/V-A 700 kVa	FALLO POR PRESION DE DIESEL	LLAMADA DE EMERGENCIA	30/08/2021	24004 horas	Corrective Order	WO Completed	Generator
657631	Gallegos Flatbed Trailer	CAMBIO DE PINES Y LUCES	INSPECCION GENERAL	30/08/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
657676	Caterpillar 236d Skid Steer L	FABRICACION DE MANGUERAS	PERSONAL DE IASA	30/08/2021	AUTO CLOSED	Corrective Order	WO Completed	Skid Steer
657884	Manitou Mht-X1490 9t Telehand	Llanta Flat	LLANTA FLAT	30/08/2021		Corrective Order	WO Completed	Telehender
657915	Caterpillar 416F2 Backhoe	No arranca	NO ARRANCA	30/08/2021		Corrective Order	WO Completed	Backhoe
657925	Freightliner Columbia Cl112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	30/08/2021		Corrective Order	WO Completed	Mule truck
657929	Freightliner Columbia Cl112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	30/08/2021	90012360	Corrective Order	WO Completed	Mule truck
657930	Freightliner Columbia Cl112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	30/08/2021		Corrective Order	WO Completed	Mule truck
657953	Coaster	Reparacion de llantas	REPARACION DE LLANTAS	30/08/2021		Corrective Order	WO Completed	Bus
657959	Freightliner Columbia Cl112	Reparacion de llantas	REPARACION DE LLANTAS	30/08/2021		Corrective Order	WO Completed	Mule truck
658053	Coaster	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUMÁTICOS	30/08/2021		Corrective Order	WO Completed	Bus
658057	Freightliner M2 106 Refrigerat	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	30/08/2021		Corrective Order	WO Completed	Refrigerator truck
658060	Mobile equipment	Acetileno y Oxigeno taller	ACETILENO Y OXIGENO PARA TALLER TACTICO	31/08/2021		Corrective Order	WO Completed	Area
658441	Landcruiser TC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658444	Landcruiser DC	CAMBIO DE UN NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658445	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658446	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658447	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658449	Freightliner Columbia Cl112	Alarma de reversa	ALARMA DE REVERSA	31/08/2021		Corrective Order	WO Completed	Mule truck
658456	Freightliner Columbia Cl112	Instalación de GPS	INSTALACIÓN DE GPS	31/08/2021		Corrective Order	WO Completed	Mule truck
658459	Landcruiser DC	A/C INSPECTION & REPAIR	NO ENFRIA	31/08/2021		Corrective Order	WO Completed	Pickup truck
658525	Hyster H300 Forklift	CAMBIO DE COMPONENTES	SUGERIDOS EQ COPAMA MINA	31/08/2021		Corrective Order	WO Completed	Forklift
658526	Caterpillar 12M	Manguera rota (Piston de los r	MANGUERA ROTA (PISTON DE LOS R	31/08/2021		Corrective Order	WO Completed	Grader
658601	Doosan D1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/08/2021	18758 hrs	PM Orders	WO Completed	Light Tower
658604	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/08/2021	23094 hrs	PM Orders	WO Completed	Light Tower
658606	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/08/2021	23385 hrs	PM Orders	WO Completed	Light Tower
658607	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/08/2021	25071 hrs	PM Orders	WO Completed	Light Tower
658617	PRAMAC GSW110P 82 kVa	CAMBIO DE ALTERNADOR DC Y BAT	LLAMADA DE EMERGENCIA	31/08/2021	14141 horas	Corrective Order	WO Completed	Generator
658624	Hyster H700 Forklift	cambio de manngueras	CAMBIO DE MANGUERAS	31/08/2021		Corrective Order	WO Completed	Forklift
658677	Freightliner M2 106 Hydroseedi	cambio de escobillas/rep caden	CAMBIO DE SSCOBILLAS	31/08/2021		Corrective Order	WO Completed	Truck
658683	Landcruiser DC	cambio de escobillas	CAMBIO DE ESCOBILLAS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658685	Unimog Service Truck	INSPECCION DE NEUMATICOS	LLANTA DE NEUMATICO FLAT	31/08/2021		Corrective Order	WO Completed	Truck
658708	PRAMAC GSW560V 407 kVa	FALLO DE PLACA DE DIODOS	LLAMADA DE EMERGENCIA	31/08/2021	14974 hrs	Corrective Order	WO Completed	Generator
658719	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658720	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658722	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658723	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658724	Landcruiser TC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	31/08/2021		Corrective Order	WO Completed	Pickup truck
658726	Coaster	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Bus
658729	Coaster	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	31/08/2021		Corrective Order	WO Completed	Bus
658879	Doosan D1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/09/2021		PM Orders	WO Completed	Light Tower
658880	Doosan D1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/09/2021	12613 horas	PM Orders	WO Completed	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
658881	DOOSAN 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/09/2021	20242 hrs	PM Orders	WO Completed	Light Tower
658882	DOOSAN 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/09/2021	29337 hrs	PM Orders	WO Completed	Light Tower
658883	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	01/09/2021	24926 hrs	PM Orders	WO Completed	Light Tower
658944	PRAMAC GSW460V 460 kVa	LIMPIEZA GENERAL DEL EQUIPO	QUIPO SUCIO	01/09/2021	19870 HORAS	Corrective Order	WO Completed	Generator
658948	Caterpillar PS-150C	Fuga de coolant	FUGA DE COOLANT	01/09/2021		Corrective Order	WO Completed	Roller PTR
659023	Caterpillar 236d Skid Steer L	REPARACION DE TANDEM	EQUIPO IASA	01/09/2021		Corrective Order	WO Completed	Skid Steer
659043	Freightliner Cl 120	AJUSTE DE CLUTCH / REVISION	AJUSTE DE CLUTCH / REVISION	01/09/2021		Corrective Order	WO Completed	Mule truck
659054	Gallegos Flatbed Trailer	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	01/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
659077	PRAMAC GSW460V 460 kVa	LIMPIEZA PREINSTALACION ALT AC	LIMPIEZA E INSPECCION	01/09/2021	19870 horas	Corrective Order	WO Completed	Generator
659079	Caterpillar CS74 Compactor	Se apago y no da inicio	SE APAGO Y NO DA INICIO	01/09/2021		Corrective Order	WO Completed	Compactor
659081	Freightliner 8170ME Water Truc	Fuga de emulsión en la tubería	FUGA DE EMULSIÓN EN LA TUBERIA	01/09/2021		Corrective Order	WO Completed	Water truck
659087	Broce Broom RJT 350	Cambio de escobillas	CAMBIO DE ESCOBILLAS	01/09/2021		Corrective Order	WO Completed	Scrubber / Sweeper
659098	Caterpillar 740B	C/ SELLO MANGUERAS HIDRAULICAS	SELLOS ROTOS	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659103	Caterpillar 740B	C/ TUBO FLEXIBLE DE ESCAPE	TUBO ROTO	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659105	Caterpillar 740B	C/ CARTER DEL MOTOR	EMPAQUE ROTO	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659149	Caterpillar 740B	C/ MANG HYD CILINDRO LEVANTE	MANGUERA ROTA	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659284	Caterpillar 740b Ej	C/ ZAPATA FRENO	ZAPATA DESGASTADA	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659297	Caterpillar CS74 Compactor	No activa el vibrador	SE APAGO Y NO DA INICIO	01/09/2021		Corrective Order	WO Completed	Compactor
659313	Grove RT880E 75TON	CAMBIO DE MOTOR DE ARRANQUE	PERSONAL TACTICO	01/09/2021		Corrective Order	WO Completed	Crane/Hoist
659334	Caterpillar 740B	EJE CARDAN CENTRAL POSTERIOR	CRUCETAS DESGASTADO	01/09/2021		Corrective Order	WO Completed	Articulated dump truck
659338	USP&E GP700/V-A 700 kVa	FALLO POR ALTA TEMPERATURA	LLAMADA DE EMERGENCIA	01/09/2021	10483 horas	Corrective Order	WO Completed	Generator
659339	Caterpillar C7.1 200 kVa	MOVIMIENTO DE GENERADOR	SE MOVILIZA GENERADOR A BANDA TRANSPORTADORA PARA REPARACION	01/09/2021	16559 horas	Corrective Order	WO Completed	Generator
659453	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	02/09/2021	10324 horas	PM Orders	WO Completed	Generator
659454	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	02/09/2021	12668 horas	PM Orders	WO Completed	Generator
659455	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	02/09/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
659497	Landcruiser TC	CAMBIO DE 2 NEUMÁTICO	CAMBIO DE 2 NEUMÁTICOS	02/09/2021		Corrective Order	WO Completed	Pickup truck
659588	Mobile equipment	ANALISIS ACEITE AGOSTO 21	SERVI FLOTA TACTICA // IASA	02/09/2021	50016084	Corrective Order	WO Completed	Area
659613	Freightliner 8170ME Water Truc	Llanta Flat	LLANTA FLAT	02/09/2021		Corrective Order	WO Completed	Water truck
659629	Freightliner Columbia Cl112	FLAT TIRE	FLAT TIRE	02/09/2021		Corrective Order	WO Completed	Mule truck
659631	Gallegos Flatbed Trailer	FLAT TIRE	FLAT TIRE	02/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
659633	Gallegos 28M3 Lime Tank	PATAS EN MAL ESTADO	PATAS EN MAL ESTADO	02/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
659640	JLG 1250 AJP Manlift	Cambio de mangueras	CAMBIO DE MANGUERAS	02/09/2021		Corrective Order	WO Completed	Manlift
659695	Caterpillar D110 E2 100KVA	LAMADA DE EMERGENCIA	REEMPLAZO DE ALT DC Y BATERIA	02/09/2021	17697 horas	Corrective Order	WO Completed	Generator
659749	PRAMAC GSW560V 407 kVa	EQUIPO DESINCRONIZADO	FALLO POR PRESION DE DIESEL, SE DESINCRONIZA	02/09/2021	18779 horas	Corrective Order	WO Completed	Generator
659775	Caterpillar 426f2 Backhoe	Fabricacion de mangueras	FABRICACION DE MANGUERAS	02/09/2021		Corrective Order	WO Completed	Backhoe
659777	Caterpillar 416F2 Backhoe	revisar fuga de aceite	REVISAR FUGA DE ACEITE	02/09/2021		Corrective Order	WO Completed	Backhoe
659782	Hilux DC	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	02/09/2021		Corrective Order	WO Completed	Pickup truck
659846	Power Curbers 5700-C	Pierde fuerza y revoluciones,	PIERDE FUERZA Y REVOLUCIONES,	02/09/2021		Corrective Order	WO Completed	Kerb Machine
659867	Caterpillar C9 250 kVa	LLAMADA DE EMERGENCIA	EVALUACION Y DIAGNOSTICO	02/09/2021	19786 horas	Corrective Order	WO Completed	Generator
659873	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	REMPLAZO DE ALT DC Y BATERIA	02/09/2021	25898 hrs	Corrective Order	WO Completed	Generator
659910	Caterpillar 336DL	FABRICACION DE MANGUERAS	PEROSNAL DE IASA	02/09/2021		Corrective Order	WO Completed	Excavator
659912	John Deere 9370R Tractor	Reparacion de llantaimplemento	REPARACION DE LLANTA DEL IMPLEMENTO	02/09/2021		Corrective Order	WO Completed	Tractor
659978	Power Curbers 5700-C	Fallo en la dirección, no se d	FALLO EN LA DIRECCIÓN, NO SE DESPLAZA, NO SUBE, NO GIRA	02/09/2021		Corrective Order	WO Completed	Kerb Machine
660037	Caterpillar C9 250 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	02/09/2021	19787 horas	Corrective Order	WO Completed	Generator
660044	PRAMAC GSW90P 74 kVa	FALLO DE BATERIA	LLAMADA DE EMERGENCIA	02/09/2021	25853 horas	Corrective Order	WO Completed	Generator
660045	TTP-0000-102	Filtros faltantes	FILTROS FALTANTES	02/09/2021		Corrective Order	WO Completed	Excavator
660046	Caterpillar 226b Skid Steer L	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	02/09/2021		Corrective Order	WO Completed	Skid Steer
660061	Hilux DC	CAMBIO DE 2 NEUMÁTICO	CAMBIO DE 2 NEUMÁTICOS	02/09/2021		Corrective Order	WO Completed	Pickup truck
660062	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	02/09/2021		Corrective Order	WO Completed	Pickup truck
660063	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	02/09/2021		Corrective Order	WO Completed	Pickup truck
660065	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	03/09/2021		Corrective Order	WO Completed	Pickup truck
660066	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	03/09/2021		Corrective Order	WO Completed	Pickup truck
660077	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	03/09/2021		Corrective Order	WO Completed	Pickup truck
660078	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	03/09/2021		Corrective Order	WO Completed	Pickup truck
660079	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	03/09/2021		Corrective Order	WO Completed	Pickup truck
660310	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/09/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
660311	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/09/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
660312	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/09/2021	18837 horas	PM Orders	WO Completed	Generator
660378	Mobile equipment	Gas refrigerante para Taller	GAS REFRRIGERANTE PARA TALLER	03/09/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
660399	Freightliner M2 106 Refrigerat	REPARAR MARCO DE PUERTA Y PISO	REPARAR MARCO DE PUERTA Y PISO	03/09/2021		Corrective Order	WO Completed	Refrigerator truck
660436	Caterpillar 236d Skid Steer L	FABRICACION MANGUERAS	PERSONAL DE IASA	03/09/2021	AUTO CLOSED	Corrective Order	WO Completed	Skid Steer
660438	Caterpillar 236d Skid Steer L	REPARACION DE AIRE ACONDICIONA	PERSONAL DE IASA	03/09/2021		Corrective Order	WO Completed	Skid Steer
660446	Gallegos Lime Tank	FUGA POR ESCOTILLAS	FUGA POR ESCOTILLAS	03/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
660453	Caterpillar CS74 Compactor	Luces delanteras estan quemada	LUCES DELANTERAS ESTAN QUEMADA	03/09/2021		Corrective Order	WO Completed	Compactor
660459	Caterpillar 12M	Aire Acondicionado	AIRE ACONDICIONADO	03/09/2021	12271 hrs	Corrective Order	WO Completed	Grader
660462	Freightliner 8170ME Water Truc	CAMBIO DE RETROVISOR	CAMBIO DE RETROVISOR	03/09/2021		Corrective Order	WO Completed	Water truck
660479	Grove RT600E 50TON	CÓDIGO E AB	C ÓDIGO E AB,	03/09/2021		Corrective Order	WO Completed	Crane/Hoist
660483	Caterpillar 14M Motorgrader	Fuga de aceite hidráulico en e	FUGA DE ACEITE HIDRÁULICO EN E	03/09/2021		Corrective Order	WO Completed	Grader
660487	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Completed	Pickup truck
660489	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Completed	Pickup truck
660497	Toyota Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Completed	Pickup truck
660500	PT050 NMR85L-HH5WA ISUZU	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	03/09/2021		PM Orders	WO Completed	Truck
660564	JLG T350 Manlift	cambio de cargador	CAMBIO DE CARGADOR DE BATERIAS	03/09/2021	90013599 900132600 90013601	Corrective Order	WO Completed	Manlift
660575	Caterpillar 740B EJ ADT	FLUSHING-MF#5,MF#6,DIF#3	FLUSHING-MF#5,MF#6,DIF#3	03/09/2021		Corrective Order	WO Completed	Articulated dump truck
660578	Caterpillar 740B EJ ADT	FLUSHING-MF2	FLUSHING-MF2	03/09/2021		Corrective Order	WO Completed	Articulated dump truck
660744	Caterpillar 226b Skid Steer L	revisar niveles de aceite hydr	REVISAR NIVELES DDE HIDRAULICOS	03/09/2021		Corrective Order	WO Completed	Skid Steer
660752	Mack Trucks GU	revisar sistema de arranque	REVISAR SISTEMA DE ARRANQUE/REPARACION DE CILINDRO HIDRAULICO	03/09/2021		Corrective Order	WO Completed	Boom truck
660807	New Holland Lm 1745	reparar selenoide de valvula	REPARAR SELENOIDE VALVULA DE INCLINACION	03/09/2021		Corrective Order	WO Completed	Telehender
660825	Gallegos Lime Tank	cambio de lantas	CAMBIO DE LLANTAS	03/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
660893	WT015 H7 CISTERNA SINOTRUK	revisar direccion	REVISAR DIRECCION	03/09/2021		Corrective Order	WO Completed	Water truck
661120	FG WILSON P88-1 64 kVa	COLOCACION DE BATERIA	MATENIMIENTO DE BATERIA	04/09/2021	5851 horas	Corrective Order	WO Completed	Generator
661201	Caterpillar 236d Skid Steer L	CAMBIO DE NEUMATICO	REPORTE IASA	04/09/2021		Corrective Order	WO Completed	Skid Steer
661225	Caterpillar 426F2 Backhoe	PM1- MANTENIMIENTO PREVENTIVO	PERSONAL DE IASA	04/09/2021		Corrective Order	WO Completed	Backhoe
661262	Caterpillar 426f2 Backhoe	PM1-MANTENIMIENTO PREVENTIVO	PM1-MANTENIMIENTO PREVENTIVO	04/09/2021		Corrective Order	WO Completed	Backhoe
661277	Manitou Mht-X1490 9t Telehand	Revision de equipo	REVISION DE EQUIPO	04/09/2021		Corrective Order	WO Completed	Telehender
661281	Caterpillar 740B EJ ADT	REEM/ BUSHING+CRUCETAS	EN MAL ESTADO	04/09/2021		Corrective Order	WO Completed	Articulated dump truck
661282	Hino Dutro 300	REVISAR INDICADOR COMBUSTIBLE	NO MARCA	04/09/2021		Corrective Order	WO Completed	Truck
661284	Caterpillar 740b Ej	REEM/ SOLENOID+SENSR ACUMLADR	REQUIERE CAMBIO	04/09/2021		Corrective Order	WO Completed	Articulated dump truck
661309	ETNYRE QUAD	Manguera hidráulica rota (Dire	MANGUERA HIDRÁULICA ROTA (DIRE	04/09/2021		Corrective Order	WO Completed	Chip Spreader
661312	Caterpillar 426f2 Backhoe	PM01-MANTENIMIENTO PREVENTIVO	PERSONAL DE IASA	04/09/2021		Corrective Order	WO Completed	Backhoe
661340	Gallegos Lime Tank	1 LLANTA FLATEADA	1 LLANTA FLATEADA	04/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
661346	Caterpillar 416F2 Backhoe	PM01 MANTENIMIENTO PREVENTIVO	PERSONAL DE IASA	04/09/2021		Corrective Order	WO Completed	Backhoe
661360	International F2674	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	04/09/2021		Corrective Order	WO Completed	Boom truck
661370	Freightliner FL112 Boom Truck	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	04/09/2021		Corrective Order	WO Completed	Boom truck
661372	Case 110JX Tractor Cable Handl	CAMBIO DE BATERIAS	CAMBIO DDE BATERIAS	04/09/2021		Corrective Order	WO Completed	Tractor
661374	DOOSAN 1005	CAMBIO BOMBILLO	FOCOS QUEMADOS	04/09/2021	29069 horas	Corrective Order	WO Completed	Light Tower
661390	Freightliner Columbia CI112	Cambio de llantas	CAMBIO DE LLAANTAS	04/09/2021		Corrective Order	WO Completed	Mule truck
661397	Mack Trucks GU	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	04/09/2021		Corrective Order	WO Completed	Boom truck
661436	Caterpillar 740B EJ ADT	R&I TYRE POS 1	R&I TYRE POS 1	04/09/2021		PM Orders	WO Completed	Articulated dump truck
661438	Caterpillar 740B EJ ADT	R&I TYRE POS 2	R&I TYRE POS 2	04/09/2021		PM Orders	WO Completed	Articulated dump truck
661439	Caterpillar 740B EJ ADT	DESGASTE POS 5,6	DESGASTE POS 5,6	04/09/2021		Corrective Order	WO Completed	Articulated dump truck
661440	Manitou Mht-X1490 9t Telehand	LLANTA BAJA DE AIRE	LLANTA BAJA DE AIRE	04/09/2021		Corrective Order	WO Completed	Telehender
661501	Mobile equipment	Reparacion de mangueras	REPARACION DE MANGUERAS, Y ACOPLES TALLER	04/09/2021		Corrective Order	WO Completed	Area
661550	Caterpillar 236d Skid Steer L	reparacion de sistema de A/A	REPARACION DE SISTEMA DE A/A	04/09/2021		Corrective Order	WO Completed	Skid Steer
661558	Hyster J40zt	revisar frenos	REVISAR FRENOS	04/09/2021		Corrective Order	WO Completed	Forklift
661669	Caterpillar 740B EJ ADT	C/ FILTRO DE LA CABINA	FILTRO OBSTRUIDOS	04/09/2021		Corrective Order	WO Completed	Articulated dump truck
661672	JLG 800 AJ Manlift	MANTENIMIENTO PREVENTIVO	PERSONAL	04/09/2021		Corrective Order	WO Completed	Manlift
661678	Hilux DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	04/09/2021		Corrective Order	WO Completed	Pickup truck
661865	Caterpillar 12M Motorgrader	PM1-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO IASA	05/09/2021		Corrective Order	WO Completed	Grader
661873	Caterpillar 14H Motorgrader	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACIETE Y FILTRO	05/09/2021		Corrective Order	WO Completed	Grader
661880	Gallegos Flatbed Trailer	LLANTAS FLATEADAS X 2	LLANTAS FLATEADAS X 2	05/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
661882	Caterpillar 140K	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO Y ACEITE IASA	05/09/2021		Corrective Order	WO Completed	Grader
661886	PRAMAC GSW120 120 kVa	EQUIPO APAGADA	LLAMADA DE EMERGENCIA	05/09/2021	6441 horas	Corrective Order	WO Completed	Generator
661888	PRAMAC GSW90P 74 kVa	FALLA A TIERRA	LLAMADA DE EMERGENCIA	05/09/2021	25903 horas	Corrective Order	WO Completed	Generator
661891	Broce Broom RJT 350	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	05/09/2021		Corrective Order	WO Completed	Scrubber / Sweeper
661904	Caterpillar 226b Skid Steer L	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	05/09/2021		Corrective Order	WO Completed	Skid Steer
661914	Hyster H300 13t Forklift (M)	Hyster 300 mangera rota	HYSTER 300 MANGERA ROTA	05/09/2021		Corrective Order	WO Completed	Forklift
661915	Freightliner M2 112 Sucker Tru	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	05/09/2021		Corrective Order	WO Completed	Sucker truck
661916	PRAMAC GSW80P 83KVA	CAMBIO ALTERNADOR DC	POR DETERIORO	05/09/2021	13682 hrs	Corrective Order	WO Completed	Generator
661920	Manitou Mht-X860 6t Telehand	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	05/09/2021	3475.1 Hrs	Corrective Order	WO Completed	Telehender
661954	Hyster H70ft 3t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO DE COPAMA	05/09/2021		Corrective Order	WO Completed	Forklift
661956	Hyster H70ft 3t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO DE COPAMA	05/09/2021		Corrective Order	WO Completed	Forklift
661957	Gallegos Flatbed Trailer	Ajuste de frenos	AJUSTE DE FRENOS	05/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
661958	Hyster E70xn 3t Forklift (E)	INSPECCION RUEDA TRASERA	EQUIPO COPAMA EVALUACION	05/09/2021		Corrective Order	WO Completed	Forklift
661962	Hyster E70xn 3t Forklift (E)	INSPECCION RUEDA TRASERA	EQUIPO COPAMA EVALUACION	05/09/2021		Corrective Order	WO Completed	Forklift
661970	Freightliner Columbia CI112	Ajuste de frenos	AJUSTE DE FRENOS	05/09/2021		Corrective Order	WO Completed	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
661971	Intraax 53121 Hendrickso	FLAT TIRE + LUCES	FLAT TIRE	05/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
662001	PRAMAC GSW170i 164 kVa	CAMBIO DE VOLTAJE	SOLICITUD DE CAMBIO DE VOLTAJE	05/09/2021 5575 horas		Corrective Order	WO Completed	Generator
662020	Caterpillar DE165E0 165 kVa	PM1 CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 16693 horas		PM Orders	WO Completed	Generator
662022	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 12235 horas		PM Orders	WO Completed	Generator
662025	PRAMAC GSW120 120 kVa	PM1 PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 6555 horas		PM Orders	WO Completed	Generator
662027	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 6554 horas		PM Orders	WO Completed	Generator
662029	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 19138 horas		PM Orders	WO Completed	Generator
662030	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 15361 horas		PM Orders	WO Completed	Generator
662031	SDMO J60U 60 kVa	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 24856 horas		PM Orders	WO Completed	Generator
662032	SDMO J30U 38KVA	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 8611 hrs		PM Orders	WO Completed	Generator
662033	Caterpillar DE88E0 58 kVa	PM1 CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 37561 horas		PM Orders	WO Completed	Generator
662034	PRAMAC GSW90P 74 kVa	PM1 PRA GSW90P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 25969 horas		PM Orders	WO Completed	Generator
662039	PRAMAC GSW65 48 kVa	PM1 PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 25114 hrs		PM Orders	WO Completed	Generator
662040	PRAMAC GSW30Y 24 kVa	PM1 PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 22070		PM Orders	WO Completed	Generator
662055	Caterpillar D110 E2 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 17188 horas		PM Orders	WO Completed	Generator
662136	Caterpillar 12M	FABRICACION DE MANGUERAS	PERSONAL DE IASA	05/09/2021		Corrective Order	WO Completed	Grader
662138	Caterpillar 740B EJ ADT	C/ FAST FILL TANQUE COMBUSTIBL	FUGA POR EL FAST FILL	05/09/2021		Corrective Order	WO Completed	Articulated dump truck
662178	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 4493 horas		Corrective Order	WO Completed	Light Tower
662180	Freightliner Columbia CI112	LLANTAS FLATEADAS X 1	LLANTAS FLATEADAS X 1	05/09/2021		Corrective Order	WO Completed	Mule truck
662193	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	05/09/2021 4082 horas		Corrective Order	WO Completed	Light Tower
662332	Caterpillar 12M	Aire Acondicionado	AIRE ACONDICIONADO	05/09/2021		Corrective Order	WO Completed	Grader
662338	Landcruiser DC	EVALUAR SISTEMA FRENOS	AJUSTE FRENO SERVICIO Y PARQUEO	05/09/2021		Corrective Order	WO Completed	Pickup truck
662378	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 64.8 horas		PM Orders	WO Completed	Generator
662379	PRAMAC GSW170i 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 8258 horas		PM Orders	WO Completed	Generator
662380	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 10422 horas		PM Orders	WO Completed	Generator
662381	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 16804 horas		PM Orders	WO Completed	Generator
662383	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 9774 horas		PM Orders	WO Completed	Generator
662386	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 16485 horas		PM Orders	WO Completed	Generator
662387	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 3633 horas		PM Orders	WO Completed	Generator
662388	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 581 horas		PM Orders	WO Completed	Generator
662389	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 839 hrs		PM Orders	WO Completed	Generator
662391	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 16084 hrs		PM Orders	WO Completed	Generator
662392	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 8643 hrs		PM Orders	WO Completed	Generator
662393	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 359 horas		PM Orders	WO Completed	Generator
662394	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 10684 horas		PM Orders	WO Completed	Generator
662395	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 159 horas		PM Orders	WO Completed	Generator
662396	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 25132 horas		PM Orders	WO Completed	Generator
662397	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 18055 horas		PM Orders	WO Completed	Generator
662398	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	05/09/2021 260 horas		PM Orders	WO Completed	Generator
662409	Mack Trucks GU	DESMONTAJE CILINDRO PRINCIPAL	SE ENVIA A TECNOSERVICIOS	05/09/2021		Corrective Order	WO Completed	Boom truck
662414	Caterpillar 12M	fabricacion de manguera	FABRICACION DE MANGUERA	05/09/2021		Corrective Order	WO Completed	Grader
662498	Freightliner Columbia CI112	revisar direccion	REVISAR LA DIRECCION	05/09/2021		Corrective Order	WO Completed	Mule truck
662502	Hyster H300 13t Forklift (M)	reparacion dde mangueras	REPARACION DE MANGUERAS	05/09/2021		Corrective Order	WO Completed	Forklift
662504	Grove RT600E 50TON	recalentamiento	RECALENTAMIENTO DDE MOTOR, CONATO DE EINCENDIO	05/09/2021		Corrective Order	WO Completed	Crane/Hoist
662506	John Deere 9370R Tractor	Reparacion de implemento	REPARACION DE IMPLENETO	05/09/2021		Corrective Order	WO Completed	Tractor
662508	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	INSTALACION DE TARJETA AVR	05/09/2021 16809 horas		Corrective Order	WO Completed	Generator
662521	JLG 800 AJ Manlift	Cambio de controles	CAMBIO DE CONTROLES	06/09/2021		Corrective Order	WO Completed	Manlift
662683	Freightliner CI 120	CHANGE TYRES X 2	CHANGE TYRES X 2	06/09/2021		Corrective Order	WO Completed	Mule truck
662722	Case 110JX Tractor Cable Handl	instalacion de vidrio	INSTALACION DE VIDRIO	06/09/2021 90013759 90013760		Corrective Order	WO Completed	Tractor
662728	Mobile equipment	epp, personal	EPP, PERSONAL	06/09/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
662736	PRAMAC GSW80P 83 kVa	COLOCACION DE ALTERNADOR DC	ALTERNADOR USADO EN OTRA UNIDAD (GS242)	06/09/2021	13697 horas	Corrective Order	WO Completed	Generator
662798	Freightliner M2 112 Sucker Tru	cambio de motor de arranque	CAMBIO DE MOTOR DE ARRANQUE	06/09/2021	90013603	Corrective Order	WO Completed	Sucker truck
662799	Freightliner M2 112 Sucker Tru	cambio de motor de arranque	CAMBIO DE MOTOR DE ARANQUE	06/09/2021	90014906	Corrective Order	WO Completed	Sucker truck
662837	Linde T30D	Montacarga no arranca	MONTACARGA NO ARRANCA	06/09/2021		Corrective Order	WO Completed	Forklift
663017	Freightliner CI 120	REPORTES VARIOS	REPORTES VARIOS	06/09/2021	90013549 90014611	Corrective Order	WO Completed	Mule truck
663020	Caterpillar 307E Miniexcavator	reparacion de bastidor	REPARACION DEL BASTIDOR	06/09/2021		Corrective Order	WO Completed	Excavator
663035	Caterpillar CS74 Compactor	Sapos del tambor rotos	SAPOS DEL TAMBOR ROTOS	06/09/2021		Corrective Order	WO Completed	Compactor
663048	Toyota Hilux	CAMBIO LUCES FRONTAL	LUZ BAJA FOCO DERECHO QUEMADO	06/09/2021		Corrective Order	WO Completed	Pickup truck
663115	PRAMAC GSW90P 74 kVa	MANTENIMIENTO CORRECTIVO	LIMPIEZA DE RADIADOR	06/09/2021	25935 horas	Corrective Order	WO Completed	Generator
663544	Broce Broom RJT 350	No avanza ni retrocede.	NO AVANZA NI RETROCEDE.	07/09/2021		Corrective Order	WO Completed	Scrubber / Sweeper
663606	Atlas Copco GESAN QIS 45 47KVA	PM1 ATL QIS45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/09/2021	5303 hrs	PM Orders	WO Completed	Generator
663651	Freightliner M2 106 Sucker Tru	Instalacion de pernos	SECADOR DE LOS FRENOS CAIDO	07/09/2021	237,992.6 Kms	Corrective Order	WO Completed	Sucker truck
663674	Caterpillar 740B EJ ADT	Cambio de oring	FUGA DE DIESEL POR ACOPLE RAPIDO DE LLENADO	07/09/2021		Corrective Order	WO Completed	Articulated dump truck
663686	Freightliner Columbia CI112	Cambio de rin y llanta	CAMBIO DE RIM Y LLANTA	07/09/2021	90013389	Corrective Order	WO Completed	Mule truck
663749	Gallegos Flatbed Trailer	BANDAS EN MAL ESTADO	BANDAS EN MAL ESTADO	07/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
663769	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/09/2021		Corrective Order	WO Completed	Pickup truck
663771	Mobile equipment	suministro	SUMINISTRO	07/09/2021		Corrective Order	WO Completed	Area
663777	Mobile equipment	suministro	SUMINISTRO	07/09/2021		Corrective Order	WO Completed	Area
663855	Caterpillar 12M	Reparacion de varillaje	REPARACION DE VARILLAJE DEL W/W	07/09/2021	90012878	Corrective Order	WO Completed	Grader
663882	Manitou Mht-X1490 9t Telehand	LLANTAS BAJAS DE AIRE	LLANTAS BAJAS DE AIRE	07/09/2021		Corrective Order	WO Completed	Telehender
663913	Gallegos Flatbed Trailer	inspeccion FUGA ACEITE/LUCES/	FUGA DE ACEITE/LUCES FRENO	07/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
663915	SJS SJ6530	reparacion de flat	REPARACION DE FLAT	07/09/2021		Corrective Order	WO Completed	Compactor
663925	Grove RT600E 50TON	cambio de tacos	TACOS DE FRENO DESGASTADOS	07/09/2021		Corrective Order	WO Completed	Crane/Hoist
663926	New Holland Lm 1745	cambio de coolam	COOALN MUY DEGRADADO	07/09/2021		Corrective Order	WO Completed	Telehender
663929	Freightliner Columbia CI112	Llanta flat	LLANTA FLAT	07/09/2021		Corrective Order	WO Completed	Mule truck
663930	Freightliner Columbia CI112	Cambio de abrazaderas aftercoo	CAMBIO DE ABRAZADERA DE AFTERCOOLER	07/09/2021		Corrective Order	WO Completed	Mule truck
663932	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	07/09/2021		Corrective Order	WO Completed	Bus
663933	Coaster	Llanta flat	LLANTA FLAT	07/09/2021		Corrective Order	WO Completed	Bus
663934	Freightliner M2 106 Refrigerat	EVALUACION MEC ENVIAR REPARAR	REQUIERE REPARACIÓN DE UNIDAD THERMOKING	07/09/2021		Corrective Order	WO Completed	Refrigerator truck
663938	Mobile equipment	Telehandler molinos falla 6291	BAJO NIVEL DE ACEITE HIDRAULCIO	07/09/2021		Corrective Order	WO Completed	Area
664125	Grove RT600E 50TON	refrigerante contaminado	CAMBIO DE EMPAQUES DE ENFRIADOR	08/09/2021		Corrective Order	WO Completed	Crane/Hoist
664184	Gallegos Flatbed Trailer	FLAT TIRE	FLAT TIRE	08/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
664210	Power Curbers 5700-C	Ganchos de la puerta del sinfi	GANCHOS DE LA PUERTA DEL SINFI	08/09/2021		Corrective Order	WO Completed	Kerb Machine
664212	Power Curbers 5700-C	Interruptor de la bomba de ag	INTERRUPTOR DE LA BOMBA DE AG	08/09/2021		Corrective Order	WO Completed	Kerb Machine
664215	Coaster	Reparacion de llanta	REEMPLAZO DE LLANTA	08/09/2021		Corrective Order	WO Completed	Bus
664216	Caterpillar 740b Ej	Revision de fuga	REVISION DE FUGA HIDRAULICA	08/09/2021		Corrective Order	WO Completed	Articulated dump truck
664230	Caterpillar 336DL	Aire acondicionado dañado	AIRE ACONDICIONADO DAÑADO	08/09/2021		Corrective Order	WO Completed	Excavator
664234	Caterpillar RM500 Reclaimer	La bomba de emulsión no succio	LA BOMBA DE EMULSIÓN NO SUCCIO	08/09/2021		Corrective Order	WO Completed	Road Reclaimer
664328	Landcruiser DC	A/C INSPECTION & REPAIR	NO ENFRIA	08/09/2021		Corrective Order	WO Completed	Pickup truck
664335	Caterpillar 12M Motorgrader	Se bloquea el sistema hidráulu	SE BLOQUEA EL SISTEMA HIDRÁULI	08/09/2021		Corrective Order	WO Completed	Grader
664349	Caterpillar 14H Motorgrader	Necesita reemplazo de hojas.	NECESITA REEMPLAZO DE HOJAS.	08/09/2021		Corrective Order	WO Completed	Grader
664386	Freightliner M2 106 Refrigerat	cambio de valvula de expasion	CAMBIO DE VALVULA DE EXPANSION	08/09/2021		Corrective Order	WO Completed	Refrigerator truck
664391	Terex RT5551 55TON	cambios de Relay	RELAY DE VALVULAS DE ESTABILIZADORES MALOS	08/09/2021		Corrective Order	WO Completed	Crane/Hoist
664403	Landcruiser TC	REVISAR SEÑAL GPS	GPS NO EMITE DATOS	08/09/2021		Corrective Order	WO Completed	Pickup truck
664448	Grove RT700E 60TON	izaje de equipo	IZAJE DE EQUIPO	08/09/2021	Soporte W36	Corrective Order	WO Completed	Crane/Hoist
664454	Caterpillar 740B	R&I Mando Final Pos 2	R&I MANDO FINAL POS 2	08/09/2021		Corrective Order	WO Completed	Articulated dump truck
664478	Mobile equipment	Reparacion de llanta	REPARACION DE LLANTA DE TELEHANDER	08/09/2021		Corrective Order	WO Completed	Area
664483	Atlas Copco GESAN QIS 45 47KVA	CORRECTIVO	ISTALACION Y PUESTA EN MARCHA DE GENERADOR	08/09/2021	5303 hrs	Corrective Order	WO Completed	Generator
664501	Hilux DC	Reparacion de llanta	LANTA FLAT	08/09/2021		Corrective Order	WO Completed	Pickup truck
664502	Freightliner CI 120	rotacion de ruedas	ROTACION DE RUEDAS	08/09/2021		Corrective Order	WO Completed	Mule truck
664503	Caterpillar TI1055clrc	Arranque auxiliar	EQUIPO NO ENCIENDE	08/09/2021		Corrective Order	WO Completed	Telehender
664507	Freightliner M2 112 Sucker Tru	Arranque auxiliar de Equipo	EQUIP NO ENCIENDE	08/09/2021		Corrective Order	WO Completed	Sucker truck
664510	Hilux DC	arranque auxiliar	EQUIPO NO ENCIENDE	08/09/2021		Corrective Order	WO Completed	Pickup truck
664513	Gallegos Flatbed Trailer	cambio s de pulmon	FUGA DE AIRE	08/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
664515	Caterpillar 14H Motorgrader	Cambio de hoja de corte	CAMBIO DE HOJA DE CORTE	08/09/2021		Corrective Order	WO Completed	Grader
664516	Coaster	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	08/09/2021		Corrective Order	WO Completed	Bus
664527	Landcruiser DC	Cambio de cilindro de freno	CAMBIO DE CILINDRO DE FRENO	08/09/2021		Corrective Order	WO Completed	Pickup truck
664599	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	09/09/2021	10324 hrs	PM Orders	WO Completed	Generator
664600	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	09/09/2021	12668 hrs	PM Orders	WO Completed	Generator
664601	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	09/09/2021	*****	PM Orders	WO Completed	Generator
664615	Freightliner Columbia CI112	Luces delanteras fedectuosas	LUCES DELANTERAS DEFECTUOSAS	09/09/2021		Corrective Order	WO Completed	Mule truck
664616	Freightliner Columbia CI112	Equipo no enciende	EQUIPO NO ENCIENDE	09/09/2021		Corrective Order	WO Completed	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
664618	Caterpillar 14H Motorgrader	Inspección Mensual de AFEX	INSPECCIÓN MENSUAL DE AFEX	09/09/2021		Corrective Order	WO Completed	Grader
664620	Caterpillar 226b Skid Steer L	Cambio de vidrio frontal	CAMBIO DE VIDRIO FRONTAL	09/09/2021		Corrective Order	WO Completed	Skid Steer
664621	Mobile equipment	Reparación de llanta telehandl	TELEHANDLER MOLINOS CON LLANTA FLAT	09/09/2021		Corrective Order	WO Completed	Area
664622	Unimog Service Truck	Cambio de componentes	CAMBIO DE COMPONENTES	09/09/2021		Corrective Order	WO Completed	Truck
664638	Atlas Copco GESAN QIS 45 47KVA	RUPTURA DE CABLE ELECTRICO	LLAMADA DE EMERGENCIA POR RUPTURA DE CABLE ELECTRICO DE ALIMENTACION	09/09/2021	5313 horas	Corrective Order	WO Completed	Generator
664643	Caterpillar D8T Dozer	El parabrisas trasero no funci	EL PARABRISAS TRASERO NO FUNCIONA	09/09/2021		Corrective Order	WO Completed	Dozer
664645	Freightliner M112 Truck Tip	Tren de ruedas traseras se mu	TREN DE RUEDAS TRASERAS SE MU	09/09/2021		Corrective Order	WO Completed	Tipper
664658	USP&E GP700/V-A 700 kVa	FALLO DE VOLTAGE AC	EQUIPO SE APAGA POR FALLO DE VOLTAGE AC	09/09/2021	10646 horas	Corrective Order	WO Completed	Generator
664671	Gallegos Flatbed Trailer	LLANTAS FLATEADAS X 1	LLANTAS FLATEADAS X 1	09/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
664696	Kobelco CKE2500E 250TON	CAMBIO DE COMPONETES	CAMBIO DE CONTROLLER Y RELAY	09/09/2021	90012894 60022483	Corrective Order	WO Completed	Crane/Hoist
664719	PB015 COASTER TOYOTA	Reemplazo de llantas	REEMPLAZO DE LLANTAS	09/09/2021		Corrective Order	WO Completed	Bus
664794	Mobile equipment	CABLE COMUNICACION VOLVO	CALIBRACION INYECTORES	09/09/2021	60022489	Corrective Order	WO Completed	Area
664805	Caterpillar 740b Ej	C/ MANG HYD FRENOS CENTRALES	MANGUERA ROTA	09/09/2021		Corrective Order	WO Completed	Articulated dump truck
664840	PRAMAC GSW110P 82 kVa	CAMBIO BATERIA	MANTENIMIENTO CORRECTIVO	09/09/2021	13815 hrs	Corrective Order	WO Completed	Generator
664855	Manitou Mht-X860 6t Telehand	Reparacion de A/C	REPARACION DE A/C	09/09/2021	3,745.50 hrs	Corrective Order	WO Completed	Telehender
664876	Caterpillar 14H Motorgrader	Manguera hidráulica desajustad	MANGUERA HIDRÁULICA DESAJUSTAD	09/09/2021		Corrective Order	WO Completed	Grader
664891	Caterpillar 140K	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	09/09/2021	12,782.300 hrs	Corrective Order	WO Completed	Grader
664893	JLG 800 AJ Manlift	SE BLOQ CON 2 PERSONAS EN CANA	SE BLOQ CON 2 PERSONAS EN CANA	09/09/2021		Corrective Order	WO Completed	Manlift
664902	Freightliner M2 106 Truck	MOV BLOQUEADOS DE CAMION CANAS	MOV BLOQUEADOS DE CAMION CANAS	09/09/2021		Corrective Order	WO Completed	Boom truck
664927	Grove GMK4100L 100TON	PRE-EVALUACION MECANICA	INSPECCION DE EQUIPO	09/09/2021		Corrective Order	WO Completed	Crane/Hoist
664940	Freightliner 8170ME Water Truc	cambio de swicht	FUGA DE AIRE	09/09/2021		Corrective Order	WO Completed	Water truck
664957	Hiace Bus	cambio de 3 llantas	LLANTAS FLAT	09/09/2021		Corrective Order	WO Completed	Bus
664959	Coaster	cambio de 4 llantas	LLANTAS EN MAL ESTADO	09/09/2021		Corrective Order	WO Completed	Bus
664960	LB002 725 CAT	reparacion electrica	REPARACION ELECTRICA	09/09/2021		Corrective Order	WO Completed	Truck
664988	PRAMAC GSW120 120 kVa	REPARAR SISTEMA ENFRIAMIENTO	FUGA REFRIGERANTE	09/09/2021	6555 horas	Corrective Order	WO Completed	Generator
664990	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	09/09/2021		Corrective Order	WO Completed	Pickup truck
664991	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	09/09/2021		Corrective Order	WO Completed	Pickup truck
664992	Mobile equipment	Barredora alquilada	CAMBIO DE ESCOBILAS	09/09/2021		Corrective Order	WO Completed	Area
664993	WT015 H7 CISTERNA SINOTRUK	Luces delanteras no funcionan	REPARACION DE LUCES	09/09/2021	65276 kms	Corrective Order	WO Completed	Water truck
664994	Grove RT600E 50TON	Fuga de refrigerante	FUGA DE REFRIGERANTE	09/09/2021		Corrective Order	WO Completed	Crane/Hoist
664995	Mobile equipment	Cisterna 533071 flat	REPARACION DE LLANTA	09/09/2021		Corrective Order	WO Completed	Area
664996	Hyster H70ft 3t Forklift (M)	Llanta flat	CAMBIO DE 1 LLANTA	09/09/2021		Corrective Order	WO Completed	Forklift
664997	Caterpillar 236d Skid Steer L	Engrase general	ENGRASE GENERAL	09/09/2021		Corrective Order	WO Completed	Skid Steer
665000	Caterpillar 226b Skid Steer L	Engrase general	ENGRASE GENERAL	09/09/2021		Corrective Order	WO Completed	Skid Steer
665003	Caterpillar 14M Motorgrader	Luz delantera no enciende	CAMBIO DE LUZ DELANTERA	09/09/2021		Corrective Order	WO Completed	Grader
665004	Coaster	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	09/09/2021		Corrective Order	WO Completed	Bus
665095	Grove GMK 4080 80TON	Equipo bloqueado	EQUIPO BLOQUEADO	10/09/2021		Corrective Order	WO Completed	Crane/Hoist
665096	Caterpillar 416F2 Backhoe	Llanta flat	REPARACIÓN DE LLANTA	10/09/2021		Corrective Order	WO Completed	Backhoe
665136	Caterpillar 226b Skid Steer L	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO/IASA	10/09/2021		Corrective Order	WO Completed	Skid Steer
665141	Freightliner Columbia CI112	FLAT TIRE	FLAT TIRE	10/09/2021		Corrective Order	WO Completed	Mule truck
665208	Caterpillar 336DL	Bajo nivel de coolant.	BAJO NIVEL DE COOLANT.	10/09/2021		Corrective Order	WO Completed	Excavator
665209	Caterpillar 226b Skid Steer L	PM01-MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	10/09/2021		Corrective Order	WO Completed	Skid Steer
665216	Manitou Mht-X1490 9t Telehand	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	10/09/2021		Corrective Order	WO Completed	Telehender
665240	GROVE GMK 5170 170TON	Cambios de Filtros	CAMBIOS E FILTROS	10/09/2021		Corrective Order	WO Completed	Crane/Hoist
665242	ETNYRE QUAD	Necesita reemplazo de lláminas	NECESITA REEMPLAZO DE LLÁMINAS	10/09/2021		Corrective Order	WO Completed	Chip Spreader
665249	Landcruiser DC	Reemplazo de rines	REEMPLAZO DE RINES	10/09/2021		Corrective Order	WO Completed	Pickup truck
665257	Hilux DC	Correctivo	CAMBIO DE CREMALLERAS - FRENOS	10/09/2021		Corrective Order	WO Completed	Pickup truck
665259	Landcruiser DC	Correctivo	PM-DIRECCION-CRUCETAS-ALARMA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665261	Landcruiser TC	Correctivo	CAMBIO DE ESCLAVA DEL CLUTCH, COOLANT	10/09/2021		Corrective Order	WO Completed	Pickup truck
665262	Landcruiser DC	CORRECTIVOS	EVAPORADOR	10/09/2021		Corrective Order	WO Completed	Pickup truck
665267	Hilux DC	Correctivo	SILLON DEL CHOFER	10/09/2021		Corrective Order	WO Completed	Pickup truck
665268	Hilux DC	Correctivo	PUERTA DEL VAGON	10/09/2021		Corrective Order	WO Completed	Pickup truck
665269	Landcruiser DC	Correctivo	BATERIA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665270	PB003 COASTER TOYOTA	Cambio de batería	BATERIA EN MAL ESTADO	10/09/2021		Corrective Order	WO Completed	Bus
665271	Hilux DC	Correctivo	COMPRESOR,ALTERNADOR,BALINERAS	10/09/2021		Corrective Order	WO Completed	Pickup truck
665275	Landcruiser TC	cambio de batería	CAMBIO DE BATERIA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665277	Landcruiser DC	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665280	Hilux DC	Correctivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665281	Hilux DC	Correctivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665282	Hilux DC	cambio de pertiga	SIN PERTIGA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665283	Hilux DC	Correctivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665291	Landcruiser DC	Reparacion de Frenos	REPARACION DE FRENOS	10/09/2021		Corrective Order	WO Completed	Pickup truck
665293	Landcruiser TC	Revision de motor	CONSUMO DE ACEITE	10/09/2021		Corrective Order	WO Completed	Pickup truck
665299	Hilux DC	Cambio de alternador	FALLA EN ALTERNADOR	10/09/2021		Corrective Order	WO Completed	Pickup truck
665300	Landcruiser TC	Correctivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665302	Landcruiser DC	Correctivo	BARRA TENSORA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665304	Landcruiser DC	Reparacion de cableado y ajust	FALLA EN FRENOS	10/09/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
665306	Hilux DC	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665310	Landcruiser DC	cambio de crucetas	CRUCETAS EN MAL ESTADO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665314	Hilux DC	cambio de crucetas	CRUCETAS Y TERMINALES EN MAL ESTADO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665317	Landcruiser DC	Correctivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665318	Hilux DC	Cambio de alternador	ALTERNADOR, POWER STERING	10/09/2021		Corrective Order	WO Completed	Pickup truck
665319	Landcruiser TC	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665322	Landcruiser TC	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665324	Hilux DC	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665326	Coaster	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Bus
665332	PB012 COASTER TOYOTA	Mant preventivo	MANT. PREVENTIVO	10/09/2021		Corrective Order	WO Completed	Bus
665337	Caterpillar 740b Ej	C/ RETENEDORA DIFEREN CENTRAL	RETENEDORA ROTA	10/09/2021		Corrective Order	WO Completed	Articulated dump truck
665338	Toyota Hilux	Correctivo	SILLON DEL CHOFER	10/09/2021		Corrective Order	WO Completed	Pickup truck
665339	Hilux DC	Correctivo	BATERIA	10/09/2021		Corrective Order	WO Completed	Pickup truck
665361	Hilux DC	rep. vagon y ventana	CORRECTIVO	10/09/2021		Corrective Order	WO Completed	Pickup truck
665416	Caterpillar 740b Ej	Reparacion de equipo	REPARACION DE LIMPIAPARABRISAS	10/09/2021		Corrective Order	WO Completed	Articulated dump truck
665459	Unimog Service Truck	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	10/09/2021		Corrective Order	WO Completed	Truck
665498	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Bus
665502	Freightliner Cl 120	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	10/09/2021		Corrective Order	WO Completed	Mule truck
665553	Caterpillar 336DL Excavator	Soldadura de pin de rolo	PIIN DE ROLO SUELTO	10/09/2021		Corrective Order	WO Completed	Excavator
665554	Coaster	cambio de 1 llanta	LLANTA FLAT	10/09/2021		Corrective Order	WO Completed	Bus
665555	Manitou Mht-X1490 9t Telehand	Reparacion de sistema de freno	SISTEMA DE FRENO DE SERVICIO NO FUNCIONA	10/09/2021		Corrective Order	WO Completed	Telehender
665556	PRAMAC GSW170i 164 kVa	LLAMADA DE EMERGENCIA	EQUIPO CON DISPLAY DESONECTADO	10/09/2021	5575 hrs	Corrective Order	WO Completed	Generator
665562	SJS SJ6530	reparacion de tornilleria	TORNILLOS FLOJOS	10/09/2021		Corrective Order	WO Completed	Compactor
665563	SJS SJ6530	Reparacion de mount	MOUNT EN MAL ESTADO	10/09/2021		Corrective Order	WO Completed	Compactor
665570	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	10/09/2021		Corrective Order	WO Completed	Pickup truck
665572	Freightliner Columbia Cl112	Reparacion de llanta	REPARACION DE LLANTA	10/09/2021		Corrective Order	WO Completed	Mule truck
665578	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021	77441 kms	PM Orders	WO Completed	Pickup truck
665579	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Pickup truck
665582	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021	94,014.00 km	PM Orders	WO Completed	Pickup truck
665584	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Pickup truck
665587	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Pickup truck
665590	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Pickup truck
665591	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Pickup truck
665595	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Bus
665596	Coaster	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	10/09/2021		PM Orders	WO Completed	Bus
665603	Hyster E50Z-27 FORKLIFT	INSPECCION GENERAL MECANICA	INSPECCION	10/09/2021		Corrective Order	WO Completed	Forklift
665623	Freightliner Columbia Cl112	Fuga de refrigerante	FUGA DE REFRIGERANTE	10/09/2021		Corrective Order	WO Completed	Mule truck
665624	Caterpillar 226b Skid Steer L	Cambio de vidrio Frontal	CAMBIO DE VIDRIO FRONTAL	10/09/2021		Corrective Order	WO Completed	Skid Steer
665626	Manitou MTH-X 10120	Reparación de A/A	AIRE ACONDICIONADO NO FUNCIONA	10/09/2021		Corrective Order	WO Completed	Telehender
665629	PB011 COASTER TOYOTA	Cambio de pernos de rueda	CAMBIO DE PERNOS DE RUEDA IZQUIERDA TRASERA	10/09/2021		Corrective Order	WO Completed	Bus
665630	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	11/09/2021		Corrective Order	WO Completed	Pickup truck
665631	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	11/09/2021		Corrective Order	WO Completed	Pickup truck
665632	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	11/09/2021		Corrective Order	WO Completed	Pickup truck
665652	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	11/09/2021		Corrective Order	WO Completed	Pickup truck
665653	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	11/09/2021		Corrective Order	WO Completed	Pickup truck
665774	Caterpillar 12M	Daño en una de las mangueras h	DAÑO EN UNA DE LAS MANGUERAS H	11/09/2021		Corrective Order	WO Completed	Grader
665812	Caterpillar 140K	FABRICACION DE MANGUERAS	PERSONAL DE IASA	11/09/2021		Corrective Order	WO Completed	Grader
665813	Caterpillar 740b Ej	C/ LINEA DEL SIST ENFRIAMIENTO	REQUIERE CAMBIO	11/09/2021		Corrective Order	WO Completed	Articulated dump truck
665846	Caterpillar 740b Ej	C/ MANG HYD DE DIRECCION	MANGUERA ROTA	11/09/2021		Corrective Order	WO Completed	Articulated dump truck
665898	ETNYRE QUAD	Fuga de aceite hidráulico en l	FUGA DE ACEITE HIDRÁULICO EN L	11/09/2021		Corrective Order	WO Completed	Chip Spreader
666000	Caterpillar DE110E 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	21791 hrs	PM Orders	WO Completed	Generator
666001	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	18161 hrs	PM Orders	WO Completed	Generator
666002	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	14398 hrs	PM Orders	WO Completed	Generator
666003	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	13903 hrs	PM Orders	WO Completed	Generator
666004	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	17830 horas	PM Orders	WO Completed	Generator
666006	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	13873 horas	PM Orders	WO Completed	Generator
666007	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	14700 hrs	PM Orders	WO Completed	Generator
666008	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	10887 hrs	PM Orders	WO Completed	Generator
666009	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	24350 horas	PM Orders	WO Completed	Generator
666011	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	28371 horas	PM Orders	WO Completed	Generator
666012	FG WILSON P88-1 64 kVa	PM1 FGW P88-1 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	5851 horas	PM Orders	WO Completed	Generator
666015	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	12565 hrs	PM Orders	WO Completed	Generator
666016	SDMO J30U 38 kVa	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	13003 horas	PM Orders	WO Completed	Generator
666017	SDMO T11UM 10KVA	PM1 SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	17753 hrs	PM Orders	WO Completed	Generator
666018	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	25026 HORAS	PM Orders	WO Completed	Generator
666019	Expert Power PN45 10KVA	PM1 EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	8301 hrs	PM Orders	WO Completed	Generator
666020	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/09/2021	36673 hrs	PM Orders	WO Completed	Light Tower

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
666024	Caterpillar CS533E Compactor	Manguera hidráulica rota	MANGUERA HIDRÁULICA ROTA	11/09/2021		Corrective Order	WO Completed	Compactor
666037	Gallegos 28M3 Lime Tank	FLAT TIRE	FLAT TIRE	11/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
666058	Hyster E70xn 3t Forklift (E)	CAMBIO DE COMPONENTE	INSPECCION POR COPAMA	11/09/2021 90013782		Corrective Order	WO Completed	Forklift
666099	Hyster H70ft 3t Forklift (M)	CAMBIO DE COMPONENTES	INSPECCION COPAMA	11/09/2021 90014873/5,3333.00 hrs		Corrective Order	WO Completed	Forklift
666123	Landcruiser DC	cambio de 4 llantas	LLANATAS EN MAL ESTADO	11/09/2021		Corrective Order	WO Completed	Pickup truck
666128	International 7400 SBA Fire Tr	reparacion de sistema de a/c	FALLO EN SISTEMA DE A/C	11/09/2021		Corrective Order	WO Completed	Fire truck
666160	Caterpillar CS533E Compactor	Revision de equipo	REVISION DE EQUIPO	11/09/2021 90014754		Corrective Order	WO Completed	Compactor
666162	Hilux DC	Reparacion de llanta	LLANTA FLAT	11/09/2021		Corrective Order	WO Completed	Pickup truck
666172	Caterpillar 426f2 Backhoe	cambio de abrazaderas	ABRAZADERAS EN MAL ESTADO	11/09/2021		Corrective Order	WO Completed	Backhoe
666178	Power Curbers 5700-C	Revision de sistema electrico	REVISION DE SISTEMA ELECTRICO	11/09/2021		Corrective Order	WO Completed	Kerb Machine
666189	Atlas Copco GESAN QIS 45 47KVA	CORRECTIVO	CORRECTIVO	11/09/2021 5399 hrs		Corrective Order	WO Completed	Generator
666190	PRAMAC GSW90P 74 kVa	CORRECTIVO	CORRECTIVO	11/09/2021 25967 hrS		Corrective Order	WO Completed	Generator
666201	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 65 hrs		PM Orders	WO Completed	Generator
666202	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 8258 hrs		PM Orders	WO Completed	Generator
666203	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 16914 horas		PM Orders	WO Completed	Generator
666204	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 16809 hrs		PM Orders	WO Completed	Generator
666205	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 839 hrs		PM Orders	WO Completed	Generator
666206	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 9774 hrs		PM Orders	WO Completed	Generator
666207	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 16485 hrs		PM Orders	WO Completed	Generator
666208	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 16084 hrs		PM Orders	WO Completed	Generator
666209	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 3633 hrs		PM Orders	WO Completed	Generator
666210	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 581 hrs		PM Orders	WO Completed	Generator
666211	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 359 horas		PM Orders	WO Completed	Generator
666212	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 10805 horas		PM Orders	WO Completed	Generator
666213	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 160 horas		PM Orders	WO Completed	Generator
666214	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 25132 horas		PM Orders	WO Completed	Generator
666215	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 18055 horas		PM Orders	WO Completed	Generator
666216	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/09/2021 260 horas		PM Orders	WO Completed	Generator
666223	PRAMAC GSW460V 460 kVa	CAMBIO DE ARNES	REEMPLAZO DE ARNES VIEJO POR FALLAS DE INYECTORES ELECTRONICOS	11/09/2021 31526 horas		Corrective Order	WO Completed	Generator
666226	Caterpillar 226b Skid Steer L	Instalación de extintor	EXTIRNO DE 10 LIBRAS AUSENTE	11/09/2021		Corrective Order	WO Completed	Skid Steer
666365	Freightliner Columbia CI112	Llanta trasera flat	LLANTA TRASERA FLAT	12/09/2021		Corrective Order	WO Completed	Mule truck
666367	Freightliner Columbia CI112	reparacion de 1 llanta	LLANTA FLAT	12/09/2021		Corrective Order	WO Completed	Mule truck
666368	Freightliner CI 120	Revisión de estado de llantas	REVISIÓN DE ESTADO DE LLANTAS	12/09/2021		Corrective Order	WO Completed	Mule truck
666369	Gallegos Flatbed Trailer	Luces traseras desprendidas	LUCES TRASERAS DESPRESNDIDAS	12/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
666371	Landcruiser DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	12/09/2021		Corrective Order	WO Completed	Pickup truck
666372	Hilux DC	Cambio de llanta	CAMBIO DE LLANTA	12/09/2021		Corrective Order	WO Completed	Pickup truck
666374	Freightliner M2 106 Hydroseedi	Reparraciones Varias	REPARACIONES VARIAS	12/09/2021		Corrective Order	WO Completed	Truck
666395	Caterpillar 236d Skid Steer L	CAMBIO DE COMPONENTE	PERSONAL DE IASA	12/09/2021		Corrective Order	WO Completed	Skid Steer
666408	Hiace Bus	cambio de 2 llantas	LLANTAS EN MAL ESTADO	12/09/2021		Corrective Order	WO Completed	Bus
666449	Bomag BW24RH	Llanta flat	LLANTA FLAT	12/09/2021		Corrective Order	WO Completed	Roller PTR
666456	Hino Series300	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/09/2021		Corrective Order	WO Completed	Truck
666506	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/09/2021		Corrective Order	WO Completed	Pickup truck
666585	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	12/09/2021		Corrective Order	WO Completed	Mule truck
666645	SJS SJ6530	Rectificacion de agujero	RECTIFICACION	12/09/2021		Corrective Order	WO Completed	Compactor
666801	Bomag BW219DH-4	EVALUAR CAMBIO DE RODILLO	EVALAUR MANIOBRAS DE IZAJE Y RETIRO	12/09/2021		Corrective Order	WO Completed	Compactor
666876	Caterpillar 740B	C/ BERING CYL SUSPENSION	BEARING DESGASTADOS	12/09/2021		Corrective Order	WO Completed	Articulated dump truck
666880	SJS SJ6530	ajuste de Pin y tornilleria	EQUIPO CON FALTA E AJUSTE EN EL PIN Y TORNILLERIA	12/09/2021		Corrective Order	WO Completed	Compactor
666884	USP&E GP700S/V-A 700 kVa	CORRECTIVO	REEMPLAZO DE BATERIAS	12/09/2021 16084 hrs		Corrective Order	WO Completed	Generator
666885	SJS SJ6530	reparacion de mount	LOS MOUNT ESTAN EN MAL ESTADO	12/09/2021		Corrective Order	WO Completed	Compactor
666888	Mack Trucks GU	CYLINDER REPAIR (MASTER TECH)	ENVIAR A MASTER TECH	12/09/2021 50016680		Corrective Order	WO Completed	Boom truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
666895	Mobile equipment	Reparacion de llanta JCB	REPARACION LLANTA JCB	12/09/2021		Corrective Order	WO Completed	Area
666901	Hino Series 300	cambio de 1 llanta	LLANTA EN MAL ESTADO	12/09/2021		Corrective Order	WO Completed	Truck
666904	Terex RT5551 55TON	arranque auxiliar	ARRANQUE AUXILIAR	12/09/2021		Corrective Order	WO Completed	Crane/Hoist
666905	Freightliner Columbia CI112	Revision de velocimetro	REVISION DE VELOCIMETRO	12/09/2021		Corrective Order	WO Completed	Mule truck
666907	Freightliner Columbia CI112	cambio de bombillo	LUCES DELANTERAS NO ENCIENDEN	12/09/2021		Corrective Order	WO Completed	Mule truck
666917	Caterpillar 307E Miniexcavator	cambio de manguera	CAMBIO DE MANGUERA	12/09/2021		Corrective Order	WO Completed	Excavator
667120	Coaster	REPARACION DE 1 LLANTA	REPARACION DE 1 LLANTA	13/09/2021		Corrective Order	WO Completed	Bus
667121	Caterpillar 14M Motorgrader	Tornillos de cilindro ausente	TORNILLOS DE CILINDRO AUSENTE	13/09/2021		Corrective Order	WO Completed	Grader
667183	Freightliner Columbia CI112	cambio de 3 llantas	LLANTAS EN MAL ESTADO	13/09/2021		Corrective Order	WO Completed	Mule truck
667211	Manitou Mht-X1490 9t Telehand	cambio de llanta	LLANTA DAÑADA	13/09/2021		Corrective Order	WO Completed	Telehender
667244	ETNYRE QUAD	Remplazo de faja	REPLAZO DE FAJA	13/09/2021		Corrective Order	WO Completed	Chip Spreader
667286	Caterpillar 740B EJ ADT	FABRICACION DE MANGUERAS	EQUIPO IASA// SONCAR	13/09/2021		Corrective Order	WO Completed	Articulated dump truck
667318	Caterpillar 426f2 Backhoe	REPARACION DE LUCES	REPARACION DE LUCES	13/09/2021		Corrective Order	WO Completed	Backhoe
667328	Caterpillar 426f2 Backhoe	Cambio de herramientas de cort	CAMBIO DE HERRAMIENTAS DE CORTE	13/09/2021		Corrective Order	WO Completed	Backhoe
667354	JLG 800 AJ Manlift	cambio de correa	CORREA DE ALTERNADOR EN MAL ESTADO	13/09/2021		Corrective Order	WO Completed	Manlift
667380	Caterpillar 740B	FLUSHING TREN DELANTERO	FLUSHING TREN DELANTERO	13/09/2021		Corrective Order	WO Completed	Articulated dump truck
667388	Grove RT650E 45TON	ajuste de manguera	FUGA DE ACEITE HIDRAULICO	13/09/2021		AFCE Job Mod Squad	WO Completed	Crane/Hoist
667398	JLG 450 AJ Manlift	cambio de palanaca e avance	NO SE DESPLAZA	13/09/2021		Corrective Order	WO Completed	Manlift
667401	JLG 1250 AJP Manlift	Revision de equipo	REVISION DE EQUIPO	13/09/2021	6187,3	Corrective Order	WO Completed	Manlift
667436	Caterpillar 740B	DESMONTAJE LLANTA POS 2	DESMONTAJE DE LLANTA	13/09/2021		Corrective Order	WO Completed	Articulated dump truck
667490	Caterpillar 740B EJ ADT	C/ BOMBA DE GRASA	BOMBA DE GRASA DAÑADA	13/09/2021		Corrective Order	WO Completed	Articulated dump truck
667559	Caterpillar 426f2 Backhoe	revision y arranque	EQUIPO NO ARRANCA	13/09/2021		Corrective Order	WO Completed	Backhoe
667564	SJS SJ6530	Reparacion de mounts	REPARACION DE MOUNTS	13/09/2021		Corrective Order	WO Completed	Compactor
667566	SJS SJ6530	cambio de 2 ruedas y torniller	CAMBIO DE 2 RUEDAS Y TRONILLERIA	13/09/2021		Corrective Order	WO Completed	Compactor
667567	TTP-0000-102	Engrase general	ENGRASE GENERAL	13/09/2021		Corrective Order	WO Completed	Excavator
667569	Freightliner Columbia CI112	Reemplazo de llantas	REEMPLAZO DE LLANTA	13/09/2021		Corrective Order	WO Completed	Mule truck
667571	Gallegos Flatbed Trailer	ajuste de frenos	AJUSTE DE FRENOS	13/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
667573	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTA	13/09/2021		Corrective Order	WO Completed	Pickup truck
667574	Hino Series 300	cambio de 1 llanta	CAMBIO DE 1 LLANTA	13/09/2021		Corrective Order	WO Completed	Truck
667575	Hilux DC	Reparacion de llanta	REPARACION DE 1 LLANTA	13/09/2021		Corrective Order	WO Completed	Pickup truck
667576	MAGNUM Light Tower	LLAMADA DE EMERGENCIA	CORRECCION DE FUGA DE ACEITE	13/09/2021	27078 hrs	Corrective Order	WO Completed	Light Tower
667577	Caterpillar 226b Skid Steer L	REPARACION AIRE ACONDIONADO	EQUIPO IASA	13/09/2021	90015149	Corrective Order	WO Completed	Skid Steer
667579	Caterpillar 236d Skid Steer L	revision de sist. de inyeccion	EQUIPO NO ARRANCA	13/09/2021		Corrective Order	WO Completed	Skid Steer
667592	Caterpillar 140K	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	13/09/2021		Corrective Order	WO Completed	Grader
667914	Pramac GSW30P 24KVA	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	14/09/2021	12398 horas	Corrective Order	WO Completed	Generator
667918	Ford 450	reparacion de aire acondiciona	REPARACION DE AIRE ACONDICIONA	14/09/2021		Corrective Order	WO Completed	Pickup truck
667919	JLG 1250 AJP Manlift	equipo bloqueado	EQUIPO BLOQUEADO	14/09/2021		Corrective Order	WO Completed	Manlift
667920	JLG 1850 AJ Manlift	EQUIPO BLOQUEADO	EQUIPO BLOQUEADO	14/09/2021		Corrective Order	WO Completed	Manlift
667922	Caterpillar 740B	MONTAJE LLANTA PM 2	MONTAJE LLANTA PM 2	14/09/2021		Corrective Order	WO Completed	Articulated dump truck
667982	Freightliner 8170ME Water Truc	llanta flat y vibración del ej	LLANTA FLAT Y VIBRACIÓN DEL EJ	14/09/2021		Corrective Order	WO Completed	Water truck
667986	Caterpillar 336DL	Pin del petate se está saliend	PIN DEL PETATE SE ESTÁ SALIEND	14/09/2021		Corrective Order	WO Completed	Excavator
667991	Freightliner CI 120	Sin Frenos	SIN FRENOS	14/09/2021		Corrective Order	WO Completed	Mule truck
668002	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668003	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668005	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668006	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668007	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668010	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668011	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668016	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668017	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668019	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668020	Landcruiser TC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668023	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668026	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668027	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668029	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668030	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668038	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668040	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668043	Caterpillar 226b Skid Steer L	REPARACION ELECTRICA	EQUIPO IASA	14/09/2021	90015146	Corrective Order	WO Completed	Skid Steer
668185	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	14/09/2021		Corrective Order	WO Completed	Pickup truck
668186	Landcruiser TC	Cambio de muelles	CAMBIO DE MUELLES	14/09/2021		Corrective Order	WO Completed	Pickup truck
668190	Isuzu NMR85L	cambio de bateria	CAMBIO DE BATERIA	14/09/2021		Corrective Order	WO Completed	Truck
668193	Ford 450	instalacion de fan clucht	INSTALACION DE FAN CLUCHT	14/09/2021		Corrective Order	WO Completed	Pickup truck
668220	Grove RT9130E 120TON	cambio de sensor de presion	SENSOR DE PRESION EN MAL ESTADO	14/09/2021	60022632	Corrective Order	WO Completed	Crane/Hoist
668230	JLG 450 AJ Manlift	CYLINDER REPAIR (MASTER TECH)	CORRECTIVE	14/09/2021	50016679	Corrective Order	WO Completed	Manlift
668265	Landcruiser TC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
668284	USP&E GP700/V-A 700 kVa	CORRECTIVO	AJUSTE Y ESTABILIZACION DE VOLTAJE	14/09/2021	10771 hrs	Corrective Order	WO Completed	Generator
668285	Landcruiser DC	SOLICITUD USUARIO	CORRECTIVO	14/09/2021		Corrective Order	WO Completed	Pickup truck
668328	Freightliner Cl 120	Reparacion de A/C	REPARACION DE A/C	14/09/2021	193505.2 kms	Corrective Order	WO Completed	Mule truck
668330	Caterpillar 12M	Revision de a/c	REVISION DE A/C	14/09/2021		Corrective Order	WO Completed	Grader
668331	Freightliner Cl 120	Reparacion de A/C	REPARACION DE A/C	14/09/2021		Corrective Order	WO Completed	Mule truck
668334	Hyster H700 Forklift	Revision de equipo	REVISION DE EQUIPO	14/09/2021		Corrective Order	WO Completed	Forklift
668335	Hyster H300 Forklift	Revision de equipo	REVISION DE EQUIPO	14/09/2021		Corrective Order	WO Completed	Forklift
668339	Caterpillar 426f2 Backhoe	reparacion de llanta	LLANTA FLAT	14/09/2021		Corrective Order	WO Completed	Backhoe
668342	New Holland Lm 1745	Revision de equipo	REVISION DE EQUIPO	14/09/2021		Corrective Order	WO Completed	Telehender
668375	Landcruiser TC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668376	Landcruiser DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668377	Landcruiser DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668378	Landcruiser DC	Cambio de llanta	CAMBIO DE LLANTA	14/09/2021		Corrective Order	WO Completed	Pickup truck
668379	Landcruiser DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	14/09/2021		Corrective Order	WO Completed	Pickup truck
668387	Caterpillar 14M Motorgrader	Fabricación de mangueras	FABRICACIÓN DE MANGUERAS	14/09/2021		Corrective Order	WO Completed	Grader
668555	Caterpillar 426f2 Backhoe	Llanta flat	LLANTA FLAT	15/09/2021	90013324	Corrective Order	WO Completed	Backhoe
668576	SDMO J30U 38KVA	FALLO DE DISYUNTOR TRIP	LLAMADA DE EMERGENCIA	15/09/2021	9615 horas	Corrective Order	WO Completed	Generator
668577	Caterpillar 12M	Necesita cambio de cuchilla	NECESITA CAMBIO DE CUCHILLA	15/09/2021		Corrective Order	WO Completed	Grader
668578	Caterpillar 416F2 Backhoe	Le hace falta una grapa para s	LE HACE FALTA UNA GRAPA PARA S	15/09/2021		Corrective Order	WO Completed	Backhoe
668582	Grove GMK4100L 100TON	Fuga de hidraulico	FUGA DE HIDRAULICO	15/09/2021		Corrective Order	WO Completed	Crane/Hoist
668583	Grove RT600E 50TON	reparacion de luces	REPARACION DE LUCES	15/09/2021		Corrective Order	WO Completed	Crane/Hoist
668585	Freightliner Columbia Cl112	LLANTA FLAT	LLANTA FLAT	15/09/2021		Corrective Order	WO Completed	Mule truck
668596	Caterpillar 740B	REEM/ PALELES DE CAPO MOTOR	FISURAS	15/09/2021		Corrective Order	WO Completed	Articulated dump truck
668597	Caterpillar 740B	REEM/ CONDENSADOR DE A/C	FISURA	15/09/2021		Corrective Order	WO Completed	Articulated dump truck
668598	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/09/2021		Corrective Order	WO Completed	Pickup truck
668608	Grove RT600E 50TON	cambio de 2 lamparas	CAMBIO DE 2 LAMPARAS	15/09/2021		Corrective Order	WO Completed	Crane/Hoist
668642	JLG 1250 AJP Manlift	revision de equipo	REVISION DE EQUIPO	15/09/2021		Corrective Order	WO Completed	Manlift
668685	Gallegos Flatbed Trailer	cambio de 4 llantas	CAMBIO DE LLANTA	15/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
668711	Kalmar	PREVENTIVE MAINTENANCE (250 H)	PREVENTIVE MAINTENANCE	15/09/2021	2698 HR	Corrective Order	WO Completed	Telehender
668745	Freightliner M112 Truck Tip	REPARACION BEM SUSPENSION	REPARACION IMREPSA	15/09/2021		Corrective Order	WO Completed	Tipper
668752	Manitou MTH-X 10120	PREVENTIVE MAINTENANCE (250 H)	PREVENTIVE MAINTENANCE (GPE)	15/09/2021	6994.6 HR	Corrective Order	WO Completed	Telehender
668768	Mobile equipment	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/09/2021		Corrective Order	WO Completed	Area
668776	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/09/2021		Corrective Order	WO Completed	Pickup truck
668777	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/09/2021		Corrective Order	WO Completed	Pickup truck
668779	Caterpillar 740b Ej	REEM/ FILTROS DE COMBUSTIBLE	BAJA PRESION	15/09/2021		Corrective Order	WO Completed	Articulated dump truck
668811	Phoenix MK7T	reparaciones varias	REPARACION DE LIMPIADORES	15/09/2021		Corrective Order	WO Completed	Chip Spreader
668875	Linde T30D	PREVENTIVE MAINTENANCE (250 H)	PREVENTIVE MAINTENANCE (GPE)	15/09/2021	3752.7 HR	Corrective Order	WO Completed	Forklift
668879	Hyster H700 Forklift	Instalacion de alarma	INSTALACION DE ALARMA DE RETROCESO	15/09/2021		Corrective Order	WO Completed	Forklift
668905	Ferrari F478	PREVENTIVE MAINTENANCE (250 H)	PREVENTIVE MAINTENANCE (GPE)	15/09/2021	6832.6 HR	Corrective Order	WO Completed	Reach Stacker
668923	SDMO J60U 60KVA	DESCONEXION Y TRASLADO	DESCONEXION Y TRASLADO	15/09/2021	260 hrs	Corrective Order	WO Completed	Generator
668954	Gallegos Flatbed Trailer	reparacion de llanta	LLANTA FLAT	15/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
668955	WT015 H7 CISTERNA SINOTRUK	Reparacion de suspension	REPARARACION DE SUSPENSION	15/09/2021		Corrective Order	WO Completed	Water truck
668958	Hyster H700 Forklift	relleno de aceite hidraulico	RELLENO DE ACEITE HIDRAULICO	15/09/2021		Corrective Order	WO Completed	Forklift
668967	Unimog Service Truck	EQUIPO NO ENCIENDE	EQUIPO NO ENCIENDE	15/09/2021		Corrective Order	WO Completed	Truck
668971	Freightliner Cl 120	Cambio de barra de dirección	CAMBIO DE BARRA DE DIRECCIÓN	15/09/2021		Corrective Order	WO Completed	Mule truck
669043	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	16/09/2021	10324 hrs	PM Orders	WO Completed	Generator
669044	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	16/09/2021	16668 hrs	PM Orders	WO Completed	Generator
669045	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	16/09/2021		PM Orders	WO Completed	Generator
669067	SDMO J30U 38KVA	CAMBIO DE DISYUNTOR	DIYUNTOR CON TRIP PERMANENTE	16/09/2021	9615 horas	Corrective Order	WO Completed	Generator
669096	DOOSAN 1005	EQUIPO NO ARRANCA	FALLO DE ARRANQUE, CAMBIO DE BATERIA O ALTERNADOR	16/09/2021	19973 horas	Corrective Order	WO Completed	Light Tower
669098	Freightliner Cl 120	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	16/09/2021		Corrective Order	WO Completed	Mule truck
669099	Caterpillar 12M	Fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	16/09/2021		Corrective Order	WO Completed	Grader
669100	Caterpillar 416F2 Backhoe	Llanta trasera izquierda flat	LLANTA TRASERA IZQUIERDA FLAT	16/09/2021		Corrective Order	WO Completed	Backhoe
669121	Caterpillar D8T Dozer	Falta de aceite hidráulico y c	FALTA DE ACEITE HIDRÁULICO Y C	16/09/2021		Corrective Order	WO Completed	Dozer
669162	Caterpillar 416F2 Backhoe	cambio de 2 llantas	LLANTAS EN MAL ESTADO	16/09/2021		Corrective Order	WO Completed	Backhoe
669176	Liugong Cpcd20	LEVANTAMIENTO DE FILTROS	INSPECCION	16/09/2021		Corrective Order	WO Completed	Forklift
669199	New Holland Lm 1745	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/09/2021	90013415	Corrective Order	WO Completed	Telehender
669251	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	16/09/2021		Corrective Order	WO Completed	Pickup truck
669267	Hyster H700 Forklift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/09/2021		Corrective Order	WO Completed	Forklift
669280	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR FALTA DE COMBUSTIBLE	16/09/2021	28030 hrs	Corrective Order	WO Completed	Generator
669326	Grove RT600E 50TON	Cambio de manguera hidra	MANGUERA HIDRAULICA ROTA	16/09/2021		Corrective Order	WO Completed	Crane/Hoist
669343	Caterpillar RM500 Reclaimer	Necesita Coolant	NECESITA COOLANT	16/09/2021		Corrective Order	WO Completed	Road Reclaimer
669362	WT013 H7 CISTERNA SINOTRUK	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/09/2021		PM Orders	WO Completed	Water truck
669389	Freightliner Columbia Cl112	ESPEJOS RAJADOS	ESPEJOS RAJADOS	16/09/2021		Corrective Order	WO Completed	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
669407	USP&E GP700/V-A 700 kVa	LLAMADA DE EMERGENCIA	APAGADO POR ALTA TEMPERATURA	16/09/2021	10819 hrs	Corrective Order	WO Completed	Generator
669425	Caterpillar RM500 Reclaimer	Revision de equipo	REVISION DE SISTEMA DE REFRIGERACION	16/09/2021		Corrective Order	WO Completed	Road Reclaimer
669427	Hyster H700 Forklift	Revision de equipo	REVISION DE SISTEMA DE ENGRASE	16/09/2021		Corrective Order	WO Completed	Forklift
669429	Caterpillar 426F2 Backhoe	Revision de equipo	REEMPLAZO DE LLANTA	16/09/2021	2472.6 hrs	Corrective Order	WO Completed	Backhoe
669437	Freightliner Columbia CI112	Revision de equipo	FUGA DE ACEITE DE TRANSMISION	16/09/2021		Corrective Order	WO Completed	Mule truck
669439	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	16/09/2021		Corrective Order	WO Completed	Pickup truck
669442	Caterpillar 12M	Revision de equipo	CAMBIO DE SENSOR DE ARTICULACION	16/09/2021	12,316.2 Hrs	Corrective Order	WO Completed	Grader
669452	Caterpillar D8T Dozer	Revision de equipo	FUGA DE ACEITE HIDRAULICO	16/09/2021		Corrective Order	WO Completed	Dozer
669454	Caterpillar 226b Skid Steer L	Revision de equipo	REPARACION DE 1 LLANTA	16/09/2021		Corrective Order	WO Completed	Skid Steer
669473	Hyster H800 32t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	16/09/2021		Corrective Order	WO Completed	Forklift
669474	Hyster H800 32t Forklift (M)	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669475	Hyster H300 13t Forklift (M)	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669476	Hyster H800 32t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	16/09/2021		Corrective Order	WO Completed	Forklift
669478	Hyster H300 13t Forklift (M)	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669479	Hyster H700 Forklift	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	16/09/2021		Corrective Order	WO Completed	Forklift
669480	Hyster H300 13t Forklift (M)	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669481	Hyster H700 Forklift	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669482	Hyster H300 Forklift	REVISION AUTOENGRASE	CORRECTIVO	16/09/2021		Corrective Order	WO Completed	Forklift
669622	SDMO J30U 38KVA	CAMBIO DE INTERRUPTOR EXTERNO	CAMBIO DE INTERRUPTOR EXTERNO	17/09/2021		Corrective Order	WO Completed	Generator
669627	Caterpillar 14M Motorgrader	Daño en pieza de bronce	DAÑO EN PIEZA DE BRONCE	17/09/2021		Corrective Order	WO Completed	Grader
669685	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669686	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669687	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669688	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669690	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669725	Hilux DC	cambio de llanta	LLANTAS EN MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669738	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	17/09/2021		Corrective Order	WO Completed	Mule truck
669740	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669747	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669755	Landcruiser TC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669767	Caterpillar 740B	ROTACION DE LLANTA POS 1	ROTACION DE LLANTA POS 1	17/09/2021	PROG 20 AL 27 DE SEP	Corrective Order	WO Completed	Articulated dump truck
669768	Caterpillar 740B	ROTACION DE LLANTA POS 2	ROTACION DE LLANTA POS 2	17/09/2021	PROG 20 AL 27 DE SEP	Corrective Order	WO Completed	Articulated dump truck
669779	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	17/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
669788	T30D LINDE	Revision de la direccion	REVISION DE LA DIRECCION	17/09/2021		Corrective Order	WO Completed	.
669820	Unimog Service Truck	Revision de equipo	REVISION DE FUGA DE REFRIGERANTE	17/09/2021		Corrective Order	WO Completed	Truck
669896	Caterpillar 416F2 Backhoe	CAMBIO DE RIM y NEUMATICOS	DANO DE RIM	17/09/2021	90014676 90014677	Corrective Order	WO Completed	Backhoe
669927	Freightliner Columbia CI112	reparacion de 1 llanta	LLANTA FLAT	17/09/2021		Corrective Order	WO Completed	Mule truck
669928	Hilux DC	Mantenimient Preventivo	MANTENIMIENTO PREVENTIVO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669929	Landcruiser TC	Camio de muelles	CAMBIO DE MUELLES	17/09/2021		Corrective Order	WO Completed	Pickup truck
669932	PB002 COASTER TOYOTA	cambio de bateria	BATERIA EN MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Bus
669933	Landcruiser DC	Cambio de bujes de barra de to	CAMBIOS DE BUJES DE BARRA DE TORSION	17/09/2021		Corrective Order	WO Completed	Pickup truck
669934	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669937	Toyota Hilux	reparacion de caja de fusibles	REPARACION DE CAJA DE FUSIBLES	17/09/2021		Corrective Order	WO Completed	Pickup truck
669938	Ford 450	Revision de equipo	CAMBIO DE ACEITE DE TRANSMISION	17/09/2021		Corrective Order	WO Completed	Pickup truck
669941	Hilux DC	cambio de pertiga	CAMBIO DE PERTIGA	17/09/2021		Corrective Order	WO Completed	Pickup truck
669942	Landcruiser DC	Revision de equipo	REPARACION DE CAJA DE TRANSFERENCIA	17/09/2021		Corrective Order	WO Completed	Pickup truck
669943	Hilux DC	Revision de equipo	CAMBIO DE LAMPARAS TRASERAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
669945	Landcruiser TC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	17/09/2021		Corrective Order	WO Completed	Pickup truck
669946	Landcruiser DC	Revision de equipo	CAMBIO DE PERDIGA	17/09/2021		Corrective Order	WO Completed	Pickup truck
669947	Landcruiser TC	Rep. Cremallera de puerta	REP. CREMLLERA DE PUERTA	17/09/2021		Corrective Order	WO Completed	Pickup truck
669964	Gallegos 28M3 Lime Tank	FUGA POR TAPA	FUGA POR TAPA	17/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
669973	Caterpillar D8T Dozer	Esta neutralizado	ESTA NEUTRALIZADO	17/09/2021		Corrective Order	WO Completed	Dozer
669992	Caterpillar D8T Dozer	Fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	17/09/2021		Corrective Order	WO Completed	Dozer
670029	Caterpillar 14M Motorgrader	CAMBIO DE SENSOR DE POSICION	EQUIPO IASA	17/09/2021	90015898	Corrective Order	WO Completed	Grader
670030	Freightliner Columbia CI112	LUCES PILOTO	LUCES PILOTO	17/09/2021		Corrective Order	WO Completed	Mule truck
670031	Freightliner Columbia CI112	AMORTIGUADORES	AMORTIGUADORES	17/09/2021		Corrective Order	WO Completed	Mule truck
670066	Hyster H300 13t Forklift (M)	Equipo Fuera de Servicio	EQUIPO FUERA DE SERVICIO	17/09/2021	2317 Hrs	Corrective Order	WO Completed	Forklift
670116	LB002 725 CAT	PM04 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	17/09/2021		Corrective Order	WO Completed	Truck
670117	Grove RT600E 50TON	REVISION ELECTRICA	INSPECCION	17/09/2021		Corrective Order	WO Completed	Crane/Hoist
670118	Grove RT600E 50TON	REVISION A/A	INSPECCION	17/09/2021		Corrective Order	WO Completed	Crane/Hoist
670126	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	17/09/2021		Corrective Order	WO Completed	Pickup truck
670127	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
670129	Landcruiser DC	Cambio de 2 lantass	LLANTAS EM MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Pickup truck
670130	Landcruiser TC	CAMBIO DE 1 LLANTA	LLANTA EN MAL ESTADO	17/09/2021		Corrective Order	WO Completed	Pickup truck
670131	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/09/2021		Corrective Order	WO Completed	Pickup truck
670139	TTP-0000-102	Revision de equipo	RELLENO DE ACEITE HIDRAULICO	17/09/2021		Corrective Order	WO Completed	Excavator
670140	Caterpillar 336DL Excavator	Revision de equipo	COLOCACION DE PIN DE BALDE	17/09/2021		Corrective Order	WO Completed	Excavator
670141	Manitou Mht-X860 6t Telehand	Revision de equipo	REVISION DE SISTEMA DE CARGA	17/09/2021		Corrective Order	WO Completed	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
670142	Caterpillar 426f2 Backhoe	Revision de equipo	ENGRASE DE EQUIPO	17/09/2021		Corrective Order	WO Completed	Backhoe
670480	FG WILSON P88-3 80 kVa	PM1 FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 25640 hrs		PM Orders	WO Completed	Generator
670481	Caterpillar DE165E0 165 kVa	PM1 CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 17056 hrs		PM Orders	WO Completed	Generator
670482	Caterpillar D110 E2 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 17729 hrs		PM Orders	WO Completed	Generator
670483	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 12575 horas		PM Orders	WO Completed	Generator
670484	PRAMAC GSW120 120 kVa	PM1 PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 6794 hrs		PM Orders	WO Completed	Generator
670485	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 17481 hrs		PM Orders	WO Completed	Generator
670488	SDMO J30U 38 kVa	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 13382 hrs		PM Orders	WO Completed	Generator
670489	SDMO J30U 38KVA	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 8979 hrs		PM Orders	WO Completed	Generator
670490	Caterpillar DE88E0 58 kVa	PM1 CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 37925 hrs		PM Orders	WO Completed	Generator
670491	PRAMAC GSW90P 74 kVa	PM1 PRA GSW90P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 26445 horas		PM Orders	WO Completed	Generator
670492	SDMO T16 16KVA	PM1 SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 24245 hrs		PM Orders	WO Completed	Generator
670493	PRAMAC GSW30Y 24 kVa	PM1 PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 22409 HORAS		PM Orders	WO Completed	Generator
670494	Pramac GSW30P 24KVA	PM1 PRA GSW30P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 12466 horas		PM Orders	WO Completed	Generator
670500	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 1060 hrs		PM Orders	WO Completed	Light Tower
670501	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 1017 hrs		PM Orders	WO Completed	Light Tower
670502	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 1000 hrs		PM Orders	WO Completed	Light Tower
670520	MAGNUM Light Tower	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	19/09/2021 27460 horas		Corrective Order	WO Completed	Light Tower
670527	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 839 horas		PM Orders	WO Completed	Generator
670528	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 359 horas		PM Orders	WO Completed	Generator
670529	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 8258 hrs		PM Orders	WO Completed	Generator
670530	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 16485 hrs		PM Orders	WO Completed	Generator
670535	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 10422 hrs		PM Orders	WO Completed	Generator
670537	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 16084 horas		PM Orders	WO Completed	Generator
670538	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 16809 hrs		PM Orders	WO Completed	Generator
670541	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 8644 horas		PM Orders	WO Completed	Generator
670542	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 3633 horas		PM Orders	WO Completed	Generator
670543	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 586 horas		PM Orders	WO Completed	Generator
670551	MAGNUM Light Tower	CORRECTIVO	CAMBIO DE MOTOR DE ARRANQUE	19/09/2021 27147 hrs		Corrective Order	WO Completed	Light Tower
670555	SDMO J60U 60KVA	CORRECTIVO	CAMBIO DE ALTERNADOR DC Y FUSIBLE	19/09/2021 261 hrs		Corrective Order	WO Completed	Generator
670565	MAGNUM Light Tower	CAMBIO MOTOR ARRANQUE	NO FUNCIONA	19/09/2021 27551 hotas		Corrective Order	WO Completed	Light Tower
670586	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 63 hrs		PM Orders	WO Completed	Generator
670587	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 9774 hrs		PM Orders	WO Completed	Generator
670588	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 11008 horas		PM Orders	WO Completed	Generator
670589	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	19/09/2021 160 horas		PM Orders	WO Completed	Generator
670624	Caterpillar 226b Skid Steer L	Instalación de extintor	INSTALACIÓN DE EXTINTOR	19/09/2021		Corrective Order	WO Completed	Skid Steer
670626	Caterpillar 226b Skid Steer L	Instalacion de extirntor	INTALACION DE EXTIRNTOR	19/09/2021		Corrective Order	WO Completed	Skid Steer
670627	Caterpillar 12M	Cambio de filtros de aire admi	CAMBIO DE FILTRO DE AIRE ADMISIÓN	19/09/2021		Corrective Order	WO Completed	Grader
670629	Caterpillar 226b Skid Steer L	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	19/09/2021		Corrective Order	WO Completed	Skid Steer
670631	Toyota Hilux	INSTALACIÓN DE CAMILLA	INSTALACIÓN DE CAMILLA	19/09/2021 96309 kms		Corrective Order	WO Completed	Pickup truck
670632	Coaster Bus	Reparación de sistema electric	REPARACIÓN DE SISTEMA ELECTRIC	19/09/2021 96664 kms		Corrective Order	WO Completed	Bus
670633	Toyota Land Cruiser	Instalacion de camilla	INSTALACION DE CAMILLA	19/09/2021 19913 kms		Corrective Order	WO Completed	Pickup truck
670634	Hino Serie 300 Box Truck	Instalacion de motor arranque	INSTALAION DE MOTOR DE ARRANQUE	19/09/2021		Corrective Order	WO Completed	Truck
670635	Toyota Hilux	Cambio de bandas y barra	CAMBIO DE BANDAS Y BARRA ESTABILIZADORA	19/09/2021 80142		Corrective Order	WO Completed	Pickup truck
670637	Toyota Hilux	CAMBIO DE BATERIAS	CAMBIO DE BATERÍAS	19/09/2021 88599 kms		Corrective Order	WO Completed	Pickup truck
670638	Coaster Bus	Cambio de bandas	CAMBIO DE BANDAS Y CILINDRO	19/09/2021 74952 kms		Corrective Order	WO Completed	Bus
670639	Toyota Hilux	Instalacion de sirena	INSTALACION DE SIRENA	19/09/2021		Corrective Order	WO Completed	Pickup truck
670640	Toyota Hilux	Reparacion de motor de arranqu	REPARACION DE MOTOR DE ARRANQU	19/09/2021		Corrective Order	WO Completed	Pickup truck
670641	Landcruiser TC	reemplazo de componentes	REEMPLAZO DE COMPONENTES	19/09/2021 40588 kms		Corrective Order	WO Completed	Pickup truck
670642	Landcruiser TC	Cambio de alternador	CAMBIO DE ALTERNADOR	19/09/2021 25598 kms		Corrective Order	WO Completed	Pickup truck
670643	Landcruiser DC	Cambio de alternador	CAMBIOD E ALTENRADOR	19/09/2021 93689		Corrective Order	WO Completed	Pickup truck
670644	Hilux DC	Cambio de plato de suspensión	CAMBIO DE PLATO DE SUSPENSIÓN	19/09/2021 46205 kms		Corrective Order	WO Completed	Pickup truck
670645	Landcruiser DC	Falla de freewheel	FALLA DE FREEWHEEL	19/09/2021 76670 KMS		Corrective Order	WO Completed	Pickup truck
670648	Hilux DC	Cambio de eje flecha	CMBIO DE EJE FLECHA	19/09/2021 73974 kms		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
670649	Hilux DC	Cambio de hoja de muelle	CAMBIO DE HOJA DE MUELLE	19/09/2021	35590 kms	Corrective Order	WO Completed	Pickup truck
670650	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTE	19/09/2021	36283 kms	Corrective Order	WO Completed	Pickup truck
670651	Hilux DC	cAMBIO DE TERMINALES DE DIRECC	CAMBIO DE TERMINALES DE DIRECCION	19/09/2021	39174 KMS	Corrective Order	WO Completed	Pickup truck
670652	Caterpillar 14H Motorgrader	Mantenimiento Sist.AFEX	MANTENIMIENTO SIST.AFEX	19/09/2021		Corrective Order	WO Completed	Grader
670653	Landcruiser DC	Cambio de kit de embrague	CAMBIO DE KIT DE EMBRAGUE Y VOLANTE	19/09/2021	46367 KMS	Corrective Order	WO Completed	Pickup truck
670654	Landcruiser TC	Cambio de radiador	CAMBIO DE RADIADOR	19/09/2021	59135 kms	Corrective Order	WO Completed	Pickup truck
670655	Hilux DC	Cambio de lampara	CAMBIO DE LAMPARA	19/09/2021	29743 kms	Corrective Order	WO Completed	Pickup truck
670656	Hilux DC	Cambio de eje de flecha LH	CAMBIO DE EJE DE FLECHA LH	19/09/2021	18019 KMS	Corrective Order	WO Completed	Pickup truck
670658	Landcruiser DC	CAMBIO DE TAMBORES	CAMBIO DE TAMBORES	19/09/2021	46367 KMS	Corrective Order	WO Completed	Pickup truck
670659	Freightliner Columbia CI112	Cambio de 4 Baterias	CAMBIO DE 4 BATERIAS	19/09/2021		Corrective Order	WO Completed	Mule truck
670660	Landcruiser TC	Cambio de 2 caliper	CAMBIO DE 2 CALIPER	19/09/2021	25718 kms	Corrective Order	WO Completed	Pickup truck
670661	Hilux DC	'CAMBIO EL EVAPORADOR AC	'CAMBIO EL EVAPORADOR AC	19/09/2021	24528 KMS	Corrective Order	WO Completed	Pickup truck
670662	Landcruiser DC	CAMBIO DE VALVULA DE EXPANSIO	CAMBIO DE VALVULA DE EXPANSION	19/09/2021	56177 KMS	Corrective Order	WO Completed	Pickup truck
670670	Hilux DC	CAMBIO DE HOJA DE MUELLE	CAMBIO DE HOJA DE MUELLE	19/09/2021	30577 kms	Corrective Order	WO Completed	Pickup truck
670673	Coaster	CAMBIO DE CILINDRO DE FRENOS	CAMBIO DE CILINDRO DE FRENOS TRASEROS	19/09/2021	30577	Corrective Order	WO Completed	Bus
670675	Hilux DC	'CAMBIO DE MUELLE	'CAMBIO DE MUELLE	19/09/2021	55335 kms	Corrective Order	WO Completed	Pickup truck
670676	Coaster	Cambio de componentes	CAMBIO DE COMPONENTES	19/09/2021	21293 kms	Corrective Order	WO Completed	Bus
670679	Hilux DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
670681	Hilux DC	CAMBIO DE HOJA DE MUELLE	CAMBIO DE HOJA DE MUELLE	20/09/2021	21746 kms	Corrective Order	WO Completed	Pickup truck
670682	Landcruiser TC	CAMBIO DE HOJA DE MUELLE	CAMBIO DE HOJA DE MUELLE	20/09/2021		Corrective Order	WO Completed	Pickup truck
670684	Landcruiser TC	'CAMBIO DE COCOBOLA	'CAMBIO DE COCOBOLA	20/09/2021	21575 kms	Corrective Order	WO Completed	Pickup truck
670685	Landcruiser TC	CAMBIO DE CALIPER DE FRENO RH	CAMBIO DE CALIPER DE FRENO RH	20/09/2021	69793 kms	Corrective Order	WO Completed	Pickup truck
670686	Landcruiser TC	CAMBIO DE CALIPER LH	CAMBIO DE CALIPER LH	20/09/2021	42101 kms	Corrective Order	WO Completed	Pickup truck
670687	Hilux DC	CAMBIO DE MUELLES (2)	CAMBIO DE MUELLES (2)	20/09/2021	69793 kms	Corrective Order	WO Completed	Pickup truck
670689	Landcruiser TC	CAMBIO DE EJE DE MANDO	CAMBIO DE EJE DE MANDO	20/09/2021	69793 kms	Corrective Order	WO Completed	Pickup truck
670700	DOOSAN 1005	FALLO DE ARRANQUE	BATERIA DESCARGADA, CAMBIO DE BATERIA	20/09/2021	29246 hrs	Corrective Order	WO Completed	Light Tower
670704	Caterpillar DE110E 110 kVa	CAMBIO DE CORREA	CORREA CON DESGASTE	20/09/2021	21621 horas	Corrective Order	WO Completed	Generator
670706	Pramac GSW30P 24KVA	FALLO DE VOLTAGE AC	EQUIPO NO GENERA VOLTAJE	20/09/2021	12466 horas	Corrective Order	WO Completed	Generator
670707	DOOSAN 1005	CAMBIO DE BOMBILLOS	BOMBILLOS QUEMADOS	20/09/2021	19992 horas	Corrective Order	WO Completed	Light Tower
670722	Freightliner M2 106 Refrigerat	Reparación de luces	REPARACIÓN DE LUCES	20/09/2021		Corrective Order	WO Completed	Refrigerator truck
670723	Freightliner M2 112	reparacion de machine brake	REPARACION DE MACHINE BRAKE	20/09/2021		Corrective Order	WO Completed	Boom truck
670724	Manitou Mht-X860 6t Telehand	Tornillo de cilindro Partido	TORNILLO DE CILINDRO PARTIDO	20/09/2021		Corrective Order	WO Completed	Telehender
670725	Unimog Service Truck	Bajo nivel e aceite de freno	BAJO NIVEL E ACEITE DE FRENO	20/09/2021		Corrective Order	WO Completed	Truck
670727	LB002 725 CAT	reparacion de aire acondiciona	REPARACION DE AIRE ACONDICIONADO	20/09/2021		Corrective Order	WO Completed	Truck
670730	Mobile equipment	cabezal intertrans flat	REPARACION DE 1 LLANTA	20/09/2021		Corrective Order	WO Completed	Area
670732	Hilux DC	reparacion de 1 llanta	LLANTA FLAT	20/09/2021		Corrective Order	WO Completed	Pickup truck
670770	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	20/09/2021		Corrective Order	WO Completed	Pickup truck
670776	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	20/09/2021		Corrective Order	WO Completed	Bus
670778	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	20/09/2021		Corrective Order	WO Completed	Bus
670797	Hino Serie 300 Box Truck	REVISAR SISTEMA ELECTRICO	PROBLEMAS ELECTRICOS	20/09/2021		Corrective Order	WO Completed	Truck
670818	Freightliner CI 120	FUGA DE AIRE / LLANTA BAJA	FUGA DE AIRE / LLANTA BAJA	20/09/2021		Corrective Order	WO Completed	Mule truck
670841	Gallegos Lime Tank	FUGA POR TAPA	FUGA POR TAPA	20/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
671054	ETNYRE QUAD	Soldadura de piso donde se car	SOLDADURA DE PISO DONDE SE CAR	20/09/2021		Corrective Order	WO Completed	Chip Spreader
671058	ETNYRE QUAD	Remplazo de faja completa	REMPLAZO DE FAJA	20/09/2021		Corrective Order	WO Completed	Chip Spreader
671075	Caterpillar 740B EJ ADT	C/ TORNILLOS MONTAJE CAJA	ROTOS	20/09/2021		Corrective Order	WO Completed	Articulated dump truck
671077	Caterpillar D8T Dozer	RESELLADO BOMBA TRANSMISION	EQUIPO IASA	20/09/2021		Corrective Order	WO Completed	Dozer
671096	SDMO J60U 60KVA	CORRECTIVO	TRASLADO Y CONEXION DE GENERADOR	20/09/2021	261 hrs	Corrective Order	WO Completed	Generator
671118	Manitou Mht-X1490 9t Telehand	Revision de equipo	EQUIPO NO ARRANCA	20/09/2021		Corrective Order	WO Completed	Telehender
671219	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	20/09/2021		Corrective Order	WO Completed	Pickup truck
671245	Caterpillar 140K	Revision de equipo	INSTALACION DE PIN DE CILINDRO DE LA HOJA	20/09/2021	1256.2 hrs	Corrective Order	WO Completed	Grader
671290	Liugong Cpcd20	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	20/09/2021	90013779	Corrective Order	WO Completed	Forklift
671302	New Holland Lm 1745	CYLINDER REPAIR (MASTER TECH)	CORRECTIVE	20/09/2021	50016860	Corrective Order	WO Completed	Telehender
671303	Broderson IC200-2C 9TON	Revision de equipo	REVISION DE EQUIPO	20/09/2021		Corrective Order	WO Completed	Crane/Hoist
671304	Freightliner CI 120	Revision de equipo	REPARACION DE LUCES DELANTERAS	20/09/2021		Corrective Order	WO Completed	Mule truck
671310	Hilux DC	'CAMBIO MUELLES	'CAMBIO MUELLES	20/09/2021	85169 kms	Corrective Order	WO Completed	Pickup truck
671311	Hilux DC	CAMBIO DE KIT DE EMBRAGUE	CAMBIO DE KIT DE EMBRAGUE	20/09/2021	9532 kms	Corrective Order	WO Completed	Pickup truck
671312	Coaster	CAMBIO DE CILINDRO DE FRENOS	CAMBIO DE CILINDRO DE FRENOS TRASEROS	20/09/2021	64946 kms	Corrective Order	WO Completed	Bus
671313	Coaster	cambio de 2 llantas	CAMBIO DE 2 LLNTAS	20/09/2021		Corrective Order	WO Completed	Bus
671314	Coaster	Cambio de 2 llantas	CAMBIO DE 2 LLNTAS	20/09/2021		Corrective Order	WO Completed	Bus
671315	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	20/09/2021		Corrective Order	WO Completed	Bus
671316	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	20/09/2021		Corrective Order	WO Completed	Bus
671317	Coaster	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	20/09/2021		Corrective Order	WO Completed	Bus
671320	Hilux DC	Cambio de cable de freno	CAMBIO DE CAMBLE DE FRENO	20/09/2021		Corrective Order	WO Completed	Pickup truck
671321	Hilux DC	'CAMBIO DE MUELLES	'CAMBIO DE MUELLES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671322	Landcruiser TC	CAMBIO CALIPER, AJUSTADORES,	CAMBIO CALIPER, AJUSTADORES, RESORTES DE DE FRENO CAMBIO DE AMORTIGUADORES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671323	Landcruiser TC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671325	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
671326	Landcruiser DC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671328	Hilux DC	CAMBIO DE KIT DE EMBRAGUE	CAMBIO DE KIT DE EMBRAGUE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671329	Landcruiser DC	BRIDA DE ACOPLAMIENTO SENSOR	BRIDA DE ACOPLAMIENTO SENSOR VELOCIDAD	20/09/2021		Corrective Order	WO Completed	Pickup truck
671330	Landcruiser DC	CAMBIO DE CILINDROS DE FRENOS	CAMBIO DE CILINDROS DE FRENOS	20/09/2021		Corrective Order	WO Completed	Pickup truck
671331	Landcruiser DC	'CRUCETAS DE EJE DE MANDO	'CRUCETAS DE EJE DE MANDO	20/09/2021		Corrective Order	WO Completed	Pickup truck
671332	Hilux DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671334	Landcruiser DC	Cambio de amortiguadores	CAMBIO DE AMORTIGUADORES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671335	Landcruiser DC	'CAMBIO DE EJE DE MANDO	'CAMBIO DE EJE DE MANDO	20/09/2021		Corrective Order	WO Completed	Pickup truck
671336	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671337	Landcruiser DC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671340	Landcruiser DC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671341	Landcruiser TC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671342	Hilux DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671344	Landcruiser TC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671345	Hilux DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671346	Landcruiser DC	CAMBIO DE ALTERNADOR	CAMBIO DE ALTERNADOR	20/09/2021		Corrective Order	WO Completed	Pickup truck
671347	Hilux DC	'CAMBIO DE PERTIGA	'CAMBIO DE PERTIGA	20/09/2021		Corrective Order	WO Completed	Pickup truck
671348	Hilux DC	CAMBIO DE CONDENSADOR Y COMPRE	CAMBIO DE CONDENSADOR Y COMPRESOR	20/09/2021		Corrective Order	WO Completed	Pickup truck
671349	Hilux DC	ROLLING BOARD LH Y RH	ROLLING BOARD LH Y RH	20/09/2021		Corrective Order	WO Completed	Pickup truck
671350	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671351	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671352	Landcruiser DC	CAMBIO DE MOTOR DE ARRANQUE	CAMBIO DE MOTOR DE ARRANQUE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671354	Landcruiser DC	'KIT DE SELLOS HOUSING BUJE BA	'KIT DE SELLOS HOUSING BUJE BARRA ESTABILIZADORA BUJE MUELLE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671355	Landcruiser TC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671357	Landcruiser TC	'DISCO FRENOS CRUCETA EJE DE	'DISCO FRENOS CRUCETA EJE DE MANDO	20/09/2021		Corrective Order	WO Completed	Pickup truck
671358	Landcruiser TC	Cambio de alternador	CAMBIO DE ALTERMADOR	20/09/2021		Corrective Order	WO Completed	Pickup truck
671359	Landcruiser DC	CAMBIO DE CABLE DE FRENO	CAMBIO DE CABLE DE FRENO	20/09/2021		Corrective Order	WO Completed	Pickup truck
671360	Landcruiser DC	Cambio de componente	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671361	Landcruiser TC	Cambio de components	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671362	Landcruiser DC	Cambio de componentes	CAMBIO DE COMPONENTES	20/09/2021		Corrective Order	WO Completed	Pickup truck
671363	Hilux DC	'CAMBIO DE CREMALLERA CONJUN	'CAMBIO DE CREMALLERA CONJUNTO DE BOMBA PALETA	20/09/2021		Corrective Order	WO Completed	Pickup truck
671364	Landcruiser DC	' BOMBA DE AGUA	' BOMBA DE AGUA	20/09/2021		Corrective Order	WO Completed	Pickup truck
671365	Landcruiser TC	Fuga de refrigerante	FUGA DE REFRIGERANTE	20/09/2021		Corrective Order	WO Completed	Pickup truck
671368	Landcruiser DC	problema con alternador	PROBLEMA CON ALTERNADOR	20/09/2021		Corrective Order	WO Completed	Pickup truck
671379	Caterpillar D110 E2 100KVA	CAMBIO DE CORREA	CORREA DESGASTADA, CON RUIDO	21/09/2021	17830 horas	Corrective Order	WO Completed	Generator
671388	Coaster	Cambio de 2 llantas y pernos	CAMBIO DE DOS LLANTAS Y PERNOS	21/09/2021		Corrective Order	WO Completed	Bus
671389	Hyster H700 Forklift	Falla alarma de hidraulico	FALLA ALARMA DE HIDRAULICO	21/09/2021		Corrective Order	WO Completed	Forklift
671390	Freightliner 8170ME Water Truc	Reparación de luces	REPARACIÓN DE LUCES	21/09/2021		Corrective Order	WO Completed	Water truck
672030	Atlas Copco GESAN QIS 45 47KVA	PM1 ATL QIS45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/09/2021	5911 horas	PM Orders	WO Completed	Generator
672031	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/09/2021	37098 hrs	PM Orders	WO Completed	Light Tower
672092	Hilux DC	Reparacion Base de Pertiga	REPARACION BASE DE PERTIGA	21/09/2021	Emergency W38	Corrective Order	WO Completed	Pickup truck
672257	Caterpillar RM500 Reclaimer	Aire Acondicionado	AIRE ACONDICIONADO	21/09/2021		Corrective Order	WO Completed	Road Reclaimer
672385	Landcruiser DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	21/09/2021		Corrective Order	WO Completed	Pickup truck
672387	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	21/09/2021		Corrective Order	WO Completed	Pickup truck
672404	Caterpillar 226b Skid Steer L	MONTAJE DE CABINA	CORRECTIVO	21/09/2021	90013690	Corrective Order	WO Completed	Skid Steer
672445	Freightliner M2 106 Hydroseedi	Cambio de Tornillo de Chumacer	CAMBIO DE TORNILLO DE CHUMACERA	21/09/2021		Corrective Order	WO Completed	Truck
672453	Landcruiser DC	Cambio de Pertiga	CAMBIO DE PERTIGA	21/09/2021	2021WK38	Corrective Order	WO Completed	Pickup truck
672457	DOOSAND 1005	CORRECTIVO	CAMBIO BATERIA	21/09/2021	25071 hrs	Corrective Order	WO Completed	Light Tower
672461	ATR-0000-001 4+320 AGRICO	cambio de lamparas	LAMPARAS DAÑADAS	21/09/2021		Corrective Order	WO Completed	Tractor
672466	Hilux DC	cambio de extintor y kit de de	CAMBIO DE EXTINTOR Y KIT DE DERRAME	21/09/2021		Corrective Order	WO Completed	Pickup truck
672467	Landcruiser TC	cambio de cinta de claxon	CAMBIO DE CINTA DE CLAXON	21/09/2021		Corrective Order	WO Completed	Pickup truck
672468	Landcruiser DC	cambio de freewheel	CAMBIO DE FREEWHEEL	21/09/2021		Corrective Order	WO Completed	Pickup truck
672469	Landcruiser TC	revision de luces	REVISION DE LUCES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672470	Hilux DC	revision de luces	REVISION DE LUCES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672471	Landcruiser TC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672472	Landcruiser DC	revision de luces	REVISION DE LUCES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672473	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672474	Coaster	reparacion de centro spring	REPARACION DE CENTRO SPRING	21/09/2021		Corrective Order	WO Completed	Bus
672475	Landcruiser DC	revision de luces	REVISION DE LUCES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672476	Hilux DC	reparacion de cableado elec	REPARACION DE CABLEADO ELECTRICO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672477	Hilux DC	rescate	RESCATE	21/09/2021		Corrective Order	WO Completed	Pickup truck
672478	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672479	Coaster	resta tmf	RSCATE DE TMF	21/09/2021		Corrective Order	WO Completed	Bus
672480	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672481	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672482	LV205 RANGER FORD	mantenimiento correctivo	MANTENIMIENTO CORRECTICO	21/09/2021		Corrective Order	WO Completed	Light Vehicles

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
672483	Coaster	sietama a/c	SISTEMA A/C	21/09/2021		Corrective Order	WO Completed	Bus
672484	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672485	Hilux DC	cambio de muelles	CAMBIO DE MUELLES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672486	Landcruiser DC	cambio de extintor	CAMBIO DE EXTINTOR	21/09/2021		Corrective Order	WO Completed	Pickup truck
672487	Coaster	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Bus
672488	Coaster	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Bus
672489	Landcruiser DC	mantenimienot preventivo	MANTENIMIENOT PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672490	Landcruiser DC	Instalacion de GPS	INSTALACION DE GPS	21/09/2021		Corrective Order	WO Completed	Pickup truck
672491	Landcruiser DC	isntalacion de GPS	INSTALACION DE GPS	21/09/2021		Corrective Order	WO Completed	Pickup truck
672492	Landcruiser DC	revision de luces	REVISION DE LUCES	21/09/2021		Corrective Order	WO Completed	Pickup truck
672493	Landcruiser DC	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672495	Landcruiser TC	cambio de correa	CAMBIO DE CORREA	21/09/2021		Corrective Order	WO Completed	Pickup truck
672498	Grove RT9130E 120TON	cambio de empaques	CAMBIO DE EMPAQUES DEL MULTIPLE DE ESCAPE	21/09/2021	90014517 90014518	Corrective Order	WO Completed	Crane/Hoist
672500	Coaster	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	21/09/2021		Corrective Order	WO Completed	Bus
672501	Hilux DC	fuga de liquido de freno	FUGA DE LIQUIDO DE FRENO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672502	Landcruiser DC	ruido en tercera marcha	RUIDO EN TERCERA MARCHA	21/09/2021		Corrective Order	WO Completed	Pickup truck
672503	Ford Hilux D/C Light Vehicle	mantenimiento correctivo	MANTENIMIENTO CORRECTIVO	21/09/2021		Corrective Order	WO Completed	Pickup truck
672726	Ford 450	revision de radiador	FUGA DE COOLAM, CAMBIO DE AFTER COOLER Y MANGUERAS DE RADIADOR	22/09/2021		Corrective Order	WO Completed	Pickup truck
672734	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Bus
672735	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Bus
672736	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
672737	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
672738	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
672739	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
672740	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
672824	Freightliner M2 106 Hydroseedi	Cambio de Manguera	CAMBIO DE MANGUERA	22/09/2021		Corrective Order	WO Completed	Truck
672835	Terex RT670 64TON	cambio de Llavin	CAMBIO DE LLAVIN	22/09/2021		Corrective Order	WO Completed	Crane/Hoist
672840	Mobile equipment	Confección de Manguera para Ta	CONFECCIÓN DE MANGUERA PARA TALLER	22/09/2021		Corrective Order	WO Completed	Area
673097	Grove RT890 90TON	revison de niveles de aceite	REVISION DE NIVELES DE ACEITE	22/09/2021		Corrective Order	WO Completed	Crane/Hoist
673098	Hilux DC	Revisar sistema de arranque	REVISAR SISTEMA E ARRANQUE	22/09/2021		Corrective Order	WO Completed	Pickup truck
673111	SJS SJ6530	INSTALACIÓN DEL EJE DE RUEDAS	INSTALACIÓN DEL EJE DE RUEDAS	22/09/2021		Corrective Order	WO Completed	Compactor
673130	Case 110JX Tractor Cable Handl	Reparación de un neumático	REPARACIÓN DE UN NEUMÁTICO	22/09/2021		Corrective Order	WO Completed	Tractor
673160	Caterpillar 740b Ej	Revision de equipo	REVISION DE A/C	22/09/2021		Corrective Order	WO Completed	Articulated dump truck
673177	Coaster	reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Bus
673178	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Bus
673179	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
673181	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/09/2021		Corrective Order	WO Completed	Pickup truck
673182	Toyota Hilux	cambio sde bandas y estabiliza	CAMBIO DE BANDAS, CAMBIO DE BUJES DE BARRA Y ESTABILIZADORA	22/09/2021	80,142.00 km	Corrective Order	WO Completed	Pickup truck
673183	Toyota Hilux	cambio de baterias y terminale	CAMBIO DE BATERIAS Y TERMINALES	22/09/2021	88,599.00 km	Corrective Order	WO Completed	Pickup truck
673184	Coaster Bus	cambio de bandas y cilindros	CAMBIO DE BANDAS Y CILINDROS DE FRENOS	22/09/2021	74,952.00 kms	Corrective Order	WO Completed	Bus
673185	Toyota Hilux	reparacion de motor de arranqu	REPARACION DE MOTOR DE ARRANQUE	22/09/2021	82,259.00 km	Corrective Order	WO Completed	Pickup truck
673186	Coaster	Rep de display de a/c	REP DE DISPLAY DE A/C	22/09/2021	37,058.00 km	Corrective Order	WO Completed	Bus
673187	Hilux DC	reparacion de actuador	REPARACION DE ACTUADOR	22/09/2021	60,508.00 km	Corrective Order	WO Completed	Pickup truck
673188	Landcruiser DC	kit anti derrame, gato y extin	KIT ANTI DERRAME, GATO Y EXTINTOR	22/09/2021	49,438.00 km	Corrective Order	WO Completed	Pickup truck
673189	Hilux DC	instalacion de tiro	ISNTALACION DE TIRO Y BOLA DE CARGA	22/09/2021		Corrective Order	WO Completed	Pickup truck
673190	PB013 COASTER TOYOTA	reparacion de luces	REPARACION DE LUCES	22/09/2021	82,137.00 km	Corrective Order	WO Completed	Bus
673191	Coaster Bus	cambio de toma de comsbutible	CAMBIO DE TOMA DE COMBUSTIBLE	22/09/2021	77,765.00 km	Corrective Order	WO Completed	Bus
673192	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	22/09/2021	49,134.00 km	Corrective Order	WO Completed	Pickup truck
673315	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	23/09/2021	no hay acceso al equipo	PM Orders	WO Completed	Generator
673316	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	23/09/2021	EQUIPO FUERA DE SERVICIO SIN H	PM Orders	WO Completed	Generator
673317	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	23/09/2021	fuera de servicio	PM Orders	WO Completed	Generator
673347	Manitou Mht-X860 6t Telehand	revision de luces y avance	REVISION DE LUCES Y AVANCE	23/09/2021		Corrective Order	WO Completed	Telehender
673348	Hilux DC	reparacion de 1 llanta	REPARACION DE 1 LLANTA	23/09/2021		Corrective Order	WO Completed	Pickup truck
673349	GROVE GMK 2035E 35TON	INSTALACION DE VIDRIO	INSTALACION DE VIDRIO	23/09/2021		Corrective Order	WO Completed	Crane/Hoist
673351	Caterpillar 426f2 Backhoe	Balde no abre	BALDE NO ABRE	23/09/2021		Corrective Order	WO Completed	Backhoe
673510	New Holland Lm 1745	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	90013788	Corrective Order	WO Completed	Telehender
673556	Landcruiser DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	23/09/2021		Corrective Order	WO Completed	Pickup truck
673577	Caterpillar 12M	Vidrio frontal roto	VIDRIO FRONTAL ROTO	23/09/2021		Corrective Order	WO Completed	Grader
673578	Caterpillar 12M	En la pantalla indica alternad	EN LA PANTALLA INDICA ALTERNAD	23/09/2021		Corrective Order	WO Completed	Grader
673580	Freightliner 8170ME Water Truc	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Water truck
673600	Grove RT9130E 120TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	90013812	Corrective Order	WO Completed	Crane/Hoist
673607	Grove RT600E 50TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Crane/Hoist

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
673610	Freightliner CI 120	VALVULA DE FRENO /EXCESO GRASA	VALVULA DE FRENO /EXCESO GRASA	23/09/2021		Corrective Order	WO Completed	Mule truck
673645	Grove RT600E 50TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Crane/Hoist
673655	Caterpillar 336DL Excavator	engrase de puntos de articulac	ENGRASE DE PUNTOS DE ARTICULACION	23/09/2021		Corrective Order	WO Completed	Excavator
673659	Mack Trucks Gu813e	reparacion de llantas delanter	REPARACION DE LLANTAS DELANTERAS	23/09/2021		Corrective Order	WO Completed	Truck
673663	Caterpillar 426f2 Backhoe	reparacion de llanta	REPARACION DE LLANTA	23/09/2021		Corrective Order	WO Completed	Backhoe
673666	Freightliner Columbia CI112	reparacion de sist comunicacio	REPARACION DE SISTEMA DE COMUNICACION	23/09/2021		Corrective Order	WO Completed	Mule truck
673667	Coaster Bus	Cambio luz escolta	FALLA ELECTRICA	23/09/2021	250,518 KM	Corrective Order	WO Completed	Bus
673669	Manitou Mht-X1490 9t Telehand	reparacion fuga de aceite	REPARACION FIGA DE ACEITE	23/09/2021		Corrective Order	WO Completed	Telehender
673670	T30D LINDE	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	.
673671	Manitou Mht-X1490 9t Telehand	reparacion de fuga de aceite	REPARACION DE FUGA DE ACEITE	23/09/2021		Corrective Order	WO Completed	Telehender
673674	Freightliner Columbia CI112	reparacion de polleras	REPARACION DE POLLERAS	23/09/2021		Corrective Order	WO Completed	Mule truck
673676	T30D LINDE	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	90013819	Corrective Order	WO Completed	.
673677	Hilux DC	REVISAR NIVELES FLUIDOS	POR FUGA DE ACEITE	23/09/2021		Corrective Order	WO Completed	Pickup truck
673679	Freightliner CI 120	reparacion alarma activa	REPARACION DE LARMA ACTIVA EN TABLERO	23/09/2021		Corrective Order	WO Completed	Mule truck
673687	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	6210.8 Hrs	Corrective Order	WO Completed	Manlift
673690	Freightliner M2 106 Refrigerat	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021	90013820 90013821	Corrective Order	WO Completed	Refrigerator truck
673692	PRAMAC GSW110P 82 kVa	LLAMADA DE EMERGENCIA	EQUIPO SIN COMBUSTIBLE	23/09/2021	13855 horas	Corrective Order	WO Completed	Generator
673696	Manitou Mht-X860 6t Telehand	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Telehender
673723	Freightliner CI 120	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Mule truck
673743	Boom Truck Iveco Tector	PREVENTIVE MAINTENACE	PREVENTIVE MAINTENANCE	23/09/2021		Corrective Order	WO Completed	Boom truck
673753	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673755	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673758	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021	86325 kms	PM Orders	WO Completed	Pickup truck
673761	Landcruiser TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673763	Freightliner M2 106 Sucker Tru	SISTEMA DE FRENOS	LLANTA TRANCADA	23/09/2021		Corrective Order	WO Completed	Sucker truck
673765	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673766	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673772	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673778	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021	16,429.00 km	PM Orders	WO Completed	Pickup truck
673779	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673782	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673783	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673785	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673787	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673791	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	23/09/2021		PM Orders	WO Completed	Pickup truck
673792	Grove RT650E 45TON	FUGA HIDRAULICA	FUGA HIDRAULICA POR CILINDRO DE LEVANTE DELANTERO IZQUIERDO	23/09/2021		Corrective Order	WO Completed	Crane/Hoist
673806	Freightliner Columbia CI112	Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/09/2021		Corrective Order	WO Completed	Mule truck
673810	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	23/09/2021		Corrective Order	WO Completed	Pickup truck
673811	Hilux DC	Revision de equipo	REEMPLAZO DE LLANTA	23/09/2021		Corrective Order	WO Completed	Pickup truck
673812	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	23/09/2021		Corrective Order	WO Completed	Pickup truck
673813	Landcruiser DC	Revision de equipo	REEMPLAZO DE LLANTA	23/09/2021		Corrective Order	WO Completed	Pickup truck
673814	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/09/2021		Corrective Order	WO Completed	Pickup truck
673818	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/09/2021		Corrective Order	WO Completed	Pickup truck
673833	Coaster Bus	cambio de escolta	CAMBIO DE ESCOLTA	24/09/2021	250,018.00 km	Corrective Order	WO Completed	Bus
673834	Coaster	reparacion electrica de ac	REPARACION ELECTRICA AC	24/09/2021		Corrective Order	WO Completed	Bus
673835	Landcruiser DC	reparacion de base de amortigu	REPARACION DE BASE DE AMORTIGU	24/09/2021		Corrective Order	WO Completed	Pickup truck
673836	Landcruiser DC	revision de direc y alternador	REVISION DE DIREC Y ALTERNADOR	24/09/2021		Corrective Order	WO Completed	Pickup truck
673837	Hilux DC	rev de embrague	REV DE EMBRAGUE	24/09/2021		Corrective Order	WO Completed	Pickup truck
673838	Hilux DC	instalacion de tiro	INSTALACION DE TIRO	24/09/2021		Corrective Order	WO Completed	Pickup truck
673839	Toyota Hilux	reparacion de electrica ac	REPARACION DE ELECTRICA AC	24/09/2021		Corrective Order	WO Completed	Pickup truck
673954	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	24/09/2021		Corrective Order	WO Completed	Pickup truck
673955	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	24/09/2021		Corrective Order	WO Completed	Pickup truck
673956	Landcruiser TC	Revision de equipo	REVISION DE EQUIPO	24/09/2021		Corrective Order	WO Completed	Pickup truck
673977	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	24/09/2021		Corrective Order	WO Completed	Pickup truck
673992	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/09/2021		Corrective Order	WO Completed	Pickup truck
673993	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/09/2021		Corrective Order	WO Completed	Pickup truck
673994	Grove GMK4100L 100TON	Revision de equipo	REVISION DE EQUIPO - REVISION DE ESCOLTA	24/09/2021		Corrective Order	WO Completed	Crane/Hoist
673995	Landcruiser TC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/09/2021		Corrective Order	WO Completed	Pickup truck
673996	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/09/2021		Corrective Order	WO Completed	Pickup truck
673997	Landcruiser TC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	24/09/2021		Corrective Order	WO Completed	Pickup truck
673998	Mobile equipment	suministro	SUMINISTRO	24/09/2021		Corrective Order	WO Completed	Area
674000	Caterpillar 226b Skid Steer L	falla electrica	FALLA ELECTRICA	24/09/2021		Corrective Order	WO Completed	Skid Steer
674001	Caterpillar 14M Motorgrader	reparacion	REPARACION	24/09/2021		Corrective Order	WO Completed	Grader
674004	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	EQUIPO APAGADO POR DISPLAY INACTIVO	24/09/2021	25969 hrs	Corrective Order	WO Completed	Generator
674005	Atlas Copco GESAN QIS 45 47KVA	LLAMADA DE EMERGENCIA	EQUIPO APAGADO SIN COMBUSTIBLE	24/09/2021	5670 hrs	Corrective Order	WO Completed	Generator
674006	Mobile equipment	reparacion llanta	REPARACION DE LLANTA DE TELEHANDER JCB ALQUILADO	24/09/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
674008	Caterpillar 426f2 Backhoe	Reparacion de llanta	REPARACION DE LLANTA	24/09/2021		Corrective Order	WO Completed	Backhoe
674009	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	24/09/2021		Corrective Order	WO Completed	Pickup truck
674018	Caterpillar 12M	Fuga de aceite	FUGA DE ACEITE	24/09/2021		Corrective Order	WO Completed	Grader
674043	Power Curbers 5700-C	Acelerador automático dañado	ACELERADOR AUTOMÁTICO DAÑADO	24/09/2021		Corrective Order	WO Completed	Kerb Machine
674152	Caterpillar D8T Dozer	CAMBIO DE BOMBA DE TRANSMISION	EQUIPO IASA	24/09/2021		Corrective Order	WO Completed	Dozer
674207	Cargador 966H Wheel Loader	FABRICACION DE MANGUERAS	EQUIPO IASA	24/09/2021		Corrective Order	WO Completed	Loader
674224	Caterpillar 12M	MANTENIMIENTO MENSUAL AFEX	MANTENIMIENTO MENSUAL AFEX	24/09/2021		Corrective Order	WO Completed	Grader
674261	Landcruiser DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	24/09/2021		Corrective Order	WO Completed	Pickup truck
674273	Intraax 53121 Hendrickso	cambio de bolsa	CAMBIO DE BOLSA	24/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
674276	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	24/09/2021		Corrective Order	WO Completed	Pickup truck
674296	Caterpillar 226b Skid Steer L	corregir fuga de aceite	EVISAR NIVELES DE ACEITRE	24/09/2021		Corrective Order	WO Completed	Skid Steer
674297	Landcruiser TC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	24/09/2021		Corrective Order	WO Completed	Pickup truck
674298	JLG 450 AJ Manlift	revisar arranque	REVISAR ARRANQUE SISTEMA DE INYECCION	24/09/2021		Corrective Order	WO Completed	Manlift
674326	Caterpillar 14M Motorgrader	Se le estan saliendo pasadores	SE LE ESTAN SALIENDO PASADORES	24/09/2021		Corrective Order	WO Completed	Grader
674364	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	25/09/2021		Corrective Order	WO Completed	Pickup truck
674365	Hilux DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	25/09/2021		Corrective Order	WO Completed	Pickup truck
674367	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	25/09/2021		Corrective Order	WO Completed	Bus
674368	Gmc Boom Truck	Revision de equipo	INSTALACION DE LAMPARA	25/09/2021		Corrective Order	WO Completed	Boom truck
674369	Hilux DC	Revision de direccion y freno	REVISION DE DIRECCION Y FRENO	25/09/2021		Corrective Order	WO Completed	Pickup truck
674370	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	25/09/2021		Corrective Order	WO Completed	Pickup truck
674371	WT013 H7 CISTERNA SINOTRUK	Revision de equipo	REVISION DE LUCES DEL EQUIPO	25/09/2021		Corrective Order	WO Completed	Water truck
674372	Landcruiser DC	revision de luces	REVISION DE LUCES	25/09/2021		Corrective Order	WO Completed	Pickup truck
674373	Hilux DC	revision de luces	REVISION DE LUCES	25/09/2021		Corrective Order	WO Completed	Pickup truck
674374	Landcruiser DC	reparacion de transmision	REPARACION DE TRANSMISION	25/09/2021		Corrective Order	WO Completed	Pickup truck
674375	Hilux DC	revision de luces	REVISION DE LUCES	25/09/2021		Corrective Order	WO Completed	Pickup truck
674509	SJS SJ6530	Revision de equipo	REVISION DE EQUIPO	25/09/2021		Corrective Order	WO Completed	Compactor
674510	Caterpillar 226b Skid Steer L	Revision de equipo	EQUIPO NO ARRANCA	25/09/2021		Corrective Order	WO Completed	Skid Steer
674514	GROVE RT9130E 120TON	arranque de equipo	ARRANQUE DE EQUIPO	25/09/2021		Corrective Order	WO Completed	Crane/Hoist
674547	Freightliner Cl 120	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	25/09/2021		Corrective Order	WO Completed	Mule truck
674561	Hilux DC	herramientas cambio de llanta	HERRAMIENTAS PARA CAMBIO DE LLANTAS	25/09/2021		Corrective Order	WO Completed	Pickup truck
674575	Mercedes Tipper Truck	Movimiento de Equipo	MOVIMIENTO DE EQUIPO	25/09/2021	Soporte W 38	Corrective Order	WO Completed	Tipper
674576	MAN 33.360 V20	HIZAJE DE EQUIPO	HIZAJE Y DESCARGA DE EQUIPO	25/09/2021	Soporte W38	Corrective Order	WO Completed	Boom truck
674581	Caterpillar 307E Miniexcavator	HIZAJE DE EQUIPO	HIZAJE Y DESCARGA	25/09/2021	Soporte W38	Corrective Order	WO Completed	Excavator
674584	Bomag BW219DH-4	IZAJE DE TAMBOR	IZAJE DE TAMBOR	25/09/2021	Soporte W38	Corrective Order	WO Completed	Compactor
674588	Boom Truck Iveco Tector	HIZAJE DE EQUIPO	HIZAJE DE EQUIPO Y DESCRAGA	25/09/2021	Soporte W38	Corrective Order	WO Completed	Boom truck
674593	Caterpillar 740b Ej	REEM/ SENSOR NIVEL COMBUSTIB	NO FUNCIONA	25/09/2021		Corrective Order	WO Completed	Articulated dump truck
674606	Caterpillar CS533E Compactor	Perdida de fuerza	PERDIDA DE FUERZA	25/09/2021		Corrective Order	WO Completed	Compactor
674620	Mobile equipment	oxigeno para taller	OXIGENO PARA TALLER	25/09/2021		Corrective Order	WO Completed	Area
674626	Hyster H700 Forklift	PROBLEMAS DE ARRANQUE	PROBLEMAS DE ARRANQUE	25/09/2021	AUTO CLOSED	Corrective Order	WO Completed	Forklift
674710	JLG 800 AJ Manlift	cambio de mangueras hidraulica	FUGA DE ACEITE HIDRAULICO	25/09/2021		Corrective Order	WO Completed	Manlift
674712	Caterpillar 12M	Alarma encendida	EN LA PANTALLA INDICA ALTERNAD	25/09/2021		Corrective Order	WO Completed	Grader
674713	Caterpillar 740B EJ ADT	cambio de llantas delanteras	CAMBIO DE LLANTAS DELANTERAS	25/09/2021		Corrective Order	WO Completed	Articulated dump truck
674799	Terex RT670 64TON	confección de manguera	CONFECCIÓN DE MANGUERA	25/09/2021	AUTO CLOSED	Corrective Order	WO Completed	Crane/Hoist
674812	Freightliner Columbia Cl112	ajuste de tornillo de maso	AJUSTE TORNILLO MASO SPING	25/09/2021		Corrective Order	WO Completed	Mule truck
674818	JLG 1250 AJP Manlift	reparacion de sistema de arran	REPARRA SISTEMA DE ARANQUE, PEDAL DANADO	25/09/2021		Corrective Order	WO Completed	Manlift
674822	JLG 1250 AJP Manlift	reparar sistema e arranque	REPARAR SISTEMA DE ARANQUE	25/09/2021		Corrective Order	WO Completed	Manlift
674844	Toyota Land Cruiser	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	25/09/2021		Corrective Order	WO Completed	Pickup truck
674859	Internation 4400 SBA 6x4 Boom	Cambio de filtro	CAMBIO DE FILTRO	25/09/2021		Corrective Order	WO Completed	Boom truck
674913	Gallegos Flatbed Trailer	LLANTA BAJA	LLANTA BAJA	25/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
674915	Trucks	LLANTA BAJA	LLANTA BAJA	25/09/2021		Corrective Order	WO Completed	Area
674923	Freightliner Columbia Cl112	LUZ CHICA QUEMADA	LUZ CHICA QUEMADA	25/09/2021		Corrective Order	WO Completed	Mule truck
674936	PRAMAC GSW560V 407 kVa	MANTENIMIENTO CORRECTIVO	CALIBRACIÓN DE INYECTORES	25/09/2021	18780 HORAS	Corrective Order	WO Completed	Generator
674948	Gallegos Lime Tank	GOLPE GUARDAFANGO	GOLPE GUARDAFANGO	25/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
674964	Coaster Bus	revision de luces	REVISION DE LUCES	25/09/2021		Corrective Order	WO Completed	Bus
674965	Coaster Bus	revision de luces	REVISION DE LUCES	25/09/2021		Corrective Order	WO Completed	Bus
674966	Coaster	cambio de bateria	CAMBIO DE BATERIA	25/09/2021		Corrective Order	WO Completed	Bus
674968	LB002 725 CAT	Revision de equipo	REEMPLAZO DE PASTILLAS DE FRENO DE ESTACIONAMIENTO	25/09/2021		Corrective Order	WO Completed	Truck
674969	Caterpillar D110 E2 100KVA	CORRECTIVO	CAMBIO DE BATERIA	25/09/2021	14444 hrs	Corrective Order	WO Completed	Generator
674971	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	25/09/2021		Corrective Order	WO Completed	Pickup truck
674973	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	25/09/2021		Corrective Order	WO Completed	Bus
674978	Grove RT880E 75TON	cambios de swicht	CAMBIOS DE MASTER SWICHT Y DE ARRANQUE	25/09/2021		Corrective Order	WO Completed	Crane/Hoist
674979	WT015 H7 CISTERNA SINOTRUK	Revision de equipo	REVISION DE FUGA DE DIESEL	25/09/2021	65,451 Kms	Corrective Order	WO Completed	Water truck
675104	Grove RT880E 75TON	Revision de equipo	REVISION DE FALLA	26/09/2021		Corrective Order	WO Completed	Crane/Hoist
675105	Internation 4400 SBA 6x4 Boom	Revision de equipo	LEVANTAMIENTO DE FILTROS	26/09/2021		Corrective Order	WO Completed	Boom truck
675107	Caterpillar 226b Skid Steer L	reparacion de llanta	LLANTA FLAT	26/09/2021		Corrective Order	WO Completed	Skid Steer
675109	SJS SJ6530	Reparacion de acople	PIN DE ACOPLER PARTIDO	26/09/2021		Corrective Order	WO Completed	Compactor
675110	Caterpillar 12M	Revision de equipo	INSTALACION DE VIDRIOS FRONTALES	26/09/2021	90014822 90014823	Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
675111	Freightliner CI 120	Revision de equipo	REPARACION DE HARNESS	26/09/2021		Corrective Order	WO Completed	Mule truck
675114	SJS SJ6530	reparacion de acople	REPARACION DE ACOPL	26/09/2021	Oportunidad	Corrective Order	WO Completed	Compactor
675161	Freightliner Columbia CI112	LLANTAS POR CAMBIO	LLANTAS POR CAMBIO	26/09/2021		Corrective Order	WO Completed	Mule truck
675172	ETNYRE QUAD	Compuertas del rodillo no abre	COMPUERTAS DEL RODILLO NO ABRE	26/09/2021		Corrective Order	WO Completed	Chip Spreader
675209	Caterpillar 12M	CORREGIR FUGA X BOMBA HEUI	EQUIPO IASA	26/09/2021	90014085 90014824	Corrective Order	WO Completed	Grader
675214	Broce Broom RJT 350	No enciende	NO ENCIENDE	26/09/2021		Corrective Order	WO Completed	Scrubber / Sweeper
675277	Freightliner CI 120	MECHANICAL INSPECTION	INSPECTION	26/09/2021		Corrective Order	WO Completed	Mule truck
675278	Freightliner CI 120	MECHANICAL INSPECTION	INSPECTION	26/09/2021		Corrective Order	WO Completed	Mule truck
675279	Freightliner CI 120	MECHANICAL INSPECTION	INSPECTION	26/09/2021		Corrective Order	WO Completed	Mule truck
675301	Freightliner Columbia CI112	LUZ QUEMADA	LUZ QUEMADA	26/09/2021		Corrective Order	WO Completed	Mule truck
675303	Freightliner 8170ME Water Truc	Aire Acondicionado	AIRE ACONDICIONADO	26/09/2021		Corrective Order	WO Completed	Water truck
675304	Intraax 53121 Hendrickso	BOLSA ROTA / TUERCA	BOLSA ROTA / TUERCA	26/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
675316	SJS SJ6530	INSTALACION DE HITCH	INSTALACION DE HITCH	26/09/2021		Corrective Order	WO Completed	Compactor
675320	SJS SJ6530	CONFECCIÓN DE HITCH	CONFECCIÓN DE HICTH	26/09/2021		Corrective Order	WO Completed	Compactor
675323	Gallegos Flatbed Trailer	AJUSTE DE FRENOS	AJUSTE DE FRENOS	26/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
675325	Freightliner CI 120	SEGUROS NO CIERRAN	SEGUROS NO CIERRAN	26/09/2021	90015885	Corrective Order	WO Completed	Mule truck
675339	FG WILSON P88-3 80 kVa	PM1 FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	25980 horas	PM Orders	WO Completed	Generator
675340	Caterpillar DE110E 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	22172 horas	PM Orders	WO Completed	Generator
675341	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	18513 horas	PM Orders	WO Completed	Generator
675342	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	14741 horas	PM Orders	WO Completed	Generator
675343	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	18210 horas	PM Orders	WO Completed	Generator
675344	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	14221 horas	PM Orders	WO Completed	Generator
675345	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	15055 horas	PM Orders	WO Completed	Generator
675346	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	6916 hrs	PM Orders	WO Completed	Generator
675349	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	8753 horas	PM Orders	WO Completed	Generator
675351	PRAMAC GSW65 48 kVa	PM1 PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	25601 horas	PM Orders	WO Completed	Generator
675352	SDMO T11UM 10KVA	PM1 SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	18134 horas	PM Orders	WO Completed	Generator
675353	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	25437 hrs	PM Orders	WO Completed	Generator
675355	Olympian GEP18-6 18KVA	PM1 OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	29560 horas	PM Orders	WO Completed	Generator
675357	SDMO T16 16KVA	PM1 SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	24662 hrs	PM Orders	WO Completed	Generator
675358	Pramac GSW25P 17KVA	PM1 PRA GSW25 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	4946 hrs	PM Orders	WO Completed	Generator
675359	Expert Power PN45 10KVA	PM1 EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	8659 HORAS	PM Orders	WO Completed	Generator
675364	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	25417 horas	PM Orders	WO Completed	Light Tower
675366	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	2530 hrs	PM Orders	WO Completed	Light Tower
675367	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	865 hrs	PM Orders	WO Completed	Light Tower
675368	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	731 horas	PM Orders	WO Completed	Light Tower
675369	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	800 horas	PM Orders	WO Completed	Light Tower
675395	Caterpillar 14H Motorgrader	FABRICACION DE MANGUERAS	EQUIPO IASA	26/09/2021		Corrective Order	WO Completed	Grader
675409	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	11056 horas	Corrective Order	WO Completed	Generator
675419	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	26/09/2021	5000 horas	Corrective Order	WO Completed	Light Tower
675431	Caterpillar 740b Ej	completar niveles de aceite	COMPLETAR NIVELES DE ACEITE	26/09/2021		Corrective Order	WO Completed	Articulated dump truck
675443	Caterpillar 12M Motorgrader	Alta Temperatura de refrigeran	ALTA TEMPERATURA DE REFRIGERAN	26/09/2021		Corrective Order	WO Completed	Grader
675452	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	65.5 horas	PM Orders	WO Completed	Generator
675453	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	8258 horas	PM Orders	WO Completed	Generator
675454	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	10422 horas	PM Orders	WO Completed	Generator
675455	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	16809 horas	PM Orders	WO Completed	Generator
675456	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	839 horas	PM Orders	WO Completed	Generator
675457	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	9774 horas	PM Orders	WO Completed	Generator
675458	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	16485 horas	PM Orders	WO Completed	Generator
675460	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	16084 horas	PM Orders	WO Completed	Generator
675461	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	8644 horas	PM Orders	WO Completed	Generator
675462	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	3633 horas	PM Orders	WO Completed	Generator
675463	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	581 horas	PM Orders	WO Completed	Generator
675464	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	359 horas	PM Orders	WO Completed	Generator
675465	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021	11052 horas	PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
675466	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021 160 horas		PM Orders	WO Completed	Generator
675467	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021 18056 hrs		PM Orders	WO Completed	Generator
675468	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021 25133 hrs		PM Orders	WO Completed	Generator
675469	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	26/09/2021 261 hrs		PM Orders	WO Completed	Generator
675497	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	26/09/2021 31772 horas		Corrective Order	WO Completed	Generator
675523	LB002 725 CAT	Revision de equipo	REVISION DE TRANSMISION - CODIGOS DE FALLA	26/09/2021 90014584		Corrective Order	WO Completed	Truck
675558	Hilux DC	cambio de amortiguadores	CAMBIO DE AMORTIGUADORES	27/09/2021		Corrective Order	WO Completed	Pickup truck
675559	Landcruiser TC	rev de frenos y direccion	REV DE FRENOS Y DIRECCION	27/09/2021		Corrective Order	WO Completed	Pickup truck
675560	Coaster	cambio de tanque de combus	CAMBIO DE TANQUE DE COMBUSTIBLE	27/09/2021		Corrective Order	WO Completed	Bus
675561	Landcruiser DC	rev de cable de freno	REV DE CABLE DE FRENO	27/09/2021		Corrective Order	WO Completed	Pickup truck
675706	Mobile equipment	Reparacion de llanta	LLANTA FLAT TELEHANDER JCB Y RETRO CAL ALQUILADAS PLANT SITE	27/09/2021		Corrective Order	WO Completed	Area
675709	SDMO J60U 60KVA	CORRECTIVO	REPARACION DE PUERTA Y VISAGRAS DE PANEL DE CONTROL	27/09/2021 261 hrs		Corrective Order	WO Completed	Generator
675712	Landcruiser DC	Reemplazo de llantas	REPARACION DE LLANTA	27/09/2021		Corrective Order	WO Completed	Pickup truck
675713	Freightliner Cl 120	Revision de equipo	AJUSTE DE FRENOS	27/09/2021		Corrective Order	WO Completed	Mule truck
675719	Freightliner M2 106 Hydroseedi	MAQUINADO DE EJE	MAQUINADO DE EJE	27/09/2021 Emergency		Corrective Order	WO Completed	Truck
675786	New Holland Lm 1745	Cambio de mangueras	CAMBIO DE MANGUERAS	27/09/2021		Corrective Order	WO Completed	Telehender
675809	Hilux DC	CAMBIO DE 4 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	27/09/2021		Corrective Order	WO Completed	Pickup truck
675810	Landcruiser DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	27/09/2021		Corrective Order	WO Completed	Pickup truck
675812	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	27/09/2021		Corrective Order	WO Completed	Pickup truck
675823	Caterpillar 14H Motorgrader	CONFECCIÓN DE MANGUERAS	CONFECCIÓN DE MANGUERA	27/09/2021		Corrective Order	WO Completed	Grader
675837	Trucks	LLANTA POR REPARACION	LLANTA POR REPARACION	27/09/2021		Corrective Order	WO Completed	Area
675916	Caterpillar 14H Motorgrader	Cilindro de desplazamiento	CILINDRO DE DESPLAZAMIENTO DE LA HOJA	27/09/2021		Corrective Order	WO Completed	Grader
675921	Internation F2674	Correa de motor rota	CORREA DE MOTOR ROTA	27/09/2021		Corrective Order	WO Completed	Boom truck
675924	Freightliner M2 106 Hydroseedi	RECTIFICACIÓN DEL EJE	RECTIFICACIÓN DEL EJE	27/09/2021 Emergency		Corrective Order	WO Completed	Truck
675945	JLG 1250 AJP Manlift	Reparacion de Manlift	REPARACION DE MANLIFT	27/09/2021		Corrective Order	WO Completed	Manlift
676028	Toyota Land Cruiser	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	27/09/2021		Corrective Order	WO Completed	Pickup truck
676088	Freightliner Columbia Cl112	ajuste engrase de frenos	AJUSTE ENGRASE DE FRENOS	27/09/2021		Corrective Order	WO Completed	Mule truck
676090	Freightliner Columbia Cl112	reparacion de cableado tablero	REPARACION DE CABLEADO DE TABLERO	27/09/2021		Corrective Order	WO Completed	Mule truck
676207	Ferrari F478	TIRE INFLATOR SUPPLY	SUPPLY	27/09/2021 90014349		Corrective Order	WO Completed	Reach Stacker
676211	Intraax 53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	27/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
676219	Caterpillar 307E Miniexcavator	REPARACIÓN DEL SWIVEL	REPARACIÓN DEL SWIVEL	27/09/2021		Corrective Order	WO Completed	Excavator
676228	Caterpillar 226b Skid Steer L	CAMBIO DE ACOPLAMIENTO RAPIDO	EQUIPO IASA	27/09/2021 90015145 90015155		Corrective Order	WO Completed	Skid Steer
676262	Coaster	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	27/09/2021		Corrective Order	WO Completed	Bus
676263	Landcruiser DC	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	27/09/2021		Corrective Order	WO Completed	Pickup truck
676264	Landcruiser DC	Revision de Frenos	REVISION DE FRENOS	27/09/2021		Corrective Order	WO Completed	Pickup truck
676269	Ford 450	Revision de sistema de refrige	REVISION DE SISTEMA DE REFRIGERACION	27/09/2021		Corrective Order	WO Completed	Pickup truck
676270	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	27/09/2021		Corrective Order	WO Completed	Bus
676619	Caterpillar D110 E2 100KVA	LLAMADA DE EMERGENCIA	CORREXION DE FASES INVERTIDAS	28/09/2021 14477 hrs		Corrective Order	WO Completed	Generator
676632	Freightliner Cl 120	Revision de equipo	REEMPLAZO DE ESPEJO RETROVISOR	28/09/2021 90014355		Corrective Order	WO Completed	Mule truck
676639	Mobile equipment	camillas para mecanicos	CAMILLAS PARA MECANICOS	28/09/2021 90014357		Corrective Order	WO Completed	Area
676646	Intraax 53121 Hendrickso	reparacion de 1 llanta	LLANTA FLAT	28/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
676650	Internation 4400 SBA 6x4 Boom	Revision de equipo	REVISION DE EQUIPO - REVISION DE TRANSMISION	28/09/2021		Corrective Order	WO Completed	Boom truck
676800	Freightliner 8170ME Water Truc	Cambio de Mangueras	FABRICACIÓN DE MANGUERASD	28/09/2021		Corrective Order	WO Completed	Water truck
676806	Ford Ranger	Llanta delantera izq Flat	LLANTA DELANTERA IZQ FLAT	28/09/2021		Corrective Order	WO Completed	Pickup truck
676852	Freightliner 8170ME Water Truc	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	28/09/2021		Corrective Order	WO Completed	Water truck
676899	Freightliner Columbia Cl112	LLANTA FLAT	LLANTA FLAT	28/09/2021		Corrective Order	WO Completed	Mule truck
676900	Grove RT600E 50TON	Cambio de manguera	CAMBIO DE MANGUERA	28/09/2021		Corrective Order	WO Completed	Crane/Hoist
676910	New Holland Lm 1745	Cilindro en reparacion	DESMONTE E INSTALACION DE CILINDRO DEL ESTABILIZADOR	28/09/2021		Corrective Order	WO Completed	Telehender
676914	New Holland Lm 1745	Instalacion de cilindro estabi	INSTALACION DE CILINDRO ESTABILIZADOR	28/09/2021		Corrective Order	WO Completed	Telehender
676948	TTP-0000-102	fabricacion de mangueras	FABRICACION DE MANGUERAS	28/09/2021		Corrective Order	WO Completed	Excavator
676958	Freightliner Cl 120	MANGUERA ROTA	MANGUERA ROTA	28/09/2021		Corrective Order	WO Completed	Mule truck
677014	Cargador 966H Wheel Loader	Revision de equipo	NO ARRANCA	28/09/2021 24,924 Hrs		Corrective Order	WO Completed	Loader
677019	Caterpillar 14M Motorgrader	Revision de equipo	REVISION DE FRENO DE ESTACIONAMIENTO	28/09/2021 90014507		Corrective Order	WO Completed	Grader
677027	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	28/09/2021		Corrective Order	WO Completed	Pickup truck
677029	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	28/09/2021		Corrective Order	WO Completed	Pickup truck
677034	Landcruiser TC	Revision de diferencial	REVISION DE DIFERENCIAL	29/09/2021		Corrective Order	WO Completed	Pickup truck
677035	Hilux DC	cambio de luces y plot	CAMBIO DE LUCES Y PLOT	29/09/2021		Corrective Order	WO Completed	Pickup truck
677259	Landcruiser TC	cambio de 2 llantas	CAMBIOS DE 2 LLANTAS	29/09/2021		Corrective Order	WO Completed	Pickup truck
677261	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	29/09/2021		Corrective Order	WO Completed	Pickup truck
677274	Manitou Mht-X860 6t Telehand	revision de falla en avance	REVISION DE FALLA EN AVANCE	29/09/2021		Corrective Order	WO Completed	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
677308	Mobile equipment	Mangueras y Acoples para taller	MANGUERAS Y ACOPLES PARA TALLER	29/09/2021		Corrective Order	WO Completed	Area
677415	Mobile equipment	FIRST AID KITS	SAFETY	29/09/2021		Corrective Order	WO Completed	Area
677419	Freightliner Columbia C112	LLANTA FLAT	LLANTA FLAT	29/09/2021		Corrective Order	WO Completed	Mule truck
677421	Gallegos 28M3 Lime Tank	LLANTA BAJA	LLANTA BAJA	29/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
677474	Hyster E70xn 3t Forklift (E)	Montacarga bloqueada	MONTACARGA BLOQUEADA	29/09/2021		Corrective Order	WO Completed	Forklift
677538	Landcruiser DC	CAMBIO 4 LLANTAS	CORRECTIVO	29/09/2021		Corrective Order	WO Completed	Pickup truck
677558	Unimog Service Truck	PROBLEMAS DE FRENO	PROBLEMAS DE FRENO	29/09/2021		Corrective Order	WO Completed	Truck
677612	Ford F550	revision de frenos y desmonte	REVISION DE FRNOS Y DESMONTE DE LLANTAS	29/09/2021		Corrective Order	WO Completed	Pickup truck
677753	Terex RT670 64TON	codigo de falla entablero	CODIGO DE FALLA EN TABLERO	29/09/2021		Corrective Order	WO Completed	Crane/Hoist
677754	Grove GMK4100L 100TON	CODIGO DE FALLA EN EL TABLERO	CODIGO DE FALLA EN EL TABLERO	29/09/2021		Corrective Order	WO Completed	Crane/Hoist
677756	Freightliner M2 106 Sucker Tru	CORTO EN SISTEMA DE LUCES Y FU	CORTO EN SISTEMA DE LUCES Y FUGA DE AIRE POR EL SELECTOR DE ALTA /BAJA	29/09/2021		Corrective Order	WO Completed	Sucker truck
677771	Landcruiser TC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	29/09/2021		Corrective Order	WO Completed	Pickup truck
677773	Hilux DC	cambio de alarma	CAMBIO DE ALARMA	29/09/2021		Corrective Order	WO Completed	Pickup truck
677774	Landcruiser DC	cambio de porta banda	CAMBIO DE PORTA BANDA	29/09/2021		Corrective Order	WO Completed	Pickup truck
677775	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	29/09/2021		Corrective Order	WO Completed	Pickup truck
677776	Landcruiser DC	cambio de boya de combustible	CAMBIO DE BOYA DE COMBUSTIBLE	29/09/2021		Corrective Order	WO Completed	Pickup truck
677778	Caterpillar CS74 Compactor	Revision de equipo	FUGA DE ACEITE HIDRAULICO	29/09/2021		Corrective Order	WO Completed	Compactor
677848	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	30/09/2021 10324 horas		PM Orders	WO Completed	Generator
677849	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	30/09/2021 12668 hoas		PM Orders	WO Completed	Generator
677850	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	30/09/2021 18837 horas		PM Orders	WO Completed	Generator
677864	Freightliner M112 Truck Tip	Revision de equipo	INSPECCION MECANICA	30/09/2021		Corrective Order	WO Completed	Tipper
677872	WT015 H7 CISTERNA SINOTRUK	Revision de equipo	REVISION DE LUCES DEL EQUIPO	30/09/2021 7545.8 Kms		Corrective Order	WO Completed	Water truck
677874	Landcruiser TC	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	30/09/2021		Corrective Order	WO Completed	Pickup truck
677875	Hilux DC	Carga de gas	REVISION DE SISTEMA DE AC	30/09/2021		Corrective Order	WO Completed	Pickup truck
677876	Freightliner M2 106 Hydroseedi	cambios de retenedoras	FUGA POR RETENEDORA DEL TANQUE	30/09/2021		Corrective Order	WO Completed	Truck
677891	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	30/09/2021 18836 hors		Corrective Order	WO Completed	Generator
677893	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	30/09/2021 15040 horas		Corrective Order	WO Completed	Generator
677996	Freightliner CI 120	DEVOLUCION FILTROS WO 669295	DEVOLUCION	30/09/2021		Corrective Order	WO Completed	Mule truck
678030	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO SIN COMBUSTIBLE	30/09/2021 28120 HORAS		Corrective Order	WO Completed	Generator
678034	Ford Ranger	CAMBIO 2 LLANTAS	CORRECTIVO	30/09/2021		Corrective Order	WO Completed	Pickup truck
678052	Caterpillar 740B	C/ CARTER DEL MOTOR	CARTER DEL MOTOR ROTO	30/09/2021		Corrective Order	WO Completed	Articulated dump truck
678053	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE BATERIA	30/09/2021 26124 HORAS		Corrective Order	WO Completed	Generator
678054	Caterpillar 740B	C/ MANG HYD ENFRIAMIENTO FRENO	MANGUERA ROTA	30/09/2021		Corrective Order	WO Completed	Articulated dump truck
678085	Caterpillar 740B EJ ADT	740B-L4F-MAINTENANCE 500 HRS	740B-L4F-MAINTENANCE 500 HRS	30/09/2021 PM5		PM proposal JDE	WO Completed	Articulated dump truck
678115	Gallegos Flatbed Trailer	engrase general	ENGRASE GEMNERAL	30/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
678119	Gallegos Flatbed Trailer	engrase general	ENGRASE GENERAL	30/09/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
678120	Caterpillar 226b Skid Steer L	engrase general	ENGRASE GENERAL	30/09/2021		Corrective Order	WO Completed	Skid Steer
678121	Caterpillar 226b Skid Steer L	engrase general	ENGRASE GENRAL	30/09/2021		Corrective Order	WO Completed	Skid Steer
678124	Hyster H70ft 3t Forklift (M)	llanta flat	LLANTADS FLAT	30/09/2021		Corrective Order	WO Completed	Forklift
678139	Atlas Copco GESAN QIS 45 47KVA	LLAMADA DE EMERGENCIA	EQUIPO PARADO	30/09/2021 5671 horas		Corrective Order	WO Completed	Generator
678142	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	30/09/2021		Corrective Order	WO Completed	Pickup truck
678143	Coaster	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	30/09/2021		Corrective Order	WO Completed	Bus
678144	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	30/09/2021		Corrective Order	WO Completed	Pickup truck
678168	JLG 800 AJ Manlift	EQUIPO SIN DIESEL	EQUIPO SE QUEDO SIN DIESEL	30/09/2021		Corrective Order	WO Completed	Manlift
678169	Freightliner M2 106 Hydroseedi	CADENA TRANCADA	CADENA TRANCADA	30/09/2021		Corrective Order	WO Completed	Truck
678180	General Mobile MLT3060K	CORRECTIVO	CAMBIO DE BATERIA	30/09/2021 5057 hrs		Corrective Order	WO Completed	Light Tower
678227	Landcruiser TC	CAMBIO ALARMA RETROCESO	REVISION ELECTRICA DEL EQUIPO	30/09/2021		Corrective Order	WO Completed	Pickup truck
678228	Landcruiser TC	REPARAR AMORTIGUADOR DELANTERO	MANTENIMIENTO CORRECTIVO	30/09/2021		Corrective Order	WO Completed	Pickup truck
678230	Freightliner M2 106 Sucker Tru	reparacion de cableado de luce	REPARACION DE CABLEADO DE LUCES	30/09/2021		Corrective Order	WO Completed	Sucker truck
678366	PRAMAC GSW65 48 kVa	LLAMADA DE EMERGENCIA	LIMPIEZA DE FUGA DE ACEITE	01/10/2021 25367 hrs		Corrective Order	WO Completed	Generator
678371	Caterpillar 14M Motorgrader	cambio de vidrio de puerta	CAMBIO DE VIDRIO DE PUERTA	01/10/2021 90014596		Corrective Order	WO Completed	Grader
678372	SJS SJ6530	armado de eje de rueda	ARMADO DE EJE DE RUEDA	01/10/2021		Corrective Order	WO Completed	Compactor
678373	Caterpillar 14M Motorgrader	Vidrio de la puerta roto	VIDRIO DE LA PUERTA ROTA	01/10/2021 90014597 90015123		Corrective Order	WO Completed	Grader
678380	Ford F-550 Light Vehicle	Reparacion de llanta	REPARACION DE LLANTA	01/10/2021		Corrective Order	WO Completed	Pickup truck
678381	Coaster	Reemplazo de llantas	REPARACION DE LLANTA	01/10/2021		Corrective Order	WO Completed	Bus
678382	Landcruiser DC	Reemplazo de llantas	REPARACION DE LLANTA	01/10/2021		Corrective Order	WO Completed	Pickup truck
678392	Caterpillar 236d Skid Steer L	Revision de equipo	ENGRASE DE EQUIPO	01/10/2021		Corrective Order	WO Completed	Skid Steer
678393	Caterpillar 226b Skid Steer L	engrase general	ENGRASE GENERAL	01/10/2021		Corrective Order	WO Completed	Skid Steer
678394	Caterpillar 236d Skid Steer L	Revision de equipo	ENGRASE DE EQUIPO	01/10/2021		Corrective Order	WO Completed	Skid Steer
678426	Caterpillar 740b Ej	C/ CRUCETAS DE CARDAN	DESGASTE	01/10/2021		Corrective Order	WO Completed	Articulated dump truck
678428	Caterpillar 740b Ej	C/ CYLIN. DIRECCION LH	DESGASTE	01/10/2021		Corrective Order	WO Completed	Articulated dump truck
678431	Caterpillar 740b Ej	REEMP/ INYECTORES DE GRASA	REEMPLAZO	01/10/2021		Corrective Order	WO Completed	Articulated dump truck
678432	Caterpillar 740b Ej	INST/PROTEC/TERMICO/ESCAPE	INST/PROTEC/TERMICO/ESCAPE	01/10/2021		Corrective Order	WO Completed	Articulated dump truck
678435	Caterpillar 336DL Excavator	Cambio de manguera	CAMBIO DE MANGUERA	01/10/2021		Corrective Order	WO Completed	Excavator

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
678436	Intraax	53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	01/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
678452	Landcruiser	TC	REPARAR SISTEMA DIRECCION	MANTENIMIENTO CORRECTIVO	01/10/2021			Corrective Order	WO Completed	Pickup truck
678454	Landcruiser	TC	CAMBIO LUCES POSTERIORES	MANTENIMIENTO CORRECTIVO	01/10/2021			Corrective Order	WO Completed	Pickup truck
678477	Landcruiser	DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678481	Hilux	DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678489	Hilux	DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678495	Landcruiser	TC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021	32,211.00 km		PM Orders	WO Completed	Pickup truck
678499	Hilux	DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678508	Ford	F550	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678510	Toyota	Hilux	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	01/10/2021			PM Orders	WO Completed	Pickup truck
678600	Hilux	DC	INSTALAR PERTIGA	INSTALACION DE PERTIGA	01/10/2021			Corrective Order	WO Completed	Pickup truck
678708	Caterpillar	320DL	se partio el casquillo	SE PARTIO EL CASQUILLO	01/10/2021			Corrective Order	WO Completed	Excavator
678755	Freightliner	Columbia CI112	cambio de polleras	CAMBIO DE POLLERAS	01/10/2021			Corrective Order	WO Completed	Mule truck
678787	Caterpillar	740b Ej	C/ MANG HYD DE FRENO	MANGUERA ROTA	01/10/2021			Corrective Order	WO Completed	Articulated dump truck
678823	Freightliner	Columbia CI112	polleras de cubre lodo	CAMBIO DE POLLERAS CUBRE LODO	01/10/2021			Corrective Order	WO Completed	Mule truck
678935	Caterpillar	740B	C/ EMPAQUETADURA MOTOR	SELLO ROTO	01/10/2021			Corrective Order	WO Completed	Articulated dump truck
678948	Caterpillar	740B EJ ADT	revisar fuga de aceite	REPARAR FUGA DE ACEITE HIDRAULICO	01/10/2021			Corrective Order	WO Completed	Articulated dump truck
678950	Gallegos	Flatbed Trailer	reparacion de luces frenos/eng	REPARACION DE LUCES FRENOS ENGRASE	01/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
678951	Freightliner	CI 120	engrase ajust luces	ENGRASE AJUSTE DE FRENOS LUCES	01/10/2021			Corrective Order	WO Completed	Mule truck
678952	Freightliner	Columbia CI112	reparacion de luces	REPARACION D ELUCES	01/10/2021			Corrective Order	WO Completed	Mule truck
678964	Caterpillar	12M	SOPORTE WO 667994	SOPORTE WO 667994	01/10/2021			Corrective Order	WO Completed	Grader
678988	Hyster	H700 Forklift	Engrase del equipo	ENGRASE DEL EQUIPO	01/10/2021			Corrective Order	WO Completed	Forklift
678992	Caterpillar	RM500 Reclaimer	Equipo colisionado	EQUIPO COLISIONADO. RUPTURA DE ACOPLE LLAVE DE PURGA	01/10/2021			Corrective Order	WO Completed	Road Reclaimer
679024	Landcruiser	DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	01/10/2021			Corrective Order	WO Completed	Pickup truck
679034	Landcruiser	DC	cambio de muelles y cable abs	CAMBIO DE MUELLES Y CABLE DE ABS	01/10/2021			Corrective Order	WO Completed	Pickup truck
679035	Hilux	DC	cambio de alarma de rev y esco	CAMBIO DE ALARMA DE REV Y ESCO	01/10/2021			Corrective Order	WO Completed	Pickup truck
679036	Landcruiser	DC	cambio de diferencial y caja d	CAMBIO DE DIFERENCIAL Y CAJA DE TIMO	01/10/2021			Corrective Order	WO Completed	Pickup truck
679037	Coaster		mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	01/10/2021			Corrective Order	WO Completed	Bus
679038	Landcruiser	DC	ajuste de freno y carga de gas	AJUSTE DE FRENO Y CARGA DE GAS	01/10/2021			Corrective Order	WO Completed	Pickup truck
679040	Coaster		cambio de cilindros de freno	CAMBIO DE CILINDROS DE FRENO	01/10/2021			Corrective Order	WO Completed	Bus
679045	Caterpillar	RM500 Reclaimer	CAMBIO DE VALVULA DE AGUA	INSTALACION DE VALVULA DE AGUA	01/10/2021	90014787		Corrective Order	WO Completed	Road Reclaimer
679055	John Deere	9370R Tractor	fabricar hicht	FABRICAR NICHT	01/10/2021	2021W40		Corrective Order	WO Completed	Tractor
679247	Mobile equipment		reparacion de llanta	REPARACION DE LLANTA DE RETRO CASE	02/10/2021			Corrective Order	WO Completed	Area
679248	WT015 H7 CISTERNA	SINOTRUK	Reemplazo de llanta	REPARACION DE LLANTA	02/10/2021			Corrective Order	WO Completed	Water truck
679249	Grove	RT9130E 120TON	Revision de equipo	ARRANQUE DE EQUIPO	02/10/2021			Corrective Order	WO Completed	Crane/Hoist
679250	John Deere	9370R Tractor	Revision de equipo	REVISION DE EQUIPO	02/10/2021			Corrective Order	WO Completed	Tractor
679252	Internation	4400 SBA 6x4 Boom	Revision de equipo	ARRANQUE DE EQUIPO	02/10/2021			Corrective Order	WO Completed	Boom truck
679253	Caterpillar	236d Skid Steer L	Revision de equipo	REVISION DE EQUIPO - REVISION DE RUEDA TRASERA	02/10/2021			Corrective Order	WO Completed	Skid Steer
679254	Grove	RT600E 50TON	Revision de equipo	REPARACION DE A/C	02/10/2021			Corrective Order	WO Completed	Crane/Hoist
679331	PRAMAC	GSW65 48 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	02/10/2021	25395 horas		Corrective Order	WO Completed	Generator
679332	Caterpillar	336DL Excavator	SENSOR REPLACEMENT	CORRECTIVE	02/10/2021			Corrective Order	WO Completed	Excavator
679345	Caterpillar	735B	C/ MANG HYD SIST LEVANTE	MANGUERA ROTA	02/10/2021			Corrective Order	WO Completed	Articulated dump truck
679376	John Deere	9370R Tractor	PM01 PREVENTIVE MAINTENANCE	CONTACTOR COPAMA	02/10/2021	90014639		Corrective Order	WO Completed	Tractor
679378	Gallegos	Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	02/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
679382	Freightliner	Columbia CI112	LLANTA FLAT	LLANTA FLAT	02/10/2021			Corrective Order	WO Completed	Mule truck
679428	Hyster	H300 13t Forklift (M)	Montacarga flat	MONTACARGA FLAT	02/10/2021			Corrective Order	WO Completed	Forklift
679460	JLG	1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/10/2021			Corrective Order	WO Completed	Manlift
679510	Freightliner	Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/10/2021			Corrective Order	WO Completed	Mule truck
679535	Freightliner	Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/10/2021			Corrective Order	WO Completed	Mule truck
679560	Freightliner	Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	02/10/2021			Corrective Order	WO Completed	Mule truck
679595	Freightliner	8170ME Water Truc	Fuga de aire en una manguera	FUGA DE AIRE EN UNA MANGUERA	02/10/2021			Corrective Order	WO Completed	Water truck
679619	Caterpillar	740b Ej	C/ BOBINA SOLENOIDE	BOBINA DEFECTUOSA	02/10/2021			Corrective Order	WO Completed	Articulated dump truck
679626	Mobile equipment		SISTEMA DE SUCCIÓN FOSA	SISTEMA DE SUCCIÓN DE FOSA	02/10/2021			Corrective Order	WO Completed	Area
679767	Caterpillar	236d Skid Steer L	EJE AVERIADO	EJE AVERIADO	02/10/2021			Corrective Order	WO Completed	Skid Steer
679771	Grove	RT600E 50TON	codigo de error por dirección	CODIGO DE ERROR POR DIRECCIÓN Y FUGA HIDRAULICA	02/10/2021			Corrective Order	WO Completed	Crane/Hoist
679772	Coaster		Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/10/2021			Corrective Order	WO Completed	Bus
679779	Doosan	D1005	CORRECTIVO	CAMBIO DE BOMBILLOS	02/10/2021	18795 hrs		Corrective Order	WO Completed	Light Tower
679784	Unimog	Service Truck	cambio de correa de compresor	CAMBIO DE CORREA DE COMPRESOR	02/10/2021			Corrective Order	WO Completed	Truck
679795	Landcruiser	DC	cambio de evaporador	CAMBIO DE EVAPORADOR	02/10/2021			Corrective Order	WO Completed	Pickup truck
679796	Landcruiser	DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	02/10/2021			Corrective Order	WO Completed	Pickup truck
679797	Coaster		revision electrico	REVISION ELECTRICO	02/10/2021			Corrective Order	WO Completed	Bus
679798	Landcruiser	TC	cambio de suspension	CAMBIO DE SUSPENSION	02/10/2021			Corrective Order	WO Completed	Pickup truck
679799	Coaster		cambio de bateria	CAMBIO DE BATERIA	02/10/2021			Corrective Order	WO Completed	Bus
679800	Hilux	DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	02/10/2021			Corrective Order	WO Completed	Pickup truck
679818	Caterpillar	426F2 Backhoe	seguro de pines	SEGURO DE PINES	03/10/2021			Corrective Order	WO Completed	Backhoe

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
679819	Freightliner M2 106 Hydroseedi	cambio de sisteme de embrague	CAMBIO DE SISTEME DE EMBRAGUE	03/10/2021		Corrective Order	WO Completed	Truck
679966	WT015 H7 CISTERNA SINOTRUK	ajuste de lamparas	LAMPARAS SUELTAS	03/10/2021		Corrective Order	WO Completed	Water truck
679968	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	03/10/2021		Corrective Order	WO Completed	Pickup truck
679982	Gallegos Flatbed Trailer	AJUSTE DE FRENO	AJUSTE DE FRENO	03/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
679983	Freightliner CI 120	AJUSTE DE FRENO	AJUSTE DE FRENO	03/10/2021		Corrective Order	WO Completed	Mule truck
679989	Intraax 53121 Hendrickso	FUGA POR PULMON	FUGA POR PULMON	03/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680034	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	03/10/2021 13784 horas		Corrective Order	WO Completed	Generator
680035	Unimog U3000 Truck	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/10/2021		Corrective Order	WO Completed	Truck
680036	PRAMAC GSW330V 315 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	03/10/2021 8738 horas		Corrective Order	WO Completed	Generator
680038	GS224 GSW165P PRAMAC	MANTENIMIENTO CORRECTIVO	INSTALACION DE ALTERNADOR AC	03/10/2021 11142 horas		Corrective Order	WO Completed	Generator
680052	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	03/10/2021		Corrective Order	WO Completed	Mule truck
680190	Gallegos Lime Tank	cambio de pulmon y banda	PULMON DAÑADO Y BANDAS EN MAL ESTADO	03/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680205	Caterpillar DE165E0 165 kVa	PM1 CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 17413 horas		PM Orders	WO Completed	Generator
680206	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 14295 hrs		PM Orders	WO Completed	Generator
680208	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 12977 horas		PM Orders	WO Completed	Generator
680209	USP&E GP700S/V-A 700 kVa	PM1 UPS GP700 V-A MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 24798 hrs		PM Orders	WO Completed	Generator
680210	Caterpillar C9 250 kVa	PM1 CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 20761 hrs		PM Orders	WO Completed	Generator
680211	SDMO J60U 60 kVa	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 6806 horas		PM Orders	WO Completed	Generator
680212	SDMO J30U 38KVA	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 9319 horas		PM Orders	WO Completed	Generator
680214	Caterpillar DE88E0 58 kVa	PM1 CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 38300 HRS		PM Orders	WO Completed	Generator
680215	PRAMAC GSW30Y 24 kVa	PM1 PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 22781 horas		PM Orders	WO Completed	Generator
680220	Doosan D1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 19283 horas		PM Orders	WO Completed	Light Tower
680221	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 1142 hrs		PM Orders	WO Completed	Light Tower
680222	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 729 horas		PM Orders	WO Completed	Light Tower
680223	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 763 horas		PM Orders	WO Completed	Light Tower
680224	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 600 hras		PM Orders	WO Completed	Light Tower
680225	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	03/10/2021 611 hrs		PM Orders	WO Completed	Light Tower
680245	Caterpillar C9 250 kVa	CAMBIO MOTOR ARRANQUE	FALLA EN ARRANQUE EQUIPO	03/10/2021 20588 horas		Corrective Order	WO Completed	Generator
680250	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 65.5 horas		PM Orders	WO Completed	Generator
680251	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 8258 hrs		PM Orders	WO Completed	Generator
680252	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 10422 hrs		PM Orders	WO Completed	Generator
680253	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 16809 horas		PM Orders	WO Completed	Generator
680254	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 839 horas		PM Orders	WO Completed	Generator
680255	Caterpillar 336DL Excavator	CAMBIO DE MANGUERA	CAMBIO DE MANGUERA	03/10/2021		Corrective Order	WO Completed	Excavator
680256	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 9774 horas		PM Orders	WO Completed	Generator
680257	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 16485 horas		PM Orders	WO Completed	Generator
680258	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 16084 horas		PM Orders	WO Completed	Generator
680259	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 8644 horas		PM Orders	WO Completed	Generator
680260	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 3633 horas		PM Orders	WO Completed	Generator
680261	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 581 horas		PM Orders	WO Completed	Generator
680263	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 361 HORAS		PM Orders	WO Completed	Generator
680264	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 11056 horas		PM Orders	WO Completed	Generator
680265	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 160 HORAS		PM Orders	WO Completed	Generator
680266	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 25132 horas		PM Orders	WO Completed	Generator
680267	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 18055 horas		PM Orders	WO Completed	Generator
680268	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	03/10/2021 261 horas		PM Orders	WO Completed	Generator
680271	SJS SJ6530	MECHANICAL REPAIRS	CORRECTIVE	03/10/2021		Corrective Order	WO Completed	Compactor
680277	Grove RT600E 50TON	INSPECCION PRE-CERTIFICACION	INSPECCION	03/10/2021		Corrective Order	WO Completed	Crane/Hoist
680282	Caterpillar D6T LGP	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Dozer
680284	Caterpillar D8T Dozer	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Dozer
680287	Caterpillar CW34 Compactor	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Compactor

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
680291	Caterpillar 226B	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Skid Steer
680292	Caterpillar 226B	TA1 INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Skid Steer
680295	JLG 1250 AJP Manlift	MECHANICAL INSPECTION	INSPECTION	03/10/2021		Corrective Order	WO Completed	Manlift
680299	Freightliner CI 120	MECHANICAL INSPECTION	INSPECTION	03/10/2021 354573		Corrective Order	WO Completed	Mule truck
680300	Caterpillar C9 250 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE MOTOR DE ARRANQUE	03/10/2021 20023 horas		Corrective Order	WO Completed	Generator
680303	Hyster H800 32t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680304	Hyster H700 Forklift	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680306	Hyster H800 32t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680307	Hyster H300 13t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680308	Hyster H700 Forklift	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680310	Hyster H300 13t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680312	Hyster H300 Forklift	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680313	Hyster H300 13t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680314	Hyster H800 32t Forklift (M)	INSPECCION SIS AUTOENGRASE	TAREA CORRECTIVA COPAMA	03/10/2021		Corrective Order	WO Completed	Forklift
680321	Caterpillar RM500 Reclaimer	BALL VALVE REPLACEMENT	CORRECTIVE	03/10/2021		Corrective Order	WO Completed	Road Reclaimer
680356	Caterpillar 226b Skid Steer L	Pedal Acelerador	PEDAL ACELERADOR	03/10/2021 90016117		Corrective Order	WO Completed	Skid Steer
680358	Freightliner Columbia CI112	Instalacion de polleras	INSTALKACION DE POLLERAS	03/10/2021		Corrective Order	WO Completed	Mule truck
680367	Caterpillar 226b Skid Steer L	Minicargador de Molinos	MINICARGADOR DE MOLINOS	03/10/2021		Corrective Order	WO Completed	Skid Steer
680386	Gallegos 28M3 Lime Tank	FUGA DE AIRE	FUGA DE AIRE	03/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680395	Caterpillar 236d Skid Steer L	Nivel de aceite de motor bajo	PRESENTA FUGA DE ACEITE	03/10/2021		Corrective Order	WO Completed	Skid Steer
680396	Caterpillar 226b Skid Steer L	NIVEL DE ACEITE HIDRAULICO	NIVEL DE ACEITE HIDRAULICO BAJO	03/10/2021		Corrective Order	WO Completed	Skid Steer
680399	John Deere 9370R Tractor	PROBLEMAS DE ARRANQUE	EQUIPO NO ARRANCA	03/10/2021		Corrective Order	WO Completed	Tractor
680400	Unimog U3000 Truck	Alarma de reversa	ALARMA DE REVERSA NO FUNCIONA	03/10/2021		Corrective Order	WO Completed	Truck
680401	Gallegos Lime Tank	FUGA DE AIRE/AJUSTE DE FRENO	FUGA DE AIRE/AJUSTE DE FRENO	03/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680415	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/10/2021		Corrective Order	WO Completed	Pickup truck
680417	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/10/2021		Corrective Order	WO Completed	Pickup truck
680419	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/10/2021		Corrective Order	WO Completed	Pickup truck
680469	Landcruiser DC	matenimiento preventivo	MANTENIMIENTO PREVENTIVO	04/10/2021		Corrective Order	WO Completed	Pickup truck
680471	Hino Dutro 300	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	04/10/2021		Corrective Order	WO Completed	Truck
680472	Hilux DC	reparacion de corto	REPARACION DE CORTO	04/10/2021		Corrective Order	WO Completed	Pickup truck
680474	Hino Serie 300	cambio de lamparas	CAMBIO DE LAMPARAS	04/10/2021		Corrective Order	WO Completed	Truck
680475	Hilux DC	Cambio de cerradura de vagon	CAMBIO DE CERRADURA DE VAGON	04/10/2021		Corrective Order	WO Completed	Pickup truck
680476	Coaster	reparacion de corto	REPARACION DE CORTO	04/10/2021		Corrective Order	WO Completed	Bus
680554	DOOSAND 1005	LLAMADA DE EMERGENCIA	CAMBIO DE CORREA DE MOTOR	04/10/2021 23358 hrs		Corrective Order	WO Completed	Light Tower
680571	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	04/10/2021 37486 horas		PM Orders	WO Completed	Light Tower
680572	DOOSAN 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	04/10/2021 29667 hrs		PM Orders	WO Completed	Light Tower
680589	SJS SJ6530	cambio de carro de traslacion	CAMBIO DE CARRO DE TRASLACION	04/10/2021		Corrective Order	WO Completed	Compactor
680590	Manitou Mht-X1490 9t Telehand	Engrase y evision de niveles d	BAJO NIVEL DE ACEITE HIDRAULICO	04/10/2021 5,039.00 hrs		Corrective Order	WO Completed	Telehender
680593	Manitou Mht-X1490 9t Telehand	engrase y revision de niveles	BAJO NIVEL DE ACEITE HIDRAULICO	04/10/2021 3,907.00 hrs		Corrective Order	WO Completed	Telehender
680594	Grove RT9130E 120TON	revision de fuga	FUGA HIDRAULICA POR ESTABILIZADOR	04/10/2021		Corrective Order	WO Completed	Crane/Hoist
680602	Mobile equipment	Rep. llanta de telehandler New	REPARACION DE LLANTA DE TELEHANDER NEW HOLAN	04/10/2021		Corrective Order	WO Completed	Area
680620	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	04/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680631	Gallegos 28M3 Lime Tank	VALVULA	VALVULA	04/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680641	Tool Trucks	CAMBIO DE LLANTA	CAMBIO DE LLANTA	04/10/2021		Corrective Order	WO Completed	Area
680645	Landcruiser DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	04/10/2021		Corrective Order	WO Completed	Pickup truck
680660	Mobile equipment	Tape para Herramientas	TAPE PARA HERRAMIENTAS	04/10/2021		Corrective Order	WO Completed	Area
680714	Tool Trucks	LLANTAS FLAT	LLANTAS FLAT	04/10/2021		Corrective Order	WO Completed	Area
680773	BT014 M2-112 Freightliner	confeccion de mangira	CONFECCION DE MANGIRA	04/10/2021		Corrective Order	WO Completed	.
680814	Caterpillar D110 E2 110 kVa	CAMBIO CORREA MOTOR	MANTENIMIENTO CORRECTIVO	04/10/2021 14608 hrs		Corrective Order	WO Completed	Generator
680832	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	04/10/2021 15160 horas		Corrective Order	WO Completed	Generator
680838	New Holland Lm 1745	reparacion de valvula cilindro	REPARACION DE VALVULA DE FCILINDRO	04/10/2021		Corrective Order	WO Completed	Telehender
680844	Freightliner Columbia CI112	LLANTA BAJA	LLANTA BAJA	04/10/2021		Corrective Order	WO Completed	Mule truck
680881	Pramac GSW30P 24KVA	CAMBIO GENERADOR AC	FALLA GENERADOR	04/10/2021 12467 horas		Corrective Order	WO Completed	Generator
680950	Gallegos Flatbed Trailer	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
680961	BT014 M2-112 Freightliner	Reviicin de fuga hidraulica	REVIICIIN DE FUGA HIDRAULICA	04/10/2021		Corrective Order	WO Completed	.
681265	Toyota Land Cruiser	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	05/10/2021		PM Orders	WO Completed	Pickup truck
681320	Landcruiser DC	cambio de correas	CAMBIO DE CORREAS	05/10/2021		Corrective Order	WO Completed	Pickup truck
681321	Coaster	reparacion de corto electrico	REPARACION DE CORTO ELECRICO	05/10/2021		Corrective Order	WO Completed	Bus
681322	Hilux DC	cambio de bateria	CAMBIO DE BATERIA	05/10/2021		Corrective Order	WO Completed	Pickup truck
681323	Landcruiser DC	reparacion de suspension	REPARACION DE SUSPENSION	05/10/2021		Corrective Order	WO Completed	Pickup truck
681330	Caterpillar CS533E Compactor	Cambio de abrazaderas	CAMBIO DE ABRAZADERAS DEL FILTRO DE ADMISION DE AIRE	05/10/2021 90014869		Corrective Order	WO Completed	Compactor
681340	Caterpillar 226b Skid Steer L	Revision de falla varias	REVISION DE EQUIPO	05/10/2021		Corrective Order	WO Completed	Skid Steer
681341	Gallegos 28M3 Lime Tank	Cambio de reloj de presion	CAMBIO DE MEDIDOR DE ACEITE	05/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
681342	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	05/10/2021		Corrective Order	WO Completed	Bus
681343	Caterpillar 236d Skid Steer L	Reparacion de llanta	REPARACION DE LLANTA	05/10/2021		Corrective Order	WO Completed	Skid Steer
681364	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	05/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
681407	Caterpillar 236d Skid Steer L	Cambio de extintor	CAMBIO DE EXTINTOR	05/10/2021		Corrective Order	WO Completed	Skid Steer
681412	Caterpillar 226b Skid Steer L	Instalacion de extintor	INSTALACION DE EXTINTOR	05/10/2021		Corrective Order	WO Completed	Skid Steer
681475	Caterpillar 236d Skid Steer L	CAMBIO DE COMPONENTE	PERSONAL DE IASA	05/10/2021	90014804 90014981	Corrective Order	WO Completed	Skid Steer
681477	Mobile equipment	insumos para taller	INSUMOS PARA TALLER	05/10/2021		Corrective Order	WO Completed	Area
681504	Hilux DC	REVISAR SEÑAL GPS	FALSA SEÑAL	05/10/2021		PM Orders	WO Completed	Pickup truck
681522	PRAMAC GSW80P 83 kVa	CAMBIO DE ALTERNADOR DC	REPARACCION Y COLOCACION DE ALTERNADOR DC	05/10/2021	13682 horas	Corrective Order	WO Completed	Generator
681530	Tool Trucks	LLANTA FLAT	LLANTA FLAT	05/10/2021		Corrective Order	WO Completed	Area
681544	Caterpillar CS533E Compactor	Cambio de Switch	CAMBIO DE SWITCH	05/10/2021		Corrective Order	WO Completed	Compactor
681624	Gallegos 28M3 Lime Tank	Fuga por tercera escotilla	FUGA POR TERCERA ESCOTILLA	05/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
681626	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	05/10/2021		Corrective Order	WO Completed	Pickup truck
681632	Freightliner M2 106 Sucker Tru	Palanca de cambio suelta	PALANCA DE CAMBIO SUELTA Y DEFENSA DELANTERA	05/10/2021		Corrective Order	WO Completed	Sucker truck
681634	WT013 H7 CISTERNA SINOTRUK	Luz de escolta defectuosa	LUZ DE ESCOLTA DEFECTUOSA	05/10/2021		Corrective Order	WO Completed	Water truck
681635	Grove RT880E 75TON	Bajo nivel de aceite motor	BAJO NIVEL ACEITE MOTOR	05/10/2021		Corrective Order	WO Completed	Crane/Hoist
681638	JLG 1250 AJP Manlift	Fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	05/10/2021		Corrective Order	WO Completed	Manlift
681641	Pramac GSW25P 17KVA	CAMBIO ALTERNADOR DC	CAMBIO DE CORREA MOTOR	05/10/2021	4946 HORAS	Corrective Order	WO Completed	Generator
681644	Freightliner Cl 120	Rueda ausente	RUEDA AUSENTE	05/10/2021		Corrective Order	WO Completed	Mule truck
681680	Coaster	reparacion de 1 llanta	REPARACION DE 1 LLANTA	05/10/2021		Corrective Order	WO Completed	Bus
681683	Cargador 966H Wheel Loader	Fuga de aceite motor	FUGA DE ACEITE MOTOR	05/10/2021		Corrective Order	WO Completed	Loader
681692	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	05/10/2021		Corrective Order	WO Completed	Pickup truck
681694	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	05/10/2021		Corrective Order	WO Completed	Pickup truck
681866	Unimog U3000 Truck	ALARMA DE REVERSA Y ACOPLES	CAMBIO DE LA ALARMA DE REVERSA Y ACOPLES DEL PK BRACKE	06/10/2021		Corrective Order	WO Completed	Truck
681904	Caterpillar 320DL	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULIC	06/10/2021		Corrective Order	WO Completed	Excavator
681906	Gallegos 28M3 Lime Tank	FUGA DE AIRE	FUGA DE AIRE	06/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
681951	New Holland Lm 1745	Remplazo de Lucas	REPLAZO DE LUCES	06/10/2021		Corrective Order	WO Completed	Telehender
681953	New Holland Lm 1745	Manguera de Turbo	MANGUERA DE TURBO	06/10/2021		Corrective Order	WO Completed	Telehender
681969	Broce Broom RJT 350	BRUSHES REPLACEMENT	PREVENTIVE	06/10/2021		Corrective Order	WO Completed	Scrubber / Sweeper
681985	Broce Broom RJT 350	cambio de filtro	CAMBIO DE FILTRO	06/10/2021		Corrective Order	WO Completed	Scrubber / Sweeper
681993	Caterpillar TL1055CLRC	Corregir la fuga de coolan	CORREGIR LA FUGA DE COOLAN	06/10/2021		Corrective Order	WO Completed	Telehender
682004	Tool Trucks	LLANTA FLAT	LLANTA FLAT	06/10/2021		Corrective Order	WO Completed	Area
682006	Tool Trucks	LLANTA FLAT	LLANTA FLAT	06/10/2021		Corrective Order	WO Completed	Area
682022	Gallegos 28M3 Lime Tank	CAUCHO DE MANGUERAS /MANOMETRO	CAUCHO DE MANGUERAS /MANOMETRO	06/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
682045	Hilux DC	Cambio de llanta	CAMBIO DE LLANTA	06/10/2021		Corrective Order	WO Completed	Pickup truck
682083	PRAMAC GSW45P 48 kVa	PM OLY GEP 88-3 MEC 300 HR	OIL & FILTER REPLACEMENT, INSPECTION	06/10/2021	9188 horas	PM Orders	WO Completed	Generator
682119	Toyota Hilux	CAMBIO CINTAS REFLECTIVAS	RENOVACION DE CINTAS	06/10/2021		Corrective Order	WO Completed	Pickup truck
682138	JLG 1250 AJP Manlift	cambio de manguera	CAMBIO DE MANGUYERA	06/10/2021		Corrective Order	WO Completed	Manlift
682146	Caterpillar 12M	Llanta flat...	LLANTA FLAT	06/10/2021		Corrective Order	WO Completed	Grader
682185	Mobile equipment	aceite 68	TOTEM ACEITE 68	06/10/2021		Corrective Order	WO Completed	Area
682191	Caterpillar 12M Motorgrader	Wiper trasero no funciona	WIPER TRASERO NO FUNCIONA	06/10/2021		Corrective Order	WO Completed	Grader
682193	Caterpillar 12M Motorgrader	S.Aut.articulacion no funciona	S.AUT.ARTICULACION NO FUNCIONA	06/10/2021		Corrective Order	WO Completed	Grader
682198	Caterpillar 12M Motorgrader	Calentimiento temp del motor	CALENTIMIENTO TEMP DEL MOTOR	06/10/2021		Corrective Order	WO Completed	Grader
682221	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	06/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
682222	Gallegos 28M3 Lime Tank	Fuga por escotilla central	FUGA POR ESCOTILLA CENTRAL	06/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
682223	Caterpillar 307E Miniexcavator	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULICO	06/10/2021		Corrective Order	WO Completed	Excavator
682225	Caterpillar 320DL	Bajo nivel de aceite motor	BAJO NIVEL DE ACEITE MOTOR	06/10/2021		Corrective Order	WO Completed	Excavator
682226	Broce Broom RJT 350	Pierde fuerza	PIERDE FUERZA	06/10/2021		Corrective Order	WO Completed	Scrubber / Sweeper
682326	Caterpillar 12M	Cambio de Cuchilla	CAMBIO DE CUCHILLA	06/10/2021		Corrective Order	WO Completed	Grader
682340	Freightliner M112 Truck Tip	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	06/10/2021		Corrective Order	WO Completed	Tipper
682341	Landcruiser TC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	06/10/2021		Corrective Order	WO Completed	Pickup truck
682345	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE BATERIA	07/10/2021	26143 horas	Corrective Order	WO Completed	Generator
682359	Grove RT600E 50TON	ELECTROVÁLVULA AVERIADA	ELECTROVALVULA DE CONTROL DE LOS ESTABILIZADORES	07/10/2021		Corrective Order	WO Completed	Crane/Hoist
682364	Caterpillar 236d Skid Steer L	CAMBIO DE EJE	CAMBIO DE EJE DE RUEDA	07/10/2021		Corrective Order	WO Completed	Skid Steer
682389	Caterpillar 320DL	FUGA DE ACEITE HIDRAULICO	FUGA DE ACEITE IDRAULICO	07/10/2021		Corrective Order	WO Completed	Excavator
682416	Caterpillar 14H Motorgrader	Temperatura Alta	TEMPERATURA ALTA	07/10/2021		Corrective Order	WO Completed	Grader
682417	Caterpillar 14H Motorgrader	Frenada	FRENADA	07/10/2021		Corrective Order	WO Completed	Grader
682430	Caterpillar 14H Motorgrader	Maquina no le sirve el bloqueo	MAQUINA NO LE SIRVE EL BLOQUEO	07/10/2021		Corrective Order	WO Completed	Grader
682432	Caterpillar 14H Motorgrader	joystick esta mal calibrado	JOYSTICK ESTA MAL CALIBRADO	07/10/2021		Corrective Order	WO Completed	Grader
682437	Caterpillar 14H Motorgrader	cambiar bronces de la corona d	CAMBIAR BRONCES DE LA CORONA D	07/10/2021		Corrective Order	WO Completed	Grader
682438	Caterpillar 14H Motorgrader	Adicional revisar la dirección	ADICIONAL REVISAR LA DIRECCIÓN	07/10/2021		Corrective Order	WO Completed	Grader
682446	Caterpillar D8T Dozer	Fuga de aceite	FUGA DE ACEITE	07/10/2021		Corrective Order	WO Completed	Dozer
682470	Hilux DC	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	07/10/2021	9611.00	Corrective Order	WO Completed	Pickup truck
682473	Landcruiser TC	BATERIA	CAMBIO DE BATERIA	07/10/2021	33890.00	Corrective Order	WO Completed	Pickup truck
682475	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTROS Y ACEITES	07/10/2021	16341.00	Corrective Order	WO Completed	Pickup truck
682481	Gallegos Flatbed Trailer	Revision de LUCES	REVISION DE LUCES	07/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
682591	Caterpillar 236d Skid Steer L	cambio de extintor	CAMBIO DE EXTINTOR DE 10 LIBRAS	07/10/2021		Corrective Order	WO Completed	Skid Steer

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
682687	Caterpillar 14M Motorgrader	fuga por damper	FUGA POR DAMPER	07/10/2021	90014894	Corrective Order	WO Completed	Grader
682691	Caterpillar 12M	flatio la llanta # 6	FLATIO LA LLANTA # 6	07/10/2021		Corrective Order	WO Completed	Grader
682692	Bomag BW24RH	problema de avance.en pendiente	PROBLEMA DE AVANCE.EN PENDIETE	07/10/2021		Corrective Order	WO Completed	Roller PTR
682695	Freightliner CI 120	PARKING BRAKE / EJE DE MANDO	PARKING BRAKE / EJE DE MANDO	07/10/2021		Corrective Order	WO Completed	Mule truck
682701	Caterpillar 12M	Daños fuga humo por el turbo	DAÑOS FUGA HUMO POR EL TURBO	07/10/2021		Corrective Order	WO Completed	Grader
682702	Caterpillar 12M	A/C enfria poco	A/C ENFRIA POCO	07/10/2021		Corrective Order	WO Completed	Grader
682715	Caterpillar 12M	Bronces desgastado	BRONCES DESGASTADO	07/10/2021		Corrective Order	WO Completed	Grader
682739	Caterpillar D8T Dozer	falta coolant	FALTA COOLANT	07/10/2021	90015195	Corrective Order	WO Completed	Dozer
682746	Caterpillar D8T Dozer	Falta aceite hidraulico	FALTA ACEITE HIDRAULICO	07/10/2021		Corrective Order	WO Completed	Dozer
682747	Pramac GSW30P 24KVA	LAVADO DE EQUIPO COMPLETO	LAVADO DE RADIADOR. MOTOR & CABINA	07/10/2021	12467 horas	Corrective Order	WO Completed	Generator
682791	PRAMAC GSW110 82 kVa	PARO DE EMERGENCIA ACTIVADO	LLAMADA DE EMERGENCIA	07/10/2021	361 horas	Corrective Order	WO Completed	Generator
682854	Caterpillar 307E Miniexcavator	Engrase general	ENGRASE GENERAL	07/10/2021		Corrective Order	WO Completed	Excavator
682861	Caterpillar 320DL	engrase general	ENGRASE GENERAL	07/10/2021		Corrective Order	WO Completed	Excavator
682864	Coaster	reparacion de 1 llanta	REPARACION DE 1 LLANTA	07/10/2021		Corrective Order	WO Completed	Bus
682868	Freightliner M2 106 Sucker Tru	Equipo no enciende	EQUIPO NO ENCIENDE	07/10/2021		Corrective Order	WO Completed	Sucker truck
682869	Freightliner Columbia CI112	Cambio de retrovisor	CAMBIO DE RETROVISOR	07/10/2021		Corrective Order	WO Completed	Mule truck
682879	Hyster H700 Forklift	Bajo nivel de aceite Motor	BAJO NIVEL DE ACEITE MOTOR	07/10/2021		Corrective Order	WO Completed	Forklift
682882	Caterpillar 740B	C/ SELLO SUSPENSION POS 1	SELLO ROTOS	07/10/2021		Corrective Order	WO Completed	Articulated dump truck
682902	PRAMAC GSW90P 74 kVa	REPARACION DE ALTERNADOR DC	REPARACION DE ALTERNADOR DC12V, 65 AMP.	07/10/2021	26143 horas	Corrective Order	WO Completed	Generator
682904	Freightliner Columbia CI112	revisar niveles de aceites	REVISAR NIVELES DE ACEITES, COMPLETAR,	07/10/2021		Corrective Order	WO Completed	Mule truck
682908	Freightliner Columbia CI112	Inspeccion de llanta	INSPECCION Y REPARACION D ELLANTA	07/10/2021		Corrective Order	WO Completed	Mule truck
682912	Mack Trucks Gu813e	reparacion de luces, fugas	REPARACION DE LUCES TRASERAS FUGA DE AIRE	07/10/2021		Corrective Order	WO Completed	Truck
682919	Freightliner CI 120	reparar alarma activa	REPARAR ALARMA ACTIVA DE FRENO	07/10/2021		Corrective Order	WO Completed	Mule truck
682923	PRAMAC GSW90P 74 kVa	REPARACION DE ALTERNADOR DC	REPARACION DE ALTERNADOR DC12V, 65 AMP.	07/10/2021	26143 horas	Corrective Order	WO Completed	Generator
682944	Caterpillar 14M Motorgrader	No bloquea	NO BLOQUEA	07/10/2021		Corrective Order	WO Completed	Grader
682945	Caterpillar 14M Motorgrader	vota aceite por el tanden izqu	VOTA ACEITE POR EL TANDEN IZQU	07/10/2021		Corrective Order	WO Completed	Grader
682953	Caterpillar 12M	Juego en los gemelos de la art	JUEGO EN LOS GEMELOS DE LA ART	07/10/2021		Corrective Order	WO Completed	Grader
682954	Caterpillar 12M	Desgaste en el tornillo	DESGASTE EN EL TORNILLO	07/10/2021		Corrective Order	WO Completed	Grader
682956	Caterpillar 12M	cambio de la tornamesa	CAMBIO DE LA TORNAMESA	07/10/2021		Corrective Order	WO Completed	Grader
682958	Freightliner CI 120	MANGUERA DE FRENOS/ TABLERO	MANGUERA DE FRENOS	07/10/2021		Corrective Order	WO Completed	Mule truck
682962	Gallegos Flatbed Trailer	AJUSTE DE FRENOS	AJUSTE DE FRENOS	07/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
682963	Freightliner CI 120	FUGA DE AIRE	FUGA DE AIRE	07/10/2021	326353.6	Corrective Order	WO Completed	Mule truck
682964	Caterpillar 12M	Cambio de llanta	CAMBIO DE LLANTA	07/10/2021		Corrective Order	WO Completed	Grader
682969	JLG 1250 AJP Manlift	CONFECCIÓN DE MANGUERA	CONFECCIÓN DE MANGUERA HIDRÁULICA	07/10/2021		Corrective Order	WO Completed	Manlift
682972	Mobile equipment	SIMPLE GREEN	SIMPLE GREEN PARA TALLER TACTICO	07/10/2021		Corrective Order	WO Completed	Area
682983	International 7400 SBA Fire Tr	Reparación de Luces	REPARACIÓN DE LUCES	08/10/2021		Corrective Order	WO Completed	Fire truck
682984	Internation F2674	Reparación de Luces	REPARACIÓN DE LUCES	08/10/2021		Corrective Order	WO Completed	Boom truck
682986	Caterpillar D110 E2 100KVA	LLAMADA DE EMERGENCIA	CAMBIO DE CORREAS	08/10/2021	14720 HORAS	Corrective Order	WO Completed	Generator
682993	Unimog Service Truck	CORREA DEL COMPRESOR	CAMBIO DE CORREA DEL COMPRESOR	08/10/2021		Corrective Order	WO Completed	Truck
683000	Hyster E70xn 3t Forklift (E)	reparacion de cables de cargad	REPARACION DE CABLES DE CARGAD	08/10/2021		Corrective Order	WO Completed	Forklift
683033	Caterpillar 336DL Excavator	PM01 PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021		Corrective Order	WO Completed	Excavator
683083	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	08/10/2021		PM Orders	WO Completed	Pickup truck
683116	Coaster	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES YFILTROS	08/10/2021		Corrective Order	WO Completed	Bus
683122	Landcruiser TC	SUSPENSION	CAMBIO DE AMORTIGUADORES	08/10/2021		Corrective Order	WO Completed	Pickup truck
683125	Caterpillar 14M Motorgrader	Cambio de sensor articulacion	CAMBIO DE SENSOR DE ARTICULACIÓN	08/10/2021		Corrective Order	WO Completed	Grader
683127	Hilux DC	RESCATE	RESCATE EN FLOTACION BATERIA	08/10/2021		Corrective Order	WO Completed	Pickup truck
683132	Hilux DC	DIRECCION	TERMINALES	08/10/2021		Corrective Order	WO Completed	Pickup truck
683134	Hilux DC	FRENOS,PARABRISAS	AJSUTE DE FRENOS	08/10/2021		Corrective Order	WO Completed	Pickup truck
683137	Landcruiser DC	LUSCES,ALAARAM	CAMBIO DE BOMBILOS ALARMA	08/10/2021		Corrective Order	WO Completed	Pickup truck
683155	Coaster	SITEMA ELECTRICO	CORTO	08/10/2021	42284.00	Corrective Order	WO Completed	Bus
683157	Hilux DC	PROBLEMAS DE POTENCIA	SELENOIDE DE TURBO	08/10/2021	56481.00	Corrective Order	WO Completed	Pickup truck
683161	Coaster	ALARMA	ALARMA DE RTROCESO	08/10/2021	12714.00	Corrective Order	WO Completed	Bus
683173	Coaster	MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO ACEITES	08/10/2021	36164.00	Corrective Order	WO Completed	Bus
683176	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO ACEITES	08/10/2021	72204.00	Corrective Order	WO Completed	Pickup truck
683178	Landcruiser DC	REPARACION CERRADURA	REPARACION DE CERRADURA PUERTAS	08/10/2021	84809.00	Corrective Order	WO Completed	Pickup truck
683181	Landcruiser DC	RESCATE EN BOTIJA	PROBLEMAS DE CORREAS,PUERTAS	08/10/2021		Corrective Order	WO Completed	Pickup truck
683197	ATLAS COPCO HILIGHT V5+	REPARACION DE CABLE	CABLE ROTO EN MALA MANIPULACION	08/10/2021	445 hrs	Corrective Order	WO Completed	Light Tower
683199	Olympian GEP150 135 kVa	CAMBIO DE CARGADOR DE BATERIA	CARGADOR DE BATERIA QUEMADO	08/10/2021	66.7 horas	Corrective Order	WO Completed	Generator
683352	Tool Trucks	LLANTA FLAT	LLANTA FLAT	08/10/2021		Corrective Order	WO Completed	Area
683380	Toyota Hilux	PRUEBA FUNCIONAL AMBULANCIAS	ARRANQUE E INSPECCION QUINCENAL	08/10/2021		PM Orders	WO Completed	Pickup truck
683381	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	08/10/2021	10324 hrs	PM Orders	WO Completed	Generator
683382	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	08/10/2021	12668 hrs	PM Orders	WO Completed	Generator
683383	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	08/10/2021	sin horas	PM Orders	WO Completed	Generator
683386	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	08/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
683404	Caterpillar 336DL Excavator	reparacion de pines, engrase	REPARACION DE PINES, ENGRASE, PASADORES	08/10/2021		Corrective Order	WO Completed	Excavator
683472	Mobile equipment	Daño en las mangueras hidrauli	DAÑO EN LAS MANGUERAS HIDRAULI	08/10/2021		Corrective Order	WO Completed	Area
683479	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	08/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
683501	Mercedes Tipper Truck	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021		Corrective Order	WO Completed	Tipper
683513	Caterpillar 426f2 Backhoe	cambio de bujes del pin	CAMBIO DE BUJES EL PIN	08/10/2021		Corrective Order	WO Completed	Backhoe
683522	Freightliner Columbia CI112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021		Corrective Order	WO Completed	Mule truck
683533	Gallegos 28M3 Lime Tank	PULMON DANADO	PULMON DANADO	08/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
683537	Freightliner Columbia CI112	LLANTA PARA CAMBIO	LLANTA PARA CAMBIO	08/10/2021		Corrective Order	WO Completed	Mule truck
683539	PRAMAC GSW460V 460 kVa	FALLO DE ALTERNADOR AC	LLAMADA DE EMERGENCIA POR FALLO DE TARGETA REGULADORA	08/10/2021	28308 horas	Corrective Order	WO Completed	Generator
683556	PRAMAC GSW90P 74 kVa	CAMBIO DE CARGADOR DE BATERIA	CAGADOR DE BATERIA DEFECTUOSO	08/10/2021	26143 horas	Corrective Order	WO Completed	Generator
683558	Caterpillar 226b Skid Steer L	Falla en sensor	FALLA EN SENSOR	08/10/2021		Corrective Order	WO Completed	Skid Steer
683674	Landcruiser DC	REPONER CUÑAS	POR PERDIDA	08/10/2021		Corrective Order	WO Completed	Pickup truck
683713	Landcruiser DC	AJUSTE CORREAS COMPRESOR AIRE	POR RUIDO	08/10/2021		Corrective Order	WO Completed	Pickup truck
683741	PRAMAC GSW460V 460 kVa	REEMPLAZO TARGETA REGULADORA	MANTENIMIENTO CORRECTIVO	08/10/2021	28309 horas	Corrective Order	WO Completed	Generator
683755	Freightliner Columbia CI112	cambio de llantas	CAMBIO DE LLANTAS	08/10/2021		Corrective Order	WO Completed	Mule truck
683761	Caterpillar 320DL	Revision de fuga	FUGA HIDRAULICA	08/10/2021	21,691.40 hrs	Corrective Order	WO Completed	Excavator
683766	Caterpillar 416F2 Backhoe	No tiene sistema AFEX	NO TIENE SISTEMA AFEX	08/10/2021		Corrective Order	WO Completed	Backhoe
683799	Gallegos 28M3 Lime Tank	ESCOTILLA ABIERTA	ESCOTILLA ABIERTA	08/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
683808	Caterpillar 740B EJ ADT	C/ MANG HYD ENFRIAMIENTO FRENO	MANGUERA ROTA	08/10/2021		Corrective Order	WO Completed	Articulated dump truck
683874	Freightliner M2 106 Refrigerat	Reparación de puerto	REPARACIÓN DE PUERTO	08/10/2021		Corrective Order	WO Completed	Refrigerator truck
683880	Freightliner Columbia CI112	Problema con encendido	PROBLEMA CON ENCENDIDO	08/10/2021		Corrective Order	WO Completed	Mule truck
683887	Freightliner M2 106	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	08/10/2021		Corrective Order	WO Completed	Bitumen truck
683908	Landcruiser TC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	08/10/2021		Corrective Order	WO Completed	Pickup truck
683909	Coaster	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	08/10/2021		Corrective Order	WO Completed	Bus
683912	Landcruiser TC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	08/10/2021		Corrective Order	WO Completed	Pickup truck
683913	Freightliner Columbia CI112	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	08/10/2021		Corrective Order	WO Completed	Mule truck
683914	Mobile equipment	Verificacion de presion	VERIFICACION DE PRESION	08/10/2021		Corrective Order	WO Completed	Area
684008	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	09/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
684017	Freightliner Columbia CI112	PROBLEMAS DE CARGA	CAIDA DE VOLTAJE	09/10/2021		Corrective Order	WO Completed	Mule truck
684042	Grove GMK 4080 80TON	Fuga por debajo de la Cabina	FUGA POR DEBAJO DE LA CABINA	09/10/2021		Corrective Order	WO Completed	Crane/Hoist
684064	Caterpillar 14M Motorgrader	FRENO DE ESTACIONAMIENTO	NO LIBERA EL FRENO DE ESTACIONAMEINTO	09/10/2021		Corrective Order	WO Completed	Grader
684076	Mobile equipment	LLAVES PARA TALLER	LLAVES PARA TALLER	09/10/2021		Corrective Order	WO Completed	Area
684102	Caterpillar 12M	Sube la temperatura de aceite	SUBE LA TEMPERATURA DE ACEITE	09/10/2021		Corrective Order	WO Completed	Grader
684103	Freightliner M112 Truck Tip	Bolsa de aire de cabina en mal	BOLSA DE AIRE DE CABINA EN MAL	09/10/2021		Corrective Order	WO Completed	Tipper
684116	Caterpillar D110 E2 100KVA	FALLO POR CEBA	EQUIPO PIERDE CEBA	09/10/2021	15972 horas	Corrective Order	WO Completed	Generator
684123	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	09/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
684125	Caterpillar D110 E2 100KVA	FALLO POR BAJO VOLTAGE	EQUIPO CON FALLA DE VOLTAGE BAJO	09/10/2021	2741 horas	Corrective Order	WO Completed	Generator
684130	Freightliner Columbia CI112	ESPEJOS RAJADOS	ESPEJOS RAJADOS	09/10/2021		Corrective Order	WO Completed	Mule truck
684235	Gallegos 28M3 Lime Tank	CAMBIO DE MANGUERAS	CORRECTIVO	09/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
684273	Internation F2674	LEVANTAMIENTO DE INFORMACION	VIDRIO QUEBRADO.... VARIOS	09/10/2021		Corrective Order	WO Completed	Boom truck
684299	Caterpillar 140K	DAÑO.DESGASTE DE LOS BUJES.	EQUIPO IASA	09/10/2021		Corrective Order	WO Completed	Grader
684379	TTP-0000-102	Cilindro para reparacion	CILINDRO PARA REPARACION	09/10/2021		Corrective Order	WO Completed	Excavator
684388	Landcruiser DC	Cambio de 4 Llantas	CAMBIO DE 4 LLANTAS	09/10/2021		Corrective Order	WO Completed	Pickup truck
684393	Intraax 53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	09/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
684516	Coaster	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	09/10/2021	CERRADO POR PLANEAMIENTO	Corrective Order	WO Completed	Bus
684519	Mobile equipment	Instalacion de hidrolavadora	INSTALACIÓN DE HIDROLAVADORA	09/10/2021		Corrective Order	WO Completed	Area
684549	Mobile equipment	nipleria para puerto	NIPLERIA PARA INSTALACION DE TUBERIAS PUERTO	09/10/2021		Corrective Order	WO Completed	Area
684653	Caterpillar 14M Motorgrader	INSTALACION HERRAMIENTA CORTE	CORRECTIVO	09/10/2021		Corrective Order	WO Completed	Grader
684676	CAT 930K	LISTADO ESCALERA	CORRECTIVO	09/10/2021	90015797	Corrective Order	WO Completed	Loader
684710	Caterpillar 307E Miniexcavator	Cadena descarrilada	CADENA DESCARRILADA	09/10/2021		Corrective Order	WO Completed	Excavator
684712	Freightliner M112 Truck Tip	Retorqueo de tornillería	RETORQUENO DE TORNILLERÍA DE DIFERENCIAL	09/10/2021		Corrective Order	WO Completed	Tipper
684717	Caterpillar 14M Motorgrader	Ruido anormal transmisión	RUIDO ANORMAL TRASMISIÓN	09/10/2021		Corrective Order	WO Completed	Grader
684726	SJS SJ6530	Pin de implemento	PIN DE IMPLEMENTO	09/10/2021		Corrective Order	WO Completed	Compactor
684801	Caterpillar 14M Motorgrader	Corrección de Fugas	CORRECCIÓN DE FUGAS	09/10/2021		Corrective Order	WO Completed	Grader
684885	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	26143 horas	PM Orders	WO Completed	Generator
684898	International 7400 SBA Fire Tr	INSTALACIÓN DE LUCES	INSTALACIÓN DE LUCES	10/10/2021		Corrective Order	WO Completed	Fire truck
684910	Landcruiser DC	SITEMA ELECTRICO	CORTO EN ALARMA DE RETROCESO	10/10/2021	44500.00	Corrective Order	WO Completed	Pickup truck
684911	Hilux DC	EXTINTOR	CAMBIO EXTINTOR	10/10/2021	60181.00	Corrective Order	WO Completed	Pickup truck
684912	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTRO	10/10/2021	53843.00	Corrective Order	WO Completed	Pickup truck
684914	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTRO	10/10/2021	51252.00	Corrective Order	WO Completed	Pickup truck
684915	Hilux DC	REPARACION TURBO	SELENOIDE	10/10/2021	20982.00	Corrective Order	WO Completed	Pickup truck
684916	Landcruiser DC	PROBLEMAS DE CARGAS	ALTERNADOR,POLEA	10/10/2021	59672.00	Corrective Order	WO Completed	Pickup truck
685047	Caterpillar 14M Motorgrader	continua con ruido extraño	CONTINUA CON RUIDO EXTRAÑO	10/10/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
685075	FG WILSON P88-3 80 kVa	PM1 FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	26450 horas	PM Orders	WO Completed	Generator
685076	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	18919 horas	PM Orders	WO Completed	Generator
685077	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	15269 horas	PM Orders	WO Completed	Generator
685078	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	18523 hrs	PM Orders	WO Completed	Generator
685079	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	14647 horaS	PM Orders	WO Completed	Generator
685080	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	15537 horas	PM Orders	WO Completed	Generator
685082	PRAMAC GSW120 120 kVa	PM1 PRA GSW120 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	7216 horas	PM Orders	WO Completed	Generator
685083	Expert Power PN45 10KVA	PM1 EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	9017 hrs	PM Orders	WO Completed	Generator
685084	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	23770 hrs	PM Orders	WO Completed	Light Tower
685086	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	1012 hrs	PM Orders	WO Completed	Light Tower
685110	MAGNUM Light Tower	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	27551 horas	Corrective Order	WO Completed	Light Tower
685113	Atlas Copco Hilight V4W	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	10/10/2021	4831 hrs	Corrective Order	WO Completed	Light Tower
685118	Olympian GEP150 135 kVa	COLOCACION DE LINEA 110 VOLTIO	COLOCACION DE LINEA 110 VOLTIO	10/10/2021	65.7 horas	Corrective Order	WO Completed	Generator
685155	Gallegos 28M3 Lime Tank	MANOMETRO	MANOMETRO	10/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
685182	Mobile equipment	cunas pra taller	CUNAS PARA TALLER	10/10/2021		Corrective Order	WO Completed	Area
685183	Gallegos 28M3 Lime Tank	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	10/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
685245	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	65.5 HORAS	PM Orders	WO Completed	Generator
685246	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	8258 HORAS	PM Orders	WO Completed	Generator
685247	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	10422 HORAS	PM Orders	WO Completed	Generator
685248	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	16809 HORAS	PM Orders	WO Completed	Generator
685249	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	839 hrs	PM Orders	WO Completed	Generator
685250	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	9764 hrs	PM Orders	WO Completed	Generator
685251	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	16485 hrs	PM Orders	WO Completed	Generator
685253	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	16084 hrs	PM Orders	WO Completed	Generator
685254	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	8644 hrs	PM Orders	WO Completed	Generator
685255	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	3633 hrs	PM Orders	WO Completed	Generator
685256	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	581 hrs	PM Orders	WO Completed	Generator
685257	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	361.2 horas	PM Orders	WO Completed	Generator
685258	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	11120 hrs	PM Orders	WO Completed	Generator
685260	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	160.1 horas	PM Orders	WO Completed	Generator
685262	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	25132 hrs	PM Orders	WO Completed	Generator
685263	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	18056 hrs	PM Orders	WO Completed	Generator
685264	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	10/10/2021	335 hrs	PM Orders	WO Completed	Generator
685364	Coaster Bus	Cambio de 1 llanta y pernos	CAMBIO DE 1 LLANTA Y PERNOS	10/10/2021		Corrective Order	WO Completed	Bus
685368	JLG 1250 AJP Manlift	Manguera rota	MANGUERA ROTA	10/10/2021		Corrective Order	WO Completed	Manlift
685370	Coaster	Reparación de llanta	REPARACIÓN DE LLANTA	10/10/2021		Corrective Order	WO Completed	Bus
685372	Rented Light Vehicle	reparacion de 1 llanta	REPRARACION DE 1 LLANTA	10/10/2021		Corrective Order	WO Completed	Area
685378	Freightliner CI 120	Cambio de motor de arranque	CAMBIO DE MOTOR DE ARRANQUE	10/10/2021		Corrective Order	WO Completed	Mule truck
685514	PRAMAC GSW460V 460 kVa	MANTENIMIENTO CORRECTIVO	INSTALACION DE TERMINALES ALTERNADOR	11/10/2021	18993 horas	Corrective Order	WO Completed	Generator
685610	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	11/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
685664	PRAMAC GSW45P 48 kVa	PM PRA GSW45P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	11/10/2021	9550 horas	PM Orders	WO Completed	Generator
685738	Intraax 53121 Hendrickso	REPARACIÓN DE UNA LLANTA	REPARACIÓN DE UNA LLANTA	11/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
685769	Grove RT600E 50TON	Instalacion de extintor	INSTALACION DE EXTINTOR	11/10/2021		Corrective Order	WO Completed	Crane/Hoist
685776	Grove RT880E 75TON	Instalación de extintor	INSTALACIÓN DE EXTINTOR	11/10/2021		Corrective Order	WO Completed	Crane/Hoist
685977	Freightliner M2 112 Sucker Tru	aceite del transfer	SOLICITUD DE ACEITE DE TRANSFER	11/10/2021		Corrective Order	WO Completed	Sucker truck
686009	Gallegos Flatbed Trailer	Cambio de 8 llantas	CAMBIO DE 8 LLANTAS	11/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
686040	Bomag BW219DH-4	Movimiento de Tambor	MOVIMIENTO DE TAMBOR	11/10/2021	SOPORTE W41	Corrective Order	WO Completed	Compactor
686103	Caterpillar 336DL	No tiene luz escolta	NO TIENE LUZ ESCOLTA	11/10/2021		Corrective Order	WO Completed	Excavator
686148	Broce Broom RJT 350	sin luz escolta	SIN LUZ ESCOLTA	11/10/2021		Corrective Order	WO Completed	Scrubber / Sweeper
686160	Mobile equipment	Pintura para taller	PINTURA PARA TALLER	11/10/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
686251	Gallegos 28M3 Lime Tank	Revisión de llanta	REVISIÓN DE LLANTA	11/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
686265	Mobile equipment	Presion de llantas	PRESION DE LLANTAS	11/10/2021		Corrective Order	WO Completed	Area
686270	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	11/10/2021	28376 horas	Corrective Order	WO Completed	Generator
686514	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	12/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
686592	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	12/10/2021		Corrective Order	WO Completed	Pickup truck
686593	Freightliner M112 Truck Tip	Problemas en la perilla	PROBLEMAS EN LA PERILLA	12/10/2021		Corrective Order	WO Completed	Tipper
686594	Cargador 966H Wheel Loader	Engrase General	ENGRASE GENERAL	12/10/2021		Corrective Order	WO Completed	Loader
686595	Hyster H300 Forklift	Reparación de un Neumático	REPARACIÓN DE UN NEUMÁTICO	12/10/2021		Corrective Order	WO Completed	Forklift
686699	Freightliner Columbia CI112	1 LLANTA FLATEADA	1 LLANTA FLATEADA	12/10/2021		Corrective Order	WO Completed	Mule truck
686777	Caterpillar 12M	reemplazo de b. de alta presi	REEMPLAZO DE BOMBA DE ALTA PRESION DE COMBUSTIBLE	12/10/2021		Corrective Order	WO Completed	Grader
686809	Gallegos Flatbed Trailer	No machimbra	NO MACHIMBRA	12/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
686831	Freightliner M2 112 Sucker Tru	Cambio de aceite transfer	REVISAR NIVELES DE ACEITE, LUCES,	12/10/2021		Corrective Order	WO Completed	Sucker truck
686833	Caterpillar 226b Skid Steer L	engrase de puntos de articulac	ENGRASE DE PUNTOSA DE ARTICULACION, REPARACION DE LUCES	12/10/2021		Corrective Order	WO Completed	Skid Steer
686929	Mobile equipment	reparacion de llanta	LLANTA DE MONTA CARGA ALQUILADA DE MSA WORKSHOP	12/10/2021		Corrective Order	WO Completed	Area
686952	Freightliner M2 112 Sucker Tru	confeccion de manguera	MANGUERA EN MAL ESTADO	12/10/2021		Corrective Order	WO Completed	Sucker truck
687010	Grove RT600E 50TON	cambio de manguera	MANGUERA EN MAL ESTADO	12/10/2021		Corrective Order	WO Completed	Crane/Hoist
687012	Caterpillar 14H Motorgrader	Revisión de nivel,de aceite	REVISION DE NIVEL DE ACEITE HIDRAULICO.	12/10/2021		Corrective Order	WO Completed	Grader
687038	Freightliner CI 120	Limpieza de frenos	LIMPIEZA DE TAMBOR DE FRENO.	12/10/2021		Corrective Order	WO Completed	Mule truck
687053	Caterpillar 740B	REEMP/ ACEITE DE LOS CYL.	MAL ESTADO LH Y RH	12/10/2021		Corrective Order	WO Completed	Articulated dump truck
687060	USP&E GP700/V-A 700 kVa	CONEXION Y PUESTA EN MARCHA	CONEXION Y PUESTA EN MARCHA	12/10/2021	11056 hrs	Corrective Order	WO Completed	Generator
687067	Hyster H700 Forklift	Reparacion de pines-engrase	REPARACION DE PINES Y ENGRASE DE MAQUINA	12/10/2021		Corrective Order	WO Completed	Forklift
687069	Hyster H700 Forklift	Engrase de maquina	ENGRASE DE MAQUINA	12/10/2021		Corrective Order	WO Completed	Forklift
687072	Caterpillar D110 E2 110 kVa	LLAMADA DE EMERGENCIA	CORREA REVENTADA	12/10/2021	17729 hrs	Corrective Order	WO Completed	Generator
687082	Terex RT670 64TON	Fab. de pines	FAB. DE PINES	12/10/2021		Corrective Order	WO Completed	Crane/Hoist
687087	AC056 XAS185 ATLAS COPCO	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	12/10/2021	1116 hrs	Corrective Order	WO Completed	Compressor
687095	Gallegos 28M3 Lime Tank	desgaste en valvula	DESGASTE EN VALVULA	12/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
687121	Caterpillar PS-150C	Reparacion de llanta	REPARACION DE LLANTA	12/10/2021		Corrective Order	WO Completed	Roller PTR
687127	Grove RT600E 50TON	Manguera Hidraulica rota	MANGUERA HIDRAULICA ROTA	12/10/2021		Corrective Order	WO Completed	Crane/Hoist
687143	Freightliner CI 120	Tubo de escape roto	TUBO DE ESCAPE ROTO	12/10/2021		Corrective Order	WO Completed	Mule truck
687144	New Holland Lm 1745	Instalación de extintor	INSTALACIÓN DE EXTINTOR	12/10/2021		Corrective Order	WO Completed	Telehender
687146	Mobile equipment	Cargador luz escolta	CARGADOR LUZ ESCOLTA	12/10/2021		Corrective Order	WO Completed	Area
687147	Hyster H700 Forklift	tornillo defectuoso	TORNILLO DEFECTUOSO DE MANIPULADOR	12/10/2021		Corrective Order	WO Completed	Forklift
687151	Pramac GSW25P 17KVA	MOVIMIENTO DE GENERADOR	MOVIMIENTO DE GENERADOR	12/10/2021	SOPORTE W41	Corrective Order	WO Completed	Generator
687153	Landcruiser DC	Cambio de luz de escolta	CAMBIO DE LUZ DE ESCOLTA	12/10/2021		Corrective Order	WO Completed	Pickup truck
687154	Landcruiser DC	RESCATE EN PIT	RESCATE EN PIT	12/10/2021		Corrective Order	WO Completed	Pickup truck
687155	Landcruiser DC	SUSPENSION	SUSPENSION	12/10/2021		Corrective Order	WO Completed	Pickup truck
687156	Landcruiser DC	AIRE ACONDICIONADO	AIRE ACONDICIONADO	12/10/2021		Corrective Order	WO Completed	Pickup truck
687315	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	13/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
687366	Pramac GSW25P 17KVA	EXTRACCION DE ALTERNADOR AC	EXTRACCION DE ALTERNADOR AC PARA REPARACION	13/10/2021	4945 horas	Corrective Order	WO Completed	Generator
687372	Bell 225f 4t Forklift (M)	engrase general	ENGRASE GENERAL	13/10/2021		Corrective Order	WO Completed	Forklift
687373	Bell 225f 4t Forklift (M)	Engrase general	ENGRASE GENERAL	13/10/2021		Corrective Order	WO Completed	Forklift
687374	Bell 225f 4t Forklift (M)	Engrase general	ENGRASE GENERAL	13/10/2021		Corrective Order	WO Completed	Forklift
687375	Bell 225f 4t Forklift (M)	Reparación por llana flat	REPARACIÓN POR LLANTA FLAT	13/10/2021		Corrective Order	WO Completed	Forklift
687378	Bell 225f 4t Forklift (M)	engrase general	ENGRASE GENERAL	13/10/2021		Corrective Order	WO Completed	Forklift
687379	Caterpillar 426F2 Backhoe	LUZ ESCOLTA AUSENTE	INSTALACION DE LUZ DE ESCOLTA	13/10/2021		Corrective Order	WO Completed	Backhoe
687380	Unimog U3000 Truck	Problmas palanca de Parking	PROBEMAS PALANCA DE PARKING BRAKE	13/10/2021		Corrective Order	WO Completed	Truck
687390	SDMO J60U 60KVA	CONEXION DE GENERADOR	CONEXION DE GENERADOR	13/10/2021	261 horas	Corrective Order	WO Completed	Generator
687405	Caterpillar 426f2 Backhoe	Instalación de luz de escolta	INSTALACIÓN DE LUZ DE ESCOLTA	13/10/2021		Corrective Order	WO Completed	Backhoe
687424	Freightliner Columbia CI112	1 LLANTA FLATEADA	1 LLANTA FLATEADA	13/10/2021		Corrective Order	WO Completed	Mule truck
687427	Freightliner Columbia CI112	FUGA DE COOLANT	FUGA DE COOLANT	13/10/2021		Corrective Order	WO Completed	Mule truck
687472	PRAMAC GSW90P 74 kVa	CABLEADO 110V ALIMENTACION	CABLEADO 110V ALIMENTACION	13/10/2021		Corrective Order	WO Completed	Generator
687473	Hyster H300 Forklift	cambio de 2 llantas	LLANTAS ENB MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Forklift
687503	Freightliner Columbia CI112	cambio de 4 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Mule truck
687507	Intraax 53121 Hendrickso	cambio de 4 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
687512	Freightliner Columbia CI112	Cambio de 2 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Mule truck
687513	Caterpillar 14M Motorgrader	Cambio de sujetadores	CAMBIO DE SUJETADORES DE HOJA DE CORTE	13/10/2021		Corrective Order	WO Completed	Grader
687517	Freightliner Columbia CI112	Cambio de 4 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Mule truck
687521	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Bus
687525	Hilux DC	cambio de 1 llanta	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Pickup truck
687526	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	13/10/2021		Corrective Order	WO Completed	Pickup truck
687568	Manitou Mht-X1490 9t Telehand	Leak Aceite en el Boom	LEAK ACEITE EN EL BOOM	13/10/2021		Corrective Order	WO Completed	Telehender
687571	Caterpillar D8T Dozer	reparaciones varias	REPARACIONES VARIAS	13/10/2021		Corrective Order	WO Completed	Dozer

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
687574	Caterpillar D8T Dozer	reparaciones varias	REPARACIONES VARIAS	13/10/2021		Corrective Order	WO Completed	Dozer
687577	Freightliner M2 106 Sucker Tru	cambio de termostato	REPARACION DE A/C	13/10/2021		Corrective Order	WO Completed	Sucker truck
687591	Mobile equipment	insumos	INSUMOS	13/10/2021		Corrective Order	WO Completed	Area
687657	Caterpillar 14M Motorgrader	Refrigerante del radiador cont	REFRIGERANTE DEL RADIADOR CONT	13/10/2021		Corrective Order	WO Completed	Grader
687690	Grove RT880E 75TON	Reemplazo de medidor	REEMPLAZO DE MEDIDOR	13/10/2021		Corrective Order	WO Completed	Crane/Hoist
687776	Caterpillar 740B	C/ VALV. DE CYL. DE SUSP.	FUGA	13/10/2021		Corrective Order	WO Completed	Articulated dump truck
687833	Caterpillar 740B	DESMONTAJE LLANTA POS 1	DESMONTAJE LLANTA POS 1	13/10/2021		Corrective Order	WO Completed	Articulated dump truck
687844	Caterpillar 740B	MONTAJE LLANTA POS 1	MONTAJE LLANTA POS 1	13/10/2021		Corrective Order	WO Completed	Articulated dump truck
687879	Internation F2674	Fuga de aceite hidraulico	NECESITA ACEITE HIDRAULICO	13/10/2021		Corrective Order	WO Completed	Boom truck
687922	Freightliner M2 106	Cambio de baterías	CAMBIO DE BATERIAS	13/10/2021		Corrective Order	WO Completed	Bitumen truck
687967	Freightliner Cl 120	Fuga de aire x valvula	FUGA DE AIRE X VALVULA	13/10/2021		Corrective Order	WO Completed	Mule truck
687995	Mobile equipment	Reparacion de llanta	REPARACION DE LLANTA	13/10/2021		Corrective Order	WO Completed	Area
688017	Landcruiser DC	CAMBIO LUCES CORTA	NO FUNCIONAN	13/10/2021		Corrective Order	WO Completed	Pickup truck
688025	Caterpillar 426f2 Backhoe	Manguera rota	MANGUERA ROTA	13/10/2021		Corrective Order	WO Completed	Backhoe
688028	Landcruiser DC	Cambio de 4 llanta	CAMBIO DE 4 LLANTA	13/10/2021		Corrective Order	WO Completed	Pickup truck
688132	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	14/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
688133	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	14/10/2021	12668 hrs	PM Orders	WO Completed	Generator
688134	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	14/10/2021		PM Orders	WO Completed	Generator
688136	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	14/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
688149	Landcruiser DC	revisión de suspensión	REVISIÓN DE SUSPENSIÓN	14/10/2021		Corrective Order	WO Completed	Pickup truck
688150	Rented Light Vehicle	cx2615 Mantenimiento	MANTENIMIENTO PREVENTIVO(RETEN LVA179)	14/10/2021		Corrective Order	WO Completed	Area
688193	New Holland Lm 1745	MANGUERA HIDRAULICA ROTA	MANGUERA HIDRAULICA ROTA	14/10/2021		Corrective Order	WO Completed	Telehender
688196	Caterpillar DE88E0 58 kVa	FALLO POR ALTAS RPM	FALLO POR ALTAS RPM	14/10/2021	38230 horas	Corrective Order	WO Completed	Generator
688198	Hilux DC	MANTENIMIENTO CORRECTIVO	AMORTIGUADORES DEL, PLATOS DE SUSP INFERIORES, BANDAS, TUERCAS	14/10/2021		Corrective Order	WO Completed	Pickup truck
688199	Coaster	MANTENIMIENTO CORRECTIVO	TACOS, BUJES DE BRAZOS DE CONTROL, LINK, BUJES BARRA	14/10/2021		Corrective Order	WO Completed	Bus
688200	Landcruiser TC	REPARACION DE DIFERENCIAL TRAS	RETENEDORAS, TUERCA DE RUEDA	14/10/2021		Corrective Order	WO Completed	Pickup truck
688201	Landcruiser TC	MANTENIMIENTO CORRECTIVO	CORREAS ACC, ESCOBILLAS, BUJES, ESCOLTA	14/10/2021		Corrective Order	WO Completed	Pickup truck
688204	Caterpillar 14M Motorgrader	Revisión sistema AFEX	REVISIÓN SISTEMA AFEX	14/10/2021		Corrective Order	WO Completed	Grader
688220	Manitou Mht-X860 6t Telehand	Manguera Hidraulica rota	CAMBIO DE MANGUERA HIDRAULICA	14/10/2021	3,955.50 hrs	Corrective Order	WO Completed	Telehender
688263	Caterpillar CS74 Compactor	Advertencia de aire de motor a	ADVERTENCIA DE AIRE DE MOTOR A	14/10/2021		Corrective Order	WO Completed	Compactor
688271	Caterpillar 14M Motorgrader	Reemplazo de termostato	REEMPLAZO DE TERMOSTATO DEL MOTOR Y LIMPIEZA AL SISTEMA DE ENFRIAMIENTO.	14/10/2021		Corrective Order	WO Completed	Grader
688281	Freightliner Cl 120	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/10/2021		Corrective Order	WO Completed	Mule truck
688284	Gallegos Flatbed Trailer	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
688292	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/10/2021		Corrective Order	WO Completed	Bus
688303	Coaster Bus	REPARAR SISTEMA FRENO	TALLER DOLLAR	14/10/2021	50017067	Corrective Order	WO Completed	Bus
688323	Freightliner Columbia Cl112	1 LLANTA FLAT + A/A	1 LLANTA FLAT + A/A	14/10/2021		Corrective Order	WO Completed	Mule truck
688355	Hyster H70ft 3t Forklift (M)	cambio de palanca de freno	CAMBIO DE PALANCA DE FREN	14/10/2021	90015271	Corrective Order	WO Completed	Forklift
688382	JLG 450 AJ Manlift	reparacion de mangueras	REPARACION DE MANGUERAS	14/10/2021		Corrective Order	WO Completed	Manlift
688392	Caterpillar 416F2 Backhoe	Neumático delantero bajo d	NEUMÁTICO DELANTERO BAJO D	14/10/2021		Corrective Order	WO Completed	Backhoe
688451	SJS SJ6530	ajuste de tornillería	AJUSTE DE TORNILLERIA	14/10/2021		Corrective Order	WO Completed	Compactor
688454	Hilux DC	cambio de llanta	CAMBIO DE LLANTA	14/10/2021		Corrective Order	WO Completed	Pickup truck
688502	Hilux DC	TIRE AND RING INSPECT/CHANGE	CAMBIO 04 LLANTAS	14/10/2021		Corrective Order	WO Completed	Pickup truck
688526	Caterpillar DE88E0 58 kVa	CAMBIO BOMBA AGUA	FUGA DE AGUA	14/10/2021	38649 horas	Corrective Order	WO Completed	Generator
688587	Terex RT670 64TON	Instalacion de rolo ajustador	INSTALACION DE ROLO AJUSTADOR DE CARRETE	14/10/2021		Corrective Order	WO Completed	Crane/Hoist
688588	Freightliner M112 Truck Tip	Neumático Flat	NEUMÁTICO FLAT	14/10/2021		Corrective Order	WO Completed	Tipper
688605	Caterpillar 416F2 Backhoe	Arranque auxiliar	ARRANQUE DE EQUIPO	14/10/2021		Corrective Order	WO Completed	Backhoe
688615	Freightliner Columbia Cl112	Revision de equipo	REEMPLAZO DE LLANTA	14/10/2021		Corrective Order	WO Completed	Mule truck
688656	Caterpillar 416F2 Backhoe	Reemplazo de llanta	REEMPLAZO DE LLANTA	14/10/2021		Corrective Order	WO Completed	Backhoe
688676	Hino Serie 300 Box Truck	Cambio de 4 llantas	CAMBIO DE 4 LLNTAS	14/10/2021		Corrective Order	WO Completed	Truck
688682	WT015 H7 CISTERNA SINOTRUK	Problema con los cambios	PROBLEMA CON LOS CAMBIOS	14/10/2021		Corrective Order	WO Completed	Water truck
688701	Caterpillar 416F2 Backhoe	Engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Backhoe
688702	Caterpillar 426F2 Backhoe	Engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Backhoe
688706	Caterpillar 426f2 Backhoe	Engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Backhoe
688707	Caterpillar 426f2 Backhoe	Engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Backhoe
688708	Caterpillar 307E Miniexcavator	Engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Excavator
688709	Caterpillar 236d Skid Steer L	engrase general	ENGRASE GENERAL	14/10/2021		Corrective Order	WO Completed	Skid Steer
688710	Caterpillar 320DL	engrase general	ENGRASE GNERAL	14/10/2021		Corrective Order	WO Completed	Excavator
688712	Manitou Mht-X1490 9t Telehand	Llanta flat	LLANTA FLAT	14/10/2021		Corrective Order	WO Completed	Telehender
688718	BT024 M2-106 FREIGHTLINER	Revisión suspensión trasera	REVISIÓN SUSPENSIÓN TRASERA	14/10/2021		Corrective Order	WO Completed	.
688728	Hilux DC	Inspección para acceso Pit	INSPECCIÓN PARA ACCESO PIT	14/10/2021		Corrective Order	WO Completed	Pickup truck
688729	Light Vehicles	CT-3982 Acceso Pit	CT-3982 ACCESO PIT	14/10/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
688733	Hilux DC	REVISION GENERAL	PITO DE REVERSA, H4	15/10/2021		Corrective Order	WO Completed	Pickup truck
688734	Hilux DC	ALARMA DE REVERSA	CAMBIO DE PITO DE REVERSA	15/10/2021		Corrective Order	WO Completed	Pickup truck
688745	Coaster	REVISION DE SUSPENSION	CAMBIO BUJES DE BARRA ESTABILIDAD	15/10/2021		Corrective Order	WO Completed	Bus
688746	Coaster	AUXILIO DE ARRANQUE REACTIVOS	CAMBIO DE BATERIA	15/10/2021		Corrective Order	WO Completed	Bus
688747	Hilux DC	REVISION DE PITO DE REVERSA	CAMBIO DE PITO DE REVERSA	15/10/2021		Corrective Order	WO Completed	Pickup truck
688748	Coaster	REVISION SIST DE CARGA	CAMBIO DE BATERIA	15/10/2021		Corrective Order	WO Completed	Bus
688749	Hiace Bus	MANTENIMIENTO CORRECTIVO	REPARACIONES VARIAS	15/10/2021		Corrective Order	WO Completed	Bus
688750	Coaster Bus	RESCATE EN CAMPAMENTO	CAMBIAR BALINERAS DE CENTRO/EJE POSTERIOR	15/10/2021		Corrective Order	WO Completed	Bus
688806	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	15/10/2021	CERRADO PLANEAMIENTO SIN DATA	PM Orders	WO Completed	Generator
688819	Pramac GSW30P 24KVA	MOVIMIENTO DE GENERADOR	MOVIMIENTO DE GENERADOR	15/10/2021	SOPORTE W41	Corrective Order	WO Completed	Generator
688915	Intraax 53121 Hendrickso	1 LLANTA FLATEADA	1 LLANTA FLATEADA	15/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
688935	ETNYRE QUAD	No le abren las compuertas	NO LE ABREN LAS COMPUERTAS	15/10/2021		Corrective Order	WO Completed	Chip Spreader
688944	Gallegos 28M3 Lime Tank	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
688987	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Bus
688990	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
688993	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
688994	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
688997	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
688999	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
689003	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
689005	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
689044	Landcruiser DC	Cambio de freno de mano	CAMBIO DE CABLE DEL FRENO DE MANO	15/10/2021	94,167 Kms	Corrective Order	WO Completed	Pickup truck
689047	Hilux DC	Cambio de muelles	CAMBIO DE MUELLES	15/10/2021	689047 Kms	Corrective Order	WO Completed	Pickup truck
689052	Landcruiser DC	Cambio de cilindros	CAMBIO DE CILINDROS, PASADORES ,CALIPER Y AMORTIGUADOR	15/10/2021	66,827 kms	Corrective Order	WO Completed	Pickup truck
689055	Landcruiser DC	Cambio de brazo	CAMBIO DE BRAZO DE SUSPENSION	15/10/2021	94,167 Kms	Corrective Order	WO Completed	Pickup truck
689056	Landcruiser DC	Cambio de caliper	CAMBIO DE CALIPER Y KIT DE EMBRAGUE	15/10/2021	38,958 kms	Corrective Order	WO Completed	Pickup truck
689058	Hilux DC	Cambio de caliper	CAMBIO DE CALIPER Y KIT DE EMBRAGUE	15/10/2021	38,958 kms	Corrective Order	WO Completed	Pickup truck
689059	Landcruiser DC	Cambio de conjunto	CAMBIO DE CONJUNTO DE RUEDA LIBRE	15/10/2021	58,356 kms	Corrective Order	WO Completed	Pickup truck
689060	Landcruiser DC	Cambio de componentes	LINK ASSY/LH COASTER	15/10/2021	17,923 kms	Corrective Order	WO Completed	Pickup truck
689061	Coaster	Cambio de componentes	LINK ASSY/LH COASTER	15/10/2021	17,923 kms	Corrective Order	WO Completed	Bus
689072	Landcruiser DC	Cambio de amortiguadores	CAMBIO DE AMORTIGUADORES	15/10/2021	64,447 kms	Corrective Order	WO Completed	Pickup truck
689074	Landcruiser DC	Instalacion de radiador	INSTALACION DE RADIADOR	15/10/2021	69,433 kms	Corrective Order	WO Completed	Pickup truck
689077	Landcruiser TC	Mant preventivo	MANT. PREVENTIVO	15/10/2021		Corrective Order	WO Completed	Pickup truck
689079	Landcruiser TC	Cambio de ajustadores	CAMBIO DE AJUSTADORES DE FRENOS	15/10/2021	46,009	Corrective Order	WO Completed	Pickup truck
689082	Hilux DC	cambio de bomba	CAMBIO DE BOMBA DE POWER STEERING	15/10/2021	58,178 kms	Corrective Order	WO Completed	Pickup truck
689083	Coaster	Reparacion de direccion	REPARACION DE DIRECCION	15/10/2021	31,052 kms	Corrective Order	WO Completed	Bus
689084	Hilux DC	Reparacion de frenos	REPARACION DE FRENOS	15/10/2021	8,346 kms	Corrective Order	WO Completed	Pickup truck
689086	Landcruiser DC	Reparacion de frenos	REPARACION DE FRENOS	15/10/2021	57,685 kms	Corrective Order	WO Completed	Pickup truck
689088	Hilux DC	Reparacion de transmision	REPARACION DE TRANSMISION	15/10/2021	41,669 kms	Corrective Order	WO Completed	Pickup truck
689091	Landcruiser TC	Reparacion de suspension	REPARACION DE SUSPENSION DEL AUTO	15/10/2021	22,431 kms	Corrective Order	WO Completed	Pickup truck
689094	Hilux DC	cambio de parabrisas	CAMBIO DE PARABRISAS	15/10/2021	25,174 kms	Corrective Order	WO Completed	Pickup truck
689097	Landcruiser DC	cambio de parabrisas	CAMBIO DE PARABRISAS	15/10/2021	38,575 kms	Corrective Order	WO Completed	Pickup truck
689101	Hilux DC	Cambio de muelles	CAMBIO DE MUELLES DE SUSPENSION	15/10/2021	36,704 kms	Corrective Order	WO Completed	Pickup truck
689105	Internation F2674	Revision de equipo	SUMINISTRO DE TAPONES METALICOS	15/10/2021		Corrective Order	WO Completed	Boom truck
689112	Landcruiser DC	Cambio de sensor	CAMBIO DE SENSOR DE VELOCIDAD	15/10/2021	65,498 kms	Corrective Order	WO Completed	Pickup truck
689120	Hilux DC	Reparacion de suspension	REPARACION DE SUSPENSION	15/10/2021	47,976 kms	Corrective Order	WO Completed	Pickup truck
689122	Hilux DC	Cambio de muelles	CAMBIO DE MUELLES	15/10/2021	40,447 kms	Corrective Order	WO Completed	Pickup truck
689125	Hilux DC	Revision de equipo	ENGRASE E INSTALACION DE EXTINTOR	15/10/2021	30.584 kms	Corrective Order	WO Completed	Pickup truck
689131	Landcruiser DC	Revision de equipo	REPARACION DE W/W. CAMBIO DE FRENO DE MANO.	15/10/2021	62,977 kms	Corrective Order	WO Completed	Pickup truck
689134	Landcruiser DC	Reparacion de A/C	REPARACION DE A/C	15/10/2021	67,509 kms	Corrective Order	WO Completed	Pickup truck
689135	Internation F2674	repracion y cambio de vastago	FUGA POR CILINDRO DE LEVANTE	15/10/2021		Corrective Order	WO Completed	Boom truck
689136	Landcruiser DC	Cambio de poleas	CAMBIO DE POLEA DEL MOTOR Y ALARMA DE RETROCESO	15/10/2021	49.011 kms	Corrective Order	WO Completed	Pickup truck
689139	Landcruiser DC	cambio de crucetas	CAMBIO DE CRUCETAS Y EJES	15/10/2021	67.059 kms	Corrective Order	WO Completed	Pickup truck
689140	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTA	15/10/2021		Corrective Order	WO Completed	Pickup truck
689143	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/10/2021		Corrective Order	WO Completed	Pickup truck
689145	Landcruiser TC	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/10/2021		Corrective Order	WO Completed	Pickup truck
689146	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/10/2021		Corrective Order	WO Completed	Pickup truck
689148	Ford F550	cambio de valvula PTO	CAMBIO DE VALVULA DE PTO	15/10/2021		Corrective Order	WO Completed	Pickup truck
689149	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	15/10/2021		Corrective Order	WO Completed	Pickup truck
689153	Landcruiser DC	Revision de equipo	REEMPLAZO DE LLANTA	15/10/2021		Corrective Order	WO Completed	Pickup truck
689189	Coaster	Cambio de correas	CAMBIO DE CORREAS	15/10/2021	48,165 kms	Corrective Order	WO Completed	Bus
689190	Landcruiser DC	Cambio de perdiga	CAMBIO DE PERDIGA	15/10/2021	45,521 kms	Corrective Order	WO Completed	Pickup truck
689191	Landcruiser TC	cambio de parabrisas	CAMBIO DE PARABRISAS	15/10/2021	71,420 kms	Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
689192	Landcruiser DC	Revision de equipo	CAMBIO DE CABLE DE FRENO, CAMBIO DE SPRING Y TAPON DE TRANSMISION.	15/10/2021 60,674 kms		Corrective Order	WO Completed	Pickup truck
689193	Landcruiser DC	cambio de parabrisas	CAMBIO DE PARABRISAS	15/10/2021 79,604 kms		Corrective Order	WO Completed	Pickup truck
689195	Hilux DC	Cambio de muelles	CAMBIO DE MUELLES	15/10/2021 29,284 kms		Corrective Order	WO Completed	Pickup truck
689197	Hilux DC	Cambio de lampara	CAMBIO DE LAMPARA	15/10/2021 13,425 kms		Corrective Order	WO Completed	Pickup truck
689199	Hilux DC	cambio de hojas de muelle	CAMBIO DE HOJAS DE MUELLE	15/10/2021 71,615 kms		Corrective Order	WO Completed	Pickup truck
689201	Landcruiser TC	Revision de equipo	REPARACION DE FRENOS, REPARACION DE DIRECCION.	15/10/2021 75,564 kms		Corrective Order	WO Completed	Pickup truck
689204	Landcruiser DC	Cambio de muelles	CAMBIO DE MUELLES	15/10/2021 99,435 kms		Corrective Order	WO Completed	Pickup truck
689210	Caterpillar TL1055CLRC	cambio de manguera	FUGA DE ACEITE HIDRAULICO	15/10/2021		Corrective Order	WO Completed	Telehender
689242	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	15/10/2021		Corrective Order	WO Completed	Bus
689244	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	15/10/2021		Corrective Order	WO Completed	Pickup truck
689246	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	15/10/2021		Corrective Order	WO Completed	Pickup truck
689405	MAGNUM Light Tower	CORRECTIVO	LAVADO DE RADIADOR Y DESMONTAJE DE BOMBA DE AGUA Y POLEA	15/10/2021 27551 hrs		Corrective Order	WO Completed	Light Tower
689435	MAGNUM Light Tower	CAMBIO BOMBA AGUA	CAMBIO ALTERNADOR DC	15/10/2021 27551 horas		Corrective Order	WO Completed	Light Tower
689439	John Deere 9370R Tractor	Reemplazo de bombillos	REEMPLAZO DE BOMBILLOS	15/10/2021		Corrective Order	WO Completed	Tractor
689485	Caterpillar D110 E2 100KVA	CAMBIO SELLO CARTER	CAMBIO BASE FILTRO	15/10/2021 15014		Corrective Order	WO Completed	Generator
689492	Grove RT650E 45TON	Instalación de extirntor	INSTALACIÓN DE EXTIRNTOR	15/10/2021		Corrective Order	WO Completed	Crane/Hoist
689493	Grove GMK4100L 100TON	Instalación de extintor	INSTALACIÓN DE EXTINTOR	15/10/2021		Corrective Order	WO Completed	Crane/Hoist
689496	Mobile equipment	Insumos Para Taller	INSUMOS PARA TALLER	15/10/2021		Corrective Order	WO Completed	Area
689509	Hino Serie 300 Box Truck	MANTENIMIENTO AIRE ACONDICIONA	LIMPIEZA DE EVAPORADOR, GAS REFRIGERANTE	15/10/2021		Corrective Order	WO Completed	Truck
689510	Landcruiser TC	REPARACION SIST AIRE ACONDICI	CAMBIO DE EVAPORADOR, CARGA DE GAS REFRIGERANTE	15/10/2021		Corrective Order	WO Completed	Pickup truck
689511	Hilux DC	MANTENIMIENTO PREVENTIVO	OIL & FILTER REPLACEMEN, INSPECTION	15/10/2021		Corrective Order	WO Completed	Pickup truck
689514	Hilux DC	REVISION DE LUCES	CAMBIO DE H4	15/10/2021		Corrective Order	WO Completed	Pickup truck
689603	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	16/10/2021 26143 horas		PM Orders	WO Completed	Generator
689643	Caterpillar 236d Skid Steer L	Llanta roza con cabima	LLANTA ROZA CON CABIMA	16/10/2021		Corrective Order	WO Completed	Skid Steer
689644	Caterpillar RM500 Reclaimer	fuga de producto por bomba	FUGA DE PRODUCTO POR BOMBA	16/10/2021		Corrective Order	WO Completed	Road Reclaimer
689645	Ford F550	A/C INSPECTION & REPAIR	NO ENFRIA	16/10/2021		Corrective Order	WO Completed	Pickup truck
689646	Caterpillar 426F2 Backhoe	Luz delantera defectuosa	LUZ DELANTERA DEFECTUOSA	16/10/2021		Corrective Order	WO Completed	Backhoe
689649	Tool Trucks	ca8655 llanta flat	CA8655 LLANTA FLAT	16/10/2021		Corrective Order	WO Completed	Area
689658	Freightliner M112 Truck Tip	El brazo del espejo retrovisor	EL BRAZO DEL ESPEJO RETROVISOR	16/10/2021		Corrective Order	WO Completed	Tipper
689687	Landcruiser TC	INSPECCION GENERAL EQUIPO	INCIDENTE EN MINA	16/10/2021		Corrective Order	WO Completed	Pickup truck
689700	Freightliner M2 106 Hydroseedi	Reemplazo de llanta	REPARACION DE LLANTA	16/10/2021		Corrective Order	WO Completed	Truck
689703	Caterpillar 320DL	No e funciona la bocina (pito)	NO E FUNCIONA LA BOCINA (PITO)	16/10/2021		Corrective Order	WO Completed	Excavator
689775	Power Curbers 5700-C	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/10/2021		Corrective Order	WO Completed	Kerb Machine
689786	Randon SR-SI-TV-03-27 Lime Tan	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689809	Randon SR-SI-TV-03-27 Lime Tan	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689811	Landcruiser TC	Reemplazo de llanta	REEMPLAZO DE LLANTA	16/10/2021		Corrective Order	WO Completed	Pickup truck
689814	Landcruiser DC	Reemplazo de llanta	REEMPLAZO DE LLANTA	16/10/2021		Corrective Order	WO Completed	Pickup truck
689818	Hilux DC	Reemplazo de llanta	REPARACION DE LLANTA	16/10/2021		Corrective Order	WO Completed	Pickup truck
689823	Gallegos 28M3 Lime Tank	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689827	Mobile equipment	confeccion de mangueras	CONFECACION DE MANGUERAS	16/10/2021		Corrective Order	WO Completed	Area
689830	Gallegos 28M3 Lime Tank	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689833	Mobile equipment	cambio de llanta	CAMBIO DE LLANTA	16/10/2021		Corrective Order	WO Completed	Area
689838	Gallegos 28M3 Lime Tank	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689846	Gallegos Lime Tank	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689849	Gallegos Lime Tank	INSPECCION Y ENGRASE	EVALUACION MECANICA	16/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
689854	Freightliner Columbia CI112	cambio de 4 llantas	LLANTAS EN MAL ESTADO	16/10/2021		Corrective Order	WO Completed	Mule truck
689870	Caterpillar 740b Ej	cambio de sensores y oring	CAMBIO DE SENSORES Y ORING	16/10/2021		Corrective Order	WO Completed	Articulated dump truck
689871	Hino Dutro 300	cambio de baterias	CAMBIO DE BATERIAS	16/10/2021		Corrective Order	WO Completed	Truck
689976	Bomag BW24RH	PM PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/10/2021		Corrective Order	WO Completed	Roller PTR
689983	Freightliner M112 Truck Tip	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/10/2021 30,006.70 km		Corrective Order	WO Completed	Tipper
689990	Freightliner M112 Truck Tip	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	16/10/2021		Corrective Order	WO Completed	Tipper
690014	Freightliner CI 120	PM MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITE Y FILTRO	16/10/2021		Corrective Order	WO Completed	Mule truck
690015	Caterpillar 740B EJ ADT	presion baja de aceite motor	PRESION BAJA DE ACEITE DE MOTOR	16/10/2021		Corrective Order	WO Completed	Articulated dump truck
690048	Caterpillar 226b Skid Steer L	instalacion de implemento	INSTALACION DE IMPLEMENTO	16/10/2021		Corrective Order	WO Completed	Skid Steer
690049	SJS SJ6530	INSPECCION Y ENGRASE	INSPECCION Y ENGRASE	16/10/2021		Corrective Order	WO Completed	Compactor
690093	Case 110JX Tractor Cable Handl	cambio de 1 llanta	LLANTA FLAT DAÑADA	16/10/2021		Corrective Order	WO Completed	Tractor
690121	Caterpillar 336DL	tensado de cadena	CADENA FLOJA EL EQUIPO PRESENTA SISTEMA DE RODAJE DETERIORADO	16/10/2021		Corrective Order	WO Completed	Excavator
690130	Caterpillar DE165E0 165 kVa	PM1 CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021 17764 HORAS		PM Orders	WO Completed	Generator
690131	Caterpillar D110 E2 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021 17950 horas		PM Orders	WO Completed	Generator
690132	Caterpillar DE110E 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021 22555 horas		PM Orders	WO Completed	Generator
690134	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021 14667 horas		PM Orders	WO Completed	Generator
690135	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021 13335 HRS		PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
690136	PRAMAC GSW460V 460 kVa	PM1 PRA GSW460V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	28376 horas	PM Orders	WO Completed	Generator
690137	Caterpillar C9 250 kVa	PM1 CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	21145 horas	PM Orders	WO Completed	Generator
690138	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	19591 horas	PM Orders	WO Completed	Generator
690139	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	15814 horas	PM Orders	WO Completed	Generator
690140	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	13228 hrs	PM Orders	WO Completed	Generator
690141	SDMO J30U 38KVA	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	9668 horas	PM Orders	WO Completed	Generator
690142	PRAMAC GSW65 48 kVa	PM1 PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	26128 horas	PM Orders	WO Completed	Generator
690143	SDMO T11UM 10KVA	PM1 SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	18495 hors	PM Orders	WO Completed	Generator
690144	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	17362 horas	PM Orders	WO Completed	Generator
690145	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	25801 horas	PM Orders	WO Completed	Generator
690147	SDMO T16 16KVA	PM1 SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	25008 horas	PM Orders	WO Completed	Generator
690148	PRAMAC GSW30Y 24 kVa	PM1 PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	23139 horas	PM Orders	WO Completed	Generator
690150	DOOSAND 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	25754 hrs	PM Orders	WO Completed	Light Tower
690167	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	11491 hrs	Corrective Order	WO Completed	Generator
690175	General Mobile MLT3060K	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	16/10/2021	5187 hrs	Corrective Order	WO Completed	Light Tower
690177	Bell 225f 4t Forklift (M)	Revision de sistema hidraulico	REVISION DE SISTEMA HIDRAULICO	16/10/2021	456.3 Hrs	Corrective Order	WO Completed	Forklift
690178	Caterpillar 12M	Fuga de aceite	FUGA DE ACEITE	16/10/2021		Corrective Order	WO Completed	Grader
690186	Freightliner M2 106 Sucker Tru	Revision de falla electrica	REVISION DE FALLA ELECTRICA - NO ARRANCA	16/10/2021		Corrective Order	WO Completed	Sucker truck
690201	Hilux DC	CAMBIO DE 2 LLANTAS	CAMBIO DE 2 LLANTAS	16/10/2021		Corrective Order	WO Completed	Pickup truck
690202	Hilux DC	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	16/10/2021		Corrective Order	WO Completed	Pickup truck
690354	Mobile equipment	Telehandler de Molinos alquila	FALLA ELECTRICA	17/10/2021		Corrective Order	WO Completed	Area
690355	New Holland Lm 1745	Fuga de aceite hidráulico	FUGA DE ACEITE HIDRAÚLICO	17/10/2021		Corrective Order	WO Completed	Telehender
690356	Freightliner Columbia CI112	Equipo no enciende	EQUIPO NO ENCIENDE	17/10/2021		Corrective Order	WO Completed	Mule truck
690357	Atlas Copco GESAN QIS 45 47KVA	PM1 ATL QIS45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	17/10/2021	6425 horas	PM Orders	WO Completed	Generator
690426	Freightliner M2 106	Tiene problemas con luces tras	TIENE PROBLEMAS CON LUCES TRAS	17/10/2021		Corrective Order	WO Completed	Bitumen truck
690427	Freightliner M2 106	Le hace falta espejo retroviso	LE HACE FALTA ESPEJO RETROVISIO	17/10/2021		Corrective Order	WO Completed	Bitumen truck
690428	Caterpillar 416F2 Backhoe	Llanta trasera izquierda baja	LLANTA TRASERA IZQUIERDA BAJA	17/10/2021		Corrective Order	WO Completed	Backhoe
690429	Caterpillar 416F2 Backhoe	Freno de parking dañado	FRENO DE PARKING DAÑADO	17/10/2021		Corrective Order	WO Completed	Backhoe
690463	Cargador 966H Wheel Loader	No sirve la bocina	NO SIRVE LA BOCINA	17/10/2021		Corrective Order	WO Completed	Loader
690481	Freightliner M2 106 Hydroseedi	cambio de filtros	EQUIPO PIERDE FUERZA	17/10/2021	41865 kms	Corrective Order	WO Completed	Truck
690547	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690549	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690552	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690558	PRAMAC GSW90P 74 kVa	CORRECTIVO	INSTALACION DE CARGADOR DE BATERIA	17/10/2021	26143 hrs	Corrective Order	WO Completed	Generator
690603	Unimog Service Truck	Revision de equipo	INSTALACION DE CORREAS	17/10/2021		Corrective Order	WO Completed	Truck
690630	Caterpillar TL642	TA1 INSPECCION MECANICA	EQUIPO IASA	17/10/2021		Corrective Order	WO Completed	Telehender
690667	Unimog Service Truck	REP DE LUCES INTERMITENTES	REP DE LUCES INTERMITENTES	17/10/2021		Corrective Order	WO Completed	Truck
690671	Tennant T7 Scrubber	INSP. GENERAL	EQUIPO INOPERATIVO/ NO ENCIENDE	17/10/2021	213.00 hrs	Corrective Order	WO Completed	Scrubber / Sweeper
690679	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	65.7 hrs	PM Orders	WO Completed	Generator
690680	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	8258 hrs	PM Orders	WO Completed	Generator
690681	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	10422 hrs	PM Orders	WO Completed	Generator
690682	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	16809 hrs	PM Orders	WO Completed	Generator
690683	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	839 hrs	PM Orders	WO Completed	Generator
690684	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	9764 hrs	PM Orders	WO Completed	Generator
690685	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	16485 hrs	PM Orders	WO Completed	Generator
690691	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	16084 hrs	PM Orders	WO Completed	Generator
690692	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	8644 hrs	PM Orders	WO Completed	Generator
690693	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	3633 hrs	PM Orders	WO Completed	Generator
690694	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	581 hrs	PM Orders	WO Completed	Generator
690695	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	361 horas	PM Orders	WO Completed	Generator
690696	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	11272 horas	PM Orders	WO Completed	Generator
690697	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	160 horas	PM Orders	WO Completed	Generator
690702	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021	25132 hrs	PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
690703	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021 18056 hrs		PM Orders	WO Completed	Generator
690706	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	17/10/2021 539 hrs		PM Orders	WO Completed	Generator
690752	Hyster J40zt	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690755	Hyster E50Z-27 FORKLIFT	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690756	Hyster H70ft 3t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690758	Hyster H800 32t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 698.00 hrs		Corrective Order	WO Completed	Forklift
690760	Hyster H300 13t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 5,921.00 hrs		Corrective Order	WO Completed	Forklift
690761	Hyster H300 Forklift	CAMBIO DE 4 NEUMATICOS	CORRECTIVO	17/10/2021		Corrective Order	WO Completed	Forklift
690762	Hyster H300 Forklift	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690763	Hyster H700 Forklift	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690764	Hyster H700 Forklift	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690765	John Deere 9370R Tractor	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 1,378.00 hrs		Corrective Order	WO Completed	Tractor
690767	John Deere 9370R Tractor	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Tractor
690768	Hyster E70xn 3t Forklift (E)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 2,099.00 hrs		Corrective Order	WO Completed	Forklift
690769	Hyster E70xn 3t Forklift (E)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690771	Hyster E70xn 3t Forklift (E)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 2,367.00 hrs		Corrective Order	WO Completed	Forklift
690772	Hyster E70xn 3t Forklift (E)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690773	Hyster H300 13t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690774	Hyster H300 13t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 3,470.00 hrs		Corrective Order	WO Completed	Forklift
690775	Hyster H800 32t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 1,293.00 hrs		Corrective Order	WO Completed	Forklift
690776	Hyster H800 32t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690777	Hyster H70ft 3t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Forklift
690778	Hyster H70ft 3t Forklift (M)	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021 404.00 hrs		Corrective Order	WO Completed	Forklift
690779	John Deere 9370R Tractor	INSPECCION Y ENGRASE	EQUIPO COPAMA	17/10/2021		Corrective Order	WO Completed	Tractor
690781	John Deere 9370R Tractor	PM01 MANTENIMIENTO PREVENTIVO	COPAMA	17/10/2021		Corrective Order	WO Completed	Tractor
690784	Freightliner Columbia Cl112	cambio de base de pollera	CAMBIO DE BASE, REPARACION	17/10/2021		Corrective Order	WO Completed	Mule truck
690803	Caterpillar 12M	Fuga de coolant	FUGA DE COOLANT	17/10/2021		Corrective Order	WO Completed	Grader
690818	USP&E GP700/V-A 700 kVa	LLAMADA DE EMERGENCIA	FALLO AL CERRAR EL BRAKE	17/10/2021 11180 hrs		Corrective Order	WO Completed	Generator
690832	Caterpillar 236d Skid Steer L	Cambio de 2 llantas	CAMBIO DE 2 LLANTAS	17/10/2021		Corrective Order	WO Completed	Skid Steer
690835	Caterpillar 236d Skid Steer L	pinos de Balde Ausentes	PINES DE BALDE AUSENTES	17/10/2021		Corrective Order	WO Completed	Skid Steer
690837	Gallegos 28M3 Lime Tank	Llanta flat	LLANTA FLAT	17/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
690838	Grove GMK4100L 100TON	Falla electrica	FALLA ELECTRICA	17/10/2021		Corrective Order	WO Completed	Crane/Hoist
690840	Hilux DC	PERTIGA Y BANDERIN PERDIDOS	INSTALACION PERTIGA NUEVA	17/10/2021		Corrective Order	WO Completed	Pickup truck
690841	Hilux DC	REPARACION DE SUSPENSION	PLATOS DE SUSPENSION, BUJES, CRUCETAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690842	Hilux DC	CAMBIO DE MUELLES	MUELLES ROTOS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690858	Hilux DC	REVISION RUIDO TRACCION DELANT	CAMBIO EJE FLECHA RH	17/10/2021		Corrective Order	WO Completed	Pickup truck
690859	Hilux DC	MANTENIMIENTO PREVENTIVO	OIL & FILTER REPLACEMEN, INSPECTION	17/10/2021		Corrective Order	WO Completed	Pickup truck
690860	Hilux DC	REVISION AIRE ACONDICIONADO	FALLAS EN COMPRESOR, CAMBIO DE COMPRESOR	17/10/2021		Corrective Order	WO Completed	Pickup truck
690861	Hilux DC	CAMBIO DE REGULADOR DE VENTANA	CAMBIO DE REGULADOR DE VENTANA FR RH	17/10/2021		Corrective Order	WO Completed	Pickup truck
690862	Landcruiser DC	REVISION AIRE ACONDICIONADO	CAMBIO DE EVAPORADOR, VALVULA EXPANSION	17/10/2021		Corrective Order	WO Completed	Pickup truck
690863	Ford F550	REVISION AIRE ACONDICIONADO	REPARACION TOMA DE CALEFACCION	17/10/2021		Corrective Order	WO Completed	Pickup truck
690864	Landcruiser DC	REVISION DE FRENOS	CAMBIO DE AJUSTADOR RH	17/10/2021		Corrective Order	WO Completed	Pickup truck
690865	Landcruiser DC	MANTENIMIENTO PREVENTIVO	PASADO 2000KM DE PM, RETENEDORA DIF DELANTERO	17/10/2021		Corrective Order	WO Completed	Pickup truck
690867	Landcruiser DC	CAMBIO DE MUELLE LH	MUELLE PARTIDO	17/10/2021		Corrective Order	WO Completed	Pickup truck
690868	Landcruiser DC	CAMBIO DE MUELLES, BUJES, BASE	PROBLEMAS SUSPENSION TRASERA	17/10/2021		Corrective Order	WO Completed	Pickup truck
690869	Hilux DC	REPARACION PUERTA DE VAGON	CAMBIO CERRADURA RH PUERTA DE VAGON	17/10/2021		Corrective Order	WO Completed	Pickup truck
690870	Landcruiser DC	REVISION SIST AIRE ACONDICIONAD	CAMBIO EVAPORADOR, VALVULA EXPANSION, CARGA DE GAS REFRIGERANTE	17/10/2021		Corrective Order	WO Completed	Pickup truck
690871	Landcruiser DC	MANTENIMIENTO PREVENTIVO	PASADO 2647KM DE PM	17/10/2021		Corrective Order	WO Completed	Pickup truck
690872	Landcruiser TC	REVISION SUSPENSION TRASERA	CAMBIO DE MUELLE LH, GRAPAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690873	Landcruiser TC	REVISION DE SISTEMA DE FRENOS	CAMBIO DE PORTABANDAS, BANDAS Y COMPONENTES INTERNOS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690874	Hilux DC	REVISION SUSPENSION TRASERA	CAMBIO DE MUELLES Y GRAPAS	17/10/2021		Corrective Order	WO Completed	Pickup truck
690999	Caterpillar DE88E0 58 kVa	FALLO POR BAJA PRESION FUEL	LLAMADA DE EMERGENCIA	18/10/2021 38321 horas		Corrective Order	WO Completed	Generator
691035	BT014 M2-112 Freightliner	Cambio de las siguientes parte	CAMBIO DE LAS SIGUIENTES PARTE	18/10/2021		Corrective Order	WO Completed	.
691057	Freightliner M112 Truck Tip	Tapa de Power Steering no apri	TAPA DE POWER STEERING NO APRI	18/10/2021 29,723.4 kms		Corrective Order	WO Completed	Tipper
691065	Gallegos 28M3 Lime Tank	1 LLANTA FLATEADA	1 LLANTA FLATEADA	18/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
691089	Freightliner M2 106	Reemplazo de baterias	REEMPLAZO DE BATERIAS - TERMINALES DE BATERIA DANADOS	18/10/2021		Corrective Order	WO Completed	Bitumen truck
691090	Manitou Mht-X1490 9t Telehand	LLANTAS BAJAS DE AIRE	LLANTAS BAJAS DE AIRE	18/10/2021		Corrective Order	WO Completed	Telehender
691092	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	18/10/2021		Corrective Order	WO Completed	Pickup truck
691093	Manitou Mht-X860 6t Telehand	FILL DE ACEITE HIDRAULICO	FILL DE ACEITE HIDRAULICO	18/10/2021		Corrective Order	WO Completed	Telehender
691136	Manitou MTH-X 10120	telehandler en malas condicione	TELEHANDER EN MALAS CONDICIONE	18/10/2021		Corrective Order	WO Completed	Telehender
691137	Hyster H300 13t Forklift (M)	cambio de aceite de transmisiso	CAMBIO DE ACEITE DE TRANSMISIO	18/10/2021		Corrective Order	WO Completed	Forklift

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
691138	Hyster H800 32t Forklift (M)	bajo nivel de aceite	BAJO NIVEL DE ACEITE	18/10/2021		Corrective Order	WO Completed	Forklift
691152	Gallegos Flatbed Trailer	cambio de copa	CAMBIO DE COPA	18/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
691155	Phoenix MK7T	Revision de equipo	REVISION DEL SISTEMA HIDRAULICO	18/10/2021		Corrective Order	WO Completed	Chip Spreader
691209	Caterpillar 320DL	engrase y rellenado de aceite	ENGRASE Y RELLENADO DE ACEITE	18/10/2021		Corrective Order	WO Completed	Excavator
691220	New Holland Lm 1745	reparacion de base de retrovis	REPARACION DE BASE DE RETORVISOR	18/10/2021		Corrective Order	WO Completed	Telehender
691264	Landcruiser DC	cambio de 2 llantas	CAMBIO DE 2 LLANTAS	18/10/2021		Corrective Order	WO Completed	Pickup truck
691292	Pramac GSW25P 17KVA	REPARAR GENERADOR AC	TALLER EMBOBINADOS NACIONALES	18/10/2021	4946 horas	Corrective Order	WO Completed	Generator
691297	Caterpillar 740B EJ ADT	fuga hidraulica	FUGA HIDRAULICA	18/10/2021		Corrective Order	WO Completed	Articulated dump truck
691378	Caterpillar 12M	Reemplazo de hojas de corte	REEMPLAZO DE HOJAS DE CORTE	18/10/2021		Corrective Order	WO Completed	Grader
691382	Coaster	CAMBIO DE LLANTAS Y TUERCAS	CAMBIO DE LLANTAS Y TUERCAS	18/10/2021		Corrective Order	WO Completed	Bus
691387	Caterpillar 140K	Reemplazo de hojas de corte	REEMPLAZO DE HOJAS DE CORTE	18/10/2021		Corrective Order	WO Completed	Grader
691408	Boom Truck Iveco Tector	Reparacion de bomba de alta	REPARACION DE BOMBA DE ALTA PRESION DE COMBUSTIBLE	18/10/2021		Corrective Order	WO Completed	Boom truck
691435	Gallegos 28M3 Lime Tank	reparacion de llanta	1 LLANTA FLAT	18/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
691458	LB002 725 CAT	cambio de tuberia de escape	TUBO DE ESCAPE ROTO	18/10/2021		Corrective Order	WO Completed	Truck
691475	Hilux DC	REVISION DE LUCES	CAMBIO DE H4, PITO DE REVERSA	18/10/2021		Corrective Order	WO Completed	Pickup truck
691476	Unimog Service Truck	Falla con los cambios	FALLA CON LOS CAMBIOS DE MARCHA	18/10/2021		Corrective Order	WO Completed	Truck
691477	Hilux DC	CAMBIO DE LAMPARAS TRASERAS	LAMPARAS QUEBRADAS	18/10/2021		Corrective Order	WO Completed	Pickup truck
691478	Hilux DC	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	18/10/2021		Corrective Order	WO Completed	Pickup truck
691479	Landcruiser DC	CAMBIO DE BUJES Y ESPACIADORES	BUJES DE BARRA TRANSVERSAL	18/10/2021		Corrective Order	WO Completed	Pickup truck
691480	Landcruiser DC	CAMBIO FILTRO DE COMBUSTIBLE	CAMBIO FILTRO DE COMBUSTIBLE	18/10/2021		Corrective Order	WO Completed	Pickup truck
691481	PB013 COASTER TOYOTA	REVISION GENERAL	CAMBIO FILTRO DE COMBUSTIBLE	18/10/2021		Corrective Order	WO Completed	Bus
691811	Mobile equipment	Insumos	INSUMOS	19/10/2021		Corrective Order	WO Completed	Area
691835	Caterpillar 236d Skid Steer L	Base Rota	BASE DEL COMPRESOR ROTA	19/10/2021		Corrective Order	WO Completed	Skid Steer
691837	Caterpillar 320DL	Cambio de V/V por fuga hidraul	CAMBIO DE V/V POR FUGA HIDRAUL	19/10/2021		Corrective Order	WO Completed	Excavator
691839	Manitou Mht-X1490 9t Telehand	Llanta flat	LLANTA CON CLAVO	19/10/2021		Corrective Order	WO Completed	Telehender
691841	Manitou Mht-X860 6t Telehand	Falla eléctrica,	FALLA ELÉCTRICA, NOO ENCIENDE, ERROR 777 POR CONFIGURACIÓN	19/10/2021		Corrective Order	WO Completed	Telehender
691866	Caterpillar 12M	Reemplazo de Cuchillas	REEMPАЗO DE CUCHILLAS	19/10/2021		Corrective Order	WO Completed	Grader
691890	PB056 BLUEBIRD INTERNATIONAL	Reparación de sistema de	REPARACIÓN DE SISTEMA DE	19/10/2021		Corrective Order	WO Completed	.
691952	International 7400 SBA Fire Tr	AIRE ACONDICIONADO Y ESCOBILLA	REPARACIÓN DEL A/A Y CAMBIO DE ESCOBILLA	19/10/2021	90015880	Corrective Order	WO Completed	Fire truck
691964	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	19/10/2021		Corrective Order	WO Completed	Pickup truck
691987	Landcruiser DC	cambio de escobilla	CAMBIO DE ESCOBILLA	19/10/2021		Corrective Order	WO Completed	Pickup truck
691988	Caterpillar CS533E Compactor	A/C no funciona	A/C NO FUNCIONA	19/10/2021		Corrective Order	WO Completed	Compactor
692005	Caterpillar RM300	REEMPLAZAR MONITOR	REEMPLAZAR MONITOR	19/10/2021	60023685/ PKG-10008007	Corrective Order	WO Completed	Road Reclaimer
692032	Hyster H300 Forklift	NEUMATICO TRASERO FLAT DER	NEUMATICO TRASERO FLAT DER	19/10/2021		Corrective Order	WO Completed	Forklift
692061	Manitou Mht-X1490 9t Telehand	Reparar llanta Trasera Izq	REPARAR LLANTA TRASERA IZQ	19/10/2021		Corrective Order	WO Completed	Telehender
692100	Freightliner M2 106 Hydroseedi	FILTRO DE TRANSMISIÓN	CAMBIO DE FILTRO DE TRANSMISIÓN	19/10/2021		Corrective Order	WO Completed	Truck
692227	Grove RT600E 50TON	Engrase del Cable	ENGRASE DEL CABLE	19/10/2021		Corrective Order	WO Completed	Crane/Hoist
692231	Grove RT880E 75TON	A/A,FRENO DE GIRO, SE NEUTRALI	A/A,FRENO DE GIRO, SE NEUTRALIZA	19/10/2021		Corrective Order	WO Completed	Crane/Hoist
692244	Caterpillar 14M Motorgrader	CAMBIO DE COMPONENTES	BACKLOG 18 OCTUBRE IASA	19/10/2021	90015728	Corrective Order	WO Completed	Grader
692260	Landcruiser DC	Mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	19/10/2021		Corrective Order	WO Completed	Pickup truck
692261	Hilux DC	revisi3ne de freno	REVISIONE DE FRENO	19/10/2021		Corrective Order	WO Completed	Pickup truck
692262	Hino Dutro 300	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	19/10/2021		Corrective Order	WO Completed	Truck
692263	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	19/10/2021		Corrective Order	WO Completed	Pickup truck
692264	Landcruiser DC	revision de frenos	REVISION DE FRENOS	19/10/2021		Corrective Order	WO Completed	Pickup truck
692267	Caterpillar 236d Skid Steer L	Reparacion de fuga HYD	REPARACION DE FUGA HIDRAULICA	19/10/2021	90016247 90016248	Corrective Order	WO Completed	Skid Steer
692269	Gallegos Flatbed Trailer	reparacion de llantas	LLANTA FLAT	19/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
692412	Gallegos Flatbed Trailer	ajuste de frenos	FRENOS DESAJUSTADOS	20/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
692470	Landcruiser DC	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	20/10/2021		Corrective Order	WO Completed	Pickup truck
692471	Landcruiser DC	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	20/10/2021		Corrective Order	WO Completed	Pickup truck
692477	Coaster Bus	reparacion de llanta	LLANTA FLAT	20/10/2021	78,495.00 km	Corrective Order	WO Completed	Bus
692478	Freightliner M2 106 Refrigerat	soldadura de Plat. de elevacio	SOLDADURA DE PLATAFORMA DE ELEVACION ROTA	20/10/2021		Corrective Order	WO Completed	Refrigerator truck
692479	Freightliner Columbia CI112	cambio de llanta	LLANTA FLAT	20/10/2021		Corrective Order	WO Completed	Mule truck
692523	Freightliner Columbia CI112	FLAT TIRE	FLAT TIRE	20/10/2021		Corrective Order	WO Completed	Mule truck
692535	Intraax 53121 Hendrickso	1 LLANTA FLATEADA	1 LLANTA FLATEADA	20/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
692551	Intraax 53121 Hendrickso	1 LLANTA FLATEADA + FUGA	1 LLANTA FLATEADA + FUGA	20/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
692668	Caterpillar 740b Ej	C/SELLOS B/B HYD HOIST+STERING	FUGAS	20/10/2021		Corrective Order	WO Completed	Articulated dump truck
692733	Caterpillar 14M Motorgrader	Bajo nivel de coolant	BAJO NIVEL DE COOLANT Y CAMBIO DE HOJA DE CORTE	20/10/2021		Corrective Order	WO Completed	Grader
692866	Hyster H700 Forklift	ALARMA DE REVERSA	ALARMA DE REVERSA	20/10/2021		Corrective Order	WO Completed	Forklift
692918	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	EQUIPO PARADO	20/10/2021	13173 hoas	Corrective Order	WO Completed	Generator
692963	Mercedes Tipper Truck	EQUIPO SE BLOQUEO	EQUIPO SE BLOQUEA	20/10/2021		Corrective Order	WO Completed	Tipper
692965	Caterpillar 426F2 Backhoe	REPARACIÓN DE NEUMÁTICO	REPARACIÓN DE NEUMÁTICO	20/10/2021		Corrective Order	WO Completed	Backhoe
692966	WT015 H7 CISTERNA SINOTRUK	LUZ DE AVERTENCIA ACTIVA	LUZ DE ADVERTENCIA ACTIVA	20/10/2021		Corrective Order	WO Completed	Water truck
692967	Hyster H70ft 3t Forklift (M)	CADENA ROTA	CADENA ROTA	20/10/2021		Corrective Order	WO Completed	Forklift
692968	Caterpillar 12M	NIVEL DE COOLANT	NIVEL DE COOLANT	20/10/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
692971	Caterpillar 236d Skid Steer L	Reparacion de A/C	REPARACION DE A/C	20/10/2021	4464 Hrs	Corrective Order	WO Completed	Skid Steer
692973	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	20/10/2021		Corrective Order	WO Completed	Bus
692974	PB012 COASTER TOYOTA	revision de a/c	A/C CON FALLA	20/10/2021		Corrective Order	WO Completed	Bus
692975	Landcruiser TC	cambio de correas	CORREAS EN MAL ESTADO	20/10/2021		Corrective Order	WO Completed	Pickup truck
692977	Landcruiser DC	reparacion de cable abs	ABS EN MAL ESTADO	20/10/2021		Corrective Order	WO Completed	Pickup truck
692978	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	20/10/2021		Corrective Order	WO Completed	Pickup truck
692979	Landcruiser DC	cambio de bombillos	BOMBILLOS QUEMADOS	20/10/2021		Corrective Order	WO Completed	Pickup truck
692980	Hilux DC	cambio de bateria	BATERIA EN MAL ESTADO	20/10/2021		Corrective Order	WO Completed	Pickup truck
692982	Coaster Bus	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	20/10/2021		Corrective Order	WO Completed	Bus
693096	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/10/2021	10324 horas	PM Orders	WO Completed	Generator
693097	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/10/2021	12668 horas	PM Orders	WO Completed	Generator
693110	Hilux DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	21/10/2021		Corrective Order	WO Completed	Pickup truck
693113	Mobile equipment	cambio de llantas	CAMBIO DE LLANTAS	21/10/2021		Corrective Order	WO Completed	Area
693129	Gallegos Flatbed Trailer	cambio de 1 llanta	LLANTA EN MAL ESTADO	21/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
693133	Caterpillar DE88E0 58 kVa	LLMADA DE EMERGENCIA	AJUSTE DE RPM Y FRECUENCIA	21/10/2021	38396 hrs	Corrective Order	WO Completed	Generator
693140	Caterpillar 236d Skid Steer L	ajuste de guardas flojas	GUARDAS FLOJAS	21/10/2021	2,790.40 hrs	Corrective Order	WO Completed	Skid Steer
693143	Caterpillar 740b Ej	C/SENSOR PRES CONVERTIDOR	SENSOR EN MAL ESTADO	21/10/2021		Corrective Order	WO Completed	Articulated dump truck
693168	Bomag BW24RH	Neumático bajo de aire	NEUMÁTICO BAJO DE AIRE	21/10/2021		Corrective Order	WO Completed	Roller PTR
693196	Caterpillar 12M	Aire Acondicionado no funciona	AIRE ACONDICIONADO NO FUNCIONA	21/10/2021		Corrective Order	WO Completed	Grader
693221	Bomag BW219DH-4	Izaje de elemento	IZAJE DE TAMBOR PARA EXTRACCIÓN DE MOTOR DE VIBRACIÓN	21/10/2021	SOPORTE W42	Corrective Order	WO Completed	Compactor
693225	New Holland Lm 1745	IZAJE DE DIFERENCIAL	IZAJE DE DIFERENCIAL	21/10/2021	SOPORTE W42	Corrective Order	WO Completed	Telehender
693226	SJS SJ6530	IZAJE DE SISMICA	IZAJE DE SISMICA Y DESMONTE EN PATIO	21/10/2021	SOPORTE W42	Corrective Order	WO Completed	Compactor
693243	Caterpillar 416E	JOCKE Y MANGUERAS	CAMBIO DE JOCKE Y MANGUERAS HIDRÁULICAS	21/10/2021		Corrective Order	WO Completed	Backhoe
693394	Freightliner M2 112 Sucker Tru	cambio de pulmon y Luces	CAMBIO DE PULMÓN LUCES	21/10/2021		Corrective Order	WO Completed	Sucker truck
693399	Freightliner Columbia CI112	CAMBIO DE CORREA	CAMBIO DE CORREA	21/10/2021		Corrective Order	WO Completed	Mule truck
693416	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Completed	Pickup truck
693420	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Completed	Pickup truck
693423	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Completed	Pickup truck
693434	Landcruiser DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Completed	Pickup truck
693451	New Holland Lm 1745	Cambio de diferencial	CAMBIO DE DIFERENCIAL	21/10/2021		Corrective Order	WO Completed	Telehender
693460	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	21/10/2021		PM Orders	WO Completed	Pickup truck
693513	Hyster H300 Forklift	REPARACIÓN DE NEUMÁTICO	REPARACIÓN DE NEUMÁTICO	21/10/2021		Corrective Order	WO Completed	Forklift
693518	Intraax 53121 Hendrickso	LLANTA FLAT	LLANTA FLAT	21/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
693519	Freightliner Columbia CI112	TAPADERA DE LAMPARA	TAPADERA DE LAMPARA	21/10/2021		Corrective Order	WO Completed	Mule truck
693530	Hilux DC	cambio de bateria	CAMBIO DE BATERIA	21/10/2021		Corrective Order	WO Completed	Pickup truck
693531	Hilux DC	cambio de pertiga	PERTIGA QUEBRADA	21/10/2021		Corrective Order	WO Completed	Pickup truck
693532	Landcruiser TC	cambio de muelles	CAMBIO DE MUELLES	21/10/2021		Corrective Order	WO Completed	Pickup truck
693533	Hilux DC	reparacion de ac	REPARACION DE AC	21/10/2021		Corrective Order	WO Completed	Pickup truck
693534	Ford Hilux D/C Light Vehicle	reparacion de control de ven	REPARACION DE CONTROL DE VENTANA	21/10/2021		Corrective Order	WO Completed	Pickup truck
693536	Landcruiser DC	revision de a/c	REVISION DE A/C	21/10/2021		Corrective Order	WO Completed	Pickup truck
693537	Hilux DC	cambio de muelles	CAMBIO DE MUELLES	21/10/2021		Corrective Order	WO Completed	Pickup truck
693538	Hilux DC	instalacion de tiro	INSTALACION DE TIRO	21/10/2021		Corrective Order	WO Completed	Pickup truck
693540	Coaster	tuercas de freno	TUERCAS DE FRENO	21/10/2021		Corrective Order	WO Completed	Bus
693547	Caterpillar 14H Motorgrader	Reemplazo de baterias	REEMPLAZO DE BATERIAS	21/10/2021		Corrective Order	WO Completed	Grader
693630	Freightliner CI 120	cambio de cable de conexion	CABLE DE CONEXION EN MAL ESTADO	22/10/2021		Corrective Order	WO Completed	Mule truck
693634	Freightliner CI 120	cambio de cable de conexion	CABLE DE CONEXION DE REMOLQUE EN MAL ESTADO	22/10/2021		Corrective Order	WO Completed	Mule truck
693636	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	FALLA EN DISPLAY Y TARJETA REGULADORA	22/10/2021	13189 hrs	Corrective Order	WO Completed	Generator
693676	Freightliner M2 106 Refrigerat	cambio de condensador	CAMBIO DE CONDENSADOR	22/10/2021		Corrective Order	WO Completed	Refrigerator truck
693682	Mobile equipment	reparacion de llanta	REPARACION DE LLANTA UTILEV ALQUILADA MSA	22/10/2021		Corrective Order	WO Completed	Area
693683	Landcruiser DC	cambio de 4 llantas	CAMBIO DE 4 LLANTAS	22/10/2021		Corrective Order	WO Completed	Pickup truck
693691	Caterpillar 320DL	Mantiene el cilindro o pistón	MANTIENE EL CILINDRO O PISTÓN	22/10/2021		Corrective Order	WO Completed	Excavator
693692	Caterpillar 320DL	El sello del cilindro o pistó	EL SELLO DEL CILINDRO O PISTÓ	22/10/2021		Corrective Order	WO Completed	Excavator
693693	Caterpillar 416F2 Backhoe	Llanta trasera izquierda baja	LLANTA TRASERA IZQUIERDA BAJA	22/10/2021		Corrective Order	WO Completed	Backhoe
693700	Caterpillar 12M	A/C enfria poco	A/C ENFRIA POCO	22/10/2021		Corrective Order	WO Completed	Grader
693792	Freightliner CI 120	LLANTA BAJA	LLANTA BAJA	22/10/2021		Corrective Order	WO Completed	Mule truck
693865	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	22/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
693872	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	22/10/2021		Corrective Order	WO Completed	Mule truck
693874	Freightliner Columbia CI112	LLANTA FLAT	LLANTA FLAT	22/10/2021		Corrective Order	WO Completed	Mule truck
693880	Freightliner CI 120	A/c	A/C	22/10/2021		Corrective Order	WO Completed	Mule truck
693887	Freightliner Columbia CI112	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	22/10/2021		Corrective Order	WO Completed	Mule truck
693892	Caterpillar D6T Dozer	SISTEMA AFEX	SISTEMA AFEX	22/10/2021		Corrective Order	WO Completed	Dozer
694186	TTP-0000-102	CAMBIO DE PIN DE CADENA	CAMBIO DE PIN DE CADENA	22/10/2021		Corrective Order	WO Completed	Excavator
694210	Caterpillar 226b Skid Steer L	INSTALACIÓN DE VIDRIO FRONTAL	INSTALACIÓN DE VIDRIO FRONTAL	22/10/2021		Corrective Order	WO Completed	Skid Steer

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
694236	Grove GMK 4080 80TON		Calibración del PAD	CALIBRACIÓN DEL PAD EXTERNO	22/10/2021			Corrective Order	WO Completed	Crane/Hoist
694244	Hilux DC		cambio lampara trasera	CAMBIO LAMPARA TRASERA	22/10/2021			Corrective Order	WO Completed	Pickup truck
694245	Coaster		cambio de bandas y cilindros	REVISION DE FRENOS	22/10/2021			Corrective Order	WO Completed	Bus
694246	Landcruiser DC		cambio de bateria	CAMBIO DE BATERIA	22/10/2021			Corrective Order	WO Completed	Pickup truck
694247	Landcruiser DC		cambio de bandas y extintor	CAMBIO DE BANDAS Y EXTINTOR	22/10/2021			Corrective Order	WO Completed	Pickup truck
694248	Ford Hilux D/C Light Vehicle		cambio de pertiga y extintor	CAMBIO DE PERTIGA Y EXTINTOR	22/10/2021			Corrective Order	WO Completed	Pickup truck
694249	Landcruiser DC		cambio de aceites y filtros	CAMBIO DE ACEITES Y FILTROS	22/10/2021			Corrective Order	WO Completed	Pickup truck
694250	Hilux DC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	22/10/2021			Corrective Order	WO Completed	Pickup truck
694253	Freightliner Columbia C112		cambio de lamparas	LAMPRAS EN MAL ESTADO	22/10/2021			Corrective Order	WO Completed	Mule truck
694318	Manitou Mht-X860 6t Telehand		limpieza de filtro	ALARMA ACTIVA POR FILTRO SATURADO	23/10/2021			Corrective Order	WO Completed	Telehender
694364	Landcruiser DC		cambio de 1 llanta	LLANTA FLAT	23/10/2021			Corrective Order	WO Completed	Pickup truck
694403	ATR-0000-001 4+320 AGRICO		revision de sistema de a/c	REVISION DE SISTEMA DE A/C	23/10/2021			Corrective Order	WO Completed	Tractor
694406	Freightliner M2 106 Hydroseedi		Rectificado de 2 Ejes	RECTIFICADO DE 2 EJES	23/10/2021	2021W43		Corrective Order	WO Completed	Truck
694407	Caterpillar 416E		reparacion de llanta	LLANTA FLAT	23/10/2021			Corrective Order	WO Completed	Backhoe
694419	Caterpillar 416F2 Backhoe		No enciende	NO ENCIENDE	23/10/2021			Corrective Order	WO Completed	Backhoe
694424	Caterpillar CS74 Compactor		Luces traseras quemada	LUCES TRASERAS QUEMADA	23/10/2021			Corrective Order	WO Completed	Compactor
694428	Caterpillar CS74 Compactor		Revision de tablero	LUZ DE ADVERTENCIA EN EL TABL	23/10/2021			Corrective Order	WO Completed	Compactor
694433	Caterpillar PS-150C		Nivel de aceite hidráulico y m	NIVEL DE ACEITE HIDRÁULICO Y M	23/10/2021			Corrective Order	WO Completed	Roller PTR
694474	Caterpillar 320DL		cambio de cilindro bucket	EQUIPO IASA	23/10/2021	50017678		Corrective Order	WO Completed	Excavator
694552	Gallegos Lime Tank		INSPECCION Y ENGRASE	EVALUACION MECANICA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694566	Gallegos		INSPECCION Y ENGRASE	EVALUACION MECANICA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694569	Gallegos		INSPECCION Y ENGRASE	EVALUACION MECANICA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694571	Gallegos		INSPECCION Y ENGRASE	EVALUACION MECANICA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694572	Gallegos		INSPECCION Y ENGRASE	EVALUACION MECANICA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694582	Caterpillar 320DL		Se le cayó un casquillo	SE LE CAYÓ UN CASQUILLO	23/10/2021			Corrective Order	WO Completed	Excavator
694610	PRAMAC GSW90P 74 kVa		MANTENIMIENTO CORRECTIVO	CARGA DE BATERÍA DAÑADO	23/10/2021	22574 horas		Corrective Order	WO Completed	Generator
694654	Gallegos Flatbed Trailer		AJUSTE DE FRENO y soldadura	AJUSTE DE FRENO Y SOLDADURA	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694699	Landcruiser DC		CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694701	Hilux DC		CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694703	Hilux DC		CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694708	Hilux DC		CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694712	Hilux DC		CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694785	Hilux DC		CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694793	Caterpillar 336DL Excavator		Reemplazo de fusible de ignici	REEMPLAZO DE FUSIBLE DE IGNICIÓN	23/10/2021			Corrective Order	WO Completed	Excavator
694823	Gallegos Flatbed Trailer		Revision de luces	REVISION DE LUCES	23/10/2021			Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
694825	Hilux DC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694826	Landcruiser TC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694827	Bomag BW219DH-4		mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	23/10/2021			Corrective Order	WO Completed	Compactor
694828	Hilux DC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694829	Hilux DC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694830	Hilux DC		Reemplazo de llantas	REEMPLAZO DE LLANTAS	23/10/2021			Corrective Order	WO Completed	Pickup truck
694908	Landcruiser DC		cambio de terminales de direcc	CAMBIO DE TERMINALES DE DIRECC	24/10/2021			Corrective Order	WO Completed	Pickup truck
694910	Landcruiser TC		mantenimiento Evaporador	MANTENIMIENTO EVAPORADOR	24/10/2021			Corrective Order	WO Completed	Pickup truck
694912	Hilux DC		cambio de bateria	CAMBIO DE BATERIA	24/10/2021			Corrective Order	WO Completed	Pickup truck
694927	Landcruiser DC		mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	24/10/2021			Corrective Order	WO Completed	Pickup truck
694937	Landcruiser DC		mantenimiento correctivo	MANTENIMIENTO CORRECTIVO	24/10/2021			Corrective Order	WO Completed	Pickup truck
694938	Coaster Bus		cambio de balinera de centro	CAMBIO DE BALINERA DE CENTRO	24/10/2021			Corrective Order	WO Completed	Bus
694939	Hilux DC		mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	24/10/2021			Corrective Order	WO Completed	Pickup truck
694940	Hilux DC		cambio de bateria y recarga de	CAMBIO DE BATERIA Y RECARGA DE GAS DE A/C	24/10/2021			Corrective Order	WO Completed	Pickup truck
694942	Hilux DC		mantenimeinto preventivo	MANTENIMIENTO PREVENTIVO	24/10/2021			Corrective Order	WO Completed	Pickup truck
694943	Hilux DC		cambio de muelles	CAMBIO DE MUELLES	24/10/2021			Corrective Order	WO Completed	Pickup truck
694944	Hilux DC		cambio de lampara trasera	CAMBIO DE LAMPARA TRASERA	24/10/2021			Corrective Order	WO Completed	Pickup truck
694946	Caterpillar DE88E0 58 kVa		LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	24/10/2021	38463 hrs		Corrective Order	WO Completed	Generator
694948	USP&E GP700/V-A 700 kVa		CORRECTIVO	LIMPIEZA Y REPARACION DE FUGA	24/10/2021	8644 hrs		Corrective Order	WO Completed	Generator
694986	Caterpillar 236d Skid Steer L		Acelarador	ACELARADOR	24/10/2021			Corrective Order	WO Completed	Skid Steer
694991	New Holland Lm 1745		Revision de niveles	REVISION DE NIVELES	24/10/2021			Corrective Order	WO Completed	Telehender
694994	Caterpillar CS74 Compactor		Display en cortocircuito	DISPLAY EN CORTOCIRCUITO	24/10/2021	90016463		Corrective Order	WO Completed	Compactor
695006	SJS SJ6530		Inst. de eje de ruedas	INST. DE EJE DE RUEDAS	24/10/2021			Corrective Order	WO Completed	Compactor
695064	Grove RT600E 50TON		LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION EQUIPO	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695069	Grove RT650E 45TON		LUBRICACION CABLES,POLEAS,BOOM	LUBRICACION EQUIPO	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695085	Mack Trucks GU		INFORMACION DE GRUA	LEVANTAMIENTO DE INFORMACION	24/10/2021			Corrective Order	WO Completed	Boom truck
695087	Freightliner FL112		LEVANTAMIENTO INFO GRUA	INFORMACION DE GRUA	24/10/2021			Corrective Order	WO Completed	Boom truck
695105	ETNYRE QUAD		Manguera hidraulica rota	MANGUERA HIDRAULICA ROTA	24/10/2021			Corrective Order	WO Completed	Chip Spreader
695111	Caterpillar DP50 Forklift (M)		PM2-MANTENIMIENTO PREVENTIVO	EQUIPO IASA	24/10/2021	90016078		Corrective Order	WO Completed	Forklift
695117	Caterpillar DP50 Forklift (M)		PM2-MANTENIMIENTO PREVENTIVO	EQUIPO IASA	24/10/2021			Corrective Order	WO Completed	Forklift
695157	Caterpillar D110 E2 100KVA		PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	18923 hrs		PM Orders	WO Completed	Generator
695159	Caterpillar C9 250 kVa		PM1 CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	20629horas		PM Orders	WO Completed	Generator
695160	SDMO J60U 60 kVa		PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	7288 hrs		PM Orders	WO Completed	Generator

Order Number	Asset Number	Description	Or Ty Description	Problem	Order Date	Status	Comment	W.O. Type Description	WO St Description	Cat 02 Description
695161	SDMO J60U 60KVA		PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	13637 horas		PM Orders	WO Completed	Generator
695162	SDMO J30U 38 kVa		PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	13727 horas		PM Orders	WO Completed	Generator
695163	Caterpillar DE88E0 58 kVa		PM1 CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	38649 horas		PM Orders	WO Completed	Generator
695164	Olympian GEP18-6 18KVA		PM1 OLY GEP 18-6 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	29890 horas		PM Orders	WO Completed	Generator
695168	DOOSAND 1005		PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	24/10/2021	25551 horas		PM Orders	WO Completed	Light Tower
695178	Grove RT880E 75TON		INSPECCION TECNICA MANIITOWOC	LUBRICACION EQUIPO	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695205	Grove RT600E 50TON		INSPECCION TECNICA MANIITOWOC	PERSONAL TECNOGRUA	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695207	Grove RT650E 45TON		INSPECCION TECNICA MANIITOWOC	EQUIPO TECNOGRUA	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695215	Grove RT890 90TON		INSPECCION TECNICA MANIITOWOC	EQUIPO TECNOGRUA	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695222	Terex RT5551 55TON		INSPECCION TECNICA MANIITOWOC	EQUIPO TECNOGRUA	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695225	Grove RT600E 50TON		INSPECCION TECNICA MANIITOWOC	INSPECCION TECNICA MANIITOWOC	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695227	Grove RT600E 50TON		INSPECCION TECNICA MANIITOWOC	EQUIPO TECNOGRUA	24/10/2021			Corrective Order	WO Completed	Crane/Hoist
695238	Olympian GEP150 135 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	65 hrs		PM Orders	WO Completed	Generator
695239	PRAMAC GSW170I 164 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	8258 hrs		PM Orders	WO Completed	Generator
695240	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	10422 hrs		PM Orders	WO Completed	Generator
695241	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	10809 hrs		PM Orders	WO Completed	Generator
695242	PRAMAC GSW110 82 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	839 horas		PM Orders	WO Completed	Generator
695243	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	9774 horas		PM Orders	WO Completed	Generator
695244	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	16487 horas		PM Orders	WO Completed	Generator
695245	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	16084 hrs		PM Orders	WO Completed	Generator
695246	USP&E GP700/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	8644 horas		PM Orders	WO Completed	Generator
695247	SDMO J60U 60KVA		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	3633 horas		PM Orders	WO Completed	Generator
695248	SDMO J60U 60KVA		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	581 horas		PM Orders	WO Completed	Generator
695249	PRAMAC GSW110 82 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	361 hrs		PM Orders	WO Completed	Generator
695250	USP&E GP700/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	11491		PM Orders	WO Completed	Generator
695251	PRAMAC GSW45 35 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	160 horas		PM Orders	WO Completed	Generator
695253	PRAMAC GSW90P 74 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	26144 horas		PM Orders	WO Completed	Generator
695254	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	25132 HORAS		PM Orders	WO Completed	Generator
695256	USP&E GP700S/V-A 700 kVa		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	18056 HORAS		PM Orders	WO Completed	Generator
695281	SDMO J60U 60KVA		INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	24/10/2021	685 HORAS		PM Orders	WO Completed	Generator
695290	Hyster J40zt		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695292	Hyster E50Z-27 FORKLIFT		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695297	Unimog Service Truck		PM y Alarma de retroceso	PM , ALARMA DE RETROCESO, CAMBO DE RETENEDORA	24/10/2021			Corrective Order	WO Completed	Truck
695300	Hyster E70xn 3t Forklift (E)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695303	Hyster E70xn 3t Forklift (E)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695304	Hyster E70xn 3t Forklift (E)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695309	Hyster H300 13t Forklift (M)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695310	Hyster H800 32t Forklift (M)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695348	Hyster H300 Forklift		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695349	Hyster E70xn 3t Forklift (E)		LIMPIEZA Y ENGRASE DE CADENAS	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695352	Tennant S30 Sweeper		INSPECCION EQUIPO	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Scrubber / Sweeper
695356	Tennant S30 Sweeper		INSPECCION DE EQUIPO	INSPECCION DE EQUIPO	24/10/2021			Corrective Order	WO Completed	Scrubber / Sweeper
695365	Tennant T7 Scrubber		INSPECCION DE EQUIPO	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Scrubber / Sweeper
695376	Hyster H700 Forklift		INSPECCION Y ENGRASE	EQUIPO COPAMA	24/10/2021			Corrective Order	WO Completed	Forklift
695403	Freightliner M2 106 Sucker Tru		No Arranca	NO TIENE LUCES DE CABINA, NO ARRANCA	24/10/2021			Corrective Order	WO Completed	Sucker truck
695434	Hilux DC		cambio de 4 llantas mas repues	CAMBIO DE 4 LLANTAS MAS REPUESTOS	24/10/2021			Corrective Order	WO Completed	Pickup truck
695453	Mobile equipment		reparacion de llanta	REPARACION DE LLANTA DE EQUIPO NO LISTADO	24/10/2021			Corrective Order	WO Completed	Area
695582	Expert Power PN45 10KVA		PM1 EXP PN45 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	25/10/2021	9378 horas		PM Orders	WO Completed	Generator
695583	Caterpillar D110 E2 100KVA		PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	25/10/2021	19334 hrs		PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
695604	Landcruiser DC	reparacion de ventana	REPARACION DE VENTANA	25/10/2021		Corrective Order	WO Completed	Pickup truck
695605	Landcruiser TC	inspeccion de engrase	INSPECCION DE ENGRASE	25/10/2021		Corrective Order	WO Completed	Pickup truck
695606	Hino Dutro 300	ajuste y engrase de balinera	AJUSTE Y ENGRASE DE BALINERA	25/10/2021		Corrective Order	WO Completed	Truck
695608	Hiace Bus	ajuste de barra de torsion	AJUSTE DE BARRA DE TORSION	25/10/2021		Corrective Order	WO Completed	Bus
695609	Hilux DC	cambio de pertiga y pito de re	CAMBIO DE PERTIGA Y PITO DE REVERSA	25/10/2021		Corrective Order	WO Completed	Pickup truck
695610	Landcruiser DC	cambio de amortiguadores	CAMBIO DE AMORTIGUADORES, BASE DE MUELLE Y GRAPA	25/10/2021		Corrective Order	WO Completed	Pickup truck
695611	PB013 COASTER TOYOTA	reparacion de bomba de vacio,	REPARACION DE BOMBA DE VACIO, CAMBIO DE BASE DE TRANSMISION Y CAMBIO DE LAMPARA	25/10/2021		Corrective Order	WO Completed	Bus
695612	Coaster	cambio de bateria	CAMBIO DE BATERIA	25/10/2021		Corrective Order	WO Completed	Bus
695613	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	25/10/2021		Corrective Order	WO Completed	Pickup truck
695620	New Holland Lm 1745	ajuste de filtro de diesel	FUGA DE COMBUSTIBLE	25/10/2021		Corrective Order	WO Completed	Telehender
695621	Phoenix MK7T	revision de funcionamiento	FAJA NO ACTIVA	25/10/2021		Corrective Order	WO Completed	Chip Spreader
695665	Manitou Mht-X1490 9t Telehand	Izaje de equipo	IZAJE EN MOLINO Y DESCARGA EN TALLER	25/10/2021	SOPORTE W43	Corrective Order	WO Completed	Telehender
695671	Mobile equipment	Acoples y Mangueras	ACOPLES Y MANGUERAS	25/10/2021		Corrective Order	WO Completed	Area
695684	Caterpillar 336DL	No tiene la válvula manual	NO TIENE LA VÁLVULA MANUAL	25/10/2021		Corrective Order	WO Completed	Excavator
695739	Gallegos 28M3 Lime Tank	LINEA TRANCADA	LINEA TRANCADA	25/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
695740	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	25/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
695765	Hyster H300 13t Forklift (M)	llanta flat	LLANTA FLAT	25/10/2021		Corrective Order	WO Completed	Forklift
695801	Freightliner Cl 120	FUGA DE AIRE	FUGA DE AIRE	25/10/2021		Corrective Order	WO Completed	Mule truck
695817	Caterpillar 740B EJ ADT	740B-L4E-MAINTENANCE 1000HRS	740B-L4E-MAINTENANCE 1000HRS	25/10/2021	PM6	PM proposal JDE	WO Completed	Articulated dump truck
695853	PRAMAC GSW90P 74 kVa	INSPECCION DE EQUIPO	CARGADOR DE BATERÍA	25/10/2021	26144 HORAS	Corrective Order	WO Completed	Generator
695936	Freightliner Columbia Cl112	SOLDADURA BASE EXTINTOR	SOLDADURA	25/10/2021		Corrective Order	WO Completed	Mule truck
695942	Freightliner Columbia Cl112	DESAJUSTE CLOTCH / ENGRASE	DESAJUSTE CLOTCH / ENGRASE	25/10/2021		Corrective Order	WO Completed	Mule truck
696002	Atlas Copco Hilight V4W	CAMBIO CABLE LUMINARIAS	CAMBIO FOCOS	25/10/2021	4269 horas	Corrective Order	WO Completed	Light Tower
696018	Caterpillar DE165E0 165 kVa	LLAMADA DE EMERGENCIA	LAVADO DE RADIADOR	25/10/2021	17640 horas	Corrective Order	WO Completed	Generator
696041	New Holland Lm 1745	TERMINAL DE DIRECCIÓN ROTO	TERMINAL DE DIRECCIÓN ROTO	25/10/2021		Corrective Order	WO Completed	Telehender
696048	Mobile equipment	Cambio de 4 llantas	LLANTAS EN MAL ESTADO	25/10/2021		Corrective Order	WO Completed	Area
696050	Gallegos Lime Tank	Cambio de estabilizadores	ESTABILIZADORES EN MAL ESTADO	25/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
696065	SJS SJ6530	Cambio de tornillos	TORNILLOS FLOJOS Y PERDIDOS	25/10/2021		Corrective Order	WO Completed	Compactor
696122	Landcruiser TC	cambio de faja y bombillos	CAMBIO DE FAJA Y BOMBILLOS	25/10/2021		Corrective Order	WO Completed	Pickup truck
696123	PB013 COASTER TOYOTA	cambio de baterías y bornes	CAMBIO DE BATERIAS Y BORNES	25/10/2021		Corrective Order	WO Completed	Bus
696124	Landcruiser DC	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	25/10/2021		Corrective Order	WO Completed	Pickup truck
696125	Hilux DC	mantenimiento Preventivo	MANTENIMIENTO PREVENTIVO	25/10/2021		Corrective Order	WO Completed	Pickup truck
696379	Valle Grande Nursery Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	26/10/2021		PM Orders	WO Completed	Building
696380	Valle Grande Geology Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	26/10/2021		PM Orders	WO Completed	Building
696381	Valle Grande Environment Offic	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	26/10/2021		PM Orders	WO Completed	Building
696382	Valle Grande Archeology Office	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	26/10/2021		PM Orders	WO Completed	Building
696443	Caterpillar 236d Skid Steer L	rellenado de aceite de hidra	BAJO NIVEL DE ACEITE HIDRAULICO	26/10/2021		Corrective Order	WO Completed	Skid Steer
696445	Gallegos 28M3 Lime Tank	Cambio de retenedora	CAMBIO DE RETENEDORA	26/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
696447	Ford F550	cambio de muñequilla	CAMBIO DE MUÑEQUILLA	26/10/2021		Corrective Order	WO Completed	Pickup truck
696492	BT014 M2-112 Freightliner	Confección de manguera	CONFECCIÓN DE MANGUERA	26/10/2021		Corrective Order	WO Completed	.
696549	Caterpillar D110 E2 110 kVa	FALLO DE ARRANQUE	LLAMADA DE EMERGENCIA	26/10/2021	17950 horas	Corrective Order	WO Completed	Generator
696575	Caterpillar C4.4 88KVA	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	26/10/2021	30167 horas	Corrective Order	WO Completed	Generator
696607	Cargador 966H Wheel Loader	INSPECCION DE MANGUERAS HIDRA	INSPECCION Y CAMBIO	26/10/2021		Corrective Order	WO Completed	Loader
696612	Caterpillar 12M	Luces delanteras en corto	LUCES DELANTERAS EN CORTO	26/10/2021		Corrective Order	WO Completed	Grader
696623	Caterpillar CS74 Compactor	Bajo nivel de refrigerante	BAJO NIVEL DE REFRIGERANTE	26/10/2021	1557hm	Corrective Order	WO Completed	Compactor
696657	WT015 H7 CISTERNA SINOTRUK	CAMBIO DE 2 LLANTAS	CAMBIO DE 2 LLANTAS	26/10/2021		Corrective Order	WO Completed	Water truck
696702	Hilux DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	26/10/2021		Corrective Order	WO Completed	Pickup truck
696703	Hilux DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	26/10/2021		Corrective Order	WO Completed	Pickup truck
696745	Freightliner Columbia Cl112	Cambio de flexible	CAMBIO DE FLEXIBLE	26/10/2021		Corrective Order	WO Completed	Mule truck
696751	Freightliner Columbia Cl112	Instalación de placa	INSTALACIÓN DE PLACA	26/10/2021		Corrective Order	WO Completed	Mule truck
696752	Caterpillar 226b Skid Steer L	Luces traseras no funcionan	LUCES TRASERAS NO FUNCIONAN	26/10/2021		Corrective Order	WO Completed	Skid Steer
696754	Freightliner M2 106 Sucker Tru	Luces traseras no apagan	LUCES TRASERAS NO APAGAN	26/10/2021		Corrective Order	WO Completed	Sucker truck
696806	Freightliner Columbia Cl112	LLANTA BAJA	LLANTA BAJA	26/10/2021		Corrective Order	WO Completed	Mule truck
696819	Freightliner Cl 120	Instalación de placas	INSTALACIÓN DE PLACAS	26/10/2021		Corrective Order	WO Completed	Mule truck
696826	Freightliner Cl 120	Instalacion de nueva placa	INSTLACION DE NUEVA PLACA	26/10/2021		Corrective Order	WO Completed	Mule truck
696831	Freightliner M112 Truck Tip	Reparación de 2 llantas	REPARACIÓN DE 2 LLANTAS	26/10/2021		Corrective Order	WO Completed	Tipper
696845	Freightliner Cl 120	AJUSTE DE FRENOS	AJUSTE DE FRENOS	26/10/2021		Corrective Order	WO Completed	Mule truck
696855	JLG 800 AJ Manlift	Equipo neutrailizado	EQUIPO NEUTRAILIZADO	26/10/2021		Corrective Order	WO Completed	Manlift
696876	Hilux DC	CAMBIO DE 4 NEUMÁTICO	CAMBIO DE 4 NEUMÁTICOS	26/10/2021		Corrective Order	WO Completed	Pickup truck
696879	Hilux DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	26/10/2021		Corrective Order	WO Completed	Pickup truck
696881	Mobile equipment	Manómetros para taller	MANOMETROS PARA TALLER	26/10/2021		Corrective Order	WO Completed	Area
696889	DOOSAN 1005	LLAMADA DE EMERGENCIA	EQUIPO PARADO	26/10/2021	20302 horas	Corrective Order	WO Completed	Light Tower
697037	Pit Operations Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	27/10/2021		PM Orders	WO Completed	Building
697038	Logistic and Transport Area 22	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	27/10/2021	Requiere limpieza	PM Orders	WO Completed	Building
697039	Heliport Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	27/10/2021	Se requiere reparaciones WO.	PM Orders	WO Completed	Building
697040	General Mod Quad Buildings	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	27/10/2021	Requiere reparacion WO.	PM Orders	WO Completed	Building

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
697041	Security Checkpoint Gold Room	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	27/10/2021		PM Orders	WO Completed	Building
697058	DOOSAND 1005	LLAMADA DE EMERGENCIA	CAMBIO DE CORREA	27/10/2021	37663 horas	Corrective Order	WO Completed	Light Tower
697091	Caterpillar 12M	Reparación de Luces	REPARACIÓN DE LUCES	27/10/2021	90016424	Corrective Order	WO Completed	Grader
697132	Caterpillar D110 E2 110 kVa	FALLO DE CARGA 12 VOLTIOS	BATERIA DESCARGADA, REVISION ELECTRICA	27/10/2021	17954 horas	Corrective Order	WO Completed	Generator
697176	BT014 M2-112 Freightliner	REV. ELECTRICA	REV. ELECTRICA	27/10/2021		Corrective Order	WO Completed	.
697182	Freightliner M2 106 Refrigerat	Cambio de batería	CAMBIO DE BATERÍA	27/10/2021		Corrective Order	WO Completed	Refrigerator truck
697187	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	27/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
697189	Gallegos Lime Tank	POLLERA	POLLERA	27/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
697198	Caterpillar 12M	Bajo nivel de aceite hidráulic	BAJO NIVEL DE ACEITE HIDRÁULIC	27/10/2021		Corrective Order	WO Completed	Grader
697199	Mobile equipment	No funcionan las luces	NO FUNCIONAN LAS LUCES	27/10/2021		Corrective Order	WO Completed	Area
697207	Caterpillar 14H Motorgrader	Bajo nivel de aceite hidráulic	BAJO NIVEL DE ACEITE HIDRÁULIC	27/10/2021		Corrective Order	WO Completed	Grader
697235	Freightliner Cl 120	revision de a/c	REVISION DE A/C	27/10/2021		Corrective Order	WO Completed	Mule truck
697238	Freightliner Columbia Cl112	LUCES / RETORVISORES	LUCES / RETORVISORES	27/10/2021		Corrective Order	WO Completed	Mule truck
697276	ETNYRE QUAD	Manguera de liberar las compue	MANGUERA DE LIBERAR LAS COMPUE	27/10/2021		Corrective Order	WO Completed	Chip Spreader
697278	Caterpillar 416F2 Backhoe	No arranca	NO ARRANCA	27/10/2021		Corrective Order	WO Completed	Backhoe
697292	Freightliner M2 106 Truck	Equipo no enciende	CAMBIO DE FILTRO DE COMBUSTIBLE	27/10/2021		Corrective Order	WO Completed	Boom truck
697398	Freightliner Cl 120	AIRE ACONDICIONADO	AIRE ACONDICIONADO	27/10/2021		Corrective Order	WO Completed	Mule truck
697407	Hyster H300 13t Forklift (M)	Reparacion de neumatico	REPARACION DE NEUMATICO	27/10/2021		Corrective Order	WO Completed	Forklift
697437	Freightliner Columbia Cl112	FUGA DE AIRE	FUGA DE AIRE	27/10/2021		Corrective Order	WO Completed	Mule truck
697440	Freightliner Cl 120	INSPECCION MEC PALANCA Y LUCES	PALANCA DE CAMBIO / LUCES	27/10/2021		Corrective Order	WO Completed	Mule truck
697557	Coaster	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUMATICOS	27/10/2021		Corrective Order	WO Completed	Bus
697561	JLG 1250 AJP Manlift	Manguera hidráulica Rota	MANGUERA HIDRÁULICA ROTA	27/10/2021		Corrective Order	WO Completed	Manlift
697563	Coaster	CAMBIO DE 2 NEUMATICOS	CAMBIO DE 2 NEUMÁTICOS	27/10/2021		Corrective Order	WO Completed	Bus
697567	DOOSAN 1005	LLAMADA DE EMERGENCIA	EQUIPO PARADO	27/10/2021	20307	Corrective Order	WO Completed	Light Tower
697650	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	28/10/2021	sin Horas	PM Orders	WO Completed	Generator
697651	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	28/10/2021	12668 hrs	PM Orders	WO Completed	Generator
697702	Caterpillar 140K	Se le salió marco de la puerta	SE LE SALIÓ MARCO DE LA PUERTA	28/10/2021		Corrective Order	WO Completed	Grader
697703	Caterpillar 14M Motorgrader	Se le salieron los bronce	SE LE SALIERON LOS BRONCE	28/10/2021		Corrective Order	WO Completed	Grader
697715	Caterpillar C4.4 88KVA	FALLO DE ARRANQUE	LLAMADA DE EMERGENCIA	28/10/2021	30204 horas	Corrective Order	WO Completed	Generator
697718	PRAMAC GSW120 120 kVa	REVISION DE EQUIPO POR HUMO	LLAMADA DE EMERGENCIA	28/10/2021	7112 horas	Corrective Order	WO Completed	Generator
697723	Caterpillar 12M Motorgrader	Se recalentado y el aire no	SE RECALENTADO Y EL AIRE NO	28/10/2021		Corrective Order	WO Completed	Grader
697724	Caterpillar 14H Motorgrader	Fusible qemandó (corto en la	FUSIBLE QEMANDO (CORTO EN LA	28/10/2021		Corrective Order	WO Completed	Grader
697730	Unimog Service Truck	Reparacion de Unimog UMT104	REPARACION DE UNIMOG UMT104	28/10/2021		Corrective Order	WO Completed	Truck
697734	Hilux DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	28/10/2021		Corrective Order	WO Completed	Pickup truck
697738	TRUCK IVECO TRAKKER 440 AT 8X8	Instalación de placa	INSTALACIÓN DE PLACA	28/10/2021		Corrective Order	WO Completed	Boom truck
697764	Caterpillar 740B	C/HARNESS HITCH CHASIS	MAL ESTADO	28/10/2021		Corrective Order	WO Completed	Articulated dump truck
697813	Hyster E70xn 3t Forklift (E)	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Completed	Forklift
697824	Freightliner Cl 120	Aire acondicionado no funciona	AIRE ACONDICIONADO NO FUNCIONA	28/10/2021		Corrective Order	WO Completed	Mule truck
697834	Hyster H700 Forklift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Completed	Forklift
697873	Hyster H800 32t Forklift (M)	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Completed	Forklift
697883	JLG 450 AJ Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Completed	Manlift
697904	Freightliner Cl 120	Tercer Brazo	TERCER BRAZO AVERIIADO	28/10/2021		Corrective Order	WO Completed	Mule truck
697922	JLG 1250 AJP Manlift	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	28/10/2021		Corrective Order	WO Completed	Manlift
697938	Caterpillar 416E	Balde del bomm se despegó	BALDE DEL BOMM SE DESPEGO	28/10/2021		Corrective Order	WO Completed	Backhoe
697940	Freightliner Cl 120	Cambio de extintor	CAMBIO DE EXTINTOR	28/10/2021		Corrective Order	WO Completed	Mule truck
697961	Gallegos Flatbed Trailer	Ajuste de frenos	AJUSTE DE FRENOS	28/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
697962	Gallegos Flatbed Trailer	Cambio de placa	CAMBIO DE PLACA	28/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
697970	Grove RT880E 75TON	Cambio de Manguera Hidraulica	CAMBIO DE MANGUERA HIDRAULICA	28/10/2021		Corrective Order	WO Completed	Crane/Hoist
697972	SJS SJ6530	Cambio de eje de traslación	CAMBIO DE EJE DE TRASLACIÓN	28/10/2021		Corrective Order	WO Completed	Compactor
697973	JLG 1250 AJP Manlift	Equipo bloqueado	EQUIPO BLOQUEADO	28/10/2021		Corrective Order	WO Completed	Manlift
697974	Hyster H700 Forklift	Bajo presión de aceite	BAJO PRESIÓN DE ACEITE	28/10/2021		Corrective Order	WO Completed	Forklift
697981	Hilux DC	PREVENTIVE MAINTENACE 5000KM	OIL & FILTER REPLACEMEN, INSPECTION	28/10/2021	35,796.00 km	PM Orders	WO Completed	Pickup truck
697995	TRUCK IVECO TRAKKER 440 AT 8X8	Extintor y Primeros Auxilios	INSTALACIÓN DE EXTINTOR Y KIT DE PRIMEROS AUXILIOS	28/10/2021		Corrective Order	WO Completed	Boom truck
698001	Hilux DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	28/10/2021		Corrective Order	WO Completed	Pickup truck
698003	Landcruiser DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	28/10/2021		Corrective Order	WO Completed	Pickup truck
698126	Case 110JX Tractor Cable Handl	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	29/10/2021		Corrective Order	WO Completed	Tractor
698127	Freightliner Cl 120	VENTANAS, VALVULA	VENTANAS, VALVULA	29/10/2021		Corrective Order	WO Completed	Mule truck
698158	SDMO T11UM 10KVA	CAMBIO CORREA ALTERNADOR	CORRECTIVO PROGRAMADO	29/10/2021	18831 hrs	Corrective Order	WO Completed	Generator
698179	Case 110JX Tractor Cable Handl	CAMBIO DE UN NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	29/10/2021		Corrective Order	WO Completed	Tractor
698200	USP&E GP700S/V-A 700 kVa	CAMBIO DE BATERIAS	BATERIAS DESCARGADAS	29/10/2021	16084 horas	Corrective Order	WO Completed	Generator
698204	PRAMAC GSW45P 48 kVa	FALLO DE ARRANQUE	EQUIPO CON PARO DE EMERGENCIA ACTIVADO	29/10/2021	9367 horas	Corrective Order	WO Completed	Generator
698273	Freightliner Columbia Cl112	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	29/10/2021	90016429	Corrective Order	WO Completed	Mule truck
698298	Caterpillar C9 250 kVa	EQUIPO SIN DIESEL	LLAMADA DE EMERGENCIA	29/10/2021	20435 horas	Corrective Order	WO Completed	Generator
698304	Freightliner Columbia Cl112	ELIMINAR FUGA X TRANSMISION	REPARAR FUGA	29/10/2021	59,835.2 Kms	Corrective Order	WO Completed	Mule truck
698319	Caterpillar 336DL Excavator	CAMBIIO DE BATERIA	CAMBIO DE BATERIA	29/10/2021		Corrective Order	WO Completed	Excavator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
698327	Grove RT700E 60TON	DESMONTAJE DE CAMPANA	DESMONTAJE DE CAMPANA	29/10/2021		Corrective Order	WO Completed	Crane/Hoist
698333	Freightliner Columbia CI112	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	29/10/2021		Corrective Order	WO Completed	Mule truck
698345	Freightliner CI 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	29/10/2021		Corrective Order	WO Completed	Mule truck
698353	Freightliner CI 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	29/10/2021		Corrective Order	WO Completed	Mule truck
698373	Gallegos Flatbed Trailer	INSP LUCES,FRENOS,POLLERAS	INSPECCION MECANICA	29/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
698375	Gallegos Flatbed Trailer	INSP LUCES,FRENOS,POLLERAS	INSPECCION MECANICA	29/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
698391	Caterpillar 426F2 Backhoe	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	29/10/2021		Corrective Order	WO Completed	Backhoe
698399	Hyster H700 Forklift	Traslado de equipo	TRASLADO DE EQUIPO	29/10/2021	2021W44	Corrective Order	WO Completed	Forklift
698400	Caterpillar 416F2 Backhoe	No arranca	NO ARRANCA	29/10/2021		Corrective Order	WO Completed	Backhoe
698403	Freightliner M2 106 Hydroseedi	Pierde fuerza	PIERDE FUERZA	29/10/2021		Corrective Order	WO Completed	Truck
698443	Manitou Mht-X1490 9t Telehand	Fuga de Aceite parte trasera	FUGA DE ACEITE PARTE TRASERA	29/10/2021		Corrective Order	WO Completed	Telehender
698473	Freightliner M2 106 Hydroseedi	CAMBIO EJE ALIMENTACION	EQUIPO HIDROSIEMBRA	29/10/2021		Corrective Order	WO Completed	Truck
698481	Grove RT650E 45TON	Equipo no acelera	EQUIPO NO ACELERA	29/10/2021		Corrective Order	WO Completed	Crane/Hoist
698482	Manitou Mht-X860 6t Telehand	Calibración de presiones	CALIBRACIÓN DE PRESIONES DE LLANTA	29/10/2021		Corrective Order	WO Completed	Telehender
698484	Internation F2674	Ubicar grua en posicion	UBICAR GRUA EN POSICION	29/10/2021		Corrective Order	WO Completed	Boom truck
698485	Mobile equipment	montacarga rentada copama	MONTACARGA RENTADA COPAMA MSA CON LLANTA FLAT	29/10/2021		Corrective Order	WO Completed	Area
698491	Landcruiser DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	29/10/2021		Corrective Order	WO Completed	Pickup truck
698492	PB003 COASTER TOYOTA	Equipo se apaga	TERMINALES EN MAL ESTADO	29/10/2021		Corrective Order	WO Completed	Bus
698493	Freightliner CI 120	Bajo nivel de refrigerante	BAJO NIVEL DE REFRIGERANTE	29/10/2021		Corrective Order	WO Completed	Mule truck
698496	ATR-0000-001 4+320 AGRICO	PM MANTENIMIENTO PREVENTIVO	PM MANTENIMIENTO PREVENTIVO	29/10/2021		Corrective Order	WO Completed	Tractor
698518	Coaster	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	29/10/2021		Corrective Order	WO Completed	Bus
698519	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	29/10/2021		Corrective Order	WO Completed	Pickup truck
698569	MAGNUM Light Tower	MANTENIMIENTO CORRECTIVO	EQUIPO PARADO	30/10/2021	27551 horas	Corrective Order	WO Completed	Light Tower
698573	Mobile equipment	Fitting y acoples	FITTING Y ACOPLES	30/10/2021		Corrective Order	WO Completed	Area
698615	Caterpillar 12M	cuna de bronce de la hoja fuer	CUNA DE BRONCE DE LA HOJA FUER	30/10/2021		Corrective Order	WO Completed	Grader
698819	Hyster H800 32t Forklift (M)	Luces Delanteras Quemadas	LUCES DELANTERAS QUEMADAS	30/10/2021		Corrective Order	WO Completed	Forklift
698820	Hyster H800 32t Forklift (M)	Espejo Delantero Derecho	ESPEJO DELANTERO DERECHO	30/10/2021		Corrective Order	WO Completed	Forklift
698821	Caterpillar 12M	CAMBIO DE BRONCE INFERIOR	CORRECTIVO	30/10/2021		Corrective Order	WO Completed	Grader
698845	Coaster	CAMBIO DE 1 NEUMATICO	CAMBIO NEUMATICO	30/10/2021		Corrective Order	WO Completed	Bus
698868	Freightliner M2 106 Hydroseedi	CAMBIO DE MANGUERA Y CONECTORE	MANGUERAS Y CONECTORES	30/10/2021		Corrective Order	WO Completed	Truck
698915	Internation F2674	LLANTA FLAT-DERECHA	LLANTA FLAT-DERECHA	30/10/2021		Corrective Order	WO Completed	Boom truck
698916	Terex RT670 64TON	CONFECION DE MANGUERA	CNFECCION DE MANGUERA	30/10/2021		Corrective Order	WO Completed	Crane/Hoist
698920	Freightliner Columbia CI112	cambio de tercer brazo y llant	TERCER BRAZO MALO Y CAMBIO DE 8 LLANTAS	30/10/2021		Corrective Order	WO Completed	Mule truck
698942	Freightliner CI 120	A/A / FUGA DE AIRE / BASE EXT	A/A / FUGA DE AIRE / BASE EXT	30/10/2021		Corrective Order	WO Completed	Mule truck
698948	Freightliner CI 120	CAPOT / SEGURO	CAPOT / SEGURO	30/10/2021		Corrective Order	WO Completed	Mule truck
698951	Freightliner CI 120	RETROVISOR / PUERTA	RETROVISOR / PUERTA	30/10/2021		Corrective Order	WO Completed	Mule truck
698988	SDMO T11UM 10KVA	MANTENIMIENTO CORRECTIVO	CAMBIO DE CORREA	30/10/2021	18591 HORAS	Corrective Order	WO Completed	Generator
698994	Hilux DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	30/10/2021		Corrective Order	WO Completed	Pickup truck
698996	Hilux DC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITES Y FILTROS	30/10/2021	24185.00	Corrective Order	WO Completed	Pickup truck
698997	Hilux DC	REVISION SIST DE ARRANQUE	CAMBIO DE BATERIA, PITO DE REVERSA	30/10/2021	32590.00	Corrective Order	WO Completed	Pickup truck
698998	Landcruiser TC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	30/10/2021	46532.00	Corrective Order	WO Completed	Pickup truck
698999	Landcruiser TC	MANTENIMIENTO CORRECTIVO	CAMBIO DE EJE CORTO,BUJES DE BARRA	30/10/2021	43532.00	Corrective Order	WO Completed	Pickup truck
699000	Toyota Hilux	REPARACIONES	SUSPENSION,DIRECCION,FRENOS	30/10/2021	83153.00	Corrective Order	WO Completed	Pickup truck
699001	PB003 COASTER TOYOTA	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	30/10/2021	258812.00	Corrective Order	WO Completed	Bus
699002	PB003 COASTER TOYOTA	DAÑOS EN PISO	DAÑOS EN PISO	30/10/2021	258813.00	Corrective Order	WO Completed	Bus
699004	Landcruiser DC	SUSPENSION,4X4,A/C	REVISION Y REPARCIO ,CARGA DE GAS	30/10/2021	71856.00	Corrective Order	WO Completed	Pickup truck
699005	Hilux DC	PROBLEMAS DE ARRANQUE	CAMBIO DE POLEA,ALTERNADOR	30/10/2021		Corrective Order	WO Completed	Pickup truck
699011	Coaster	FRENOS	CAMBIO DE CILINDROS Y BANDAS DE FRENOS	31/10/2021		Corrective Order	WO Completed	Bus
699012	Coaster	CAMBIO DE LINK TRASEROS	CAMBIO DE LINK TRASEROS DE DIRECCION	31/10/2021		Corrective Order	WO Completed	Bus
699013	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	31/10/2021		Corrective Order	WO Completed	Pickup truck
699014	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	31/10/2021	82877.00	Corrective Order	WO Completed	Pickup truck
699017	Landcruiser DC	REVISION LUCES	CAMBIO DE PLOT DE LUCES DELANTERAS	31/10/2021	67605.00	Corrective Order	WO Completed	Pickup truck
699018	Landcruiser DC	SITEMA DE VENTANA	CAMBIO DE MOTOR DE SUBIR VENTANA	31/10/2021	86499.00	Corrective Order	WO Completed	Pickup truck
699019	Toyota Hilux	SISTEMA DE FRENOS	RPARACION DE VALVULA REPARTIDORA	31/10/2021	92791.00	Corrective Order	WO Completed	Pickup truck
699021	Landcruiser TC	CORRECTIVOS	SUSPENSION,DIRECCION,FRENOS	31/10/2021	75807.00	Corrective Order	WO Completed	Pickup truck
699022	Hilux DC	MANTENIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	31/10/2021	10658.00	Corrective Order	WO Completed	Pickup truck
699023	Hilux DC	MANTENIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	31/10/2021	20399.00	Corrective Order	WO Completed	Pickup truck
699024	Hino Serie 300	REPARACION LUCES	REPARACION LUCES,CAMBIO DE BOMBILLOS	31/10/2021	151887.00	Corrective Order	WO Completed	Truck
699026	Case 110JX Tractor Cable Handl	FUGA HIDRAULICA	FUGA HIDR{AULICA	31/10/2021		Corrective Order	WO Completed	Tractor
699027	Isuzu NMR85L	CORREAS	INSTLACION DE CORREAS DE ALTERNADOR	31/10/2021	55144.00	Corrective Order	WO Completed	Truck
699028	Landcruiser DC	REPARACION DE A/C	RECARGA Y CAVIO DE GAS A/C	31/10/2021	43333.00	Corrective Order	WO Completed	Pickup truck
699029	Hilux DC	PROBLEMAS ELECTRICOS	CAMBIO SE FUSIBLES,BOMBILLOS	31/10/2021		Corrective Order	WO Completed	Pickup truck
699030	Toyota Hilux	MANTENIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	31/10/2021	91722.00	Corrective Order	WO Completed	Pickup truck
699031	Hilux DC	A/C,FRENOS	CARGA Y VACIO DE GAS,AJUSTE DE FRENOS	31/10/2021	44157.00	Corrective Order	WO Completed	Pickup truck
699033	Coaster	MANTENIMIENTO PREVENTIVO	CAMBIO DE FILTRO Y ACEITES	31/10/2021	35076.00	Corrective Order	WO Completed	Bus
699034	Hilux DC	CORRECTIVO	CREMALLERA,MUELLE,GRAPAS,ABS	31/10/2021	75946.00	Corrective Order	WO Completed	Pickup truck
699035	Hilux DC	CORRECTIVO	CAMBIO DE MUELLES	31/10/2021	37805.00	Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
699036	Landcruiser DC	CORRECTIVO	CAMBIO DE BANDAS,KIT DE REFUERZO COCOBOLA,CABLE DE FRENO	31/10/2021 60842.00		Corrective Order	WO Completed	Pickup truck
699037	Hino Series 300 Truck	CORRECTIVO	CAMBIO DE ACEITES DIFERENCIA, ALARMA,ENGRASE,AJUSTE DE FRENOS	31/10/2021 66124.00		Corrective Order	WO Completed	Truck
699039	Landcruiser DC	REVISION DE LUCES	CAMBIO DE BOMBILLO Y ALARMA	31/10/2021 46304.00		Corrective Order	WO Completed	Pickup truck
699042	Freightliner Cl 120	cambio de evaporador	CAMBIO DE EVAPORADOR	31/10/2021		Corrective Order	WO Completed	Mule truck
699044	Mobile equipment	Bombillos para taller	BOMBILLOS PARA TALLER	31/10/2021		Corrective Order	WO Completed	Area
699180	DOOSAN 1005	PM DOO D1005 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 30098 hrs		PM Orders	WO Completed	Light Tower
699213	PB013 COASTER TOYOTA	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUM[ATICOS	31/10/2021		Corrective Order	WO Completed	Bus
699229	JLG 800 AJ Manlift	EQUIPO NO ENCIENDE	PROBLEMAS DE ENCENDIDO	31/10/2021		Corrective Order	WO Completed	Manlift
699248	Caterpillar 14H Motorgrader	Ruedas delanteras desalineadas	RUEDAS DELANTERAS DESALINEADAS	31/10/2021		Corrective Order	WO Completed	Grader
699250	Mobile equipment	Insumos para Taller	INSUMOS PARA TALLER	31/10/2021		Corrective Order	WO Completed	Area
699258	GS181 D110 E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 23784 horas		PM Orders	WO Completed	Generator
699260	GS191 D110 E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 32555 horas		PM Orders	WO Completed	Generator
699261	GS194 D110 E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 14617 horas		PM Orders	WO Completed	Generator
699262	Gallegos Flatbed Trailer	ENGRASE	ENGRASE	31/10/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
699263	GS202 DE110E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 12074 horas		PM Orders	WO Completed	Generator
699264	GS204 DE110E2 CAT	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 13135 horas		PM Orders	WO Completed	Generator
699267	FG WILSON P88-3 80 kVa	PM1 FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 26.79 kh		PM Orders	WO Completed	Generator
699268	Caterpillar D110 E2 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 18303 hrs		PM Orders	WO Completed	Generator
699269	Caterpillar DE110E 110 kVa	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 22919 hrs		PM Orders	WO Completed	Generator
699271	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 14981 hrs		PM Orders	WO Completed	Generator
699272	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 14978 horas		PM Orders	WO Completed	Generator
699273	PRAMAC GSW110P 82 kVa	PM1 PRA GSW110 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 15833 hrs		PM Orders	WO Completed	Generator
699274	PRAMAC GSW80P 83 kVa	PM1 PRA GSW80P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 13715 hrs		PM Orders	WO Completed	Generator
699275	Caterpillar C9 250 kVa	PM1 CAT C9 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 21549 horas		PM Orders	WO Completed	Generator
699276	SDMO J30U 38KVA	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 10003 hrs		PM Orders	WO Completed	Generator
699277	SDMO T11UM 10KVA	PM1 SDM T11UM MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 18808 horas		PM Orders	WO Completed	Generator
699278	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 26140 hrs		PM Orders	WO Completed	Generator
699279	SDMO T16 16KVA	PM1 SDM T16 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 25338 horas		PM Orders	WO Completed	Generator
699280	PRAMAC GSW30Y 24 kVa	PM1 PRA GSW30Y MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 23498 hrs		PM Orders	WO Completed	Generator
699290	USP&E GP700/V-A 700 kVa	PREVENTIVE MAINTENACE 300HRS	OIL & FILTER REPLACEMEN, INSPECTION	31/10/2021 11867 horas		Corrective Order	WO Completed	Generator
699335	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 65.8 horas		PM Orders	WO Completed	Generator
699336	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 8258 horas		PM Orders	WO Completed	Generator
699337	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 10422 horas		PM Orders	WO Completed	Generator
699338	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 16809 horas		PM Orders	WO Completed	Generator
699339	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 839 hrs		PM Orders	WO Completed	Generator
699340	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 9774 hrs		PM Orders	WO Completed	Generator
699341	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 16487 hrs		PM Orders	WO Completed	Generator
699342	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 16084 hrs		PM Orders	WO Completed	Generator
699343	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 8644 hrs		PM Orders	WO Completed	Generator
699344	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 3633 hrs		PM Orders	WO Completed	Generator
699345	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 581 hrs		PM Orders	WO Completed	Generator
699346	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 361 horas		PM Orders	WO Completed	Generator
699347	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 16641 horas		PM Orders	WO Completed	Generator
699348	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 163 horas		PM Orders	WO Completed	Generator
699350	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 26242 horas		PM Orders	WO Completed	Generator
699352	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 25138 hrs		PM Orders	WO Completed	Generator
699355	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 18057 hrs		PM Orders	WO Completed	Generator
699356	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	31/10/2021 866 hrs		PM Orders	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
699375	Coaster	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	31/10/2021		Corrective Order	WO Completed	Bus
699435	Freightliner Columbia CI112	Cambio de batería	CAMBIO DE BATERÍA	31/10/2021		Corrective Order	WO Completed	Mule truck
699485	Caterpillar 14H Motorgrader	Se le rompio una manguera	SE LE ROMPIO UNA MANGUERA	31/10/2021		Corrective Order	WO Completed	Grader
699573	Hyster H300 13t Forklift (M)	llanta flat	LLANTA FLAT	31/10/2021		Corrective Order	WO Completed	Forklift
699578	Caterpillar 426f2 Backhoe	Equipo no enciende	EQUIPO NO ENCIENDE	31/10/2021		Corrective Order	WO Completed	Backhoe
699582	Hilux DC	Inspección Mensual de llantas	INSPECCIÓN MENSUAL DE LLANTAS	31/10/2021		Corrective Order	WO Completed	Pickup truck
699583	Hyster H800 32t Forklift (M)	Problemas con luces	PROBLEMAS CON LUCES	31/10/2021		Corrective Order	WO Completed	Forklift
699584	Hilux DC	Revisión de llanta mensual	REVISIÓN DE LLANTA MENSUAL	31/10/2021		Corrective Order	WO Completed	Pickup truck
699585	Landcruiser TC	Inspección Mensual llanta	INSPECCIÓN MENSUAL DE LLANTA	31/10/2021		Corrective Order	WO Completed	Pickup truck
699607	International 7400 SBA Fire Tr	Inspección de llanta mensual	INSPECCIÓN DE LLANTA MENSUAL	31/10/2021		Corrective Order	WO Completed	Fire truck
699608	Hilux DC	Inspección mensual de llanta	INSPECCIÓN MENSUAL DE LLANTA	31/10/2021		Corrective Order	WO Completed	Pickup truck
699609	Hilux DC	Inspección mensual de llanta	INSPECCIÓN MENSUAL DE LLANTA	31/10/2021		Corrective Order	WO Completed	Pickup truck
699610	Caterpillar CS533E Compactor	Problemas con el Acelerador	PROBLEMAS CON EL ACELERADOR	31/10/2021		Corrective Order	WO Completed	Compactor
699611	Tennant T7 Scrubber	Engrase general	ENGRASE GENERAL	31/10/2021		Corrective Order	WO Completed	Scrubber / Sweeper
700042	Caterpillar 14M Motorgrader	REEMPLAZO DE MANGUERA HID	CORRECTIVO	01/11/2021		Corrective Order	WO Completed	Grader
700070	Internation F2674	CAMBIO DE 2 NEUMATICOS	CAMBIO TRANSMISION Y BARRA DIRECCION	01/11/2021	90016555	Corrective Order	WO Completed	Boom truck
700170	Tennant T7 Scrubber	BRUSHES REPLACEMENT	CORRECTIVE	01/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
700176	Caterpillar C9 250 kVa	EQUIPO SIN DIESEL	LLAMADA DE EMERGENCIA	01/11/2021	20474 horas	Corrective Order	WO Completed	Generator
700513	Hilux DC	A/C	CARGAS DE GAS	02/11/2021	26494.00	Corrective Order	WO Completed	Pickup truck
700514	Landcruiser DC	REPARACION DE LUCES	CAMBIO DE PLOT	02/11/2021	101025.00	Corrective Order	WO Completed	Pickup truck
700515	Landcruiser TC	BATERIA	CAMBIO DE BATERIA	02/11/2021	33254.00	Corrective Order	WO Completed	Pickup truck
700517	Coaster	BATERIA	CAMBIO DE BATERIA	02/11/2021	9606.00	Corrective Order	WO Completed	Bus
700519	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700520	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700521	Landcruiser DC	CORRECTIVO	SUSPENSION,DIRECCION,REAPARACION DE CABLES	02/11/2021	71529.00	Corrective Order	WO Completed	Pickup truck
700527	Landcruiser DC	PERTIGA	INSTALACION DE PERTIGA	02/11/2021		Corrective Order	WO Completed	Pickup truck
700528	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	02/11/2021	20529.00	Corrective Order	WO Completed	Pickup truck
700558	Freightliner Columbia CI112	CAMBIO DE ESPEJO RETROVISOR	CAMBIO DE ESPEJO RETROVISOR	02/11/2021		Corrective Order	WO Completed	Mule truck
700560	Caterpillar 236d Skid Steer L	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	02/11/2021		Corrective Order	WO Completed	Skid Steer
700585	Caterpillar 320DL	Reparacion de sistema AFEX	REPARACION DE SISTEMA AFEX	02/11/2021		Corrective Order	WO Completed	Excavator
700589	Gallegos Flatbed Trailer	ENGRASE	ENGRASE	02/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
700593	Hino Series300	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Truck
700598	Freightliner CI 120	A/A	A/A	02/11/2021		Corrective Order	WO Completed	Mule truck
700606	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700607	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700625	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	02/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
700627	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700633	Caterpillar 12M	Revision de fuga de refrigeran	REVISION DE FUGA DE REFRIGERANTE DE MOTOR	02/11/2021	12710.8 Horas	Corrective Order	WO Completed	Grader
700653	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700700	Caterpillar RM300	Revision de falla electrica	REVISION DE FALLA ELECTRICA	02/11/2021		Corrective Order	WO Completed	Road Reclaimer
700732	Caterpillar 416F2 Backhoe	pasador de giro de la pluma se	PASADOR DE JIRO DE LA PLUMA SE	02/11/2021		Corrective Order	WO Completed	Backhoe
700735	BT014 M2-112 Freightliner	REEMPLAZO DE MANGUERA HYD	REEMPLAZO DE MANGUERA HYD	02/11/2021		Corrective Order	WO Completed	.
700788	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Pickup truck
700796	Ford F550	CAMBIO DE COMPONENTE	AUTO PUMP 12 VOLT	02/11/2021	60024102	Corrective Order	WO Completed	Pickup truck
700853	Hyster H700 Forklift	Cambio de motor	CAMBIO DE MOTOR	02/11/2021	90011961	Corrective Order	WO Completed	Forklift
700898	Hiace Bus	Reparacion de llantas	REPARACION DE LLANTAS	02/11/2021		Corrective Order	WO Completed	Bus
700902	Freightliner M2 112 Sucker Tru	Fabricacion de bases para bate	FABRICACION DE BASE PARA BATERIAS	02/11/2021		Corrective Order	WO Completed	Sucker truck
700950	Landcruiser DC	CONJUNTO GUIA FRONTAL SUPERIOR	CAMBIO	02/11/2021		Corrective Order	WO Completed	Pickup truck
700951	Mobile equipment	Reparacion de 1 llanta	REPARACION DE 1 LLANTA	02/11/2021		Corrective Order	WO Completed	Area
700952	Coaster	CAMBIO CONJUNTO CILINDRO	ASUMIDO DOLLAR	02/11/2021		Corrective Order	WO Completed	Bus
700955	Landcruiser DC	REPARACION ELECTRICA	LUCES DE SEGURIDAD	02/11/2021	SE DEBE ASUMIR	Corrective Order	WO Completed	Pickup truck
700956	Hilux DC	CAMBIO HOJA MUELLE	UNA HOJA FUE CAMBIADA EN JUNIO Y LA OTRA SEPTIEMBRE	02/11/2021		Corrective Order	WO Completed	Pickup truck
700962	Caterpillar 236d Skid Steer L	Revision de ruedas	REVISION DE RUEDAS - TORNILLOS FLOJOS	02/11/2021		Corrective Order	WO Completed	Skid Steer
700978	Pramac GSW25P 17KVA	MOVIMIEN TTO DE GENERADOR	MOVIMIEN TTO DE GENERADOR	02/11/2021	Soporte W44	Corrective Order	WO Completed	Generator
700980	Hilux DC	Mantenimiento preventivo	CAMBIO DE FILTROS Y ACEITES	02/11/2021		Corrective Order	WO Completed	Pickup truck
700981	Landcruiser DC	MANTENIMIENTO CORRECTIVO	REPARACION SIST COCOBOLAS	02/11/2021	70187 kms	Corrective Order	WO Completed	Pickup truck
700982	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	02/11/2021	70187 kms	Corrective Order	WO Completed	Pickup truck
700983	Ford F550	SERVICIO PRESTADO	DESARMADO FRONTAL PARA SACAR COMPRESOR Y CONDENSADOR	02/11/2021	41831 kms	Corrective Order	WO Completed	Pickup truck
700984	Hilux DC	REVISION SIST ARRANQUE	CAMBIO DE BATERIA, CAMBIO DE ALTERNADOR	02/11/2021	53730 kms	Corrective Order	WO Completed	Pickup truck
701020	Caterpillar 236d Skid Steer L	Fuga de aceite Motor	FUGA DE ACEITE MOTOR	03/11/2021		Corrective Order	WO Completed	Skid Steer
701165	Freightliner M2 106 Hydroseedi	Cambio de tornilleria de carro	CAMBIO DE TORNILLERIA DE CARROCERIA	03/11/2021		Corrective Order	WO Completed	Truck
701202	Freightliner CI 120	Alarma de reversa no funciona	ALARMA DE REVERSA NO FUNCIONA	03/11/2021		Corrective Order	WO Completed	Mule truck
701205	Landcruiser DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	03/11/2021		Corrective Order	WO Completed	Pickup truck
701214	TTP-0000-102	reparacion de gabilan	REPARACION GABILAN	03/11/2021		Corrective Order	WO Completed	Excavator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
701218	PRAMAC GSW560V 407 kVa	CAMBIO DE ASPAS	CAMBIO DE ASPAS NUEVAS POR LAS ORIGINALES DE GS182	03/11/2021	15868 horas	Corrective Order	WO Completed	Generator
701254	Caterpillar 14H Motorgrader	Manguera q va al filtro del ai	MANGUERA Q VA AL FILTRO DEL AI	03/11/2021		Corrective Order	WO Completed	Grader
701271	Caterpillar DE88E0 58 kVa	REPLAZO DE CORREA	MANTENIMIENTO CORRECTIVO	03/11/2021	38706 hrs	Corrective Order	WO Completed	Generator
701315	Freightliner CI 120	cambio de bomba de agua	CAMBIO DE BOMBA DE AGUA	03/11/2021		Corrective Order	WO Completed	Mule truck
701384	Manitou Mht-X1490 9t Telehand	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	03/11/2021		Corrective Order	WO Completed	Telehender
701397	Freightliner Columbia CI112	Reemplazo de llantas	REEMPLAZO DE LLANTAS	03/11/2021		Corrective Order	WO Completed	Mule truck
701443	Unimog U3000 Truck	cambio de valvula de machine b	CAMBIO DE VALVULA DE MACHINE BRAKE	03/11/2021		Corrective Order	WO Completed	Truck
701478	Hilux DC	cambio de terminales	CAMBIO DE TERMINALES	03/11/2021		Corrective Order	WO Completed	Pickup truck
701481	Landcruiser DC	cambio de muelles y espaciador	CAMBIO DE MUELLES Y ESPACIADOR	03/11/2021		Corrective Order	WO Completed	Pickup truck
701483	Hilux DC	cambio de terminales internos	CAMBIO DE TERMINALES INTERNOS	03/11/2021		Corrective Order	WO Completed	Pickup truck
701485	Coaster	cambio de aspa de abanico	CAMBIO DE ASPA DE ABANICO	03/11/2021		Corrective Order	WO Completed	Bus
701486	Hilux DC	cambio de eje flecha	CAMBIO DE EJE FLECHA	03/11/2021		Corrective Order	WO Completed	Pickup truck
701488	Hilux DC	cambio de brazos de suspension	CAMBIO DE BRAZOS DE SUSPENSION	03/11/2021		Corrective Order	WO Completed	Pickup truck
701492	Hilux DC	cambio de hoja de muelle	CAMBIO DE HOJA DE MUELLE	03/11/2021		Corrective Order	WO Completed	Pickup truck
701493	Landcruiser TC	REPARACION DE SISTEMA A/C	REPARACION DE SISTEMA A/C	03/11/2021		Corrective Order	WO Completed	Pickup truck
701495	Landcruiser DC	cambio de sensor de faja unica	CAMBIO DE SENSOR DE FAJA UNICA, TENSORA Y CORREA	03/11/2021		Corrective Order	WO Completed	Pickup truck
701496	Landcruiser TC	reparacion de kit de cocobola	REPARACION DE KIT DE COCOBOLA	03/11/2021		Corrective Order	WO Completed	Pickup truck
701498	Hilux DC	cambio de vidrio trasero	CAMBIO DE VIDRIO TRASERO	03/11/2021		Corrective Order	WO Completed	Pickup truck
701508	Cargador 966H Wheel Loader	reparacion de cerradura	REPARACION DE CERRADURA	03/11/2021		Corrective Order	WO Completed	Loader
701514	Hilux DC	revision de lamparas	REVISION DE LAMPARAS	03/11/2021		Corrective Order	WO Completed	Pickup truck
701524	Hilux DC	reparacion de transmision	REPARACION DE TRANSMISION	03/11/2021		Corrective Order	WO Completed	Pickup truck
701531	Landcruiser TC	cambio de banda, y esclavo de	CAMBIO DE BANDA, Y ESCLAVO DE CLUCHT	03/11/2021		Corrective Order	WO Completed	Pickup truck
701534	Landcruiser TC	cambio de eje mando corto	CAMBIO DE EJE MANDO CORTO	03/11/2021		Corrective Order	WO Completed	Pickup truck
701535	Hilux DC	cambio de compresor de a/c	CAMBIO DE COMPRESOR DE A/C	03/11/2021		Corrective Order	WO Completed	Pickup truck
701537	Hilux DC	cambio de platos de suspension	CAMBIO DE PLATOS DE SUSPENSION	03/11/2021		Corrective Order	WO Completed	Pickup truck
701541	GROVE GMK 2035E 35TON	MECHANICAL INSPECTION	INSPECTION	03/11/2021		Corrective Order	WO Completed	Crane/Hoist
701588	Hyster H300 13t Forklift (M)	Cambio de llantas traseras	CAMBIO DE LLANTAS TRASERAS	03/11/2021		Corrective Order	WO Completed	Forklift
701604	Freightliner M2 106 Hydroseedi	Instalacion de GPS	INSTALACION DE GPS	03/11/2021		Corrective Order	WO Completed	Truck
701606	PB003 COASTER TOYOTA	Instalacion de GPS	INSTALACION DE GPS	03/11/2021		Corrective Order	WO Completed	Bus
701636	JLG T350 Manlift	MECHANICAL INSPECTION	INSPECTION	03/11/2021		Corrective Order	WO Completed	Manlift
701663	PRAMAC GSW560V 407 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE CORREA REVENTADA	03/11/2021	15876 hrs	Corrective Order	WO Completed	Generator
701673	Caterpillar DE88E0 58 kVa	EQUIPO APAGADO	LLAMADA DE EMERGENCIA	03/11/2021	38717 horas	Corrective Order	WO Completed	Generator
701675	Pit	MOVILIZACION DE GENERADOR	MOVILIZACION DE GENERADOR	03/11/2021		Corrective Order	WO Completed	.
701676	PRAMAC GSW460V 460 kVa	EXTRACCION DE ASPAS DE MOTOR	XTRACCION DE ASPAS PARA COLOCACION A LA UNIDAD GS182	03/11/2021	28376 horas	Corrective Order	WO Completed	Generator
701680	Freightliner M2 106 Hydroseedi	Mantenimiento de superestrucut	MANTENIMIENTO DE SUPERESTRUCTURA	03/11/2021		Corrective Order	WO Completed	Truck
701684	Landcruiser DC	CAMBIO DE EVAPORADOR, VALVULA	MANTENIMIENTO CORRECTIVO	03/11/2021	77441 kms	Corrective Order	WO Completed	Pickup truck
701685	Landcruiser DC	Cambio de componentes	MANTENIMIENTO CORRECTIVO	03/11/2021	68904 kms	Corrective Order	WO Completed	Pickup truck
701686	Coaster	CAMBIO DE MUELLE LH	MANTENIMIENTO CORRECTIVO	03/11/2021		Corrective Order	WO Completed	Bus
701687	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO CORREAS DE AC, CORREA DE ALT, CAMBIO DE BATERIA	03/11/2021		Corrective Order	WO Completed	Pickup truck
701688	Coaster	MANTENIMIENTO CORRECTIVO	REPARACION CERRADURA PUERTA DE CHOFER	03/11/2021	37947 kms	Corrective Order	WO Completed	Bus
701689	Hilux DC	CAMBIO DE RETROVISOR LH	CAMBIO DE RETROVISOR LH	03/11/2021	21015 kms	Corrective Order	WO Completed	Pickup truck
701690	Landcruiser TC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	03/11/2021	33379.0 kms	Corrective Order	WO Completed	Pickup truck
701692	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO PITO DE REVERSA, CORREA A/C, POLEA TENSORA A/C, LIMPIEZA DE EVAPORADOR	03/11/2021	33380 kms	Corrective Order	WO Completed	Pickup truck
701693	Landcruiser DC	PROBLEMAS DE ARRANQUE	CAMBIO DE BATERIA	03/11/2021	64269 kms	Corrective Order	WO Completed	Pickup truck
701694	Landcruiser DC	REVISION DE LUCES	CAMBIO DE LAMPARA TRASERA RH, H4	03/11/2021		Corrective Order	WO Completed	Pickup truck
701695	Landcruiser TC	INSPECCION GENERAL	CAMBIO DE POLEA TENSORA, CORREA UNICA ACC, BOMBILLO 12V	03/11/2021	84637 kms	Corrective Order	WO Completed	Pickup truck
701773	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	04/11/2021	no aplica	PM Orders	WO Completed	Generator
701774	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	04/11/2021	no aplia	PM Orders	WO Completed	Generator
701810	Caterpillar 236d Skid Steer L	Soporte de balde defectuoso	SOPORTE DE BALDE ROTO, REQUIERE TRABAJO DE SOLDADURA	04/11/2021		Corrective Order	WO Completed	Skid Steer
701822	Manitou Mht-X1490 9t Telehand	THM-103 Llanta Flat	THM-103 LLANTA FLAT	04/11/2021		Corrective Order	WO Completed	Telehender
701930	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	04/11/2021		Corrective Order	WO Completed	Pickup truck
701931	Freightliner M112 Truck Tip	cambio de perilla de alta y ba	CAMBIO DE PERILLA DE ALTA Y BAJA	04/11/2021		Corrective Order	WO Completed	Tipper
702099	Gallegos Flatbed Trailer	ajuste de S de sistema de Fren	AJUSTE DE S DE SISTEMA DE FRENO	04/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
702101	Caterpillar 14H Motorgrader	cambio de mangueras de admisio	CAMBIO DE MANGUERAS DE ADMISION	04/11/2021	21,595.00 hrs	Corrective Order	WO Completed	Grader
702102	Caterpillar PS-150C	cambio de selenoide de parada	CAMBIO DE SELENOIDE DE PARADA	04/11/2021		Corrective Order	WO Completed	Roller PTR
702105	SJS SJ6530	Colocacion de tornilleria	SIN TORNILLERIA LOS EJES DE TRASLACION	04/11/2021		Corrective Order	WO Completed	Compactor
702124	Caterpillar 336DL	Petate desajustado	PETATE DESAJUSTADO	04/11/2021		Corrective Order	WO Completed	Excavator
702127	Caterpillar 336DL	Aire Acondicionado	AIRE ACONDICIONADO	04/11/2021		Corrective Order	WO Completed	Excavator
702130	PB002 COASTER TOYOTA	cambio de baterias	CAMBIO DE BATERIAS	04/11/2021		Corrective Order	WO Completed	Bus

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
702182	Coaster	cambio de 2 llantas	LLANTAS FLAT	04/11/2021		Corrective Order	WO Completed	Bus
702196	WT013 H7 CISTERNA SINOTRUK	Reparacion de llanta	REPARACION DE LLANTA	04/11/2021		Corrective Order	WO Completed	Water truck
702204	Freightliner M2 106 Hydroseedi	MECHANICAL INSPECTION (PROFILE	INSPECTION	04/11/2021 50017848		Corrective Order	WO Completed	Truck
702205	Freightliner M2 106 Hydroseedi	MECHANICAL INSPECTION (PROFILE	INSPECTION	04/11/2021 50017848		Corrective Order	WO Completed	Truck
702232	Gmc Boom Truck	LEVANTAMIENTO DE INFORMACION	DATOS TECNICOS DE GRUA	04/11/2021		Corrective Order	WO Completed	Boom truck
702235	Gmc Boom Truck	LEVANTAMIENTO INFORMACION	INFORMACION FILTROS	04/11/2021		Corrective Order	WO Completed	Boom truck
702256	Internation F2674	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	04/11/2021 90016764		Corrective Order	WO Completed	Boom truck
702268	Internation F2674	LEVANTAMIENTO DE INFORMACION	INFORMACION DE GRUA	04/11/2021		Corrective Order	WO Completed	Boom truck
702289	Toyota Land Cruiser	cambio de llanta flat	CAMBIO DE LLANTA FLAT	04/11/2021		Corrective Order	WO Completed	Pickup truck
702321	JLG 450 AJ Manlift	cambio de bateria	CAMBIO DE BATERIA	04/11/2021		Corrective Order	WO Completed	Manlift
702376	Hilux DC	Cambio de 2 llanta	CAMBIO DE 2 LLANTAS	04/11/2021		Corrective Order	WO Completed	Pickup truck
702377	Landcruiser DC	MANTENIMIENTO CORRECTIVO	REPARACION ABS, CAMBIO FREEWHEEL, LUBRICACION CERRADURA DE PUERTAS,	04/11/2021		Corrective Order	WO Completed	Pickup truck
702378	Landcruiser DC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITE Y FILTROS	04/11/2021 52397 kms		Corrective Order	WO Completed	Pickup truck
702379	Landcruiser DC	MANTENIMIENTO CORRECTIVO	MANTENIMIENTO CORRECTIVO	04/11/2021		Corrective Order	WO Completed	Pickup truck
702380	Hilux DC	CAMBIO DE RETROVISOR CHOCADO	RETROVISOR LH	04/11/2021		Corrective Order	WO Completed	Pickup truck
702381	Landcruiser TC	MANTENIMIENTO CORRECTIVO	REPARACIONES ELECTRICAS, CAMBIO DE BOMBILLOS, CAMBIO DE AMORTIGUADOR DE DIRECCIO	04/11/2021		Corrective Order	WO Completed	Pickup truck
702382	Hilux DC	FUGA CREMALLERA	CAMBIO DE CREMALLERA	04/11/2021		Corrective Order	WO Completed	Pickup truck
702383	Landcruiser DC	REVISION GENERAL, CORREA ROTA	REVISION GENERAL, CORREA ROTA	04/11/2021		Corrective Order	WO Completed	Pickup truck
702384	Landcruiser DC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITE Y FILTROS	04/11/2021 4628 kms		Corrective Order	WO Completed	Pickup truck
702385	Landcruiser DC	REVISION DE RUIDOS	REVISION DE RUIDOS	04/11/2021		Corrective Order	WO Completed	Pickup truck
702395	Hilux DC	Cambio de 1 llanta	CAMBIO DE1 LLANTA	04/11/2021		Corrective Order	WO Completed	Pickup truck
702397	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	04/11/2021		Corrective Order	WO Completed	Pickup truck
702398	Hilux DC	Cambio de 1 llanta	CAMBIO DE 1 LLANTA	04/11/2021		Corrective Order	WO Completed	Pickup truck
702426	USP&E GP700/V-A 700 kVa	FALLO DE TARGETA REGULADORA	VOLTAGE AC INESTABLE APAGA EQUIPO	05/11/2021 11616 horas		Corrective Order	WO Completed	Generator
702483	Caterpillar D110 E2 100KVA	CAMBIO DE RETENEDORAS	CAMBIO DE RETENEDORAS DE VOLANTE & DAMPER	05/11/2021 19078 horas		Corrective Order	WO Completed	Generator
702522	Caterpillar 416E	Pierde fuerza	PIERDE FUERZA	05/11/2021		Corrective Order	WO Completed	Backhoe
702523	PRAMAC GSW460V 460 kVa	TERMINACION DE ARMADO	TERMINACION DE ARMADO, ARRANQUE & PRUEBA	05/11/2021 19894 horas		Corrective Order	WO Completed	Generator
702599	Freightliner Cl 120	Reemplazo de llantas	REEMPLAZO DE LLANTAS	05/11/2021		Corrective Order	WO Completed	Mule truck
702645	Freightliner M2 112	LEVANTAMIENTO INFORMACION GRUA	LEVANTAMIENTO DE INFORMACION	05/11/2021		Corrective Order	WO Completed	Boom truck
702750	Caterpillar 336DL Excavator	INSPECCION MECANICA	INSPECCION MECANICA	05/11/2021		Corrective Order	WO Completed	Excavator
702752	Freightliner M2 106 Sucker Tru	INSPECCION GENERAL Y ENGRASE	INSPECCIÓN Y ENGRASE	05/11/2021		Corrective Order	WO Completed	Sucker truck
702775	Caterpillar 336DL	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021 90016875		Corrective Order	WO Completed	Excavator
702785	Caterpillar 12M Motorgrader	Aire Acondicionado	AIRE ACONDICIONADO	05/11/2021		Corrective Order	WO Completed	Grader
702788	Ford F550	Limpieza de pantalla	LIMPIEZA DE PANTALLA DE TANQUE DE AGUA	05/11/2021		Corrective Order	WO Completed	Pickup truck
702813	Caterpillar 12M	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Grader
702824	Freightliner M2 106 Hydroseedi	Instalacion de grapas	INSTALACION DE GRAPAS DE ESTRUCTURA	05/11/2021		Corrective Order	WO Completed	Truck
702831	TTP-0000-102	reparar fuga de aceite	REVISAR FUGA DE ACEITE Y COMPLETAR	05/11/2021		Corrective Order	WO Completed	Excavator
702833	SJS SJ6530	cambio de conector	CAMBIO DE CONECTOR	05/11/2021		Corrective Order	WO Completed	Compactor
702836	USP&E GP700S/V-A 700 kVa	CORRECTIVO	ARRANUQUE Y PUESTA EN MARCHA	05/11/2021 25133 hrs		Corrective Order	WO Completed	Generator
702839	Grove RT890 90TON	Instalacion de retrovisor	INTALACION DE RETROVISOR	05/11/2021		Corrective Order	WO Completed	Crane/Hoist
702840	Hyster H800 32t Forklift (M)	no realiza movimiento lateral	NO REALIZA MOVIMIENTO LATERAL	05/11/2021		Corrective Order	WO Completed	Forklift
702841	Landcruiser TC	cambio de 1 llanta	CAMBIO DE 1 LLANTA	05/11/2021		Corrective Order	WO Completed	Pickup truck
702844	USP&E GP700S/V-A 700 kVa	CORRECTIVO	ARRANUQUE Y PUESTA EN MARCHA	05/11/2021 18056 hrs		Corrective Order	WO Completed	Generator
702847	Caterpillar 14M Motorgrader	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Grader
702849	Caterpillar 14H Motorgrader	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Grader
702851	Caterpillar 14H Motorgrader	PM1,MANTENIMIENTO PREVENTIVO	PM1,MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Grader
702859	Caterpillar PS-150C	PM1,MANTENIMIENTO PREVENTIVO	PM1,MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Roller PTR
702895	Caterpillar RM500 Reclaimer	PM1,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	05/11/2021		Corrective Order	WO Completed	Road Reclaimer
702929	Landcruiser DC	MANTENIMIENTO CORRECTIVO	MANTENIMIENTO CORRECTIVO	05/11/2021		Corrective Order	WO Completed	Pickup truck
702930	Toyota Hilux	CAMBIO DE RETROVISOR RH	RETROVISOR GOLPEADO, BASE PARTIDA	05/11/2021		Corrective Order	WO Completed	Pickup truck
702931	Hilux DC	MANTENIMIENTO CORRECTIVO	MANTENIMIENTO CORRECTIVO	05/11/2021		Corrective Order	WO Completed	Pickup truck
702932	Landcruiser TC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITES Y FILTRO	05/11/2021		Corrective Order	WO Completed	Pickup truck
702933	Landcruiser TC	MANTENIMIENTO CORRECTIVO	CAMBIO DE TERMINALES DE DIRECCION	05/11/2021		Corrective Order	WO Completed	Pickup truck
702934	Ford Hilux D/C Light Vehicle	MANTENIMIENTO CORRECTIVO	CAMBIO DE COMPONENTES	05/11/2021		Corrective Order	WO Completed	Pickup truck
702935	Hilux DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE ESCOLTA	05/11/2021		Corrective Order	WO Completed	Pickup truck
703044	Mobile equipment	Insumos de taller	INSUMOS DE TALLER	06/11/2021		Corrective Order	WO Completed	Area
703046	Hyster E70xn 3t Forklift (E)	equipo no enciende	EQUIPO NO ENCIENDE	06/11/2021		Corrective Order	WO Completed	Forklift
703047	Freightliner Columbia Cl112	Llanta flat	LLANTA FLAT	06/11/2021		Corrective Order	WO Completed	Mule truck
703048	Gallegos Flatbed Trailer	Llanta flat	LLANTA FLAT	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703049	USP&E GP700/V-A 700 kVa	FALLO DE VOLTAGE	VOLTAGE AC ELEVADO	06/11/2021 11640 horas		Corrective Order	WO Completed	Generator
703050	Hyster H300 13t Forklift (M)	Cambio de escobillas	CAMBIO DE ESCOBILLAS	06/11/2021		Corrective Order	WO Completed	Forklift
703051	Grove RT9130E 120TON	A/c NO FUNCIONA	AIRE ACONDICIONADO NO FUNCIONA	06/11/2021		Corrective Order	WO Completed	Crane/Hoist
703062	Freightliner M112 Truck Tip	Llanta delantera flat	LLANTA DELANTERA FLAT	06/11/2021		Corrective Order	WO Completed	Tipper

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
703063	Caterpillar 140K	Se mete el polvo a la cabina	SE METE EL POLVO A LA CABINA	06/11/2021		Corrective Order	WO Completed	Grader
703073	Boom Truck Iveco Tector	REVISION/INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Boom truck
703074	ATR-0000-001 4+320 AGRICO	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Tractor
703082	International 7400 SBA Fire Tr	INSPECCION GENERAL Y ENGRASE	EQUIPO DE EMERGENCIA	06/11/2021		Corrective Order	WO Completed	Fire truck
703088	ATLAS COPCO HILIGHT V5+	CORRECTIVO	CORRECTIVO	06/11/2021 958 hrs		Corrective Order	WO Completed	Light Tower
703089	Caterpillar 140K	Bolsa de aire del asiento no s	BOLSA DE AIRE DEL ASIENTO NO S	06/11/2021		Corrective Order	WO Completed	Grader
703093	Caterpillar 140K	Fuga de aceite en el motor	FUGA DE ACEITE EN EL MOTOR	06/11/2021		Corrective Order	WO Completed	Grader
703096	Case 110JX Tractor Cable Handl	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Tractor
703100	Internation 4400 SBA 6x4 Boom	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Boom truck
703104	Freightliner CI 120	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Mule truck
703108	Freightliner CI 120	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Mule truck
703133	Freightliner M112 Truck Tip	REVISION/INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Tipper
703136	Freightliner M112 Truck Tip	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Tipper
703149	Freightliner CI 120	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Mule truck
703155	Freightliner CI 120	INSPECCION / INSTALACION GPS	EQUIPO SATRACK	06/11/2021		Corrective Order	WO Completed	Mule truck
703197	Hyster H800 32t Forklift (M)	INSPECCION Y CALIBRACION	INSPECCION MECANICA	06/11/2021		Corrective Order	WO Completed	Forklift
703202	Tennant T7 Scrubber	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703210	Tennant T7 Scrubber	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703211	Tennant T7 Scrubber	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703216	Tennant S30 Sweeper	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703236	Tennant S30 Sweeper	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703238	Tennant S30 Sweeper	INSPECCION MECANICA	EQUIPO COPAMA	06/11/2021		Corrective Order	WO Completed	Scrubber / Sweeper
703240	LB002 725 CAT	PM2,MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	06/11/2021		Corrective Order	WO Completed	Truck
703250	Gallegos Flatbed Trailer	1 LLANTA FLATEADA	1 LLANTA FLATEADA	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703252	Intraax 53121 Hendrickso	UNA LLANTA FLATEADA+CAMBIO	UNA LLANTA FLATEADA+CAMBIO	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703261	Gallegos Flatbed Trailer	2 LLANTAS FLATEADAS	2 LLANTAS FLATEADAS	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703263	Gallegos Flatbed Trailer	FRENOS	FRENOS	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703266	Intraax 53121 Hendrickso	FUGA DE AIRE	FUGA DE AIRE	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703269	Freightliner CI 120	FRENOS+FLAT	FRENOS+FLAT	06/11/2021		Corrective Order	WO Completed	Mule truck
703297	Gallegos Flatbed Trailer	MANGUERAS DE AIRE ROTAS	MANGUERAS DE AIRE ROTAS	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703345	Pramac GSW25P 17KVA	CORRECTIVO	CONEXION DE GENERADOR	06/11/2021 4946 hrs		Corrective Order	WO Completed	Generator
703539	Caterpillar D8T Dozer	soldadura en guardas	SOLDADURAS EN GUARDAS	06/11/2021		Corrective Order	WO Completed	Dozer
703568	Hyster H300 13t Forklift (M)	Reparacion de llanta	LLANTA FLAT	06/11/2021		Corrective Order	WO Completed	Forklift
703583	John Deere 9370R Tractor	Programacion de equipo	PROGRAMACION DE EQUIPO	06/11/2021		Corrective Order	WO Completed	Tractor
703600	Hilux DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	06/11/2021		Corrective Order	WO Completed	Pickup truck
703601	Hilux DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	06/11/2021		Corrective Order	WO Completed	Pickup truck
703617	Tool Trucks	cisterna flat	CISTERNA FLAT	06/11/2021		Corrective Order	WO Completed	Area
703618	Mobile equipment	JCB alquilado llanta	CAMBIO DE LLANTA	06/11/2021		Corrective Order	WO Completed	Area
703619	Gallegos 28M3 Lime Tank	tuberia de descarga tapadas	TUBERIA DE DESCARGA TAPADAS	06/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703620	Freightliner M2 106 Refrigerat	cajeta defectuosa sin remachee	REPARACION DE CAJEA PARTE SUPERIOR	06/11/2021		Corrective Order	WO Completed	Refrigerator truck
703621	Landcruiser DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	06/11/2021		Corrective Order	WO Completed	Pickup truck
703762	Hilux DC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITES Y FILTROS	07/11/2021		Corrective Order	WO Completed	Pickup truck
703763	Hilux DC	Cambio de vidrio Puerta Chofer	VIDRIO PARTIDO	07/11/2021		Corrective Order	WO Completed	Pickup truck
703764	Landcruiser DC	CAMBIO DE CONECTOR DE H4 RH	CONECTOR DETERIORADO	07/11/2021		Corrective Order	WO Completed	Pickup truck
703765	Isuzu NMR85L	REVISION DE MOTOR	MOTOR REQUIERE REPARACION/TRANCADO	07/11/2021		Corrective Order	WO Completed	Truck
703766	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE BATERIA, BUJES DE MULLES	07/11/2021		Corrective Order	WO Completed	Pickup truck
703768	Landcruiser DC	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITES Y FILTROS	07/11/2021		Corrective Order	WO Completed	Pickup truck
703773	Freightliner Columbia CI112	Alarma de reversa no funciona	CAMBIO DE ALARMA DE REVERSA	07/11/2021		Corrective Order	WO Completed	Mule truck
703781	Grove RT880E 75TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021 90017025	264.5 hrs	Corrective Order	WO Completed	Crane/Hoist
703788	Caterpillar RM500 Reclaimer	Soldadura de acople de manguer	SOLDADURA DE ACOUPLE DE MANGUER	07/11/2021 2021W45		Corrective Order	WO Completed	Road Reclaimer
703789	CAT 930K	cambio de 2 bateria	CAMBIO DE BATERIA	07/11/2021		Corrective Order	WO Completed	Loader
703808	Hyster E70xn 3t Forklift (E)	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Completed	Forklift
703811	Hyster E70xn 3t Forklift (E)	BATTERY MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Completed	Forklift
703830	Gallegos Flatbed Trailer	cambio de llantas	CAMBIO DE LLANTAS	07/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703837	Intraax 53121 Hendrickso	cambio de llantas	CAMBIO DE LLANTAS	07/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703840	Gallegos Flatbed Trailer	Cambio de llantas	CAMBIO DE LLANTAS	07/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
703864	Toyota Hilux	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/11/2021		Corrective Order	WO Completed	Pickup truck
703876	Grove GMK 4080 80TON	PREVENTIVE MAINTENANCE	PREVENTIVE MAINTENANCE	07/11/2021		Corrective Order	WO Completed	Crane/Hoist
703948	Caterpillar DE165E0 165 kVa	PM1 CAT DE165E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 18126 hrs		PM Orders	WO Completed	Generator
703949	Caterpillar D110 E2 100KVA	PM1 CAT D110 E2 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 15556 hrs		PM Orders	WO Completed	Generator
703953	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 19951 hrs		PM Orders	WO Completed	Generator
703954	PRAMAC GSW560V 407 kVa	PM1 PRA GSW560V MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 63238 hrs		PM Orders	WO Completed	Generator
703956	SDMO J60U 60KVA	PM1 SDM J60U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 1083 horas		PM Orders	WO Completed	Generator
703957	Caterpillar DE88E0 58 kVa	PM1 CAT DE88E0 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 39005 hrs		PM Orders	WO Completed	Generator
703958	PRAMAC GSW65 48 kVa	PM1 PRA GSW65 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 26467 hrs		PM Orders	WO Completed	Generator
703964	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	07/11/2021 1000 horas		PM Orders	WO Completed	Light Tower
703975	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	07/11/2021		Corrective Order	WO Completed	Pickup truck
703997	Eagle Beaver 50sgl-Pt	Relleno de aceite hidraulico	RELLENO DE ACEITE HIDRAULICO	07/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
704023	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 66 hrs		PM Orders	WO Completed	Generator
704024	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 8259 hrs		PM Orders	WO Completed	Generator
704026	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 10423 hrs		PM Orders	WO Completed	Generator
704027	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 16810 hrs		PM Orders	WO Completed	Generator
704028	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 839 horas		PM Orders	WO Completed	Generator
704029	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 9774 HRS		PM Orders	WO Completed	Generator
704030	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 16487 horas		PM Orders	WO Completed	Generator
704031	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 46084 horas		PM Orders	WO Completed	Generator
704032	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 8644 horas		PM Orders	WO Completed	Generator
704034	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 3633 hors		PM Orders	WO Completed	Generator
704035	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 581 horas		PM Orders	WO Completed	Generator
704037	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 361 horas		PM Orders	WO Completed	Generator
704038	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 11768 horas		PM Orders	WO Completed	Generator
704039	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 163 horas		PM Orders	WO Completed	Generator
704040	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 26371 horas		PM Orders	WO Completed	Generator
704056	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 25139 horas		PM Orders	WO Completed	Generator
704057	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021 18057 horas		PM Orders	WO Completed	Generator
704058	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	07/11/2021		PM Orders	WO Completed	Generator
704134	CAT 930K	Revision de fugas hidraulicas	REVISION DE FUGAS HIDRAULICAS EN EL EQUIPO	07/11/2021		Corrective Order	WO Completed	Loader
704157	USP&E GP700S/V-A 700 kVa	CORRECTIVO	CORREGIR FALLA EN CONTROL BLOQUEADO Y ARRANQUE	07/11/2021 18058 hrs		Corrective Order	WO Completed	Generator
704164	Freightliner M2 106 Hydroseedi	Reparacion de cableado	REPARACION DE CABLEADO ELECTRICO DE BOMBA	07/11/2021		Corrective Order	WO Completed	Truck
704167	Freightliner M2 106 Hydroseedi	Revision de falla en equipo	EQUIPO PIERDE FUERZA EN LAS LOMAS	07/11/2021		Corrective Order	WO Completed	Truck
704190	Linde T30D	Palanca rota montacarga	PALANCA ROTA MONTACARGA	07/11/2021 4372.3 Hrs		Corrective Order	WO Completed	Forklift
704215	SJS SJ6530	ajuste de tornilleria	AJUSTE DE TORNILLERIA	07/11/2021		Corrective Order	WO Completed	Compactor
704258	Olympian GEP150 135 kVa	CAMBIO DE CARGADOR DE BATERIA	CAMBIO DE CARGADOR DAÑADO	07/11/2021 66.7 horas		Corrective Order	WO Completed	Generator
704261	Grove RT880E 75TON	Cambio de bateria	CAMBIO DE BATERÍA	07/11/2021		Corrective Order	WO Completed	Crane/Hoist
704282	Valle Grande Archeology Office	limpieza de paredes	LIMPIEZA DE PAREDES	08/11/2021		Corrective Order	WO Completed	Building
704418	Logistic and Transport Area 22	Remplazo de lamparas	REEMPLAZO DE LAMPARAS	08/11/2021		Corrective Order	WO Completed	Building
704419	Heliport Offices	topes de estacionamiento	TOPEs DE ESTACIONAMIENTO	08/11/2021 Se requiere reparaciones WO.		Corrective Order	WO Completed	Building
704423	Heliport Offices	reemplazo de lamparas	REEMPLAZO DE LAMPARAS	08/11/2021		Corrective Order	WO Completed	Building
704425	Heliport Offices	reparacion de puertas	REPARACION DE PUERTAS	08/11/2021		Corrective Order	WO Completed	Building
704460	Grove RT880E 75TON	Equipo no enciende	TERMINRL NEGATIVO FLOJO	08/11/2021		Corrective Order	WO Completed	Crane/Hoist
704461	Grove RT600E 50TON	FALLA MOTOR ACTIVA	FALLA MOTOR ACTIVA	08/11/2021		Corrective Order	WO Completed	Crane/Hoist
704466	Caterpillar D110 E2 100KVA	CAMBIO DE RADIADOR ROTO	CAMBIO E RADIADOR POR FUGA DE REFRIGERANTE	08/11/2021 19078 horas		Corrective Order	WO Completed	Generator
704469	Valle Grande Environment Offic	limpieza de paredes	LIMPIEZA DE PAREDES	08/11/2021		Corrective Order	WO Completed	Building
704471	Valle Grande Environment Offic	extractor de baño	EXTRACTOR DE BAÑO	08/11/2021		Corrective Order	WO Completed	Building
704482	Pit Operations Offices	revisar aire	REVISAR AIRE	08/11/2021		Corrective Order	WO Completed	Building
704531	CAT 930K	Revision al sistema AFEX	REVISION AL SISTEMA AFEX	08/11/2021		Corrective Order	WO Completed	Loader
704554	Caterpillar 14H Motorgrader	Llanta flat del lado derecho	LLANTA FLAT DEL LADO DERECHO	08/11/2021		Corrective Order	WO Completed	Grader
704586	Mobile equipment	Reemplazo de balineras	REEMPLAZO DE BALINERAS DE BANDEJAS DE ACEITE	08/11/2021		Corrective Order	WO Completed	Area
704636	Mobile equipment	relleno de aceite de motor	RELLENO DE ACEITE DE MOTOR	08/11/2021		Corrective Order	WO Completed	Area
704637	Caterpillar 416E	El seguro del pasador que suje	EL SEGURO DEL PASADOR QUE SUJE	08/11/2021		Corrective Order	WO Completed	Backhoe
704696	Landcruiser DC	Mantenimiento correctivo	MANTENIMIENTO CORRECTIVO	08/11/2021		Corrective Order	WO Completed	Pickup truck
704698	Landcruiser DC	reemplazo de aceite y filtros	MANTENIMIENTO PREVENTIVO	08/11/2021		Corrective Order	WO Completed	Pickup truck
704703	Hilux DC	cambio de bateria	ARRANQUE AUXILIAR	08/11/2021		Corrective Order	WO Completed	Pickup truck
704707	Landcruiser TC	cambio de tabores, pernos y tu	CAMBIO DE TABORES, PERNOS Y TUERCAS	08/11/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
704710	Hilux DC	cambio de cremallera	CAMBIO DE CREMALLERA	08/11/2021		Corrective Order	WO Completed	Pickup truck
704713	Hilux DC	cambio de pernos y tuercas	CAMBIO DE PERNOS Y TUERCAS	08/11/2021		Corrective Order	WO Completed	Pickup truck
704716	Hilux DC	Rep. de actuador delantero	REPARACION DE 4X4	08/11/2021		Corrective Order	WO Completed	Pickup truck
704718	Landcruiser DC	cambio de fusible de 20 amp	REVISION DE LUCES	08/11/2021		Corrective Order	WO Completed	Pickup truck
704776	Bomag BW24RH	No enciende	NO ENCIENDE	08/11/2021		Corrective Order	WO Completed	Roller PTR
704803	Linde T30D	Inspeccion electrica del equip	LUCES NO FUNCIONAN .	08/11/2021		Corrective Order	WO Completed	Forklift
704855	PT044 HINO DUTRO 300	lamparas	LAMPARAS	08/11/2021		Corrective Order	WO Completed	Light Vehicles
704882	Hyster E70xn 3t Forklift (E)	revisar baterias, lubricacion	REVISAR BATERIAS, LUBRICACION	08/11/2021		Corrective Order	WO Completed	Forklift
704934	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	08/11/2021		Corrective Order	WO Completed	Pickup truck
704978	Mobile equipment	Reparacion de llanta CM-1392	REPARACION DE LLANTA DE EQUIPO NO LISTADO	08/11/2021		Corrective Order	WO Completed	Area
705427	Coaster	CAMBIO ABANICOS DE CONDENSADOR	BANICOS CON GOLPES, BUJES DESGASTADOS	09/11/2021		Corrective Order	WO Completed	Bus
705428	Hiace Bus	MANTENIMIENTO PREVENTIVO	REEMPLAZO DE ACEITES Y FILTROS	09/11/2021		Corrective Order	WO Completed	Bus
705429	Hiace Bus	MANTENIMIENTO CORRECTIVO	CAMBIO DE TERMINAL DE DIRECCION, CAMBIO DE BANDAS DE FRENO	09/11/2021		Corrective Order	WO Completed	Bus
705431	Hilux DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE PASTILLAS DE FRENOS, BOMBILLO HALOGENO, PERNOS Y TUERCAS	09/11/2021		Corrective Order	WO Completed	Pickup truck
705432	Hilux DC	REVISION GENERAL	CAMBIO DE TUERCA Y PERNO DE RUEDAS	09/11/2021		Corrective Order	WO Completed	Pickup truck
705510	BT014 M2-112 Freightliner	REEMPLAZO DE2 LLANTAS	REEMPLAZO DE2 LLANTAS	09/11/2021		Corrective Order	WO Completed	.
705519	Caterpillar 416E	Mantiene la alarma de presión	MANTIENE LA ALARMA DE PRESIÓN	09/11/2021		Corrective Order	WO Completed	Backhoe
705522	Caterpillar 416E	Tapadera o cobertura principal	TAPADERA O COBERTURA PRINCIPAL	09/11/2021		Corrective Order	WO Completed	Backhoe
705527	Gallegos Flatbed Trailer	CAMBIO DE LLANTAS	CAMBIO DE LLANTAS	09/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
705528	BT014 M2-112 Freightliner	REP. MANGUERA HIDRAULICA	REP. MANGUERA HIDRAULICA	09/11/2021		Corrective Order	WO Completed	.
705613	Freightliner M2 106	El quemador de arriba no prend	EL QUEMADOR DE ARRIBA NO PREND	09/11/2021		Corrective Order	WO Completed	Bitumen truck
705646	Caterpillar D8T Dozer	El master switch no da vuelta	EL MASTER SWITCH NO DA VUELTA	09/11/2021		Corrective Order	WO Completed	Dozer
705650	Mobile equipment	Suministro de materiales	SUMINISTRO DE MATERIALES	09/11/2021		Corrective Order	WO Completed	Area
705672	Caterpillar D110 E2 100KVA	ENTRAGA DE EQUIPO	REEMPLAZO DEL GS-190	09/11/2021	19079.7 horas	Corrective Order	WO Completed	Generator
705973	Freightliner M112 Truck Tip	Llanta trasera izquierda baja	LLANTA TRASERA IZQUIERDA BAJA	09/11/2021		Corrective Order	WO Completed	Tipper
706157	Coaster	cambio de 2 llantas	LLANTAS EN MAL ESTADO	09/11/2021		Corrective Order	WO Completed	Bus
706158	Landcruiser DC	cambio de 2 llantas	LLANTAS EN MAL ESTADO	09/11/2021		Corrective Order	WO Completed	Pickup truck
706160	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	09/11/2021		Corrective Order	WO Completed	Pickup truck
706161	Landcruiser DC	Reparacion de 1 llanta	REPARACION DE 1 LLANTA	09/11/2021		Corrective Order	WO Completed	Pickup truck
706162	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	09/11/2021		Corrective Order	WO Completed	Pickup truck
706165	Caterpillar 740B EJ ADT	cambio de swicht en falla	CAMBIO DE SWICHT EN FALLA	09/11/2021		Corrective Order	WO Completed	Articulated dump truck
706166	Manitou Mht-X1490 9t Telehand	bajo nivel de aceite de difren	BAJO NIVEL DE ACEITE DE DIFRENCIAL	09/11/2021		Corrective Order	WO Completed	Telehender
706169	ATR-0000-001 4+320 AGRICO	Ajuste de tornilleria	AJUSTE DE TORNILLERIA	09/11/2021		Corrective Order	WO Completed	Tractor
706173	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	09/11/2021		Corrective Order	WO Completed	Pickup truck
706174	Bell 225f 4t Forklift (M)	Reemplazo de cinturon	REEMPLAZO DE CINTURON DE SEGURIDAD	09/11/2021	horas 469.1	Corrective Order	WO Completed	Forklift
706188	Expert Power PN45 10KVA	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	09/11/2021	9443 hrs	Corrective Order	WO Completed	Generator
706343	Freightliner M2 106 Hydroseedi	Revision de equipo	REVISION DE CADENAS E HILO GRAFITADO EN POLEAS	10/11/2021		Corrective Order	WO Completed	Truck
706361	Security Checkpoint Gold Room	REPARACION DE URINAL	REPARACION DE URINAL	10/11/2021	15.1 hrs	Corrective Order	WO Completed	Building
706362	Security Checkpoint Gold Room	REP. CERRADURA Y PAREDES LAT.	REP. CERRADURA Y PAREDES LAT.	10/11/2021	15.1 hrs	Corrective Order	WO Completed	Building
706365	Gallegos 28M3 Lime Tank	Reparacion de llanta	REPARACION DE LLANTA	10/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
706372	LB002 725 CAT	Correccion de fuga hidraulica	CORRECCION DE FUGAS DE ACEITE EN EL EQUIPO	10/11/2021		Corrective Order	WO Completed	Truck
706405	Caterpillar 740B EJ ADT	REEMPLAZO INTERRUPTOR BYPASS	EQUIPO IASA	10/11/2021		Corrective Order	WO Completed	Articulated dump truck
706406	Caterpillar 740B EJ ADT	Cambio de swicht y filtro	CAMBIO DE SWICHT Y FILTRO	10/11/2021		Corrective Order	WO Completed	Articulated dump truck
706415	Gallegos Flatbed Trailer	1 LLANTA FLATEADA	1 LLANTA FLATEADA	10/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
706418	ATR-0000-001 4+320 AGRICO	Cambio de tornillos	TORNILLOS EN MAL ESTADO	10/11/2021		Corrective Order	WO Completed	Tractor
706450	Unimog Service Truck	Reparación llanta Unimog 05	REPARACIÓN LLANTA UNIMOG 05	10/11/2021		Corrective Order	WO Completed	Truck
706473	Hino Serie 300	cambio de bujes, pines de muel	MANTENIMIENTO CORRECTIVO	10/11/2021		Corrective Order	WO Completed	Truck
706476	Hilux DC	cambio de bateria	BATERIA ENMAL ESTADO	10/11/2021		Corrective Order	WO Completed	Pickup truck
706477	Landcruiser DC	cambio de bombillo	REVISION DE LUCES	10/11/2021		Corrective Order	WO Completed	Pickup truck
706479	Coaster	cambio de fusibles y bombillos	PROBLEMAS DE LUCES	10/11/2021		Corrective Order	WO Completed	Bus
706481	Hilux DC	cambio de escobillas y bombill	MANTENIMIENTO CORRECTIVO	10/11/2021		Corrective Order	WO Completed	Pickup truck
706482	Coaster	cambio de bateria	MANTENIMIENTO CORRECTIVO	10/11/2021		Corrective Order	WO Completed	Bus
706484	PRAMAC GSW460V 460 kVa	MANTENIMIENTO CORRECTIVO	INSTALACIÓN DE TUBO DE ESCAPE	10/11/2021	7105 horas	Corrective Order	WO Completed	Generator
706493	Landcruiser DC	limpieza de sistema de combust	PERDIDA DE FUERZA	10/11/2021		Corrective Order	WO Completed	Pickup truck
706494	Coaster	reparacion de cableado electri	CORTO EN LUCES BAJAS	10/11/2021		Corrective Order	WO Completed	Bus
706495	Landcruiser DC	reparacion electrica	REPARACION ELECTRICA	10/11/2021		Corrective Order	WO Completed	Pickup truck
706496	Landcruiser DC	cambio de cocobolas	CAMBIO DE COCOBOLAS	10/11/2021		Corrective Order	WO Completed	Pickup truck
706497	Landcruiser DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	10/11/2021		Corrective Order	WO Completed	Pickup truck
706543	Caterpillar 14M Motorgrader	Necesita cambio de hoja	NECESITA CAMBIO DE HOJA	10/11/2021		Corrective Order	WO Completed	Grader
706547	Caterpillar 140K	Revision de equipo	ALARAMA DE ALTA TEMPERATURA DE REFRIGERANTE	10/11/2021		Corrective Order	WO Completed	Grader
706579	Caterpillar 14M Motorgrader	CAMBIO DE HOJA DE CORTE	CAMBIO DE HOJA DE CORTE	10/11/2021		Corrective Order	WO Completed	Grader
706657	JLG 800 AJ Manlift	revision electrica	REVISION ELECTRICA	10/11/2021		Corrective Order	WO Completed	Manlift
706661	Unimog Service Truck	Reparacion de tanque de diesel	REPARACION DE TANQUE DE DIESEL	10/11/2021		Corrective Order	WO Completed	Truck
706666	Manitou Mht-X860 6t Telehand	bajo nivel de coolam	EQUIPO SE CALENTO	10/11/2021		Corrective Order	WO Completed	Telehender

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
706715	Gallegos Flatbed Trailer	ESTANDARIZACION DE LUCES	ESTANDARIZACION DE LUCES	10/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
706719	Grove RT600E 50TON	relleno de aceite de motor	RELLENO DE ACEITE DE MOTOR	10/11/2021		Corrective Order	WO Completed	Crane/Hoist
706734	Gallegos Flatbed Trailer	Instalacion de llanta	INATALACION DE LLANTA	10/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
706756	PRAMAC GSW460V 460 kVa	LLAMADA DE EMERGENCIA	PARO DE EMERGENCIA ACTIVADO	11/11/2021	7105 hrs	Corrective Order	WO Completed	Generator
706866	Caterpillar 226b Skid Steer L	Reemplazo de bateria	REEMPLAZO DE BATERIA	11/11/2021		Corrective Order	WO Completed	Skid Steer
706893	Hilux DC	Reparacion de llanta	REPARACION DE LLANTA	11/11/2021		Corrective Order	WO Completed	Pickup truck
706933	Gallegos Lime Tank	UNA LLANTA FLATEADA	UNA LLANTA FLATEADA	11/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
706947	Boom Truck Iveco Tector	cambio de aceite de motor	CAMBIO DE ACEITE DE MOTOR	11/11/2021		Corrective Order	WO Completed	Boom truck
706961	Hyster H300 Forklift	cambio de baterias	BATRIAS EN MAL ESTADO	11/11/2021		Corrective Order	WO Completed	Forklift
706999	Hiace Bus	cambio de llanta	CAMBIO DE LLANTA	11/11/2021		Corrective Order	WO Completed	Bus
707010	Landcruiser TC	cambio de 4 llantas	LLANTAS EN MAL ESTADO	11/11/2021		Corrective Order	WO Completed	Pickup truck
707048	Bell 225f 4t Forklift (M)	revision de equipo	REVISION DE EQUIPO	11/11/2021	125.10 hrs	Corrective Order	WO Completed	Forklift
707049	SJS SJ6530	Rev y reparacion de equipo	REVISION Y REPARACION DE EQUIPO	11/11/2021		Corrective Order	WO Completed	Compactor
707065	Unimog Service Truck	Reparacion de tanque de combus	REPARACION DE TANQUE DE COMBUSTIBLE	11/11/2021		Corrective Order	WO Completed	Truck
707096	JLG 800 AJ Manlift	cambio de manguera	CAMBIO DE MANGUERA	11/11/2021	7.070.46 hrs	Corrective Order	WO Completed	Manlift
707102	Caterpillar CS533E Compactor	No le funciona el A/C	NO LE FUNCIONA EL A/C	11/11/2021	Hrs	Corrective Order	WO Completed	Compactor
707122	Ford Ranger	Reparar sist frenos y direccio	DESGASTE	11/11/2021		Corrective Order	WO Completed	Pickup truck
707168	Coaster Bus	REPARACION DE PISO Y AIRCO	ROTURA	11/11/2021		Corrective Order	WO Completed	Bus
707192	Caterpillar DE22E3 17.6 kVa	MANTENIMIENTO CORRECTIVO	INSTALACIÓN DE BATERÍA	11/11/2021	14935 horas	Corrective Order	WO Completed	Generator
707199	Freightliner M2 106 Sucker Tru	cambio de fan y damper	CAMBIO DE FAN Y DAMPER	11/11/2021		Corrective Order	WO Completed	Sucker truck
707243	Manitou Mht-X1490 9t Telehand	desintalacion de diferencial	DESINTALACION DE DIFERENCIAL	11/11/2021		Corrective Order	WO Completed	Telehender
707283	Caterpillar CS533E Compactor	Revision de A/C	REVISION DE A/C	11/11/2021		Corrective Order	WO Completed	Compactor
707284	Landcruiser DC	Reparacion de llanta	REPARACION DE LLANTA	11/11/2021		Corrective Order	WO Completed	Pickup truck
707290	Freightliner M2 106 Refrigerat	Revision de fan clutch	REVISION DE FAN CLUTCH DEL MOTOR	11/11/2021		Corrective Order	WO Completed	Refrigerator truck
707363	Caterpillar 14M Motorgrader	Reemplazo de baterias	REEMPLAZO DE BATERIAS	12/11/2021		Corrective Order	WO Completed	Grader
707399	MAGNUM Light Tower	MANTENIMIENTO CORRECTIVO	CAMBIO DE MOTOR DIESEL	12/11/2021	27551 horas	Corrective Order	WO Completed	Light Tower
707420	Mobile equipment	CONSUMIBLE OCTUBRE	CONSUMIBLE OCTUBRE	12/11/2021		Corrective Order	WO Completed	Area
707552	Bomag BW24RH	Mofle en mal estado (roto)	MOFLE EN MAL ESTADO (ROTO)	12/11/2021		Corrective Order	WO Completed	Roller PTR
707604	LB002 725 CAT	Cambio de manguera Afex	MANGUERAS DE AFEX EN MAL ESTADO	12/11/2021		Corrective Order	WO Completed	Truck
707620	Freightliner Columbia CI112	Ajuste de escolta y fuga de ac	ESCOLTA SUELTA Y FUGA DE TRANSMISION	12/11/2021		Corrective Order	WO Completed	Mule truck
707876	Coaster	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	12/11/2021		Corrective Order	WO Completed	Bus
707877	Landcruiser DC	Reparacion de frenos, y cocobo	REPARACION DE FRENOS, Y COCOBOLAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
707878	Hilux DC	cambio de lampara trasera	LAMPARA TRASERA ROTA	12/11/2021		Corrective Order	WO Completed	Pickup truck
707879	Coaster Bus	cambio de bateria	REVISION DE SITEMA DE ARRANQUE	12/11/2021		Corrective Order	WO Completed	Bus
707881	Hilux DC	cambio de fusible y bombillo	REVISION DE LUCES	12/11/2021		Corrective Order	WO Completed	Pickup truck
707882	Hilux DC	mantenimiento preventivo	MANTENIMIENTO PREVENTIVO	12/11/2021		Corrective Order	WO Completed	Pickup truck
707884	Freightliner M2 106 Hydroseedi	cambio de bateria	CAMBIO DE BATERIA	12/11/2021		Corrective Order	WO Completed	Truck
707892	Landcruiser TC	cambio de crucetas	CRUCETAS EN MAK ESTADO	12/11/2021		Corrective Order	WO Completed	Pickup truck
707893	Toyota Land Cruiser	cambio de balineras de rueda	REVISION DE BALINERAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
707894	Landcruiser DC	cambio de polea y fajas	CAMBIO DE POLEA Y FAJAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
707895	Landcruiser DC	cambio de bateria y faja	BATERIA EN MAL ESTADO	12/11/2021		Corrective Order	WO Completed	Pickup truck
707897	Hino Serie 300	cambio de termianles	TERMINALES EN MAL ESTADO	12/11/2021		Corrective Order	WO Completed	Truck
707933	Caterpillar 740B EJ ADT	Cambio de tuberias de escape	DAÑOS EN TUBERIAS DE ESCAPE	12/11/2021		Corrective Order	WO Completed	Articulated dump truck
707961	Freightliner Columbia CI112	reparacion de a/c	REPARACION DE A/C	12/11/2021	72,215.90 km	Corrective Order	WO Completed	Mule truck
708019	Hilux DC	cambio de terminal	CAMBIO DE TERMINAL	12/11/2021		Corrective Order	WO Completed	Pickup truck
708192	Landcruiser TC	reparacion de 1 llanta	REPARACION DE 1 LLANTA	12/11/2021		Corrective Order	WO Completed	Pickup truck
708194	Gallegos Flatbed Trailer	cambio de llanta	CAMBIO DE LLANTA	12/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
708207	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
708208	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
708227	Hilux DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	12/11/2021		Corrective Order	WO Completed	Pickup truck
708295	General Mod Quad Buildings	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	13/11/2021		PM Orders	WO Completed	Building
708296	Heliport Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	13/11/2021		PM Orders	WO Completed	Building
708297	Logistic and Transport Area 22	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	13/11/2021		PM Orders	WO Completed	Building
708327	Freightliner CI 120	Reemplazo de pulmones de freno	REEMPLAZO DE PULMON DE FRENO	13/11/2021		Corrective Order	WO Completed	Mule truck
708348	Boom Truck Iveco Tector	Revision de equipo	REVISION DE EQUIPO	13/11/2021		Corrective Order	WO Completed	Boom truck
708398	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	FALTA DE COOLANT	13/11/2021	25139 horas	Corrective Order	WO Completed	Generator
708416	Caterpillar 226b Skid Steer L	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	13/11/2021		Corrective Order	WO Completed	Skid Steer
708433	Hiace Bus	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	13/11/2021		Corrective Order	WO Completed	Bus
708485	Unimog Service Truck	Reparacion retrovisor UMT104	REPARACION RETROVISOR UMT104	13/11/2021		Corrective Order	WO Completed	Truck
708555	Caterpillar 14M Motorgrader	En el ángulo de dirección 2 la	EN EL ÁNGULO DE DIRECCIÓN 2 LA	13/11/2021		Corrective Order	WO Completed	Grader
708558	Caterpillar 14M Motorgrader	El joystick de giro de la c	EL JOYSTICK DE GIRO DE LA C	13/11/2021		Corrective Order	WO Completed	Grader
708566	Freightliner CI 120	Cambio de Válvula	CAMBIO DE VÁLVUL;A Y FILTRO SECADOR	13/11/2021		Corrective Order	WO Completed	Mule truck
708618	Freightliner Columbia CI112	Revision de equipo	REVISION DE CRUCETAS Y FUGA DE AIRE.	13/11/2021		Corrective Order	WO Completed	Mule truck
708633	Eagle Beaver 50sgl-Pt	FUGA DE AIRE / CABLE DE CHOQUE	FUGA DE AIRE / CABLE DE CHOQUE	13/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
708697	Gallegos Flatbed Trailer	FRENOS	FRENOS	13/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
708787	Freightliner CI 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Mule truck
708788	Hyster H700 Forklift	PM 50HRS	PM 50HRS POR CAMBIO DE MOTOR	13/11/2021		Corrective Order	WO Completed	Forklift
708790	Freightliner CI 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Mule truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
708813	Freightliner Cl 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Mule truck
708822	Freightliner Cl 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Mule truck
708829	Freightliner Cl 120	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Mule truck
708835	Mack Trucks Gu813e	PM MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Truck
708846	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	13/11/2021		Corrective Order	WO Completed	Pickup truck
708859	Freightliner M2 106 Hydroseedi	CAMBIO DE HILO GRAFITADO	CAMBIO DE HILO GRAFITADO	13/11/2021		Corrective Order	WO Completed	Truck
708890	PRAMAC GSW460V 460 kVa	MANTENIMIENTO CORRECTIVO	DESMONTAJE DEL ALTERNADOR AC	13/11/2021	19894 horas	Corrective Order	WO Completed	Generator
709010	Caterpillar 12M	Necesita cambio de hoja	NECESITA CAMBIO DE HOJA	13/11/2021		Corrective Order	WO Completed	Grader
709011	Hilux DC	La correa esta generando un ru	LA CORREA ESTA GENERANDO UN RU	13/11/2021		Corrective Order	WO Completed	Pickup truck
709026	Bell 225f 4t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LUBRICACION DE EQUIPO	13/11/2021		Corrective Order	WO Completed	Forklift
709041	Bell 225f 4t Forklift (M)	INSTALACION DE GPS	INSTALACION DE GPS	13/11/2021		Corrective Order	WO Completed	Forklift
709072	Freightliner Cl 120	INSTALACION DE GPS	INSTALACION DE GPS	13/11/2021		Corrective Order	WO Completed	Mule truck
709093	Freightliner Cl 120	INSPECCION / INSTALACION GPS	INSPECCION / INSTALACION GPS	13/11/2021		Corrective Order	WO Completed	Mule truck
709099	Freightliner Cl 120	INSPECCION / INSTALACION GPS	INSTALACION DE GPS	13/11/2021		Corrective Order	WO Completed	Mule truck
709154	Caterpillar D8T Dozer	INSTALACION DE GPS	INSTALACION DE GPS	13/11/2021		Corrective Order	WO Completed	Dozer
709158	WT015 H7 CISTERNA SINOTRUK	Reparación de sistema de Luces	REPARACIÓN DE SISTEMA DE LUCES	13/11/2021		Corrective Order	WO Completed	Water truck
709174	Caterpillar 12M	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Grader
709175	Caterpillar 12M	INSPECCION HERRAMIENTA CORTE	INSPECCION	13/11/2021		Corrective Order	WO Completed	Grader
709177	Cargador 966H Wheel Loader	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	13/11/2021		Corrective Order	WO Completed	Loader
709185	Grove GMK4100L 100TON	Revision de fuga hidraulica	REVISION DE FUGA HIDRAULICA	13/11/2021		Corrective Order	WO Completed	Crane/Hoist
709197	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Bus
709198	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709200	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709201	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709202	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709203	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709204	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	13/11/2021		Corrective Order	WO Completed	Pickup truck
709302	Security Checkpoint Gold Room	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	14/11/2021		PM Orders	WO Completed	Building
709344	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/11/2021		Corrective Order	WO Completed	Pickup truck
709346	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTA	14/11/2021		Corrective Order	WO Completed	Pickup truck
709347	Landcruiser TC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/11/2021		Corrective Order	WO Completed	Pickup truck
709348	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/11/2021		Corrective Order	WO Completed	Pickup truck
709349	Landcruiser DC	Reemplazo de llantas	REEMPLAZO DE LLANTAS	14/11/2021		Corrective Order	WO Completed	Pickup truck
709355	Grove RT650E 45TON	Revision de fuga HYD	REVISION DE FUGA HIDRAULICA	14/11/2021		Corrective Order	WO Completed	Crane/Hoist
709356	Grove GMK4100L 100TON	Revision de fuga de diesel	REVISION DE FUGA DE DIESEL	14/11/2021		Corrective Order	WO Completed	Crane/Hoist
709367	Boom Truck Iveco Tector	Confeccion de bisagras	CONFECCION DE VISAGRAS DEL VAGON	14/11/2021		Corrective Order	WO Completed	Boom truck
709391	Caterpillar 14H Motorgrader	INSPECCION HERRAMIENTAS CORTE	INSPECCION MECANICA	14/11/2021		Corrective Order	WO Completed	Grader
709394	Caterpillar 14H Motorgrader	INSPECCION / INSTALACION GPS	INSTALACION DE GPS	14/11/2021		Corrective Order	WO Completed	Grader
709400	ATLAS COPCO HILIGHT V5+	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	14/11/2021	577 hors	Corrective Order	WO Completed	Light Tower
709401	Caterpillar 12M	INSPECCION /INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Grader
709404	PRAMAC GSW65 48 kVa	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	14/11/2021	26428 horas	Corrective Order	WO Completed	Generator
709408	Grove RT600E 50TON	Manguera hidráulica Rota	MANGUERA HIDRÁULICA ROTA	14/11/2021		Corrective Order	WO Completed	Crane/Hoist
709440	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	14/11/2021		Corrective Order	WO Completed	Pickup truck
709444	Caterpillar 140K	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	14/11/2021		Corrective Order	WO Completed	Grader
709458	Caterpillar 336DL	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Excavator
709518	Mobile equipment	Estación de Lavado de Ojos	ESTACIÓN DE LAVADO E OJOS	14/11/2021		Corrective Order	WO Completed	Area
709531	Cargador 966H Wheel Loader	PM01 MANTENIMIENTO PREVENTIVO	EQUIPO IASA	14/11/2021		Corrective Order	WO Completed	Loader
709543	Cargador 966H Wheel Loader	INSPECCION HERRAMIENTAS CORTE	EQUIPO IASA	14/11/2021		Corrective Order	WO Completed	Loader
709552	Caterpillar RM300	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Road Reclaimer
709561	Caterpillar CS74 Compactor	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Compactor
709713	Freightliner M2 106 Truck	INSPECCION GRUA Y CAMION	INSPECCION MECANICA	14/11/2021		Corrective Order	WO Completed	Boom truck
709720	Hilux DC	mantenimiento correctivo	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709721	Landcruiser DC	cambio de conjunto de tensora	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709722	Freightliner Columbia Cl112	INSPECCION Y ENGRASE EQUIPO	INSPECCION GENERAL	14/11/2021		Corrective Order	WO Completed	Mule truck
709723	Landcruiser TC	reemplazo de aceites y filtros	MANTENIMIENTO PREVENTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709724	Freightliner Columbia Cl112	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Mule truck
709725	Landcruiser TC	cambio de muelles y accesorios	MANTENIMEINTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709726	Landcruiser DC	cambio de filtros y aceite	MANTENIMIENTO PREVENTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709727	Landcruiser DC	cambio de sensor, bateria y ki	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709728	Hilux DC	cambio de bandas y tacos	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709731	Landcruiser TC	cambio de aceites y filtros	MANTENIMIENTO PREVENTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709733	Coaster	CAMBIO DE 3 NEUMÁTICOS	CAMBIO DE 3 NEUMÁTICOS	14/11/2021		Corrective Order	WO Completed	Bus
709734	Landcruiser TC	cambio de muelles y accesorios	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709735	Landcruiser DC	cambio de bandas, pito y engra	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709736	Coaster	cambio de filtros y aceite	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Bus
709737	Coaster	cambios de link, suspension	CAMTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Bus
709738	Ford F550	INSPECCION GENERAL MECANICA	MACANICA Y ELECTRICA	14/11/2021		Corrective Order	WO Completed	Pickup truck
709741	Landcruiser DC	cambio de refrigerante	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
709743	Hiace Bus	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	14/11/2021		Corrective Order	WO Completed	Bus
709744	Hilux DC	cambio de bateria, pito de rev	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709745	Hilux DC	cambio de filtros y aceite	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709746	International 7400 SBA Fire Tr	INSPECCION / INSTALACION GPS	GPS	14/11/2021		Corrective Order	WO Completed	Fire truck
709747	Landcruiser DC	reparacion de caja de timon	MANTENIMIENTO CORRECTIVO	14/11/2021		Corrective Order	WO Completed	Pickup truck
709748	Gallegos Flatbed Trailer	INSP FRENO/LUCES/NEUMATICOS	INSPECCION MECANICA	14/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
709752	Hyster H70ft 3t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709754	Hyster H70ft 3t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709756	Hyster E70xn 3t Forklift (E)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709768	Hyster H800 32t Forklift (M)	LIMPIEZA Y LUBRICACION CADENAS	LUBRICACION DE EQUIPO	14/11/2021		Corrective Order	WO Completed	Forklift
709769	Hyster H300 13t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709787	Hyster H70ft 3t Forklift (M)	LIMPIEZA Y LUBRICACION CADENAS	LUBRICACION DE EQUIPO	14/11/2021		Corrective Order	WO Completed	Forklift
709792	Hyster H70ft 3t Forklift (M)	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709795	Hyster H800 32t Forklift (M)	INSPECCION /INSTALACION GPS	LUBRICACION EQUIPO	14/11/2021		Corrective Order	WO Completed	Forklift
709826	Hyster H300 Forklift	LUBRICACION CADENAS Y EQUIPO	LIMPIEZA Y LUBRICACION DE CADENAS	14/11/2021		Corrective Order	WO Completed	Forklift
709830	Hyster E70xn 3t Forklift (E)	LIMPIEZA Y LUBRICACION CADENAS	LUBRICACION DE EQUIPO	14/11/2021		Corrective Order	WO Completed	Forklift
709841	PRAMAC GSW90P 74 kVa	LLAMADA DE EMERGENCIA	EQUIPO SIN COMBUSTIBLE	14/11/2021	26445.1 horas	Corrective Order	WO Completed	Generator
709854	Mobile equipment	Kit antierrames para taller	KIT ANTIDERRAMES PARA TALLER	14/11/2021		Corrective Order	WO Completed	Area
709857	PRAMAC GSW110P 82 kVa	LLAMADA DE EMERGENCIA	LAVADO DE RADIADOR	14/11/2021	15903 horas	Corrective Order	WO Completed	Generator
709861	Freightliner Cl 120	FUGA DE AIRE / CABLE DE MOTOR	FUGA DE AIRE / CABLE DE MOTOR	14/11/2021		Corrective Order	WO Completed	Mule truck
709886	Unimog Service Truck	Cambio de Sillón	CAMBIO DE SILLÓN	14/11/2021		Corrective Order	WO Completed	Truck
709892	ATLAS COPCO HILIGHT V5+	PM ATL HILIGHT V5+ MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	14/11/2021	781 hrs	PM Orders	WO Completed	Light Tower
709905	SJS SJ6530	reparacion de mangueras	MANNGUERAS ROTAS	14/11/2021		Corrective Order	WO Completed	Compactor
710132	Pit Operations Offices	2W Insp Office Build Infrastru	2W INSP OFFICE BUILD INFRASTRU	15/11/2021		PM Orders	WO Completed	Building
710155	International 7400 SBA Fire Tr	Revision de luces	REVISION DE LUCES DEL EQUIPO	15/11/2021		Corrective Order	WO Completed	Fire truck
710177	Mobile equipment	Reposicion de kit	REPOSICION DE KITS ANTI DERRAME	15/11/2021		Corrective Order	WO Completed	Area
710183	International 7400 SBA Fire Tr	Revision de codigos de falla	REVISION DE CODIGOS DE FALLA	15/11/2021		Corrective Order	WO Completed	Fire truck
710190	Caterpillar 12M	Filtro de aciete de motor	FILTRO DE ACIETE DE MOTOR	15/11/2021		Corrective Order	WO Completed	Grader
710220	Caterpillar D8T Dozer	Bajo nivel de aceite hidráulic	BAJO NIVEL DE ACEITE HIDRÁULIC	15/11/2021		Corrective Order	WO Completed	Dozer
710253	Coaster	cambio de cilindros de frenos	MANTENIMIENTO CORRECTIVO	15/11/2021		Corrective Order	WO Completed	Bus
710255	Hilux DC	cambio de clutch	CAMBIO DE CLUTCH	15/11/2021		Corrective Order	WO Completed	Pickup truck
710268	PRAMAC GSW80P 83 kVa	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	15/11/2021	13706 horas	Corrective Order	WO Completed	Generator
710314	Freightliner Cl 120	FUGA DE AIRE /AJUSTE DE FRENO	FUGA DE AIRE /AJUSTE DE FRENO	15/11/2021		Corrective Order	WO Completed	Mule truck
710331	Boom Truck Iveco Tector	Problema con la manguera del r	PROBLEMA CON LA MANGUERA DEL R	15/11/2021		Corrective Order	WO Completed	Boom truck
710333	Boom Truck Iveco Tector	No le funciona el A/C	NO LE FUNCIONA EL A/C	15/11/2021		Corrective Order	WO Completed	Boom truck
710353	Bomag BW24RH	Tiene bajo nivel de aceite de	TIENE BAJO NIVEL DE ACEITE DE	15/11/2021		Corrective Order	WO Completed	Roller PTR
710483	Hilux DC	LAVADO DE AUTO	LAVADO DE AUTO	15/11/2021		Corrective Order	WO Completed	Pickup truck
710850	Caterpillar D110 E2 100KVA	MANTENIMIENTO CORRECTIVO	CAMBIO DE ALTERNADOR DC Y BATERIA	15/11/2021	16205 horas	Corrective Order	WO Completed	Generator
710915	Coaster	Reemplazo de llantas	REEMPLAZO DE LLANTAS	15/11/2021		Corrective Order	WO Completed	Bus
710916	Hilux DC	Reemplazo de 4 llantas	REEMPLAZO DE 4 LLANTAS	15/11/2021		Corrective Order	WO Completed	Pickup truck
710917	Landcruiser DC	Reparacion de llantas	REPARACION DE LLANTAS	15/11/2021		Corrective Order	WO Completed	Pickup truck
710937	JLG 800 AJ Manlift	Revision de equipo	EQUIPO BLOQUEADO	15/11/2021	63992 Hrs	Corrective Order	WO Completed	Manlift
711407	Caterpillar 236d Skid Steer L	relleno de aceite de motor	RELLENO DE ACEITE DE MOTOR	16/11/2021		Corrective Order	WO Completed	Skid Steer
711444	EX036 EC480DL Volvo	C/ LINEAS CYL DE BUCKET	DEFECTUOSA	16/11/2021	CENMAN	Corrective Order	WO Completed	Excavator
711572	Freightliner Columbia Cl112	reparar fuga de aceite	REVISAR Y REPARAR FUGA DE ACEITE	16/11/2021		Corrective Order	WO Completed	Mule truck
711573	Freightliner Cl 120	reparacion de mangueras neumat	REPARACION DE MANGUERA NEUMATICA	16/11/2021		Corrective Order	WO Completed	Mule truck
711604	TRUCK IVECO TRAKKER 440 AT 8X8	Bajo nivel de aceite Motor	BAJO NIVEL DE ACEITE MOTOR	16/11/2021		Corrective Order	WO Completed	Boom truck
711608	Freightliner M2 106 Hydroseedi	Cambio de hilo grafitado	CAMBIO DE HILO GRAFITADO	16/11/2021		Corrective Order	WO Completed	Truck
711612	Manitou Mht-X860 6t Telehand	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULIC	16/11/2021		Corrective Order	WO Completed	Telehender
711645	PT050 NMR85L-HH5WA ISUZU	CRUCETA DE EJE DE MANDO	CRUCETA DE EJE DE MANDO	16/11/2021		Corrective Order	WO Completed	Truck
711667	Caterpillar DE22E3 17.6 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE REGULADOR DE VOLTAJE	16/11/2021	14937 horas	Corrective Order	WO Completed	Generator
711862	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711863	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711864	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711865	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711866	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711871	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711875	Hilux DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711876	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711877	Hilux DC	CAMBIO DE 2 NEUMÁTICOS	CAMBIO DE 2 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711885	Landcruiser DC	CAMBIO DE 1 NEUMÁTICO	CAMBIO DE 1 NEUMÁTICOS	17/11/2021		Corrective Order	WO Completed	Pickup truck
711908	Gallegos 28M3 Lime Tank	FUGA POR ESCOTILLA	FUGA POR ESCOTILLA	17/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
711919	Caterpillar 416E	Pin del brazo de la retro	PIN DEL BRAZO D ELA RETRO	17/11/2021		Corrective Order	WO Completed	Backhoe
711994	Caterpillar D8T Dozer	Falta refrigerante	FALTA REFRIGERANTE	17/11/2021		Corrective Order	WO Completed	Dozer
712111	Gallegos 28M3 Lime Tank	Cambio de 2 bolsas	CAMBIO DE 2 LBOLSAS	17/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
712114	Unimog Service Truck	Falla en encendido	FALLA EN ENCENDIDO	17/11/2021		Corrective Order	WO Completed	Truck
712126	WT015 H7 CISTERNA SINOTRUK	Aire acondicionado no funciona	AIRE ACONDICIONADO NO FUNCIONA	17/11/2021		Corrective Order	WO Completed	Water truck
712132	Mobile equipment	insumos para taller	INSUMS PARA TALLER	17/11/2021		Corrective Order	WO Completed	Area

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
712296	Caterpillar D6T LGP	Cambio de baterías	CAMBIO DE BATERIAS	17/11/2021		Corrective Order	WO Completed	Dozer
712372	Landcruiser DC	reparacion de 1 llanta	REPARACION DE 1 LLANTA	17/11/2021		Corrective Order	WO Completed	Pickup truck
712375	Freightliner CI 120	llanta flat	LLANTA FLAT	17/11/2021		Corrective Order	WO Completed	Mule truck
712376	Hyster H700 Forklift	Cambio de ECM	CAMBIO DE ECM	17/11/2021		Corrective Order	WO Completed	Forklift
712392	ATLAS COPCO HILIGHT V5+	mantenimiento PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	17/11/2021		Corrective Order	WO Completed	Light Tower
712393	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENST SBY	INSPECCIÓN GENERAL Y ARRANQUE DE EQUIPO	17/11/2021 66 horas		Corrective Order	WO Completed	Generator
712395	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENST SBY	INSPECCIÓN GENERAL Y ARRANQUE DE EQUIPO	17/11/2021 8258 horas		Corrective Order	WO Completed	Generator
712396	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INSPECCION GENERAL Y ARRANQUE DE EQUIPO	17/11/2021 10423 horas		Corrective Order	WO Completed	Generator
712408	Unimog Service Truck	CAMBIO DE BATERÍAS	CAMBIO DE BATERÍAS	17/11/2021		Corrective Order	WO Completed	Truck
712411	JLG 800 AJ Manlift	Cambio de manguera hidráulica	CAMBIO DE ,MANGJUERA HIDRÁULICA	17/11/2021		Corrective Order	WO Completed	Manlift
712492	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	18/11/2021 10324 hrs		PM Orders	WO Completed	Generator
712493	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	18/11/2021 12668 hrs		PM Orders	WO Completed	Generator
712546	Landcruiser DC	Filtro de aceite	FILTRO DE ACEITE	18/11/2021		Corrective Order	WO Completed	Pickup truck
712547	Freightliner CI 120	Fuga de Coolant	CAMBIO DE MANGUERA	18/11/2021		Corrective Order	WO Completed	Mule truck
712563	Freightliner M2 106	EQUIPO NO ENCIENDE	EQUIPO NO ENCIENDE	18/11/2021		Corrective Order	WO Completed	Bitumen truck
712569	Mobile equipment	Manguera para elevador de Tall	MANGUERA PARA ELEVADOR DE TALLER	18/11/2021		Corrective Order	WO Completed	Area
712571	Caterpillar DP50 Forklift (M)	Arranque del Equipo	ARRANQUE DEL EQUIPO	18/11/2021		Corrective Order	WO Completed	Forklift
712609	Bomag BW24RH	varilla de aceite quebrada	VARILLA DE ACEITE QUEBRADA	18/11/2021		Corrective Order	WO Completed	Roller PTR
712647	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INSPECCION GENERAL PRUEBA Y FUNCIONAMIENTO	18/11/2021 16487 HRS		Corrective Order	WO Completed	Generator
712658	Gallegos 28M3 Lime Tank	LLANTA FLAT	LLANTA FLAT	18/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
712659	Coaster	Cambio de 6 llantas	CAMBIO DE 6 LLANTAS	18/11/2021		Corrective Order	WO Completed	Bus
712688	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	18/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
712963	Hyster E70xn 3t Forklift (E)	cambio de llantas traseras	CAMBIO DE LLANTAS TRASERAS	18/11/2021		Corrective Order	WO Completed	Forklift
712965	Hyster E70xn 3t Forklift (E)	cambio de llantas traseras	CAMBIO DE LLANTAS TRASERAS	18/11/2021		Corrective Order	WO Completed	Forklift
712967	Hyster E70xn 3t Forklift (E)	cambio de lant as traseras	CAMBIO DE LLANTAS TRASERAS	18/11/2021		Corrective Order	WO Completed	Forklift
712969	Manitou MHT10180L Telehandler	Falla con la reversa	FALLA CON LA REVERSA	18/11/2021		Corrective Order	WO Completed	Telehender
712970	Boom Truck Iveco Tector	Fuga de aceite motor	FUGA DE ACEITE MOTOR	18/11/2021		Corrective Order	WO Completed	Boom truck
712995	Caterpillar 416E	Fuga de aceite por el diferen	FUGA DE ACEITE POR EL DIFEREN	18/11/2021		Corrective Order	WO Completed	Backhoe
713035	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	CAMBIO DE BATERIA	18/11/2021 25139 horas		Corrective Order	WO Completed	Generator
713036	Caterpillar D110 E2 100KVA	MANTENIMIENTO CORRECTIVO	CAMBIO DE EMPAQUE DEL ENFRIADOR	18/11/2021 19282 horas		Corrective Order	WO Completed	Generator
713037	PRAMAC GSW110P 82 kVa	MANTENIMIENTO CORRECTIVO	DESINTALACION DE EQUIPO	18/11/2021 13190 horas		Corrective Order	WO Completed	Generator
713039	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENST SBY	PRUEBA DE ARRANQUE Y FUNCIONAMIENTO	18/11/2021 16809 horas		Corrective Order	WO Completed	Generator
713049	PRAMAC GSW110P 82 kVa	FALLO DE BOMBA DE INYECCION	LLAMADA DE EMERGENCIA POR BOMBA DE INYECCION TRANCADA POR FALTA DE DIESEL	18/11/2021 15190 horas		Corrective Order	WO Completed	Generator
713094	Coaster	MANTENIMIENTO CORRECTIVO	CAMBIO DE CORREAS DE ACCESORIOS, CAMBIO DE BASE DE AMORTIGUADORES Y GRAPAS	19/11/2021 47196.00		Corrective Order	WO Completed	Bus
713097	Landcruiser TC	MANTENIMIENTO CORRECTIVO	BUJES DE AMORTIGUADORES TRASEROS, AJUSTE DE FRENOS	19/11/2021 83691.00		Corrective Order	WO Completed	Pickup truck
713179	Coaster	MANTENIMIENTO CORRECTIVO	CAMBIO DE CORREAS DE ACCESORIOS, CAMBIO DE BASE DE AMORTIGUADORES Y GRAPAS	19/11/2021 47193.00		Corrective Order	WO Completed	Bus
713216	Hilux DC	REPARACIONES	SUSPENSION,FRENOS	19/11/2021 96688.00		Corrective Order	WO Completed	Pickup truck
713218	LV245 HILUX TOYOTA	REPARACIONES	SUSPENSION,FRENOS	19/11/2021 84688.00		Corrective Order	WO Completed	Light Vehicles
713223	LV245 HILUX TOYOTA	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	19/11/2021 84688.00		Corrective Order	WO Completed	Light Vehicles
713226	Coaster	MANTENIMIENTO CORRECTIVO	CAMBIO DE LINK DE BARRA DE TRASERO	19/11/2021 58790.00		Corrective Order	WO Completed	Bus
713229	Coaster Bus	MANGUERA DEL TANQUE	CAMBIO DE MANGUERA DEL TANQUE DE COMB.	19/11/2021 100972.00		Corrective Order	WO Completed	Bus
713237	Ford Ranger Sc	REPARACIONES	CAMBIO DE FLECHA	19/11/2021 15071.00		Corrective Order	WO Completed	Pickup truck
713238	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	19/11/2021 47572.00		Corrective Order	WO Completed	Pickup truck
713242	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE FREEWEEEL,FRENOS,BALINERAS,CABLE DE FRENOS,,KIT DE REFUERZO DE COCOBOL	19/11/2021 47572.00		Corrective Order	WO Completed	Pickup truck
713250	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE FRENOS, RETENDORA DE DIFERENCIAL,CAUCHOS DE MUELLES	19/11/2021 85292.00		Corrective Order	WO Completed	Pickup truck
713252	Landcruiser DC	MANTENIMIENTO CORRECTIVO	COCOBOLA	19/11/2021 74468.00		Corrective Order	WO Completed	Pickup truck
713279	Landcruiser DC	A/C	REVISION,LIMPIEZA DEL SISTEMA	19/11/2021 55750.00		Corrective Order	WO Completed	Pickup truck
713280	Coaster Bus	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	19/11/2021 82400.00		Corrective Order	WO Completed	Bus
713283	Coaster Bus	PROBLEMAS DE INYECCION	BOMBA DE INYECCION	19/11/2021 82400.00		Corrective Order	WO Completed	Bus
713289	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	19/11/2021 23858.00		Corrective Order	WO Completed	Pickup truck
713292	Caterpillar D8T Dozer	CONFECCIÓN DE MANGUERAS	CONFECCIÓN DE MANGUERAS	19/11/2021		Corrective Order	WO Completed	Dozer
713300	Hilux DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE CLUTCH	19/11/2021 23858.00		Corrective Order	WO Completed	Pickup truck
713301	Hilux DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	19/11/2021 13250.00		Corrective Order	WO Completed	Pickup truck
713305	Hilux DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE CALIPER,TACOS DE FRENOS	19/11/2021 56890.00		Corrective Order	WO Completed	Pickup truck
713308	Landcruiser DC	DIRECCION	CAMBIO DE CAJA DE TIMON	19/11/2021 74468.00		Corrective Order	WO Completed	Pickup truck
713353	PRAMAC GSW460V 460 kVa	LAVADO DE RADIADOR	EQUIPO SE CALIENTA POR RADIADOR SUCIO	19/11/2021 7143 horas		Corrective Order	WO Completed	Generator
713382	SDMO J60U 60KVA	CAMBIO DE GENERADOR	CAMBIO DE GENERADOR POR FALLA DE BOMBA DE INYECCION DEL GS258	19/11/2021 6398 horas		Corrective Order	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
713398	Caterpillar 236d Skid Steer L	soporte de extintor	SOPORTE DE EXTINTOR	19/11/2021		Corrective Order	WO Completed	Skid Steer
713424	Gallegos Flatbed Trailer	LLANTA FLAT	LLANTA FLAT	19/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
713429	Coaster	Cambio de 6 llantas	CAMBIO DE 6 LLANTAS	19/11/2021		Corrective Order	WO Completed	Bus
713495	Pit Operations Offices	Mantenimienio Preventivo	MANTENIMIENO PREVENTIVO	19/11/2021 W47		Corrective Order	WO Completed	Building
713501	Gallegos Flatbed Trailer	AJUSTE DE FRENO	AJUSTE DE FRENO	19/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
713535	Caterpillar 320DL	PM01 MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	19/11/2021		Corrective Order	WO Completed	Excavator
713626	Caterpillar DE22E3 17.6 kVa	REEMPLAZO DE CORREA	MANTENIMIENTO CORRECTIVO	19/11/2021 14965 horas		Corrective Order	WO Completed	Generator
713646	Caterpillar 426f2 Backhoe	Reparacion de llanta flat	REPARACION DE LLANTA FLAT	19/11/2021		Corrective Order	WO Completed	Backhoe
713653	Grove RT890 90TON	Revisar niveles	REVISAR NIEVELES DE ACEITE Y COMPLETAR	19/11/2021		Corrective Order	WO Completed	Crane/Hoist
713692	Freightliner Columbia CI112	Bajo nivel de aceite motor	BAJO NIVEL DE ACEITE MOTOR	19/11/2021		Corrective Order	WO Completed	Mule truck
713697	Ford 450	reparación de aire acondiciona	REPARACIÓN DE AIRE ACONDICIONA	19/11/2021		Corrective Order	WO Completed	Pickup truck
713698	Bomag BW24RH	Varilla partida	VARILLA PARTIDA	19/11/2021		Corrective Order	WO Completed	Roller PTR
713724	Caterpillar DE110E 110 kVa	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	19/11/2021 23107 horas		Corrective Order	WO Completed	Generator
713728	Caterpillar D110 E2 100KVA	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	19/11/2021 19573 horas		Corrective Order	WO Completed	Generator
713730	Caterpillar D110 E2 100KVA	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	19/11/2021 19266 horas		Corrective Order	WO Completed	Generator
713732	Caterpillar C4.4 88KVA	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	19/11/2021 30737 horas		Corrective Order	WO Completed	Generator
713734	Olympian GEP18-6 18KVA	MANTENIMIENTO PREVENTIVO	REEMPLAZA DE ACEITE Y FILTROS	19/11/2021 29980 horas		Corrective Order	WO Completed	Generator
713812	USP&E GP700S/V-A 700 kVa	MANTENIMIENTO CORRECTIVO	LIMPIEZA DE DERRAME DE COOLANT	20/11/2021 25139 horas		Corrective Order	WO Completed	Generator
713813	Caterpillar DE22E3 17.6 kVa	LLAMADA DE EMERGENCIA	CAMBO DE MANGUERA DE RADIADOR	20/11/2021 14965 hors		Corrective Order	WO Completed	Generator
713880	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	20/11/2021 63343.00		Corrective Order	WO Completed	Pickup truck
713884	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE ALTERNADOR,REPARACION ABS	20/11/2021 63343.00		Corrective Order	WO Completed	Pickup truck
713885	Hilux DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE CLUTCH	20/11/2021 48139.00		Corrective Order	WO Completed	Pickup truck
713887	Toyota Land Cruiser	RESCATE EN MOLINO	CAMBIO DE ALTERNADOR Y BATERIA	20/11/2021 192770.00		Corrective Order	WO Completed	Pickup truck
713891	Landcruiser TC	RESCATE EN OFICINA AMBIENTE	CAMBIO DE BATERIA	20/11/2021 81109.00		Corrective Order	WO Completed	Pickup truck
713920	Hilux DC	PERTIGA	INSTALCION DE PERTIGA	20/11/2021 34835.00		Corrective Order	WO Completed	Pickup truck
713923	Toyota Land Cruiser	CORTO ELECTRICO	REPARACION DE SIRENA	20/11/2021 12530.00		Corrective Order	WO Completed	Pickup truck
713928	Hyster H700 Forklift	Reparación de un Neumático	REPARACIÓN DE NEUMÁTICO	20/11/2021		Corrective Order	WO Completed	Forklift
714001	Unimog Service Truck	Reparación Luces Unimog 07	REPARACIÓN LUCES UNIMOG 07	20/11/2021		Corrective Order	WO Completed	Truck
714009	Mack Trucks Gu813e	fabricacion de mangueras	FABRICACION DE MANGUERAS	20/11/2021		Corrective Order	WO Completed	Truck
714015	Caterpillar 226b Skid Steer L	Relleno aceite hidraulico	RELLENO ACEITE HIDRAULICO	20/11/2021		Corrective Order	WO Completed	Skid Steer
714023	Caterpillar 307E Miniexcavator	Trabajos varios	TRABAJOS VARIOS	20/11/2021		Corrective Order	WO Completed	Excavator
714040	Grove RT600E 50TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714041	Terex RT670 64TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714072	Shuttlelift RTCD5540F 15TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714075	Shuttlelift RTCD5540F 15TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714080	Broderson IC200-2C 9TON	TOMA DE MUESTRAS DE ACEITES	MUESTREO DE ACEITE PARA ANALISIS	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714105	Caterpillar 12M	se le calento aceite hidraulic	SE LE CALENTO ACEITE HIDRAULIC	20/11/2021		Corrective Order	WO Completed	Grader
714174	Unimog Service Truck	reparacion de luces	REPARACIÓN DE LUCES Y LLANTA	20/11/2021		Corrective Order	WO Completed	Truck
714193	WT015 H7 CISTERNA SINOTRUK	Bajo nivel de aceite hidraulic	BAJO NIVEL DE ACEITE HIDRAULIC	20/11/2021		Corrective Order	WO Completed	Water truck
714195	Landcruiser DC	Cambio de 4 llantas	CAMBIO DE 4 LLANTAS	20/11/2021		Corrective Order	WO Completed	Pickup truck
714217	Gallegos Flatbed Trailer	FUGA DE AIRE / ENGRASE	FUGA DE AIRE / ENGRASE	20/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
714218	Hino Series 300	Cambio de luz escolta	CAMBIO DE LUZ ESCOLTA	20/11/2021		Corrective Order	WO Completed	Truck
714225	Intraax 53121 Hendrickso	AJUSTE DE FRENO	AJUSTE DE FRENO/ FRENOS REVISION	20/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
714247	Internation 4400 SBA 6x4 Boom	reparacion de puerta	REPRARACION DE PUERTA	20/11/2021		Corrective Order	WO Completed	Boom truck
714248	Grove RT650E 45TON	fuga de aceite hidraulico	FUGA DE ACEITE HIDRAULICO	20/11/2021		Corrective Order	WO Completed	Crane/Hoist
714266	SDMO T11UM 10KVA	FALLO POR PRESION DE ACEITE	FALLO POR MALA LECTURA DE SENSOR DE PRESION DE ACEITE	20/11/2021 19079 horas		Corrective Order	WO Completed	Generator
714295	Manitou Mht-X1490 9t Telehand	Revisar nivel de aceite	REPARAR Y REVISAR NIVELES DE ACEITE	20/11/2021		Corrective Order	WO Completed	Telehender
714296	Gallegos Flatbed Trailer	reparacion de llantas	REPARACION DE LLANTAS	20/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
714299	Freightliner Columbia CI112	engrase general	ENGRASE GENERAL	20/11/2021		Corrective Order	WO Completed	Mule truck
714308	Hyster H70ft 3t Forklift (M)	reparacion de sistema de carga	REPARACION DE SISTEMA DE CARGA	20/11/2021		Corrective Order	WO Completed	Forklift
714309	Manitou Mht-X1490 9t Telehand	reperar fuga de aceite	REPARAR FUGA DE ACEITE	20/11/2021		Corrective Order	WO Completed	Telehender
714377	SDMO J30U 38KVA	LLAMADA DE EMERGENCIA	EQUIPO PARADO	20/11/2021 10189 horas		Corrective Order	WO Completed	Generator
714396	LB002 725 CAT	Instalación de extintor	INSTLACIÓN DE EXTINTOR	20/11/2021		Corrective Order	WO Completed	Truck
714399	Hilux DC	CAMBIO DE 4 NEUMATICOS	CAMBIO DE 4 NEUMATICOS	20/11/2021		Corrective Order	WO Completed	Pickup truck
714400	Mobile equipment	CONFECCIÓN DE MANGUERAS	CONFECCIÓN DE MANGUERAS	20/11/2021		Corrective Order	WO Completed	Area
714579	LV162 RANGERS SC FORD	INTERCOOLER, TURBO	CAMBIO DE INTERCOOLER Y TURBO	21/11/2021 79086.00		Corrective Order	WO Completed	Light Vehicles
714580	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	21/11/2021 62670.00		Corrective Order	WO Completed	Pickup truck
714589	Caterpillar 320DL	Inspección general	INSPECCIÓN GENERAL DEL EQUIPO	21/11/2021		Corrective Order	WO Completed	Excavator
714629	Caterpillar 416E	Pin principal de la pluma sali	PIN PRINCIPAL DE LA PLUMA SALI	21/11/2021		Corrective Order	WO Completed	Backhoe
714668	WT013 H7 CISTERNA SINOTRUK	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021		Corrective Order	WO Completed	Water truck
714767	Freightliner CI 120	Cambio de extintor	CAMBIO DE EXTINTOR	21/11/2021		Corrective Order	WO Completed	Mule truck
714784	Isuzu NMR85L	Llanta flat #5	LLANTA FLAT #5	21/11/2021		Corrective Order	WO Completed	Truck
714855	EX036 EC480DL Volvo	C/ DE ALTERNADOR	CAMBIO	21/11/2021		Corrective Order	WO Completed	Excavator
714861	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INSPECCION GENERAL Y ARRANQUE DE EQUIPO	21/11/2021 10423 horas		Corrective Order	WO Completed	Generator
714862	SDMO J30U 38 kVa	PM1 SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021 13727 horas		PM Orders	WO Completed	Generator
714869	USP&E GP700S/V-A 700 kVa	INSPECCION GENERADOR RESPALDO	INSPECCION GENERAL PRUEBA Y FUNCIONAMIENTO	21/11/2021 16488 horas		Corrective Order	WO Completed	Generator

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
714877	Olympian GEP150 135 kVa	INSPECCION SEMANAL GENST SBY	INSPECCIÓN GENERAL Y ARRANQUE DE EQUIPO	21/11/2021 66 horas		Corrective Order	WO Completed	Generator
714878	PRAMAC GSW170I 164 kVa	INSPECCION SEMANAL GENST SBY	INSPECCIÓN GENERAL Y ARRANQUE DE EQUIPO	21/11/2021 8258 horas		Corrective Order	WO Completed	Generator
714880	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENST SBY	PRUEBA DE ARRANQUE Y FUNCIONAMIENTO	21/11/2021 16809 horas		Corrective Order	WO Completed	Generator
714916	Caterpillar D110 E2 100KVA	VERIFICACION DE HOROMETRO	VERIFICACION DE HOROMETRO	21/11/2021 19387 horas		Corrective Order	WO Completed	Generator
714917	FG WILSON P88-3 80 kVa	PM1 FGW P88-3 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021 27090 horas		PM Orders	WO Completed	Generator
714933	Gallegos 28M3 Lime Tank	Engrase de patas	ENGRASE DE PATAS	21/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
714939	LB002 725 CAT	Cambio de extintor	CAMBIO DE EXTINTOR	21/11/2021		Corrective Order	WO Completed	Truck
714943	Caterpillar 12M Motorgrader	Bajo nivel de aceite motor	BAJO NIVEL DE ACEITE MOTOR	21/11/2021		Corrective Order	WO Completed	Grader
714944	Hyster H700 Forklift	Fuga por tapon de motor	FUGA POR TAPON DE MOTOR	21/11/2021		Corrective Order	WO Completed	Forklift
714945	PRAMAC GSW90P 74 kVa	PM1 PRA GSW90P MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021 26445 horas		PM Orders	WO Completed	Generator
714946	PRAMAC GBW15 14 kVa	PM1 PRA GBW15 MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021 714946		PM Orders	WO Completed	Generator
714950	Gallegos Lime Tank	LLANTA FLAT	LLANTA FLAT	21/11/2021		Corrective Order	WO Completed	Trailer / Flatbed / Lime Tank
714952	Doosan D1005	MANTENIMIENTO PREVENTIVO	MANTENIMIENTO PREVENTIVO	21/11/2021 19282 horas		Corrective Order	WO Completed	Light Tower
714957	MAGNUM Light Tower	MANTENIMIENTO CORRECTIVO	CAMBIO DE MOTOR DIESEL	21/11/2021 27551 horas		Corrective Order	WO Completed	Light Tower
714960	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 9775 hrs		PM Orders	WO Completed	Generator
714961	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 3633 hors		PM Orders	WO Completed	Generator
714963	SDMO J60U 60KVA	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 581 horas		PM Orders	WO Completed	Generator
714966	USP&E GP700S/V-A 700 kVa	INSPECCION GENERADOR RESPALDO	INSPECCION GENERADOR RESPALDO	21/11/2021 16084 horas		Corrective Order	WO Completed	Generator
714968	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 8644 horas		PM Orders	WO Completed	Generator
714971	SDMO J30U 38KVA	PM SDM J30U MEC 300 HR	OIL & FILTER REPLACEMEN, INSPECTION	21/11/2021 9791 hrs		PM Orders	WO Completed	Generator
714978	PRAMAC GSW110 82 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 361 horas		PM Orders	WO Completed	Generator
714979	USP&E GP700/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 12019 horas		PM Orders	WO Completed	Generator
714981	PRAMAC GSW45 35 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 163 horas		PM Orders	WO Completed	Generator
714982	PRAMAC GSW90P 74 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 26445 horas		PM Orders	WO Completed	Generator
714991	USP&E GP700S/V-A 700 kVa	INSPECCION SEMANAL GENSET SBY	INPECCION GENERAL Y PRUEBA FUNCIONAMIENTO	21/11/2021 18058 horas		PM Orders	WO Completed	Generator
715030	DOOSAN 1005	LLAMADA DE EMERGENCIA	EQUIPO PARADO	21/11/2021 30214 horas		Corrective Order	WO Completed	Light Tower
715304	Unimog Service Truck	Reparación de un Neumático	REPARACIÓN DE NEUMÁTICO	22/11/2021		Corrective Order	WO Completed	Truck
715333	Caterpillar 12M	Llanta flat	LLANTA FLAT	22/11/2021		Corrective Order	WO Completed	Grader
715389	PRAMAC GSW80P 83 kVa	FALLO DE VOLTAGE AC	FALLO DE VOLTAJE AC, NO KLEVANTA SUFICIENTE VOLTAGE	22/11/2021 10938 horas		Corrective Order	WO Completed	Generator
715589	Caterpillar C7.1 200 kVa	CAMBIO DE BATERIA	CAMBIO DE BATERIA DESCARGADA	22/11/2021 16560 horas		Corrective Order	WO Completed	Generator
715607	Caterpillar C7.1 200 kVa	CAMBIO DE CT Y REVISION DE REG	CAMBIO DE CT & REVISION DE TARGETA REGULADORA	22/11/2021 16560 horas		Corrective Order	WO Completed	Generator
715632	Caterpillar C9 250 kVa	LIMPIEZA DE EQUIPO	EQUIPO CON FUGA DE ACEITE	22/11/2021 20713 horas		Corrective Order	WO Completed	Generator
715965	Caterpillar DE88E0 58 kVa	LLAMADA DE EMERGENCIA	CAMBIO DE ALTERNADOR DC	23/11/2021 39171 horas		Corrective Order	WO Completed	Generator
715969	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	23/11/2021 56257.00		Corrective Order	WO Completed	Pickup truck
715971	Landcruiser DC	MANTENIMIENTO CORRECTIVO	COCOBOLA,MULLE,BALINERAS	23/11/2021 56257.00		Corrective Order	WO Completed	Pickup truck
715972	Hilux DC	MANTENIMINETO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	23/11/2021 85452.00		Corrective Order	WO Completed	Pickup truck
715973	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO EVAPORADOR, BANDAS,ALARMA	23/11/2021 57911.00		Corrective Order	WO Completed	Pickup truck
715974	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE CAJA DE TIMON	23/11/2021 85525.00		Corrective Order	WO Completed	Pickup truck
715975	Landcruiser DC	BATERIA	CAMBIO DE BATERIA	23/11/2021 74987.00		Corrective Order	WO Completed	Pickup truck
715977	Hino Series300	FRENOS	DAÑOS EN CILINDROS DE FRENOS	23/11/2021 65264.00		Corrective Order	WO Completed	Truck
715979	Landcruiser DC	MANTENIMIENTO PREVENTIVO	CAMBIO DE ACEITES Y FILTROS	23/11/2021 45435.00		Corrective Order	WO Completed	Pickup truck
715980	Landcruiser DC	MANTENIMIENTO CORRECTIVO	CAMBIO DE FREEWEEL	23/11/2021 32671.00		Corrective Order	WO Completed	Pickup truck
715981	Hilux DC	PERNOS DE RUEDAS	CAMBIO DE PERNOS Y TUERCAS DE RUEDAS	23/11/2021 19398.00		Corrective Order	WO Completed	Pickup truck
715982	Landcruiser DC	ESCOLTA Y ALARMA	CAMBIO DE ESCOLTA Y ALARMA	23/11/2021 66371.00		Corrective Order	WO Completed	Pickup truck
715983	PT050 NMR85L-HH5WA ISUZU	TRANSMISION	CAMBIO DE ACEITE DE TRANSMISION	23/11/2021 52963.00		Corrective Order	WO Completed	Truck
716031	Caterpillar 416E	Nivel de aceite hidráulico	NIVEL DE ACEITE HIDRÁULICO	23/11/2021		Corrective Order	WO Completed	Backhoe
716070	Freightliner Columbia CI112	cambio de 4 llantas	LLANTAS EN MAL ESTADO	23/11/2021		Corrective Order	WO Completed	Mule truck
716106	Caterpillar DE88E0 58 kVa	CORRECTIVO	CORRECTIVO	23/11/2021 39174 hrs		Corrective Order	WO Completed	Generator
716200	Hilux DC	REPARAR SISTEMA ARRANQUE	NO ENCIENDE NO ARRANCA	23/11/2021		Corrective Order	WO Completed	Pickup truck
716268	Landcruiser TC	CAMBIO DE BATERIA Y FILTRACION	CAMBIO DE BATERIA Y FILTRACION	23/11/2021 81,515.00 km		Corrective Order	WO Completed	Pickup truck
716282	Caterpillar DE88E0 58 kVa	LAVADO DE RADIADOR	MANTENIMIENTO CORRECTIVO	23/11/2021 39174 hrs		Corrective Order	WO Completed	Generator
716318	Hiace Bus	reparacion de 1 llanta	REPARACION DE 1 LLANTA	23/11/2021		Corrective Order	WO Completed	Bus
716320	Caterpillar 226b Skid Steer L	reparacion de llanta	LLANTA FLAT	23/11/2021		Corrective Order	WO Completed	Skid Steer
716529	PRAMAC GSW80P 83 kVa	REVISION DE ALTERNADOR AC	DESMONTAJE DE ALTERNADOR AC POR FALLA DE VOLTAJE	24/11/2021 10948 horas		Corrective Order	WO Completed	Generator
716530	PRAMAC GSW80P 83 kVa	CONFIGURACION DE CONTROL	CAMBIO DE CONTROL DAÑADO	24/11/2021 10948 horas		Corrective Order	WO Completed	Generator
716606	Caterpillar 12M	Avería en la dirección	AVERÍA EN LA DIRECCIÓN	24/11/2021		Corrective Order	WO Completed	Grader

Order Number	Asset Number Description	Or Ty Description	Problem	Order Date	Status Comment	W.O. Type Description	WO St Description	Cat 02 Description
716672	Landcruiser DC	Revision de luces	BOMBILLO HALOGENO - REEMPLAZO	24/11/2021		Corrective Order	WO Completed	Pickup truck
716679	PB002 COASTER TOYOTA	Mantenimiento correctivo	REPARACION CABLEADO ELECTRICO VALVULA DE COMPENSACION A/C, AJUSTE DE BOMBA DE IN	24/11/2021		Corrective Order	WO Completed	Bus
716684	Hilux DC	Revision de embrague	REEMPLAZO DE KIT DE EMBRAGUE	24/11/2021		Corrective Order	WO Completed	Pickup truck
716686	Hilux DC	Mantenimiento preventivo	REEMPLAZO DE FILTROS Y ACEITE	24/11/2021		Corrective Order	WO Completed	Pickup truck
716687	Landcruiser TC	Mantenimiento correctivo	MANTENIMIENTO CORRECTIVO	24/11/2021		Corrective Order	WO Completed	Pickup truck
716688	Hilux DC	Revision de equipo	CORRECTIVO	24/11/2021		Corrective Order	WO Completed	Pickup truck
716689	Hilux DC	Revision de equipo	CORRECTIVO	24/11/2021		Corrective Order	WO Completed	Pickup truck
716691	Hilux DC	Revision de equipo	CORRECTIVO	24/11/2021		Corrective Order	WO Completed	Pickup truck
716714	Hyster H70ft 3t Forklift (M)	cambio de bateria	BATERIA EN MAL ESTADO	24/11/2021		Corrective Order	WO Completed	Forklift
716830	Caterpillar 236d Skid Steer L	perforar aguejero de engrase	PERFORAR AGUEJERO DE ENGRASE	24/11/2021		Corrective Order	WO Completed	Skid Steer
716861	SDMO J60U 60KVA	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	24/11/2021 6521 hrs		Corrective Order	WO Completed	Generator
716873	WT015 H7 CISTERNA SINOTRUK	cambio de 2 llantas	LLANTAS EN MAL ESTADO	24/11/2021		Corrective Order	WO Completed	Water truck
716878	Mobile equipment	Reparacion de llanta	LLANTA DA??ÑADA PLACA	24/11/2021		Corrective Order	WO Completed	Area
716894	Atlas Copco GESAN QIS 45 47KVA	LLAMADA DE EMERGENCIA	LLAMADA DE EMERGENCIA	24/11/2021 6644 hrs		Corrective Order	WO Completed	Generator
716906	Caterpillar 14M Motorgrader	Fuga de diésel	FUGA DE DIÉSEL	24/11/2021		Corrective Order	WO Completed	Grader
716909	Caterpillar 416F2 Backhoe	Llanta delantera del lado izqu	LLANTA DELANTERA DEL LADO IZQU	24/11/2021		Corrective Order	WO Completed	Backhoe
716912	Freightliner Cl 120	Reparación de silenciador	REPARACIÓN DE SILENCIADOR	24/11/2021		Corrective Order	WO Completed	Mule truck
716975	Grove RT600E 50TON	Revision de falla electrica	REVISION DE FALLA ELECTRICA	24/11/2021		Corrective Order	WO Completed	Crane/Hoist
717167	Caterpillar 226b Skid Steer L	reparacion de sistema electric	REPARACIUON DE SISTEMA DE ARRANQUE	25/11/2021		Corrective Order	WO Completed	Skid Steer
717168	Caterpillar 416F2 Backhoe	revision d ellantas	REVISION DE LLANTAS	25/11/2021		Corrective Order	WO Completed	Backhoe
717171	PRAMAC GSW110P 82 kVa	LAVADO DE EQUIPO	LAVADO DE MAQUINA & RADIADOR	25/11/2021 15190 horas		Corrective Order	WO Completed	Generator
717174	Hyster E70xn 3t Forklift (E)	revisar sistema de carga	REVISAR SISTEMA DE CARGA	25/11/2021		Corrective Order	WO Completed	Forklift
717581	Freightliner Columbia Cl112	Llanta flat	LLANTA FLAT	25/11/2021		Corrective Order	WO Completed	Mule truck
717582	TTP-0000-102	Engrase general	ENGRASE GENERAL	25/11/2021		Corrective Order	WO Completed	Excavator
717613	ATR-0000-001 4+320 AGRICO	Revision de A/C	REVISION DE A/C	25/11/2021		Corrective Order	WO Completed	Tractor
717627	Landcruiser DC	Reemplazo de 4 llantas	REEMPLAZO DE 4 LLANTAS	25/11/2021		Corrective Order	WO Completed	Pickup truck
717685	SDMO J30U 38 kVa	CAMBIO DE CORREA	CORREA ROTA	25/11/2021 13830 horas		Corrective Order	WO Completed	Generator
717699	Hyster H700 Forklift	reparacion de llantas	REPARACION DE LLANTAS	25/11/2021		Corrective Order	WO Completed	Forklift
717701	WT015 H7 CISTERNA SINOTRUK	reparacion de luces	REPARACION DE LUCES	25/11/2021		Corrective Order	WO Completed	Water truck
717719	Unimog Service Truck	Reparacion de luces	REPARACIPON DE LUCES/W/W	26/11/2021		Corrective Order	WO Completed	Truck
717819	PRAMAC GSW110P 82 kVa	CAMBIO DE RETENEDORAS	CAMBIO DE RETENEDORAS DE VOLANTE & DAMPER	26/11/2021 15190 horas		Corrective Order	WO Completed	Generator
717845	Freightliner Columbia Cl112	reparacion de llantas	REPOARACION DE LLANTAS	26/11/2021		Corrective Order	WO Completed	Mule truck
717984	Hino Series 300 Truck	cambio de pines de muelles	CORRECTIVO	26/11/2021 66,251.00km		Corrective Order	WO Completed	Truck
717986	Hilux DC	cobertores de asiento	CORECTIVO	26/11/2021 48,914.00km		Corrective Order	WO Completed	Pickup truck
717987	Toyota Hilux	instalacion de 3era luz de fre	CORRECTIVO	26/11/2021 91,722.00 km		Corrective Order	WO Completed	Pickup truck
717988	PB002 COASTER TOYOTA	revison de frenos	CORRECTIVO	26/11/2021 286,248.00 km		Corrective Order	WO Completed	Bus
717992	LV214 HILUX TOYOTA	rep. sistema electrico	CORRECTIVO	26/11/2021 106,815.00 km		Corrective Order	WO Completed	Light Vehicles
717994	Hilux DC	cambio de cruceta	CORRECTIVO	26/11/2021 42,525.00 km		Corrective Order	WO Completed	Pickup truck
718021	Hino Series 300 Truck	Cambio de retenedora diferenci	CORRECTIVO	26/11/2021 66,245.00		Corrective Order	WO Completed	Truck
718025	Landcruiser DC	reemplazo de aceites y filtros	CORRECTIVO	26/11/2021 70,979.00 km		Corrective Order	WO Completed	Pickup truck
718026	Landcruiser DC	cambio de escobilla	MANTENIMIENTO CORRECTIVO	26/11/2021 40,947.00 kms		Corrective Order	WO Completed	Pickup truck
718034	Hino Serie 300	cambio de escolta	CORRECTIVO	26/11/2021		Corrective Order	WO Completed	Truck
718039	Landcruiser DC	cambio de claxon	CORRECTIVO	26/11/2021		Corrective Order	WO Completed	Pickup truck
718065	Hilux DC	cambio de cable de freno	CORRECTIVO	26/11/2021 59,480.00 km		Corrective Order	WO Completed	Pickup truck